

Contact Log

- 9/16/96 Received message from Rhonda, SEMCO, that they discovered sand in the UST and they will contact Fire Dept. to obtain permission to cut top part of UST at site & empty sand before tank removal.
- 9/17/96 Tank was filled $\sim 2/3$ w/ concrete, but the remaining $1/3$ ^{still} contained diesel, according to Rhonda, SEMCO. This is evidence that the tank was not closed properly, so the tank should still be hauled as hazardous & hauled to appropriate haz. disposal facility.