



89 NOV 27 AM 11:48

November 21, 1989

Alameda County
Larry Seto
Hazardous Materials
80 Swannway Room 200
Oakland, CA 94621

RE: Leak Detection Certification

Please find enclosed the leak detection certification for Shell Oil Service Station sites. The following locations are enclosed. If you have any questions, please call us at (714) 546-1227.

Sincerely,

Stephen W. Hogie
Service Station Services

SWH/js

1. 318 Livermore
Livermore, CA
WIC# 204-4380-03

gettler — ryan inc. general contractors

November 7, 1989

Ms. Lisa Foster
Shell Oil Company
Post Office Box 4023
Concord, California 94520

Reference: Shell Service Station ³⁸⁰WIC# 204-4780-03
318 S. Livermore
Livermore, California

On July 25, 1989, Gettler-Ryan Inc. technicians performed the annual Shell Oil Company survey of operations at the above referenced location. All necessary systems were in place and operating correctly. The leak detectors were noted to be in place, operating correctly and sealed with a lead seal.

Please do not hesitate to call should you have any questions or comments.



Timothy J. Dahl

cc: Service Station Services (Josephine)

SHELL OIL COMPANY

1989 INSPECTION PROGRAM

LOCATION: 3135 Livermore Ave

JOB # 1250-8

Livermore

WIC # 204-4380-0303

	FILL CAP	VAPOR CAP	FILL ADAPTOR	VAPOR ADAPTOR	O-RING GASKETS	FILL TUBES
SU-2000	<u>OK</u>	<u>OK</u>	<u>OK</u>	<u>OK</u>	<u>OK</u>	<u>OK</u>
RU-2000	<u>OK</u>	<u>OK</u>	<u>OK</u>	<u>OK</u>	<u>OK</u>	<u>OK</u>
REGULAR	<u>OK</u>	<u>OK</u>	<u>OK</u>	<u>OK</u>	<u>OK</u>	<u>OK</u>
DIESEL	<u>N/A</u>	<u>N/A</u>	<u>N/A</u>	<u>N/A</u>	<u>N/A</u>	<u>N/A</u>

RONAN PRODUCT LINE SENSORS:

YES: _____ NO: ✓

TLS-250 TANK MONITORING SYSTEM:

YES: _____ NO: ✓


OWENS-CORNING MONITORING SYSTEM:

YES: _____ NO: ✓

SYSTEM OPERATION CHECK:

YES: _____ NO: ✓

TANK HOLE MONITORING WELLS:



Livermore Ave

DEPTH TO LIQUID

HYDROCARBON THICKNESS

A -	<u>N/A</u>	_____
B -	<u>N/A</u>	_____
C -	<u>N/A</u>	_____
D -	<u>N/A</u>	_____

COMMENTS: NO monitoring wells on tank slab

CONTRACTOR: GETTLER-RYAN INC.

MECHANIC: Ratonara

DATE: 7/25/89

LOCATION: 3185 Livermore Ave
Livermore
WIC #204-4380-0303

LEAK DETECTOR INSTALLATION & PRESSURE

TEST REPORT

1250

TEST RESULTS		ITEMS TESTED						
		LEAK DETECTORS		PRODUCT LINES	IMPACT VALVES (describe island location)			
		NEW LEAK DETECTOR	SEALED		ISLAND 'A'	ISLAND 'B'	ISLAND 'C'	ISLAND 'D'
PASS	Pass	No	Yes		OK	replaced	OK	
FAIL (describe problem)								
CORRECTIVE ACTION (only as authorized by Shell)								
PASS	Pass	Yes	Yes		OK	OK	OK	
FAIL (describe problem)								
CORRECTIVE ACTION (only as authorized by Shell)								
PASS	Pass	No	Yes		OK	OK	OK	
FAIL (describe problem)								
CORRECTIVE ACTION (only as authorized by Shell)								

IMPACT VALVE STABILIZERS - EXISTING- 9 INSTALLED-

COMMENTS: Replace the impact valve on dispenser 5/16 Regular

SHELL REGULAR

REGULAR

SUPER SHELL

65

LOCATION: 3185 Livemore Ave
Livermore
 WIC #204-4380-0303

TEST REPORT

12-50-9

TEST RESULTS	ITEMS TESTED							
	LEAK DETECTORS			PRODUCT LINES	IMPACT VALVES (describe island location)			
	X				ISLAND 'A'	ISLAND 'B'	ISLAND 'C'	ISLAND 'D'
	NEW LEAK DETECTOR	SEALED		OUTSIDE SOUTH	OUTSIDE NORTH	INSIDE		
PASS	Pass	No	Yes		OK	replaced	OK	
FAIL (describe problem)								
CORRECTIVE ACTION (only as authorized by Shell)								
PASS	Pass	Yes	Yes		OK	OK	OK	
FAIL (describe problem)								
CORRECTIVE ACTION (only as authorized by Shell)								
PASS	Pass	No	Yes		OK	OK	OK	
FAIL (describe problem)								
CORRECTIVE ACTION (only as authorized by Shell)								

SHELL REGULAR SUPER SHELL

IMPACT VALVE STABILIZERS - EXISTING- 9 INSTALLED-

COMMENTS: Replace the impact valve on dispenser 5/1a Regular