

STID 4266

James P. Bowers, PE
R. William Rudolph, Jr., PE

June 23, 1993
SCI 537.004

STID Lu

Ms. Susan Hugo
Alameda County Health Care Services Agency
80 Swan Way, Room 200
Oakland, California 94621

Groundwater Monitoring Program
4300 San Pablo Avenue
Emeryville, California

Dear Ms. Hugo:

Subsurface Consultants, Inc. (SCI) has performed groundwater monitoring at the referenced site since June 1990. Monitoring event data indicates that groundwater has been impacted by previous gasoline and diesel releases. Although it appears that the dissolved product plume exists beneath the site and may extend beneath a portion of San Pablo Avenue, it has not significantly impacted properties down and side gradient of the previous tanks.

Since contaminant levels have not significantly changed since monitoring began, we recommend that the program be revised to consist of semi-annual monitoring of the upgradient well MW-1, and the two downgradient wells MW-5 and MW-6. The monitoring events will be performed as outlined in our previous monitoring event letters (see letter dated May 24, 1993).

If you are in concurrence with this revision, please provide your approval in writing to Mr. Ignacio Dayrit of the City of Emeryville at the address listed below.

■ Subsurface Consultants, Inc.

171 12th Street • Suite 201 • Oakland, California 94607 • Telephone 510-268-0461 • FAX 510-268-0137


Mr. Ignacio Dayrit
SCI 537.004
June 24, 1993
Page 2

■ Subsurface Consultants, Inc.

If you have any questions, please call.

Yours very truly,

Subsurface Consultants, Inc.



Jeriann N. Alexander
Civil Engineer 40469 (expires 3/31/95)



R. William Rudolph
Geotechnical Engineer 741 (expires 12/31/92)

JNA:RWR:egh

cc: Mr. Ignacio Dayrit
City of Emeryville
2200 Powell Street, 12th Floor
Emeryville, California 94608

Mr. Rich Hiett
Regional Water Quality Control Board
2101 Webster Street, Suite 500
Oakland, California