

Castlewood C.C.
707 Country Club Lane
Pleasanton

10/23/92

MEMO to file:

Tim Berger of BSK Associates called today. Last week he had requested permission to introduce potable H₂O to the monitoring well on this site in hopes to developing it. Having done that, he indicated that the water went down the well casing and essentially "just disappeared, indicating that formations had ~~not~~ ^{H₂O} failed to ^{not} enter the well, because the well was not yet developed, but rather because no native H₂O is present at the depth this well is constructed (TD is 50' BG).

I agreed, and consulted with Mr. Rich Hiett of RWQCB, who also agreed. I told Mr. Berger to go ahead and destroy the well. I also told him that after review of the report, we'll decide what additional work, if any, would be needed here.

Mr. Berger indicated that all the samples collected from the boring were ND for target compounds. Subjective indications based on observations of the geologist during drilling corroborate these results.

SES