



FACSIMILE MESSAGE

COPY

CHEVRON U.S.A. PRODUCTS COMPANY
West Central Region
Marketing Department SR-2410 Camino Ramon

Mail Address: P.O. Box 5004, San Ramon, CA 94583-0804
(Street Address: 2410 Camino Ramon)

Reply by Facsimile: (510) 842-9591

Date: 6/29/92

To: Chris Bramer Fax Number: 370-7959

Sierra Environmental

From: Nancy L. Vukelich Phone No.: (510) 842-9581

Site Assessment and Remediation Engineer

Subject: #9-5630 - 997 Grant Avenue

SAN LORENZO

Comments: Please resample all wells, if possible, within the next week. I feel the results reported are anomalous based on historical results. This is a critical site for me with respect to dealings with the property owner and regulators. It is "imperative" that sampling protocol be followed to avoid any cross-contamination. Based on the results of this analysis next actions will be determined.

NUMBER OF PAGES INCLUDING COVER SHEET 2

Please have this data faxed to me immediately upon receipt. Call to advise of schedule.



Table 2. Analytic Results for Ground Water - Former Chevron Service Station #9-5630, 997 Grant Avenue, San Lorenzo, California

Well ID	Date Sampled	Analytic Lab	Analytic Method	TPPH(G) B T E X O&G					
				-----ppb-----					
C-1	12/5/90	SAL	8015/8020/503E	<50	<0.5	<0.5	<0.5	<0.5	<5,000
	9/6/91	SPA	8015/8020	<50	<0.5	<0.5	<0.5	<0.5	---
	12/4/91	SPA	8015/8020	<50	<0.5	<0.5	<0.5	<0.5	---
	4/2/92	SPA	8015/8020	<50	<0.5	<0.5	<0.5	<0.5	<5,000
	6/3/92	SPA	8015/8020	<50	1.4	1.5	0.6	3.0	---
C-2	12/5/90	SAL	8015/8020	<50	0.7	<0.5	<0.5	0.5	---
	9/6/91	SPA	8015/8020	<50	1.3	0.6	0.7	1.5	---
	12/4/91 ²	---	---	---	---	---	---	---	---
	4/2/92	SPA	8015/8020	<50	<0.5	<0.5	<0.5	<0.5	---
	6/3/92	SPA	8015/8020	180	12	13	7.9	21	---
C-3	12/5/90	SAL	8015/8020	<50	1	0.7	<0.5	<0.5	---
	9/6/91	SPA	8015/8020	1,100	150	0.6	51	1.9	---
	12/4/91	SPA	8015/8020	89	<0.5	<0.5	0.7	0.6	---
	4/2/92	SPA	8015/8020	60	2.1	1.3	1.1	3.2	---
	6/3/92	SPA	8015/8020	7,600	94	86	26	89	---
C-4	12/5/90	SAL	8015/8020	<50	4	2	0.7	3	---
	9/6/91 ¹	---	---	---	---	---	---	---	---
AA (Trip Blank)	12/5/90	SAL	8015/8020	<50	<0.5	<0.5	<0.5	<0.5	---
	9/6/91	SPA	8015/8020	<50	<0.5	<0.5	<0.5	<0.5	---
	12/4/91	SPA	8015/8020	<50	<0.5	<0.5	<0.5	<0.5	---
	4/2/92	SPA	8015/8020	<50	<0.5	<0.5	<0.5	<0.5	---
	6/3/92	SPA	8015/8020	<50	<0.5	<0.5	<0.5	<0.5	---
BB (Bailer Blank)	9/6/91	SPA	8015/8020	<50	<0.5	<0.5	<0.5	<0.5	---
	12/4/91	SPA	8015/8020	<50	<0.5	<0.5	<0.5	<0.5	---
	4/2/92	SPA	8015/8020	<50	<0.5	<0.5	<0.5	<0.5	---
	6/3/92	SPA	8015/8020	<50	<0.5	<0.5	<0.5	<0.5	---