

# Ditch Pade Dairy

5/18/94

Meeting w/ M. Briggs (RESNA), R. Dodge +  
J. Dodge

Decide add'l MW's not required at this  
time. MW-4 at Shell is downgraded

do S.B. east ~~of~~ and west of pit to  
determine extent of soil contam.

Will decide if g.w. grab sample necessary  
when doing S.B.s.