



AGENCY  
DAVID J. KEARS, Agency Director

ARNOLD PERKINS, DIRECTOR  
RAFAT A. SHAHID, DEPUTY DIRECTOR

Certified Mail # P 368 729 259  
01/02/96  
STID# 3732

Alameda County  
Environmental Protection Division  
1131 Harbor Bay Parkway, Room 250  
Alameda CA 94502-6577  
(510) 567-6700

Notice of Requirement to Reimburse

Don Wallace  
Henry Moller & Sons  
155 Seacliff Dr. East  
Aptos, C A 95003

Responsible Party (RP) #1  
Property Owner

Hamid Taeb  
Boulevard Development  
856 North Commerce  
Orange, C A 92667

Responsible Party (RP) #2

Henry Moller & Sons Meat Pack  
5710 Foothill Rd  
Pleasanton, CA 94566

SITE

Date First Reported 02/20/90  
Substance: Gasoline  
Petroleum: (X) Yes  
Source: F

The federal Petroleum Leaking Underground Storage Tank Trust Fund (Federal Trust Fund) provides funding to pay the local and state agency administrative and oversight costs associated with the cleanup of releases from underground storage tanks. The legislature has authorized funds to pay the local and state agency administrative and oversight costs associated with the cleanup of releases from underground storage tanks. The direct and indirect costs of overseeing site investigation or remedial action at the above site are funded, in whole or in part, from the Federal Trust Fund. The above individual(s) or entity(ies) have been identified as the party or parties responsible for investigation and cleanup of the above site. **YOU ARE HEREBY NOTIFIED** that pursuant to Title 42 of the United States Code, Section 6991b(h) (6) and Section 25297.1 of the California Health and Safety Code, the above Responsible Party or Parties must reimburse the State Water Resources Control Board (SWRCB) not more than 150 percent of the total amount of site specific oversight costs actually incurred while overseeing the cleanup of the above referenced underground storage tank site, and the above Responsible Party or Parties (RPs) must make full payment of such costs within 30 days of receipt of a detailed invoice from the SWRCB.

A determination of a secondary RP status may be made if it is shown that one or more of the RP(s) is performing corrective action and it is clear that the party seeking secondary status did not in any way initiate or contribute to the actual discharge. If the primary RP fails to perform corrective action, then the secondary RP will be considered a primary RP. To request designation as a secondary RP, contact this office.

Reimburse Letter  
01/02/96  
StID# 3732  
Page 2

Any action or inaction by this local agency associated with corrective action, including responsible party identification, is subject to petition to the SWRCB. Petitions must be filed within 30 days from the date of the action/inaction. To obtain petition procedures, Please fax your request to Roni Riley at the SWRCB at (916) 227-4349 telephone the SWRCB at (916) 227-4408.  
Please contact Eva CHU, Hazardous Materials Specialist at this office if you have any further questions concerning this matter.

  
Gordon Coleman, Acting Chief  
Contract Project Director

c: Mike Harper, SWRCB

Please Circle One  Add  Delete  Change

Reason: Consolidate former RPs, add new RP

ALAMEDA COUNTY  
HEALTH CARE SERVICES



AGENCY  
DAVID J. KEARS, Agency Director

RO#1151  
ARNOLD PERKINS, DIRECTOR  
RAFAT A. SHAHID, DEPUTY DIRECTOR

Certified Mail # P 368 729 258  
01/02/96  
STID# 3732

Alameda County  
Environmental Protection Division  
1131 Harbor Bay Parkway, Room 250  
Alameda CA 94502-6577  
(510) 567-6700

Notice of Requirement to Reimburse

Don Wallace

Henry Moller & Sons  
155 Seacliff Dr. East  
Aptos, C A 95003

Responsible Party (RP) #1  
Property Owner

Hamid Taeb

Boulevard Development  
856 North Commerce  
Orange, C A 92667

Responsible Party (RP) #2

Henry Moller & Sons Meat Pack  
5710 Foothill Rd  
Pleasanton, CA 94566

SITE

Date First Reported 02/20/90  
Substance: Gasoline  
Petroleum: (X)Yes  
Source: F

The federal Petroleum Leaking Underground Storage Tank Trust Fund (Federal Trust Fund) provides funding to pay the local and state agency administrative and oversight costs associated with the cleanup of releases from underground storage tanks. The legislature has authorized funds to pay the local and state agency administrative and oversight costs associated with the cleanup of releases from underground storage tanks. The direct and indirect costs of overseeing site investigation or remedial action at the above site are funded, in whole or in part, from the Federal Trust Fund. The above individual(s) or entity(ies) have been identified as the party or parties responsible for investigation and cleanup of the above site. **YOU ARE HEREBY NOTIFIED** that pursuant to Title 42 of the United States Code, Section 6991b(h)(6) and Section 25297.1 of the California Health and Safety Code, the above Responsible Party or Parties must reimburse the State Water Resources Control Board (SWRCB) not more than 150 percent of the total amount of site specific oversight costs actually incurred while overseeing the cleanup of the above referenced underground storage tank site, and the above Responsible Party or Parties (RPs) must make full payment of such costs within 30 days of receipt of a detailed invoice from the SWRCB.

A determination of a secondary RP status may be made if it is shown that one or more of the RP(s) is performing corrective action and it is clear that the party seeking secondary status did not in any way initiate or contribute to the actual discharge. If the primary RP fails to perform corrective action, then the secondary RP will be considered a primary RP. To request designation as a secondary RP, contact this office.

Reimburse Letter  
01/02/96  
StID# 3732  
Page 2

Any action or inaction by this local agency associated with corrective action, including responsible party identification, is subject to petition to the SWRCB. Petitions must be filed within 30 days from the date of the action/inaction. To obtain petition procedures, Please fax your request to Roni Riley at the SWRCB at (916) 227-4349 telephone the SWRCB at (916) 227-4408.  
Please contact Eva CHU, Hazardous Materials Specialist at this office if you have any further questions concerning this matter.

  
Gordon Coleman, Acting Chief  
Contract Project Director

c: Mike Harper, SWRCB

Please Circle One  Add  Delete  Change

Reason: Consolidate former RPs, add new RP



Certified Mail # P 367 604 242

03/23/92  
STID# 3732

DEPARTMENT OF ENVIRONMENTAL HEALTH  
Hazardous Materials Division  
80 Swan Way, Rm. 200  
Oakland, CA 94621  
(510) 271-4320

**Notice of Requirement to Reimburse**

Don Wallace

4366 J Malta Circle  
Palm Desert, C A 92260

Responsible Party #1  
Property Owner

Evelyn Moller  
Henry Moller & Sons  
5710 Foothill Rd  
Pleasanton, C A 94566

Responsible Party #2  
Contact Person  
Contact Company

Henry Moller & Sons Meat Pack  
5710 Foothill Rd.  
Pleasanton, CA 94566

SITE

Date First Reported 02/20/90  
Substance: Gasoline  
Petroleum: (X)Yes

The federal Petroleum Leaking Underground Storage Tank Trust Fund (Federal Trust Fund) provides funding to pay the local and state agency administrative and oversight costs associated with the cleanup of releases from underground storage tanks. The legislature has authorized funds to pay the local and state agency administrative and oversight costs associated with the cleanup of releases from underground storage tanks. The direct and indirect costs of overseeing removal or remedial action at the above site are funded, in whole or in part, from the Federal Trust Fund. The above individual(s) or entity(ies) have been indentified as the party or parties responsible for investigation and cleanup of the above site. YOU ARE HEREBY NOTIFIED that pursuant to Title 42 of the United States Code, Section 6991b(h)(6) and Sections 25297.1 and 25360 of the California Health and Safety Code, the above Responsible Party or Parties must reimburse the State Water Resources Control Board not more than 150 percent of the total amount of site specific oversight costs actually incurred while overseeing the cleanup of the above underground storage tank site, and the above Responsible Party or Parties must make full payment of such costs within 30 days of receipt of a detailed invoice from the State Water Resources Control Board.

Please contact Scott SEERY, Hazardous Materials Specialist at this office if you have any questions concerning this matter.

Edgar B. Howell, III, Chief  
Contract Project Director

cc: Sandra Malos, SWRCB

SWRCB Use:  Add: X Reason: New Case

ec



Certified Mail # P367 604 241

03/23/92  
STID# 3732

DEPARTMENT OF ENVIRONMENTAL HEALTH  
Hazardous Materials Division  
80 Swan Way, Rm. 200  
Oakland, CA 94621  
(510) 271-4320

**Notice of Requirement to Reimburse**

Don Wallace

4366 J Malta Circle  
Palm Desert, C A 92260

Responsible Party #1  
Property Owner

Evelyn Moller

Henry Moller & Sons  
5710 Foothill Rd  
Pleasanton, C A 94566

Responsible Party #2  
Contact Person  
Contact Company


Henry Moller & Sons Meat Pack  
5710 Foothill Rd.  
Pleasanton, CA 94566

**SITE**

Date First Reported 02/20/90  
Substance: Gasoline  
Petroleum: (X)Yes

The federal Petroleum Leaking Underground Storage Tank Trust Fund (Federal Trust Fund) provides funding to pay the local and state agency administrative and oversight costs associated with the cleanup of releases from underground storage tanks. The legislature has authorized funds to pay the local and state agency administrative and oversight costs associated with the cleanup of releases from underground storage tanks. The direct and indirect costs of overseeing removal or remedial action at the above site are funded, in whole or in part, from the Federal Trust Fund. The above individual(s) or entity(ies) have been indentified as the party or parties responsible for investigation and cleanup of the above site. YOU ARE HEREBY NOTIFIED that pursuant to Title 42 of the United States Code, Section 6991b(h)(6) and Sections 25297.1 and 25360 of the California Health and Safety Code, the above Responsible Party or Parties must reimburse the State Water Resources Control Board not more than 150 percent of the total amount of site specific oversight costs actually incurred while overseeing the cleanup of the above underground storage tank site, and the above Responsible Party or Parties must make full payment of such costs within 30 days of receipt of a detailed invoice from the State Water Resources Control Board.

Please contact Scott SEERY, Hazardous Materials Specialist at this office if you have any questions concerning this matter.

  
Edgar B. Howell, III, Chief  
Contract Project Director

cc: Sandra Malos, SWRCB

SWRCB Use:

Add: X Reason: New Case

*er*



First-Class Mail  
Postage & Fees Paid  
USPS  
Permit No. G-10

• Print your name, address, and ZIP Code in this box •

ENVIRONMENTAL PROTECTION

95 JAN -9 PH 2: 16

Alameda County Cc4580  
Environmental Health Services  
1131 Harbor Bay Pkwy., #250  
Alameda CA 94502-6577

Is your RETURN ADDRESS completed on the reverse side?

**SENDER:**

- Complete items 1 and/or 2 for additional services.
- Complete items 3, 4a, and 4b.
- Print your name and address on the reverse of this form so that we can return this card to you.
- Attach this form to the front of the mailpiece, or on the back if space does not permit.
- Write "Return Receipt Requested" on the mailpiece below the article number.
- The Return Receipt will show to whom the article was delivered and the date delivered.

I also wish to receive the following services (for an extra fee):

- 1.  Addressee's Address
- 2.  Restricted Delivery

Consult postmaster for fee.

3. Article Addressed to: E. Chu #3732  
Ro 1151  
Don Wallace  
Henry Moller & Sons  
155 Seacliff Dr. East  
Aptos CA 95003

4a. Article Number  
P 368 729 258

4b. Service Type

Registered  Certified  
 Express Mail  Insured  
 Return Receipt for Merchandise  COD

7. Date of Delivery  
1-5-96

5. Received By: (Print Name)

8. Addressee's Address (Only if requested and fee is paid)

6. Signature: (Addressee or Agent)

X *Don Wallace*

PS Form 3811, December 1994

Domestic Return Receipt

Thank you for using Return Receipt Service.