

FACING DUE SOUTH

BUNKER



GASOLINE



FACING SOUTH
TWO UST'S
100 G GASOLINE, 1500 G BUNKER OIL



TANK HAS NUMEROUS HOLES. SLUDGE DRIPPING OUT OF THE BOTTOM



PIPING REMOVED



41 04-29-03
P0001567.JPG



42 04-29-03
P0001568.JPG




43 04-29-03
P0001569.JPG




44 04-29-03
P0001571.JPG



45 04-29-03
P0001572.JPG




46 04-29-03
P0001573.JPG



47 04-29-03
P0001574.JPG



48 04-29-03
P0001575.JPG



39 04-29-03
P0001565.JPG




40 04-29-03
P0001566.JPG





20 FT N. OF TANK PIT
PIPE TRENCH



PIPING TRENCH
SAMPLING



FORMER GASOLINE TANK
FLATTENED W/ EXCAVATOR



TOP ←
TANK
PIT
SIDE

DISCOLORED SOIL
FROM BENEATH
TANK







