RECEIVED

By dehloptoxic at 8:51 am, Feb 22, 2007



Glenn Leong Treadwell & Rollo 501 14th Street, 3rd Floor Oakland, CA 94612

February 20, 2007

Mr. Leong,

The detections of methylene chloride in the soil samples for your project Emeryville Industrial Ct (CT# 186612), are likely the result of laboratory contamination. Because this solvent is used to extract for other analytes, a shared container is likely to have exposure to this solvent.

During the period your samples were being analyzed, we observed sporadic methylene chloride contamination in the refrigerated sample storage area. The source of this contamination has since been detected and removed. Additionally, C&T is in process of upgrading the air circulation system within this storage area to further reduce and eliminate potential contamination of samples by volatile solvents.

Should you have any further questions, please feel free to contact me at your leisure.

Sincerely,

Steven E. Stanley

Client Services Dept. Mgr.



Glenn Leong Treadwell & Rollo 501 14th Street, 3rd Floor Oakland, CA 94612

February 20, 2007

Mr. Leong,

The detections of methylene chloride in the soil samples for your project Emeryville Industrial Ct (CT# 186708), are likely the result of laboratory contamination. Because this solvent is used to extract for other analytes, a shared container is likely to have exposure to this solvent.

During the period your samples were being analyzed, we observed sporadic methylene chloride contamination in the refrigerated sample storage area. The source of this contamination has since been detected and removed. Additionally, C&T is in process of upgrading the air circulation system within this storage area to further reduce and eliminate potential contamination of samples by volatile solvents.

Should you have any further questions, please feel free to contact me at your leisure.

Sincerely.

Steven E. Stanley

Client Services Dept. Mgr.