

January 31, 2000

To: Mr. Mark Johnson
Regional Water Quality Control Board
1515 Clay Street, Suite 1400
Oakland, California 94612

Re: Quarterly Groundwater Monitoring Report, for October 1 to December 31, 1999, Site Cleanup Requirements Order No. 98-009, The Sherwin-Williams Facility, Emeryville, California


The following items are enclosed via Courier.

Description	No. of Copies
Subject report in CD-ROM format	1
Cover Letter	1
Certification	1

The item(s) are transmitted: At your request For your action
 For your review/comment For your files
 For your approval For your information

Comments: Please note that this CD includes all four 1999 monitoring reports.

Sincerely,



Michael B. Marsden, R.G., C.H.G.
Senior Associate Hydrogeologist

cc: (via U.S. mail)
Susan Hugo
Ignacio Dayrit
George Stavnes
Vera Nelson
Jay Grover
Barbara Cook

Peggy Peischl
Reber Brown, Ph.D.
Robert Cave
Jody Sparks
Sandra Maxfield

January 31, 2000

6495.99-003

Mr. Mark Johnson
Regional Water Quality Control Board
1515 Clay Street, Suite 1400
Oakland, California 94612

Subject: Quarterly Self-Monitoring Report, October 1 to December 31, 1999, Site Cleanup Requirements Order No. 98-009, The Sherwin-Williams Company, Emeryville, California

Dear Mr. Johnson:

Enclosed is the self-monitoring report, prepared by LFR Levine · Fricke (LFR) on behalf of The Sherwin-Williams Company, for the quarterly period of October 1 through December 31, 1999. This self-monitoring report is submitted pursuant to the requirements of Site Cleanup Requirements (SCR) Order No. 98-009, issued by the Regional Water Quality Control Board on February 19, 1998. Self-monitoring activities conducted at The Sherwin-Williams Company site in Emeryville, California ("the Site") during this quarterly reporting period were in compliance with requirements of the SCR and self-monitoring program. This report summarizes the eleventh consecutive quarter of data collected in the self-monitoring program, which consists of the sampling and analysis of 53 wells. Since December 1989, approximately 22 sampling events have been conducted at the Site. As discussed previously, The Sherwin Williams Company will be proposing an amended self-monitoring program.

This report presents historical data and the results of the quarterly groundwater-monitoring program conducted at the Site in October 1999. In addition, this report includes summaries of the operation of the Sherwin-Williams groundwater extraction and treatment systems and information about removal of contaminants from extracted groundwater at the Site, as required by the SCR.

I certify, under penalty of perjury, that this document and all attachments are prepared under my direction or supervision and the information submitted is, to the best of my knowledge and belief, true, accurate, and complete.

If you have any questions or comments regarding this report, please call Larry Mencin at (216) 566-1768 or me at (510) 652-4500.

Sincerely,



Michael B. Marsden, R.G., C.H.G.
Senior Associate Hydrogeologist

Enclosure

cc: Distribution List

DISTRIBUTION LIST (CD Only):

Susan Hugo
Alameda County Department of
Environmental Health
Hazardous Materials Division
1131 Harbor Bay Parkway, 2nd floor
Alameda, California 94502-6577

Ignacio Dayrit
Projects Coordinator
Development Services Department
Project Development Division
City of Emeryville, Redevelopment Agency
2200 Powell Street, 12th Floor
Emeryville, California 94608

George Stavnes
The Sherwin-Williams Company
1450 Sherwin Avenue
Emeryville, California 94608

Vera Nelson
Erler & Kalinowski, Inc.
1730 So. Amphlett Blvd., Suite 320
San Mateo, California 94402

Jay Grover
Chiron Corporation
4560 Horton Street
Emeryville, California 94608-2916

Barbara Cook
California Environmental Protection Agency
Dept. of Toxic Substances Control, Region 2
700 Heinz Ave., Suite 200
Berkeley, California 94710

Peggy Peischl
Treadwell and Rollo
2 Theater Square, #216
Orinda, California 94563

Reber Brown, Ph.D.
Environmental Investigations Branch
California Dept. of Health Services
5900 Hollis Street, Suite E
Emeryville, California 94608

Robert Cave
Air Quality Engineer
BAAQMD
939 Ellis Street
San Francisco, California 94109

Jody Sparks
Toxics Assessment Group
1801 Hanover Drive, Suite C
PO Box 73620
Davis, California 95617-3620

Sandra Maxfield
ENTRIX, Inc.
590 Ygnacio Valley Road, Suite 200
Walnut Creek, California 94596

DISTRIBUTION LIST (CD/Hard Copy):

Larry Mencin
The Sherwin-Williams Company
101 Prospect Avenue, N.W.
Cleveland, Ohio 44115-1075

Randi Parker-Germains
45th Street Artists' Cooperative
1420 45th Street
Emeryville, California 94608


Melissa Mednick (2 copies)
Community Relations and Socioeconomic
Analysis
Mara Feeney & Associates
5689 Oak Grove Avenue
Oakland, California 94618

DISTRIBUTION LIST (Letter Only):

Mara Feeney, Principal
Mara Feeney & Associates
19 Beaver Street
San Francisco, California 94114-1514

CERTIFICATION

All hydrogeologic and geologic information, conclusions, and recommendations in this document have been prepared under the supervision of and reviewed by an LFR Levine-Fricke California-Certified Hydrogeologist.



Michael B. Marsden
Senior Associate Hydrogeologist
California Registered Geologist (6536)
California Certified Hydrogeologist (566)

1-31-00

Date