

10/19/88.

9:45 Talked with Bob Phipps of Trammel Crow & explained to him that the lead blast operators needed to be fit-tested for respirator use & that the cartridges used with the respirator must be capable of filtering out the cement-lead dust. I told him an industrial hygienist ~~was~~ would be able to fit test the workers & that an industrial hygienist could probably be found in the phone book. Bob asked if the respirator supplier could fit test the workers. I told Bob it depended upon the supplier's capabilities as to whether they could fit test people. I explained to Bob that respirators must be fitted to the individual like any piece of clothing - different people wear different sizes.

Floor was lead blasted & epoxy coated ~~per~~ my recall of the site activities. 2/16/90
Katherine Sherrill

8:52 Per conversation with ^{Gordon} ~~Gordon~~ Simpson (of U.S.) the business is now Romeo & Juliet Shoe repair. Gordon said they have no documentation confirming that the floor was lead blasted & epoxy coated. I told Gordon I'd write a letter to Trammel Crow. 2/20/90