Drogos, Donna, Env. Health

Subject:	RO2949 - 638-632 2nd
Entry Type:	Phone call

 Start:
 Wed 9/19/2007 11:25 AM

 End:
 Wed 9/19/2007 11:25 AM

 Duration:
 0 hours

9/17/07, 1015a, Dan Autwarg Need Itr & staff person to get case to apply to USTCF Clearwater said to call, have had case for awhile

09/20/07, 1125a, Dan Autwarg, property owner 626 2nd St Cell 510-772-7625 Work 510-832-6532 dan@marcussupply.com

Refinancing property, bank wants evidence that they are in USTCF to refinace property To complete application need case number & caseworker according to Clearwater. Told him he likely needs NOR indicating case in LOP program.

He is only refinancing the property not redeveloping it.

Told him I worked on listing his case but Clearwater did not provide context maps allowing me to identify location of UST so address of UST location could not be identified. Have not gone back to complete case listing. Verified that reports & info submitted by Clearwater.

Discussed property history. He has researched. PG&E owned USTs & property, last owned in 1950s. His family purchased in 1960s. His family did not use the USTs. He closed them in place this year. 5 USTs 2 PHC & cluster of 3 were cresote. PG&E confirmed they owned PHC USTs to him & his attorney & accepted liability. PG&E deny's owning cresote USTs. PG&E facility directly across the street from USTs (former RO50, now DTSC lead).

Requested he send me documentation that PG&E owned & operated USTs. Need that info to complete case listing & identify them as RPs. Also give me full contact info for their contact at PG&E. He will have his attorney e-mail me the documentation.

Told him if he sends me that information I will complete case listing on Monday & have his case worker assigned next week. Estimate3 NORs issued in 2 weeks.

Told him contamination detected. Additional investigation and potentially cleanup will be req'd at his site.

Drogos, Donna, Env. Health

Subject:RO2949 - 623-636 2NDEntry Type:Phone call

 Start:
 Mon 7/16/2007 3:00 PM

 End:
 Mon 7/16/2007 3:00 PM

 Duration:
 0 hours

Discuss site with Mathew Rider Smith, Clearwater

Unable to identify site with maps provided in report, need to list site by address of UST location. Maps provided do not ashow placement of UST in relation to different property addresses.

He will post an addendum to SWI that depicts UST locations in contrext.

He will also provide full contact info for RP