

**DEPARTMENT OF ENVIRONMENTAL HEALTH**

Facility Name	: N/A	Owner	: N/A
Site Address	: 170 WOODLAND WAY	Owner Address	: 170 WOODLAND WAY
Facility Phone	:	Owner Phone	:
Type of Facility	: 5520 FACILITY CLOSUREDEH OVERSIGHTDEPT HOURLY RATE		

Facility ID	: FA0324727	Inspector	: EE0000180 - BARBARA JAKUB
Record ID	: PR0524703	Inspector Phone	: (510) 567-6737 Ext. 36737
License/Permit Number	: PT0318959	Inspection Start Time	: Not Specified
Person in Charge	: N/A	Inspection Stop Time	: Not Specified
Inspection Date	: 2/14/2017	Total Inspection Time	: 40 min.
Inspection Number	: DA7GDMLQD	Travel Start Time	: Not Specified
Purpose of Inspection	: B87 - SITE CLOSURE DEH REVIEW	Travel Stop Time	: Not Specified
Result	: 00 - NOT APPLICABLE	Total Travel Time	: 30 min.
Re-Inspection Date	: Not Specified		
Total Score	: 0.00		

**Inspection Violations**

No violations cited.

**Overall Inspection Comments**

BARBARA JAKUB ON-SITE FOR OVEREXCAVATION SAMPLING OF 300 GALLON SINGLE WALL STEEL HOME HEATING OIL TANK. TANK WAS DISCOVERED AFTER OWNER OBSERVED FUEL OIL ENTERING CORNER OF BASEMENT CLOSEST TO THE GARAGE. OWNER HAD REPLACED EXISTING CONCRETE DRIVEWAY WITH PAVERS. GGTR DETERMINED THAT IT WAS A UST CAUSING THE RELEASE. SPECULATION THAT THE RELEASE WAS CAUSED BY WATER ENTERING THROUGH THE PAVERS AND FILLING THE TANK CAUSED THE RELEASE IN THIS YEAR OF RECC RAIN. NO HOLES WERE OBSERVED IN THE TANK DURING REMOVAL.

ASUNCION MORA OF GOLDEN GATE TANK REMOVAL PERFORMED SAMPLING. TWO SOIL SAMPLES WERE COLLECTED, THE FIRST WAS 9609 WHAT WAS STATED A THE FILL END OF THE TANK. THE SECOND SAMPLE WAS 9609-W TOWARDS THE GARAGE. SAMPLES WERE COLLECTED 4 FEET BELOW GRADE INTO BEDROCK. THE TANK PIT HAD A HYDROCARBON ODOR AND SOIL FROM THE SAMPLE LOCATION ALSO SMELLED HYDROCARBONS BUT SEEMED LESS STRONG. SOIL SLIGHTLY STAINED GRAY IN THE TANK PIT, AS WELL. WATER ENTERING HOLE FROM PREVIOUS RAIN EVENTS.



Barbara Jakub  
Hazardous Materials Specialist