JA 989

UNDERGROUND STORAGE TANK UNAUTHORIZED RELEASE (LEAK) / CONTAMINATION SITE REPORT		
EMERGENCY HAS STATE OFFICE OF EMERGENCY SERVICES FOR LOCAL AGENCY SERVICES FOR LOCAL AGENCY THAT LAW A DESCRIPTION OF THE PROPERTY OF THE PROP		
	YES 1 NO YES X NO	I HEREBY CERTIFY THAT I AM A DESIGNATED GOVERNMENT EMPLOYEE AND THAT I HAVE REPORTED THIS INFORMATION TO LOCAL OFFICIALS PURSUANT TO SECTION 25180.7 OF
REPORT DATE CASE # THE HEALTH AND SAFTY CODE:		
1.	M 2 M 1 J 4 J 8 V 8 V PHONE	SIGNED DATE
		do agent tot arto
DBY	REPRESENTING X OWNER/OPERATOR REGIONAL BOARD	8) 984-6536 Jina Berry
REPORTED BY	LOCAL AGENCY OTHER	Pacific Environmental Group, Inc.
Æ	ADDRESS	
	1601 Civic Center Drive, Suite 20	
4	NAME	CONTACT PERSON PHONE
RESPONSIBLE PARTY	ARCO Petroleum Products UNKNOWN	Mr. Kyle Christie (415 571-2434
ESPO PA	ADDRESS 2000 Alameda de las Pulgas, Suite 218, San Matee CA 94402	
<b>A</b>	STREET STREET	
_	FACILITY NAME (IF APPLICABLE)  ARCO Service Station #374	OPERATOR PHONE Santosh Kumar Sud (415 658-7508
Š.	ADDRESS	Santosh Kumar Sud   (415 658-7508
SITE LOCATION	6407 Telegraph Ave.	Oakland Alameda 94609
SITE	CROSS STREET TYPE OF AREA X COMM	CITY COUNTY ZIP
.	l Alcatray	MERCIAL INDUSTRIAL RURAL TYPE OF BUSINESS X RETAIL FUEL STATION OTHER OTHER
ğ.,	LOCAL AGENCY AGENCY NAME	CONTACT PERSON PHONE
ENTI-	Alameda County Public Health	Ed Howell (415 271-4320
MPLEMENTING AGENCIES	REGIONAL BOARD	PHONE
3	San Francisco Bay Region	Dyan White (415 464-0838
Ж <sub>О</sub>	Gasoline \$Super-unleaded)	QUANTITY LOST (GALLONS)
SUBSTANCES INVOLVED	(2)	< 10 □ UNKNOWN
SES SES	(4)	
DATE DOCUMENTS		NTORY CONTROL SUBSURFACE MONITORING NUISANCE CONDITIONS
ERY/ABATEMENT		NTORY CONTROL SUBSURFACE MONITORING NUISANCE CONDITIONS  CREMOVAL X OTHER *
ABAT	DATE DISCHARGE BEGAN	METHOD USED TO STOP DISCHARGE (CHECK ALL THAT APPLY)
	M M D D Y Y X UNKNOWN	X REMOVE CONTENTS REPLACE TANK CLOSE TANK
DISCOV	HAS DISCHARGE BEEN STOPPED?	REPAIR TANK REPAIR PIPING CHANGE PROCEDURE
	X YES NO IFYES, DATE 1 2 M D B 8 N 8	
SOURCEICAUSE	SOURCE OF DISCHARGE TANKS ONLY CAPACITY  X TANK LEAK UNKNOWN 12,000 GAL.	MATERIAL CAUSE(S)  X FIBERGLASS OVEREIL DIRECTOR
β2 Σ	PIPINGLEAK UNKNOWN 12,000 GAL.	O TENTILE IN NOTIONE/PAIEURE
ğ	OTHER UNKNOWN	OTUED ON HOUSEN
$\rightarrow$	CHECKONEONLY N/A - see comments	SPILL OTHER
Z SE	UNDETERMINED SOIL ONLY GROUNDWATER	DRINKING WATER - (CHECK ONLY IF WATER WELLS HAVE ACTUALLY BEEN AFFECTED)
50	CHECK ONE ONLY	
STATUS	SITE INVESTIGATION IN PROGRESS (DEFINING EXTENT OF PROBLEM)	CLEANUP IN PROGRESS SIGNED OFF (CLEANUP COMPLETED OR UNNECESSARY)
_	NO ACTION TAKEN POST CLEANUP MONITORING IN PROGRESS	NO FUNDS AVAILABLE TO PROCEED EVALUATING CLEANUP ALTERNATIVES
	CHECK APPROPRIATE ACTION(S) (SEE BACK FOR DETAILS)  CAP SITE (CD)  EXCAVATE & DISPOSE (ED)  REMOVE FREE PRODUCT (ED)  FINIANCED BIO DECRADATION (ED)	
REMEDIAL		REMOVE FREE PRODUCT (FP) ENHANCED BIO DEGRADATION (IT)
	CONTAINMENT BARRIER (CB) EXCAVATE & TREAT (ET)	PUMP & TREAT GROUNDWATER (GT) REPLACE SUPPLY (RS)
$\dashv$	TREATMENT AT HOOKUP (HU) NO ACTION REQUIRED (NA)	X OTHER (OT) TO Be Determined
COMMENTS	*Discovered by signal from Ray-Che	em leak detector probe.
	-Investigation into leak source	ce is continuimag. Gasoline did not
	enter soll or groundwater; it was containment. Gasoline within sec	s contained within the secondary condary containment removed 12/14/88