ALAMEDA COUNTY HEALTH CARE SERVICES

AGENCY DAVID J. KEARS, Agency Director



State Water Resources Control Board Division of Clean Water Programs UST Local Oversight Program

RAFAT A. SHAHID, Assistant Agency Director

Certified Mail # P367 604 281

07/02/92 STID# 4223 DEPARTMENT OF ENVIRONMENTAL HEALTH Hazardous Materials Division 80 Swan Way, Rm. 200 Oakland, CA 94621 (510) 271-4320

Notice of Requirement to Reimburse

Mr. John Tatum Ninety-eight Ave Associates 1025 98th Ave. Oakland Ca 94603

Responsible Party #1 Property Owner

Ms. Irene Soto Pacific Bell 2600 Camino Ramon 2 E050 San Ramon Ca 94544

Responsible Party #2 Contact Person Contact Company

Pioneer Packing Co. 1031 - 98th Ave. Oakland, CA 94603

SITE

Date First Reported 07/01/86

Substance: Gasoline Petroleum: (X) Yes

The federal Petroleum Leaking Underground Storage Tank Trust Fund (Federal Trust Fund) provides funding to pay the local and state agency administrative and oversight costs associated with the cleanup of releases from underground storage tanks. The legislature has authorized funds to pay the local and state agency administrative and oversight costs associated with the cleanup of releases from underground storage tanks. The direct and indirect costs of overseeing removal or remedial action at the above site are funded, in whole or in part, from the Federal Trust Fund. The above individual(s) or entity(ies) have been indentified as the party or parties responsible for investigation and cleanup of the above site. YOU ARE HEREBY NOTIFIED that pursuant to Title 42 of the United States Code, Section 6991b(h)(6) and Sections 25297.1 and 25360 of the California Health and Safety Code, the above Responsible Party or Parties must reimburse the State Water Resources Control Board not more than 150 percent of the total amount of site specific oversight costs actually incurred while overseeing the cleanup of the above underground storage tank site, and the above Responsible Party or Parties must make full payment of such costs within 30 days of receipt of a detailed invoice from the State Water Resources Control Board.

Please contact Barney CHAN, Hazardous Materials Specialist at this office if you have any questions concerning this matter.

Edgar B. Howell, III, Chief Contract Project Director

cc: Sandra Malos, SWRCB

SWRCB Use:

Add: X Reason: New Case

HEALTH CARE SERVICES

AGENCY



DAVID J. KEARS, Agency Director

Certified Mail # P367604282

07/02/92 STID# 4223 State Water Resources Control Board Division of Clean Water Programs UST Local Oversight Program

RAFAT A. SHAHID, Assistant Agency Director

DEPARTMENT OF ENVIRONMENTAL HEALTH Hazardous Materials Division 80 Swan Way, Rm. 200 Oakland, CA 94621 (510) 271-4320

Notice of Requirement to Reimburse

Mr. John Tatum Ninety-eight Ave Associates 1025 98th Ave. Oakland Ca 94603

Responsible Party #1 Property Owner

Ms. Irene Soto Pacific Bell 2600 Camino Ramon 2 E050 San Ramon Ca 94544

Responsible Party #2 Contact Person Contact Company

Pioneer Packing Co. 1031 - 98th Ave. Oakland, CA 94603

SITE

Date First Reported 07/01/86

Substance: Gasoline Petroleum: (X) Yes

The federal Petroleum Leaking Underground Storage Tank Trust Fund (Federal Trust Fund) provides funding to pay the local and state agency administrative and oversight costs associated with the cleanup of releases from underground storage tanks. The legislature has authorized funds to pay the local and state agency administrative and oversight costs associated with the cleanup of releases from underground storage tanks. The direct and indirect costs of overseeing removal or remedial action at the above site are funded, in whole or in part, from the Federal Trust Fund. The above individual(s) or entity(ies) have been indentified as the party or parties responsible for investigation and cleanup of the above site. YOU ARE HEREBY NOTIFIED that pursuant to Title 42 of the United States Code, Section 6991b(h)(6) and Sections 25297.1 and 25360 of the California Health and Safety Code, the above Responsible Party or Parties must reimburse the State Water Resources Control Board not more than 150 percent of the total amount of site specific oversight costs actually incurred while overseeing the cleanup of the above underground storage tank site, and the above Responsible Party or Parties must make full payment of such costs within 30 days of receipt of a detailed invoice from the State Water Resources Control Board.

Please contact Barney CHAN, Hazardous Materials Specialist at this office if you have any questions concerning this matter.

Edgar B. Howell, III, Chief Contract Project Director

cc: Sandra Malos, SWRCB

SWRCB Use:

Add: X Reason: New Case

UNITED STATES POSTAL SERVICE
OFFICIAL BUSINESS

SENDER INSTRUCTIONS
Print your name, address and ZIP Code in the space below.

• Complete items 1, 2, 3, and 4 on the reverse.

• Attach to front of article if space permits, otherwise affor to back of pericle.

• Endorse article "Return Receipt Required and the reverse.

TO

Print Sender's name, address, and ZIP Code in the space below.

TO

DEPARTMENT OF ENVIRONMENTAL HEALTH

HAZARDOUS MATERIALS DIVISON

BO SWAN WAY, SUITE 200 AND ALLEY AND A

Put your adjess in the "RETURN TO" Space on the revicerd from being returned to you. The return receipt fee will to and the date of delivery. For additional fees the following for fees and check box(es) for additional service(s) reques 1. Show to whom delivered, date, and addressee's a (Extra charge)	erse side. Failure to do this will prevent the provide you the name of the parson delivered agreement of services are available. Consult postmaster aster.
3. Article Addressed to: (BC) #4223	4. Article Number P 367 604 281
Ninety-eight Ave Associates Attn: Mr. John Tatum 1025 98th Avenue Oakland, CA 94603	Type of Service: Registered Insured Certified COD Express Mail Return Receipt for Merchandise Always obtain signature of addressee Or agent and DATE DELIVERED
6. Signature Addless X 6. Signature — Agent	8. Addressee's Address (ONLY if requested and fee paid)
X 7. Date of Delivery	
PS Plan 3011, Mar. 1988 . U.S.G.P.O. 1988-21	2-865 DOMESTIC RETURN CONTROL