

2/1/89 - Spoke to Kent of SCS Engineers. He is going to send me the lab. report of the re-sampling after the additional trenching. I enjoined him they may have to install a monitoring well. He claimed the soil was contaminated by material leaking from the pipe. Bob Bohman of Cactus Valley Fire said the tanks did not have holes in them, and felt with the extent of contamination on that one side wall sample, it could had been when they removed the piping and material leaked out. (Camp etc was not at the site during the removal).

11/12/96 sent draft case closure summary to RWSCB for review & approval.