









Consulting Engineers

P.O. BOX 996 • BENICIA, CA 94510 (707) 746-6915 • (707) 746-6916 • FAX: (707) 746-5581

RECEIVED

10:31 am, Apr 23, 2009

Alameda County Environmental Health

KEI-J89-1106.R8 June 11, 1990

Unocal Corporation 2000 Crow Canyon Place, Suite #400 P.O. Box 5155 San Ramon, CA 94583

Attention: Mr. Ron Bock

Continuing Subsurface Investigation at

Unocal Service Station #3072 2445 Castro Valley Boulevard Castro Valley, California

Dear Mr. Bock:

This report presents the results of our subsurface investigation for the referenced site in accordance with Kaprealian Engineering, Inc's. (KEI) proposal KEI-P89-1106.P2 dated January 8, 1990. The purpose of the investigation was to determine if the subsurface soil and ground water (if encountered) has been impacted at the site. The following work performed by KEI was initiated for the purpose of divestment.

Coordination with regulatory agencies.

Logging and Preparation of Boring Logs for eight exploratory borings.

Soil sampling.

Ground water sampling.

Laboratory analyses.

Data analyses, interpretation and report preparation.

SITE DESCRIPTION AND BACKGROUND

The subject site is presently used as a gasoline station. Α Location Map and Site Plans are attached to this report.

KEI's work at the site began on November 14, 1989, when KEI collected soil samples following the removal of three fuel storage tanks and one waste oil tank at the referenced site. samples (A1, A2, B1, B2, C1 and C2) under the fuel storage tanks were collected at a depth of 13.5 feet. The soil sample (WO1)

. KEI-J89-1106.

KEI-J89-1106.R8
June 11, 1990
Page 2

under the waste oil tank was collected at a depth of 10.5 feet. All soil samples were analyzed by Sequoia Analytical Laboratory in Redwood City, California. The samples under the fuel storage tanks were analyzed for total petroleum hydrocarbons (TPH) as gasoline, and benzene, toluene, xylenes and ethylbenzene (BTX&E). In addition, the two samples from under the diesel tank were analyzed for TPH as diesel. Analytical results showed TPH as gasoline ranging from non-detectable to 11 ppm, with non-detectable BTX&E concentrations in each case. TPH as diesel concentrations were non-detectable for the two diesel tank bottom samples. The soil sample from under the waste oil tank was analyzed for TPH as gasoline, BTX&E, TPH as diesel, total oil and grease (TOG), EPA method 8010, and EPA method 8270 compounds, and the Laboratory analyses metals cadmium, chromium, lead and zinc. showed TPH as gasoline at 5.9 ppm, metals ranging from non-detectable to 45 ppm, 55 ppb of 1,1-dichloroethene, and non-detectable levels of all other constituents analyzed. Analytical results are summarized in Table 2, and sample point locations are shown on the attached Site Plan, Figure 2.

On November 16, 1989, KEI collected six sidewall soil samples, designated as SW1 through SW6, and a water sample, designated as W1, from the fuel tank pit. The tank pit wat measured to be 11.5 feet below the ground surface. The tank pit water level was The sidewall soil samples were collected approximately 6 to 12-inches above the tank pit water level. All samples were analyzed for TPH as Three of the six sidewall soil samples gasoline and BTX&E. (labeled SW2, SW3 and SW4) and the water sample were also analyzed for TPH as diesel. Laboratory analyses of the soil samples showed TPH as gasoline ranging from non-detectable to 29 ppm for four of the six samples, with samples SW1 and SW4 showing 140 and 160 ppm, respectively. TPH as diesel levels were nondetectable for two of the sidewall samples with sample SW4 showing 24 ppm. Analyses of the water sample showed 11,000 ppb TPH as diesel, 26,000 ppb TPH as gasoline, and 670 ppb benzene. Analytical results of the soil samples are summarized in Table 2, and sample point locations are shown on the attached Site Plan, Figure 2.

On November 28, 1989, KEI returned to the site to meet with the representative of the Alameda County Health Care Services (ACHCS) to clarify ACHCS guidelines as applied to the subject site for fuel tank pit excavation and sampling. In response to the meeting, KEI submitted a Phase I work plan (KEI-P89-1106.P1) dated November 30, 1989, to define the extent of contamination in the vicinity of the tank pit. The work plan was approved by the ACHCS in a letter dated December 8, 1989.

î . ē

On December 22, 1989, KEI returned to the site after further excavation to collect additional sidewall soil samples from the fuel tank pit. Soil was excavated from the north, east and south sides of the pit. Sidewall soil samples, designated as SW1(17), SW2(17), SW7, SW8, SW9, SW10, SW11 and SW3(13), were collected at depths of approximately 9 or 11 feet, and analyzed on-site by Mobile Chem Labs, Inc., of Lafayette, California, a state-certified mobile laboratory. After excavation, TPH as gasoline was detected at concentrations of 1,500 and 1,900 ppm on the northerly wall of the pit, at concentrations ranging from 3.0 to 1,700 ppm on the easterly wall, and at 410 ppm on the southerly wall. Analytical results are summarized in Table 3, and sample point locations are shown on the attached Site Plan, Figure 3.

Based on the analytical results, KEI recommended the installation of nine exploratory borings to further define the extent of the soil contamination.

On January 18 and 19, 1990, three two-inch diameter monitoring wells (designated as MW1, MW2 and MW3 on the attached Site Plan) were installed at the site. The monitoring wells were drilled and completed to total depths ranging from 22 to 30 feet. water was encountered at depths ranging from 9 to 20.5 feet beneath the surface during drilling. The wells were developed on January 22 and 23, 1990. Analytical results of the soil samples, collected from the borings for monitoring wells (MW1, MW2 and MW3), indicated non-detectable levels of TPH as gasoline and BTX&E in all soil samples, except for sample MW1(5), which showed 2.8 ppm of TPH as gasoline, 0.051 ppm of benzene, and 0.11 ppm of Analytical results of the ground water samples ethylbenzene. collected from monitoring wells MW2 and MW3 indicated non-detectable levels of TPH as gasoline and BTX&E. In well MW1, TPH as gasoline and benzene were detected at 32 and 4.2 ppb, respective-Analytical results of the soil samples are summarized in Table 6, and water samples in Table 7.

On February 14, 1990, three soil samples, labeled P1, P2 and P3, were collected from the product pipe trenches at depths ranging from 2.5 to 4.0 feet. Analytical results indicate levels of TPH as gasoline ranging from 6.0 to 87 ppm. Results of the soil analyses are summarized in Table 4. Soil sample locations are shown on the attached Site Plan, Figure 4.

KEI returned to the site on March 9, 1990, when three sidewall soil samples, labeled SWB, SWC and SWD, were collected from the sidewalls of the waste oil tank at depths of 8 to 9 feet. The waste oil tank pit had been excavated to a depth of 11 to 12 feet. Analytical results of the soil samples (SWB, SWC and SWD), collected from sidewalls of the waste oil tank pit, indicate non-

र उ

detectable levels of TOG and all EPA 8010 constituents for each of the three samples. Laboratory analyses indicate non-detectable levels of TPH as gasoline and BTX&E for samples SWC and SWD, while SWB showed 37 ppm TPH as gasoline with 0.10 ppm benzene. TPH as diesel levels were non-detectable for sample SWC, with both SWB and SWD less than 10 ppm. Results of the soil samples are summarized in Table 5. Soil sample point locations are shown on the attached Site Plan, Figure 5.

FIELD ACTIVITIES

On April 24 and 25, 1990, eight exploratory borings (designated as EB1 through EB8 on the attached Site Plan, Figure 1) were drilled at the site. Subsurface materials penetrated and the depths at which soil samples were collected are shown in the attached Boring Logs.

The eight borings were drilled and/or sampled to depths of 10-1/2 to 15 feet below grade. Ground water was encountered at depths of approximately 10 to 14 feet beneath the surface in each boring except EB4 where ground water was not encountered. Soil and bedrock samples were collected at a maximum spacing of 5 foot intervals, changes in lithology, obvious areas of contamination and at the soil-bedrock/water table interface beginning at a depth of 5 feet in each of the borings. Undisturbed soil samples collected by driving a California-modified split-spoon sampler ahead of the drilling augers. The clean, two-inch diameter brass tubes holding the samples were sealed with aluminum foil, plastic caps and tape, and stored in a cooled ice chest for delivery to a state certified laboratory. Drilling was generally stopped about one to two feet after intersecting the first water table, except for EB4, which was terminated at a depth of 14.5 feet and ground water was not encountered. A water sample was collected from boring EB5 only, using a clean acrylic The water sample was placed in VOA vials, with Teflonlined screw caps, and labeled and stored in a cooler on ice for delivery to the laboratory. All borings were backfilled to the surface with neat cement.

ANALYTICAL RESULTS

Samples were analyzed at Sequoia Analytical Laboratory in Redwood City, California, and were accompanied by properly executed Chain of Custody documentation. Soil samples from all borings and the water sample from EB5 were analyzed for total petroleum hydrocarbons (TPH) as gasoline using EPA method 5030 in conjunction with modified 8015, and benzene, toluene, xylenes and ethylbenzene (BTX&E) using EPA method 8020. The results of soil analyses are summarized in Table 1, and the results of the water analyses are

summarized in Table 8. Copies of the laboratory analyses and Chain of Custody documentation are attached to this report.

Analytical results of the soil samples, collected from the eight exploratory borings (EB1 through EB8), indicate non-detectable levels of TPH as gasoline in all samples, except EB1(9.5), EB4(14), EB6(5), EB7(5) and EB8(5), in which levels ranged from 1.7 to 5.0 ppm. Benzene was detected in all soil samples and the levels ranged from 0.0053 to 0.023 ppm.

The water sample analysis collected from boring EB5 immediately after drilling indicates a level of TPH as gasoline at 5,900 ppb with a level of benzene at 840 ppb. However, the results of the analyses may not be representative of formation water, and therefore they should be used for information purposes only.

HYDROLOGY AND GEOLOGY

The water table stabilized in the existing monitoring wells at depths ranging from 7.35 to 9.00 feet below the surface as measured on March 22, 1990. The ground water flow direction appeared to be to the northeast on March 22, 1990, (based on water level data collected from the three monitoring wells). Ground water flow direction is shown on the attached Site Plan, Figure 1.

Based on review of regional geologic maps (U.S. Geological Survey Open-File Report 80-540 "Preliminary Geologic Map of the Hayward Quadrangle, Alameda and Contra Costa Counties, California" by T.W. Dibblee, Jr., 1980), the subject site is underlain by Quaternary-age alluvium. Mapped bedrock outcrops adjacent to the site include the marine Panoche Formation (Kpc), which is described as a conglomerate generally composed of granite, dioritie, quartzite and black chert cobbles in a sandstone matrix and the Knoxville Formation (JKk), which is described as consisting of dark micaceous shale with minor thin sandstone.

Also, the site is situated approximately 3,000 feet northeast of the mapped trace of the active Hayward Fault; 1,900 feet southwest of the concealed mapped trace of the East Chabot Fault; and 1,800 feet northeast of the mapped trace (northern terminous?) of the West Chabot Fault.

As exposed in the underground tank pit excavation, the earth materials at the subject site consist of artificial fill materials at the surface which are typically 1 to 2 feet thick, and locally vary up to a maximum of about 9 feet at the east wall of the pit excavation. These fill materials are in turn underlain by dark gray silty clay soil materials, which are about 2.5 feet

\$ 5

thick. The soil materials are underlain by greenish-brown to yellowish brown highly weathered to slightly weathered shale, which varies from soft to moderately hard with abundant fractures (both clay healed and relatively open).

The results of the drilling activities at the site indicate that bedrock materials underlying the site are composed of brown and gray shale, which is slightly to highly weathered. The depth to the bedrock materials appears to vary considerably from about 5 to 6 feet below grade in the vicinity of well MW1 and boring EB2, to about 21-1/2 feet in the vicinity of well MW2, to greater than 22 feet in the vicinity of well MW3 (maximum depth explored). However, bedrock commonly underlies that site at a depth of about 10 feet as encountered in the majority of the borings at the site and exposures in the old tank pit excavation.

RECOMMENDATIONS

Based on the analytical results, KEI recommends the installation of two additional monitoring wells to further define the extent of ground water contamination. In addition, KEI recommends the implementation of monthly monitoring and quarterly sampling of the existing monitoring wells. KEI's proposal for this work is attached for your review and consideration.

DISTRIBUTION

A copy of this report should be sent to Alameda County Health Care Services, and to the Regional Water Quality Control Board, San Francisco Bay Region.

LIMITATIONS

Soil deposits and rock formations may vary in thickness, lithology, saturation, strength and other properties across any site. In addition, environmental changes, either naturally-occurring or artificially-induced, may cause changes in the extent and concentration of any contaminants. Our studies assume that the field and laboratory data are reasonably representative of the site as a whole, and assume that subsurface conditions are reasonably conducive to interpolation and extrapolation.

€ . 😘

The results of this study are based on the data obtained from the field and laboratory analyses obtained from a state certified laboratory. We have analyzed this data using what we believe to be currently applicable engineering techniques and principles in the Northern California region. We make no warranty, either expressed or implied, regarding the above, including laboratory analyses, except that our services have been performed in accordance with generally accepted professional principles and practices existing for such work.

Should you have any questions regarding this report, please feel free to call me at (707) 746-6915.

No. 1310

ENGINEERING

Sincerely,

Kaprealian Engineering, Inc.

Don R. Braun

Certified Engineering Geologist

License No. 1310 Exp. Date 6/30/90

Mo Kym

Mardo Kaprealian President

jad

Attachments:

Tables 1 through 8

Location Map

Site Plans - Figures 1 through 5

Boring Logs

Laboratory Results

Chain of Custody documentation

Proposal

仓 . 办

TABLE 1
SUMMARY OF LABORATORY ANALYSES
SOIL

(Collected on April 24 and 25, 1990)

Sample <u>Number</u>	TPH as <u>Gaso</u> line	<u>Benzene</u>	<u>Toluene</u>	<u>Xylenes</u>	Ethylbenzene
EB1(5)	ND	0.0063	0.042	0.011	ND
EB1(9.5)	4.9	0.0078	0.24	0.11	0.028
EB1(13.5)	ИD	0.0087	0.048	ND	ND
EB2(5)	ND	0.0053	0.020	0.013	0.0068
EB2(10)	ND	0.0059	0.026	0.013	0.0050
EB3 (5)	ND	0.0069	0.031	0.017	ND
EB3 (9)	ND	0.0093	0.023	ND	ND
EB4 (5)	ND	0.0091	0.034	ND	ND
EB4(10)	ND	0.0090	0.27	ND	ND
EB4 (14)	1.7	0.0079	0.43	ND	ND
EB5(5)	ND	0.0095	0.015	ND	ND
EB6(5)	5.0	0.066	0.021	0.11	0.032
EB6(10)	ND	0.0086	0.060	0.014	0.0052
EB6(13)	ND	0.0080	0.16	0.24	0.0092
EB7(5)	3.0	0.040	0.056	0.073	0.034
EB7 (9.5)	ND	0.0081	0.078	0.025	0.015
EB7(13.5)	ND	0.0054	0.085	0.012	ND
EB8 (5)	2.7	0.023	0.067	0.078	0.013
EB8 (10)	ND	0.0072	0.056	0.019	0.0050
Detection					
Limits	1.0	0.0050	0.0050	0.0050	0.0050

ND = Non-detectable.

蛋 . 哦

TABLE 2
SUMMARY OF LABORATORY ANALYSES
SOIL

(Collected on November 14 & 16, 1989)

<u>Sample</u>	Depth (feet)	TPH as <u>Diesel</u>	TPH as <u>Gasoline</u>	<u>Benzene</u>	<u>Toluene</u>	<u>Xylenes</u>	Ethyl- <u>benzene</u>
A1	13.5	ND	2.4	ND	ND	ND	ND
A2	13.5	ND	ND	ND	ND	ND	ND
B1	13.5		1.9	ND	ND	ND	ND
B2	13.5		11	ND	ND	ND	ND
C1	13.5		1.5	ND	ND	ND	ND
C2	13.5		7.5	ND	ND	ND	ND
SW1	10.5		140	0.31	0.12	3.0	0.88
SW2	10.5	ND	ND	ND	ND	ND	ND
SW3	10.5	ND	ND	ND	ND	ND	ND
SW4	9.5	24	160	0.33	6.4	30	9.4
SW5	9.5		3.5	0.06	0.27	0.76	0.19
SW6	10		29	0.12	0.21	2.0	0.58
WO1(11)	* 11	ND	5.9	ND	ND	ND	ND
Detection Limits	on	1.0	1.0	0.05	0.1	0.1	0.1

^{*} TOG and all 8270 constituents were non-detectable. All 8010 constituents were non-detectable except 1,1-dichloroethene at 55 ppb. Metals concentrations were as follows: cadmium 2.5 ppm, chromium 39 ppm, lead 1.1 ppm, and zinc 45 ppm.

ND = Non-detectable.

\$: T

TABLE 3
SUMMARY OF LABORATORY ANALYSES
SOIL

(Collected on December 22, 1989)

Sample	Depth (feet)	TPH as <u>Diesel</u>	TPH as <u>Gasoline</u>	Benzene Toluene		Xylenes	Ethyl- benzene
SW1(17)	11	ND	1,900	14	24	120	28
SW2(17)	11	ND	1,500	17	29	92	23
SW7	9	ND	1,700	16	33	110	26
SW8	9	ND	200	2.6	0.9	7.7	5.0
SW3(13)	9	ND	690	11	11	28	11
SW9	9	ИD	3.0	0.2	0.1	0.1	ND
SW10	9	ND	500	4.0	5.9	22	6.9
SW4(11)	9	ND	410	2.7	3.9	19	3.8
Detection Limits	on	1.0	1.0	0.1	0.1	0.1	0.1

ND = Non-detectable.



TABLE 4 SUMMARY OF LABORATORY ANALYSES SOIL

(Collected on February 14, 1990)

<u>Sample</u>	Depth (feet)	TPH as <u>Gasoline</u>	<u>Benzene</u>	<u>Toluene</u>	Xylenes	<u>Ethylbenzene</u>
P1	4.0	87	0.33	0.17	10	2.3
P2	2.5	6.0	0.23	ND	0.33	0.11
Р3	3.0	10	0.47	0.11	1.1	0.32
Detec Limit		1.0	0.05	0.1	0.1	0.1

ND = Non-detectable.

TABLE 5 SUMMARY OF LABORATORY ANALYSES SOIL

(Collected on March 9, 1990)

<u>Sample</u>	Depth <u>(feet)</u>	TPH as <u>Diesel</u>	TPH as <u>Gasoline</u>	<u>Benzene</u>	<u>Toluene</u>	Xylenes	Ethyl- <u>benzene</u>
SWB*	8.0	<10	37	0.10	0.10	0.74	0.25
SWC*	9.0	ND	ND	ND	ND	ND	ND
SWD*	9.0	<10	ND	ND	ND	ND	ND
Detecti Limits	on	1.0	1.0	0.05	0.1	0.1	0.1

^{*} TOG levels and concentrations of all EPA 8010 constituents were non-detectable.

ND = Non-detectable.

TABLE 6 SUMMARY OF LABORATORY ANALYSES SOIL

(Collected on January 18, 1990)

-	Depth <u>(feet)</u>	TPH as <u>Gasoline</u>	<u>Benzene</u>	<u>Toluene</u>	<u>Xylenes</u>	Ethylbenzene
MW1(5)	5.0	2.8	0.051	ND	ND	0.11
MW1(6.5)	6.5	ND	ND	ND	ND	ND
MW1(10.0) 10.0	ND	ND	ND	ND	ND
(m)				\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\		175
MW2(5)	5.0	ND	ND	ND	ND	ND
MW2(6.5)	6.5	ND	ND	ND	ND	ND
MW2(9.0)	9.0	ND	ND	ND	ND	ND
MW2(10)	10.0	ND	ND	ND	ND	ND
MW2(15)	15.0	ND	ND	ND	ND	ND
MW2(16.5		ND	ND	ND	ND	ND
MW2 (20)	20.0	ИD	ND	ИD	ИД	ИД
1670 /E)	5 0	ND	MD	ND	ND	ND
MW3 (5)	5.0	ND	ND	ND	ND	ND
MW3(6.5)		ND	ND	ND	ND	ND
MW3(9)	9.0	ND	ND	ND	ND	ND
Detectio	n					
Limits		1.0	0.05	0.1	0.1	0.1

ND = Non-detectable.

TABLE 7 SUMMARY OF LABORATORY ANALYSES WATER

(Samples collected on March 22, 1990)

Sample <u>Number</u>	TPH as <u>Gasoline</u>	<u>Benzene</u>	<u>Toluene</u>	<u>Xylenes</u>	<u>Ethylbenzene</u>
MW1	32	4.2	ND	1.1	0.36
MW2	ND	ND	ND	ND	ND
ММЗ	ND	ND	ND	ND	ND
MW4*	ND	ND	ND	ND	ND
Detecti Limits	on 30	0.3	0.3	0.3	0.3

ND = Non-detectable.

*Sample MW4 is a duplicate of sample MW2.

Results in parts per billion (ppb), unless otherwise indicated.

T. . 18

4i, . • ii.

TABLE 8

SUMMARY OF LABORATORY ANALYSES WATER

(Collected on April 25, 1990)

Sample <u>Number</u>	TPH as <u>Gasoline</u>	<u>Benzene</u>	<u>Toluene</u>	Xylenes	Ethylbenzene
EB6	5,900	840	34	73	100
Detection Limits	n 30	0.3	0.3	0.3	0.3

Results in parts per billion (ppb), unless otherwise indicated.

Water samples were collected during drilling. The results of the analyses may not be representative of formation water, they should be used for information only. NOTE:








Consulting Engineers

P.O. BOX 996 • BENICIA, CA 94510 (707) 746-6915 • (707) 746-6916 • FAX: (707) 746-5581



LOCATION MAP

Unocal Service Station #3072 2445 Castro Valley Blvd. Castro Valley, California










Consulting Engineers

P.O. BOX 996 • BENICIA, CA 94510 (707) 746-6915 • (707) 746-6916 • FAX: (707) 746-5581



Ground Water Flow Direction

Ground Water Elevation in feet (MSL) on 3/22/90.

Unocal Service Station #3072 2445 Castro Valley Blvd. Castro Valley, California








Consulting Engineers

P.O. BOX 996 • BENICIA, CA 94510 (707) 746-6915 • (707) 746-6916 • FAX: (707) 746-5581



LEGEND

* Sample Point Location

Unocal S/S #3072 2445 Castro Valley Blvd. Castro Valley, CA








Consulting Engineers

P.O. BOX 996 • BENICIA, CA 94510 (707) 746-6915 • (707) 746-6916 • FAX: (707) 746-5581



LEGEND

* Sample Point Location

Unocal S/S #3072 2445 Castro Valley Blvd. Castro Valley, CA








Consulting Engineers

PO. BOX 996 • BENICIA, CA 94510 (707) 746-6915 • (707) 746-6916 • FAX: (707) 746-5581



LEGEND

* Sample Point Location



Unocal Service Station # 3072 2445 Castro Valley Blvd. Castro Valley, California








Consulting Engineers

PO. BOX 996 • BENICIA, CA 94510 (707) 746-6915 • (707) 746-6916 • FAX: (707) 746-5581



LEGEND

* Sample Point Location



Unocal Service Station # 3072 2445 Castro Valley Blvd. Castro Valley, California



BORING LOG										
Project No. KEI-P89-110				Во	ring 1	Diameter "	Logged By D.L.			
Project Nan Castro Val		ocal	We	ell H	ead E	levation	Date Drilled 4/25/90			
Boring No. EB1						Hollow-stem Auger	Drilling Company EGI			
Penetration blows/6"	G. W. level	Depth (feet Samp)	t) graphy		phy	Description				
					THE THE PARTY OF T		over fill consisting of ad gravel, moist.			
		 _	_			Fill is very mo	oist at 3.5 feet.			
14/24/37		5		CL/ CH		shale fragment hard, moist, d olive, cementa	gravel consisting of is to 1-1/2" diameter, lark greenish gray and ition.			
19/24/34		— 10 — —		N/A			ely hard, fractured, I, decomposed and clayey			
27/45/50-4"		_ _ _	뷬			Shale, as above becoming harde	e, less weathered, er with depth.			
27/36/50-2 1/2"	₹	— 15 — - 15 —				Wet at 14 feet.				
	:	 20	\dashv	:			TH DRILLED: 13.5' TH SAMPLED: 15'			



		BORING LOG										
Project No. KEI-P89-110				Boring Diameter			Logged By D.L.					
Project Nam Castro Vali		ocal	We	ell H	ead E N/A	levation	Date Drilled 4/25/90					
Boring No. EB2				rilli		Hollow-stem Auger	Drilling Company EGI					
Penetration blows/6"	G. W. level	Depth (feet	t) graphy			Description						
							underlain by fill clay, sand and gravel.					
				CL/ CH			very stiff, moist, very vel consists entirely ents.					
21/42/50		- 5 - - -		N/A		Shale, hard, sl	PROCK————————————————————————————————————					
16/32/29 19/27/39	<u> </u>	— — — 10				Shale, as above weathered than	e, moist to wet, less a above.					
19/2//39			Н									
		— 15 — - — - — — — — — — — — — — — — — — — —										
		20					TH DRILLED: 12' TH SAMPLED: 13.5'					





	BORING LOG										
Project No KEI-P89-11			i	В	oring 8	Diameter Logged By D.L.					
	Project Name Unocal Well Head El N/A						Date Drilled 4/25/90				
Boring No. EB3				rilli ethod		Hollow-stem Auger	Drilling Company EGI				
Penetration blows/6#	G. W. level	Samp1	t)	gra		Desc	Description				
:		0					underlain by fill clay, sand and gravel.				
5/26/30		 5		CL/ CH			ilt, 5% sand and gravel ter, stiff, moist, very				
				GC CL/ CH		<pre>moist, olive k angular shale tine?.</pre>	vith sand, very dense, brown, gravel is mostly framents, trace serpen- nd, very stiff, moist,				
15/21/32	<u> Ā</u>	_ _ _ 10		GC		Clayey gravel w	vith sand, very dense, wet, yellowish brown.				
							PTH DRILLED: 9'PTH SAMPLED: 10.5'				





				во	RII	NG LOG		
Project No. KEI-P89-110				Во	ring 1	Diameter	Logged By D.L.	
Project Nam Castro Vall		ocal	We	ell H	ead E	levation	Date Drilled 4/24/90	
Boring No. EB4			rilli ethod		Hollow-stem Auger	Drilling Company EGI		
Penetration blows/6"	etration G. W. Dept ws/6" level (fee Samp			gra		Description		
	N O T	- - -		<u> </u>			underlain by fill clay, sand and gravel.	
	E N C	<u> </u>		CL/ CH			d, very stiff, moist, vish brown to black.	
15/23/46	оиитекер р			GC		moist, olive b	with sand, very dense, prown, gravel is en- maybe bedrock weathered	
49/50-3" 50-5 3/4"	U R I N G	10 10				Shale, hard, sl	BEDROCK fractured ightly moist, fractured clay-lined fractures,	
25/41/50-5 1/2"	D R I L						: 12 feet to olive gray, easing with depth.	
50-2"	L N G	15 		-			ing at 14 feet.	
		— 20					TH SAMPLED: 14.5'	

				BORI	NG LOG						
Project No KEI-P89-11				Borin	g Diameter 8"						
Project Na Castro Val		ocal	We]	ll Head N/	Elevation A	Date Drilled 4/25/90					
Boring No. EB5	-			illing thod	Hollow-stem Auger	Drilling Company EGI					
Penetration blows/6"	G. W. level	Samp1	t)	Strati- graphy USCS		escription					
		- O		69775	A. C. Pavemer	nt					
10/10/11 10/9/8 7/6/8		5		GP/ SP	road and ut	and fill, 5-10% fines, lity trench backfill.					
12/33/50		10 15 15 20		N/A	Shale, modera fractured, of fractures, of fr	BEDROCK Stely hard, moist, Secomposed with clay-lined olive to olive gray. DEPTH DRILLED: 9.5' DEPTH SAMPLED: 11'					



BORING LOG												
Project No KEI-P89-110				В		Diameter 8"	Logged By D.L.					
Project Nan Castro Val		ocal	We	ell H	ead E	levation	Date Drilled 4/24/90					
Boring No. EB6				rilli ethod		Hollow-stem Auger	Drilling Company EGI					
Penetration blows/6"	G. W. level	Depth (feet Samp	!)	gra		Desc	cription					
							underlain by fill sand and gravel.					
7/11/15		5		CH/		Clay, 5-10% sand, 5-10% gravel to 3/4" diameter, very stiff, moist, black.						
21/33/45		— 10 —		N/A			BEDROCK ightly moist to moist, thered with clay-lined we brown.					
45/50-4"	<u> </u>	_ _ _					e, less weathered than ss increasing with depth					
50-3 1/4"		— 15 —					TH DRILLED: 14' TH SAMPLED: 14.5'					



BORING LOG												
Project No. KEI-P89-110				В		Diameter 3"	Logged By D.L.					
Project Nam Castro Val		ocal	We		ead Ei N/A	levation	Date Drilled 4/24/90					
Boring No. EB7						Hollow-stem Auger	Drilling Company EGI					
Penetration blows/6"	G. W. level	Samp]	:)	gra		Description						
		0				A. C. Pavement gravel baserod	underlain by sand and k.					
6/12/21		5		CL/ CH		Clay, 5-10% sand and gravel to 3 diameter, very stiff, moist, bl lensed with greenish gray parti cemented layers below 5 feet, c ed layers have blocky texture (caliche?).						
5/50 30/49/50 - 5"		- - - - -		N/A		Shale, hard, sl	DROCK ightly moist to moist, thered with clay-lined ve brown.					
30/45/30 3		_	Н									
50-5 1/2"												
50~5"	₽	15 					TH DRILLED: 13.5' TH SAMPLED: 14'					



BORING LOG											
Project No. KEI-P89-116				В		Diameter 8"	Logged By D.L.	DRB			
Project Nan Castro Val		ocal	We	ell H	ead E N/A	levation	Date Drille	ed			
Boring No. EB8				rilli		Hollow-stem Auger	Drilling Company EGI				
Penetration blows/6"	netration G. W. Dept ows/6" level (fee Sam				ati- phy S	Desc	Description				
						A. C. Pavement gravel baseroo		sand and			
11/13/20				CL/		Clay, 10-20% sa diameter, very At 5 feet, blac with locally s blocky texture 6 feet. Color change at	stiff, mois k and greeni trong cement e, greenish g	st, black. sh gray, ation, gray below			
11/25/40	<u> </u>	10 		N/A		Shale, moderate weathered, fra	to black. BEDROCK Shale, moderately hard, moist, very weathered, fractured, clay-lined fractures, olive to olive brown.				
30/41/47											
		_ _ _ 20					TH DRILLED:	12' 13.5'			



P.O. Box 996

Benicia, CA 94510 Attention: Mardo Kaprealian, P.E. Client Project ID:

Matrix Descript: Analysis Method:

First Sample #:

Unocal, Castro Valley, 2445 C V Blvd.

Soil EPA 5030/8015/8020

004-3689

Analyzed:

Sampled: Apr 24-25, 1990

Received:

Apr 26, 1990 May 7, 1990

Reported: May 9, 1990

TOTAL PETROLEUM FUEL HYDROCARBONS with BTEX DISTINCTION (EPA 8015/8020)

Sample Number	Sample Description	Low/Medium B.P. Hydrocarbons mg/kg (ppm)	Benzene mg/kg (ppm)	Toluene mg/kg (ppm)	Ethyl Benzene mg/kg (ppm)	Xylenes mg/kg (ppm)	
004-3689	EB1 (5)	N.D.	0.0063	0.042	N.D.	0.011	
004-3690	EB1 (9.5)	4.9	0.0078	0.24	0.028	0.11	
004-3691	EB1 (13.5)	N.D.	0.0087	0.048	N.D.	N.D.	
004-3692	EB2 (5)	N.D.	0.0053	0.020	0.0068	0.013	
004-3693	EB2 (10)	N.D.	0.0059	0.026	0.0050	0.013	
004-3694	EB3 (5)	N.D.	0.0069	0.031	N.D.	0.017	
004-3695	EB3 (9)	N.D.	0.0093	0.023	N.D.	N.D.	
004-3696	EB4 (5)	N.D.	0.0091	0.034	N.D.	N.D.	
004-3697	EB4 (10)	N.D.	0.0090	0.27	N.D.	N.D.	
004-3698	EB4 (14)	1.7	0.0079	0.43	N.D.	N.D.	
Detection Limits	3:	1.0	0.0050	0.0050	0.0050	0.0050	

Low to Medium Boiling Point Hydrocarbons are quantitated against a gasoline standard. Analytes reported as N.D. were not present above the stated limit of detection.

SEQUOIA ANALYTICAL

Belinda C. Vega Project Manager

43689.KEi <1>



P.O. Box 996

Benicia, CA 94510

Attention: Mardo Kaprealian, P.E.

Client Project ID:

Matrix Descript:

First Sample #:

Unocal, Castro Valley, 2445 C V Blvd. Soil

EPA 5030/8015/8020

Analysis Method: 004-3699 Sampled:

Apr 24-25, 1990

Received:

Apr 26, 1990

Analyzed: Reported: May 7, 1990 May 9, 1990

TOTAL PETROLEUM FUEL HYDROCARBONS with BTEX DISTINCTION (EPA 8015/8020)

Sample Number	Sample Description	Low/Medium B.P. Hydrocarbons mg/kg (ppm)	Benzene mg/kg (ppm)	Toluene mg/kg (ppm)	Ethyl Benzene mg/kg (ppm)	Xylenes mg/kg (ppm)
004-3699	EB5 (5)	N.D.	0.0095	0.015	N.D.	N.D.
004-3701	EB6 (5)	5.0	0.066	0.021	0.032	0.11
004-3702	EB6 (10)	N.D.	0.0086	0.060	0.0052	0.014
004-3703	EB6 (13)	N.D.	0.0080	0.16	0.0092	0.24
004-3704	EB7 (5)	3.0	0.040	0.056	0.034	0.073
004-3705	EB7 (9.5)	N.D.	0.0081	0.078	0.015	0.025
004-3706	EB7 (13.5)	N.D.	0.0054	0.085	N.D.	0.012
004-3707	EB8 (5)	2.7	0.023	0.067	0.013	0.078
004-3708	EB8 (10)	N.D.	0.0072	0.056	0.0050	0.019

						 -
Detection Limits:	1.0	0.0050	0.0050	0.0050	0.0050	
1						

Low to Medium Boiling Point Hydrocarbons are quantitated against a gasoline standard. Analytes reported as N.D. were not present above the stated limit of detection.

SEQUOIA ANALYTICAL

Belinda C. Vega Project Manager



Samos				()			RE & ADDRESS	AMALYSES BEQLESTED					TURN ARGUNO TIME:		
WITHESSING A	CENCY (<u> </u>	 				Castro Vallex Valley Blvd.						Regular		
SAIPLE ID NO.		TIES	2 01r 	 water g	 RAB CO	#0. Of #P CONT.	SAMPLING LOCATION	T-H-G	BIXE	1			REMARKS		
FB1-(5)	4-26.90		1	1 1	/ !	1 ,	See Sample I.D. #				 		0043689		
BI- (9.5)			1] !	V!	! ,	.)	1	v!				690		
B1- (13.5)			1 1/		v!	! /		! /	V!				1 691		
£B 2 - (S)	1	· · · · · · · · · · · · · · · · · · ·	· /	 	v	! /		1	1				692		
=B2-(10)	: :		1	1	v!	1 /		10				1	693		
e _{B3} -(5)	1		1 /		v!	! ,		/	V	!			694		
(g) - (g)	, ,		/		1	1,	/	! 1/	1 //	!	.		695		
:B4- (5)	1 6	<u></u>	V	 	1	- - -		V	1 0			ļ.	1 696		
=159= (3) =B4= 10	1 1		1 /	+ +	v!	! /		1	1 - 1				697		
ender in	or; (Sig	nature)	1 .	26/90	so		ed by: (Signature). Ly M' Lary]	for anal	ysis:			y the laboratory accepting samples analysis been stored in ice?		
Telinquish o	m fa		4/2	490	241	Received by: (Signature) 2. Will samples remain refrigerated						<u> </u>			
tel inquished	lby: {\$19	nature)	i/ •	late/Time		Receiv	ed by: (Signeture)	3. Did any samples received for analysis have head space?							
lel Papushed	1 by: (519	nature)		late/lim	; 	In-	ed (Storatore)	4. were samples in appropriate containers and property packaged 1 2							



SMOLES						E & ADDRESS		AHAL VSE:	TURN AROUND TIKE:		
UITHESSING A	CENCY (- - - -			Castro Valley Castro Valley Blud.				<u>Regular</u>	
SAMPLE ID NO.		TIRE	50 1L	LATER GRAB	USO.	SAMPLING LOCATION	 TPH-G	10 1 × F		REMARKS	
134-(14)	 				1)	Secsample I.D. *	V	V		0043698	
'B5-(5)	1 1				! ,		1/	1/		699	
BS - (10)	, i				! ,		V	1 /		List hall too	
BG- 5	: :		1 /	V	! ,		1/	1 /		701	
BE (10)	ii		! /	V	! ,		1			702	
BE -(13)		,	1	<i>V</i>	,		i/			703	
в 7 - (S)	: :		! 1/	V	! ,		1/	V		704	
B7 (9.5)	1		1 /		1 ,	1	!V	121		705	
	4.24-90		 	 _/	- 		IV			706	
on inquisited	(ME)	nature)	17/-	ate/Time 7490	<u> /_e</u>	ed by: (Signature) by Mr Lo ed by: (Signature)	j 	for analysis	ed by the laboratory accepting samples for analysis been stored in ice?		
Tame	Mola	,	14/2	1 1201		Zernh / -	2. Will samples remain refrigerated until analyzed?				
el inquished			7 /	ate/lime _	Receiv	ed by: (Signature)	3. Did any samples received for analysis have head space?				
	i by: (Sig	gnature)	0	ate/Time	Receiv	ed by: (Signature)	4. were samples in appropriate containers and property package of the samples of the sample of the samples of t				
	, · ·		 		 		1 catgnature fitte Date				

SAMPLER	SAMPLER							E & ASORESS		A	HAL YSI	s BEQ	ESTED			TURN AROUND TIKE:
MITHESSING	ACENCY	<u> </u>	− i	Unocal - Castro Valley 2445 Castro Valley Blvd.												Regular I
SAMPLE ID NO.	 DATE	Ties	soir 	 WIER	 GAAB	cos	DF CO::17.	SAMPLING LOCATION	7- HJL	BIXE					 	REMARKS
EB8-5			V	 	1/		-	See boring I.D. #	V	1/		 		 	 	0043708
EB8-10	4/25/90			i — I I —	 	 	-					 	 	 	├ 	1 1
		! 	<u> </u>	 	 	 	 		 	 		 	 	 	 	1 1 1
 	1	 	1] 	 	 		1			 	 	 		, 1 -{ 1
	- 	 	- 	; 	; 	i 	 	 	- 	 		 	 	 	 	4
Ret inquishe	(لاقدا)		4/	pate/Ti	9 J	^ટ ¦ +—	Tin	ed by: (Signature) M! fc ed by: (Signature)	 	for a	wlysi	6:		/		the laboratory accepting samples malysis been stored in ice?
Tem-	mr fa	ii.	14/2	26/9	70		Se.	ud //	2. Will samples remin refri				<u></u>		i	
1	letinguished by: (Signature) Date/fime Received by: (Signature)				 	_				10		halysis have head space?				
``	d by: (Si	gnature)	1 1	ate/Ti	me:		Received by: ·(Signature)								111e 7/26/90	





Kaprealian Engineering, Inc. Client Project ID: Unocal, Castro Valley, 2445 Castro Valley Blvd Sampled: Apr 25, 1990 P.O. Box 996 Sample Descript.: Water, EB5-W Received: Apr 26, 1990 Benicia, CA 94510 Analysis Method: EPA 5030/8015/8020 Analyzed: Apr 26, 1990 Attention: Mardo Kaprealian, P.E. Lab Number: 004-3688 Reported: Apr 30, 1990

TOTAL PETROLEUM FUEL HYDROCARBONS WITH BTEX DISTINCTION (EPA 8015/8020)

Analyte	Detection Limit	Sample Results
	<i>µ</i> g/L (ppb)	μg/L (ppb)

Low to Medium B	loiling Point I	lydrocarbor	1\$	3,00)		•••••	5,900	
Benzene	**********	**************		30)		******	840	
Toluene	*************	********		3()	*******		34	
Ethyl Benzene				31	·			100	
Xylenes	**************			3(·			73	

Low to Medium Boiling Point Hydrocarbons are quantitated against a gasoline standard.

Analytes reported as N.D. were not present above the stated limit of detection. Because matrix effects and/or other factors required additional sample dilution, detection limits for this sample have been raised.

SEQUOIA ANALYTICAL

Belinda C. Vega Project Manager



MITHESSING AGENCY			İ	Unccal - Castro Valley 2445 Castro Valley Blvd.					; 	Α	HAL YSE	S DEQU	ESTED			TURN AROUND TIME:	
			-						1 1		ļ	 	 	! !		Regular	
SAMPLE ID NO.	DATE	TIME	201r 	 WATER	 GRAB	 COMP	NO. OF CONT.	SAMPLING LOCATION	7PH-6	BIXE			1	 		REMARKS	
FBS-W	4-25-96		1	\\ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \		\ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \	2									004368AB	
Relinquished by: (Signature) Relinquished by: (Signature) Date/fine Relinquished by: (Signature) Date/fine Relinquished by: (Signature) Date/fine				8	leng Mi Jang				nalysi eve al ill sa id any	the laboratory accepting samples malysis been stored in ice? d until analyzed? malysis have head space? malysis have head space? malysis have head space? malysis have head space?							