

The Hertz Corporation 225 Brae Boulevard, Park Ridge, NJ 07656

Via Certified Mail

Return Receipt Requested

July 8, 2011

Mr. Keith Matthews Oakland Fire Department 250 Frank H. Ogawa Plaza, Suite 3341 Oakland, CA 94614

Re:

Gasoline Release Hertz Rent-A-Car 8000 Earhart Road Oakland, CA 94621

Dear Mr. Matthews:

Attached please find the Underground Storage Tank Unauthorized Release (Leak)/contamination Site Report for the gasoline release at the above referenced site. As previously discussed, the source of the release has been repaired and response actions are ongoing.

If you have any questions, or require additional information, I may be reached at (201) 307-2526 or via e-mail at tegan@hertz.com.

Sincerely,

Timothy B. Egan

Sr. Program Manager

Environmental Compliance & Remediation

cc:

Barbara Cook, Department of Toxic Substance Control Max Shahbazian, San Francisco Bay Regional Water Quality Board United States Environmental Protection Agency, Region 9 Oil Program Donna Drogos, Alameda County Health Care Services Agency Dale Klettke, Port of Oakland

Neale Bedrock, The Hertz Corporation

ELEM HE TOTAL HOW

| UNDERGROUND STORAGE TANK UNAUTHORIZED RELEASE (LEAK) / CONTAMINATION SITE REPORT | | | |
|---|--|---|-----------------------------------|
| EMERGENCY HAS STATE OFFICE OF EMERGENCY SERVICES FOR LOCAL AGENCY USE ONLY REPORT BEEN FILED? TYPES NO. HEREBY CERTIFY THAT I AM A DESIGNATED GOVERNMENT EMPLOYEE AND THAT I HAVE | | | |
| | ORT DATE CASE # | REPORTED THIS INFORMATION TO LOCAL OFFICIAL THE HEALTH AND SAFETY CODE. | LS PURSUANT TO SECTION 25180.7 OF |
| 7/5/ | /2011 11-4019 | | |
| | NAME OF INDIVIDUAL FILING REPORT PHONE | SIGNATURE SIGNATURE | DATE |
| ≿ | Timothy Egan (201) 3 | 307-2526 | 3.2 |
| REPORTED BY | ☐ LOCAL AGENCY ☐ REGIONAL BOARD | COMPANY OR AGENCY NAME The Hertz Corporation | |
| | Ø OWNER/OPERATOR ☐ OTHER ADDRESS | The Head Corporation | |
| | 225 Brae Blvd | Park Ridge | NJ 07656 |
| w _y | STREET NAME | CONTACT PERSON | STATE ZIP PHONE |
| RESPONSIBLE PARTY | The Hertz Corporation Unknown | Timothy Egan | (201) 307-2526 |
| ESPO | | Park Ridge | NJ 07656 |
| Œ | | CITY | STATE ZIP |
| SITE LOCATION | Hertz Rent-A-Car | OPERATOR The Hertz Corporation | PHONE (510) 639-0200 |
| | ADDRESS | | |
| | STREET | Oakland Alameda county | 94621 zip |
| | CROSS STREET Langley Street | | |
| <u> </u> | LOCAL AGENCY AGENCY NAME | | PHONE |
| TING | Oakland Fire Department | | (510) 238-3927 |
| IMPLEMENTING AGENCIES | REGIONAL BOARD | | PHONE |
| IMPL A | San Francisco Bay Regional Water Qualtilty Contro | ol Board | (510) 622-4824 |
| ļ | (1) NAME | | TY LOST (GALLONS) |
| NCES | Gasoline | 2,000 | |
| SUBSTANCES INVOLVED | (2) | | |
| ļ | | | Unknown |
| MENT | DATE DISCOVERED HOW DISCOVERED Tank To | | Nuisance Conditions |
| Y/ABATEMENT | DATE DISCHARGE BEGAN | ory Control Subsurface Monitoring METHOD USED TO STOP DISCHARGE (CHECK | Other K ALL THAT APPLY) |
| | 6/28/2011 | Remove Contents Close Tank | · |
| DISCOVER | HAS DISCHARGE BEEN STOPPED? | Repair Tank Change Proced | lure . |
| | YES NO IF YES, DATE 7/2/2011 | Repair Piping | |
| SOURCE/ CAUSE | SOURCE OF DISCHARGE CAUSE(S) | | |
| ర్లో | | I ☐ Corrosion ☒ Rupture/Failure ☐ Unkr | nown Spill Other |
| CASE TYPE | CHECK ONE ONLY | | |
| | ☑ Undetermined ☐ Soil Only ☐ Groundwater ☐ Drinking Water – (CHECK ONLY IF WATER WELLS HAVE ACTUALLY BEEN AFFECTED) | | |
| = | CHECK ONE ONLY No Action Taken | ase Closed (Cleanup Completed or Unnecess | san/1 |
| CURRENT | ☐ Leak Being Confirmed ☐ Po | ollution Characterization ost Cleanup Monitoring in Progress | |
| S C | ☐ Preliminary Site Assessment Workplan Submitted ☐ CI | leanup Underway | |
| | Preliminary Site Assessment Underway CHECK APPROPRIATE ACTION(S) | | |
| REMEDIAL ACTION | ☐ Cap Site (CD) ☐ Excavate & Treat (ET) ☐ Contamination Barrier (CB) ☐ No Action Required (NA) | ☐ Treatment At Hookup (HU)☐ Enhanced Bio Degradation (IT) | ☐ Other |
| REM | ☐ Vacuum Extract (VE) ☐ Remove Free Product (FP) ☐ Replace Supply (RS) | | |
| | ☐ Excavate & Dispose (ED) ☐ Pump & Treat Groundwater (GT) | | ~ |
| COMMENTS | Subject site is hybrid system with aboveground tank and und gasoline detected in discharge, later traced to oil water sepa | arator and ultimately to a vacant dispe- | enser position. Ongoing |
| MME | remedial actions to date consist of exploratory excavation and recovery of approximately 900 gallons gasoline from piping | | |
| ñ | trench. Additional response/remediation is ongoing. Hazardous Material Incident Report is being prepared for submittal to | | |