

The Hertz Corporation 225 Brae Boulevard, Park Ridge, NJ 07656

> Via Certified Mail Return Receipt Requested

July 8, 2011

Mr. Keith Matthews Oakland Fire Department 250 Frank H. Ogawa Plaza, Suite 3341 Oakland, CA 94614

Re:

Gasoline Release Hertz Rent-A-Car 8000 Earhart Road Oakland, CA 94621

Dear Mr. Matthews:

Attached please find the Underground Storage Tank Unauthorized Release (Leak)/contamination Site Report for the gasoline release at the above referenced site. As previously discussed, the source of the release has been repaired and response actions are ongoing.

If you have any questions, or require additional information, I may be reached at (201) 307-2526 or via e-mail at tegan@hertz.com.

Sincerely,

Timothy B. Egan

Sr. Program Manager

Environmental Compliance & Remediation

cc:

Barbara Cook, Department of Toxic Substance Control

Max Shahbazian, San Francisco Bay Regional Water Quality Board United States Environmental Protection Agency, Region 9 Oil Program

Donna Drogos, Alameda County Health Care Services Agency

Dale Klettke, Port of Oakland

Neale Bedrock, The Hertz Corporation

UNDERGROUND STORAGE TANK UNAUTHORIZED RELEASE (LEAK) / CONTAMINATION SITE REPORT						
EMERGENCY HAS STATE OFFICE OF EMERGENCY SERVICES			FOR LOCAL AGENCY USE ONLY I HEREBY CERTIFY THAT I AM A DESIGNATED GOVERNMENT EMPLOYEE AND THAT I HAVE			
	☐ Yes ☐ No REPORT BEEN FILED? ☐ Yes ☐ No		⊠ No	REPORTED THIS INFORMATION TO LOCAL OFFICIALS PURSUANT TO SECTION 25180.7 OF		
REPORT DATE CASE #				THE HEALTH AND SAFETY CODE.		
7/5/	5/2011 11-4019			SIGNED		DATE
	NAME OF INDIVIDUAL FILING REPORT		PHONE	Orottes	SIGNATURE	5 9
REPORTED BY	Timothy Egan		(201) 3	07-2526		3
	REPRESENTING			COMPANY OR AGENCY NAME		
	☐ LOCAL AGENCY ☐ REGION OWNER/OPERATOR ☐ OTHE		The Hertz C	The Hertz Corporation		
3EPC	ADDRESS					
	225 Brae Blvd			Park Ric	lge	NJ 07656 STATE ZIP
SITE LOCATION RESPONSIBLE PARTY	STREET NAME			CONTACT PERSO	ON	PHONE.
	The Hertz Corporation Unknown			Timothy Egan		(201) 307-2526
	ADDRESS					
				Park Ridge CITY LOPERATOR		NJ 07656
	STREET FACILITY NAME (IF APPLICABLE)					STATE ZIP PHONE
	Hertz Rent-A-Car			The Hertz Corporation		(510) 639-0200
	ADDRESS					
	8000 Earhart Road			Oakland	Alameda	94621
	CROSS STREET			CITY	COUNTY	ZiP
	Langley Street					
IMPLEMENTING AGENCIES	LOCAL AGENCY AGENCY NAME				PHONE	
	Oakland Fire Department				(510) 238-3927	
					PHONE	
	REGIONAL BOARD					
	San Francisco Bay Regional Water Qualtilty Control Board (510) 622-4824					
SUBSTANCES	(1) NAME QUANTITY LOST (GALLONS)					
	Gasoline 2,000 Unknown					
	(2)					
	☐ Unknown					
DISCOVERY/ABATEMENT	DATE DISCOVERED	HOW DISCOVERED	Tank	Test	Tank Removal	Nuisance Conditions
	7/2/2011			ory Control	Subsurface Monitoring	Other
	DATE DISCHARGE BEGAN				O STOP DISCHARGE (CHECK	(ALL THAT APPLY)
	6/28/2011 DUNKNOWN			Remove Contents Close Tank Repair Tank Change Procedure Replace Tank Other Repair Plping		
OVE	HAS DISCHARGE BEEN STOPPED?					
DISC						
SOURCE	☐ Tank Leak ☑ Piping Leak ☐ Unknown ☐ Other ☐ Overfill ☐ Corrosion ☒ Rupture/Failure ☐ Unk					nown Spill Other
တ္တပ						
CASE	CHECK ONE ONLY					
3 F	☐ Undetermined ☐ Soil Only ☐ Groundwater ☐ Drinking Water – (CHECK ONLY IF WATER WELLS HAVE ACTUALLY BEEN AFFECTED)					
CURRENT	CHECK ONE ONLY Case Closed (Cleanup Completed or Unnecessary)					
	☐ Leak Being Confirmed ☐ Case Closed (Clearible Completed of Office Cessary)					
	☐ Remediation Plan ☐ Post Cleanup Monitoring in Progress					
	☐ Preliminary Site Assessment Workplan Submitted ☐ Cleanup Underway ☐ Preliminary Site Assessment Underway					
REMEDIAL ACTION	CHECK APPROPRIATE ACTION(S)					
	☐ Cap Site (CD) ☐ Excavate & Treat (ET) ☐ Treatment At Hookup (HU)					Olher
	☐ Contamination Barrier (CB) ☐ No Action Required (NA) ☐ Enhanced Bio Degradation (IT) ☐ Vacuum Extract (VE) ☐ Remove Free Product (FP) ☐ Replace Supply (RS)					
	Excavate & Dispose (ED) Pump & Treat Groundwater (GT) Vent Soil (VS)					
w	Subject site is hybrid system with aboveground tank and undergound piping. Release identified by Sewer District based on					
ENT	gasoline detected in discharge, later traced to oil water separator and ultimately to a vacant dispenser position. Ongoing					
COMMENTS	remedial actions to date consist of exploratory excavation and recovery of approximately 900 gallons gasoline from piping trench. Additional response/remediation is ongoing. Hazardous Material Incident Report is being prepared for submittal to					
0	the OES.					