



1647 International Blvd., Oakland, CA
3/2/2016, B Jakub
Adding dry ice to lower LEL

03/02/2016 15




03/02/2016 15



1647 International Blvd., Oakland, CA
3/2/2016, B Jakub
Pulling tank





1647 International Blvd., Oakland, CA
3/2/2016, B Jakub
Side of building along 17th Ave.



1647 International Blvd., Oakland, CA
3/2/2016, B Jakub
placing tank on plastic for cleaning



1647 International Blvd., Oakland, CA
3/2/2016, B Jakub
Scooping out material from beneath tank
(greenish gray stained soil)

03/02/2016 16



1647 International Blvd., Oakland, CA
3/2/2016, B Jakub
First soil sample

03/02/2016 16



1647 International Blvd., Oakland, CA
3/2/2016, B Jakub
Stained soil from beneath tank

03/02/2016 16



03/02/2016 16



1647 International Blvd., Oakland, CA
3/2/2016, B Jakub
Side of tank

03/02/2016 16



1647 International Blvd., Oakland, CA
3/2/2016, B Jakub
Soil showing signs of staining

03/02/2016 16



1647 International Blvd., Oakland, CA
3/2/2016, B Jakub
Side of tank



1647 International Blvd., Oakland, CA
3/2/2016, B Jakub
Cleaning tank for cutting



1647 International Blvd., Oakland, CA
3/2/2016, B Jakub
Soil from 11.5 feet still showing signs of staining.

03/02/2016 16