Wickham, Jerry, Env. Health

To:

Friel, Ana

Cc:

denis.l.brown@shell.com

Subject: RE: 3420 San Pablo Ave, Oakland - RO 0006; Request for 30-day Extension for Report

Ana,

Based upon your request, the schedule for report submittal for case RO0006 is extended to December 15, 2006.

Regards,

Jerry Wickham

Hazardous Materials Specialist

Alameda County Environmental Health

1131 Harbor Bay Parkway

Suite 250

Alameda, CA 94502-6577

510-567-6791 phone

510-337-9335 Fax

jerry.wickham@acgov.org

From: Friel, Ana [mailto:afriel@cambria-env.com] Sent: Wednesday, October 25, 2006 2:33 PM

To: Wickham, Jerry, Env. Health Cc: denis.l.brown@shell.com

Subject: 3420 San Pablo Ave, Oakland - RO 0006; Request for 30-day Extension for Report

Jerry,

In your work plan approval letter dated June 29, 2006, you requested that the subsurface investigation report for the proposed work be submitted to your office by November 3, 2006. Owing to scheduling difficulties and then laboratory delays, we just received the soil data report this week, and have not yet received the soil vapor report.

Please also be aware that the laboratory failed to analyze the soil vapor samples within the 72-hour recommended hold time, but did analyze them and will provide a report.

Because of the late receipt of analytical data (and some still pending, but expected any time now), on behalf of Shell, we respectfully request a 30-day extension for preparation and submittal of our technical report from November 3 to December 4, 2006.

We appreciate your understanding and consideration of this request.

Ana Friel, PG Associate Geologist Cambria Environmental Technology, Inc.

408 7th Street, Suite A, Eureka, CA 95501 afriel@cambria-env.com p (707) 268-3812 f (707) 268-8180 c (707) 845-4066

This e-mail may contain confidential and privileged material for the sole use of the intended recipient. Any review or distribution by others is strictly



DAVID J. KEARS, Agency Director





ENVIRONMENTAL HEALTH SERVICES

ENVIRONMENTAL PROTECTION 1131 Harbor Bay Parkway, Suite 250 Alameda, CA 94502-6577 (510) 567-6700 FAX (510) 337-9335

June 29, 2006

Denis Brown Shell Oil Products US 20945 S. Wilmington Ave. Carson, CA 90810-1039

Shahriar Almasi Portola Valley Shell 965 Laurel Glen Drive Palo Alto, CA 94304

Subject: Fuel Leak Case No. RO0000006, Shell#13-9619, 3420 San Pablo Avenue, Oakland, CA – Work Plan Approval

Dear Denis Brown and Shahriar Almasi:

Alameda County Environmental Health (ACEH) staff has reviewed the fuel leak case file for the above referenced site and the document entitled, "Site Investigation Work Plan," dated June 22, 2006, prepared on your behalf by Cambria Environmental Technology, Inc. The Work Plan proposes three soil borings to evaluate the lateral and vertical extent of elevated lead concentrations in shallow soil near former dispensers and three soil borings to collect soil gas samples near the station building. We concur with the proposed scope or work.

We request that you perform the proposed work and send us the reports described below.

TECHNICAL REPORT REQUEST

Please submit technical reports to Alameda County Environmental Health (Attention: Mr. Jerry Wickham), according to the following schedule:

- August 15, 2006 Quarterly Monitoring Report for the Second Quarter 2006
- November 3, 2006 Subsurface Investigation Report
- November 15, 2006 Quarterly Monitoring Report for the Third Quarter 2006

These reports are being requested pursuant to California Health and Safety Code Section 25296.10. 23 CCR Sections 2652 through 2654, and 2721 through 2728 outline the responsibilities of a responsible party in response to an unauthorized release from a petroleum UST system, and require your compliance with this request.

Denis Brown Shahriar Almasi June 29, 2006 Page 2

ELECTRONIC SUBMITTAL OF REPORTS

Effective January 31, 2006, the Alameda County Environmental Cleanup Oversight Programs (LOP and SLIC) require submission of all reports in electronic form to the county's ftp site. Paper copies of reports will no longer be accepted. The electronic copy replaces the paper copy and will be used for all public information requests, regulatory review, and compliance/enforcement activities. Instructions for submission of electronic documents to the Alameda County Environmental Cleanup Oversight Program ftp site are provided on the attached "Electronic Report Upload (ftp) Instructions." Please do not submit reports as attachments to electronic mail.

Submission of reports to the Alameda County ftp site is an addition to existing requirements for electronic submittal of information to the State Water Resources Control Board (SWRCB) Geotracker website. Submission of reports to the Geotracker website does not fulfill the requirement to submit documents to the Alameda County ftp site. In September 2004, the SWRCB adopted regulations that require electronic submittal of information for groundwater cleanup programs. For several years, responsible parties for cleanup of leaks from underground storage tanks (USTs) have been required to submit groundwater analytical data, surveyed locations of monitor wells, and other data to the Geotracker database over the Internet. Beginning July 1, 2005, electronic submittal of a complete copy of all necessary reports was required in Geotracker (in PDF format). Please visit the SWRCB website for more information on these requirements (http://www.swrcb.ca.gov/ust/cleanup/electronic reporting).

PERJURY STATEMENT

All work plans, technical reports, or technical documents submitted to ACEH must be accompanied by a cover letter from the responsible party that states, at a minimum, the following: "I declare, under penalty of perjury, that the information and/or recommendations contained in the attached document or report is true and correct to the best of my knowledge." This letter must be signed by an officer or legally authorized representative of your company. Please include a cover letter satisfying these requirements with all future reports and technical documents submitted for this fuel leak case.

PROFESSIONAL CERTIFICATION & CONCLUSIONS/RECOMMENDATIONS

The California Business and Professions Code (Sections 6735, 6835, and 7835.1) requires that work plans and technical or implementation reports containing geologic or engineering evaluations and/or judgments be performed under the direction of an appropriately registered or certified professional. For your submittal to be considered a valid technical report, you are to present site specific data, data interpretations, and recommendations prepared by an appropriately licensed professional and include the professional registration stamp, signature, and statement of professional certification. Please ensure all that all technical reports submitted for this fuel leak case meet this requirement.

UNDERGROUND STORAGE TANK CLEANUP FUND

Please note that delays in investigation, later reports, or enforcement actions may result in your becoming ineligible to receive grant money from the state's Underground Storage Tank Cleanup Fund (Senate Bill 2004) to reimburse you for the cost of cleanup.

Denis Brown Shahriar Almasi June 29, 2006 Page 3

AGENCY OVERSIGHT

If it appears as though significant delays are occurring or reports are not submitted as requested, we will consider referring your case to the Regional Board or other appropriate agency, including the County District Attorney, for possible enforcement actions. California Health and Safety Code, Section 25299.76 authorizes enforcement including administrative action or monetary penalties of up to \$10,000 per day for each day of violation.

If you have any questions, please call me at (510) 567-6791.

Sincerely,

Jerry Wickham, P.G.

Hazardous Materials Specialist

Enclosure: ACEH Electronic Report Upload (ftp) Instructions

cc: Ana Friel

Cambria Environmental Technology, Inc.

270 Perkins Street Sonoma, CA 95476

Donna Drogos, ACEH Jerry Wickham, ACEH

File

ALAMEDA COUNTY HEALTH CARE SERVICES

AGENCY





ENVIRONMENTAL HEALTH SERVICES ENVIRONMENTAL PROTECTION 1131 Harbor Bay Parkway, Suite 250 Alameda, CA 94502-6577

(510) 567-6700 FAX (510) 337-9335

April 14, 2006

Denis Brown Shell Oil Products US 20945 S. Wilmington Ave. Carson, CA 90810-1039

Shahriar Almasi Portola Valley Shell 965 Laurel Glen Drive Palo Alto, CA 94304

Subject: Fuel Leak Case No. RO0000006, Shell#13-9619, 3420 San Pablo Avenue, Oakland, CA

Dear Denis Brown and Shahriar Almasi:

Alameda County Environmental Health (ACEH) staff has reviewed the fuel leak case file for the above referenced site and the report entitled, "Groundwater Monitoring Report – First Quarter 2006, Water Leak Investigation, and Risk Evaluation," dated March 28, 2006, prepared on your behalf by Cambria Environmental Technology, Inc. The report provides a summary of first quarter 2006 groundwater monitoring activities, a single groundwater extraction event from well MW-6R, a water leak investigation, and a screening-level risk evaluation. The report also includes recommendations to decommission well MW-8 and prepare a Work Plan to conduct soil vapor sampling around the on-site station building.

We request that you address the following technical comments, perform the proposed work, and send us the reports described below.

TECHNICAL COMMENTS

- Soil Vapor Sampling. ACEH concurs with the recommendation to conduct soil vapor sampling in the area of the on-site station building due to elevated concentrations of fuel hydrocarbons detected in groundwater and the intermittent presence of separate phase hydrocarbons in well MW-6R. Please propose a scope of work to collect soil vapor samples in the Work Plan requested below.
- 2. Lead in Soil. Lead was detected at a concentration of 2,000 milligrams per kilogram (mg/kg) in a soil sample (P-7-2.0) collected beneath the former dispenser island along 35th Street. The "Groundwater Monitoring Report First Quarter 2006, Water Leak Investigation, and Risk Evaluation," dated March 28, 2006 suggests that the lead is not the result of a fuel release. However, this conclusion appears to be based on the detection of relatively low concentrations of TPHg and BTEX in soil sample P-7-2.0. It is also possible that a significant historic release of leaded gasoline occurred in the area of soil sample P-7-2.0 and that the low concentrations of purgeable and volatile fuel hydrocarbons in the soil sample are due to

Denis Brown Shahriar Almasi April 14, 2006 Page 2

the effects of aging. The highest concentrations of TPHg in groundwater have been detected along 35th Street. The dispensers and product line are the only apparent source of fuel hydrocarbons in this area of the site. We request that you propose additional soil borings to define the lateral and vertical extent of lead in the area of the former dispenser island and product line. Please propose the borings in the Work Plan requested below.

- 3. **Well Decommissioning**. ACEH concurs with the recommendation to decommission well MW-8. Please present documentation of the well decommissioning in the Subsurface Investigation Report requested below.
- 4. Hydraulic Gradient and Plume Stability. Groundwater mounding in the interior and northwestern portions of the site have not allowed clear definition of groundwater flow directions across the site. The uncertainty in groundwater flow directions and the potential for multiple releases from different areas of the site also make it difficult to assess plume stability. Elevated concentrations of TPHg continue to be detected in groundwater monitoring well MW-10, which is the only off-site well in a downgradient direction. During the first five groundwater sampling events following installation of well MW-10 (October 1991 to October 1992), the concentration of TPHg detected in groundwater from well MW-10 ranged from 3,000 to 27,000 micrograms per liter (μg/L). During the most recent groundwater sampling event on January 24, 2006, the concentration of TPHg in groundwater from well MW-10 was 6,110 μg/L. Please continue quarterly groundwater monitoring in order to evaluate plume stability and the effects of past water line leaks on apparent hydraulic gradient.

TECHNICAL REPORT REQUEST

Please submit technical reports to Alameda County Environmental Health (Attention: Mr. Jerry Wickham), according to the following schedule:

- May 15, 2006 Quarterly Monitoring Report for the Second Quarter 2006
- June 30, 2006 Work Plan for Subsurface Investigation
- August 15, 2006 Quarterly Monitoring Report for the Third Quarter 2006

These reports are being requested pursuant to California Health and Safety Code Section 25296.10. 23 CCR Sections 2652 through 2654, and 2721 through 2728 outline the responsibilities of a responsible party in response to an unauthorized release from a petroleum UST system, and require your compliance with this request.

ELECTRONIC SUBMITTAL OF REPORTS

Effective January 31, 2006, the Alameda County Environmental Cleanup Oversight Programs (LOP and SLIC) require submission of all reports in electronic form to the county's ftp site. Paper copies of reports will no longer be accepted. The electronic copy replaces the paper copy and will be used for all public information requests, regulatory review, and compliance/enforcement activities. Instructions for submission of electronic documents to the Alameda County

Denis Brown Shahriar Almasi April 14, 2006 Page 3

Environmental Cleanup Oversight Program ftp site are provided on the attached "Electronic Report Upload (ftp) Instructions." Please do not submit reports as attachments to electronic mail.

Submission of reports to the Alameda County ftp site is an addition to existing requirements for electronic submittal of information to the State Water Resources Control Board (SWRCB) Geotracker website. Submission of reports to the Geotracker website does not fulfill the requirement to submit documents to the Alameda County ftp site. In September 2004, the SWRCB adopted regulations that require electronic submittal of information for groundwater cleanup programs. For several years, responsible parties for cleanup of leaks from underground storage tanks (USTs) have been required to submit groundwater analytical data, surveyed locations of monitor wells, and other data to the Geotracker database over the Internet. Beginning July 1, 2005, electronic submittal of a complete copy of all necessary reports was required in Geotracker (in PDF format). Please visit the SWRCB website for more information on these requirements (http://www.swrcb.ca.gov/ust/cleanup/electronic reporting).

In order to facilitate electronic correspondence, we request that you provide up to date electronic mail addresses for all responsible and interested parties. Please provide current electronic mail addresses and notify us of future changes to electronic mail addresses by sending an electronic mail message to me at jerry.wickham@acgov.org.

PERJURY STATEMENT

All work plans, technical reports, or technical documents submitted to ACEH must be accompanied by a cover letter from the responsible party that states, at a minimum, the following: "I declare, under penalty of perjury, that the information and/or recommendations contained in the attached document or report is true and correct to the best of my knowledge." This letter must be signed by an officer or legally authorized representative of your company. Please include a cover letter satisfying these requirements with all future reports and technical documents submitted for this fuel leak case.

PROFESSIONAL CERTIFICATION & CONCLUSIONS/RECOMMENDATIONS

The California Business and Professions Code (Sections 6735, 6835, and 7835.1) requires that work plans and technical or implementation reports containing geologic or engineering evaluations and/or judgments be performed under the direction of an appropriately registered or certified professional. For your submittal to be considered a valid technical report, you are to present site specific data, data interpretations, and recommendations prepared by an appropriately licensed professional and include the professional registration stamp, signature, and statement of professional certification. Please ensure all that all technical reports submitted for this fuel leak case meet this requirement.

UNDERGROUND STORAGE TANK CLEANUP FUND

Please note that delays in investigation, later reports, or enforcement actions may result in your becoming ineligible to receive grant money from the state's Underground Storage Tank Cleanup Fund (Senate Bill 2004) to reimburse you for the cost of cleanup.

Denis Brown Shahriar Almasi April 14, 2006 Page 4

AGENCY OVERSIGHT

If it appears as though significant delays are occurring or reports are not submitted as requested, we will consider referring your case to the Regional Board or other appropriate agency, including the County District Attorney, for possible enforcement actions. California Health and Safety Code, Section 25299.76 authorizes enforcement including administrative action or monetary penalties of up to \$10,000 per day for each day of violation.

If you have any questions, please call me at (510) 567-6791.

Sincerely,

Jerry Wickham, P.G.

Hazardous Materials Specialist

Enclosure: ACEH Electronic Report Upload (ftp) Instructions

cc: Ana Friel
Cambria Environmental Technology, Inc.
270 Perkins Street
Sonoma, CA 95476

Donna Drogos, ACEH Jerry Wickham, ACEH File **AGENCY**



DAVID J. KEARS, Agency Director

ENVIRONMENTAL HEALTH SERVICES

ENVIRONMENTAL PROTECTION 1131 Harbor Bay Parkway, Suite 250 Alameda, CA 94502-6577 (510) 567-6700 FAX (510) 337-9335

January 19, 2006

Denis Brown Shell Oil Products US 20945 S. Wilmington Ave. Carson, CA 90810-1039

Shahriar Almasi Portola Valley Shell 965 Laurel Glen Drive Palo Alto, CA 94304

Scanned already upirade

Subject: Fuel Leak Case No. RO0000006, Shell#13-9619, 3420 San Pablo Avenue, Oakland, CA

Dear Denis Brown and Shahriar Almasi:

Alameda County Environmental Health (ACEH) staff has reviewed the fuel leak case file for the above referenced site and the report entitled, "Site Conceptual Model," dated December 19, 2005, prepared on your behalf by Cambria Environmental Technology, Inc. The Site Conceptual Model report provides a summary of environmental activities and conditions for the former Shell site and includes information on the former Thrift Oil service station at 3400 San Pablo Avenue in Oakland. The report includes the following recommendations:

- Shell continue joint groundwater monitoring with the adjacent Thrifty site,
- Thrifty survey its monitoring wells to a Geotracker acceptable datum,
- Shell investigate possible water leaks, landscape irrigation, sanitary sewer, and storm drains as sources of the observed periodic groundwater mounding,
- Shell complete a screening level risk evaluation.

ACEH concurs with the above recommendations and requests that you submit a screening level risk evaluation that includes results from the investigation of possible water leaks by March 31, 2006. ACEH requests that you address the following technical comments, perform the proposed work, and send us the reports described below.

TECHNICAL COMMENTS

- 1. Cross Sections. The three cross sections prepared for the site clearly illustrate site conditions and are highly useful for data interpretation.
- 2. Vertical Extent of Contamination. Based on the continuous layers of fine-grained soils in the upper 25 feet and evidence from the soil borings that contamination decreases with depth, ACEH concurs that further investigation of the vertical extent of contamination is not needed.

Denis Brown Shahriar Almasi January 19, 2006 Page 2

TECHNICAL REPORT REQUEST

Please submit technical reports to Alameda County Environmental Health (Attention: Mr. Jerry Wickham), according to the following schedule:

- February 15, 2006 Quarterly Monitoring Report for the Fourth Quarter 2005
- March 31, 2006 Screening Level Risk Evaluation (to include results of investigation of possible water leaks)
- May 15, 2006 Quarterly Monitoring Report for the First Quarter 2006

These reports are being requested pursuant to California Health and Safety Code Section 25296.10. 23 CCR Sections 2652 through 2654, and 2721 through 2728 outline the responsibilities of a responsible party in response to an unauthorized release from a petroleum UST system, and require your compliance with this request.

ELECTRONIC SUBMITTAL OF REPORTS

Effective January 31, 2006, the Alameda County Environmental Cleanup Oversight Programs (LOP and SLIC) require submission of all reports in electronic form to the county's ftp site. Paper copies of reports will no longer be accepted. The electronic copy replaces the paper copy and will be used for all public information requests, regulatory review, and compliance/enforcement activities. Instructions for submission of electronic documents to the Alameda County Environmental Cleanup Oversight Program ftp site are provided on the attached "Electronic Report Upload (ftp) Instructions." Please do not submit reports as attachments to electronic mail.

Submission of reports to the Alameda County ftp site is an addition to existing requirements for electronic submittal of information to the State Water Resources Control Board (SWRCB) Geotracker website. Submission of reports to the Geotracker website does not fulfill the requirement to submit documents to the Alameda County ftp site. In September 2004, the SWRCB adopted regulations that require electronic submittal of information for groundwater cleanup programs. For several years, responsible parties for cleanup of leaks from underground storage tanks (USTs) have been required to submit groundwater analytical data, surveyed locations of monitor wells, and other data to the Geotracker database over the Internet. Beginning July 1, 2005, electronic submittal of a complete copy of all necessary reports was required in Geotracker (in PDF format). Please visit the SWRCB website for more information on these requirements (http://www.swrcb.ca.gov/ust/cleanup/electronic_reporting).

In order to facilitate electronic correspondence, we request that you provide up to date electronic mail addresses for all responsible and interested parties. Please provide current electronic mail addresses and notify us of future changes to electronic mail addresses by sending an electronic mail message to me at jerry.wickham@acgov.org.

PERJURY STATEMENT

All work plans, technical reports, or technical documents submitted to ACEH must be accompanied by a cover letter from the responsible party that states, at a minimum, the following. "I declare, under penalty of perjury, that the information and/or recommendations contained in the

Denis Brown Shahriar Almasi January 19, 2006 Page 3

attached document or report is true and correct to the best of my knowledge." This letter must be signed by an officer or legally authorized representative of your company. Please include a cover letter satisfying these requirements with all future reports and technical documents submitted for this fuel leak case.

PROFESSIONAL CERTIFICATION & CONCLUSIONS/RECOMMENDATIONS

The California Business and Professions Code (Sections 6735, 6835, and 7835.1) requires that work plans and technical or implementation reports containing geologic or engineering evaluations and/or judgments be performed under the direction of an appropriately registered or certified professional. For your submittal to be considered a valid technical report, you are to present site specific data, data interpretations, and recommendations prepared by an appropriately licensed professional and include the professional registration stamp, signature, and statement of professional certification. Please ensure all that all technical reports submitted for this fuel leak case meet this requirement.

UNDERGROUND STORAGE TANK CLEANUP FUND

Please note that delays in investigation, later reports, or enforcement actions may result in your becoming ineligible to receive grant money from the state's Underground Storage Tank Cleanup Fund (Senate Bill 2004) to reimburse you for the cost of cleanup.

AGENCY OVERSIGHT

If it appears as though significant delays are occurring or reports are not submitted as requested, we will consider referring your case to the Regional Board or other appropriate agency, including the County District Attorney, for possible enforcement actions. California Health and Safety Code, Section 25299.76 authorizes enforcement including administrative action or monetary penalties of up to \$10,000 per day for each day of violation.

If you have any questions, please call me at (510) 567-6791.

Sincerely,

Jerry Wickham, P.G.

Hazardous Materials Specialist

Enclosure: ACEH Electronic Report Upload (ftp) Instructions

cc: Matthew Derby, Cambria Environmental Technology, Inc., 5900 Hollis Street, Suite A Emeryville, CA 94608

Ana Friel, Cambria Environmental Technology, Inc., 270 Perkins Street, Sonoma, CA 95476

Donna Drogos, ACEH Jerry Wickham, ACEH File


CAMBRIA

April 28, 2005

Ms. Roseanna Garcia-La Grille Alameda County Health Care Services Agency 1131 Harbor Bay Parkway, Suite 250 Alameda, California 94502-6577

Re: Record Fee Title Owner for:

Shell-branded Service Station 3420 San Pablo Avenue Oakland, California Incident # 98995748





Dear Ms. Garcia-La Grille:

In accordance with section 25297.15(a) of Chapter 6.7 of the California Health and Safety Code and on behalf of Equilon Enterprises LLC dba Shell Oil Products US (Shell), we are providing you with the name of the current record fee title owner (and address) for the above referenced site.

Shahriar Almasi and Azita Almasi, 965 Laurel Glen Drive, Palo Alto, CA 94304

Sincerely,

Cambria Environmental Technology, Inc.

Ana Friel

Senior Project Geologist

cc: Denis Brown, Shell Oil Products US, 20945 S. Wilmingtion Ave., Carson, CA 90810 Shahriar Almasi and Azita Almasi, 965 Laurel Glen Drive, Palo Alto, CA 94304

Cambria Environmental Technology, Inc.

270 Perkins Street Sonoma, CA 95476 Tel (707) 935-4850 Fax (707) 935-6649

ALAMEDA COUNTY HEALTH CARE SERVICES

AGENCY



DAVID J. KEARS, Agency Director

March 9, 2004

Ms. Karen Petryna Shell Oil Products US 20945 S. Wilmington Ave. Carson, CA 90810 ENVIRONMENTAL HEALTH SERVICES
ENVIRONMENTAL PROTECTION
1131 Harbor Bay Parkway, Suite 250

Alameda, CA 94502-6577 (510) 567-6700 FAX (510) 337-9335

Dear Ms. Petryna:

Subject: Fuel Leak Case RO0000006, 3420 San Pablo Ave., Oakland, 94608

Alameda County Environmental Health has reviewed the case file for the subject site, including the January 15, 2004 Fourth Quarter 2003 Monitoring Report from Cambria Environmental. We request that a FS/CAP be prepared for this site. We also request that you address the following technical comments.

TECHNICAL COMMENTS

- 1. Although free product is observed only in MW-6R, elevated dissolved TPHg, BTEX and MTBE is present site-wide and has migrated off-site. Free product has been observed in MW 1, 5 and 7 in the past. The site has been monitored since 1991 and dissolved TPHg concentrations remain elevated in the higher impacted wells. This is indicative of a continuing on-going releases and/or the lack of natural bio-degradation.
- 2. The extent of the petroleum release has not been determined either laterally or vertically. Off-site wells MW-9 and MW-10 recently detect up to 7100 ppb TPHg, 20 ppb benzene and 180 ppb MTBE. MW-5, located within twenty feet of the former Thrifty Oil (current ARCO) service station reported 7500 ppb TPHg and 63 ppb MTBE in the 4th Quarter 2003 QMR. It is likely that the plumes from these two sites have commingled. It is recommended that these sites co-ordinate sampling events and provide cross-sectional plots including both sites.
- 3. Historic remediation at the sites has only consisted of free product removal, by bailing and skimmers, and the former UST removals. The 1994 SVE test concluded that this remediation method appears to be a viable approach and vapor extraction piping was installed beneath the onsite building for potential future use.
- 4. The July 2001 Sensitive Receptor and Utilities Survey concluded that utilities within San Pablo Ave. could be acting as preferential pathways, however, no further investigation was proposed. We recommend that you review results from investigations of the 3400 San Pablo Ave. site, to help determine if additional investigation is warranted. The presence of 7100 ppb TPHg in MW-10 recently, indicates that the utilities are not effectively controlling the plume migration.
- 5. As an interim RAP, our office concurs with your proposal to perform groundwater extraction from the site prior to the next sampling event. We recommend extraction from all elevated TPH impacted wells and consider additional extraction events based upon your future monitoring results.

Ms. Karen Petryna RO0000006, 3420 San Pablo Ave., Oakland, 94608 March 9, 2004 Page 2 of 2

TECHNICAL REPORT REQUEST

• April 12, 2004- Provide your written response to the technical comments above.

You may contact me at (510) 567-6765 if you have any questions.

Sincerely,

Barney M. Chan

Hazardous Materials Specialist

Bornes M Che

C: B. Chan, D. Drogos

Mr. Matt Derby, Cambria Environmental, 5900 Hollis St., Suite A, Emeryville, CA 94608

Mr. Mike Bowery, Thrifty Oil Co., 13116 Imperial Highway, Santa Fe Springs,

CA 90670-0138

3400SanPabloAve3_8_04

To:





Company: **ACDEHS** Fax: 510-337-9335 Phone: 510-567-6780

Susan Hugo

From:	Ian Young	
Phone:	510-420-3305; Fax 510 420-9170	
Pages:	3	
Date:	2/13/01	
Re:	DWR Driller's Reports Request Authorization	

Fax

Susan,

Enclosed, please find the Request Authorizations for the following sites:

- 1) 2800 Telegraph Rd., Oakland CA
- 2) 3420 San Pablo Ave., Oakland CA 2000


Please fax the forms back to me when you have completed them. I appreciate your assistance, and thank you for your help with these projects. Spring Journal Marsh

lan Young

Sinecrel

Staff Geologist

Cambria Environmental Technology, Inc. 1144 65th Street Suite B Oakland, CA 94508 Tel (510) 420-0700 Fax (510) 420-9170



WELL DRILLER'S REPORTS INSPECTION REQUEST AND AGREEMENT

Project: Former 5/2/15000	sea Station
Location: 3420 5 Poblo As	
County: Alemado	Contract Number:
Request is made pursuant to Section 13751 or inspect or copy Water Well Driller's Reports which	f the California Water Code for permission to th are on file in your office.
In accordance with the requirements of Section agreed that such reports, or any copy or copies inspection by the public but will be used sold studies. If copies are made or taken, each cop OFFICIAL USE ONLY" and will be kept in a restrof this governmental agency or to its contracted agents must be returned to the Department completion of work by the contracted agent.	s made thereof, will not be made available for ely by this governmental agency for making by will be stamped "CONFIDENTIAL" or "FOR ficted file, access to which is limited to the staff agents. Any copies furnished to contracted
No information contained in these reports can be permission of the owner of the well. In Young — Cambria	ALLE DIE
In Young - Combris Contracted Agent 1144 65th St. Suita B	1131 Harbor Bry Parkway, 2nd Floor
Oakland CA 94608	Alamada A 94502 City, State, & Zip Code
By City State, 8) Zipt Gode Officer State Gaelegist	City, State, & Zip Code ByOfficer
Title (7) (510) 420 - 3305 Telephone	Title
2/13/01 Date	Telephone Date

(For Departmental Information: _____copies sent ____

ALAMEDA COUNTY HEALTH CARE SERVICES

AGENCY



DAVID J. KEARS, Agency Director

ENVIRONMENTAL HEALTH SERVICES

1131 Harbor Bay Parkway, Suite 250 Alameda, CA 94502-6577 (510) 567-6700 (510) 337-9335 (FAX)

November 5, 1999

Ms. Karen Petryna Equiva Services, LLC P.O. Box 6249 Carson, CA 90749-6249 Kokp Hol

RE:

Shell Service Station (STID # 381)

3420 San Pablo Avenue, Oakland, California 94608

LANDOWNER NOTIFICATION AND PARTICIPATION REQUIREMENTS

Dear Ms. Petryna:

This letter is to inform you of new legislative requirements pertaining to cleanup and closure of sites where an unauthorized release of hazardous substance, including petroleum, has occurred from an underground storage tank (UST). Section 25297.15(a) of Ch. 6.7 of the Health & Safety Code requires the primary or active responsible party to notify all current record owners of fee title to the site of: 1) a site cleanup proposal, 2) a site closure proposal, 3) a local agency intention to make a determination that no further action is required, and 4) a local agency intention to issue a closure letter. Section 25297.15(b) requires the local agency to take all reasonable steps to accommodate responsible landowners' participation in the cleanup or site closure process and to consider their input and recommendations.

For purposes of implementing these sections, you have been identified as the primary or active responsible party. Please provide to this agency, within twenty (20) calendar days of receipt of this notice, a complete mailing list of all current record owners of fee title to the site. You may use the enclosed "list of landowners" form (sample letter 2) as a template to comply with this requirement. If the list of current record owners of fee title to the site changes, you must notify the local agency of the change within 20 calendar days from when you are notified of the change.

If you are the sole landowner, please indicate that on the landowner list form. The following notice requirements do not apply to responsible parties who are the sole landowner for the site.

LANDOWNER NOTIFICATION

Re: 3420 San Pablo Avenue, Oakland, CA

November 5, 1999

Page 2 of 2

In accordance with Section 25297.15(a) of Ch. 6.7 of the Health & Safety Code, you must certify to the local agency that all current record owners of fee title to the site have been informed of the proposed action before the local agency may do any of the following:

- 1) consider a cleanup proposal (corrective action plan)
- 2) consider a site closure proposal
- 3) make a determination that no further action is required
- 4) issue a closure letter

You may use the enclosed "notice of proposed action" form (sample letter 3) as a template to comply with this requirement. Before approving a cleanup proposal or site closure proposal, determining that no further action is required, or issuing a closure letter, the local agency will take all reasonable steps necessary to accommodate responsible landowner participation in the cleanup and site closure process and will consider all input and recommendations from any responsible landowner.

Please call me at (510) 567-6780 should you have any questions about the content of this letter.

Sincerely,

Susan L. Hugo

Hazardous Materials Specialist

Attachments

cc:

Chuck Headlee, RWQCB

SH / files

SAM	IPLE LETTER (2): LIST OF LANDOWNERS FORM	
	e of local agency et address	
SUB.	JECT: CERTIFIED LIST OF RECORD FEE TITLE OWNERS FOR (Site Namess)	e and
	e: Fill out item 1 if there are multiple site landowners. If you are the sole site lan item 1 and fill out item 2.)	downer,
1.	In accordance with section 25297.15(a) of Chapter 6.7 of the Health & Safety (name of primary responsible party), certify that the following is a complete I current record fee title owners and their mailing addresses for the above site:	
2.	In accordance with section 25297.15(a) of Chapter 6.7 of the Health & Safety (<u>name of primary responsible party</u>), certify that I am the sole landowner for site.	
Since	erely,	
Signa	ature of primary responsible party	
Name	e of primary responsible party	:

AGENCY
Name of local agency Street address City
SUBJECT: NOTICE OF PROPOSED ACTION SUBMITTED TO LOCAL AGENCY FOR (Site Name and Address)
In accordance with section 25297,15(a) of Chapter 6.7 of the Health & Safety Code, I, (<u>name of primary responsible party</u>), certify that I have notified all responsible landowners of the enclosed proposed action. Check space for applicable proposed action(s):
cleanup proposal (corrective action plan)
site closure proposal
local agency intention to make a determination that no further action is required
local agency intention to issue a closure letter
Sincerely,
Signature of primary responsible party
Name of primary responsible party
cc: Names and addresses of all record fee title owners

CAMBRIA

falleel to
falleel to
facilitaite FACIMILE

- Willreplacemen

tion, anstall tomorrow

Ave. - for sile mage

To:

Susan Hugo

Organization: ACDEH

Fax #:

(510) 337-9335

Re:

Shell Service Station.

3420 San Pablo Ave.

Oakland, California

Date:

î.,

17.

June 15, 1998

Pages:

1, including this cover sheet.

Ms. Hugo:

This is the scope of work for the well replacement project at 3420 San Pablo, Oakland, scheduled for June 18 and 19, 1998. We plan to install the two wells according to typical ACDEH standards on June 18th, 1998, beginning at 8:00 a.m. We will do the vault rebuilds and completions on June 19th, 1998.

3420 San Pablo Avenue, Oakland

Cross street: 35th Street WIC #204-5508-5306

Shell Engineer - Alex Perez

- Install two monitoring wells, each up to 30 feet deep, to replace former wells MW-3 and MW-6. Wells constructed of 2" diameter PVC screen and casing and finished with traffic rated Christy vaults.
- MW-1: Rebuild well vault around existing well.
- MW-4: Rebuild well vault around existing well approx. 4" higher.
- MW-5: Rebuild well vault around existing well approx. 5" higher.
- MW-7: Rebuild well vault around existing well.
- MW-8: Rebuild well vault around existing well approx. 3" higher.

Well locations are shown on the attached figure. Please call if you have any questions.

From the desk of...

Paul Waite

Engineer Cambria Environmental Technology, Inc. 1144 65th Street, Suite C

Oakland, CA 94608

(510) 420-0700 Fax: (510) 420-9170

Paul Waite

Thank you.

CAMBRIA

Mr. Chris Pruner To:

Organization: Gregg Drilling & Systems, Inc.

Fax #:

(510) 313-0302

Re:

17

13.

3420 San Pablo

Qakland, California

Date:

June 15, 1998

Pages:

1, including this cover sheet.

Chris:

Here is the scope of work for the project at 3420 San Pablo, Oakland, scheduled for June 18 and 19, 1998. We would like to install the two wells on the 18th, beginning at 8:00 a.m., and do the rebuilds and completions on the 19th.

3420 San Pabio Avenue, Oakland

Cross street: 35th Street WIC #204-5508-5306

Shell Engineer - Alex Perez

- Install two monitoring wells, each up to 30 feet deep, to replace former wells MW-3 and MW-6. Wells constructed of 2" diameter PVC screen and casing and finished with traffic rated Christy vaults.
- MW-1: Rebuild well vault around existing well.
- MW-4: Rebuild well vault around existing well approx. 4" higher.
- MW-5: Rebuild well vault around existing well approx. 5" higher.
- MW-7: Rebuild well vault around existing well.
- MW-8: Rebuild well vault around existing well approx. 3" higher.

Well locations are shown on attached figure. Please call if you have any questions.

Thanks.

Paul Wait

From the desk of...

Paul Waite

FACSIMILE

Engineer

Cambria Environmental Technology, Inc. 1144 65th Street, Suite C

Oakland, CA 94608

(510) 420-0700

Fax: (510) 420-9170

Figure I. Future Building Location and Well Replacement - Shell Service Station WIC #204-5508-5306, 3420 San Pablo Avenue, Oakland, California

To: Susan Hugo 510-337-9335
From Paulwaite Cambria Phone 510-420-3305
TOTAL P.01

P:VROJECT/SHELLIGHEM 20 CHOURES I WELLE WPLAN

 \hat{I}^{*} .



Via Facsimile and U.S. Mail (510) 337-9335

PROTECTION February 6, 1998

Ms. Susan Hugo Alameda County Department of Environmental Health 1131 Harbor Bay Parkway, Suite 250 Alameda, California 94502-6577

Re: Vapor Extraction Piping Installation

Shell Service Station 3420 San Pablo Avenue Oakland, California WIC #204-5508-5306 Cambria Project #240-0554

Dear Ms. Hugo:

This letter documents the January 27, 1998 meeting between Susan Hugo and Madhulla Logan of the Alameda County Department of Environmental Health (ACDEH) and Paul Waite, Pete McKereghan, and Sampath Rangarajan of Cambria Environmental Technology, Inc. (Cambria) concerning the site referenced above. Cambria is the environmental consultant for Shell Oil Products Company (Shell) for this site. The site is currently under renovation, and Shell intends to construct an operating service station and student training center on the property.

As we discussed, ACDEH does not require Shell to install a "liquid boot" vapor barrier in the foundation of the proposed building at the site. The building will be built on a layer of imported silty clay fill soil approximately 1 foot thick with approximately 93% compaction. A 4-inch thick layer of gravel base course will be placed on the fill soil. A layer of 6-mil plastic sheeting will be installed on top of the gravel, followed by a layer of sand and the cement building slab. Shell will install perforated plastic piping into the gravel base course. The piping will be capped outside of the building to allow future access, if necessary. The purpose of the plastic vapor extraction piping is to give Shell a method to remove any hydrocarbon vapors that accumulate beneath the building in the future. The attached drawing shows the planned layout of the building and piping.

Cambria

ENVIRONMENTAL

TECHNOLOGY, INC.

1144 65TH STREET,

SUITE B

OAKLAND,

CA 94608

PH: (510) 420-0700

Fax: (510) 420-9170

Shell is currently conducting a modified risk-based corrective action (RBCA) analysis to evaluate the potential risk presented by residual hydrocarbons in soil and ground water to the future occupants of the building. As we discussed, the preliminary analysis indicates that there should be no significant risk to building occupants. However, Shell will install the vapor extraction piping beneath the building to prevent hydrocarbon vapors from accumulating inside of the building if the situation changes. As part of the risk analysis, Cambria will develop target ground water concentrations for site constituents of concern (COCs). If, in the future, the COC ground water concentrations in the monitoring wells near the building exceed the target concentrations, an assessment of the indoor air COC concentrations will be conducted, and, if necessary, the vapor extraction piping will be used to abate any COC vapors present.

Shell will install the building foundation soon. As you stated, Shell does not require the permission of the ACDEH to proceed with the installation of the vapor extraction piping. We will keep you updated on the schedule of the project, and we will discuss the results of the risk analysis before the building is occupied.

Thank you for your assistance. If you have any questions or comments about this project, please contact me as soon as possible at (510) 420-3305.

Sincerely,

Cambria Environmental Technology, Inc.

Paul Waite

Project Engineer

cc:

A.E. (Alex) Perez, Shell Oil Products Company, P.O. Box 8080, Martinez, California 94553, Fax (510) 335-5029


Ray Newsome, Shell Oil Products Company, P.O. Box 8080, Martinez, California 94553, Fax (510) 335-5016


Madhulla Logan, ACDEH, 1131 Harbor Bay Parkway, Suite 250, Alameda, California 94502-6577, Fax (510) 337-9335


Blythe Wilson, RHL, 1390 Willow Pass Rd., Suite420, Concord, California 94520-5250, Fax (510) 609-6304

Cortez Johnson, Winmax Construction, 4336 Leimert Blvd., Los Angeles, California 90008, Fax (213) 299-1473, Site Fax (510) 923-9342

F:\PROJECT\SHELL\OAK3420\Reports\ACDEHJan27meet.wpd









Via Facsimile and U.S. Mail (510) 337-9335

Ms. Susan Hugo Alameda County Department of Environmental Health 1131 Harbor Bay Parkway, Suite 250 Alameda, California 94502-6577

Re: Vapor Extraction Piping Installation

Shell Service Station 3420 San Pablo Avenue Oakland, California WIC #204-5508-5306 Cambria Project #240-0554

Dear Ms. Hugo:

This letter documents the January 27, 1998 meeting between Susan Hugo and Madhulla Logan of the Alameda County Department of Environmental Health (ACDEH) and Paul Waite, Pete McKereghan, and Sampath Rangarajan of Cambria Environmental Technology, Inc. (Cambria) concerning the site referenced above. Cambria is the environmental consultant for Shell Oil Products Company (Shell) for this site. The site is currently under renovation, and Shell intends to construct an operating service station and student training center on the property.

As we discussed, ACDEH does not require Shell to install a "liquid boot" vapor barrier in the foundation of the proposed building at the site. The building will be built on a layer of imported silty clay fill soil approximately 1 foot thick with approximately 93% compaction. A 4-inch thick layer of gravel base course will be placed on the fill soil. A layer of 6-mil plastic sheeting will be installed on top of the gravel, followed by a layer of sand and the cement building slab. Shell will install perforated plastic piping into the gravel base course. The piping will be capped outside of the building to allow future access, if necessary. The purpose of the plastic vapor extraction piping is to give Shell a method to remove any hydrocarbon vapors that accumulate beneath the building in the future. The attached drawing shows the planned layout of the building and piping.

Cambria

ENVIRONMENTAL

TECHNOLOGY, INC.

1144 65TH STREET,

SUITE B

OAKLAND,

CA 94608

PH: (510) 420-0700

Fax: (510) 420-9170

Shell is currently conducting a modified risk-based corrective action (RBCA) analysis to evaluate the potential risk presented by residual hydrocarbons in soil and ground water to the future occupants of the building. As we discussed, the preliminary analysis indicates that there should be no significant risk to building occupants. However, Shell will install the vapor extraction piping beneath the building to prevent hydrocarbon vapors from accumulating inside of the building if the situation changes. As part of the risk analysis, Cambria will develop target ground water concentrations for site constituents of concern (COCs). If, in the future, the COC ground water concentrations in the monitoring wells near the building exceed the target concentrations, an assessment of the indoor air COC concentrations will be conducted, and, if necessary, the vapor extraction piping will be used to abate any COC vapors present.

Shell will install the building foundation soon. As you stated, Shell does not require the permission of the ACDEH to proceed with the installation of the vapor extraction piping. We will keep you updated on the schedule of the project, and we will discuss the results of the risk analysis before the building is occupied.

Thank you for your assistance. If you have any questions or comments about this project, please contact me as soon as possible at (510) 420-3305.

Sincerely,

Cambria Environmental Technology, Inc.

Paul Waite

Project Engineer

cc:

A.E. (Alex) Perez, Shell Oil Products Company, P.O. Box 8080, Martinez, California 94553, Fax (510) 335-5029


Ray Newsome, Shell Oil Products Company, P.O. Box 8080, Martinez, California 94553, Fax (510) 335-5016


Madhulla Logan, ACDEH, 1131 Harbor Bay Parkway, Suite 250, Alameda, California 94502-6577, Fax (510) 337-9335


Blythe Wilson, RHL, 1390 Willow Pass Rd., Suite420, Concord, California 94520-5250, Fax (510) 609-6304

Cortez Johnson, Winmax Construction, 4336 Leimert Blvd., Los Angeles, California 90008, Fax (213) 299-1473, Site Fax (510) 923-9342

F:\PROJECT\SHELL\OAK3420\Reports\ACDEHJan27meet.wpd









Via Facsimile and U.S. Mail (510) 337-9335

Ms. Susan Hugo Alameda County Department of Environmental Health 1131 Harbor Bay Parkway, Suite 250 Alameda, California 94502-6577

Re: Vapor Extraction Piping Installation

Shell Service Station 3420 San Pablo Avenue Oakland, California WIC #204-5508-5306 Cambria Project #240-0554

Dear Ms. Hugo:

This letter documents the January 27, 1998 meeting between Susan Hugo and Madhulla Logan of the Alameda County Department of Environmental Health (ACDEH) and Paul Waite, Pete McKereghan, and Sampath Rangarajan of Cambria Environmental Technology, Inc. (Cambria) concerning the site referenced above. Cambria is the environmental consultant for Shell Oil Products Company (Shell) for this site. The site is currently under renovation, and Shell intends to construct an operating service station and student training center on the property.

As we discussed, ACDEH does not require Shell to install a "liquid boot" vapor barrier in the foundation of the proposed building at the site. The building will be built on a layer of imported silty clay fill soil approximately 1 foot thick with approximately 93% compaction. A 4-inch thick layer of gravel base course will be placed on the fill soil. A layer of 6-mil plastic sheeting will be installed on top of the gravel, followed by a layer of sand and the cement building slab. Shell will install perforated plastic piping into the gravel base course. The piping will be capped outside of the building to allow future access, if necessary. The purpose of the plastic vapor extraction piping is to give Shell a method to remove any hydrocarbon vapors that accumulate beneath the building in the future. The attached drawing shows the planned layout of the building and piping.

Cambria

ENVIRONMENTAL

TECHNOLOGY, INC.

1144 65TH STREET,

SUITE B

OAKLAND,

CA 94608

PH: (510) 420-0700

Fax: (510) 420-9170

Shell is currently conducting a modified risk-based corrective action (RBCA) analysis to evaluate the potential risk presented by residual hydrocarbons in soil and ground water to the future occupants of the building. As we discussed, the preliminary analysis indicates that there should be no significant risk to building occupants. However, Shell will install the vapor extraction piping beneath the building to prevent hydrocarbon vapors from accumulating inside of the building if the situation changes. As part of the risk analysis, Cambria will develop target ground water concentrations for site constituents of concern (COCs). If, in the future, the COC ground water concentrations in the monitoring wells near the building exceed the target concentrations, an assessment of the indoor air COC concentrations will be conducted, and, if necessary, the vapor extraction piping will be used to abate any COC vapors present.

Shell will install the building foundation soon. As you stated, Shell does not require the permission of the ACDEH to proceed with the installation of the vapor extraction piping. We will keep you updated on the schedule of the project, and we will discuss the results of the risk analysis before the building is occupied.

Thank you for your assistance. If you have any questions or comments about this project, please contact me as soon as possible at (510) 420-3305.

Sincerely,

Cambria Environmental Technology, Inc.

Paul Waite

Project Engineer

cc:

A.E. (Alex) Perez, Shell Oil Products Company, P.O. Box 8080, Martinez, California 94553, Fax (510) 335-5029


Ray Newsome, Shell Oil Products Company, P.O. Box 8080, Martinez, California 94553, Fax (510) 335-5016


Madhulla Logan, ACDEH, 1131 Harbor Bay Parkway, Suite 250, Alameda, California 94502-6577, Fax (510) 337-9335


Blythe Wilson, RHL, 1390 Willow Pass Rd., Suite420, Concord, California 94520-5250, Fax (510) 609-6304

Cortez Johnson, Winmax Construction, 4336 Leimert Blvd., Los Angeles, California 90008, Fax (213) 299-1473, Site Fax (510) 923-9342

F:\PROJECT\SHELL\OAK3420\Reports\ACDEHJan27meet.wpd









Via Facsimile and U.S. Mail (510) 337-9335

Ms. Susan Hugo Alameda County Department of Environmental Health 1131 Harbor Bay Parkway, Suite 250 Alameda, California 94502-6577

Re: Vapor Extraction Piping Installation

Shell Service Station 3420 San Pablo Avenue Oakland, California WIC #204-5508-5306 Cambria Project #240-0554

Dear Ms. Hugo:

This letter documents the January 27, 1998 meeting between Susan Hugo and Madhulla Logan of the Alameda County Department of Environmental Health (ACDEH) and Paul Waite, Pete McKere ghan, and Sampath Rangarajan of Cambria Environmental Technology, Inc. (Cambria) concerning the site referenced above. Cambria is the environmental consultant for Shell Oil Products Company (Shell) for this site. The site is currently under renovation, and Shell intends to construct an operating service station and student training center on the property.

As we discussed, ACDEH does not require Shell to install a "liquid boot" vapor barrier in the foundation of the proposed building at the site. The building will be built on a layer of imported silty clay fill soil approximately 1 foot thick with approximately 93% compaction. A 4-inch thick layer of gravel base course will be placed on the fill soil. A layer of 6-mil plastic sheeting will be installed on top of the gravel, followed by a layer of sand and the cement building slab. Shell will install perforated plastic piping into the gravel base course. The piping will be capped outside of the building to allow future access, if necessary. The purpose of the plastic vapor extraction piping is to give Shell a method to remove any hydrocarbon vapors that accumulate beneath the building in the future. The attached drawing shows the planned layout of the building and piping.

Cambria

ENVIRONMENTAL

TECHNOLOGY, INC.

11**44** 65TH STREET,

Suite B

Oakland,

CA 94608

Рн: (510) 420-0700

Fax: (510) 420-9170

Shell is currently conducting a modified risk-based corrective action (RBCA) analysis to evaluate the potential risk presented by residual hydrocarbons in soil and ground water to the future occupants of the building. As we discussed, the preliminary analysis indicates that there should be no significant risk to building occupants. However, Shell will install the vapor extraction piping beneath the building to prevent hydrocarbon vapors from accumulating inside of the building if the situation changes. As part of the risk analysis, Cambria will develop target ground water concentrations for site constituents of concern (COCs). If, in the future, the COC ground water concentrations in the monitoring wells near the building exceed the target concentrations, an assessment of the indoor air COC concentrations will be conducted, and, if necessary, the vapor extraction piping will be used to abate any COC vapors present.

Shell will install the building foundation soon. As you stated, Shell does not require the permission of the ACDEH to proceed with the installation of the vapor extraction piping. We will keep you updated on the schedule of the project, and we will discuss the results of the risk analysis before the building is occupied.

Thank you for your assistance. If you have any questions or comments about this project, please contact me as soon as possible at (510) 420-3305.

Sincerely,

Cambria Environmental Technology, Inc.

Paul Waite

Project Engineer

cc:


A.E. (Alex) Perez, Shell Oil Products Company, P.O. Box 8080, Martinez, California 94553, Fax (510) 335-5029


Ray Newsome, Shell Oil Products Company, P.O. Box 8080, Martinez, California 94553, Fax (510) 335-5016


Madhulla Logan, ACDEH, 1131 Harbor Bay Parkway, Suite 250, Alameda, California 94502-6577, Fax (510) 337-9335

Blythe Wilson, RHL, 1390 Willow Pass Rd., Suite420, Concord, California 94520-5250, Fax (510) 609-6304

Cortez Johnson, Winmax Construction, 4336 Leimert Blvd., Los Angeles, California 90008, Fax (213) 299-1473, Site Fax (510) 923-9342









Via Facsimile and U.S. Mail (510) 337-9335

Ms. Susan Hugo Alameda County Department of Environmental Health 1131 Harbor Bay Parkway, Suite 250 Alameda, California 94502-6577

Re: Vapor Extraction Piping Installation

Shell Service Station 3420 San Pablo Avenue Oakland, California WIC #204-5508-5306 Cambria Project #240-0554

Dear Ms. Hugo:

This letter documents the January 27, 1998 meeting between Susan Hugo and Madhulla Logan of the Alameda County Department of Environmental Health (ACDEH) and Paul Waite, Pete McKereghan, and Sampath Rangarajan of Cambria Environmental Technology, Inc. (Cambria) concerning the site referenced above. Cambria is the environmental consultant for Shell Oil Products Company (Shell) for this site. The site is currently under renovation, and Shell intends to construct an operating service station and student training center on the property.

As we discussed, ACDEH does not require Shell to install a "liquid boot" vapor barrier in the foundation of the proposed building at the site. The building will be built on a layer of imported silty clay fill soil approximately 1 foot thick with approximately 93% compaction. A 4-inch thick layer of gravel base course will be placed on the fill soil. A layer of 6-mil plastic sheeting will be installed on top of the gravel, followed by a layer of sand and the cement building slab. Shell will install perforated plastic piping into the gravel base course. The piping will be capped outside of the building to allow future access, if necessary. The purpose of the plastic vapor extraction piping is to give Shell a method to remove any hydrocarbon vapors that accumulate beneath the building in the future. The attached drawing shows the planned layout of the building and piping.

Cambria

ENVIRONMENTAL

TECHNOLOGY, INC.

1144 65TH STREET,

SUITE B

OAKLAND,

CA 94608

PH: (510) 420-0700

Fax: (510) 420-9170

Shell is currently conducting a modified risk-based corrective action (RBCA) analysis to evaluate the potential risk presented by residual hydrocarbons in soil and ground water to the future occupants of the building. As we discussed, the preliminary analysis indicates that there should be no significant risk to building occupants. However, Shell will install the vapor extraction piping beneath the building to prevent hydrocarbon vapors from accumulating inside of the building if the situation changes. As part of the risk analysis, Cambria will develop target ground water concentrations for site constituents of concern (COCs). If, in the future, the COC ground water concentrations in the monitoring wells near the building exceed the target concentrations, an assessment of the indoor air COC concentrations will be conducted, and, if necessary, the vapor extraction piping will be used to abate any COC vapors present.

Shell will install the building foundation soon. As you stated, Shell does not require the permission of the ACDEH to proceed with the installation of the vapor extraction piping. We will keep you updated on the schedule of the project, and we will discuss the results of the risk analysis before the building is occupied.

Thank you for your assistance. If you have any questions or comments about this project, please contact me as soon as possible at (510) 420-3305.

Sincerely,

Cambria Environmental Technology, Inc.

Paul Waite

Project Engineer

cc:


A.E. (Alex) Perez, Shell Oil Products Company, P.O. Box 8080, Martinez, California 94553, Fax (510) 335-5029


Ray Newsome, Shell Oil Products Company, P.O. Box 8080, Martinez, California 94553, Fax (510) 335-5016


Madhulla Logan, ACDEH, 1131 Harbor Bay Parkway, Suite 250, Alameda, California 94502 6577, Fax (510) 337-9335

Blythe Wilson, RHL, 1390 Willow Pass Rd., Suite420, Concord, California 94520-5250, Fax (510) 609-6304

Cortez Johnson, Winmax Construction, 4336 Leimert Blvd., Los Angeles, California 90008, Fax (213) 299-1473, Site Fax (510) 923-9342









Via Facsimile and U.S. Mail (510) 337-9335

Ms. Susan Hugo Alameda County Department of Environmental Health 1131 Harbor Bay Parkway, Suite 250 Alameda, California 94502-6577

Re: Vapor Extraction Piping Installation

Shell Service Station 3420 San Pablo Avenue Oakland, California WIC #204-5508-5306 Cambria Project #240-0554

Dear Ms. Hugo:

This letter documents the January 27, 1998 meeting between Susan Hugo and Madhulla Logan of the Alameda County Department of Environmental Health (ACDEH) and Paul Waite, Pete McKereghan, and Sampath Rangarajan of Cambria Environmental Technology, Inc. (Cambria) concerning the site referenced above. Cambria is the environmental consultant for Shell Oil Products Company (Shell) for this site. The site is currently under renovation, and Shell intends to construct an operating service station and student training center on the property.

As we discussed, ACDEH does not require Shell to install a "liquid boot" vapor barrier in the foundation of the proposed building at the site. The building will be built on a layer of imported silty clay fill soil approximately 1 foot thick with approximately 93% compaction. A 4-inch thick layer of gravel base course will be placed on the fill soil. A layer of 6-mil plastic sheeting will be installed on top of the gravel, followed by a layer of sand and the cement building slab. Shell will install perforated plastic piping into the gravel base course. The piping will be capped outside of the building to allow future access, if necessary. The purpose of the plastic vapor extraction piping is to give Shell a method to remove any hydrocarbon vapors that accumulate beneath the building in the future. The attached drawing shows the planned layout of the building and piping.

Cambria

ENVIRONMENTAL

TECHNOLOGY, INC.

1144 65TH STREET,

Suite B

OAKLAND,

CA 94608

Рн: (510) 420-0700

Fax: (510) 420-9170

Shell is currently conducting a modified risk-based corrective action (RBCA) analysis to evaluate the potential risk presented by residual hydrocarbons in soil and ground water to the future occupants of the building. As we discussed, the preliminary analysis indicates that there should be no significant risk to building occupants. However, Shell will install the vapor extraction piping beneath the building to prevent hydrocarbon vapors from accumulating inside of the building if the situation changes. As part of the risk analysis, Cambria will develop target ground water concentrations for site constituents of concern (COCs). If, in the future, the COC ground water concentrations in the monitoring wells near the building exceed the target concentrations, an assessment of the indoor air COC concentrations will be conducted, and, if necessary, the vapor extraction piping will be used to abate any COC vapors present.

CAMBRIA

Shell will install the building foundation soon. As you stated, Shell does not require the permission of the ACDEH to proceed with the installation of the vapor extraction piping. We will keep you updated on the schedule of the project, and we will discuss the results of the risk analysis before the building is occupied.

Thank you for your assistance. If you have any questions or comments about this project, please contact me as soon as possible at (510) 420-3305.

Sincerely,

Cambria Environmental Technology, Inc.

Paul Waite

Project Engineer

cc:


A.E. (Alex) Perez, Shell Oil Products Company, P.O. Box 8080, Martinez, California 94553, Fax (510) 335-5029


Ray Newsome, Shell Oil Products Company, P.O. Box 8080, Martinez, California 94553, Fax (510) 335-5016


Madhulla Logan, ACDEH, 1131 Harbor Bay Parkway, Suite 250, Alameda, California 94502-6577, Fax (510) 337-9335

Blythe Wilson, RHL, 1390 Willow Pass Rd., Suite420, Concord, California 94520-5250, Fax (510) 609-6304

Cortez Johnson, Winmax Construction, 4336 Leimert Blvd., Los Angeles, California 90008, Fax (213) 299-1473, Site Fax (510) 923-9342









Via Facsimile and U.S. Mail (510) 337-9335

Ms. Susan Hugo Alameda County Department of Environmental Health 1131 Harbor Bay Parkway, Suite 250 Alameda, California 94502-6577

Re: Vapor Extraction Piping Installation

> Shell Service Station 3420 San Pablo Avenue Oakland, California WIC #204-5508-5306 Cambria Project #240-0554

Dear Ms. Hugo:

This letter documents the January 27, 1998 meeting between Susan Hugo and Madhulla Logan of the Alameda County Department of Environmental Health (ACDEH) and Paul Waite, Pete McKereghan, and Sampath Rangarajan of Cambria Environmental Technology, Inc. (Cambria) concerning the site referenced above. Cambria is the environmental consultant for Shell Oil Products Company (Shell) for this site. The site is currently under renovation, and Shell intends to construct an operating service station and student training center on the property.

As we discussed, ACDEH does not require Shell to install a "liquid boot" vapor barrier in the foundation of the proposed building at the site. The building will be built on a layer of imported silty clay fill soil approximately 1 foot thick with approximately 93% compaction. A 4-inch thick layer of gravel base course will be placed on the fill soil. A layer of 6-mil plastic sheeting will be installed on top of the gravel, followed by a layer of sand and the cement building slab. Shell will install perforated plastic piping into the gravel base course. The piping will be capped outside of the building to allow future access, if necessary. The purpose of the plastic vapor extraction piping is to give Shell a method to remove any hydrocarbon vapors that accumulate beneath the building in the future. The attached drawing shows the planned layout of the building and piping.

CAMBRIA

ENVIRONMENTAL

TECHNOLOGY, INC.

1144 65TH STREET,

SUITE B

OAKLAND,

CA 94608

PH: (510) 420-0700

Fax: (510) 420-9170

Shell is currently conducting a modified risk-based corrective action (RBCA) analysis to evaluate the potential risk presented by residual hydrocarbons in soil and ground water to the future occupants of the building. As we discussed, the preliminary analysis indicates that there should be no significant risk to building occupants. However, Shell will install the vapor extraction piping beneath the building to prevent hydrocarbon vapors from accumulating inside of the building if the situation changes. As part of the risk analysis, Cambria will develop target ground water concentrations for site constituents of concern (COCs). If, in the future, the COC ground water concentrations in the monitoring wells near the building exceed the target concentrations, an assessment of the indoor air COC concentrations will be conducted, and, if necessary, the vapor extraction piping will be used to abate any COC vapors present.

CAMBRIA

Shell will install the building foundation soon. As you stated, Shell does not require the permission of the ACDEH to proceed with the installation of the vapor extraction piping. We will keep you updated on the schedule of the project, and we will discuss the results of the risk analysis before the building is occupied.

Thank you for your assistance. If you have any questions or comments about this project, please contact me as soon as possible at (510) 420-3305.

Sincerely,

Cambria Environmental Technology, Inc.

Paul Waite

Project Engineer

cc:


A.E. (Alex) Perez, Shell Oil Products Company, P.O. Box 8080, Martinez, California 94553, Fax (510) 335-5029


Ray Newsome, Shell Oil Products Company, P.O. Box 8080, Martinez, California 94553, Fax (510) 335-5016

Madhulla Logan, ACDEH, 1131 Harbor Bay Parkway, Suite 250, Alameda, California 94502-6577, Fax (510) 337-9335

Blythe Wilson, RHL, 1390 Willow Pass Rd., Suite420, Concord, California 94520-5250, Fax (510) 609-6304

Cortez Johnson, Winmax Construction, 4336 Leimert Blvd., Los Angeles, California 90008, Fax (213) 299-1473, Site Fax (510) 923-9342





February 6, 1998

R 6

Via Facsimile and U.S. Mail (510) 337-9335

Ms. Susan Hugo Alameda County Department of Environmental Health 1131 Harbor Bay Parkway, Suite 250 Alameda, California 94502-6577

Re: Vapor Extraction Piping Installation

Shell Service Station 3420 San Pablo Avenue Oakland, California WIC #204-5508-5306 Cambria Project #240-0554

Dear Ms. Hugo:

This letter documents the January 27, 1998 meeting between Susan Hugo and Madhulla Logan of the Alameda County Department of Environmental Health (ACDEH) and Paul Waite, Pete McKereghan, and Sampath Rangarajan of Cambria Environmental Technology, Inc. (Cambria) concerning the site referenced above. Cambria is the environmental consultant for Shell Oil Products Company (Shell) for this site. The site is currently under renovation, and Shell intends to construct an operating service station and student training center on the property.

As we discussed, ACDEH does not require Shell to install a "liquid boot" vapor barrier in the foundation of the proposed building at the site. The building will be built on a layer of imported silty clay fill soil approximately 1 foot thick with approximately 93% compaction. A 4-inch thick layer of gravel base course will be placed on the fill soil. A layer of 6-mil plastic sheeting will be installed on top of the gravel, followed by a layer of sand and the cement building slab. Shell will install perforated plastic piping into the gravel base course. The piping will be capped outside of the building to allow future access, if necessary. The purpose of the plastic vapor extraction piping is to give Shell a method to remove any hydrocarbon vapors that accumulate beneath the building in the future. The attached drawing shows the planned layout of the building and piping.

Shell is currently conducting a modified risk-based corrective action (RBCA) analysis to evaluate the potential risk presented by residual hydrocarbons in soil and ground water to the future occupants of the building. As we discussed, the preliminary analysis indicates that there should be no significant risk to building occupants. However, Shell will install the vapor extraction piping beneath the building to prevent hydrocarbon vapors from accumulating inside of the building if the situation changes. As part of the risk analysis, Cambria will develop target ground water concentrations for site constituents of concern (COCs). If, in the future, the COC ground water concentrations in the monitoring wells near the building exceed the target concentrations, an assessment of the indoor air COC concentrations will be conducted, and, if necessary, the vapor extraction piping will be used to abate any COC vapors present.

CAMBRIA

ENVIRONMENTAL

TECHNOLOGY, INC.

1144 65TH STREET,

SUITE B

OAKLAND,

CA 94608

Pit: (510) 420-07(0)

Fax: (510) 421)-9170

Susan Hugo February 6, 1998





Shell will install the building foundation soon. As you stated, Shell does not require the permission of the ACDEH to proceed with the installation of the vapor extraction piping. We will keep you updated on the schedule of the project, and we will discuss the results of the risk analysis before the building is occupied.

Thank you for your assistance. If you have any questions or comments about this project, please contact me as soon as possible at (510) 420-3305.

Sincerely,

Cambria Environmental Technology, Inc.

Paul Waite

Project Engineer

cc:

V.

A.E. (Alex) Perez, Shell Oil Products Company, P.O. Box 8080, Martinez, California 94553, Fax (510) 335-5029


Ray Newsome, Shell Oil Products Company, P.O. Box 8080, Martinez, California 94553, Fax (510) 335-5016

Madhulla Logan, ACDEH, 1131 Harbor Bay Parkway, Suite 250, Alameda, California 94502-6577, Fax (510) 337-9335

Blythe Wilson, RHL, 1390 Willow Pass Rd., Suite420, Concord, California 94520-5250, Fax (510) 609-6304

Cortez Johnson, Winmax Construction, 4336 Leimert Blvd., Los Angeles, California 90008, Fax (213) 299-1473, Site Fax (510) 923-9342

February 6, 1998



Via Facsimile and U.S. Mail (510) 337-9335

Ms. Susan Hugo Alameda County Department of Environmental Health 1131 Harbor Bay Parkway, Suite 250 Alameda, California 94502-6577

Re: Vapor Extraction Piping Installation

Shell Service Station 3420 San Pablo Avenue Oakland, California WIC #204-5508-5306 Cambria Project #240-0554

Dear Ms. Hugo:

This letter documents the January 27, 1998 meeting between Susan Hugo and Madhulla Logan of the Alameda County Department of Environmental Health (ACDEH) and Paul Waite, Pete McKereghan, and Sampath Rangarajan of Cambria Environmental Technology, Inc. (Cambria) concerning the site referenced above. Cambria is the environmental consultant for Shell Oil Products Company (Shell) for this site. The site is currently under renovation, and Shell intends to construct an operating service station and student training center on the property.

As we discussed, ACDEH does not require Shell to install a "liquid boot" vapor barrier in the foundation of the proposed building at the site. The building will be built on a layer of imported silty clay fill soil approximately 1 foot thick with approximately 93% compaction. A 4-inch thick layer of gravel base course will be placed on the fill soil. A layer of 6-mil plastic sheeting will be installed on top of the gravel, followed by a layer of sand and the cement building slab. Shell will install perforated plastic piping into the gravel base course. The piping will be capped outside of the building to allow future access, if necessary. The purpose of the plastic vapor extraction piping is to give Shell a method to remove any hydrocarbon vapors that accumulate beneath the building in the future. The attached drawing shows the planned layout of the building and piping.

CAMBRIA

ENVIRONMENTAL

TECHNOLOGY, INC.

1144 65TH STREET,

SUITE B

OAKLAND,

CA 94608

Pri: (510) 420-07(0)

FAX: (510) 12(0-9170)

Shell is currently conducting a modified risk-based corrective action (RBCA) analysis to evaluate the potential risk presented by residual hydrocarbons in soil and ground water to the future occupants of the building. As we discussed, the preliminary analysis indicates that there should be no significant risk to building occupants. However, Shell will install the vapor extraction piping beneath the building to prevent hydrocarbon vapors from accumulating inside of the building if the situation changes. As part of the risk analysis, Cambria will develop target ground water concentrations for site constituents of concern (COCs). If, in the future, the COC ground water concentrations in the monitoring wells near the building exceed the target concentrations, an assessment of the indoor air COC concentrations will be conducted, and, if necessary, the vapor extraction piping will be used to abate any COC vapors present.

Susan Hugo February 6, 1998





Shell will install the building foundation soon. As you stated, Shell does not require the permission of the ACDEH to proceed with the installation of the vapor extraction piping. We will keep you updated on the schedule of the project, and we will discuss the results of the risk analysis before the building is occupied.

Thank you for your assistance. If you have any questions or comments about this project, please contact me as soon as possible at (510) 420-3305.

Sincerely,

Cambria Environmental Technology, Inc.

Paul Waite

Project Engineer

cc:

A.E. (Alex) Perez, Shell Oil Products Company, P.O. Box 8080, Martinez, California 94553, Fax (510) 335-5029

Ray Newsome, Shell Oil Products Company, P.O. Box 8080, Martinez, California 94553, Fax (510) 335-5016

Madhulla Logan, ACDEH, 1131 Harbor Bay Parkway, Suite 250, Alameda, California 94502-6577, Fax (510) 337-9335

Blythe Wilson, RHL, 1390 Willow Pass Rd., Suite420, Concord, California 94520-5250, Fax (510) 609-6304

Cortez Johnson, Winmax Construction, 4336 Leimert Blvd., Los Angeles, California 90008, Fax (213) 299-1473, Site Fax (510) 923-9342

ALAMEDA COUNTY HAZARDOUS MATERIALS DIVISION

01/27/98

UNDERGROUND STORAGE TANK CLEANUP SITE

SOURCE OF FUNDS: F-FEDERAL INSPECTOR: SH AGENCY#: 10000

381 SUBSTANCE: 8006619 -Gasoline StID:

SITE NAME: Shell Oil Company DATE REPORTED : 02/15/89 ADDRESS : 3420 San Pablo Ave DATE CONFIRMED: 08/08/88

CITY/ZIP: Oakland, CA 94608 MULTIPLE RP's : N

CASE TYPE: O CONTRACT STATUS: 4 PRIOR: 2B3 EMERGENCY RESPONSE:

DATE END: 07/20/92 RP SEARCH : S

PRELIM ASSESSMENT : C DATE BEGIN: DATE END: REMEDIAL INVESTIG : U DATE BEGIN: DATE END: DATE BEGIN: REMEDIAL ACTION : DATE BEGIN: POST REMED MONITOR: DATE BEGIN: DATE END: DATE END:

TYPE ENFORCEMENT ACTION TAKEN: 1 DATE OF ENFORC. ACTION: 07/20/92

UNDERGROUND STORAGE TANK CLEANUP SITE - SCREEN #2

LUFT FIELD MANUAL CONSIDERATION: 3SHSAW CASE CLOSED: on:

REMEDIAL ACTIONS TAKEN: DT EXC START:

RP COST: RP #1: CONTACT: Alex Perez \$0.00

RP COMPANY NAME: Shell Oil Company Ph:

ADDRESS: P. O. Box 8080

CITY/STATE: Maratinez Ca 94553

△PiMENT:

December 4, 1997



<u>Via Facsimile and U.S. Mail</u> (510) 337-9335

Ms. Susan Hugo Alameda County Department of Environmental Health 1131 Harbor Bay Parkway, Suite 250 Alameda, California 94502-6577

Re: Well Abandonment Approval

Shell Service Station 3420 San Pablo Avenue Oakland, California WIC #204-5508-5306 Cambria Project #240-0554

Dear Ms. Hugo:

This letter documents your December 4, 1997 conversation with Paul Waite of Cambria Environmental Technology Inc. (Cambria). As we discussed, Shell Oil Products Company (Shell) is conducting renovation activities at the site referenced above. The site buildings and above-ground improvements have been removed, although the underground storage tanks are still in place. The construction activities are proceeding rapidly because of concerns about excessive rains this winter. Shell wants to pave the lot and pour the concrete foundation of the future building as soon as possible to protect the site from being saturated during the rainy season.

In order to continue construction activities at the site, two existing monitoring wells (MW-3 and MW-6) have to be abandoned because they are within the footprint of the planned building. On December 4, 1997, you stated that we can proceed with the abandonment of these two wells by pressure grouting. We have scheduled the well abandonment for Friday, December 5, 1997 at 9:00 a.m.

Cambria

Environmentai

TECHNOLOGY, INC.

1144 65 no Segron,

Sourc B

OAXLAND,

CA 94608

Pic (510) 420 0700

Fee (510) 420-4170

As discussed, Shell will install two replacement wells in the approximate locations shown on the attached figure. Before pouring the concrete building pad, Shell will install a vapor barrier, consisting of layered plastic sheeting, underneath the building foundation. Shell will be ready to pour the building pad within the next week, and they will begin framing the building immediately thereafter. The building will be finished as early as February 1998. Before the building is occupied, Shell will conduct an initial risk evaluation for future building occupants.

Susan Hugo December 4, 1997

CAMBRIA

Please indicate that you approve of this scope of work by signing below and returning this letter to Cambria by facsimile at (510) 420-9170 as soon as possible.

Thank you for your assistance. Please call if you have any questions.

Sincerely,

Cambria Environmental Technology, Inc.

Paul Waite

Project Engineer

Authorization to Proceed with Well Abandonment Shell Service Station 3420 San Pablo Avenue, Oakland, California

Approved by [name]

Signature

Date

Alameda County Dept. of

Environmental Health

CC:

A.E. (Alex) Perez, Shell Oil Products Company, P.O. Box 8080, Martinez, California 94553, Fax (510) 335-5029

Ray Newsome, Shell Oil Products Company, P.O. Box 8080, Martinez, California 94553, Fax (510) 335-5016

Alvin Kan, Alameda County Public Works Department, 951 Turner Court, Suite 300, Hayward, California 94545-2651, Fax (510) 670-5262

F:\PROJECT\SHRUL\OAK3420\Corresp.97\ACDEHDec4let.wpd



31D 381

November 17, 1997

<u>Via Facsimile</u> (510) 337-9335

Ms. Susan Hugo Alameda County Department of Environmental Health 1131 Harbor Bay Parkway, Suite 250 Alameda, California 94502-6577

Re: Well Abandonment Request

> Shell Service Station 3420 San Pablo Avenue Oakland, California WIC #204-5508-5306 Cambria Project #240-0554

Dear Ms. Hugo:

As we discussed today, Shell Oil Products Company (Shell) is conducting renovation activities at the site referenced above. The site buildings and above-ground improvements have been removed, although the underground storage tanks are still in place. The construction activities are proceeding rapidly because of concerns about excessive rains this winter.

Shell wants to protect the soil at the site from being saturated by rain this winter. They will be paving most of the lot this week. In addition, Shell would like to pour the foundation for the planned service station building this week. The footprint of the planned building is over existing monitoring wells MW-3 and MW-6. We recommend abandoning those two wells by pressure grouting and installing two replacement wells. The attached figure shows the location of the building, the existing wells, and our recommended locations for replacement wells. We have submitted the permit to abandon the monitoring wells to the Alameda County Department of Public Works, but they require your approval to issue the permits.

CAMBRIA

After you have reviewed the site plan, please contact me at (510) 420-3305 to discuss this project. Thank you for your assistance.

ENVIRONMENTAL

Sincerely,

Cambria Environmental Technology, Inc.

1144 65 HES BRIDE,

Tremology, Inc.

Score II

Paul Waite

Project Engineer

CA 94608

OAKLAND,

cc:

A.E. (Alex) Perez, Shell Oil Products Company, P.O. Box 8080, Martinez, California 94553, 3 Fax (510) 335-5029

Pri (510) 420 0700

Alvin Kan, Alameda County Public Works Department, 951 Turner Court, Suite 300, Hayward, California 94545-2651, Fax (510) 670-5262

Cast (510) 420-9170

F:\PROJECT\SHELL\OAK3420\Corresp.97\ACDEHNov17let.wpd

CAMBRIA




Figure 1. Future Building Location and Well Replacement - Shell Service Station WIC #204-5508-5306, 3420 San Pablo Avenue, Oakland, California



November 14, 1997

Via Facsimile (510) 337-9335

Ms. Susan Hugo Alameda County Department of Environmental Health 1131 Harbor Bay Parkway, Suite 250 Alameda, California 94502-6577

Re: Construction Activities and Well Abandonments

Shell Service Station 3420 San Pablo Avenue Oakland, California W1C #204-5508-5306 Cambria Project #240-0554

Dear Ms. Hugo:

Shell Oil Products Company (Shell) is conducting renovation activities at the site referenced above. The site buildings and above-ground improvements have been removed, although the underground storage tanks are still in place. Forty cubic yards of soil that were excavated during piping renovations have been hauled off the site and disposed. The site is currently being graded and approximately 1,000 additional cubic yards of soil will be removed from the site and disposed as early as November 15, 1997.

The site will be paved shortly and the entire station will be rebuilt during 1998. Because of the future construction, two of the existing ground water monitoring wells (MW-3 and MW-6) will have to be abandoned. We have submitted the permit to abandon the monitoring wells by pressure grouting to the Alameda County Department of Public Works, but they require your approval to issue the permits. The attached site plan shows the location of the monitoring wells. We would like to abandon these wells as soon as possible.

CAMBRIA

Today I left you a voice-mail message summarizing the above activities. Please contact me at (510) 420-3305 to discuss this project. Thank you for your assistance.

TECHNOLOGY, INC.

ENVIRONMENTAL

Sincerely,

Cambria Environmental Technology, Inc.

1144 65to Street,

Serio: B

Paul Waite

Project Engineer

OAKLAND,

CA 94608

ee:

A.E. (Alex) Perez, Shell Oil Products Company, P.O. Box 8080, Martinez, California 94553,

Fax (510) 335-5029

Alvin Kan, Alameda County Public Works Department, 951 Turner Court, Suite 300, Hayward, California 94545-2651, Fax (510) 670-5262

Exx; (510) 420-9170

Put (510) 426-6760

F:\PROJECT\SHELL\OAK3420\Corresp.97\Nov12let.wpd

white -env.health yellow -facility pink -files

RLAMEDA COUNTY, DEPARTMENT OF ENUIRONMENTAL HEALTH

1131 Harbor Bay Pkwy Alameda CA 94502 510/567-6700

Hazardous Materials Inspection Form

11, 111

Site ID #381_ Site Name Shell Survice Stationer's Date 6 26,97
,
Site Address 3420 for Pablo ane.
City Dakland Zip 94 608 Phone
MAX AMT stored > 500 lbs, 55 gal., 200 cft.?
Inspection Categories: I. Haz. Mat/Waste GENERATOR/TRANSPORTER II. Hazar dous Materials Business Plan, Acutely Hazar dous Materials III. Under ground Storage Tanks
* Calif. Administration Code (CAC) or the Health & Safety Code (HS&C)
Comments:
On Site for the removal of one fiberglans (100 gal)
danalewalled waste will tank . Product sixing
were also removed of Coil samples called of
from the treacher
Trong Briffen (Oakland Fire Digt. on site)
ULEK = // E102 = 2 /0
The tank appeared to be in good Shape
Manifest # 93335180, Hank disposed at Excheson
Establed by Crossy Es averton.
firsted ground wally greatent at the batton of
the of Cavation. Brown when Sampling will due
to the close proximity I will MWB from the wante ail
Tonk pet . Hest stapling west (7/97)
grandwale from All 3 must be analyze
The NERT STATE BIET, CIHC, TRACTAS 16, Cd, Cr. Zonfili
20016
a sour somple were calledy from the of cavalion
aldunans of 1 production of the
THE d. BIET MIRE E. Pb. (910 Sail Smighten)
Contact 11, 111
Title Inspector
Signature Signature August August



ARCHITECTURE ENGINEERING ENVIRONMENTAL SERVICES

1390 Willow Pass Rd., Suite 420, Concord, CA 94520-5250 Telephone: (510) 609-6300 Facsimile: (510) 609-6304

BLYTHE R. WILSON

June 16, 1997

Established 1966

Managing Architect Associate

Alameda County Environmental Health Department

JOHN W. JOHNSON Architect Co-President 1131 Harbor Bay Parkway, 2nd Floor Alameda, CA 94502

RE:

Shell Oil Company Waste Oil Tank & Piping Removal

BRIAN F. ZITA Architect Co-President Youth Services Academy 3420 San Pablo Avenue Oakland, CA RHL JOB #6957.10

TOHN B. HICKS Architect Vice President

Dear Mr. Oliva:

On behalf of Shell Oil Company we would like to make an application for a permit to remove the 550 gallon waste oil tank and product piping at the above referenced facility.

CECIL R. SPENCER Architect Vice President

Enclosed are three copies of the completed UST closure plan, 8 1/2 X 11 site plan. State A & B form, basic site safety plan, Contractor's license, Contractor's hazardous substance removal and workman's comp. insurance certificates and a check attached to this letter for six-hundred, thirty dollars (\$630.00) the deposit/refund fee to remove one UST.

BRUCE J. GREENFIELD Managing Architect Associate

Note that the existing underground fuel storage tanks will not be removed. These tanks will be emptied and temporarily closed for the duration of the demolition and subsequent rebuilding of the facility (approximately 6 months).

HOWARD G. KIMURA Architect Associate If you have any questions, comments or require additional information or fees, don't hesitate to call me. Your expeditious attention to this matter is greatly appreciated as the demolition of the facility is scheduled to begin this week.

Sincere regards,

CHRIS LAWTON Regional Manager Associate RHL Design Group, Inc.

Zaiga Gianino

Project Coordinator

JAMES E.-PRESTEN Regional Manager Associate

Enclosures

CC:

Mr. Ray Newsome - Shell Oil Company

file

bKOIECTION ENVESCHERITYT

83:5 WW LINNILS

GARY M. SEMLING Managing Architect Associate

BELLEVUE, WA LA HABRA, CA

PETALUMA, CA

SACRAMENTO, CA

SCOTTSDALE, AZ

A COUNTY HEALTH CARE SERVICE

DEPARTMENT OF ENVIRONMENTAL HEALTH ENVIRONMENTAL PROTECTION DIVISION

1131 HARBOR BAY PARKWAY, RM 250

ALAMEDA, PHONE # CA 94502-6577 510/567-6700

Cen capy of the accepted plans must be on the job and aveilable to all contractors and craftsmen involved with the

to be acceptable and essentially med the requirements of State and coad Health Laws. Changes to your closure plans These closurdiremoval plans have been received and found

inderground Storage Tonk Closure Perruit Application Atomeda County Division of Mazardous Materials

ACCEPTED

1131 Halbor Bay Parkway, Suite 250 Alameda, CA \$4502-6577

State and local taxis, the project proposed herein is now reseased for insurance of any required building permits for increased by this Department are to assure compliance with

construction/destruction.

removed.

changes meet the requirements of State and local laws.

Needy the Department at least 72 hours prior to the following required inapperions:

Removed of Tank(s) and Ploing

Sampling

Final inspection

Issuance of a) permit to reperato, the permitsion delegated and all applicable laws and regulations. Any changes or alistations of those plans and spacifications must be sconisted to this this Department and to the Figs are building inspections Department to determine it subt changes meet the tequirements of State and local laws.

THERE IS A FINANCIAL PENALTY FOR NOT OSTAINING THESE INSPECTIONS:

Contact Specialist

UNDERGROUND TANK CLOSURE PLAN Complete according to attached instructions

1/		
1.	Business Name San Pablo Avenue Shell	
ť	Business Owner or Contact Person (PRINT) Ray Newsome	
2. \	Site Address 3420 San Pablo Avenue	
	City Oakland Zip 94608 Phone	·
3/	Mailing Address 1390 Willow Pass Road, Suite 900	
	City <u>Concord</u> Zip <u>94520</u> Phone <u>510-67</u>	5-6128
4.:	Land Owner Shell Oil Products Company	
	Address 1390 Willow Pass Rd. Ste 900 City, State Concord, CA Zip	94520
5.	Generator name under which tank will be manifested <u>Shell Oil Pr</u>	oducts
	Company	
	EPA I.D. No. under which tank will be manifested cap 98/4020	E88
*	Product Vigor ziping will also be tremo	

6.	Contractor Armer/Rorman & Associates
	Address 1561 3rd Avenue
	City Walnut Creek Phone 510-937-8501
	License Type * A & B ID# 256896
	*Effective January 1, 1992, Business and Professional Code Section 7058.7 requires prime contractors to also hold Hazardous Waste Certification issued by the State Contractors License Board.
7.	Consultant (if applicable) RHL Design Group, Inc. ; Zaiga Gianino
	Address 1390 Willow Pass Road, Suite 420
	City <u>Concord</u> , CA 94520 Phone <u>510-609-6300</u>
8.	Contact Person for Investigation (if applicable)
	Name Alex Perez Title Environmental Engineer
	Phone
9.	Number of tanks being closed with this plan (1 (one)
	Length of piping being removed under this plan < 75' (fuel & w/o piping)
	Total number of underground tanks at this facility (**confirmed with owner or operator) 4 (four)
LO.	State Registered Hazardous Waste Transporters/Facilities (see instructions).
• • U	nderground storage tanks must be handled as hazardous waste **
	a) Product/Residual Sludge/Rinsate Transporter
	Name <u>Crosby and Overton</u> EPA I.D. No. <u>CAD982524480</u>
	Hauler License No. 0025 License Exp. Date
	Address _8430 Amelia Street
	City Oakland State CA Zip 94621
	b) Product/Residual Sludge/Rinsate Disposal Site
	Name <u>Erickson Incorporated</u> EPA ID# <u>CAD009466392</u>
	Address 255 Parr Boulevard
	City Richmond State CA Zip 94801

c) Tank and Piping Transporter							
Name <u>Erickson Incorporated</u>	_ EPA	I.D. N	o. <u>CA</u>	D00946	6392		
Hauler License No. 0019	_	Licens	e Exp.	Date .	5-31	<u>-96</u>	
Address <u>255 Parr Boulevard</u>			· · ·			-1	
City Richmond		State _	CA	Zip	948	01	
d) Tank and Piping Disposal Site							
Name <u>Erickson Incorporated</u>	_ EPA	I.D. No	o. <u>Ca</u> l	000946	6392		
Address <u>255 Parr Boulevard</u>		 .					
City Richmond		State _	CA	Zip	948	01	
. Sample Collector							
Name <u>Scott McCloud</u>							
Company <u>Cambria Environmental Tech</u>	molo	gy, Inc.	.	··•··			
Address <u>1144 65th Street</u>							
City Oakland State CA	_ Zip	94608		Phone	510-	<u>420-0</u>	700
. Laboratory							
Name <u>Sequoia Analytical Labs</u>							
Address 404 N. Wiget Lane							
City <u>Walnut Creek</u>	st	tate <u>C</u>	<u> </u>	Zip <u>94</u>	1598		
State Certification No. 145							
. Have tanks or pipes leaked in the pa	st?	Yes[]	No[[x] [Jnknov	wn[]	
If yes, describe.							
			· · · · · ·	· · · · · ·			
		\		· · · ·	<u> </u>		

14. Describe methods to be used for rendering tank inert:

15 pounds of CO2 in the form of dry ice for each 1,000 gallons

of tank capacity will be placed in each tank.

Before tanks are pumped out and inerted, all associated piping must be flushed out into the tanks. All accessible associated piping must then be removed. Inaccessible piping must be permanently plugged.

The Bay Area Air Quality Management District, 415/771-6000, along with local Fire and Building Departments, must also be contacted for tank removal permits. Fire departments typically require the combustible gas indicator to verify tank inertness. It is the contractor's responsibility to bring a working combustible gas indicator on-site to verify that the tank is inert.

15. Tank History and Sampling Information *** (see instructions) ***

	Tank	Material to be sampled (tank contents, soil, ground water)	Location and Depth of Samples
Capacity	Use History include date last used (estimated)		
550	-Tank installed 1985 -Motor waste oil -02/97 last use date (approx.)	soil, water if applicable	(1) confirmatory samples will be taken from beneath the waste oil tank two feet below native soil/backfill interface. One sample centrally located beneath the waste oil tank and one sample of native soil under piping if required.

One soil sample must be collected for every 20 linear feet of piping that is removed. A ground water sample must be collected if any ground water is present in the excavation.

Excavated/Stockpiled Soil
Sampling Plan
One composite sample, consisting of four individual brass Planding cylinders will be analyzed for every 50 cubic words of soil. Samples will be analyzed for many thinks and the samples will be analyzed for many thinks and the samples will be analyzed for many thinks and the samples will be analyzed for many thinks and the samples will be analyzed for many thinks and the samples will be analyzed for many thinks and the samples will be analyzed for many thinks and the samples will be analyzed for many thinks and the samples will be analyzed for many thinks and the samples will be analyzed for many thinks and the samples will be analyzed for many thinks and the samples will be analyzed for many thinks and the samples will be analyzed for many thinks and the samples will be analyzed for many thinks and the samples will be analyzed for many thinks and the samples will be analyzed for many the samples will be analyzed for many thinks and the samples will be analyzed for many thinks and the samples will be analyzed for many thinks and the samples will be analyzed for many thinks and the samples will be analyzed for many the samples will be analyzed for many thinks and the samples will be analyzed for many the samples will be analyzed for the samples will be analyzed for many the samples will be analyzed for many the samples will be analyzed for the samples wi
yards of soil. Samples will be analyzed for TPHG, BIXE and
MTBE. If detectable amounts of petroleum hydrocarbons are found, samples will be tested for lead.

Stockpiled soil must be placed on bermed plastic and must be completely covered by plastic sheeting.

Will the excavated soil be returned to the excavation immediately after the tank removal? [] yes [] no [X] unknown

If yes, explain reasoning ___

If unknown at this point in time, please be aware that excavated soil may not be returned to the excavation without <u>prior</u> approval from Alameda County. This means that the contractor, consultant, or responsible party must communicate with the specialist IN ADVANCE of backfilling operations.

- 16. Chemical methods and associated detection limits to be used for analyzing samples:

 The Tri-Regional Board recommended minimum verification analyses and practical quantitation reporting limits should be followed.

 See attached Table 2.
- 17. Submit Site Health and Safety Plan (See Instructions)

Containment Sought	EPA, DHS, or Other Sample Preparation Method Number	EPA, DHS, or Other Analysis Method Number	Method Detection Limit
WASTE OIL TANK(& FUEL) PIPING TPH G TPH D TPH & BTX&E O & G BTX&E CL HC ICAP or AA	GCFID 5030, 3550, SOIL GCFID 5030, 3510, WATER	8260, 5520 D & F, 8240 or 8010 & 8020, 8270, SOIL 5520 B & F, 602, 624 or 8260 & 601, 8270, WATER	SOIL WATER 1.0 50.0 1.0 50.0 50.0 5,000.0 .005 0.5

MIBE on Kyling Samples

18. Submit Worker's Compensation Certificate copy		
Name of Insurer Republic Indemnity 19. Submit Plot Plan ***(See Instructions)***		- -
20. Enclose Deposit (See Instructions)		
21. Report any leaks or contamination to this office within discovery. The written report shall be made on an Underground St Unauthorized Leak/Contamination Site Report (ULR) form	_	
22. Submit a closure report to this office within 60 days of the ta This report must contain all the information listed in item instructions.	nk remov 1 22 of	al. the
23. Submit State (Underground Storage Tank Permit Application) For (one B form for each UST to be removed) (mark box 8 for "tank r the upper right hand corner)	cms A and emoved")	d B in
I declare that to the best of my knowledge and belief the statinformation provided above are correct and true.	tements	and
I understand that information, in addition to that provided about needed in order to obtain an approval from the Environmental Division and that no work is to begin on this project until the approved.	Protect	ion
I understand that any changes in design, materials or equipment will plan if prior approval is not obtained.	l void th	his
I understand that all work performed during this project will a compliance with all applicable OSHA (Occupational Safety a Administration) requirements concerning personnel health and sunderstand that site and worker safety are solely the responsibil property owner or his agent and that this responsibility is not assumed by the County of Alameda.	and Heal afety. itv of	lth I the
Once I have received my stamped, accepted closure plan, I will c project Hazardous Materials Specialist at least three working days of site work to schedule the required inspections.	ontact in adva	the nce
CONTRACTOR INFORMATION		
Name of Business <u>Armer/Norman & Associates</u>		
Name of Individual Bill Armen		
Signature	7	
PROPERTY OWNER OR MOST RECENT TANK OPERATOR (Circle one)		
Name of Business Shell Oil Products Company		
Name of Individual Ray Newsome, Senior Construction Engineer		
Signature X I.T. Rick Date 6/9/97 FOR RAY NEWSOME		
rev 4/6/95 - 6 -		

BASIC SITE SAFETY PLAN SAN PABLO AVENUE SHELL 3420 San Pablo Avenue Oakland, California

SITE SAFETY PLAN - WASTE OIL TANK REMOVAL

Prior to removal of tanks a "Tail Gate" safety meeting will occur.

On site safety officer: Bill Armer, Armer/Norman & Associates, (510) 937-8501.

- 1. There is (1) 550 gallon double wall fiberglass waste oil tank to be removed at this site.
- 2. Drain and flush all piping into tank or appropriate container.
- 3. Remove all flammable liquids from the tank.
- 4. Excavate to the top of the tank and disconnect all associated piping.
- 5. Prior to complete excavation and tank removal the tanks must be inerted by the following method:

The vapors in the tank will be inerted/purged by adding solid carbon dioxide (dry ice) in the minimum amount of 15 lbs. per 1000 gal. of tank capacity. The dry ice should be crushed and distributed evenly over the greatest possible area to secure rapid evaporation. As the dry ice vaporizes, flammable vapors will flow out of the tank and may surround the area. Hence, observe all normal safety precautions regarding flammable vapors. Make sure that all of the dry ice has vaporized.

After the tank has been freed of vapors and verified to below 10% of the lower explosive level using a liquid explosive level meter (l.e.l.), prior to moving it from the site, plug or cap all holes. Use threaded (boiler) plugs to plug any corrosion leak holes. One tank fitting plug should have a 1/8" vent hole to prevent the tank from being subjected to an excessive pressure differential caused by extreme temperature changes.

- 6. Temporarily plug all tank openings, complete excavation and remove the tank. USE EXTREME CAUTION DURING REMOVAL OPERATION.
- Remove tanks and secure at grade.
- 8. No fiberglass or steel tank shall be reused. Render all tanks useless after removing from site.

9. As an added precaution, regardless of condition, the anks shall be labeled adjacent to the fill opening in legible letters as follows:

"TANKS HAVE CONTAINED FLAMMABLE LIQUIDS NOT GAS-FREE NOT SUITABLE FOR FOOD OR DRINKING WATER"

- 10. Assure tank disposal is in accordance with all governing regulations.
- 11. Shell Oil Products Company Representative and Contractor shall inspect open excavation for evidence of product leakage.
- 12. The Contractor shall have the following items on site:
 - a) Fire extinguishers
 - b) LEL meter
 - c) First Aid Kit
 - d) Level D Protective Equipment:
 Chemically resistant steel toe inner boots
 Chemically protective outer boots
 Safety glasses or goggles
 Hard hat
 Face shield
 Gloves
- 13. When site is left unattended, the 6'-0" fence around the property shall be locked.

EMERGENCY PLAN

In the event of an accident, the Contractor shall proceed with the following steps:

1) / Dial 911 and provide the following information:

"THERE IS A (FIRE OR DANGEROUS SPILL) AT <u>3420 SAN PABLO AVENUE</u>, <u>OAKLAND</u>". If anyone is trapped or needs medical attention, tell the answering dispatcher. Stay on the phone and be prepared to answer any questions concerning the situation.


- 2) Attend any injured persons and direct incoming assistance to them.
- 3) Attempt to extinguish any fire, if you can do so safely. Have the extinguisher ready to use in the event of any dangerous spill. Try to contain any spill, or use absorbent on smaller spills.
- 4) Report to arriving emergency response personnel to provide them any information or assistance they may need.
- 5) Notify the following:

SHELL Representative, Ray Newsome Oakland Fire Department State Office of Emergency Services 510/675-6128 510/444-3322 800/852-7550 (24 hrs)

HOSPITAL LOCATION MAP

For Shell Oil Products Company San Pablo Avenue Shell

3420 San Pablo Avenue @ 35th Street



Nearest Hospital(s):

SUMMIT MEDICAL CENTER

350 Hawthorne Avennue Oakland, CA

KAISER PERMANENTE MEDICAL CENTER

280 West MacArthur Boulevard Oakland, CA

Nearest Trauma Center:

HIGHLAND HOSPITAL

1411 East 31st Street Oakland, CA

STATE OF CALIFORNIA DEPARTMENT OF

CONTRACTORS' STATE LICENSE BOARD

.... 256896

Issued:

3-13-69



This license is the property of the Registrar of Contractors, is not transferable, and shall be returned to the Registrar upon demand when suspended, re-voked, or invalidated for any reason. It becomes void if not



Pursuant to the provisions of Chapter 9 of Division 3 of the Business and Professions Code and the Rules and Regulations of the Contractors' State License Board, the Registrar of Contractors does hereby issue this license to:

ARMER/NORMAN & ASSOCIATES

to engage in the business or act in the capacity of a contractor in the follow-Wrecking ing classification(s):


C - 27

LANDSCAPING

Sc- 44 Solar

A В GENERAL ENGINEERING CONTRACTOR GENERAL BUILDING CONTRACTOR

WITNESS my hand and official seal this dey of April, 1981



Registrar of Contractors Signature of licensee

Signature of person who qualified on behalf of the licensee

13L-26 (REV. 6-76)

³րուդրանդրանըստրուդրանըստրուդրանըստրուդրանըստրուդրանրացրանըստրուդրանըստրուդրանրուդրանրությունը և հերանրանրանր STATE OF CALIFORNIA

STATE AND CONSUMER SERVICES AGENCY CONTRACTORS STATE LICENSE BOARD



Building Quality



HAZARDOUS SUBSTANCES REMOVAL AND REMEDIAL ACTIONS OF RTIFICATION

Pursuant to the provisions of Section 7058 7 of the Business and Professions Code, the Registrar of Contractors does hereby certify that the following qualifying person has successfully completed the hazardous substances removal and remedial actions examination.



Qualifier:

WILLIAM ALLEN ARMER

License No.:

256896

Namestyle:

ARMER/NORMAN & ASSOCIATES

NESS my hand and official seal this

MARCH, 1991

This certification is the property of the Registrar of Contractors, is not transferable, and shall be returned to the Registrar upon demand when suspended, revoked, or invalidated for any reason.

Dung & Pellin Registrar of Contractors

13L-36 (7/88)

ACORD CERTIFICATE OF INSURANCE	DAYE (MM/DD/YY)		
PRODUCER THIS CERTIFIC CONFERS NO	ATE IS ISSUED AS A MATTER OF INFORMATION ONLY AND RIGHTS UPON THE CERTIFICATE HOLDER. THIS CERTIFICATE MEND, EXTEND OR ALTER THE COVERAGE AFFORDED BY THE		
Truckee, CA 96161 916-582-3636 COMPANY A	COMPANIES AFFORDING COVERAGE		
LETTER	Republic Indemnity Co of Amer		
Armer/Norman & Associates COMPANY			
Walnut Creek COMPANY D			
CA 94596 COMPANY F			
COVERAGES			
THIS IS TO CERTIFY THAT THE POLICIES OF INSURANCE LISTED BELOW HAVE BEEN IS INDICATED, NOTWITHSTANDING ANY REQUIREMENT, TERM OR CONDITION OF ANY CONTROL OF THE INSURANCE AFFORDED BY THE EXCLUSIONS AND CONDITIONS OF SUCH POLICIES. LIMITS SHOWN MAY HAVE BEEN	ONTRACT OR OTHER DOCUMENT WITH RESPECT TO WHICH THIS POLICIES DESCRIBED HEREIN IS SUBJECT TO ALL THE TERMS,		
CO TYPE OF INSURANCE POLICY NUMBER POLICY NUMBER DATE (MM//DD	TIVE POLICY EXPRATION DATE (MM/DD/YY) LIMITS		
GENERAL LIABILITY	GENERAL AGGREGATE		
COMMERCIAL GENERAL LIABILITY	PRODUCTS-COMP/OP AGG.		
CLAIMS MADEOCCUR	PERSONAL & ADV.INJURY		
OWNER'S & CONTRACTOR'S PROT	EACH OCCURENCE		
 	FIRE DAMAGE (Any one fire)		
	MED. EXPENSE (Any one person)		
AUTOMOBILE LIABILITY ANY AUTO	COMBINED SINGLE LIMIT		
ALL OWNED AUTOS SCHEDULED AUTOS HIRED AUTOS	BODILY INJURY (Per person) BODILY INJURY		
NON-OWNED AUTOS GARAGE LIABILITY	(Per accident)		
EXCESS LIABILITY	PROPERTY DAMAGE EACH OCCURENCE		
UMBRELLA FORM	AGGREGATE		
OTHER THAN UMBRELLA FORM	Addressit		
WORKER'S COMPENSATION AND 130957-22 4/01	/97 4/01/98 EACH ACCIDENT 1,000,000		
EMPLOYER'S LIABILITY	DISEASE-POLICY LIMIT 1,000,000		
OTHER	DISEASE-EACH EMPLOYEE 1 1,000,000		
DESCRIPTION OF OPERATIONS/LOCATIONS/VEHICLES/SPECIAL ITEMS Per State Statute			
CERTIFICATE HOLDER CANCELLAT	ION:		
SHOULD ANY OF THE ABOVE DESCRIBED POLICIES BE CANCELLED BEFORE THE EXPIRATION DATE THEREOF, THE ISSUING COMPANY WILL ENDEAVOR TO MAIL 10 DAYS WRITTEN NOTICE TO THE CERTIFICATE HOLDER NAMED TO THE LEFT, BUT FAILURE TO MAIL SUCH NOTICE SHALL IMPOSE NO OBLIGATION OR LIABILITY OF ANY KIND UPON THE COMPANY, ITS AGENTS OR REPRESENTATIVES.			
1 1220 Busedown	REPRESENTATIVE 026923000 101 ACORD CORPORATION 1990		

STATE OF CALIFORNIA

STATE WATER RESOURCES CONTROL BOARD

UNDERGROUND STORAGE TANK PERMIT APPLICATION - FORM A



	CO CONTROL OF THE PARTY OF THE
1	
اد 4)	

1 NEW PERMIT 3 RENEWAL PERMIT				
MARK ONLY 1 NEW PERMIT 3 RENEWAL PERMIT ONE ITEM 2 INTERIM PERMIT 4 AMENDED PERMIT	5 CHANGE OF INFORMATION 7 PERMANENTLY CLOSED SIT	E		
I. FACILITY/SITE INFORMATION & ADDRESS - (MUST BE COMPLETED)				
Ban Pablo Avenue Shell	NAME OF OPERATOR Marcus Hasan	······		
3420 San Pablo Avenue	NEAREST CROSS STREET 35th Street PARCEL # (OPTIONAL)			
CITY NAME	STATE ZIP CODE SITE PHONE # WITH APEA CODE			
Oakland	CA 94608 510-653-5700	1_		
TO INDICATE	OCAL-AGENCY COUNTY-AGENCY STATE-AGENCY FEDERAL-AGENCY FEDERAL-AGENCY	CY'		
* If owner of UST is a public agency, complete the following: name of supervisor of division, section or office which or		<u> </u>		
TYPE OF BUSINESS 1 GAS STATION 2 DISTRIBUTOR 3 FARM 4 PROCESSOR 5 OTHER	RESERVATION OR TRUST LANDS 4 OF TANKS AT SITE E. P. A. I. D. # (optional)			
EMERGENCY CONTACT PERSON (PRIMARY)	EMERGENCY CONTACT PERSON (SECONDARY) - optional			
DAYS: NAME (LAST, FIRST) Hasan Marcus (510) (653-5709	DAYS: NAME (LAST, FIRST) MOITGOMERY, JOB (510) 653-570	a		
NIGHTS: NAME (LAST, FIRST) PHONE # WITH AREA CODE	NIGHTS: NAME (LAST, FIRST) PHONE # WITH AREA CODE			
(510)653-7995	(510)653-570	29		
II. PROPERTY OWNER INFORMATION - (MUST BE COMPLETED)				
Shell Oil Products Company	CARE OF ADDRESS INFORMATION			
MAILING OR STREET ADDRESS 1390 Willow Pass Road, Suite 900	box to indicate INDIVIDUAL LOCAL-AGENCY STATE-AGENCY CORPORATION PARTNERSHIP COUNTY-AGENCY FEDERAL-AGE			
CITY NAME	STATE ZIP_CODE PHONE # WITH AREA CODE			
Concord	CA 94520 50-675-6100			
III. TANK OWNER INFORMATION - (MUST BE COMPLETED)				
Shell Oil Products Company	CARE OF ADDRESS INFORMATION			
MAILING OR STREET ADDRESS 1390 Willow Pass Road, Suite 900	▶ box to indicate			
CONCOIC	STATE ZIP CODE PHONE # WITH AREA CODE			
I. 30-1-1-1-1-1-1-1-1-1-1-1-1-1-1-1-1-1-1-1	1.720 - 2.0			
IV. BOARD OF EQUALIZATION UST STORAGE FEE ACCOUNT NUM	MBER - Call (916) 322-9669 if questions arise.			
TY (TK) HQ [4]4-]-[0000074				
V. PETROLEUM UST FINANCIAL RESPONSIBILITY - (MUST BE CO	MPLETED) - IDENTIFY THE METHOD(S) USED			
- 00x 10 HOLDER	RETY BOND 5 LETTER OF CREDIT 6 EXEMPTION 7 STATE FUND ERTIFICATE OF DEPOSIT 10 LOCAL GOV'T, MECHANISM 99 OTHER			
VI. LEGAL NOTIFICATION AND BILLING ADDRESS Legal notification	on and billing will be sent to the tank owner unless box I or II is checked.	~		
CHECK ONE BOX INDICATING WHICH ABOVE ADDRESS SHOULD BE USED FOR LEGAL NOT	IFICATIONS AND BILLING: I II III.			
THIS FORM HAS BEEN COMPLETED UNDER PENALTY OF PERJURY, AND TO THE BEST OF MY KNOWLEDGE, IS TRUE AND CORRECT				
TANK OWNER'S NAME (PRINTED & SIGNATURE) TANK OWNER'S TITLE DATE MONTH/DAY/YEAR				
	struction Engineer 6/9/97			
LOCAL AGENCY USE ONLY				
COUNTY # JURISDICTION (FACILITY #			
LOCATION CODE - OPTIONAL CENSUS TRACT # - OPTIONAL	SUPVISOR - DISTRICT CODE - OPTIONAL			

THIS FORM MUST BE ACCOMPANIED BY AT LEAST (1) OR MORE PERMIT APPLICATION - FORM B, UNLESS THIS IS A CHANGE OF SITE INFORMATION ONLY.

OWNER MUST FILE THIS FORM WITH THE LOCAL AGENCY IMPLEMENTING THE UNDERGROUND STORAGE TANK REGULATIONS

STATE OF CALIFORNIA

STATE WATER RESOURCES CONTROL BOARD

UNDERGROUND STORAGE TANK PERMIT APPLICATION - FORM B



COMPLETE A SEPARATE FORM FOR EACH TANK SYSTEM.

MARK ONLY 1 NEW PERMIT 3 RENEWAL PERMIT 5 CHANGE OF INFORMATION 7 PERMANENTLY CLOSED ON SITE ONE ITEM 2 INTERIM PERMIT 4 AMENDED PERMIT 6 TEMPORARY TANK CLOSURE 8 TANK REMOVED
DBA OR FACILITY NAME WHERE TANK IS INSTALLED: San Pablo Avenue Shell - 3420 San Pablo Ave. Oaklar
I. TANK DESCRIPTION COMPLETE ALL ITEMS - SPECIFY IF UNKNOWN
A OWNER'S TANK I. D. # B. MANUFACTURED BY: Owens Corning
C. DATE INSTALLED (MO/DAY/YEAR) 1985 D. TANK CAPACITY IN GALLONS: 550
II. TANK CONTENTS IF A-1 IS MARKED, COMPLETE ITEM C.
A 1 MOTOR VEHICLE FUEL
D. IF (A.1) IS NOT MARKED, ENTER NAME OF SUBSTANCE STORED Motor Waste Oil C. A. S. #:
III. TANK CONSTRUCTION MARK ONE ITEM ONLY IN BOXES A, B, AND C, AND ALL THAT APPLIES IN BOX D AND E
A. TYPE OF SYSTEM 2 SINGLE WALL 3 SINGLE WALL WITH EXTERIOR LINER 5 INTERNAL BLADDER SYSTEM 95 UNKNOWN SYSTEM 2 SINGLE WALL 4 SINGLE WALL IN A VAULT 99 OTHER
B. TANK
C. INTERIOR 1 RUBBER LINED 2 ALKYD LINING 3 EPOXY LINING 4 PHENOLIC LINING LINING OR 5 GLASS LINING 5 UNLINED 95 UNKNOWN 99 OTHER COATING IS LINING MATERIAL COMPATIBLE WITH 100% METHANOL? YES NO
D. EXTERIOR CORROSION PROTECTION 1 POLYETHYLENE WRAP 2 COATING 3 VINYL WRAP PROTECTION 3 VINYL WRAP 95 UNKNOWN 99 OTHER
E. SPILL AND OVERFILL, etc. SPILL CONTAINMENT INSTALLED (YEAR) OVERFILL PREVENTION EQUIPMENT INSTALLED (YEAR) NO STRIKER PLATE YES NO DISPENSER CONTAINMENT YES NO O
IV. PIPING INFORMATION CIRCLE A IF ABOVE GROUND OR U IF UNDERGROUND, BOTH IF APPLICABLE
A. SYSTEM TYPE A U 1 SUCTION A U 2 PRESSURE AU 3 GRAVITY A U 4 FLEXIBLE PIPING A U 99 OTHER
B. CONSTRUCTION A U 1 SINGLE WALL A U 2 DOUBLE WALL A U 3 LINED TRENCH A U 95 UNKNOWN A U 99 OTHER
C. MATERIAL AND CORROSION A U 1 BARE STEEL A U 2 STAINLESS STEEL A U 3 POLYVINYL CHLORIDE (PVC) A U 4 FIBERGLASS PIPE CORROSION A U 5 ALUMINUM A U 6 CONCRETE A U 7 STEEL W/ COATING A U 8 100% METHANOL COMPATIBLE W/FRP PROTECTION A U 9 GALVANIZED STEEL A U 10 CATHODIC PROTECTION A U 95 UNKNOWN A U 99 OTHER
D. LEAK DETECTION 1 MECHANICAL LINE LEAK 2 LINE TIGHTNESS 5 CONTINUOUS INTERSTITIAL 4 ELECTRONIC LINE 5 AUTOMATIC PUMP 99 OTHER SHUTDOWN 99 OTHER
V. TANK LEAK DETECTION
1 VISUAL CHECK 2 MANUAL INVENTORY 3 VADOZE 4 AUTOMATIC TANK 5 GROUND WATER 6 ANNUAL TANK MONITORING 9 WEEKLY MANUAL 10 MONITORING 95 UNKNOWN 99 OTHER
VI. TANK CLOSURE INFORMATION (PERMANENT CLOSURE IN-PLACE)
1. ESTIMATED DATE LAST USED (MO/DAY/YR) 2. ESTIMATED QUANTITY OF SUBSTANCE REMAINING GALLONS 3. WAS TANK FILLED WITH INERT MATERIAL? YES NO ON
THIS FORM HAS BEEN COMPLETED UNDER PENALTY OF PERJURY, AND TO THE BEST OF MY KNOWLEDGE, IS TRUE AND CORRECT
TANK OWNER'S NAME (PRINTED & SIGNATURE) X S. T. Kick for Shell D: 1 Products Co. DATE 6/9/97
LOCAL AGENCY USE ONLY THE STATE I.D. NUMBER IS COMPOSED OF THE FOUR NUMBERS BELOW
STATE I.D.# COUNTY # JURISDICTION # FACILITY # TANK #
PERMIT NUMBER PERMIT APPROVED BY/DATE PERMIT EXPIRATION DATE

THIS FORM MUST BE ACCOMPANIED BY A PERMIT APPLICATION - FORM A, UNLESS A CURRENT FORM A HAS BEEN FILED. FORM C MUST BE COMPLETED FOR INSTAULATIONS. THIS FORM SHOULD BE ACCOMPANIED BY A PLOT PLAN. FILE THIS FORM WITH THE LOCAL AGENCY IMPLEMENTING THE UNDERGROUND STORAGE TANK REGULATIONS

STATE OF CALIFORNIA

STATE WATER RESOURCES CONTROL BOARD

UNDERGROUND STORAGE TANK PERMIT APPLICATION - FORM A



COMPLETE THIS FORM FOR EACH FACILITY/SITE

		
MARK ONLY 1 NEW PERMIT 3 RENEWAL PERMIT ONE ITEM 2 INTERIM PERMIT 4 AMENDED PERMIT	5 CHANGE OF INFORMATION 7 PERMANENTLY CLOSED, SIT 6 TEMPORARY SITE CLOSURE	ΓE
I. FACILITY/SITE INFORMATION & ADDRESS - (MUST BE COMPLI		
Ban Pablo Avenue Shell	Marcus Hasan	
3420 San Pablo Avenue	NEAREST CROSS STREET 35th Street PARCEL # (OPTIONAL)	
CITY NAME Oakland	STATE ZIP CODE SITE PHONE # WITH AREA CODE 510-653-5704	
✓ BOX	OCAL-AGENCY COUNTY-AGENCY STATE-AGENCY FEDERAL-AGENCY	
* If owner of UST is a public agency, complete the following: name of supervisor of division, section or office which op		
TYPE OF BUSINESS 1 GAS STATION 2 DISTRIBUTOR 3 FARM 4 PROCESSOR 5 OTHER	PESERVATION OR TRUST LANDS # OF TANKS AT SITE E. P. A. I. D. # (optional)	
EMERGENCY CONTACT PERSON (PRIMARY)	EMERGENCY CONTACT PERSON (SECONDARY) - optional	
DAYS: NAME (LAST, FIRST) PHONE # WITH AREA CODE	DAYS: NAME (LAST, FIRST) PHONE # WITH AREA CODE	
Hasan, Marcus (510) 653-5709	Montgomery, Joe (510) 653-570	ا_ ا ^م ر
NIGHTS: NAME (LAST, FIRST) PHONE # WITH AREA CODE	NIGHTS: NAME (LAST, FIRST) PHONE # WITH AREA CODE	
(510)653-7995	(510)653-570	29
II. PROPERTY OWNER INFORMATION - (MUST BE COMPLETED)	·	
Shell Oil Products Company	CARE OF ADDRESS INFORMATION	
MAILING OR STREET ADDRESS	box to indicate INDIVIDUAL LOCAL-AGENCY STATE-AGENC	OY
1390 Willow Pass Road, Suite 900	CORPORATION PARTNERSHIP COUNTY-AGENCY FEDERAL-AGE	
CONCORD	STATE ZIP CODE PHONE # WITH AREA CODE 50-675-6100	
III. TANK OWNER INFORMATION - (MUST BE COMPLETED)		7.7.
Shell Oil Products Company	CARE OF ADDRESS INFORMATION	
MAILING OR STREET ADDRESS 1390 Willow Pass Road, Suite 900	box to indicate Individual Local-agency State-agency Corporation Partnership County-agency Federal-age	
CONCORC	STATE ZIP CODE PHONE # WITH AREA CODE 510-675-6100	,
IV. BOARD OF EQUALIZATION UST STORAGE FEE ACCOUNT NUM		
TY (TK) HQ 44000074	10-10 - 10 - 10 - 10 - 10 - 10 - 10 - 1	
V. PETROLEUM UST FINANCIAL RESPONSIBILITY - (MUST BE CO		
	RETY BOND 5 LETTER OF CREDIT 6 EXEMPTION 7 STATE FUND ERTIFICATE OF DEPOSIT 10 LOCAL GOV'T. MECHANISM 99 OTHER	
VI. LEGAL NOTIFICATION AND BILLING ADDRESS Legal notification	on and billing will be sent to the tank owner unless box I or II is checked.	
CHECK ONE BOX INDICATING WHICH ABOVE ADDRESS SHOULD BE USED FOR LEGAL NOTI	IFICATIONS AND BILLING: I II III.	WEAT-11.
THIS FORM HAS BEEN COMPLETED UNDER PENALTY OF PERJURY, AN	ND TO THE BEST OF MY KNOWLEDGE, IS TRUE AND CORRECT	
	WNER'S TITLE DATE MONTH/DAY/YEAR	
X D.T. Kick for Shell O: 1 hoduets Co. Con	struction Engineer 6/9/97	
LOCAL AGENCY USE ONLY		
COUNTY # JURISDICTION #	FACILITY #	
LOCATION CODE · OPTIONAL CENSUS TRACT # - OPTIONAL	SUPVISOR - DISTRICT CODE - OPTIONAL	
	1	

STATE OF CALIFORNIA STATE WATER RESOURCES CONTROL BOARD


UNDERGROUND STORAGE TANK PERMIT APPLICATION - FORM B



COMPLETE A SEPARATE FORM FOR EACH TANK SYSTEM.

MARK ONLY 1 NEW PERMIT 3 RENEWAL PERMIT 5 CHANGE OF INFORMATION 7 PERMANENTLY CLOSED ON SITE ONE ITEM 2 INTERIM PERMIT 4 AMENDED PERMIT 6 TEMPORARY TANK CLOSURE 8 TANK REMOVED
DBA OR FACILITY NAME WHERE TANK IS INSTALLED: San Pablo Avenue Shell - 3420 San Pablo Ave. Oaklan
I. TANK DESCRIPTION COMPLETE ALL ITEMS SPECIFY IF UNKNOWN
A OWNER'S TANK I.D. # B. MANUFACTURED BY: Owen'S Corning
C. DATE INSTALLED (MO/DAY/YEAR) 1985 D. TANK CAPACITY IN GALLONS: 550
II. TANK CONTENTS IF A-1 IS MARKED, COMPLETE ITEM C.
A 1 MOTOR VEHICLE FUEL
D. IF (A.1) IS NOT MARKED, ENTER NAME OF SUBSTANCE STORED MOTOR Waste Oil C. A. S. #:
III. TANK CONSTRUCTION MARK ONE ITEM ONLY IN BOXES A, B, AND C, AND ALL THAT APPLIES IN BOX D AND E
A. TYPE OF X 1 DOUBLE WALL 3 SINGLE WALL WITH EXTERIOR LINER 5 INTERNAL BLADDER SYSTEM 95 UNKNOWN SYSTEM 2 SINGLE WALL 4 SINGLE WALL IN A VAULT 99 OTHER
B. TANK
C. INTERIOR
D. EXTERIOR
E. SPILL AND OVERFILL, etc. SPILL CONTAINMENT INSTALLED (YEAR) OVERFILL PREVENTION EQUIPMENT INSTALLED (YEAR) NO STRIKER PLATE YES NO DISPENSER CONTAINMENT YES NO OF
IV. PIPING INFORMATION CIRCLE A IF ABOVE GROUND ON U IF UNDERGROUND, BOTH IF APPLICABLE
A. SYSTEM TYPE A U 1 SUCTION A U 2 PRESSURE A U 3 GRAVITY A U 4 FLEXIBLE PIPING A U 99 OTHER
B. CONSTRUCTION A U 1 SINGLE WALL A W 2 DOUBLE WALL A U 3 LINED TRENCH A U 95 UNKNOWN A U 99 OTHER
C. MATERIAL AND A U 1 BARE STEEL A U 2 STAINLESS STEEL A U 3 POLYVINYL CHLORIDE (PVC) A (1) 4 FIBERGLASS PIPE CORROSION A U 5 ALUMINUM A U 6 CONCRETE A U 7 STEEL W/COATING A U 8 100% METHANOL COMPATIBLE W/FRP PROTECTION A U 9 GALVANIZED STEEL A U 10 CATHODIC PROTECTION A U 95 UNKNOWN A U 99 OTHER
D. LEAK DETECTION 1 MECHANICAL LINE LEAK 2 LINE TIGHTNESS 53 CONTINUOUS INTERSTITIAL 4 ELECTRONIC LINE 5 AUTOMATIC PUMP 99 OTHER 15 AUTOMATIC PUMP 99 OTHER 15 AUTOMATIC PUMP 99 OTHER
V. TANK LEAK DETECTION
1 VISUAL CHECK 2 MANUAL INVENTORY MONITORING GAUGING MONITORING 5 GROUND WATER 6 ANNUAL TANK MONITORING GAUGING MONITORING TESTING 9 WEEKLY MANUAL 10 MONTHLY TANK 9 S UNKNOWN 99 OTHER
VI. TANK CLOSURE INFORMATION (PERMANENT CLOSURE IN-PLACE)
1. ESTIMATED DATE LAST USED (MOIDAY/YR) 2. ESTIMATED QUANTITY OF SUBSTANCE REMAINING GALLONS INERT MATERIAL? 3. WAS TANK FILLED WITH YES NO Q
THIS FORM HAS BEEN COMPLETED UNDER PENALTY OF PERJURY, AND TO THE BEST OF MY KNOWLEDGE, IS TRUE AND CORRECT
TANK OWNER'S NAME (PRINTED & SIGNATURE) X S. T. Kick for Shell D: 1 Products Co. DATE 6/9/97
LOCAL AGENCY USE ONLY THE STATE I.D. NUMBER IS COMPOSED OF THE FOUR NUMBERS BELOW
COUNTY # JURISDICTION # FACILITY # TANK # STATE I.D.#
PERMIT NUMBER PERMIT APPROVED BY/DATE PERMIT EXPIRATION DATE

THIS FORM MUST BE ACCOMPANIED BY A PERMIT APPLICATION - FORM A, UNLESS A CURRENT FORM A HAS BEEN FILED. FORM C MUST BE COMPLETED FOR INSTALLATIONS. THIS FORM SHOULD BE ACCOMPANIED BY A PLOT PLAN. FILE THIS FORM WITH THE LOCAL AGENCY IMPLEMENTING THE UNDERGROUND STORAGE TANK REGULATIONS



STATE OF CALIFORNIA STATE WATER RESOURCES CONTROL BOARD

UNDERGROUND STORAGE TANK PERMIT APPLICATION - FORM B



COMPLETE A SEPARATE FORM FOR EACH TANK SYSTEM.

MARK ONLY 1 NEW PERMIT 3 RENEWAL PERMIT 5 CHANGE OF INFORMATION 7 PERMANENTLY CLOSED ON SITE ONE ITEM 2 INTERIM PERMIT 6 TEMPORARY TANK CLOSURE 4 8 TANK REMOVED
DBA OR FACILITY NAME WHERE TANK IS INSTALLED: San Pablo Avenue Shell - 3420 San Pablo Ave. Oaklan
I. TANK DESCRIPTION COMPLETE ALL ITEMS - SPECIFY IF UNKNOWN
A OWNER'S TANK I.D. # B. MANUFACTURED BY: Owens Corning
C. DATE INSTALLED (MO/DAY/YEAR) 1985 D. TANK CAPACITY IN GALLONS: 550
II. TANK CONTENTS IF A-1 IS MARKED, COMPLETE ITEM C.
A 1 MOTOR VEHICLE FUEL 4 OIL 8. C. 1a REGULAR UNLEADED 3 DIESEL 6 AVIATION GAS 2 PETROLEUM 80 EMPTY 1 PRODUCT 1b PREMIUM UNLEADED 4 GASAHOL 7 METHANOL 1 to MIOGRADE UNLEADED 5 JET FUEL 8 M95 3 CHEMICAL PRODUCT 95 UNKNOWN 2 2 WASTE 2 LEADED 99 OTHER (DESCRIBE IN ITEM D. BELOW)
D. IF (A.1) IS NOT MARKED, ENTER NAME OF SUBSTANCE STORED Motor Waste Oil C.A.S.#:
III. TANK CONSTRUCTION MARK ONE ITEM ONLY IN BOXES A, B, AND C, AND ALL THAT APPLIES IN BOX D AND E
A. TYPE OF X 1 DOUBLE WALL 3 SINGLE WALL WITH EXTERIOR LINER 5 INTERNAL BLADDER SYSTEM 95 UNKNOWN SYSTEM 2 SINGLE WALL 4 SINGLE WALL IN A VAULT 99 OTHER
B. TANK
C. INTERIOR
D. EXTERIOR
D/ PIDING WEADON
A. SYSTEM TYPE A U 1 SUCTION A U 2 PRESSURE A(U)3 GRAVITY A U 4 FLEXIBLE PIPING A U 99 OTHER B. CONSTRUCTION A U 1 SINGLE WALL A U 3 LINED TRENCH A U 95 UNKNOWN A U 99 OTHER
C. MATERIAL AND A U 1 BARE STEEL A U 2 STAINLESS STEEL A U 3 POLYVINYL CHLORIDE (PVC) A U 4 FIBERGLASS PIPE CORROSION A U 5 ALUMINUM A U 6 CONCRETE A U 7 STEEL W COATING A U 8 100% METHANOL COMPATIBLE W/FRP PROTECTION A U 9 GALVANIZED STEEL A U 10 CATHODIC PROTECTION A U 95 UNKNOWN A U 99 OTHER
D. LEAK DETECTION 1 MECHANICAL LINE LEAK 2 LINE TIGHTNESS 5 CONTINUOUS INTERSTITIAL 4 ELECTRONIC LINE 15 AUTOMATIC PUMP 99 OTHER 99 OTHER 99 OTHER
V. TANK LEAK DETECTION
1 VISUAL CHECK 2 MANUAL INVENTORY 3 VADOZE 4 AUTOMATIC TANK 5 GROUND WATER 5 GROU
VI. TANK CLOSURE INFORMATION (PERMANENT CLOSURE IN-PLACE)
1. ESTIMATED DATE LAST USED (MO/DAY/YR) 2. ESTIMATED QUANTITY OF SUBSTANCE REMAINING GALLONS INERT MATERIAL? 2. ESTIMATED QUANTITY OF GALLONS INERT MATERIAL? NO 🔯
THIS FORM HAS BEEN COMPLETED UNDER PENALTY OF PERJURY, AND TO THE BEST OF MY KNOWLEDGE, IS TRUE AND CORRECT
TANK OWNER'S NAME (PRINTED & SIGNATURE) X O. T. Lik for Shell D: 1 Products Co. DATE 6/9/97
LOCAL AGENCY USE ONLY THE STATE I.D. NUMBER IS COMPOSED OF THE FOUR NUMBERS BELOW
STATE I.D.# COUNTY # JURISDICTION # FACILITY # TANK #
PERMIT NUMBER PERMIT APPROVED BY/DATE PERMIT EXPIRATION DATE

1 WAST OIL TANK REMOVED 6/26/97
STATE WATER RESOURCES CONTROL BOARD

STATE WATER RESOURCES CONTROL BOARD

UNDERGROUND STORAGE TANK PERMIT APPLICATION - FORM A

COMPLETE THIS FORM FOR EACH FACILITY/SITE

MARK ONLY 1 NEW PERMIT 3 RENEWAL PERMIT ONE ITEM 2 INTERIM PERMIT 4 AMENDED PERMIT	5 CHANGE OF INFORMATION 7 PERMANENTLY CLOSED SITE 6 TEMPORARY SITE CLOSURE			
I. FACILITY/SITE INFORMATION & ADDRESS - (MUST BE COMPLETED)				
DBA OR FACILITY NAME	Marcus Hasan			
ADDRESS	NEAREST CROSS STREET PARCEL # (OPTIONAL)			
3420 San Pablo Avenue	STATE ZIP CODE SITE PHONE # WITH AREA CODE			
Oakland	CA 94608 510-653-5709			
BOX CORPORATION MOIVIDUAL PARTNERSHIP LOCAL-AGENCY COUNTY-AGENCY STATE-AGENCY PEDERAL-AGENCY				
* If owner of UST is a public agency, complete the following: name of supervisor of division, section or office which op TYPE OF BUSINESS 27 1 GAS STATION 2 DISTRIBUTOR	A It lidnivit is Or iviting by gure entitle ment following			
TYPE OF BUSINESS 1 GAS STATION 2 DISTRIBUTOR 3 FARM 4 PROCESSOR 5 OTHER	OR TRUST LANDS			
EMERGENCY CONTACT PERSON (PRIMARY)	EMERGENCY CONTACT PERSON (SECONDARY) - optional			
PHONE # WITH AREA CODE	DAYS: NAME (LAST, FIRST) PHONE # WITH AREA CODE			
Hagan Marcus (50) 655-5109_	Montgomery JOB (510) 653-5709 MIGHTS: NAME (LAST FIRST) PHONE WITH AREA CODE			
NIGHTS: NAME (LAST, FIRST) PHONE # WITH AREA CODE (510) 653-7995	NIGHTS: NAME (LAST, FIÁST) PHONE # WITH AREA CODE (510) 653 - 5709			
II. PROPERTY OWNER INFORMATION - (MUST BE COMPLETED)	CARE OF ADDRESS INFORMATION			
Shell Oil Products Company	OTAL S. FIRST CO.			
2.101. 0.1.	V DOX 10 INGCOLO INDIVIDUAL LOCAL-AGENCY STATE-AGENCY CORRECTION PARTICIPAL COLINTY-AGENCY FEDERAL-AGENCY			
1390 Willow Pass Road, Suite 900	CONPORATION THANKE THE PROPERTY OF THE PROPERT			
CITY NAME	STATE ZIP CODE 94520 SD-675-6100			
CONCORD INCORNATION - (MUST BE COMPLETED)				
III. TANK OWNER INFORMATION - (MUST BE COMPLETED)	CARE OF ADDRESS INFORMATION			
Shell Oil Products Company	✓ box to indicate			
MAILING OR STREET ADDRESS 1390 Willow Pass Road, Suite 900	CORPORATION PARTNERSHIP COUNTY-AGENCY FEDERAL-AGENCY			
CITY NAME	STATE ZIP CODE PHONE # WITH AREA CODE 510 - 675-6100			
[(m/orc)				
IV. BOARD OF EQUALIZATION UST STORAGE FEE ACCOUNT NU	MBER - Call (916) 322-9669 if questions arise.			
TY (TK) HQ 4 4- 000074				
V. PETROLEUM UST FINANCIAL RESPONSIBILITY - (MUST BE CO	OMPLETED) - IDENTIFY THE METHOD(S) USED			
	SURETY BOND 5 LETTER OF CREDIT 6 EXEMPTION 7 STATE FUND			
8 STATE FUND & CHIEF FINANCIAL OFFICER LETTER 9 STATE FUND &	CERTIFICATE OF DEPOSIT 10 LOCAL GOVT, MECHANISM 98 OTHER			
TIL ELGARITOTII TOTTI	tion and billing will be sent to the tank owner unless box I or II is checked.			
CHECK ONE BOX INDICATING WHICH ABOVE ADDRESS SHOULD BE USED FOR LEGAL NOTIFICATIONS AND BILLING:				
THIS FORM HAS BEEN COMPLETED UNDER PENALTY OF PERJURY, AND TO THE BEST OF MY KNOWLEDGE, IS TRUE AND CORRECT				
TANK OWNER'S NAME (PRINTED & SIGNATURE) TANK OWNER'S TITLE DATE MONTH/DAY/YEAR				
X S.T. Kik for Shell 0: 1 hoduts Co. Construction Engineer 6/9/97				
LOCAL AGENCY USE ONLY HUBISDICTION # FACILITY #				
COUNTY # JURISDICTIO	N#			
	, , , , , , , , , , , , , , , , , , , ,			
LOCATION CODE - OPTIONAL CENSUS TRACT # - OPTIONAL	SUPVISOR • DISTRICT CODE • OPTIONAL			

SHELL OIL CORPORATION

QUARTERLY REPORT TO

THE CALIFORNIA REGIONAL WATER QUALITY CONTROL BOARD

	204 5509 5206
Service Station WIC Number: Site Address (Number, Street):	204-5508-5306 3420 San Pablo
City:	Oakland
County:	_Alameda
Actions in the past three months:	
Collected 1st quarter ground water samples and su	abmited 1st quarter monitoring report
Collected 1st quarter ground water samples and su Actions planned for next three months:	abmited 1st quarter monitoring report
	abmited 1st quarter monitoring report
Actions planned for next three months: Submit 2nd quarter monitoring report.	
Actions planned for next three months: Submit 2nd quarter monitoring report. Soil Contamination defined? Y\N	N
Actions planned for next three months: Submit 2nd quarter monitoring report. Soil Contamination defined? Y\N Soil Clean-up in progress? Y\N	
Actions planned for next three months:	N N
Actions planned for next three months: Submit 2nd quarter monitoring report. Soil Contamination defined? Y\N Soil Clean-up in progress? Y\N Free-product plume defined? Y\N	N N NA

ALAMEDA COUNTY HEALTH CARE SERVICES

AGENCY



DAVID J. KEARS, Agency Director

RAFAT A. SHAHID, DIRECTOR

April 18, 1996

Mr. R Jeff Granberry Shell Oil Products Company P.O. Box 4023 Concord, California 94524 DEPARTMENT OF ENVIRONMENTAL HEALTH 1131 Harbor Bay Parkway Alameda, CA 94502-6577 (510) 567-6777

RE: Shell Oil Company Sites

Dear Mr. Granberry:

Recently, reports for the Shell Oil Company sites have been submitted to different inspectors / case officers that are not the assigned case workers. I'm currently overseeing the investigation / cleanup of the following Shell Oil Company sites in this department:

STID#	Site Name	Address	
3670 814 381 3613 413 3673 3618	Melina Albany Shell Bay Super Shell Shell Oil Company Former Shell Oil Pill Hill Shell Shell Service Station Broadway Shell	999 San Pablo Avenue, Albany 1800 Powell Street, Emeryvill 3420 San Pablo Ave., Oakland 500 40th Street, Oakland 2800 Telegraph Ave., Oakland 230 W MacArthur Blvd., Oaklan 5755 Broadway, Oakland	R006

Please inform your consultants that all quarterly monitoring reports and work plans for the above mentioned sites should be submitted to my attention.

If you have any questions concerning this letter, please call me at (510) 567-6780.

Sincerely,

Susan L. Hugo

Susan Z-Hugo

Senior Hazardous Materials Specialist

c: Jun Makishima, Interim Director, Environmental Health Gordon Coleman, Acting Chief, Environmental Protection / files 5500 Shellmound Street, Emeryville, CA 94608-2411

Fax: 510-547-5043 Phone: 510-450-6000

Jeff Granberry

March 1, 1995

Dennis Byrne Alameda County Department of Environmental Health 1131 Harbor Bay Parkway, Suite 250 Alameda, California 94502-6577

Re: Shell Service Station WIC #204-5508-5306 3420 San Pablo Avenue

> Oakland, California WA Job #81-0612-105

Dear Mr. Byrne:

This letter describes recently completed and anticipated activities at the Shell service station referenced above (Figure 1.) This status report satisfies the quarterly reporting requirements prescribed by California Administrative Code Title 23 Waters, Chapter 3, Subchapter 16, Article 5, Section 2652.d. Included below are descriptions and results of activities performed in the first quarter 1995 and proposed work for the second quarter 1995.

Hydrocarbon Removal	Pounds Removed	Cumulative Pounds	
Summary	Past Quarter	Removed	
Separate-phase Hydrocarbon	0.44	18.54	

First Quarter 1995 Activities:

- Blaine Tech Services (BTS) of San Jose, California measured ground water depths and collected ground water samples from the wells. BTS' report describing these activities and the analytic report for the ground water samples are included as Attachment A.
- BTS removed a total of 0.44 pounds of separate-phase hydrocarbons (SPH) from skimmers in wells MW-4 and MW-7 and bailed SPH from well MW-6 this quarter (Table 1). To date, approximately 18.54 pounds of SPH have been removed by skimmers and additional bailing.
- Weiss Associates (WA) prepared a ground water elevation contour map for wells screened in the first water bearing zone (Figure 2). Since wells MW-1, MW-3, MW-4



and MW-5 are screened slightly deeper than the other site wells, these wells are contoured separately (Figure 3).

Anticipated Second Quarter 1995 Activities:

- WA will submit a report presenting the results of the second quarter 1995 ground water sampling and ground water depth measurements. The report will include tabulated chemical analytic results, SPH removal data and ground water elevation contour maps.
- SPH skimmers are installed in wells MW-4, MW-4 and MW-7. The skimmers will be purged of hydrocarbons quarterly until no SPH are measured in these wells. SPH volumes removed will be tabulated in subsequent quarterly status reports.

Conclusions and Recommendations:

In most wells, ground water elevations have increased from 1.8 to 5.1 ft above ground water elevations recorded last quarter. This elevation increase has resulted in the reversal of the apparent ground water flow direction of the upper water-bearing zone beneath the northern portion of the site compared to fourth quarter 1994. We will monitor ground water elevations in upcoming quarters to assess whether this trend continues.

Please call if you have any questions.

Sincerely, Weiss Associates

sətsiəossA ssiəW

Grady S. Glasser Technical Assistant

ו בכוווווכעו עיפיפומווי

James W. Carmody, C.E.G. Senior Project Hydrogeologist

Attachments:

:00

Dan Kirk, Shell Oil Company, P.O. Box 4023, Concord, California 94524 Lisa McCann, California Regional Water Quality Control Board, San Francisco Bay Region, 2101 Webster

A - BTS' Ground Water Monitoring Report

Street, Suite 500, Oakland, California 94612

No. EG 1576 CERTIFIED ENGINEERING егентумняюн вос





Figure 2. Monitoring Well Locations and Ground Water Elevation Contours, Upper Water-Bearing Zone - January 3, 1995 - Shell Service Station WIC #204-5508-5306, 3420 San Pablo Avenue, Oakland, California



Oakland, California January 3, 1995 - Shell Service Station WIC #204-5508-5306, 3420 San Pablo Avenue, Figure 3. Monitoring Well Locations and Ground Water Elevation Contours, Lower Water-Bearing Zone -

Inferred ground water flow direction

11 01



5500 Shellmound Street, Emeryville, CA 94608-2411

Fax: 510-547-5043 Phone: 510-547-5420

December 21, 1994

Dennis Byrne
Alameda County Department of
Environmental Health
1131 Harbor Bay Parkway,
Suite 250
Alameda, California 94502-6577



Re: Shell Service Station WIC #204-5508-5306 3420 San Pablo Avenue Oakland, California WA Job #81-0612-104

Dear Mr. Byrne:

This letter describes recently completed and anticipated activities at the Shell service station referenced above (Figure 1.) This status report satisfies the quarterly reporting requirements prescribed by California Administrative Code Title 23 Waters, Chapter 3, Subchapter 16, Article 5, Section 2652.d. Included below are descriptions and results of activities performed in the fourth quarter 1994 and proposed work for the first quarter 1995.

Hydrocarbon Removal	Pounds Removed Fourth	Cumulative Pounds	
Summary	Quarter 1994	Removed	
Separate-phase Hydrocarbon	3.33	18.10	

Fourth Quarter 1994 Activities:

- Blaine Tech Services (BTS) of San Jose, California measured ground water depths and collected ground water samples from the wells. BTS' report describing these activities and the analytic report for the ground water samples are included as Attachment A.
- BTS removed a total of 3.33 pounds of separate-phase hydrocarbons (SPHs) from skimmers in wells MW-4 and MW-7 and bailed SPHs from well MW-6 this quarter (Table 1). To date, approximately 18.10 pounds of SPHs have been removed by skimmers and additional bailing.

Weiss Associates (WA) prepared a ground water elevation contour map for wells screened in the first water bearing zone (Figure 2). Since wells MW-1, MW-3, MW-4 and MW-5 are screened slightly deeper than the other site wells, these wells are contoured separately (Figure 3).

Anticipated First Quarter 1995 Activities:

- WA will submit a report presenting the results of the first quarter 1995 ground water exampling and ground water depth measurements. The report will include tabulated chemical analytic results, SPH removal data and ground water elevation contour maps.
- SPH skimmers are installed in wells MW-2, MW-4 and MW-7. The skimmers will be purged of hydrocarbons quarterly until no SPHs are measured in these wells. SPH volumes removed will be tabulated in subsequent quarterly status reports.

Conclusions and Recommendations:

In most wells ground water elevations have decreased. This elevation decrease still continues to result in the reversal of the apparent ground water flow direction beneath the northern portion of the site compared to second quarter 1993. We will monitor ground water elevations in upcoming quarters to assess whether this trend continues.

Please call if you have any questions.

GEOLOGIST ENGINEERING

No. EG 1576 CERTIFIED

Sincerely,
Weiss Associates

1. Somme

J. Michael Asport Staff Scientist I

James W. Carmody, C.E.G. (
Senior Project Hydrogeologist

A - BTS' Ground Water Monitoring Report

Attachments:

:၁၁

Dan Kirk, Shell Oil Company, P.O. Box 4023, Concord, California 94524
Lisa McCann, California Regional Water Quality Control Board, San Francisco Bay Region, 2101 Webster
Street, Suite 500, Oakland, California 94612

JMA/JWC:jma




Figure 2. Monitoring Well Locations and Ground Water Elevation Contours, Lower Water-Bearing Zone -October 27, 1994 - Shell Service Station WIC #204-5508-5306, 3420 San Pablo Avenue, Oakland, California




Figure 3. Monitoring Well Locations and Ground Water Elevation Contours, Lower Water-Bearing Zone - October 27, 1994 - Shell Service Station WIC #204-5508-5306, 3420 San Pablo Avenue, Oakland, California



5500 Shellmound Street, Emeryville, CA 94608-2411

Fax: 510-547-5043 Phone: 510-450-6000

October 4, 1994

Dennis Byrne
Alameda County Department of
Environmental Health
1131 Harbor Bay Parkway,
Suite 250
Alameda, California 94502-6577

5110381

Re: Shell Service Station WIC #204-5508-5306 3420 San Pablo Avenue Oakland, California WA Job #81-0612-104 PLAZMAT

Dear Mr. Byrne:

This letter describes recently completed and anticipated activities at the Shell service station referenced above (Figure 1.) This status report satisfies the quarterly reporting requirements prescribed by California Administrative Code Title 23 Waters, Chapter 3, Subchapter 16, Article 5, Section 2652.d. Included below are descriptions and results of activities performed in the third quarter 1994 and proposed work for the fourth quarter 1994.

Hydrocarbon Removal	Pounds Removed Second	Cumulative Pounds
Summary	Quarter 1994	Removed
Separate-phase Hydrocarbon	0.07	14.77

Third Quarter 1994 Activities:

• Blaine Tech Services (BTS) of San Jose, California measured ground water depths and collected ground water samples from the wells. BTS' report describing these activities and the analytic report for the ground water samples are included as Attachment A.



- BTS removed a total of 0.07 pounds of separate-phase hydrocarbons (SPHs) from a skimmer in well MW-7 and bailed SPHs from well MW-6 this quarter (Table 1). To date, approximately 14.77 pounds of SPHs have been removed by skimmers and additional bailing.
- Weiss Associates (WA) prepared a ground water elevation contour map for wells screened in the first water bearing zone (Figure 2). Since wells MW-1, MW-3, MW-4 and MW-5 are screened slightly deeper than the other site wells, these wells are contoured separately (Figure 3).

Anticipated Fourth Quarter 1994 Activities:

- WA will submit a report presenting the results of the fourth quarter 1994 ground water sampling and ground water depth measurements. The report will include tabulated chemical analytic results, SPH removal data and ground water elevation contour maps.
- SPH skimmers are installed in wells MW-2, MW-4 and MW-7. The skimmers will be purged of hydrocarbons quarterly until no SPHs are measured in these wells. SPH volumes removed will be tabulated in subsequent quarterly status reports.

Conclusions and Recommendations:

In most wells ground water elevations have decreased. This elevation decrease still continues to result in the reversal of the apparent ground water flow direction beneath the northern portion of the site compared to second quarter 1993. We will monitor ground water elevations in upcoming quarters to assess whether this trend continues.




Figure 2. Monitoring Well Locations and Ground Water Elevation Contours, Upper Water-Bearing Zone - July 19, 1994 - Shell Service Station WIC #204-5508-5306, 3420 San Pablo Avenue, Oakland, California




Figure 3. Monitoring Well Locations and Ground Water Elevation Contours, Lower Water-Bearing Zone - July 19, 1994 - Shell Service Station WIC #204-5508-5306, 3420 San Pablo Avenue, Oakland, California

10/05/94




Figure 2. Monitoring Well Locations and Ground Water Elevation Contours, Upper Water Bearing Zone -April 13, 1994 - Shell Service Station WIC #204-5508-5306, 3420 San Pablo Avenue. Oakland, California




Figure 3. Monitoring Well Locations and Ground Water Elevation Contours, Lower Water Bearing Zone -April 13, 1994 - Shell Service Station WIC #204-5508-5306, 3420 San Pablo Avenue,

s612-012.al



5500 Shellmound Street, Emeryville, CA 94608-2411

Fax: 510-547-5043 Phone: 510-547-5420

94 JUL 12 PH 4: 45

June 22, 1994

Dennis Byrne
Alameda County Department of
Environmental Health
80 Swan Way, Room 200
Oakland, California 94621-1426

5038

Re: Shell Service Station

WIC #204-5508-5306 ~ 3420 San Pablo Avenue

Oakland, California WA Job #81-612-104 04608

Dear Mr. Byrne:

This letter describes recently completed and anticipated activities at the Shell service station referenced above (Figure 1.) This status report satisfies the quarterly reporting requirements prescribed by California Administrative Code Title 23 Waters, Chapter 3, Subchapter 16, Article 5, Section 265.d. Included below are descriptions and results of activities performed in the quarter 1994 and proposed work for the third quarter 1994.

Hydrocarbon Removal	Pounds Removed Second	Cumulative Pounds	
Summary	Quarter 1994	Removed	
Separate-phase Hydrocarbon	0.9	14.82	

Second Quarter 1994 Activities:

• Blaine Tech Services (BTS) of San Jose, California measured ground water depths and collected ground water samples from the wells. BTS' report describing these activities and the analytic report for the ground water samples are included as Attachment A.



- BTS removed a total of 0.17 gallons of separate-phase hydrocarbons (SPHs) from skimmers in wells MW-1 and MW-4 and bailed SPHs from wells MW-5, MW-6 and MW-7 this quarter (Table 1). To date, approximately 2.47 gallons of SPHs have been removed by skimmers and additional bailing.
- Weiss Associates (WA) prepared a ground water elevation contour map for wells screened in the first water bearing zone (Figure 2). Since wells MW-1, MW-3, MW-4 and MW-5 are screened slightly deeper than the other site wells, these wells are contoured separately (Figure 3).

Anticipated Third Quarter 1994 Activities:

- WA will submit a report presenting the results of the third quarter 1994 ground water sampling and ground water depth measurements. The report will include tabulated chemical analytic results, SPH removal data and ground water elevation contour maps.
- SPH skimmers are installed in wells MW-1, MW-2, and MW-4. The skimmers will be purged of hydrocarbons quarterly until no SPHs are measured in these wells. Hydrocarbon volumes purged will be tabulated in subsequent quarterly status reports.

Conclusions and Recommendations:

Ground water elevations have increased. This elevation increase still continues to result in the reversal of the apparent ground water flow direction beneath the northern portion of the site compared to second quarter 1993. We will monitor ground water elevations in upcoming quarters to assess whether this trend continues.







5500 Shellmound Street, Emeryville, CA 94608-2411

Fax: 510-547-5043 - Phone: 510-450-6000

94 APR 14 PM 12: 34

April 8, 1994

Dennis Byrne
Alameda County Department of
Environmental Health
80 Swan Way, Room 200
Oakland, California 94621-1426

STO 381

Re: Shell Service Station

WIC #204-5508-5306 3420 San Pablo Avenue Oakland, California WA Job #81-612-104

Dear Mr. Byrne:

This letter describes recently completed and anticipated activities at the Shell service station referenced above (Figure 1.) This status report satisfies the quarterly reporting requirements prescribed by California Administrative Code Title 23 Waters, Chapter 3, Subchapter 16, Article 5, Section 265.d. Included below are descriptions and results of activities performed in the first quarter 1994 and proposed work for the second quarter 1994.

First Quarter 1994 Activities:

- Weiss Associates (WA) evaluated the results of a soil vapor extraction (SVE) test conducted at the site. The SVE test results, which are enclosed with this report as Attachment A, concludes that SVE may be a viable remedial alternative at this site.
- Blaine Tech Services (BTS) of San Jose, California measured ground water depths in all eleven site wells and collected ground water samples from the wells. BTS' report describing these activities and presenting analytic results for ground water is included as Attachment B.



- BTS removed < 0.02 gallons of floating hydrocarbons from skimmers in wells MW-1 and To date, approximately 2.29 gallons of floating MW-4 this quarter (Table 1). hydrocarbons have been removed by bailing and by floating hydrocarbon skimmers.
- WA prepared a ground water elevation contour map for wells screened in the first water bearing zone (Figure 2). Since wells MW-1, MW-3, MW-4 and MW-5 are screened slightly deeper than the other site wells, these wells are contoured separately (Figure 3).

Anticipated Second Quarter 1994 Activities:

- WA will submit a report presenting the results of the second quarter 1994 ground water sampling and ground water depth measurements. The report will include tabulated chemical analytic results, floating hydrocarbon removal data and ground water elevation contour maps.
- Floating hydrocarbon skimmers are installed in wells MW-1, MW-2, and MW-4. skimmers will be purged of hydrocarbons quarterly until no floating hydrocarbons are measured in these wells. Hydrocarbon volumes purged will be tabulated in subsequent quarterly status reports.

Conclusions and Recommendations:

Ground water elevations have increased. This elevation increase still continues to result in the reversal of the apparent ground water flow direction beneath the northern portion of the site compared to second quarter 1993. We will monitor ground water elevations in upcoming quarters to assess whether this trend continues.

Floating hydrocarbon thickness decreased compared to last quarter. WA will monitor the floating hydrocarbon thickness and begin monthly floating hydrocarbon purging if the skimmers are not effectively removing floating hydrocarbons.






Figure 2. Monitoring Well Locations and Ground Water Elevation Contours, Upper Water Bearing Zone -October 13, 1993 - Shell Service Station WIC #204-5508-5306, 3420 San Pablo Avenue, Oakland, California






Figure 3. Monitoring Well Locations and Ground Water Elevation Contours, Lower Water Bearing Zone - October 13, 1993 - Shell Service Station WIC #204-5508-5306, 3420 San Pablo Avenue, Oakland, California

S612-006.ai






Figure 1. Site Location Map - Shell Service Station WIC #204-5508-5306, 3420 San Pablo Avenue, Oakland, California



Fax: 510-547-5043 Phone: 510-450-6000

January 27, 1994

Dan Kirk Shell Oil Company P.O. Box 5278 Concord, California 94520-9998

> Re: Soil Vapor Extraction Test Results Shell Service Station WIC #204-5508-5306 3420 San Pablo Avenue Oakland, California WA Job #81-612-88

Dear Mr. Kirk:

This letter presents the results of Weiss Associates' (WA) soil vapor extraction (SVE) test at the Shell service station referenced above (Figure 1) on November 16, 1993. The test protocol, results, and conclusions are described below.

Test Protocol

We used a VR System V3 engine to test wells MW-1, MW-2, MW-4 and MW-6 individually for 15 minutes each to assess which wells could produce the most vapor-phase hydrocarbons. Based on these short test, we selected wells MW-1 and MW-6 for longer-term testing. While performing the SVE test on MW-1, we monitored vacuum influence in wells MW-3 and MW-4. During the SVE test on MW-6, we monitored vacuum influence in well MW-2. Nearby well MW-11 was not monitored because it was in the street and could not be accessed safely.

Test Results

During extraction from each well, we adjusted the vacuum applied to maximize the flow rate from the well and to avoid pulling ground water into the SVE system. The applied vacuum ranged from 40 to 64 inches of water. The achieved vapor flow rates ranged from 8 to 19 scfm. The hydrocarbon concentrations in soil vapor ranged from 1,400 to 4,500 ppmv TPH-G based on laboratory analytic results, while TPH-G removal rates ranged from 7 to 32 pounds per day.

Mr. Dan Kirk January 27, 1994



The 9,000 ppmv methane detected in soil vapor extracted from well MW-6 may suggest anaerobic biologic activity in the subsurface.

The vacuum influence data during extraction from well MW-1 suggests that the actual radius of influence extends beyond 30 ft. However the relatively small measured influence suggests that the effective radius of influence may be less than 30 ft. The vacuum influence data during extraction from MW-6 is unreliable since the measured vacuum may be attributed to residual vacuum from testing of MW-2 earlier in the day.

Test Conclusions

Based on these test results, SVE may remove vapor-phase hydrocarbons from the subsurface at moderate rates. However, the benzene removal may be negligible since no benzene was detected in the extracted soil vapor. If you implement SVE at this site, the achievable vapor flow rates will be limited by the ground water upwelling in the extraction wells and the shallow depth of water.

We appreciate this opportunity to provide hydrogeologic consulting services to Shell. Please call Bob Clark-Riddell or Scott MacLeod if you have any questions.

Sincerely, Weiss Associates

Joyce E. Adams Senior Staff Geologist

super E. adams

Bob Clark-Riddell, P.E. Project Engineer

Bob-Clark-fiddell

JEA/BGR:jca

J:\HC ENG\SHELL\OAK-612\612L1DE3.WP




Figure 1. Well Location Map and Vacuum Measurements - Shell Service Station WIC #204-5508-5306, 3420 San Pablo Avenue, Oakland, California

Table 1. Soil Vapor Extraction Test Data - Shell Service Station WIC# 204-5508-5306, 3420 San Pablo, Oakland, California

EXPOSED						INLET CONCENTRATION						SS RI	EMOVAL (b)	VACUUM INFLUENCE			
WELL DEPTH (a) APPLIE	VACUUM APPLIED (inches H2O)	FLOW RATE (scfm)	ELAPSED TIME (min)	-	FID <	TPH-G				TPH-0		BENZENE (lb/day)	WELL ID	DISTANCE (ft)	VACUUM ("H2O)		
MW-1	5 - 10.6	60	9	5	>	10,000				>	29		0.0	MW-3 MW-4	68 30	0.00 0.02	
MW-1	5 - 10.6	64	8	180	>	10,000	2,900	<	4		7	<	0.01	MW-3 MW-4	68 30	0.00	-
MW-2	4 10.4	40	10	3	>	10,000				>	32		0.0				
MW-2	4 10.4	40	9	10	>	10,000	***			>	29		0.0		***		
MW-4	5 - 11.4	55	4	14	>	10,000			,	>	13		0.0				
MW-6	5 - 12.3	51	15	9	>	7,600	4,500	<	2		22	<		MW-2	83	0.05	(c)
MW-6	5 - 12.3	51	19	81	>	1,000	1,400	<	2 .		9	<	0.05	MW-2	83	0.04	(c)

Notes:

(a) = Depth interval below ground surface between top of well screen and ground water.

(b) = Mass removal rate based on Bay Area Air Quality Management District's Manual of Procedures for Soil Vapor Extraction, July 17, 1991.

Rate = concentration(ppmv) x flow rate(scfm) x (1 lb-mole/386 cu ft) x molecular weight (86 lb/lb-mole for TPH-G as hexane, 78 for benzene) x 1,440 minutes/day x 0.000001.

(c) = Data may be unreliable since well was used for extraction testing earlier during test.

FID = Portable flame ionization detector measurements. MW-6 measurements are less the methane reading of 2,400 ppmv and 9,000 ppmv, respectively.

TPH-G = Total petroleum hydrocarbons by EPA Method 5030.

BENZENE = Benzene by EPA Method 8020.

scfm = Standard cubic feet per minute.

ppmv = Parts per million by volume.

--- = Data not reliable or representative.




Figure 2. Monitoring Well Locations and Ground Water Elevation Contours, Upper Water Bearing Zone - January 20, 1994 - Shell Service Station WIC #204-5508-5306, 3420 San Pablo Avenue, Oakland, California




Figure 3. Monitoring Well Locations and Ground Water Elevation Contours, Lower Water Bearing Zone -January 20, 1994 - Shell Service Station WIC #204-5508-5306, 3420 San Pablo Avenue,

s612-010.ai



Fax: 510-54 2-5849 Whome: 510-450-6000

94 JAN 18 PM 2: 47

January 13, 1994

Dennis Byrne Alameda County Department of Environmental Health 80 Swan Way, Room 200 Oakland, California 94621-1426 STIPZP

Re: Shell Service Station
WIC #204-5508-5306
3420 San Pablo Avenue
Oakland, California
WA Job #81-612-203

Dear Mr. Byrne:

This letter describes recently completed and anticipated activities at the Shell service station referenced above (Figure 1.) This status report satisfies the quarterly reporting requirements prescribed by California Administrative Code Title 23 Waters, Chapter 3, Subchapter 16, Article 5, Section 265.d. Included below are descriptions and results of activities performed in the fourth quarter 1993 and proposed work for the first quarter 1994.

Fourth Quarter 1993 Activities:

- Blaine Tech Services (BTS) of San Jose, California measured ground water depths in all eleven site wells and collected ground water samples from seven of the Wells MW-1, MW-4, MW-5 and MW-6 contained floating hydrocarbons and were not sampled. BTS' report describing these activities and presenting analytic results for ground water is included as Attachment A.
- BTS purged a total of 0.14 gallons of floating hydrocarbons from skimmers in wells MW-1 and MW-4 this quarter (Table 1). To date, approximately 2.27 gallons of floating hydrocarbons have been removed by bailing and by floating hydrocarbon skimmers.
- WA prepared a ground water elevation contour map for wells screened in the first water bearing zone (Figure 2). Since wells MW-1, MW-3, MW-4 and MW-5 are screened slightly deeper than the other site wells, these wells are contoured separately (Figure 3).
- WA conducted a soil vapor extraction test on November 16, 1993 to assess whether SVE is a viable remedial option for this site. Results of this test will be submitted shortly under separate cover.



Anticipated First Quarter 1994 Activities:

- WA will submit a report presenting the results of the first quarter 1994 ground water sampling and ground water depth measurements. The report will include tabulated chemical analytic results, floating hydrocarbon removal data and ground water elevation contour maps.
- Floating hydrocarbon skimmers are installed in wells MW-1, MW-2, MW-4 and MW-6. The skimmers will be purged of hydrocarbons quarterly until no floating hydrocarbons are measured in these wells. Hydrocarbon volumes purged will be tabulated in subsequent quarterly status reports.

Conclusions and Recommendations:

Ground water elevations have decreased. This elevation decrease resulted in the reversal of the apparent ground water flow direction beneath the northern portion of the site compared to second quarter 1993. We will monitor ground water elevations in upcoming quarters to assess whether this trend continues.

Floating hydrocarbon thickness decreased compared to last quarter. WA will monitor the floating hydrocarbon thickness and begin monthly floating hydrocarbon purging if the skimmers are not effectively removing floating hydrocarbons.




Figure 3. Monitoring Well Locations and Ground Water Elevation Contours, Lower Water Bearing Zone -July 12, 1993 - Shell Service Station WIC #204-5508-5306, 3420 San Pablo Avenue, Oakland, California




Figure 2. Monitoring Well Locations and Ground Water Elevation Contours, Upper Water Bearing Zone - July 12, 1993 - Shell Service Station WIC #204-5508-5306, 3420 San Pablo Avenue, Oakland, California



5500 Shellmound Street, Emeryville, CA 94608-2411

Fax: 510-547-5043 Phone: 510-450-6000

93 OCT-15 PH 12: 22

October 11, 1993

Dennis Byrne
Alameda County Department of
Environmental Health
80 Swan Way, Room 200
Oakland, California 94621-1426

STIP 381

Re: Shell Service Station WIC #204-5508-5306 3420 San Pablo Avenue Oakland, California WA Job #81-612-203

Dear Mr. Byrne:

This letter describes recently completed and anticipated activities at the Shell service station referenced above (Figure 1.) This status report satisfies the quarterly reporting requirements prescribed by California Administrative Code Title 23 Waters, Chapter 3, Subchapter 16, Article 5, Section 265.d. Included below are descriptions and results of activities performed in the third quarter 1993 and proposed work for the fourth quarter 1993.

Third Ouarter 1993 Activities:

- Blaine Tech Services (BTS) of San Jose, California measured ground water depths in nine
 of the eleven site wells and collected ground water samples from seven of the wells.
 Wells MW-9 and MW-11 were recently paved over and could not be sampled. Two of the
 wells contained floating hydrocarbons and were not sampled. BTS' report describing these
 activities and presenting analytic results for ground water is included as Attachment A.
- BTS purged a total of 1.09 gallons of floating hydrocarbons from wells MW-1 and MW-4 this quarter (Table 1). To date, about 2.13 gallons of floating hydrocarbons have been removed by purging the wells and by floating hydrocarbon skimmers.
- WA prepared a ground water elevation contour map for wells screened in the first water bearing zone (Figure 2). Since wells MW-1, MW-3, MW-4 and MW-5 are screened slightly deeper than the other site wells, these wells are contoured separately (Figure 3).

Dennis Byrne October 11, 1993

> WA relocated wells MW-9 and MW-11 and reset the well vaults to grade on July 21, 1993.

Anticipated Fourth Quarter 1993 Activities:

- WA will submit a report presenting the results of the fourth quarter 1993 ground water sampling and ground water depth measurements. The report will include tabulated chemical analytic results, floating hydrocarbons removal data and ground water elevation contour maps.
- Floating hydrocarbon skimmers are installed in wells MW-1, MW-2, MW-4 and MW-6. The skimmers will be purged of hydrocarbons quarterly until no floating hydrocarbons are measured in these wells. Hydrocarbon volumes purged will be tabulated in subsequent quarterly status reports.

Conclusions and Recommendations:

Ground water elevations have decreased by about two feet compared to second quarter. This elevation decrease probably resulted in the reversal of apparent ground water flow in the wells on the northern portion of the site compared to last quarter. We will monitor ground water elevations in upcoming quarters to assess whether this trend continues. WA will also monitor the floating hydrocarbon thickness and begin monthly floating hydrocarbon purging if the skimmers do not appear to be sufficient to remove floating hydrocarbons.




Figure 3. Monitoring Well Locations and Ground Water Elevation Contours, Lower Water Bearing Zone - April 6, 1993 - Shell Service Station WIC #204-5508-5306, 3420 San Pablo Avenue, Oakland, California




Figure 2. Monitoring Well Locations and Ground Water Elevation Contours, Upper Water Bearing Zone -April 6, 1993 - Shell Service Station WIC #204-5508-5306, 3420 San Pablo Avenue, Oakland, California

Environmental and Geologic Services

Fax: 510-547-5043 Phone: 510-547-5420

5500 Shellmound Street, Emeryville, CA 94608-2411

June 9, 1993

Dennis Byrne
Alameda County Department of
Environmental Health
80 Swan Way, Room 200
Oakland, California 94621-1426

KID 381

Re: Shell Service Station WIC #204-5508-5306 3420 San Pablo Avenue Oakland, California WA Job #81-612-203

Dear Mr. Byrne:

This letter describes recently completed and anticipated activities at the Shell service station referenced above (Figure 1.) This status report satisfies the quarterly reporting requirements prescribed by California Administrative Code Title 23 Waters, Chapter 3, Subchapter 16, Article 5, Section 265.d. Included below are descriptions and results of activities performed in the second quarter 1993 and proposed work for the third quarter 1993.

Second Quarter 1993 Activities:

- Blaine Tech Services (BTS) of San Jose, California measured ground water depths in nine
 of the eleven site wells and collected ground water samples from six of the wells.
 Wells MW-9 and MW-11 were recently paved over and could not be sampled. Three of
 the wells contained floating hydrocarbons and were not sampled. BTS' report describing
 these activities and presenting analytic results for ground water is included as
 Attachment A.
- BTS purged a total of 0.26 gallons of floating hydrocarbons from wells MW-1 and MW-2 (Table 1). To date, about 1.04 gallons of floating hydrocarbons have been removed by purging the wells or by using passive floating hydrocarbon skimmers.
- WA prepared a ground water elevation contour map for wells screened in the first water bearing zone (Figure 2). Since wells MW-1, MW-3, MW-4 and MW-5 are screened slightly deeper than the other site wells, these wells are contoured separately (Figure 3).

Dennis Byrne June 9, 1993



Anticipated Third Quarter 1993 Activities:

- WA will submit a report presenting the results of the third quarter 1993 ground water sampling and ground water depth measurements. The report will include tabulated chemical analytic results, floating hydrocarbons removal data and ground water elevation contour maps.
- Floating hydrocarbon skimmers are installed in wells MW-1, MW-2, MW-4 and MW-6. The skimmers will be purged of hydrocarbons quarterly until no floating hydrocarbons are measured in these wells. Hydrocarbon volumes purged will be tabulated in subsequent quarterly status reports.

Conclusions and Recommendations:

Despite a ground water rise of about five to six feet compared to the fourth quarter of 1992, hydrocarbon concentrations in ground water and floating hydrocarbon thicknesses measured in the wells have not increased compared to historical values. WA will monitor the floating hydrocarbon thickness and begin monthly floating hydrocarbon purging if the skimmers do not appear to be sufficient to remove floating hydrocarbons.




Figure 3. Monitoring Well Locations and Ground Water Elevation Contours, Lower Water Bearing Zone -January 12, 1993 - Shell Service Station WIC #204-5508-5306, 3420 San Pablo Avenue, Oakland, California




Figure 2. Monitoring Well Locations and Ground Water Elevation Contours, Upper Water Bearing Zone -January 12, 1993 - Shell Service Station WIC #204-5508-5306, 3420 San Pablo Avenue, Oakland, California



5500 Shellmound Street, Emeryville, CA 94608-2411

Fax: 510-547-5043 Phone: 510-547-5420

April 12, 1993

Dennis Byrne Alameda County Department of Environmental Health 80 Swan Way, Room 200 Oakland, California 94621-1426

> Re: Shell Service Station WIC #204-5508-5306 3420 San Pablo Avenue Oakland, California WA Job #81-612-203

Dear Mr. Byrne:

A CONTRACTOR OF THE PROPERTY O

This letter describes recently completed and anticipated activities at the Shell service station referenced above (Figure 1.) This status report satisfies the quarterly reporting requirements prescribed by California Administrative Code Title 23 Waters, Chapter 3, Subchapter 16, Article 5, Section 265.d. Included below are descriptions and results of activities performed in the first quarter 1993 and proposed work for the second quarter 1993.

First Quarter 1993 Activities:

- Blaine Tech Services (BTS) of San Jose, California measured ground water depths in eight of the eleven site wells and collected ground water samples from three of the wells. Five of the wells contained floating hydrocarbons and were not sampled. Wells MW-9 and MW-11 were recently paved over and well MW-10 was blocked by a car. BTS' report describing these activities and presenting analytic results for ground water is included as Attachment A. Ground water elevation data is presented in Table 1 and analytic results from ground water are presented in Table 2.
- BTS purged about 0.52 gallons of floating hydrocarbons from well MW-1 and about 0.25 gallons from with MW-2 (Table 3).
- WA prepared a ground water elevation contour map for wells screened in the first water bearing zone (Figure 2). Since wells MW-1, MW-3, MW-4 and MW-5 screen a deeper water-bearing zone than the other site wells, these wells are contoured separately (Figure 3).

2



Floating hydrocarbon skimmers were installed in wells MW-1, MW-2, MW-4 and MW-6. The skimmers will be purged of hydrocarbons monthly until no floating hydrocarbons are mesured in these wells. Hydrocarbon volumes purged will be tabulated in subsequent quarterly status reports.

Anticipated Second Quarter 1993 Activities:

WA will submit a report presenting the results of the second quarter 1993 ground water sampling and ground water depth measurements. The report will include tabulated chemical analytic results, floating hydrocarbons removal data and a ground water elevation contour map.

Conclusions and Recommendations:

Ground water has risen about five to six feet compared to last quarter, which may explain the floating hydrocarbons that are recently detected in the wells. WA will monitor the floating hydrocarbon thickness and begin monthly floating hydrocarbon purging if the skimmers do not appear to be sufficient to remove floating hydrocarbons.

Please call if you have any questions.

ED GER

No. EG-1845 CERTIFIED ENGINEERING **GEOLOGIST**

Sincerely, Weiss Associates

J. Michael Asport Teshnical Assistant

Joseph P. Theisen, C.E.G. Senior Hydrogeologist

JMA/JPT: jma

J:\SHELL\600\QMRPTS\612QMFE3.WP

Attachments:

Figures Tables

A - Emcon Associates Ground Water Monitoring Report

Dan Kirk, Sheil Oil Company, P.O. Box 5278, Concord, California 94520-9998 cc: Lisa McCann, California Regional Water Quality Control Board, San Francisco Bay Region, 2101 Webster Street, Suite 500, Oakland, California 94612




Figure 3. Monitoring Well Locations and Ground Water Elevation Contours, Lower Water Bearing Zone - October 12, 1992 - Shell Service Station WIC #204-5508-5306, 3420 San Pablo Avenue, Oakland, California




Figure 2. Monitoring Well Locations and Ground Water Elevation Contours, Upper Water Bearing Zone - October 12, 1992 - Shell Service Station WIC #204-5508-5306, 3420 San Pablo Avenue, Oakland, California

(



Fax: 510-547-5043 Phone: 510-547-5420

93 FED 15 FM 1:35

February 10, 1993

Dennis Byrne
Alameda County Department of
Environmental Health
80 Swan Way, Room 200
Oakland, California 94621-1426

Re: Shell Service Station
WIC #204-5508-5306
3420 San Pablo Avenue
Oakland, California
WA Job #81-612-203

Dear Mr. Byrne:

This letter describes recently completed and anticipated activities at the Shell service station referenced above (Figure 1.) This status report satisfies the quarterly reporting requirements prescribed by California Administrative Code Title 23 Waters, Chapter 3, Subchapter 16, Article 5, Section 265.d. Included below are descriptions and results of activities performed in the fourth quarter 1992 and proposed work for the first quarter 1993.

Fourth Quarter 1992 Activities:

- EMCON Associates (EMCON) of San Jose, California measured ground water depths from all site wells and collected ground water samples from six of the eleven site wells. Five of the wells contained floating hydrocarbons and were not sampled. Emcon's report describing these activities and presenting analytic results for ground water is included as Attachment A.
- WA conducted a well survey to locate any wells within a 4 mile radius that may have been installed since 1990. One additional well was located at 3400 San Pablo Blvd., which is across the street to the west of the site. This well appears to be a monitoring well.



WA reviewed previous investigation reports and well logs to better understand the variable ground water elevations across the site. Since WA determined that wells MW-1, MW-3, MW-4 and MW-5 screen a deeper water-bearing zone than the other site wells, we contoured ground water elevations for these wells separately (Figures 2 and 3). The recontoured data that excludes wells MW-1, MW-3, MW-4 and MW-5 suggests a ridge of higher ground water elevation extends roughly east-west through the northern portion of the site. It is possible that a leaky water pipe or other water source could explain the mounding observed in the shallow water bearing zone. WA will continue reviewing previous and future water level data to assess the nature of the ground water flow.

Anticipated First Quarter 1993 Activities:

- WA will install floating hydrocarbon skimmers in wells MW-1, MW-2, MW-4 and MW-6 to remove the floating hydrocarbons in these wells. The skimmers will be purged of hydrocarbons quarterly until no floating hydrocarbons are measured in these wells. Hydrocarbon volumes purged will be tabulated in subsequent quarterly status reports.
- WA will submit a report presenting the results of the first quarter 1993 ground water sampling and ground water depth measurements. The report will include tabulated chemical analytic results and a ground water elevation contour map.

Please call if you have any questions.

Sincerely,

Weiss Associates

J. Michael Asport

Aum

Technical Assistant

Joseph P. Theisen, C.E.G. Senior Hydrogeologist

JMA/JPT:jma

J:\SHELL\600\612QMJA3.WP

Attachments:

Figures

BRITIFIED


ENGINEERING GEOLOGIST

A - Emcon Associates Ground Water Monitoring Report

cc: Dan Kirk, Shell Oil Company, P.O. Box 5278, Concord, California 94520-9998 Lisa McCann, California Regional Water Quality Control Board, San Francisco Bay Region, 2101 Webster Street, Suite 500, Oakland, California 94612

Table 1. Ground Water Elevation Data - Shell Service Station WIC #204-5508-4507, 2142 East 12th Street, Oakland, California

Well ID	Date	Top-of-Casing Elevation (ft above msl)	Depth to Water (ft)	Ground Water Elevation (ft above msl)
MW-1	01/28/92	21.28	10.84	10.44
MW-2	01/28/92	21.56	8.78	12.78
MW-3	01/28/92	21.78	9.99	11.79
MW-4	01/28/92	20.31	9.54	10.77
MW-5	01/28/92	20.91	8.45	12.46
MW-6	01/28/92	22.32	8.90	13.42
MW-7	01/28/92	20.36	7.11	13.25
MW-8	01/28/92	20.95	7.72	13.23
MW-9	01/28/92	21.19	9.02	12.17
MW-10	01/28/92	19.74	7.60	12.14
MW-11	01/28/92	22.06	8.74	13.32



ď

Figure 2. Ground Water Elevation Contour Map - January 28, 1992 - Shell Service Station WIC #204-5508-5306, 3420 San Pablo Averse, Oakland, California




Figure 2. Monitoring Well Locations and Ground Water Elevation Contours - July 13, 1992 - Shell Service Station WIC #204-5508-5306, 3420 San Pablo Avenue, Oakland, California







Figure 2. Ground Water Elevation Contours - May 4, 1992 - Shell Service Station WIC #204-5508-5306, 3420 San Pablo Avenue, Oakland, California







October 21, 1991

Department of Environmental Health Hazardous Materials Program 80 Swan Way, Room 200 Oakland, California 94621

Attention:

Ms. Susan Hugo

Reference:

Shell Oil Company

3420 San Pablo Ave. @ 35th

Oakland, California

Ms. Hugo:

Please find a copy of the Certificate of Tightness for the #1 SU2000 tank and it's product carrying line for the referenced location. Also enclosed are the test results.

Please call me if you should have any questions or comments.

Sincerely,

Timothy J. Dahl

Enclosure


STRAIGHT TO YOU FROM YAL MILLER AT OC TANKS CORPORATION IN BEAUTIFUL DOHNTOWN BAKERSFIELD



PHONE HUMBER FAX NUMBER (805)399-9597 (805)399-8338

TO: SUSAN MUGO AT: DATE: 8-22-7/# OF PAGES 3

FAX #: 415-568-3206





Jobsite Checklist For Tank Precision Test Using The Hydrostatic Tank Monitor

ob Name	Contract.	OIC.	2				
ddrées (MU PAGEO	7	35 TH		State		10-10-1
	THEMPO -	14	· · · · · · · · · · · · · · · · · · ·				
 	_ Record date and time tank was	last filled (wait 24 hou	ırş from last delk	very)			
	_ Record today's date and time						
			Groundwater Level	Tank #1	Tank #2	Tank #3	Tank #
	Record tank U.L. numbér (if kno	wn)			****		
	Product stored			Ari			
	Tank nominal capacity (galigns)) -		12,000			
	Preparation: †1. Measure and record grou	ndwater table lavel.					
,	 Fili reservoir riser pipe ap over réservoir top. The je must be at least 12" high- groundwater table. 	proximately 127 vel in the riser pipe er than the		-			
	3. Diameter af reservoir rise						
	 Inspect all exposed monit for leaks. 	oring fitting plugs					
13/9/	Begin test: 5. Record time (wait three h	ours after step #2).					
<i>,</i> ,	 Measure and record liquid riser pipe. 	tievet in reservoir		16			
، _د درد.	†7A. Messure and record group 7B. Record dispenser meter r	NGWATOT IZDO! ISVO). Asrligge					
[B]91_	 Record time (wait four hot both steps #8 and #7). 	ıra after completing					
	 Measure and record liquid riser pipe. 			16			
	†10A. Measure and record group 10B. Record dispenser meter r	rdwater table level. sading,	***				
	End test: Calculate changes: 11A. Reservoir deer pipe level (step #9).	Step #6 minus					
	116. Groundwater level (step # step #10A).	7A less or minus					
	11C. Dispensed product (step # step #10B).	78 minus		<u> </u>	······		
uite interpi iness test a	retation—The calculated changes f.05 gallons per hour with a 95% p	. (lines 11Å, 118, ånd röbäbility of detection	11C) must mee 1 and a 5% prob	tall of the criteria ability of a false als	in ¢oluma **8 irm:	" below to pase	the
(A) >rileria	(6) Tank* passes test if To	(C) ink* test is inconclus	ive if	lease contact the C	'NC Taple Siet	d Randas tinas	### ## 4 ## *
10#11A 10#11B 10#11C	and less than 10" or	ore than 1" """ more than 10" "" more than 600 galloi	b i 5:	48-8172 if you have locedure.	e any question:	s regarding this	Get (+1A)
	<u>6</u>	2,/3,'9/		Myrica		070	
		U보(원) technician's nam valness card to bo			

se a lage measure and water finder #7868-1870 waterforing finding pasts by Dayco National Sylon, Chief to determine ecourate liquid levels in sets wells and the reservoir. Bhit capacity 12,000 gallen capacity or less apact loot acops 8 through 19 9 improve the test accuracy, discontinue dispensing, then repeat test steps #6 through #11.

TANKS

O/C Tanks Corporation One Levis Square, Box 10025 Toledo, Ohio 43898-0028

Address of Engineer

Spece Smills

Stw phace Aut / 357H ST Shell Oil Location

Onkulue - CA

Dear :

One KIRK

Enclosed are the results of the took integrity Test

Enclosed are the results of the tank integrity tests performed at the above location on (Date). The system used for the tests is, the Hydrostatic Tank Monitor for double wall tanks. This system meets or exceeds both the NFPA, and the federal EPA criteria for tank precision testing, and is able to detect a leak rate of .05 gallons per hour with at least a 95% probability of detection and no more than a 5% probability of a false alarm.

This criteria of .05 gallons per hour is not to be construed as a permissible leak rate. Rather, it is an accuracy tolerance of the testing protocol and allows for the many variables involved.

We essume no responsibility for product leakage. Our responsibility extends only to leak testing of the tank on the date tested, within the accuracy tolerance of the Hydrostatic Tank Monitor System.

Tank#	Tank UL#	Tank Capacity	<u>Product</u>	Level Change (Line 11A)	Test Result (Pass/Fall)
1 2	AVA	12,000	WATER	-0_	Pass
3		•			
5		•			

Attached is the detailed jobsite checklist for your records. Also enclosed is our invoice.


Regards,

George D. Crosby Field Service Manager O/C Tanks

6/27/89

F:SHELTEST.GDC/bam

Enclosure



FACSIMILE COVER SHEET

TO:	Alamada County Envino Health - Susan	Hvao
COMPANY:		
FROM:	Borry McCon	
DATE:	8-20-91	
RE:	Ins Cart	
COMMENȚS:	Originals mailed 8-22 per our	
.•	Conversation. Questions please	
•	call	٠
	3 pages including cover.	•

IF THERE ARE ANY PROPLEMS WITH THIS TRANSMISSION, PLEASE CALL (415) 783-7500

AUTHORIZED REPRESS TATIVE

CAIR Bystems (03/00)



O/G TANKS CORPORATION ONE LEVIS BOUARE, P.O. BOX 10025, TOLEDO, OHIO 43699-6025, (419) 246-8000

Auguer 26, 1991

Mr. Susan Hugo Alameda County Environmental Health

Fax 415-568-3706

Subject: Shell Oll

3420 San Pablo at 35th

Oakland, CA

Dear Mr. Hugo,

O/C TANKS was contacted by Denny of Gettler/Ryan on August 2, 1991, conserving water in the primary tank at the Shell Oil station in Oakland, California.

This tank had been repaired in January of 1991 after an outer wall lask was repaired from the interior of the tank.

O/C TANKS field service technicians have found a leak near the deflector plate in the bottom of the tank. This problem appears to be a lack of bonding the repair to the shell wall creating a channel through the deflector plate.

Our procedure will be to grind the shell wall three fact by three feet and encapsulate this area with a 7 ply fiberglass lay-up. After all repairs are completed, the tank will be tasted to ensure the integrity of the work.

If there are any further questions, feel free to contact my effice.

Regards,

Ange

George D. Grosby Field Service Manager

ab

es: W. V. Miller

Jany Later 191

STRAIGHT TO YOU FROM VAL MILLER AT O/C TANKS CORPORATION IN BEAUTIFUL DOHNTOWN BAKERSFIELD



PHONE NUMBER FAX NUMBER (805)399-8338

10: SUSAN 11460

AT:_______# OF PAGES_

FAX #: 415-568-3206

NOTES:

white -env.health yellow -facility pink -files

ALAMEDA COUNTY, DEPARTMENT OF ENVIRONMENTAL HEALTH

80 Swan Way, #200 Oakland, CA 94621 (415) 271-4320

Hazardous Materials Inspection Form

 Π,Π

***	***************************************	·····	"Site Site Name Shell Service Station Today's 9,22,9/
11.4	A BUSINESS PLANS (Title 19)		
	1. immediate Reporting 2. Bus. Plan Sids. 3. RR Cans > 30 days 4. inventory information	2703 25503(b)	Site Address 3420 San Palolo Ave
		25503.7 25504(a) 2730	city Oakland Zip 94 GOS Phone
	5. Inventory Complete 6. Emergency Response 7. Training	25504(b) 25504(c)	
	8. Deficiency 9. Modification	25505(a) 25505(b)	MAX AMT stored > 500 lbs, 55 gal., 200 cft,?
			Inspection Categories: 1777 # 5067 5706 5706 5706 5706 5706 5706 5706
II.B	ACUTELY HAZ, MATLS 10. Registration Form Filed	25533(a)	
	11. Form Complete	25533(b) 25534(c)	III. Underground Tanks
	13. Implement Sch. Regid? (Y/N 14. OffSite Conseq. Assess.	1) 25524(c)	1:30-
	15. Probable Risk Assessment 16. Persons Responsible 17. Certification	25534(d) 25534(g) 25534(j)	* Calif. Administration Code (CAC) or the Health & Safety Code (HS&C)
	18. Exemption Request? (Y/N) 19. Trade Secret Requested?	25536(b) 25538	Comments:
	<u> </u>		UNDERGROUND TANK (SUL) Investigated
III.	UNDERGROUND TANKS (Title	23)	for leaks in the primary containment
ē	1. Permit Application 2. Pipeline Leak Detection	25284 (H&S)	System. Geffler Ryan Contractor, 0/e-tork
G	3. Records Maintenance 4. Release Report	25292 (H&S) 2712 2651	repair
 -	5. Closure Plans 6. Method	2670	
	Nonthly Test Daily Vadose		NEEDS:
	Semi-annual gnawater One time sols 3) Daily Vadose One time sols Annual fank test 4) Monthly Gnawater One time sols 5) Daily inventory Annual tank testing Cont tiple leak det Vadose/gnawater mon, 6) Daily inventory Annual tank testing Cont place leak det 7) Weekly Tank Gouge Annual tank testing By Annual tank testing Cont place leak det 7) Weekly Tank Gouge Annual tank testing By Annual Tank Testing By Annual Tank Testing		a please send the current worker's comp. Insurance
			Certificate 87 charge on tile office of 4/1/91
for Existing Tank			2) little of the Political of The Thirty
XISI			The frecision that desire
9			gerformed on the last you, 1946, apa
Monitoring			repairing the Recordary Containment (wall)
Mon		(3) Sile Safely Plan promilled for the reprier
			of secondary wall will remain the some for
•	9) Other		I the investigation of the fromany wall.
•	Date:	2643	Delermine of the grimary wall lange be
	y. Soil lesting .	2646 2647	regained or not by doing regain walnation
Tanks	12.Access. Secure	2632 2634	Bostotell under dec. 266/1 Pla Title 23.
	13.Mans submit Date:	2711	5) all regains to be performed muce meet the
ž	14. As Built Date:	2635	bearing meate of Title 23 under article 6 Callewrence
lev I	8/88		repairs)
		(de	& Submit alon documentation of work to be
	Contact: 1	arry ma	Cox dospol I despre Ortunal work will com
		AFETY N	nonagen Inspector:
	Signature:	+	CICC The state of
	aightaidie.	<u> </u>	Signature: Man & This

SHELL OIL COMPANY QUARTERLY REPORT TO THE CALIFORNIA REGIONAL WATER QUALITY CONTROL BOARD, BAY AREA REGION

April 11, 1991

0/

Site Address:	3420 San Pablo Av		Site ID No	204550853		
	Oakland, California	a	· · · · · · · · · · · · · · · · · · ·			
County of:	Alameda					
Actions in the pa	st 3 months:					
	ment permit for off-site ct from monitoring well			rmed quarter	y ground water mo	onitoring.
Actions planned f	for the next 3 months:					
assessment report	ntry secured, install, defor Shell, agency review wells MW-1 and MW-2.	v. Perforr				
Soil contaminatio Free product plur Dissolved constitu		No No No		cleanup in p	rogress? nup in progress?	No Yes No
Contractor: Delta	a Environmental Consul	tants, Inc	•			



91 FEB - 6 AMII: 10

O/C TANKS CORPORATION

ONE LEVIS SQUARE, P.O. BOX 10025, TOLEDO, OHIO 43699-0025, (419) 248-8000

February 4, 1991 Ms. Susan L. Hugo Alameda County Health 800 Swain Way Room #200 Oakland, CA 94621

Fax # 415-568-3706

Subject: Shell Oil

35th & San Pablo Oakland, CA

Dear Ms. Hugo,

O/C TANKS Field Service has been called to investigate the outer wall leak at the Shell Oil station in Oakland, California. Our technicians have found an area on the outer wall that has caused the loss of water from the annular space.

This defect in the shell wall is an apparent process error that was not discovered during the initial testing at the plant or before installatin.

This area has been identified by cutting away the inner wall and locating the area on the outer wall and then remanufacturing this area.

The process of remanufacturing will consist of making the complete repair of the outer wall from the inside of the tank; at this point, the inner wall would be completely repaired and stored to meet or exceed the original tank structural specifications.

After the tank repair is completed, we will conduct an air/soap test to insure the integrity of the remanufactured area and that the inner tank is leak-free after completing the air/soap test. The hydrostatic monitor will be reactivated and a precision test will be conducted on both the inner and outer tank walls.

If there are any further questions concerning the work or procedures, feel free to contact my office at 419-248-8196.

Regards,

Yeorge

George D. Crosby

Field Service Manager

cc: S. C. Macy

L. R. Whately

R. T. Lawrence

W. V. Miller (805) 3 99- 9597

G13055



A SUBSIDIARY OF OWENS-CORNING HIBERGLAS

MAKS CORPORATION ONE LEVIS SQUARE, P.O. BOX 10025, TOLEDO, OHIO 43699-0025, (419) 248-8000

February 4, 1991 Mr. Susan L. Bugo Administ Receivery Rendere BIR Ladia Way F. 4. 1 (1976)

Commence of the

March 1 11 Bury on the

 In the control of the property of the decreasing also the control out; out within the literature, relations of the twelf intens The state that have reased that last of early fire it.

The second of the second property of the contract of the contr and the second of the second o

in the control of the second o

 In the control of the c in a company of the second of

the second of the control of the second of the North Control of the second of the seco

1. e en tage Se en en tr A Cold To the two Meanings of

con Si C Bady t. R. Whately R. T. Lawrence W V. Miller G13055

white -env.health yellow -facility pink -files

ALAMEDA COUNTY, DEPARTMENT OF ENVIRONMENTAL HEALTH

80 Swan Way, #200 Oakland, CA 94621 (415) 271-4320

Hazardous Materials Division Inspection Form

	Site ID#	SIte Na	me Shell Clif Corry. Today's Date	21 <u>B</u> 191
	(De	1.00	San Parlo One EPA ID#	
	City	wan	ZIp <u>94 60</u> 9 Phone	
=	MAX Amt. Stored > 500lb Hazardous Waste general The marked Items represe	ed per mo		(HS&C)
=			1	
I.A	GENERATOR (Title 22) 1. Waste (D 2. EPA (D 3. > 90 days 4. Label dates 5. Blennial	* 66471 66472 66508 66508 66493	Comments: Pressure testing tank upc u	va
Manifest	6. Records 7. Correct 8. Copy sent 9. Exception 10. Copies Recid	66492 66484 66492 66484 66492	or secondary for 1 kr. I	fac.
¥]gc.	11. Treatment 12. On-site Disp. (H.S.&C.) 13. Ex Haz. Waste	66371 26189.5 66570	testing - filling annully space	e
Prevention	14. Communications15. Alsie Space16. Local Authority17. Maintenance18. Training	67121 67124 67126 67120 67105	fito Tite Thetel by Gettler Ryan	
gency	19. Prepared 20. Name List 21. Copies 22. Emg. Coord. Img.	67140 67141 67141 67144	Derrich Houd DK tank Sulk	nes
Containen, Tanks	23. Condition 24. Compatibility 25. Maintenance 26. Inspection 27. Butter Zone 28. Tank inspection 29. Containment 30. Safe Storage 31. Freeboard	67241 67242 67243 67244 67246 67259 67245 67257		
.В	TRANSPORTER (Title 22) 32. Applic./Insurance 33. Comp. Cert./CHP Insp. 34. Containers	66428 66448 66465		
Manifest	35. Vehicles 36. EPA ID ≠s 37. Correct 38. HW Delivery 39. Records	66465 66531 66541 66543 66544		
Confre	40. Name/ Covers 41. Recyclables	66545 66800		
9 V 6/				1
	Contact:			
	Title:		Inspector:	- -/
	Signature: _		Signature:	

-env.health white yellow -facility -files pink

ALAMEDA COUNTY, DEPARTMENT OF ENVIRONMENTAL HEALTH

80 Swan Way, #200 Oakland, CA 94621 (415) 271-4320

Hazardous Materials Division Inspection Form

pink -	He He	azardo:	us Materials Division Inspection Form
Site li	0# Site	Name	Shell Service Station Today's Date 1,3991 an Pablo Ave. EPA ID# ZIP 94608 Phone
City	Vakland		
Hazardo	t. Stored > 500lbs/5 us Waste generated	ber monen	? Y N 1. Haz. Mat/Wasie General Visit Materials 11. Business Plans, Acute Hazardous Materials 11. Underground Tanks
The mar	ked Items represent	violations	of the Calif. Administration Code (CAC) or the Health & Safety Code (HS&C)
atainen, Tanks gency Prevention Misc. Manifest	, Waste ID * 2. EPA ID > 90 days Label dates Biennial	66471 66472 66508 66508 66508 66493 66492 66484 66492 66484 66492 66371 26189,5 66570 67121 67124 67126 67120 67140 67141 67141 67141 67242 67242 67242 67243 67244 67245 67257	Comments: A link was differented in the secondary containment of the things and the personal top the container where on site. Robert printer of stay puilled (certifichment) was also on the where work in volved: "bleterming where the look is in the econotary the look is in the econotary containment and assess off it is regainable or not. Owene Corners must provint documents or regards of the findings to the department, if bregain is to be done on the tank a workplane.
I.B TRAN	32. Applic./Insurance 33. Comp. Cert./CHP Insp. 34. Containes 35. Vehicles 36. EPA ID #s 37. Correct 38. HW Delivery 39. Records	66428 66448 66465 66531 66541 66543 66544	for approval.
Confr	40. Name/ Cavers 41. Recyclables	66545 66800	
Rev 6/88	<u>.</u>		
	Contact: Title: Signature:	Pe (De	Inspector: Inspec

qeller - ryan inc.

Tatolic 1852 Malagaran The state of the s ROSE LIBERT REGISSION Dartanot

Brant hear from h

EDECOUNTY HEALTH CARE SERVICE AG DEPARTMENT OF ENVIRONMENTAL HEALTH HAZARDOUS MATERIALS DIVISION 80 SWAN WAY, ROOM 200 OAKLAND, CA 94621 PHONE NO. 415/271-4320

Y

ACCEPTED

DEPARTMENT OF ENVIRONMENTAL HEALTH 470 - 27th Street, Third Floor Telephone: (415) 874-7237 Oakland, CA 94512

able and essenticily mech the requirements of State and local health laws. Changes to your plans indicated by this Those plans have boon reviewed and found to be accept-Department are to essure compliance with State and local lews. The project proposed horein is now released for issu-

One copy of those accepted plans must be on the job and avoilthe to all contractors and crafismen involved with ands of any required building permits for construction. the removel,

Any introductions of these plans and specifications must the telemithed to this Department and to the fire and Building languation Department to determine if such Notify the Descriment of least 48 hours prior to the chemis, many the requirements of State and local laws, folionia: required inspections:

Removal of Tank and Piping -Sampling

Assuance of a permit to operate is dependent on compliance with accepted plans and all applicable laws and -Final Inspection

THERE IS A FINANCIAL PENALTY FOR NOT OSTAINING THESE INSPECTIONS.

REPAIR UNDERGROUND TANK Complete according to attached instructions

火1.	Business Name Shell Service Station	
·	Business Owner Shell Oil Company	
Х 2.	site Address 3420 San Pablo Ave @ 35th	
	city Oakland zip 946 - Phone 653-	5709
X3.	Mailing Address PO. 4023	<u> </u>
	city Concord zip 94520 Phone 675-	6100
۶ ₄ .	Land Owner Shell Oil Company	
	Address PO. 4023 city, State A Zip	94520
×5.	Generator name under which tank will be manifested	
	N/A	
	EPA I.D. No. under which tank will be manifested	

rev 12/90

6:	contractor Gettler-Kyan In	····
	Address 2150 West Winton Ave	
	city Hayward CA Phone	
	License Type B, CG/, 040 ID# 220793	
7.	Consultant N/A	
	Address	
	City N/A Phone N/A	
8.	Contact Person for Investigation	
	Name Dan Kink Title Engineer	
	Phone <u>Co75-6/60</u>	
9.	Number of tanks being closed under this plan	
	Length of piping being removed under this plan N/O	.,, ·· **.
	Total number of tanks at facility 3	
10.	State Registered Hazardous Waste Transporters/Facilities (see instructions).	
	** Underground tanks are hazardous waste and must be handled * as hazardous waste	*
	a) Product/Residual Sludge/Rinsate Transporter	
	Name EPA I.D. No.	
	Hauler License No License Exp. Date	
	Address	/ .
	City State Zip	···
	b) Product/Residual Sludge/Rinsate Disposal Site	
	NameEPA I.D. No.	
	Address	
	City State Zip	

	Name EPA I.D. No	
	Hauler License No License Exp. Date	_
	Address	
	City State Zip	
	d) Tank and Piping Disposal Site	
	Name	
	Address	,
	City State Zip	
•	Experienced Sample Collector	
	Name	
	Company	
	Address	
	City State Zip Phone	
•	Laboratory	
	Name // A	
	Address	
	State Certification No.	.,,,,
. :	Have tanks or pipes leaked in the past? Yes [] No	
•	If yes, describe.	
_		

14. Describe methods to be used for rendering tank inert

N/A

Before tanks are pumped out and inerted, all associated piping must be flushed out into the tanks. All accessible associated piping must then be removed. Inaccessible piping must be plugged.

The Bay Area Air Quality Management District (771-6000), along with local Fire and Building Departments, must also be contacted for tank removal permits. Fire departments typically require the use of explosion proof combustible gas meters to verify tank inertness. It is the contractor's responsibility to bring a working combustible gas meter on site to verify tank inertness.

15. Tank History and Sampling Information

Ta	nk	Material to	_
Capacity	Use History (see instructions)	be sampled (tank contents, soil, ground- water, etc.)	Location and Depth of Samples
10,000 Gal	N/A	NA	NA

One soil sample must be collected for every 20 feet of piping that is removed. A ground water sample must be collected should any ground water be present in the excavation.

Exca	vated/Stockpiled Soil	
Stockpiled Soil Volume (Estimated)	Sampling Plan	
N/A	N/A	

Stockpiled soil must be placed on bermed plastic and must be completely covered by plastic sheeting.

; 1-29-91 ; 15:34 ;

16. Chemical methods and associated detection limits to be used for analyzing samples

The Tri-Regional Board recommended minimum verification analyses and practical quantitation reporting limits should be followed. See attached Table 2.

Contaminant Sought	EPA, DHS, or Other Sample Preparation Method Number	EPA, DHS, or Other Analysis Method Number	Method Detection Limit
,			
MA	N/A	NA	1/19
		·	

17. Submit Site Health and Safety Plan (See Instructions)

NT BY	:Gettler-Ryan Inc.	; 1-29-91 ; 15:35 ;		→415 568 3706	;#
18.	Submit Worker's C	in 1-29-91; 15:35; Compensation Certificate Somitive (See Instructions) See Instructions) or contamination to this	copy	_	
	Name of Insurer	Submitted	Yo	Susan	Hug
19.	Submit Plot Plan	(See Instructions)	017	1/29/91	
20.	Enclose Deposit (See Instructions)	• 6	2 11:00	am.
21.	of discovery. Th	e report shall be made (thorized Leak/Contaminat	on an Un	deraround -	
22.	Submit a closure tank removal. Th in item 22 of the	report to this office wis report must contain a instructions.	ithin 60 all the	days of the information l	isted
I de	clare that to the information provi	best of my knowledge and ded above are correct an	nd belie nd true.	f the stateme	nts
be r Envi	needed in order to	ormation in addition to obtain an approval from and that no work is to be proved.	n the De	partment of	-
I ur void	derstand that any it this plan if pri	changes in design, mate or approval is not obtai	erials of	r equipment w	ill
in c	compliance with al. .nistration) requi:	work performed during t l applicable OSHA (Occup rements concerning perso a and worker safety are	pational nnel he	Safety and Health and safet	salth by.

I understand that site and worker safety are solely the responsibility of the property owner or his agent and that this responsibility is not shared nor assumed by the County of Alameda.

Once I have received my stamped, accepted closure plan, I will contact the project Hazardous Materials Specialist at least three working days in advance of site work to schedule the required inspections.

Signature of Contractor

Name (prease type) Timothy Dake For Gettler - RYAN INC.	
Signature Tribus Park	
Date 1-29-91	
Signature of Site Owner or Operator	
Name (please type) TIMOTHY DAHL FOR SHELL OIL COMPANY	
Signature TIMOTHY DAND	
Date 1-29-91	

	5607 CERTI	FICATE F INSU	RAE	SRM	01910 ISSUE DATE 04/12/90		
COOPER & COOK INSURANCE SERVICES			но втныя он	PON THE CENTIFICA	A MATTER OF INFORMATION ONLY AND CONFERS ITE HOLDER. THIS CERTIFICATE DOES NOT AMEND, SE AFFORDEBY THE POLICIES BELOW		
PASANTON CA 94566			C	OMPANIES AFFO	RDING COVERAGE		
C	DDE SUB-CODE		COMPANY A	NATT. TIME	ION EIDE ING GO OF THE		
_ IN	SURED	······································	COMPANY	MAIL UN	ION FIRE INS CO OF PITTS		
d	GETTLER-RYAN, INC.		COMPANY _	FIREMANS	S FUND INSURANCE		
1	2150 WEST WINTON AV HAYWARD, CA 94545	/ENUE	LETTER C	INS CO (OF THE STATE OF PENNSYLV		
	,		LETTER	NO AMER O	CO FOR PROP/CASUALTY		
			COMPANY E LETTER		CINDEMNITY		
S.	OVERAGES THIS IS TO CERTIES THAT	THE DOLLOUS OF WALE					
	INDICATED, NOTWITHSTA CERTIFICATE MAY BE ISSI EXCLUSIONS AND CONDIT	THE POLICIES OF INSURANCE LIST NOING ANY REQUIREMENT, TERM JED OR MAY PERTAIN, THE INSUR, TONS OF SUCH POLICIES. LIMITS S	ED BELOW HAVE BEEN IS OR CONDITION OF ANY CO ANCE AFFORDED BY THE F SHOWN MAY HAVE BEEN R	SUED TO THE INSUR NTRACT OR OTHER POLICIES DESCRIBE EDUCED BY PAID CI	RED NAMED ABOVE FOR THE POLICY PERIOD DOCUMENT WITH RESPECT TO WHICH THIS D HEREIN IS SUBJECT TO ALL THE TERMS, LAIMS.		
.ТЯ	TYPE OF INBURANCE	POLICYNUMBER		POLICY EXPIRATION			
A	GENERAL LIABILITY	GL5424154		DATE (MM/DD/YY 04/01/91			
	CLAIMS MADE X OCCUR.			-, -, -, -, -, -, -, -, -, -, -, -, -, -	PRODUCTS-COMP/OPS AGGR \$ 2,000		
	OWNER'S & CONTRACTOR'S PROT.				PERSONAL & ADVERTISING INJURY \$ 1,000		
					FIRE DAMAGE (Any one lire) \$ 1,000		
В	AUTOMOBILE LIABILITY	MZA80082127	04/01/00	04/01/01	MEDICAL EXPENSE (Any one person \$ 5		
	ANY AUTO	MDR0000ZIZ/	04/01/90	04/01/91	COMBINED SINGLE \$ 1 000		
<u> </u> _(LL OWNED AUTOS				BODILY		
	X HIRED AUTOS				(Per person)		
	X NON-OWNED AUTOS	·			BODILY INJURY {Per acc}		
	GARAGE LIABILITY				PROPERTY DAMAGE \$		
С	EXCESS LIABILITY	4790-5698	04/01/90	04/01/91	<u> </u>		
	X UMBRELLA OTHER THAN UMBRELLA FORM	-	,,	-, -, -, -, -, -, -, -, -, -, -, -, -, -	1,000 s 1,000		
E	WORKER'S COMPENSATION	PC994725	04/01/90	04/01/91	STATUTORY		
	AND			•	\$ 1,000 (EACH ACCIDENT)		
_	EMPLOYERS' LIABILITY	· · · · · · · · · · · · · · · · · · ·			\$ 1,000 (DISEASE-POLICY LIMIT) \$ 1,000 (DISEASE-EACH EMPLOYEE		
	отн.						
ļ	,						
DES	CRIPTION OF OPERATIONS/LOCATIONS/	VEHICLES/RESTRICTIONS/SPECIA	L ITEMS	· · · · · · · · · · · · · · · · · · ·			
"ALL CALIFORNIA OPERATIONS"							
CE	RTIFICATE HOLDER		CANCELLATION				
			igene en	F THE ABOVE DESC	RIBED POLICIES BE CANCELLED BEFORE THE		
(COUNTY OF ALAMEDA				SSUING COMPANY WILL END EAVOR TO		
, },	DEPARTMENT OF ENV	IRONMENTAL HEALTH	LEFT, BUT FAIL	URE TO MAIL SUCH	TO THE CERTIFICATE HOLDER NAMED TO THE NOTICE SHALL IMPOSE NO OBLIGATION OR		
_	80 SWAN WAY, ROOM OAKLAND, CA 946	4565			COMPANY, ITS AGENTS ON REPRESENTATIVES.		
	, ormanian, on 940	4 1	AUTHORIZED REPRESE	NTATIVE	1/		
INS	NSURNET 25 8 (3/88)						
					INSURNET, INC. 1988		

field hervice manual o/c tanks corporation

eection	Safaty	
bullerin		
date	1/1/90	Ļ
supersedes	1/4/84	Į.

SUBJECT: CUSTOMER TANK PREPARATION PRIOR TO ENTRY

POLICY

It is the responsibility of the customer or final owner to properly clean, defume and in general make conditions safe prior to an O/C Tanks Field Technician entering any tank. This includes entry due to O/C Tanks quality problems.

BACKGROUND

O/C Tanks Field Techniquens are not authorized to inspect or work on any UGST where conditions are not suitable to ensure their health and safety. Each techniquen has written tank entry requirements are are not to be violated.

The customer will be required to properly prepare a tank for entry because the customer is in the best position to efficiently do so, i.e.:

- . Cleaning frequently involves specialized equipment arranged for at the local level.
- . O/C Tanks is not equipped, nor trained to clean tanks.
- . Cleaning ranks can be harardous if one is unfamiliar with the specific precautions that should be observed when working with a particular product.
- . Only a clean tank can be properly inspected.
- Manway must be unobstructed free from pumps, piping, etc.

PROCEDURE

The Field Service Department will, at first telephone contact, inform the job contact of the following requirements that must be met prior to entry of a UGST.

A. <u>Fetroloum Tanks</u>

- 1. The tank must have had the product pumped out to within 1" or less of the bottom. This requires the use of hand pump.
- 2. Fuel oil tanks must not only be pumped nearly dry but also manually cleaned out.
- 3. After pumping out, the tank must be ventilated until it is vapor free. The use of an exhausting eductor (venturi) on the fill tube is recommended. The tank will not be out into until the vapor level in the tank is less than 10% LEL.

JI-KYBII IIICI — i i-Zā-bi i bidu ido imina danekarielu-

) # J

Facry Procedure (cont'd)

7. Initial Entry
When the above entry requirements are met, entry may be made with the use
of an approved air-supplied mask and an Egress air cylinder.

Prior to the first entry of the day, test the vapor level from outside the tank. If less then 100 LEL, take the merer into the tank and check for hot spots. If the 0, is less than 19.3% or the vapor level exceeds 200 LEL, exit the tank an continue ventilating.

Remove any residual product with an approved pumping system or by manual means. Dry the area with regs or "oil dry" material and dispose of in a safe place:

Plug internal openings after the air check.

- a. Manifolded went lines may be plugged with an expandable plug or by forcing the ball of a check valve arrangement up tight against the fitting with wood.
- b. Submerged pumps, if not removed, are to be electrically disconnected and locked out, then capped at the bottom. The return line is to be plugged with a cork.
- q. Suction and siphon lines are to be capped or enclosed in plastic to prevent drips.
- Continuous Monitoring
 Vapor level and O, level must be monitored continuously, either through the
 entry hole or down the exhauster with the probe (at least 12" below the
 exhauster into the fill pipe). Readings above 20% LEL or less than
 19.5%
 O, require work to dease, and workers to immediately exit the tank, and an
 investigation as to the source with subsequent correction.
- 9. Inspection
 Inspect the tank for damage; record all data on appropriate sheet.
- 10. Repair

 If an agreement is reached and the tank is to be repaired, proceed as follows:
 - a. The tank must be mechanically ventilated at all times.
 - b. Complete the Confined Space Entry Permit and post at tank entry hole. (Note: A new Confined Space Entry Permit is required for each day's entry or for recentry during the work day if work is stopped, such as for lunch.)
 - c. Instruct the safety observer and standby of their duties and emergency procedures.
 - d. A safety harness with lifelines is required for in-ground tank entry.

ಆ ೯ - ೯೩೦೩ ೧೯೩೬ ಅಂತರ ಮಾರ್ ಟಾಕ್

RCV BY: Gettier-Kyan Inc. 1-25-91; 9:00 ; OC TANKS BAKERSFIELD
**RCV BY: Gettier-Kyan Inc. 1-25-91; 9:00 ; OC TANKS BAKERSFIELD
Lay-up around the fit * plate or on the weld on the *** which secures . the coupling to the fitting plate.

4

- Remove fitting and fitting plate. This removal is done by utilizing abrasive tools and breaking all bond between the fitting plate and the rank wall.
- 2. Prepare tank for acceptance of a new fitting. Grind off all old lay ups and insure that tank wall is not damaged underneath the adjoining rips.
- 3. Install new fitting using factory technique. If the fitting plate does not match the outvature of the tank due to tank deflection, increase the numbers of plies of met beneath the fitting plate.

PROCEDURE - Internal Repairs *

- A. Tank Entry When tank entry is required and there is no manway on the tank to allow for entrance, entry must be made through the endcap. On tanks in which a hemispherical endoup is present, entrance should be made through the hemispherical endesp. Prior to entry, the following procedures will be followed.
 - 2. Impact hole larger than four inches in diameter:
 - Bridge the hole utilizing tape or a section of the wall which has been broken in, if possible. Insure that this bridge is smooth and does not disrupt the shape of the wall.
 - b. Grind the entire eres around the hole, insuring that ground area extends around the damage and the bridging material a distance equal to the diameter of the hole being repaired.
 - c. Lay-up the hole. Secure materials equal to the size of the ground area. Lay-up should consist of seven plies of alternating mat and woven roving, starting and finishing with mat.
 - d. If ribs are required to be removed in either of these impact holes, the procedure to replace ribs is to be followed,
- C. Orushed or Cracked Ribs A cracked rib is defined as a fracture on the

REPAIR PROCEDURE - UNDERGROUND STORAGE TANKS

PURPOSE

This procedure is established to provide guidelines when making field repairs on fiberglass underground storage tanks (USGT's). This procedure covers repairs made on tanks that are above ground and those that are buried.

PROCEDURE - General

- A. Unusual and unexpected hazards may be encountered when UGST's are being repaired. For this reason, field personnel having cause to enter UCST apaces will exercise proper safety precautions as outlined in the safety procedures.
- all wassing and to be made using UL listed yow materials such as resin,

5

General Requirements

1. Instruct the Safety Obserber (cont'd)

b. Attempt to pull the technician toward the entry hole by means of the lifeline.

JAA TUNUS DAVENOLIEFRA

- e. But on the sefety harness and attach lifeline,
- d. Put on the SCBA and test operation.
- e. After the errival of the fire department or rescue squad, assist in the rescue and removal of the man.

2. Remove All Possible Product

Use a hand pump or approved flammable fluid pump to remove as much product as possible. No more than 1" of product should be in the tank prior to ventilation.

3. Start Ventilation

Connect an approved air-driven air mover to exhaust air from the fill pipe or other pipe or hose within 12" of tank bottom. The air mover must be bonded to the tank and grounded when in use. Extend exit point of exhaust at least 12 feet above grade.

Continue to ventilate until test with the combustible gas meter indicates the LEL is less than 10% within 12" of tank bottom. Stop venting for 15 minutes then take combustible gas test. Then continue venting until 10% LEL. Remove the fill pipe to check. Ventilation can take between 2 hours depending on the amount of product left in the tank,

If tank lines are manifolded, the line of the tank to be entered must be broken and blanked off to isolate the tank and allow defuming of the tank.

4. Cut Entry Hole

Cut entry hole, if cutting is required, only after tests confirm the vapor level with 12" of the tank bottom is 0% of the LEL. Use only an air powered saw. The minimum hole size to facilitate rescue if required is 18" x 18".

5. Tests Before Entering

After the entry hole is out, check the vapor level and 0, level through the entry hole.

Minimum entry requirements are:

Vapor level lass than 10% LEL with approved air-supplied respirator 0, level greater than 19.5% If vapor rises above 20% must leave tank and continue venting until below 10% again.

6. Gonfined Space Entry Pormic Obtain a completed Entry Permit or complete the attached Confined Space Entry Permit and post near the entry hole.

Comonitor

Safety Bulletin #1 1/9/90

		•
ITEM	PREFERRED EQUIPMENT	Approved Alternates
Salf Contained Breathing Apparatus (Rescue Air)	Bio Marine Industries Bio Pak	
Wrist Harness	Atlas Safety Equipment No. 130 Wristlets . No. 520 Safety Line . No. 500 Safety Line with 50 ft. 1/2" Dis. Polypropylene Rope	Any Equivalent - Must be NIOSH approved
Rope Ladder	Atlas Safety Equipment No. 363 Ladder with Polyethylene Side Rails length to be Specified	Any Equivalent - Must be NIOSH approved
Space Hester	Mopeco Ventilating Heater No. ACH-2 Propane Fired 500 CFM 50,000 BTU/Hr.	
O ₂ Analyzer	Bio Marine Series 200.04225 0-25% with Remote Senso Leather Carrying Case	r &
Fire Extinguisher	All Purpose A-B-C Type Dry Chemical Capacity 10 lbs. Min., UL Rating 3-A, 30-B,C Min.	
Air Mask Filter	3M Air Purifier & Regulator Panel Cartridge W-2811	Del-Monox 190B Cartridge Type BA-5
Air Mask CÓ Monitor/Alarm	Test Gas #	
Pump-Flammable Fluids	Sandpiper Model SA2-A 2" with Buns N Parts	Any equivalent air driven diaphragm type pump
Organic Respirator	Per current O/C Tanks plant approved Personne Protective Equipment Li	

Gas Tech 2417534

field service menual e/c tanks corporation

section	Safety	•
bullatin	1	-
date	1/1/90	
supersedes	1/4/84	

·幕 7

APPROVED SAFETY DEVICES

ITEM	Preferred Equipment	APPROVED ALTERNATES
Combustible Vapor and O ₂ Alexa	Bio-Marine No. 900R Calibration Kit P/N 160 Batter Charger F/N 140 Calibration Cylinders Lead Filters P/N 137 Carry Case P/N 147 Probe	Gas Tech Model 1214
Fresh Air Mask	MSA Constant Flow Respirator 460863 . Ultra View Face . Air Hose 455022 . Couplings	Any equivalent with NIOSH approval
Portable Light	Teledyne Explosion Proof Lantern 287EX	Any portable light raced for use in explosive aumosphere
Air Mover - Electric	Coppus Vanco "C" Explosion Proof	VL Glass/Group D
Air Mover - Air Driven	Coppus Jectair Air Mover 3" Model Equipped with Grounding Device	Lamb Air Mover 3" Model or Equal Per Rated Capacity
Pipe Plugs (Internal Expanding)	Mosller Mfg. Co. Pipe I.D. Mosller No. 1" 44141-4 1-1/4" 44050-4 1-1/2" 44165-5 1-3/4" 44027-2 2" 46098-3 2-1/4" 44402-2 2-1/2" 44052-2 3" 44117-4 3-7/8" 40246-2	
Choct Harness	Atlas Safety Equipment Nylon No. 238	Any Equivalent-Must be NIOSH approved
Self Contained Breathing Apparatus (Escape Air)	Survivor Mippack System	Any equipment with NIOSH approval and minimum 10 min. air supply

field service menual o/c tanks corporation

 SAFARY	section
	bulletin
 1/1/90	date
1/4/84	supersedes

FIELD SAFETY - GENERAL

I. POLICY

Unusual and frequently unexpected scute hazards may be encountered when Field Service personnel must enter a tank, manhole or pipe. For this reason, all O/C Tanks personnel having cause to enter a tank, manhole, pipe, pit, ditch, or other confined space will exercise proper safety precautions as outlined in this procedure and others that apply to specific situations.

II. RESPONSIBILITY

Safety is the responsibility of each O/G Tanks employee. Ultimately, this responsibility rests with the Field Service Manager operating the Field Service Organization. In fulfilling this responsibility, the Field Service Manager shall:

- A. Insure that proper safety equipment is available, in good working order, and that the operation and calibration of instruments is understood by Field Technicians.
- B. Insure that employees under their control understand and comply with the various safety Policies, Procedures and Precautions as provided.

III. HAZARDS

The hazards commonly encountered are:

- A. Toxic vapors in fatal concentrations may result from known material in the tank, by gradual release from sludge or scale, or be introduced by leakage from interconnected systems due to failure to blank off or disconnect pipelines or ducts.
- B. Lack of oxygen, causing asphyxiation may result from chemicals absorbing or replacing oxygen in the tank air or from inert gas often used to exclude oxygen to reduce the possibility of emplosions. Air in clean tanks closed for an extended period may become deficient in oxygen. Improper or insdequate ventilation during tank work may also result in a lack of oxygen.
- G. Electric shock from portable lights, tools or associated electrical equipment.
- D. Injury from mechanical equipment such as mixers, conveyors, etc., inadvertently activated.
- E. Bodily injury from direct contact with corrosives or dermanitisproducing chemicals.

*ሮፕ ነ*ማ የ

III. HAZARDS (cont'd)

- F. physical hazards such as slipping, falling and falling objects.
- G. Burn hazards resulting from accidental opening of a steam valve in a line which has not been blanked off or ignition of flammable vapors.
- H. Fire and explosion from flammable liquid vapors such as gasoline.

IV. SAFETY REQUIREMENTS - GENERAL Every attempt has been made to make the safety procedures established by these instructions as foolproof as possible. However, there is no substitute for constant elertness and intelligent planning in every vassel or pipe entry situation.

In addition to rigid enforcement of the provisions of the established procedures, it is essential that all persons involved in each job recognize the extreme hazards involved and act accordingly. Enforcement of these minimum safeguards will under no circumstances be considered as relieving those involved from responsibility for any unforeseen development or circumstance.

If the conditions of the procedures cannot be specifically met or if questions arise from the interpretation of any part of these procedures, they are to be referred to the technicians immediate supervisor for resolution.

fie:	ld ser	vice	manual
0/0	tanks	cor	poration

pection	Bafaty	
bullatin	3	
date	1/1/90	
supersedes	1/4/84	

SAFETY PROCEDURE - UNDERGROUND PETROLEUM TANK ENTRY

The following procedure will be employed whenever an OCF Field Technician has cause to enter an underground petroleum storage tank, either for inspection or repair. Any additional state, local or federal regulations must be observed. Additional customer requirements should be cleared through Field Service in Toledo.

General Requirements

- 1, Only air-powered mechanical tools are to be employed.
- 2. The tank is to be mechanically ventilated at all times that a man is inside the tank.
- 3. Use of a positive pressure air-supplied mask with Egress cylinder is required at all times unless it can be absolutely ascertained that the tank has never contained a product and is vapor free, toxic hazard free and contains sufficient 0,.
- 4. An approved safety harness with lifelines attached must be worn by the man entering the tank.
- 5. Tanks having an atmosphere over 130°F are not be entered.
- 6. Only an approved explosion proof light source is to be used.
- 7. A Confined Space Entry Permit is required to be completed and posted prior to each tank entry.
- 8. A reliable safety observer with an SCBA safety harness and an air horn with no duties other than assisting and monitoring the O/C Tanks technician, must be available for immediate use at all times. The safety observer is allowed to pass tools and similarly assist the man in the tank as long as voice and preferably visual contact is maintained. If the safety observer must leave the tank area, the technician is to halt work and exit the tank immediately.

In addition to the primary safety observer, one (1) additional man must be within hearing distance and aware of the air horn signal and summon outside assistance (fire department, rescue squad, etc.) and stand by to direct them to the scene and also to help in a physical rescue if required.

- 9. No flash pictures are to be taken in the tank.
- 10. No air tests are to be performed on a tank containing product. Reference NFPA 329.

חזיין באוואן קאל פאנפת סבו, בני ואלני

General Requirements (cont'd)

- Backfill and/or slab must be properly shored to prevent collapse or cave-in.
- 12. No product deliveries are to be made to any tank on the site while a man is in a tank.

Entry Procedure

MOA BLIGHER LELEVAN THE

- 1. Instruct Sefety Observer
 - a. Monitoring the combustion and O2 meter.
 - b. Being elert for possible sources of ignition (disarette smokers, open flames, etc.).
 - c. Constantly watching for erratic movements of the tachnician while he is in the tank.
 - d. Assisting in feeding and pulling lifelines and air lines.
 - e. Assisting the technician by seesing tools, materials, "to.
 - f. Maintaining visual or voice contact with the man in the term.
 - g. Punting on the safety harmess and use of lifelines.
 - h. Use of SCBA and mir horn.
 - Emergency procedure and telephone numbers.

The pafety observer is to tell the technician (yell loudly, sound six horn) to exit tank if:

- a. The slarms on the combustion and 02 mater go off.
- b. The compressor stops or something interrupts or restricts air supply to the technicien.
- A source of ignition is close by.
- d. The movements of the technician indicate he is getting "dru k" or otherwise unstable.
- e. A fire breaks out in the tank or in the immediate area of the technician in the tank.

in rafety observer is not to enter the tank for rescue under any circumstance, til a rescue toam is on the scene.

If prysical rescue is required, the safety observer is to:

Summon the backup man (sound air horn if necessary) who will immediately call for outside help (fire department, rescue squad, etc.).



SHELL OIL CORPORATION QUARTERLY REPORT TO THE CALIFORNIA REGIONAL WATER QUALITY CONTROL BOARD County of ALAMEDA Date of Report: 10/15/90

Site ID: 204550853 3420 SAN PABLO AVE City of OAKLAND

Actions in past three months: SOUGHT ENCROACHMENT PERMIT FOR OFF-SITE MONITORING WELLS. PERFORMED QUARTERLY GROUND WATER MONITORING.

Actions planned for next three months: AFTER RIGHTS-OF-ENTRY SECURED. INSTALL DEVELOP, AND SAMPLE OFF-SITE MONITORING WELLS. PREPARE PROBLEM ASSESSMENT REPORT FOR SHELL, AGENCY REVIEW.

Soil contamination defined? No Contractor: DELTA ENVIRONMENTAL

Soil clean-up in progress? No Free product plume defined? No Free product clean-up in progress? No Dis'ld const'nt plume defined? No Dis'ld const'nt clean-up in progress? No

853 - -



90 APR -4 AMII: 00

3330 Data Drive Rancho Cordova, CA 95670 916/638-2085 FAX:916/638-8385

March 29, 1990

Mr. Dennis Byrne
Environmental Health Services
Hazardous Materials Department
County of Alameda
470 27th Street
Oakland, California 94607

Subject: Project Status - Shell Service Station

3420 San Pablo Avenue, Oakland, California

Delta Project No. 40-88-666

Dear Mr. Byrne:

This letter is an update on work currently being performed for the subject site. On January 18 and 19, 1990, five monitoring wells were drilled and installed. All monitoring wells were later sampled. A report with findings is forthcoming. Quarterly sampling will be performed in April 1990.

If you have any questions regarding this site, please call me at (916) 638-2085.

Sincerely,

DELTA ENVIRONMENTAL CONSULTANTS, INC.

Hal Hansen

Hydrogeologist/Project Manager

Hal Hansen

HH:ecd

cc: Ms. Lisa McCann, California Regional Water Quality Control Board, San Francisco Bay Region Ms. Diane Lundquist, Shell Oil Company



89 NOV 31 AM 10: 36

3330 Data Drive Rancho Cordova, CA 95670 916/638-2085 FAX:916/638-8385

November 20, 1989

Mr. Dennis Byrne Environmental Health Services Hazardous Materials Department County of Alameda 470 27th Street Oakland, California 94607

Subject:

Project Status--Shell Service Station

3420 San Pablo Avenue, Oakland, California

Delta Project No. 40-88-666

Dear Mr. Byrne:

This letter is to update you on the status of the subject site. Delta Environmental Consultants, Inc. (Delta), has been seeking an encroachment permit from the City of Oakland to proceed with the second phase of hydrogeologic assessment described in Delta's *Preliminary Hydrogeologic Assessment Report*, dated July 31, 1989.

The acquisition of this permit has taken longer than anticipated due to the City's reviewing process. It is believed that the permit application will be approved prior to December 1, 1989. As soon as the permit is obtained, Delta is ready to proceed with the second phase of our hydrogeologic assessment, including advancement of four soil borings and installation of four monitoring wells, as described in the aforementioned report.

If you have any questions, please call me at (916) 638-2085.

Sincerely,

DELTA ENVIRONMENTAL CONSULTANTS, INC.

Hal E. Hansen

Hydrogeologist/Project Manager

Hal E. Warsen

HEH:mid

cc/enc: Ms. Lisa McCann, California Regional Water Quality Control Board,

San Francisco Bay Region

Ms. Diane Lundquist, Shell Oil Company

19 July 1989

DEPARTMENT OF ENVIRONMENTAL HEALTH Hazardous Materials Program 80 Swan Way, Rm. 200 Oakland, CA 94621 (415)

Hal Hansen Delta Environmental Consultants, Inc. 3330 Data Drive Rancho Cordova, CA 95670

Subject: Requested File Search concerning 3400 San Pablo Avenue, Oakland, CA 94608.

Dear Mr. Hansen:

Enclosed please find the boring logs and analytical data present in our files concerning the facility listed above. This information is being communicated to you as per your written request of 5 July, 1989.

This packet is limited to information available to this department and does not reflect information which may be accessible from other agencies or businesses involved with this property.

Please direct any further correspondence or questions which you may have regarding this matter to Dennis Byrne, Hazardous Materials Specialist, at (415) 271-4320.

Sincerely,

Rafat A. Shahid, Chief, Hazardous Materials Division

RAS: DB

7/6/87



DEPT. OF ENVIRONMENTAL HEALTH
HAZARDOUS MATERIALS

3330 Data Drive Rancho Cordova, CA 95670 916/638-2085 FAX:916/638-8385

July 5, 1989

Mr. Dennis Byrne Environmental Health Services Hazardous Materials Division 80 Swan Way, Room 200 Oakland, California 94621

Subject:

Request for Information 3400 San Pablo Avenue Oakland, California

Delta Project No. 40-88-666

Dear Mr. Byrne:

Delta Environmental Consultants, Inc. is requesting information on soil and ground contamination at 3400 San Pablo Avenue in Oakland, California. Any information regarding this site would be greatly appreciated.

If you need any additional information or have any questions, please don't hesitate to call me at (916) 638-2085. Thank you for your cooperation in this matter.

Sincerely,

DELTA ENVIRONMENTAL CONSULTANTS, INC.

Hal Hansen

Hydrogeologist

Hal Hansen

HEH:cf Enclosure HEALTH CARE SERVICES
DAVID J. KEARS, AGENCY



Department of Environmental Health Hazardous aterials Division 80 Swan Way, Room 200 Oakland, CA 94621

CXXIX NX KRSX KR, Agency Director

ZHEKAKUDGAEKIKUNGKA HEKIR KIKA KEK VERK BIKIBIKEN KIKABAK

(415) 271-4320

15 March, 1989

Daryl Nations Delta Environmental Consultants, Inc. 11030 White Rock Road Suite 110 Rancho Cordova, Ca. 95670

Subject: Monitoring Well Installation at 3420 San Pablo Avenue in

Oakland.

Dear Mr. Nations:

Thank you for the work plan submitted to our office concerning the installation of four groundwater monitoring wells at 3420 San Pablo Avenue in Oakland. The proposed well locations and follow-up analysis meets with the approval of the Alameda County Department of Environmental Health, Hazardous Materials Division.

If you have any questions concerning this matter, please contact, Dennis Byrne, Hazardous Materials Specialist, at (415) 271-4320.

Sincerely,

Rafat A. Shahid, Chief,

Hazardous Materials Division

RAS: DB

FUELLEAK CASE FORM

Enter Date 5 / 5/89
Review Date 58/1/89
Date of Last Corr 2 / 15/89
Report Date 2/15/89
Rev Stat
Evaluator
site Name Shell
Street Number 3420
Street San Pablo Cur
city <u>oakland</u>
Zip
County
Primary Substance <u>900669</u>
Secondary Substance
Max. Soil Conc. (ppm) 1400
Soil Affected (Y) U
Max. GW Impact (ppb)
Case Type S G D (0)
Groundwater Depth 8
Missing Tests
Proof An
P1001
Well Status $N\omega$
well Status IV W
Priority B3
Rank
Status N
· · · · · · · · · · · · · · · · · · ·
Xdate/
Tdate/
Idate ///////
Rdate ////
Cdate ////
Pdate //
Enfrcedate / /
Sdate / /
Perm 1 2 3
Abate Method () †
Abace Mechod (/)
Lead Agency L R Division UPC
Lead Agency I R O DIVISION OF
Consultant OFC Lab ANX
_ 1
Funds S F
Enforce Type (0) 1 2
Pilot Program Y N
RP Search (S) I R N
Comment (80 Characters)
Plan for for the things in extend identification
Plan Jos for deflippethin extent identification
V V V V