

Ingersoll-Rand  
1944 Marina  
San Leandro

2017

Memo to file:

3/2/98

I spoke w/ J. McDermitt (Capsule) re: my review of SLED records re: possible UST sites near Ingersoll-Rand. No obvious "smoking guns" were identified.

We discussed 3 potential steps needed to move the project forward:

- ① define northern limits of plume - this will require access to Mark and Case properties
- ② identify receptor populations off-site (e.g., 4M, Case, Mark, etc.) and collect sufficient data to make a risk management decision
- ③ get new Ste in areas where FDP and high conc. were detected in '85 study - these data will be used in RBCA for off-site receptors

Mr. McDermitt will get back to me this week to inform me of his conversations w/ his clients.

DS



**James E. Nash**  
President

1970 Oakcrest Avenue, Suite 215  
St. Paul, MN 55113

(612) 636-2644  
Fax (612) 636-3106

Robert L. Heindl

Facilities Manager  
Ingersoll-Rand  
Equipment Sales

**INGERSOLL-RAND**  
CONSTRUCTION & MINING

Ingersoll-Rand Company  
1495 Valley Center Parkway  
Bethlehem, PA 18017-2293  
(215) 882-8804  
Fax: (215) 882-8859

Alex P. Aguirre, Jr.

Operations Manager  
Northern California

 **INGERSOLL-RAND**

Ingersoll-Rand Equipment Sales  
1944 Marina Boulevard  
San Leandro, CA 94577  
(510) 357-9131  
(510) 633-3488 Pager