ALAMEDA COUNTY HEALTH CARE SERVICES

AGENCY

DAVID J. KEARS, Agency Director

2021

ENVIRONMENTAL HEALTH SERVICES ENVIRONMENTAL PROTECTION 1131 Harbor Bay Parkway, #250 Alameda, CA 94502-6577 (510) 567-6700 FAX (510) 337-9335

Certified Mail #P143589311 09/12/96 STID# 3963

Notice of Requirement to Reimburse

Mr. Jim Newman, Mgr. Cal Trans P.o. Box 23660 Oakland, California 94623-0660

SF-Oak Bay Bridge 0 BayBridge Toll Pl Oakland , CA 94623 Responsible Party (RP) Property Owner

SITE

Date First Reported 09/11/96

Substance: Gasoline Petroleum: (X) Yes

Source: F

The federal Petroleum Leaking Underground Storage Tank Trust Fund (Federal Trust Fund) provides funding to pay the local and state agency administrative and oversight costs associated with the cleanup of releases from underground storage tanks. The legislature has authorized funds to pay the local and state agency administrative and oversight costs associated with the cleanup of releases from underground storage tanks. The direct and indirect costs of overseeing site investigation or remedial action at the above site are funded, in whole or in part, from the Federal Trust Fund. The above individual(s) or entity(ies) have been identified as the party or parties responsible for investigation and cleanup of the above site. YOU ARE HEREBY NOTIFIED that pursuant to Title 42 of the United States Code, Section 6991b(h)(6) and Section 25297.1 of the California Health and Safety Code, the above Responsible Party or Parties must reimburse the State Water Resources Control Board (SWRCB) not more than 150 percent of the total amount of site specific oversight costs actually incurred while overseeing the cleanup of the above referenced underground storage tank site, and the above Responsible Party or Parties must make full payment of such costs within 30 days of receipt of a detailed invoice from the SWRCB.

A determination of a secondary RP status may be made if it is shown that one or more of the RP(s) is performing corrective action and it is clear that the party seeking secondary status did not in any way initiate or contribute to the actual discharge. If the primary RP fails to perform corrective action, then the secondary RP will be considered a primary RP. To request designation as a secondary RP, contact this office.

AGENCY DAVID J. KEARS, Agency Director



tate Water Resources Control Board
Division of Clean Water Programs
UST Local Oversight Program

certified mailer #P 367 604 608

December 16, 1991 STID# 3573 DEPARTMENT OF ENVIRONMENTAL HEALTH Hazardous Materials Program 80 Swan Way, Rm. 200 Oakland, CA 94621

Notice of Requirement to Reimburse

Melquides F. & Antonia D. Jocson 17771 Meekland Ave. Hayward, CA 94541

Responsible Party Contact Person Contact Company

Jocson Auto Electric 17771 Meekland Ave. Hayward, CA 94541

SITE

Date First Reported: 01/03/91 Substance: gasoline Petroleum (X) Yes

The federal Petroleum Leaking Underground Storage Tank Trust Fund (Federal Trust Fund) provides funding to pay the local and state agency administrative and oversight costs associated with the cleanup of releases from underground storage tanks. The legislature has authorized funds to pay the local and state agency administrative and oversight costs associated with the cleanup of releases from underground storage tanks. The direct and indirect costs of overseeing removal or remedial action at the above sight are funded, in whole or in part, from the Federal Trust Fund. The above individual(s) or entity(ies) have been identified as the party or parties responsible for investigation and cleanup of the above site. YOU ARE HEREBY NOTIFIED that pursuant to Title 42 of the United States Code, Section 6991b(h)(6) and Sections 25297.1 and 25360 of the California Health and Safety Code, the above Responsible Party or Parties must reimburse the State Water Resources Control Board not more than 150 percent of the total amount of site specific oversight costs actually incurred while overseeing the cleanup of the above underground storage tank site, and the above Responsible Party or Parties must make full payment of such costs within 30 days of receipt of a detailed invoice from the State Water Resources Control Board.

If you have any questions concerning this matter please contact Thomas Peacock, Supervising Hazardous Material Specialist, at this office.

Edgar B. Howell, III, Chief Contract Project Director

cc: Sandra Malos, SWRCB

SWRCB Use

add: X

Reason: New case

ALAMEDA COUNTY

HEALTH CARE SERVICES

November 15, 1991

STID# 3573

AGENCY

DAVID J. KEARS, Agency Director



tate Water Resources Control Board Division of Clean Water Programs UST Local Oversight Program

> DEPARTMENT OF ENVIRONMENTAL HEALTH Hazardous Materials Program 80 Swan Way, Rm. 200 Oakland, CA 94621

xxx(510) 271-4320

Notice of Requirement to Reimburse

Melquides F. & Antonia D. Jocson 3110 Raleigh Ct. Fremont, CA 94555

certified mailer #P 367 604 349

Responsible Party Contact Person Contact Company

Jocson Auto Electric 17771 Meekland Ave. Hayward, CA 94541

SITE

Date First Reported:01/03/91 Substance: gasoline Petroleum (X) Yes

The federal Petroleum Leaking Underground Storage Tank Trust Fund (Federal Trust Fund) provides funding to pay the local and state agency administrative and oversight costs associated with the cleanup of releases from underground storage tanks. The legislature has authorized funds to pay the local and state agency administrative and oversight costs associated with the cleanup of releases from underground storage tanks. The direct and indirect costs of overseeing removal or remedial action at the above sight are funded, in whole or in part, from the Federal Trust Fund. The above individual(s) or entity(ies) have been identified as the party or parties responsible for investigation and cleanup of the above site. YOU ARE HEREBY NOTIFIED that pursuant to Title 42 of the United States Code, Section 6991b(h)(6) and Sections 25297.1 and 25360 of the California Health and Safety Code, the above Responsible Party or Parties must reimburse the State Water Resources Control Board not more than 150 percent of the total amount of site specific oversight costs actually incurred while overseeing the cleanup of the above underground storage tank site, and the above Responsible Party or Parties must make full payment of such costs within 30 days of receipt of a detailed invoice from the State Water Resources Control Board.

If you have any questions concerning this matter please contact Thomas Peacock, Supervising Hazardous Material Specialist, at this office.

Edgar B. Howell, III, Chief Contract Project Director

cc: Sandra Malos, SWRCB

SWRCB Use :

add: X

Reason: New case

P 367 604 349

RECEIPT FOR CERTIFIED MAIL

NO INSURANCE COVERAGE PROVIDED NOT FOR INTERNATIONAL MAIL (See Reverse)

Street and No 3110 Raleigh Ct PO. State and ZIP Code Fremont, CA 945	-
3110 Raleigh Ct PO State and ZIP Code Fremont, CA 945	-
PO. State and ZIP Code Fremont, CA 945	-
Postage	
	\$
Certified Fee	
Special Delivery Fee	
Restricted Delivery Fee	
Return Receipt showing to whom and Date Delivered	-
Return Receipt showing to whom, Date, and Address of Delivery	
TOTAL Postage and Fees	\$2.29
Postmark or Date	

P 367 604 608

RECEIPT FOR CERTIFIED MAIL

NO INSURANCE COVERAGE PROVIDED NOT FOR INTERNATIONAL MAIL

	(See Reverse)		
≏U.S.G.P.O. 1989-234-555	Sent to The Jocson		
. 1989.	Street and No. Meekland	Ave.	
s.a.P.o	P.O., State and ZIP Code Hayward, CA 945	41	
U.§	Postage	s ·	
	Certified Fee		^
Form 3800, June 1985	Special Delivery Fee		(
	Restricted Delivery Fee		Ľ
	Return Receipt showing to whom and Date Delivered		
	Return Receipt showing to whom, Date, and Address of Delivery		
June	TOTAL Postage and Fees	\$2.29	
3800,	Postmark or Date	m	
er a	Postmark or Date HIS YEAR 430.413	4pm	7/
PS F	420/	17-11-	

SENDER: Complete items 1 and 2 when additional services are de and, and complete items 3 and 4. Put your address. a "RETURN TO" Space on the reverse side. Failure do this will prevent this card from being returned to you. The return receipt fee will provide you the name of the person delivered to and the date of delivery. For additional fees the following services are available. Consult postmaster for fees and check box(es) for additional service(s) requested. 1. Show to whom delivered, date, and addressee's address. 2. Restricted Delivery (Extra charge)			
3. Article Addressed to: M.F. & A.D. Jocson	4. Article Number		
17771 Meekland Ave. Hayward, CA 94541	Type of Service: Registered Insured COD Express Mail Return Receipt for Merchandise		
	Always obtain signature of addressee or agent and DATE DELIVERED.		
5. Signature - Address X - DOCK 6. Signature - Agent X 7. Date of Delivery 1.2/18/9/ Rodram	8. Addressee's Address (UNLY if requested and fee paid)		
PS Form 3811, Mar. 1988 # US G.P.O. 1988-212	SAS DOMESTIC DETUDAL DECEMBER		