

JUL 30 2002

FIGURE 1 - Vicinity Map



© 1997 DeLorme, Street Atlas USA

Mag 16.00
Fri Nov 05 17:12 1999

Scale 1:3,906 (at center)

200 Feet

100 Meters

HORTON

Local Road

Interstate/Limited Access

Major Connector

Railroad

Table 1
Potential Off-Site Sources

Former Tosco 76 Service Station 3737, Emeryville, California

Map ID	Site	Street Address	Environmental Database Listing(s)
1	Schwabacker Frey	5733 Pelledreau	LUST (gasoline; soil affected) CORTESE
2	Michel Pelton Co. (Animal Care Products)	5743 Landregan/Horton	LUST (leak reported 2/23/87; inactive status; not on priority list) NORTH BAY TOXICS LIST
2	Hogland, Bogart, etc.	5743 Landregan/Horton	UST (tank removed)
3	Chevron Emeryville Terminal	Southwest corner of Landregan and Powell	LUST (leak reported 2/23/87; inactive status; not on priority list) NORTH BAY TOXICS LIST
4	Bay Airgas (formerly Airco Supply Co.)	1350 Powell	UST (unleaded gas; closed; removed)
5	Construction Services	1300 Powell	LUST (oily sheen found 6/97)
6	American Bituminous Asphalt	1520 Powell	CERCLIS/NFRAP (further remedial action planned)
6	Chevron Asphalt Plant & Terminal	1520 Powell	SCL LUST NORTH BAY TOXICS LIST
7	Westinghouse Electric Corporation	5899 Peladeau	SCL (preliminary assessment, no further remedial action planned) CERCLIS/NFRAP LUST (transformer oil spill; remediation started 9/21/85) NORTH BAY TOXICS LIST
8	Hydraulic Electro Service Corporation	5812 Hollis	LUST (diesel; groundwater affected; post remedial action underway) CORTESE

JUL 30 2002

**BAY COUNTIES
PETROLEUM, INC.**

7-25-02

Eva

As I promised

Dave DeWitt