RECEIVED

12:42 pm, Jul 14, 2008

Alameda County Environmental Health

SECOND QUARTER 2008 GROUNDWATER MONITORING REPORT

240 W. MACARTHUR BOULEVARD OAKLAND, CALIFORNIA

Prepared for:

MR. GLEN POY-WING OAKLAND AUTO WORKS OAKLAND, CALIFORNIA

July 2008



SECOND QUARTER 2008 GROUNDWATER MONITORING REPORT

240 W. MACARTHUR BOULEVARD OAKLAND, CALIFORNIA

Prepared for:

MR. GLEN POY-WING OAKLAND AUTO WORKS 240 W. MACARTHUR BOULEVARD OAKLAND, CALIFORNIA 94612

Prepared by:

STELLAR ENVIRONMENTAL SOLUTIONS, INC. 2198 SIXTH STREET BERKELEY, CALIFORNIA 94710

July 8, 2008

Project No. 2003-43



GEOSCIENCE & ENGINEERING CONSULTING

July 8, 2008

Mr. Jerry Wickham Hazardous Materials Specialist Alameda County Environmental Health Department Local Oversight Program 1131 Harbor Bay Parkway, Suite 250 Alameda, CA 94502

Subject: Second Quarter 2008 Groundwater Monitoring Report

Oakland Auto Works Facility – 240 W. MacArthur Boulevard, Oakland, California Alameda County Environmental Health Department Fuel Leak Case No. RO0000142

Dear Mr. Wickham:

Enclosed is the Stellar Environmental Solutions, Inc. report summarizing recent activities conducted at the referenced site. This report presents the findings of the Second Quarter 2008 groundwater monitoring event (the 39th site groundwater monitoring event since August 1997).

This report was uploaded to both the State Water Board's GeoTracker system (T0600102243) and the Alameda County Environmental Health Department's Electronic Upload ftp system.

We declare, under penalty of perjury, that the information and/or recommendations contained in the attached document or report is true and correct to the best of my knowledge.

If you have any questions regarding this report, please contact us at (510) 644-3123.

Sincerely,

Henry Pietropaoli, R.G., R.E.A.

Brust S. Mpkdin

Henry Rehysola

Project Manager

Richard S. Makdisi, R.G., R.E.A.

Principal

cc: Mr. Glen Poy-Wing, property owner and Responsible Party



TABLE OF CONTENTS

			Page			
1.0	INTRO	ODUCTION	1			
	Regula Scope Site D	t Backgroundatory Statusof Reportescription	1 2 2			
2.0	PHYS	ICAL SETTING	7			
	Lithol	graphy and Surface Water Drainageogydwater Hydrology	7			
3.0		ND QUARTER 2008 GROUNDWATER TORING AND SAMPLING	11			
4.0		JLATORY CONSIDERATIONS, ANALYTICAL RESULTS, FINDINGS	13			
	Groun Groun	atory Considerationsdwater Sample Analytical Methodsdwater Sample Resultsy Control Sample Analytical Results	14			
5.0	SUMN	MARY, CONCLUSIONS, AND PROPOSED ACTIONS	23			
		ary and Conclusionssed Actions				
7.0	REFE	RENCES AND BIBLIOGRAPHY	26			
8.0	LIMITATIONS					
Apper	ndices					
Appen	ndix A	Current Event Groundwater Monitoring Field Records				
Appendix B		Current Event Analytical Laboratory Report and Chain-of-Custody Record				
Appen	ndix C	Historical Groundwater Monitoring Well Analytical Data				
Appen	ıdix D	Historical Groundwater Elevation Data				

TABLES AND FIGURES

Tables Pa	age
Table 1 Groundwater Monitoring Well Construction and Groundwater Elevation Data 240 W. MacArthur Boulevard, Oakland, California	. 12
Table 2 Groundwater Sample Analytical Results – June 17, 2008 Hydrocarbons, BTEX, and MTBE	. 17
Table 3 Groundwater Sample Analytical Results – June 17, 2008 Lead Scavengers and Fuel Oxygenates	. 17
Figures Pa	age
Figure 1 Site Location Map	3
Figure 2 Site Plan	4
Figure 3 Groundwater Elevation Map – June 17, 2008	9
Figure 4 Gasoline Isoconcentration Contours – June 2008	. 18
Figure 5 Diesel Isoconcentration Contours – June 2008	. 19
Figure 6 Benzene Isoconcentration Contours – June 2008	. 21
Figure 7 MTBE Isoconcentration Contours – June 2008	. 22

1.0 INTRODUCTION

PROJECT BACKGROUND

The subject property, located at 240 W. MacArthur Boulevard in Oakland, Alameda County, California, is owned by Glen Poy-Wing and his wife of Oakland Auto Works, for whom Stellar Environmental Solutions, Inc. (SES) has provided environmental consulting services since July 2003. The site has undergone contaminant investigations and remediation since 1991 (discussed below).

A list of all known environmental reports is included in Section 7.0, References and Bibliography. This report presents finding for the 39th site groundwater monitoring event since monitoring began in August 1997.

In 2002, the current property owners purchased the property and assumed responsibility for continued environmental investigations. The property was formerly owned by Mr. Warren Dodson (Dodson Ltd.) and operated as Vogue Tyres.

REGULATORY STATUS

The Alameda County Environmental Department of Environmental Health (ACEH) is the lead regulatory agency for the case, acting as a Local Oversight Program (LOP) for the Regional Water Quality Control Board (Water Board). There are no ACEH or Water Board cleanup orders for the site; however, all site work has been conducted under oversight of ACEH. In our August 2003 review of the ACEH case file, we determined that all known technical reports for the site were included in the case file to that point.

The previous consultant requested site closure in March 2003 (AEC, 2003a). ACEH received that request and, in a letter dated April 16, 2003, requested additional site characterization prior to considering case closure. That work was subsequently conducted by SES, and was summarized in our April 2004 Soil and Groundwater Investigation Report (SES, 2004c). In December 2004, SES submitted a workplan for interim remedial action (including additional site characterization and an evaluation of soil vapor extraction as an interim corrective action). ACEH responded to that workplan in its March 2006 letter (Water Board, 2006), approving the work (with minor technical revisions). The December 2004 workplan was implemented in May 2007 and presented in a separate technical report, dated August 1, 2007. ACEH responded in its

letter dated August 24, 2007 requesting a workplan for the installation and operation of a soil vapor extraction (SVE) system. The SVE system design was submitted by SES to ACEH, and was approved by ACEH in its letter dated October 5, 2007; the letter included a request for a SVE System Start-Up Report by March 10, 2008. Implementation of SVE remediation has been delayed indefinitely by the property owner due to financial/personal considerations. The delay has been tentatively approved by ACEH who has requested to be kept apprised of the situation every 6 months. Quarterly groundwater monitoring is still being conducted on an uninterrupted basis at the site.

The site is in compliance with State Water Resources Control Board's "GeoTracker" requirements for uploading of technical data and reports. In addition, electronic copies of technical documentation reports published since the Second Quarter of 2005 have been uploaded to ACEH's file transfer protocol (ftp) system.

The site has been granted a Letter of Commitment (and has been receiving financial reimbursement) from the California Underground Storage Tank Cleanup Fund.

SCOPE OF REPORT

This report discusses the work conducted between April 1st and June 30, 2008 (i.e., the 39th groundwater monitoring and sampling event, conducted on June 17, 2008).

SITE DESCRIPTION


The project site is located at 240 W. MacArthur Boulevard in Oakland, California (see Figure 1). The rectangular-shaped project site is approximately 14,000 square feet (140 feet long by 100 feet wide), and is oriented with its long axis parallel to W. MacArthur Boulevard (approximately northwest-southeast). The project site is essentially flat and is wholly paved. One structure currently exists on the property—an automobile servicing shop that covers approximately 50 percent of the property.

The building is currently occupied by Oakland Auto Works. Figure 2 is a site plan showing adjacent land uses.

Adjacent land use includes: a Shell-brand service station (*to the south*); W. MacArthur Boulevard (*to the west*); Howe Street (*to the north*); and a paved driveway, then a multi-story (with basement) health services building (*to the east*).

Figure 1 shows the site location. Figure 2 shows the site plan and locations of current groundwater monitoring well, previous investigative borings and former underground fuel storage tanks (UFSTs).





HISTORICAL ENVIRONMENTAL ACTIVITIES

This section summarizes historical (prior to the current quarter) environmental remediation and site characterization activities, based on documentation provided by the current property owners as well as ACEH files.

Historical remediation and site characterization activities include:

- **Pre-1991.** Three 10,000-gallon gasoline UFSTs from a former Gulf service station occupancy were removed prior to 1991 (there is no available documentation regarding the removals).
- 1991. A waste oil sump was removed. Limited overexcavation was conducted, and there was no evidence of residual soil contamination, with the exception of 360 milligrams per kilogram (mg/kg) of petroleum oil & grease (Mittelhauser Corporation, 1991b).
- 1996. A 350-gallon waste oil UFST was removed. Elevated levels of diesel and oil & grease were detected in confirmation soil samples. Subsequent overexcavation was conducted, and there was no evidence of residual soil contamination (All Environmental, Inc., 1997a).
- **January 1997.** In accordance with a request by ACEH, a subsurface investigation was conducted (All Environmental, Inc., 1997b). Six exploratory boreholes were advanced to a maximum depth of 20 feet, and soil samples were collected.
- August 1997. Additional site characterization was conducted. This included sampling of three boreholes, installation of four groundwater monitoring wells, and the initial groundwater sampling event.
- **February 2001.** Four additional groundwater monitoring wells were installed. Maximum historical soil concentrations were detected in well MW-5 in the northeastern corner of the subject property: 11,700 mg/kg of gasoline and 25.6 mg/kg of benzene (AEC, 2001b).
- October 2001. Short-term (less than 1-day duration) groundwater and vapor extraction from five wells was conducted over 4 days (AEC, 2001e) (referred to by that consultant as "Hi-Vac" process).
- **2003.** A sensitive receptor and vicinity water well survey was conducted.
- **April 2004.** Additional site characterization was conducted, including: advancing and sampling of 12 exploratory boreholes; analysis of 64 soil and 12 grab-groundwater sample results; and further evaluation of site hydrogeology and contaminant extent and magnitude.
- **June 2004 to present.** Quarterly groundwater monitoring.

- May to June 2007. Additional site characterization and interim remedial action evaluation. This included eight exploratory boreholes; analysis of 8 soil-gas, 18 soil, and 8 grab-groundwater samples; and a 6-hour SVE pilot test.
- **September 2007.** A workplan for installation and operation of a full SVE system was submitted to ACEH on September 28, 2007.
- October 2007 ACEH has requested submittal of a SVE System Start-Up Report by March 10, 2008.
- **February 2008.** At the request of the property owner, ACEH agreed to a delay of the implementation of SVE remediation due to the property owner's personal and financial situation. ACEH has requested to be kept apprised of the situation every 6 months.

To date, a total of 39 groundwater monitoring events have been conducted at the site.

2.0 PHYSICAL SETTING

The following evaluation of the physical setting of the site—including topography, surface water drainage, and geologic and hydrogeologic conditions—is based on previous (1991 through April 2003) site investigations conducted by others, and site investigations and groundwater monitoring data collected by SES since 2003.

TOPOGRAPHY AND SURFACE WATER DRAINAGE

The site is on a gently-sloping alluvial fan at the base of the Berkeley/Oakland Hills, which rise approximately 1,100 feet above mean sea level (amsl) and are located approximately 3 miles east of San Francisco Bay. The mean elevation of the subject property is approximately 82 feet amsl. The subject property is essentially flat, with a local topographic gradient to the west. The nearest surface water bodies are: 1) Glen Echo Creek, a northeast-southwest trending creek located approximately 800 feet southeast of the subject property; and 2) Rockridge Branch, a north-south trending creek located approximately 1,000 feet northwest of the subject property. Both creeks are culverted underground in the areas nearest the subject property.

LITHOLOGY

A previous SES report included geologic cross-sections through the area of historical investigations (SES, 2004c). The following summarizes site lithologic conditions.

The unsaturated zone (from ground surface to approximately 20 feet below ground surface [bgs]) consists of interbedded silty/sandy clays with silty/clayey sand, with occasional gravelly zones. In the sand zones, clay and/or silt content is high, and the sand is generally very fine- to fine-grained—such that the unit is, in essence, gradational between a clayey sand and a sandy clay. The most laterally-extensive unsaturated zone unit is a sandy clay encountered between ground surface and approximately 15 feet, locally pinching out and displaying lenticular form. Locally, this unit is interbedded with a sandy clay. The sediment types and geometry are suggestive of channel deposits, which is common in depositional facies in this area.

Depth to groundwater in all onsite April 2004 boreholes and all May 2007 boreholes was approximately 20 to 21 feet bgs, predominantly in a saturated, loose, clayey sand. The saturated portion of this clayey sand constitutes the bottom of the unit; the saturated zone is approximately 0.5 to 2.5 feet thick, underlain in all boreholes by a cohesive, non-water-bearing clay. The top of


this clay was consistently at a depth of approximately 21 to 23 feet. Of the 12 boreholes in the April 2004 investigation, 9 were advanced at least 1.5 feet into this clay before terminating (and not encountering visible moisture or sand). Two boreholes B31 and B32 were advanced to 32 feet bgs in the May 2007 investigation and showed this clay extending from its upper reach of 21 to 23 feet bgs to 32 feet bgs. One of the boreholes in the April 2004 investigation was advanced deeper, documenting a thickness of at least 4.5 feet. The lithologic data (supported by soil sample analytical data from both the 2004 and 2007 investigations) strongly suggest that this clay unit inhibits downward migration of groundwater contamination.

The site lithology is consistent with that documented at the adjacent Shell service station site. Specifically, those boreholes have documented the thin upper, water-bearing zone underlain by the likely non-water-bearing clay unit. In three of the four Shell well boreholes, that clay unit was at least 2 feet thick. In one of the well boreholes, the clay unit was underlain by a saturated clayey sand unit (from approximately 22 to 25.5 feet bgs, which was underlain by a non-water-bearing clay). There is insufficient data to conclude whether the second deepest saturated clayey sand is connected to the shallower sitewide saturated zone. The March 2004 Shell boreholes SB-1 and SB-2 (between the Shell wells and the subject property) all terminated at 20 feet bgs, which was too shallow to encounter the underlying clay unit.

GROUNDWATER HYDROLOGY

The number and positioning of the existing eight site monitoring wells is currently adequate to evaluate the general groundwater flow direction and gradient. Four of the wells (MW-1, MW-2, MW-3, and MW-4) are screened between approximately 15 and 25 feet bgs, and the other four (MW-5, MW-6, MW-7, and MW -8) are screened at a depth of 10 to 20 feet.

Figure 3 is a groundwater elevation map that shows elevations and contours from the current (June 2008) groundwater monitoring event. Monitoring wells MW-1, MW-5, MW-6, MW-7, and MW-8 were dry during this sampling event, and therefore were not used in the construction of the Figure 3 groundwater elevation map. Groundwater flow direction in this event was generally to the west, although the data suggest local variations. A generally westward (with a slight southern component) groundwater flow direction has also been measured at the adjacent Shell-branded service station (Cambria Environmental Technology, 2004). Subject property groundwater gradient in the current event could not be measured in all areas of the site, however it was approximately 0.008 feet/foot where measurable. Historical groundwater gradient has varied between approximately 0.002 and 0.008 feet/foot, averaging approximately 0.005 feet/foot.



2003-43-192

Figure 3 contains a rose diagram that shows historical groundwater flow direction measured at the site. The rose diagram is a histogram that has been wrapped around a circle and has the following characteristics:

- Each wedge represents a 15-degree arc of groundwater flow direction.
- The length of each wedge (circle radius) represents the number of sampling events with data falling within the 15-degree arc.
- The bold black line from the center of the circle to the outer edge is the mean groundwater flow direction.
- The arcs extending to either side of the mean groundwater flow direction line represent the 95-degree confidence interval of the data.

Historical equilibrated water levels (in wells) have been measured at depths of approximately 13 to 16 feet (slightly higher than first occurrence of groundwater encountered during drilling), indicating that groundwater occurs under slightly confining conditions. The range of water level elevations has varied by approximately 3 feet, and shows a strong seasonal variation, with highest elevations during the rainy winter-spring seasons and lowest elevations during the dry summer-fall seasons.

Appendix D contains historical site groundwater monitoring well elevation data.

3.0 SECOND QUARTER 2008 GROUNDWATER MONITORING AND SAMPLING

This section presents the groundwater sampling and analytical methods for the current event (Second Quarter 2008), conducted on June 17, 2008. Table 1 summarizes monitoring well construction and groundwater monitoring data. Groundwater analytical results are presented and discussed in Section 4.0. Monitoring and sampling protocols were in accordance with the SES technical workplan (SES, 2003) submitted to ACEH, and subsequent technical revision requested by ACEH. The groundwater sampling event involved the collection of one set of "post-purge" samples from all wells, in accordance with recent revisions to the quarterly monitoring program approved by ACEH.

Specific activities for this event included:

- Measuring static water levels and field measurement of "pre-purge" groundwater samples for hydrogeochemical parameters (temperature, pH, electrical conductivity, turbidity, and dissolved oxygen) in the eight site wells; and
- Collecting "post-purge" groundwater samples from four of the eight onsite wells for field measurement of the aforementioned hydrogeochemical parameters, and for offsite laboratory analyses for contaminants of concern.

Five of the eight monitoring wells could not be sampled due to seasonally lowered groundwater levels that resulted from the low seasonal rainfall in 2007-2008. The locations of all site monitoring wells are shown on Figure 2. Well construction information and water level data are summarized in Table 1. All site wells are 2-inch-diameter PVC, although the borehole geologic logs for MW-1 through MW-4 completed by the previous consultant mistakenly indicated that they are 4-inch-diameter. Appendix A contains the groundwater monitoring field records for the current event.

Groundwater monitoring well water level measurements, sampling, and field analyses were conducted by Blaine Tech Services (San Jose, California) under the supervision of SES personnel. To minimize the potential for cross-contamination, wells were purged and sampled in order of increasing contamination (based on the previous quarter analytical results).

Table 1
Groundwater Monitoring Well Construction and Groundwater Elevation Data 240 W. MacArthur Boulevard, Oakland, California

	W 11 D 41	Well Scree	ned Interval	Groundwater	Groundwater	
Well	Well Depth (feet bgs)	Depth (feet) Elevation (feet)		Level Depth ^(a) June 17, 2008	Elevation ^(b) June 17, 2008	
MW-1	25	19.5 to 24.5	54.5 to 49.5	Dry	NR	
MW-2	25	14.5 to 24.5	64.2 to 54.2	20.60	57.85	
MW-3	25	14.5 to 24.5	63.4 to 53.4	18.80	58.78	
MW-4	25	14.5 to 24.5	63.6 to 53.6	18.23	59.51	
MW-5	20	9 to 19	70.6 to 60.6	Dry	NR	
MW-6	20	9 to 19	69.7 to 59.7	Dry	NR	
MW-7	20	9 to 19	69.6 to 59.6	Dry	NR	
MW-8	20	9 to 19	67.7 to 57.7	Dry	NR	

Notes:

NR = not recorded (dry or only residual water in silt trap)

As the first monitoring task, static water levels were measured in three of the eight site wells (five of the site wells were dry) using an electric water level indicator. Each well was then purged of three wetted casing volumes, and aquifer stability parameters were measured between each purging. When measurements indicated that representative formation water was entering the well, a groundwater sample set was collected from each well with the purging bailer. Samples were then transferred to appropriate sampling containers (40-ml VOA vials with hydrochloric acid preservative and 1-liter amber glass jars), labeled, and placed in coolers with "blue ice." All groundwater samples were managed under chain-of-custody procedures from the time of sample collection until samples were received in the laboratory.

Approximately 6.6 gallons of wastewater (purge water and equipment decontamination rinseate) was containerized in a labeled, 55-gallon steel drum and temporarily stored onsite. This non-hazardous water will continue to be accumulated onsite until it is cost-effective to coordinate its disposal, at which time it will be profiled and disposed of at a permitted wastewater treatment facility.

⁽a) Pre-purge measurement, feet below top of well casing.

⁽b) Pre-purge measurement, feet above mean sea level

4.0 REGULATORY CONSIDERATIONS, ANALYTICAL RESULTS, AND FINDINGS

This section presents analytical results of the most recent monitoring event, preceded by a summary of relevant regulatory considerations.

REGULATORY CONSIDERATIONS

Environmental Screening Levels

There are no published cleanup goals for detected site contaminants in groundwater. The Regional Water Quality Control Board (Water Board) has published "Environmental Screening Levels" (ESLs), which are screening-level concentrations for soil and groundwater that incorporate both environmental and human health risk considerations, and are used as a preliminary guide in determining whether additional remediation and/or investigation are warranted. The ESLs are not cleanup criteria; rather, they are conservative screening-level criteria designed to be protective of both drinking water resources and aquatic environments in general. The groundwater ESLs are composed of one or more components, including ceiling value, human toxicity, indoor air impacts, and aquatic life protection. Exceedance of ESLs suggests that additional remediation and/or investigation may be warranted, such as monitoring plume stability to demonstrate no risk to sensitive receptors in the case of sites where drinking water is not threatened.

The City of Oakland, via its Urban Land Redevelopment Program, utilizes a similar ESL approach in evaluating whether active remediation is necessary at sites proposed for redevelopment. This program is not currently applicable to the site, as no redevelopment is being proposed.

For all site contaminants with published drinking water standards—benzene, toluene, ethylbenzene, and xylenes (BTEX); and methyl *tertiary*-butyl ether (MTBE)—the drinking water standards are equal to or greater than the published ESLs.

Sensitive Receptors

Risk evaluation commonly includes the identification of sensitive receptors, including vicinity groundwater supply wells. As discussed in a previous report (SES, 2004c), the Department of Water Resources identified only one groundwater supply well within 1,500 feet of the site.

Based on its distance and upgradient location relative to the site, there is no reasonable potential for this well to intercept shallow groundwater emanating from the subject property.

As specified in the *San Francisco Bay Region Water Quality Control Plan* (Water Board, 2004), all groundwaters are considered potential sources of drinking water unless otherwise approved by the Water Board, and are assumed to ultimately discharge to a surface water body and potentially impact aquatic organisms. In the case of groundwater contamination, ESLs are published for two scenarios: groundwater <u>is</u> a source of drinking water, and groundwater <u>is not</u> a source of drinking water. Qualifying for the higher ESLs (applicable to groundwater <u>is not</u> a source of drinking water) requires meeting one of the following two criteria:

- 1. The Water Board has completed the *East Bay Plain Groundwater Basin Beneficial Use Evaluation Report* (Water Board, 1999) that delineates three types of areas with regard to beneficial uses of groundwater: Zone A (significant drinking water resource), Zone B (groundwater unlikely to be used as drinking water resource), and Zone C (shallow groundwater proposed for designation as Municipal Supply Beneficial Use). The subject site falls within Zone A.
- 2. A site-specific exemption can be obtained from the Water Board. Such an exemption has not been obtained for this site.

As discussed below, multiple groundwater contaminants have been detected in excess of ESLs, for both groundwater beneficial scenarios (groundwater <u>is</u> versus <u>is not</u> a potential drinking water resource). These data indicate that continued site characterization is warranted until it can be demonstrated that site-sourced contamination poses no unacceptable risk to sensitive receptors. Our subsequent discussion of groundwater contamination is in the context of the ESL criteria for sites where groundwater <u>is</u> a potential drinking water resource.

GROUNDWATER SAMPLE ANALYTICAL METHODS

Groundwater samples were analyzed in accordance with the methods proposed in the SES technical workplan. Analytical methods included:

- Total volatile hydrocarbons gasoline range (TVHg), by EPA Method 8015B (all wells);
- BTEX and MTBE, by EPA Method 8260B;
- The lead scavengers 1,2-dichloroethane (EDC) and 1,2-dibromoethane (EDB), by EPA Method 8260B (all wells except MW-4 and MW-7, which historically have had little or no site-sourced contamination);
- Total extractable hydrocarbons diesel range (TEHd), by EPA Method 8015M (all wells except MW-4 and MW-7, which historically have never detected diesel); and
- Fuel oxygenates, by EPA Method 8260B.

Groundwater samples were analyzed in accordance with the methods proposed in the SES technical workplan. The analytical results for the current event indicate no significant differences from historical analytical results.

GROUNDWATER SAMPLE RESULTS

Five of the eight monitoring wells could not be sampled during this event because of insufficient water due to seasonally lowered groundwater levels. Tables 2 and 3 summarize the contaminant analytical results of the current monitoring event. Appendix B contains the certified analytical laboratory report and chain-of-custody record. Appendix C contains historical site groundwater monitoring well analytical data.

Gasoline and Diesel

Figure 4 shows gasoline isoconcentration contours for the recent event. Gasoline was detected in all three of the wells sampled. Detected concentrations ranged from 190 micrograms per liter (μ g/L) in well MW-4 to 2,400 μ g/L in well MW-2. All of the gasoline concentrations exceeded the 100- μ g/L ESL criterion where groundwater is a drinking water resource. Monitoring wells MW-2 and MW-3 also exceeded the ESL where groundwater is not a drinking water resource (210 μ g/L).

The gasoline concentrations in the Second Quarter 2008 compared to the Second Quarter 2007 show a significant decrease in the gasoline concentration at the monitoring well located just upgradient of the source area (MW-2). A decrease in the gasoline concentration was also observed in downgradient well MW-3 since the previous sampling in June 2007. Gasoline is known to be present offsite under Howe Street (to the northwest) and under W. MacArthur Boulevard (to the southwest). The current quarter historical high TPHg and increasing concentration trend in MW-4 is suspected to be migrating from the adjacent Shell contaminant plume to the southeast.

Figure 5 shows diesel isoconcentration contours for the recent event. Diesel was detected in all of the wells in which it was analyzed for, MW-2 and MW-3, with concentrations ranging from $4,300\,\mu\text{g/L}$ to $1,200\,\mu\text{g/L}$, respectively. These concentrations exceed the 210- $\mu\text{g/L}$ ESL criterion (where groundwater is not a drinking water resource) in both wells. The concentrations observed during this Second Quarter 2008 event are much lower than the previous event (in which diesel concentrations were observed at a historic high) and also significantly lower than the Second Quarter 2007 event.

The diesel plume footprint has historically been similar to that of the gasoline plume but somewhat smaller, and of secondary concern relative to gasoline, with concentrations historically

at significantly lower levels than gasoline. Dies Street (to the northwest) and under W. MacArthur	

Table 2 Groundwater Sample Analytical Results – June 17, 2008 Hydrocarbons, BTEX, and MTBE

Well	TVHg	TEHd	Benzene	Toluene	Ethyl- benzene	Total Xylenes	MTBE
MW-1	NS	NS	NS	NS	NS	NS	NS
MW-2	2,400	4,300	3.9	2.2	3.0	9.4	73
MW-3	2,100	1,200	7.9	< 0.5	< 0.5	0.8	86
MW-4	190	NA	NA	NA	NA	NA	NA
MW-5	NS	NS	NS	NS	NS	NS	NS
MW-6	NS	NS	NS	NS	NS	NS	NS
MW-7	NS	NS	NS	NS	NS	NS	NS
MW-8	NS	NS	NS	NS	NS	NS	NS
ESLs	100 / 210	100 / 210	1.0 / 46	150 / 650	40 / 130	20 / 100	5.0 / 1,800

Notes:

ESLs = Water Board Environmental Screening Levels for commercial/industrial sites where groundwater *is/is not* a potential drinking water resource MTBE = methyl *tertiary*-butyl ether; TEHd = total extractable hydrocarbons - diesel range; TVHg = total volatile hydrocarbons - gasoline range NA = not analyzed for this contaminant; NS = not sampled

All concentrations are expressed in micrograms per liter (µg/L), equivalent to parts per billion (ppb).

Samples in bold-face type exceed the ESL commercial/industrial criterion where groundwater is considered a potential drinking water resource.

Table 3
Groundwater Sample Analytical Results – June 17, 2008
Lead Scavengers and Fuel Oxygenates

Well	EDC	DIPE	TBA
MW-1	NS	NS	NS
MW-2	1.9	11	71
MW-3	1.1	3.2	22
MW-4	NA	NA	NA
MW-5	NS	NS	NS
MW-6	NS	NS	NS
MW-7	NS	NS	NS
MW-8	NS	NS	NS
ESLs	0.5 / 690	NLP	12 / 18,000

Notes:


ESLs = Water Board Environmental Screening Levels for commercial/industrial sites where groundwater *is/is not* considered a drinking water resource. Samples in **bold-face** type exceed the ESL commercial/industrial criterion where groundwater is considered a potential drinking water resource.


DIPE = isopropyl ether; EDC = ethylene dichloride (1,2-dichloroethane); TBA = tertiary-butyl alcohol

The table includes only detected fuel oxygenates and lead scavengers; contaminants analyzed for and not detected include EDB, ETBE, and TAME.

NA = not analyzed for this contaminant; NS = not sampled; NLP = no level published.

All concentrations are expressed in micrograms per liter (µg/L), equivalent to parts per billion (ppb).





Benzene, Toluene, Ethylbenzene, and Total Xylenes

Figure 6 shows the benzene isoconcentration contours for the recent event. Benzene was detected in both of the wells in which it was analyzed—at concentrations of 3.9 μ g/L in MW-2 and 7.9 μ g/L in MW-3. These concentrations were in excess of the 1.0 μ g/L ESL criterion where groundwater is a drinking water resource, but not above the 46 μ g/L ESL where groundwater is not a drinking water resource.

Trace concentrations of toluene, ethylbenzene, and total xylenes were also detected during this event, but were below the ESL criteria where groundwater is a drinking water resource. Historically, these analytes are detected in generally the same wells in which benzene is detected.

Methyl tertiary-Butyl Ether

Figure 7 shows MTBE isoconcentration contours for the recent event. MTBE was detected above the regulatory ESLs in both of the wells in which it was sampled; in MW-2 at 73 μ g/L and MW-3 at 86 μ g/L. As discussed in previous reports (SES, 2004c), MTBE appears to be migrating onto the subject property from the adjacent (to the east) Shell-branded service station. This contamination, however, is unrelated to the separate site-sourced MTBE contamination.


Lead Scavengers and Fuel Oxygenates


The lead scavenger EDC was in excess of the ESL criteria where groundwater is a potential drinking water resource (0.5 μ g/L) in MW-2 and MW-3 at 1.9 μ g/L and 1.1 μ g/L respectively. However, the concentrations were well below the ESL where groundwater is not a potential drinking water resource, 690 μ g/L. The lead scavenger EDB was not detected in either of the two wells it was analyzed for during this event.

Two fuel oxygenates were detected during the current event. DIPE was detected in both of the wells it was analyzed for—at 11 μ g/L in MW-2 and 3.2 μ g/L in MW-3. There are currently no ESLs for DIPE. TBA was detected in both wells in which it was analyzed for—at 71 μ g/L in MW-2 and 22 μ g/L in MW-3. The concentration of TBA was above the ESL of 12 μ g/L where groundwater is a drinking water resource, but well below the ESL where groundwater is not considered a drinking water resource at 18,000 μ g/L.

QUALITY CONTROL SAMPLE ANALYTICAL RESULTS

Laboratory QC samples (e.g., method blanks, matrix spikes, surrogate spikes) were analyzed by the laboratory in accordance with requirements of each analytical method. All laboratory QC sample results and sample holding times were within the acceptance limits of the methods (Appendix B).





2003-43-196

5.0 SUMMARY, CONCLUSIONS, AND PROPOSED ACTIONS

SUMMARY AND CONCLUSIONS

- The site has undergone site investigations and remediation since 1991 (SES has been involved since August 2003) to address soil and groundwater contamination associated with the former onsite UFSTs.
- Sufficient site characterization has been conducted to evaluate the risks associated with residual soil contamination, and to evaluate corrective action options. The data indicate that, if remedial action is not implemented, residual site contamination will remain at elevated levels for many years and longer. A workplan for installation and operation of a SVE system has been submitted and approved by ACEH, however, implementation of the system has been postponed by the property owner.
- A total of 39 groundwater monitoring/sampling events have been conducted in the eight site wells between August 1997 and the current event. ACEH is the lead regulatory agency.
- Five of the eight monitoring wells could not be sampled during this monitoring event because of insufficient water due to low groundwater levels.
- Groundwater at the site appears to be slightly confined, with a flow direction ranging between northwest and west. Subject property groundwater gradient in the current event was approximately 0.008 feet/foot. Historical groundwater gradient has varied between approximately 0.002 and 0.008 feet/foot, averaging approximately 0.005 feet/foot. Groundwater levels in wells that were reliably measurable (MW-2, MW-3, and MW-4) lowered by an average of 0.12 feet since the previous quarter.
- The groundwater plume geometry is typical of what has been observed in previous monitoring events. Seasonal effects do not appear to change the plume migration direction.
- The primary site chemicals of concern, with regard to concentrations and risk issues, are gasoline, benzene, and MTBE. Diesel, aromatic hydrocarbons, lead scavengers, and fuel oxygenates are present at lesser concentrations and over a smaller area.
- The greatest concentrations of gasoline, diesel, and benzene in groundwater are located in the northern corner of the site (near the source area). Maximum groundwater

contamination by MTBE was detected in the downgradient portion of the property, indicating that the center of mass of these contaminants has migrated downgradient. Groundwater contamination above ESL criteria extends offsite (likely no more than 25 feet) beneath Howe Street and W. MacArthur Boulevard.

- As stipulated by ACEH, analysis for lead scavengers will continue to be conducted in wells MW-1, MW-5, and MW-6 (provided there is sufficient water). Fuel oxygenates were detected in those wells, and in MW-2, MW-3, and MW-8. Because lead scavengers and fuel oxygenates are analyzed by the same method at no additional cost, the responsible party has elected to continue analysis for lead scavengers and fuel oxygenates in all wells except MW-4 and MW-7.
- A previous water well survey identified no vicinity water wells with the potential to intercept site-sourced groundwater contamination.
- Potential preferential pathways identified include deep sanitary sewer lines beneath Howe Street and W. MacArthur Boulevard (adjacent to the subject property). Based on the historical detection of gasoline and MTBE in well MW-7 (beyond the Howe Street deep utilities), it appears unlikely that the Howe Street deep utilities are acting as a preferential pathway for site-sourced groundwater contamination. The influence of deep utilities beneath W. MacArthur Boulevard is not known.
- The adjacent Shell service station is contributing minor MTBE and gasoline groundwater contamination to the eastern corner of the subject property. This contamination is unrelated to the separate, site-sourced MTBE and gasoline groundwater contamination in the northern and western portions of the subject property. The current quarter historical high TPHg and increasing concentration trend in MW-4 is suspected to be migrating from the adjacent Shell contaminant plume to the southeast.
- The lower than average groundwater level elevations continue to present excellent conditions for maximizing contaminant mass recovery through the proposed SVE system.
- The site is currently receiving reimbursements from the California Tank Fund.

PROPOSED ACTIONS

The Responsible Party proposes to implement the following actions to address regulatory concerns:

ACEH requested a SVE System Start-Up Report be submitted by March 10, 2008, however, implementation of SVE remediation has been delayed indefinitely by the property owner due to financial/personal considerations. The delay has been verbally

- approved by the ACEH case officer Mr. Jerry Wickham, who has requested to be kept apprised of the situation every 6 months.
- SES recommends that the SVE be installed and operated to remove source area subsurface contamination and move the site toward regulatory closure.
- Quarterly groundwater monitoring of site wells should be continued to monitor the stability of the contaminant plume.
- Required Electronic Data Format uploads should continued to be made to the GeoTracker database, and electronic copies of technical reports should be uploaded to ACEH's ftp system.
- Reimbursement requests should continue to be submitted under the State of California Petroleum UST Cleanup Fund. In the event the property is sold, the current Responsibility Party will coordinate with the new Responsibility Party to transfer Tank Fund eligibility.

7.0 REFERENCES AND BIBLIOGRAPHY

- Advanced Environmental Concepts, Inc. (AEC), 2003a. 1st Quarter Groundwater Sampling Report (2003) Former Vogue Tyres Facility 240 W. MacArthur Boulevard, Oakland, California. March 7.
- Advanced Environmental Concepts, Inc. (AEC), 2003b. 2nd Quarter Groundwater Sampling Report (2003) Former Vogue Tyres Facility 240 W. MacArthur Boulevard, Oakland, California. April 30.
- Advanced Environmental Concepts, Inc. (AEC), 2002a. December 2001 Quarterly Groundwater Sampling Report Former Vogue Tyres Facility 240 W. MacArthur Boulevard, Oakland, California. January 30.
- AEC, 2002b. March 2002 Quarterly Groundwater Sampling Report Former Vogue Tyres Facility 240 W. MacArthur Boulevard, Oakland, California. April 19.
- Advanced Environmental Concepts, Inc. (AEC), 2002c. 2nd Quarter Groundwater Sampling Report (2002) Former Vogue Tyres Facility 240 W. MacArthur Boulevard, Oakland, California. July 17.
- Advanced Environmental Concepts, Inc. (AEC), 2002d. 4th Quarter Groundwater Sampling Report (2002) Former Vogue Tyres Facility 240 W. MacArthur Boulevard, Oakland, California. November 11.
- Advanced Environmental Concepts, Inc. (AEC), 2001a. December 2000 Quarterly Groundwater Sampling Report Former Vogue Tyres Facility 240 W. MacArthur Boulevard, Oakland, California. January.
- Advanced Environmental Concepts, Inc. (AEC), 2001b. Additional Soil and Groundwater Assessment 240 W. MacArthur Boulevard, Oakland, County of Alameda, California. March.
- Advanced Environmental Concepts, Inc. (AEC), 2001c. May 2001 Quarterly Groundwater Sampling Report Former Vogue Tyres Facility 240 W. MacArthur Boulevard, Oakland, California. May 27.

- Advanced Environmental Concepts, Inc. (AEC), 2001d. July 2001 Quarterly Groundwater Sampling Report Former Vogue Tyres Facility 240 W. MacArthur Boulevard, Oakland, California. August 31.
- Advanced Environmental Concepts, Inc. (AEC), 2001e. Summary "Hi-Vac" Workplan Former Vogue Tyres Facility 240 W. MacArthur Boulevard, Oakland, California. September 11.
- Advanced Environmental Concepts, Inc. (AEC), 2001f. October 2001 Quarterly Groundwater Sampling and Summary "Hi-Vac" Report Former Vogue Tyres Facility 240 W. MacArthur Boulevard, Oakland, California. December 15.
- Advanced Environmental Concepts, Inc. (AEC), 2000a. Quarterly Groundwater Sampling Report Former Vogue Tyres Facility 240 W. MacArthur Boulevard, Oakland, California. August 11.
- Advanced Environmental Concepts, Inc. (AEC), 2000b. Additional Groundwater Assessment Workplan for Former Vogue Tyres Facility 240 W. MacArthur Boulevard, Oakland, County of Alameda, California. October.
- Advanced Environmental Concepts, Inc. (AEC), 1999. Quarterly Groundwater Sampling Report

 Former Vogue Tyres Facility 240 W. MacArthur Boulevard, Oakland, California.

 January 22.
- Advanced Environmental Concepts, Inc. (AEC), 1998a. Second Quarterly Groundwater Sampling Report Former Vogue Tyres Facility 240 W. MacArthur Boulevard, Oakland, California. April 2.
- Advanced Environmental Concepts, Inc. (AEC), 1998b. Request for Site Closure Former Vogue Tyres Facility 240 W. MacArthur Boulevard, Oakland, California. June 29.
- Advanced Environmental Concepts, Inc. (AEC), 1998c. Third Quarterly Groundwater Sampling Report Former Vogue Tyres Facility 240 W. MacArthur Boulevard, Oakland, California. August 2.
- Advanced Environmental Concepts, Inc. (AEC), 1998d. Fourth Quarterly Groundwater Sampling Report Former Vogue Tyres Facility 240 W. MacArthur Boulevard, Oakland, California. November 6.
- Advanced Environmental Concepts, Inc. (AEC), 1997a. Subsurface Soil and Groundwater Investigation Workplan for Former Vogue Tyres Facility 240 W. MacArthur Boulevard, Oakland, California. June.

- Advanced Environmental Concepts, Inc. (AEC), 1997b. Continuing Soil and Groundwater Assessment for Former Vogue Tyres Facility 240 W. MacArthur Boulevard, Oakland, California. August.
- Advanced Environmental Concepts, Inc. (AEC), 1997c. First Quarterly Groundwater Sampling Report Former Vogue Tyres Facility 240 W. MacArthur Boulevard, Oakland, California. December 21.
- All Environmental, Inc., 1997a. Underground Storage Tank Removal and Excavation, Transport and Disposal of Contaminated Soil Report 240 W. MacArthur Boulevard, Oakland, California. January 3.
- All Environmental, Inc., 1997b. Phase II Subsurface Investigation Report 240 W. MacArthur Boulevard, Oakland, California. February 14.
- All Environmental, Inc., 1997c. Soil and Groundwater Investigation Workplan 240 W. MacArthur Boulevard, Oakland, California. April 15.
- Cambria Environmental Technology, Inc., 2004. Second Quarter 2004 Monitoring Report, Shell-branded Service Station, 230 W. MacArthur Boulevard, Oakland, California. July 29.
- Guidici, 2003. Supervisor, City of Oakland Public Works Department Sewer Maintenance. Personal communication to Joe Dinan of SES. September 8.
- Mittelhauser Corporation, 1991a. Magnetic Survey for Underground Utilities and Recommendations at 240 W. MacArthur Boulevard, Oakland, California. February 21.
- Mittelhauser Corporation, 1991b. Sump Removal and Waste Oil Cleanup at 240 W. MacArthur Boulevard, Oakland, California. April 9.
- Regional Water Quality Control Board (Water Board), 1999. East Bay Plain Groundwater Basin Beneficial Use Evaluation Report.
- Regional Water Quality Control Board (Water Board), 2005. Screening for Environmental Concerns at Sites With Contaminated Soil and Groundwater. February.
- Regional Water Quality Control Board (Water Board), 2004. Water Quality Control Plan, Triennial Review. Water Board Staff Report. November 5.

- Regional Water Quality Control Board San Francisco Bay Region (Water Board), 2008. Screening for Environmental Concerns at Sites With Contaminated Soil and Groundwater. May.
- Stellar Environmental Solutions, Inc. (SES), 2003a. Workplan for Additional Site Characterization, 240 W. MacArthur Boulevard, Oakland, California. August 20.
- Stellar Environmental Solutions, Inc. (SES), 2003b. Third Quarter 2003 Groundwater Monitoring Report, 240 W. MacArthur Boulevard, Oakland, California. September 5.
- Stellar Environmental Solutions, Inc. (SES), 2003c. Amended Workplan for Additional Site Characterization, 240 W. MacArthur Boulevard, Oakland, California. December 10.
- Stellar Environmental Solutions, Inc. (SES), 2004a. Fourth Quarter 2003 Groundwater Monitoring Report, 240 W. MacArthur Boulevard, Oakland, California. January 12.
- Stellar Environmental Solutions, Inc. (SES), 2004b. First Quarter 2004 Groundwater Monitoring Report, 240 W. MacArthur Boulevard, Oakland, California. April 12.
- Stellar Environmental Solutions, Inc. (SES), 2004c. Soil and Groundwater Investigation Report, 240 W. MacArthur Boulevard, Oakland, California. June 8.
- SES, 2004d. Second Quarter 2004 Groundwater Monitoring Report, 240 W. MacArthur Boulevard, Oakland, California. July 12.
- Stellar Environmental Solutions, Inc. (SES), 2004e. Third Quarter 2004 Groundwater Monitoring Report, 240 W. MacArthur Boulevard, Oakland, California. October 11.
- Stellar Environmental Solutions, Inc. (SES), 2004f. Workplan for Additional Site Characterization and Interim Remedial Action, 240 W. MacArthur Boulevard, Oakland, California. December 27.
- Stellar Environmental Solutions, Inc. (SES), 2005a. Fourth Quarter 2004 Groundwater Monitoring and Annual Summary Report, 240 W. MacArthur Boulevard, Oakland, California. January 18.
- Stellar Environmental Solutions, Inc. (SES), 2005b. First Quarter 2005 Groundwater Monitoring Report, 240 W. MacArthur Boulevard, Oakland, California. March 31.
- Stellar Environmental Solutions, Inc. (SES), 2005c. Second Quarter 2005 Groundwater Monitoring Report, 240 W. MacArthur Boulevard, Oakland, California. July 8.

- Stellar Environmental Solutions, Inc. (SES), 2005d. Third Quarter 2005 Groundwater Monitoring Report, 240 W. MacArthur Boulevard, Oakland, California. October 12.
- Stellar Environmental Solutions, Inc. (SES), 2006a. Fourth Quarter 2005 Groundwater Monitoring and Annual Summary Report, 240 W. MacArthur Boulevard, Oakland, California. January 18.
- Stellar Environmental Solutions, Inc. (SES), 2006b. First Quarter 2006 Groundwater Monitoring Report, 240 W. MacArthur Boulevard, Oakland, California. April 21.
- Stellar Environmental Solutions, Inc. (SES), 2006c. Second Quarter 2006 Groundwater Monitoring Report, 240 W. MacArthur Boulevard, Oakland, California. July 11
- Stellar Environmental Solutions, Inc. (SES), 2006d. Third Quarter 2006 Groundwater Monitoring Report, 240 W. MacArthur Boulevard, Oakland, California. September 29.
- Stellar Environmental Solutions, Inc. (SES), 2007a. Fourth Quarter 2006 Groundwater Monitoring and Annual Summary Report, 240 W. MacArthur Boulevard, Oakland, California. January 16.
- Stellar Environmental Solutions, Inc. (SES), 2007b. First Quarter 2007 Groundwater Monitoring Report, 240 W. MacArthur Boulevard, Oakland, California. May 4.
- Stellar Environmental Solutions, Inc. (SES), 2007c. Second Quarter 2007 Groundwater Monitoring Report, 240 W. MacArthur Boulevard, Oakland, California. July 11.
- Stellar Environmental Solutions, Inc. (SES), 2007d. Corrective Action Assessment Report, 240 W. MacArthur Boulevard, Oakland, California. August 1.
- Stellar Environmental Solutions, Inc. (SES), 2007e. Workplan for Soil Vapor Extraction System Installation and Operation Oakland Auto Works 240 W. MacArthur Blvd., Oakland, CA. September 28.
- Stellar Environmental Solutions, Inc. (SES), 2007f. Third Quarter 2007 Groundwater Monitoring Report, 240 W. MacArthur Boulevard, Oakland, California. October 1.
- Stellar Environmental Solutions, Inc. (SES), 2008a. Fourth Quarter 2007 Groundwater Monitoring and Annual Summary Report, 240 W. MacArthur Boulevard, Oakland, California. January 30.
- Stellar Environmental Solutions, Inc. (SES), 2008b. First Quarter 2008 Groundwater Monitoring Report, 240 W. MacArthur Boulevard, Oakland, California. April 25.

8.0 LIMITATIONS

This report has been prepared for the exclusive use of the current property owners (Mr. and Mrs. Glen Poy-Wing, d.b.a. Oakland Auto Works) their representatives, and the regulators. No reliance on this report shall be made by anyone other than those for whom it was prepared.

The findings and conclusions presented in this report are based on the review of previous investigators' findings at the site, as well as site activities conducted by SES since August 2003. This report provides neither a certification nor guarantee that the property is free of hazardous substance contamination. This report has been prepared in accordance with generally accepted methodologies and standards of practice of the area. The SES personnel who performed this limited remedial investigation are qualified to perform such investigations and have accurately reported the information available, but cannot attest to the validity of that information. No warranty, expressed or implied, is made as to the findings, conclusions, and recommendations included in the report.

The findings of this report are valid as of the present. Site conditions may change with the passage of time, natural processes, or human intervention, which can invalidate the findings and conclusions presented in this report. As such, this report should be considered a reflection of the current site conditions as based on the investigation and remediation completed.

APPENDIX A

Current Event Groundwater Monitoring Field Records

SPH or Purge Water Drum Log

Client:

Stellar Env.

Site Address: 740 W. Macarthur blud., Oakland

STATUS OF DRUM(S) UPON	ARRIVAL					
Date	6/22/67	9/16/07	12/19/07	3/28/08	6/17/08	
Number of drum(s) empty:	0	2	2	2		
Number of drum(s) 1/4 full:	1					
Number of drum(s) 1/2 full:	700 1				十四	
Number of drum(s) 3/4 full:	Ø					
Number of drum(s) full:		Í			1	
Total drum(s) on site:	3	3	3	3		
Are the drum(s) properly labeled?	Y	М	У	У	Y	
Drum ID & Contents:	Prige H20 -	Soil Cuttines	5 OUGE > 50:1 -	_n	Purge/soil	
If any drum(s) are partially or totally filled, what is the first use date:			4			

- If you add any SPH to an empty or partially filled drum, drum must have at least 20 gals. of Purgewater or DI Water.
- -If drum contains SPH, the drum MUST be steel AND labeled with the appropriate label.
- -All BTS drums MUST be labeled appropriately.

STATUS OF DRUM(S) UPON	DEPART	JRE				
Date	6/22/07	9/18/07	12/19/07	3/28/08	6/17/08	
Number of drums empty:	8		////	ì	1	
Number of drum(s) 1/4 full:	0		/			
Number of drum(s) 1/2 full:					1	
Number of drum(s) 3/4 full:						
Number of drum(s) full:			1			
Total drum(s) on site:	3	3	3	3	3	
Are the drum(s) properly labeled?	Y	Y	Y	Y	415	
Drum ID & Contents:	Page H2U -	Soil (ntings	auge's soil		purge/soil	

LOCATION OF DRUM(S)

Describe location of drum(s):

Next to Dimpster

FINAL STATUS						
Number of new drum(s) left on site this event	0	0	0	0	0	
Date of inspection:	6/22/07	16 9/14/09	10/19/07	3/28/08	6/17/08	
Drum(s) labelled properly:	Y	1 Y	ý	4	4	
Logged by BTS Field Tech:	Sil	RUI	KN	15	BO	
Office reviewed by:	M	men	6	PE	8	

TEST EQUIPMENT CALIBRATION LOG

PROJECT NAM	ME OBREBNO	Auto Works		PROJECT NUI	WBER 080617	-BD1	
EQUIPMENT NAME	EQUIPMENT NUMBER	DATE/TIME OF TEST		EQUIPMENT READING	CALIBRATED TO: OR WITHIN 10%:	TEMP.	INITIALS
HACH Turbidimeter	4198161	0900	20 100 800	21 100 807	405		<i>B</i> D
MYRON ultrameter	0218304	0910	14 4 7 10	4.2 7.1 10.00	405	22.1°c	BO
4	1	comp	3900	3907	405	20.2°	150
			-	p ^e .			
				·			

Page _/_ of _/_

WELLHEAD INSPECTION CHECKLIST

Date	117/08	Client	Ste	llar		. · · · · · · · · · · · · · · · · · · ·		
Site Address	240 W 1	Mue H	rthu-					
Job Number	080617	-BD1		Tec	hnician	<i>7</i> S	Doshi	
Well ID	Well Inspected - No Corrective Action Required	Water Bailed From Wellbox	Wellbox Components Cleaned	Cap Replaced	Debris Removed From Wellbox	Lock Replaced	Other Action Taken (explain below)	Well Not Inspected (explain below)
MW-4	X							
MW-7	-						X	
MW-8	· ×							
MW-6	×							
MW-2	X							***************************************
MW-3							×	
MW-1							X	
MW-5	-						X	
								-
NOTES:	MW-77	1 str	ipped	TAB;	MW.	3 7	both to	z bs strippe
MW-1 >	MW-77	; MW	-5=>	1 50/7	Missi	na		
								4-01-18-00-19-00-19-00-19-00-19-00-19-00-19-00-19-00-19-00-19-00-19-00-19-00-19-00-19-00-19-00-19-00-19-00-19-

SAN DIEGO

WELL GAUGING DATA

Project #	2/7-30/_ Date	6/17/08	Client	fellar
Site 2012 11 :	21 - 1 - 1	RII D	un I	

		Well		Depth to	Thickness of	Immiscibles			Survey Point:	
Well ID	Time	Size (in.)	Sheen / Odor	Immiscible Liquid (ft.)	Immiscible Liquid (ft.)		Depth to water (ft.)	Depth to well bottom (ft.)	TOB or	Notes
MW-4	0927	2					18.23	23.90		
MW-7	0938	2		insuff	icient	H20	20.00	20.00		DRY
MV-8	0445	2	40mm	INSUFFI	cient	H20	19.90	19.90		DRY
MW-6	1010	2		INSUFF	ucient	H ₂ O	20.10	20.10		DRY
MW-2	1005	2					10.60	24.30		
MW-3	1015	2					18.80	24.30		
MW-1	1020	2	000E	* 110 S. INSUFFIC	·	ectep*	23.90	24.20		
MW-5	1030	2		INSUFFI	cient	H20	20.10	20.10	+ 1-10-10-1-1-1-1-1-1-1-1-1-1-1-1-1-1-1-1	PRY
					*************************	*************************************				
	·									
				·						
								·		

LL MONITORING DATA SH. I

Client: STELLAR	
Well Diameter: 2 3 4 6 8	
Depth to Water (DTW): 23.90	-
Thickness of Free Product (feet):	
D.O. Meter (if req'd): YSI HACH	
Column x 0.20) + DTW]:	
Water a Sampling Method: Bailer Peristaltic Disposable Bailer Extraction Pump Extraction Port Dedicated Tubing Other:	
Gals. Jume Well Diameter Multiplier Well Diameter Multiplier 0.05 1" 0.04 4" 0.65 2" 0.16 6" 1.47 3" 0.37 Other radius²* 0.163	
Turbidity (NTUs) Gals. Removed Observations	
able to sample	
	
Gallons actually evacuated:	
Depth to Water:	
Laboratory: Kiff CalScience Other	
Oxygenates (5) Other:	
Duplicate I.D. (if applicable):	
Oxygenates (5) Other:	
mg/L Post-purge:	g/L
mV Post-purge: m	V
	Date:

Blaine Tech Services, Inc. 1680 Rogers Ave., San Jose, CA 95112 (800) 545-7558

WLLL MONITORING DATA SHELL

		**	LIVIUI IVIUINII	ORING DATA	A SHEL 1				
Project #:	0806	o/7 -	BD 1	Client:	TellAR				
Sampler:	BD				117/0	8			
Well I.D.:	MW-	2		Well Diamete					
Total Well	Depth (TI)): 24.	30	Depth to Wate	Depth to Water (DTW): 20.60				
Depth to Fr	ee Produc	t:		Thickness of Free Product (feet):					
Referenced	to:	PVC	Grade	D.O. Meter (if	reg'd):	YSI HACH			
DTW with	80% Rech	arge [(H	eight of Water	Column x 0.20		21.34			
	Bailer Disposable B Positive Air I Electric Subr	Displacement of the second of	Other	Well Diamet	Other: Well 1 0.04 0.16 0.16	Extraction Port Dedicated Tubing Diameter Multiplier 0.65 1.47			
1 Case Volume	Speci	ified Volum	es Calculated Vo		0.37 Other	radius ² * 0.163			
Time	Temp (°F or %)	рН 7:13	Cond. (mS or AS)	Turbidity (NTUs)	Gals. Removed	Observations			
1150		 	650	1000	0.5	GRY /c/oupy			
1152	21.8	7.08	663	1000	1.0				
1154	21.2	7.07	660	1000	1.5				
						*			
Did well de	water?	Yes (Ŋø	Gallons actual	ly evacuated:	1.5			
Sampling D	ate: 6/1	7/08	Sampling Time	e: // <i>59</i>	Depth to Wate	r: 19.92			
Sample I.D.	: Mh	1-2		Laboratory:	Kiff CalScience	e Other			
Analyzed fo	or: TPH-G	BTEX	MTBE TPH-D	Oxygenates (5)	Other: See	coc			
EB I.D. (if a	applicable)):	@ Time	Duplicate I.D.	(if applicable):				
Analyzed fo	or: TPH-G	BTEX	MTBE TPH-D	Oxygenates (5)	Other:				
D.O. (if req'	(d): Pr	re-purge:		mg/L F	ost-purge:	mg/ _{1.}			
O.R.P. (if re	eq'd): Pi	re-purge:		mV F	ost-purge:	mV			

WLLL MONITORING DATA SHEL.

				··•					
Project #:	0806	17-	BD1	Client:	STELLA	1-R			
Sampler:	BD			Date:	117/08				
Well I.D.:	MW-3	>		Well Diamete	_	6 8			
Total Well			30	Depth to Wate	er (DTW): 18	. 80			
Depth to Fr	ee Produc	t:		Thickness of Free Product (feet):					
Referenced	to:	PVO	Grade	D.O. Meter (if req'd): YSI HACH					
DTW with	80% Rech	arge [(H	leight of Water	Column x 0.20)) + DTW]:	19.90			
0.8	Oisposable B Positive Air I Electric Subn Gals.) X	Displaceme nersible	Other	Well Diame	Other: Other: Other: Well	Bailer Disposable Bailer Extraction Port Dedicated Tubing Diameter Multiplier 0.65 1.47			
1 Case Volume	Speci	fied Volun	nes Calculated Vo	lume	U.S.1 Office	radius * 0.163			
Time 1216	Temp	pH	Cond. (mS or as)	Turbidity (NTUs)	Gals. Removed	Observations Grey (
	23.0	642	692		0.8	Grey/cloudy			
1218	22.5			947	1.6				
1220	23.0	6.37	710	1000	2.4	1			
Did well de	water?	Yes	No	Gallons actual	ly evacuated:	2.4			
Sampling D	ate: 6/	7/08	Sampling Time	: 1228	Depth to Wate	r: <i>19.00</i>			
Sample I.D.	: mu	1-5		Laboratory:	Kiff CalScience				
Analyzed fo	or: TPH-G	BTEX	MTBE TPH-D	Oxygenates (5)	Other: See	COC			
EB I.D. (if a	applicable)	:	(a) Time	Duplicate I.D.	(if applicable):				
Analyzed fo	r: TPH-G	BTEX	MTBE TPH-D	Oxygenates (5)	Other:				
D.O. (if req	'd): Pr	e-purge:		mg/L I	Post-purge:	· mg/1.			
O.R.P. (if re	eg'd): Pr	e-purge:		mV I	Post-purge:	mV			

W. L MONITORING DATA SHEL.

			~							
Project #:	08061	7 - 13/	2/	Client:	Stallar					
Sampler:	B.D.			Date:	0/17/08					
Well I.D.:	MW -	ef		Well Diameter: Ø 3 4 6 8						
Total Well	Depth (TI)): <i>23</i>	.90	Depth to Wa	Depth to Water (DTW): 18.23					
Depth to F	ree Produc	t:		1	f Free Product (fe					
Referenced	l to:	PVO	Grade	D.O. Meter	· · · · · · · · · · · · · · · · · · ·	YSI HACH				
DTW with	.80% Rech	arge [(H	leight of Water	Column x 0.	20) + DTW]:	19.36				
	Disposable E Positive Air Electric Subi (Gals.) X	Displaceme mersible	Other	Gals. Well Dia	Other Other	Extraction Port Dedicated Tubing : Diameter Multiplier 0.65 1.47				
Time	Temp (°F or ©	рН	Cond. (mS or AS)	Turbidity (NTUs)	Gals. Removed	Observations				
1109	19.7	6.26	485	1000	0.9	Brown Cloudy				
1111	19.3	6.08	462	1000	1.8					
1113	19.4	6.07	461	71000	2.7	1				

Did well de	ewater?	Yes (NO NO	Gallons actu	ally evacuated:	2.7				
Sampling D	Date: 6/1	7/08	Sampling Time	e: ///Cp	Depth to Wate	T: 20.3085				
Sample I.D	: MU-	_		Laboratory:	Kiff CalScience	e Other				
Analyzed fo	or: TPH-G	BTEX	MTBE TPH-D	Oxygenates (5)) Other: 5ee	coc				
EB I.D. (if	applicable)):	@ Time	Duplicate I.I	D. (if applicable):					
Analyzed fo	or: TPH-G	BTEX	MTBE TPH-D	Oxygenates (5)		angle of				
D.O. (if req	'd): Pi	re-purge:		mg/L	Post-purge:	mg/L				
O.R.P. (if r	eg'd): Pi	re-purge:		mV	Post-purge:	mV				

LL MONITORING DATA SH. . T

j.				···						
Project #:	0800	017	-BO /	Client	•	STel	IAR			
Sampler:	BD	7.7		Date:	. 6	STe1	108			
Well I.D.:	MW-S	5		Well I	Diameter				8	
Total Well	Depth (TD)): 20	0.10	Depth	to Water	r (DTW): 2c	7.10	<u> </u>	
Depth to Fr	ee Product	:		Thick	Thickness of Free Product (feet):					
Referenced	to:	PVC	Grade	D.O. N	D.O. Meter (if req'd): YSI HACH					
DTW with	80% Rech	arge [(H	Ieight of Water	Colum	n x 0.20)) + DTV	V]:			
Purge Method:	Bailer Disposable B Positive Air I Electric Subn	Displaceme		Waterry Peristation etion Pump		-	g Method Other		Bailer Disposable Bail Extraction Por Dedicated Tubi	rt
(Gals.) X = 1 Case Volume Specified Volumes Calculated Vo					1" 2" 3"	0.04 0.16 0.37	4" 6" Other		0.65 1.47 radius ² * 0.163	
Time				Turbidity (NTUs)		Gals. Removed		E	Observation	S
	2002	(C) EN	7720	unas	/E 78	540	ng le			
				-		***************************************				
Did well der	water?	Yes	Nø	Gallon	s actually	y evacua	ated:			<i>'</i>
Sampling D	ate:		Sampling Time	e:		Depth t	o Wate	r:		
Sample I.D.	•			Labora	tory:	Kiff C	alScience	. 0	ther	
Analyzed fo	r: TPH-G	BTEX	MTBE TPH-D	Oxygen	ates (5)	Other:			/	
EB I.D. (if a	pplicable)		@ Time	Duplic	ate I.D. (if applic	cable):	$\overline{}$		
Analyzed fo	r: лрн-G	BTEX	MTBE TPH-D	6 6 6 7 8 9 9 9 9 9 9 9 9 9 9 9 9 9 9 9 9 9 9	ates (5)	Other:		/		
D.O. (if req'	d): Pro	e-purge:		$^{ m mg}/_{ m L}$	Po	ost-purge	: /			mg/L
O.R.P. (if re	q'd): Pre	e-purge:		mV	Po	ost-purge	:			mV
,			.F			/				

Blaine Tech Services, Inc. 1680 Rogers Ave., San Jose, CA 95112 (800) 545-7558

WL_L MONITORING DATA SHEL.

Project #: 080617 - BD1				Client	<u>:</u>	TELLAR	•	
Sampler:	BU	WP.		Date:	C	TELLAR 17/17/08		
Well I.D.:	mw-	b		Well I	Diameter		6 8	
Total Well	Depth (TD)): <i>2</i>	0.10	Depth to Water (DTW): 20.10				
Depth to Fr	ee Produc	t:		Thickness of Free Product (feet):				
Referenced	to:	#VC)	Grade	D.O. Meter (if req'd): YSI HACH				
DTW with	80% Rech	arge [(ŀ	Height of Water	Colum	n x 0.20) + DTW]:		
Purge Method:	Bailer Disposable B Positive Air I Electric Subr	Displacem	ent Extrac Other	Waterry Peristation etion Pump	2	Sampling Method Other	Disposable Bailer Extraction Port Dedicated Tubing	
((1 Case Volume	Gals.) X Speci	ified Volur	= nes Calculated Vo	_ Gals. olume	1" 2" 3"	0.04 4" 0.16 6" 0.37 Othe	0.65 1.47	
Time	Temp (°F or °C)	рН	Cond. (mS or μS)	(N	bidity TUs)	Gals. Removed	Observations	
	INSUFF	leien	+ H20 / u	inab)	e fo	sample		
	•							
Did well de	water?	Yes	No/	<u>l</u> Gallon	s actuall	y évacuated:		
Sampling D	ate:	· · · · · · · · · · · · · · · · · · ·	Sampling Time	·	/	Depth to Wate	er:	
Sample I.D.	•			Labora	itory:	Kiff CalScienc		
Analyzed fo	r: TPH-G	втех	MTBE TPH-D	Oxygen	ates (5)	Other:		
EB I.D. (if a	applicable)):	@ Time	Duplic	ate I.D.	(if applicable) <i>:</i>		
Analyzed fo	or: дрн-G	BTEX	MTBE TPH-D	Oxygen		Other:		
D.O. (if req	ˈd): Pr	e-purge:		^{mg} /L	Р	ost-purge:	mg/L	
O.R.P. (if re	eq'd): Pr	e-purge:		mV	Р	ost-purge:	mV	

WLLL MONITORING DATA SHEL.

Project #:	0806	17-	13101	Client	: <i>5</i> 7	ELLS	4 R	
Sampler:	B.D			Date:	6	ELL.	100	
Well I.D.:	mw-	7		Well Diameter: ② 3 4 6 8				
Total Well			. 00	Depth to Water (DTW): 20.00				
Depth to Fr	ee Product	•	·	Thick	ness of F	ree Prodi		
Referenced	to:	PVC	Grade	D.O. N	Meter (if	req'd):		YSI HACH
DTW with 80% Recharge [(Height of Wate				Colum	n x 0.20)) + DTW]:	_
Purge Method:	Bailer Disposable B Positive Air I Electric Subn	Displaceme	ent Extrac Other	Waterry Peristation tion Pump	Well Diamete		Other:	Disposable Bailer Extraction Port Dedicated Tubing
((1 Case Volume	Gals.) XSpeci	fied Volun		_ Gals. olume	1" 2" 3"	0.04 0.16 0.37	4" 6" Other	0.65 1.47 radius ² * 0.163
Time	Temp (°F or °C)	рН	Cond. (mS or μS)	1	bidity TUs)	Gals. Re	moved	Observations
	INSUFF	FICIER	OT H20	/ no	5m	mp/e	2	
·								
***			•					
with the control of t								
Did well de	water?	Yes	/No	Gallons actually evacuated:				
Sampling D	ate:		Sampling Time	e:		Depth to	Water	:
Sample I.D.	.:			Laboya	itory:	Kiff Ca	IScience	Other
Analyzed fo	or: тры-G	BTEX	MTBE TPH-D	Oxygen	ates (5)	Other:		-
EB I.D. (if	applicable)	:	@ Time	Duplic	ate I.D. ((if applic	able):	
Analyzed fo	от: трн-G	BTEX	MTBE TPH-D	Oxygen	ates (5)	Other:	/	
D.O. (if req	'd): Pr	e-purge:		mg/L	P	ost-purge:		mg/ ₁ .
O.R.P. (if re	eg'd): Pr	e-purge:		mV	р	ost-purge:		mV

WLLL MONITORING DATA SHEL.

Project #:	08000	·7-/	BD	Client: STELLAR Date: 6/17/08				
Sampler:	BD			Date:	6	117	108	
Well I.D.:	MW-	8		Well Diameter: 2 3 4 6 8				
Total Well		. \	7.90	Depth to Water (DTW): 19.90				
Depth to Free Product:						ree Prod		
Referenced	to:	PVD	Grade		Aeter (if			YSI HACH
DTW with	80% Rech	arge [(H	leight of Water	Colum	n x 0.20)) + DTW]:	
Purge Method: Bailer Disposable Bailer				Waterra Peristattic ction Pump			Other:	Bailer Disposable Bailer Extraction Port Dedicated Tubing
1 Case Volume	Gals.) X Speci	fied Volun	e Calculated Vo	_ Gals. olume	1" 2" 3"	0.04 0.16 0.37	4" 6" Other	0.65 1.47 radius ² * 0.163
Time	Temp (°F or °C)	рН	Cond. (mS or μS)		oidity ΓUs)	Gals. Re	moved	Observations
	INSUFF	-/c/er	T H20	/ un	able	fo	Sum	sle
Did well de	water?	Yes	No	Gallon	s actuall	y, evacua	ted:	
Sampling D			Sampling Time			Depth to		/
Sample I.D.	•			Labora	tory:		IScience	Other
Analyzed fo	or: TPH-G	втех	MTBE TPH-D	Oxygen	ates (5)	Other:		
EB I.D. (if a	applicable)		@ Time	Duplic	ate I.D.	if applic	able):	
Analyzed fo	or: 7РН-G	ВТЕХ	MTBE TPH-D	Oxygen		Other:		
D.O. (if req	'd): Pr	e-purge:		mg/ _L	Р	ost-purge:		nig/ _{L.}
O.R.P. (if re	eq'd): Pr	e-purge:		mV	Р	ost/purge:		mV

APPENDIX B

Current Event Analytical Laboratory Report and Chain-of-Custody Record



Curtis & Tompkins, Ltd., Analytical Laboratories, Since 1878

2323 Fifth Street, Berkeley, CA 94710, Phone (510) 486-0900

Laboratory Job Number 204067 ANALYTICAL REPORT

Stellar Environmental Solutions

2198 6th Street

Berkeley, CA 94710

Project : 2003-43

Location : Oakland Auto Works

Level : II

Sample ID	<u>Lab ID</u>
MW-2	204067-001
MW-3	204067-002
MW-4	204067-003

This data package has been reviewed for technical correctness and completeness. Release of this data has been authorized by the Laboratory Manager or the Manager's designee, as verified by the following signatures. The results contained in this report meet all requirements of NELAC and pertain only to those samples which were submitted for analysis. This report may be reproduced only in its entirety.

Signature:

Project Manager

Date: <u>07/02/2008</u>

Date: <u>06/27/2008</u>

Signature:

Senior Program Manager

NELAP # 01107CA

Page 1 of ____



CASE NARRATIVE

Laboratory number: 204067

Client: Stellar Environmental Solutions

Project: 2003-43

Location: Oakland Auto Works

Request Date: 06/18/08 Samples Received: 06/18/08

This hardcopy data package contains sample and QC results for three water samples, requested for the above referenced project on 06/18/08. The samples were received cold and intact.

TPH-Purgeables and/or BTXE by GC (EPA 8015B):

No analytical problems were encountered.

TPH-Extractables by GC (EPA 8015B):

No analytical problems were encountered.

Volatile Organics by GC/MS (EPA 8260B):

No analytical problems were encountered.



Total Volatile Hydrocarbons Lab #: 204067 Location: Oakland Auto Works EPA 5030B Client: Stellar Environmental Solutions Prep: Project#: 2003-43 Analysis: EPA 8015B Batch#: 139419 Matrix: Water Sampled: 06/17/08 Units: ug/L Diln Fac: 1.000 Received: 06/18/08

Field ID: MW-2 Lab ID: 204067-001 Type: SAMPLE Analyzed: 06/19/08

 Analyte
 Result
 RL

 Gasoline C7-C12
 2,400
 50

Surrogate%RECLimitsTrifluorotoluene (FID)12769-140Bromofluorobenzene (FID)13173-144

Field ID: MW-3 Lab ID: 204067-002 Type: SAMPLE Analyzed: 06/19/08

 Analyte
 Result
 RL

 Gasoline C7-C12
 2,100
 50

Surrogate%RECLimitsTrifluorotoluene (FID)12869-140Bromofluorobenzene (FID)12373-144

Field ID: MW-4 Lab ID: 204067-003 Type: SAMPLE Analyzed: 06/19/08

Analyte Result RL
Gasoline C7-C12 190 Y 50

Surrogate%RECLimitsTrifluorotoluene (FID)9669-140Bromofluorobenzene (FID)10273-144

Type: BLANK Analyzed: 06/18/08

Lab ID: QC447133

 Analyte
 Result
 RL

 Gasoline C7-C12
 ND
 50

Surrogate %REC Limits
Trifluorotoluene (FID) 96 69-140
Bromofluorobenzene (FID) 100 73-144

Y= Sample exhibits chromatographic pattern which does not resemble standard

ND= Not Detected

RL= Reporting Limit

Page 1 of 1



Batch QC Report

	Total Volati	le Hydrocarbon	s
Lab #:	204067	Location:	Oakland Auto Works
Client:	Stellar Environmental Solutions	Prep:	EPA 5030B
Project#:	2003-43	Analysis:	EPA 8015B
Type:	LCS	Diln Fac:	1.000
Lab ID:	QC447134	Batch#:	139419
Matrix:	Water	Analyzed:	06/18/08
Units:	ug/L		

Analyte	Spiked	Result	%REC	Limits
Gasoline C7-C12	2,000	1,885	94	80-120

Surrogate	%REC	Limits
Trifluorotoluene (FID)	113	69-140
Bromofluorobenzene (FID)	102	73-144

Page 1 of 1 7.0



Batch QC Report

	Total Volati	le Hydrocarbons	3
Lab #: 204067	7	Location:	Oakland Auto Works
Client: Stella	ar Environmental Solutions	Prep:	EPA 5030B
Project#: 2003-4	13	Analysis:	EPA 8015B
Field ID:	MW-2	Batch#:	139419
MSS Lab ID:	204067-001	Sampled:	06/17/08
Matrix:	Water	Received:	06/18/08
Units:	ug/L	Analyzed:	06/19/08
Diln Fac:	1.000		

Type: MS

Lab ID: QC447137

Analyte	MSS Result	Spiked	Result	%REC	Limits
Gasoline C7-C12	2,416	2,000	4,134	86	67-120

Surrogate	%REC	Limits	
Trifluorotoluene (FID)	133	69-140	
Bromofluorobenzene (FID)	141	73-144	

Type: MSD Lab ID: QC447138

Analyte	Spiked	Result	%REC	Limits	RPD L
Gasoline C7-C12	2,000	4,173	88	67-120	1 2

Surrogate	%REC	Limits
Trifluorotoluene (FID)	127	69-140
Bromofluorobenzene (FID)	143	73-144



Total Extractable Hydrocarbons Lab #: 204067 Location: Oakland Auto Works Client: Stellar Environmental Solutions Prep: EPA 3520C Project#: 2003-43 EPA 8015B Analysis: Matrix: Water Sampled: 06/17/08 Units: Received: ug/L 06/18/08 Diln Fac: 1.000 Prepared: 06/23/08 Batch#: 139573 Analyzed: 06/25/08

Field ID: MW-2 Lab ID: 204067-001

Type: SAMPLE

Analyte	Result	RL	
Diesel C10-C24	4,300	50	

Surrogate	%REC	Limits
Hexacosane	110	63-130

Field ID: MW-3 Lab ID: 204067-002

Type: SAMPLE

Analyte	Result	RL	
Diesel C10-C24	1,200	50	

Surrogate	%REC	Limits
Hexacosane	110	63-130

Type: BLANK Lab ID: QC447763

Analyte	Result	RL	
Diesel C10-C24	ND	50	

Surrogate	%REC	Limits
Hexacosane	67	63-130

ND= Not Detected RL= Reporting Limit

Page 1 of 1 10.0



Batch QC Report

Total Extractable Hydrocarbons						
Lab #:	204067	Location:	Oakland Auto Works			
Client:	Stellar Environmental Solutions	Prep:	EPA 3520C			
Project#:	2003-43	Analysis:	EPA 8015B			
Matrix:	Water	Batch#:	139573			
Units:	ug/L	Prepared:	06/23/08			
Diln Fac:	1.000	Analyzed:	06/25/08			

Type: BS Cleanup Method: EPA 3630C

Lab ID: QC447764


Analyte	Spiked	Result	%REC	Limits
Diesel C10-C24	2,500	2,476	99	61-120

Surrogate	%REC	Limits
Hexacosane	97	63-130


Type: BSD Cleanup Method: EPA 3630C

Lab ID: QC447765


Analyte	Spiked	Result	%REC	Limits	RPD	Lim
Diesel C10-C24	2,500	2,526	101	61-120	2	29



\\Lims\gdrive\ezchrom\Projects\GC26\Data\177a013, A



\\Lims\gdrive\ezchrom\Projects\GC26\Data\177a014, A



\Lims\gdrive\ezchrom\Projects\GC15B\Data\176b033, B



	BTXE &	Oxygenates	
Lab #:	204067	Location:	Oakland Auto Works
Client:	Stellar Environmental Solutions	Prep:	EPA 5030B
Project#:	2003-43	Analysis:	EPA 8260B
Field ID:	MW-2	Batch#:	139438
Lab ID:	204067-001	Sampled:	06/17/08
Matrix:	Water	Received:	06/18/08
Units:	ug/L	Analyzed:	06/19/08
Diln Fac:	1.000		

Analyte	Result	RL	
tert-Butyl Alcohol (TBA)	71	10	
MTBE	73	0.5	
Isopropyl Ether (DIPE)	11	0.5	
Ethyl tert-Butyl Ether (ETBE)	ND	0.5	
1,2-Dichloroethane	1.9	0.5	
Benzene	3.9	0.5	
Methyl tert-Amyl Ether (TAME)	ND	0.5	
Toluene	2.2	0.5	
1,2-Dibromoethane	ND	0.5	
Ethylbenzene	3.0	0.5	
m,p-Xylenes	7.3	0.5	
o-Xylene	2.1	0.5	

Surrogate	%REC	Limits
Dibromofluoromethane	107	80-123
1,2-Dichloroethane-d4	124	76-138
Toluene-d8	108	80-120
Bromofluorobenzene	92	80-120

Page 1 of 1 2.0



	BTXE &	Oxygenates	
Lab #:	204067	Location:	Oakland Auto Works
Client:	Stellar Environmental Solutions	Prep:	EPA 5030B
Project#:	2003-43	Analysis:	EPA 8260B
Field ID:	MW-3	Batch#:	139438
Lab ID:	204067-002	Sampled:	06/17/08
Matrix:	Water	Received:	06/18/08
Units:	ug/L	Analyzed:	06/19/08
Diln Fac:	1.000		

Analyte	Result	RL
tert-Butyl Alcohol (TBA)	22	10
MTBE	86	0.5
Isopropyl Ether (DIPE)	3.2	0.5
Ethyl tert-Butyl Ether (ETBE)	ND	0.5
1,2-Dichloroethane	1.1	0.5
Benzene	7.9	0.5
Methyl tert-Amyl Ether (TAME)	ND	0.5
Toluene	ND	0.5
1,2-Dibromoethane	ND	0.5
Ethylbenzene	ND	0.5
m,p-Xylenes	0.8	0.5
o-Xylene	ND	0.5

Surrogate	%REC	Limits
Dibromofluoromethane	102	80-123
1,2-Dichloroethane-d4	113	76-138
Toluene-d8	102	80-120
Bromofluorobenzene	91	80-120

Page 1 of 1 3.0



Batch QC Report

	BTXE	& Oxygenates	
Lab #: Client: Project#:	204067 Stellar Environmental Solutions 2003-43	Location: Prep: Analysis:	Oakland Auto Works EPA 5030B EPA 8260B
Matrix: Units: Diln Fac:	Water ug/L 1.000	Batch#: Analyzed:	139438 06/19/08

Type: BS Lab ID: QC447214

Analyte	Spiked	Result	%REC	Limits
tert-Butyl Alcohol (TBA)	125.0	125.5	100	55-158
MTBE	25.00	23.66	95	60-136
Isopropyl Ether (DIPE)	25.00	26.57	106	63-122
Ethyl tert-Butyl Ether (ETBE)	25.00	26.06	104	62-133
1,2-Dichloroethane	25.00	25.14	101	77-125
Benzene	25.00	24.58	98	80-120
Methyl tert-Amyl Ether (TAME)	25.00	28.44	114	69-137
Toluene	25.00	30.14	121	80-121
1,2-Dibromoethane	25.00	26.36	105	80-120
Ethylbenzene	25.00	28.99	116	80-124
m,p-Xylenes	50.00	60.35	121	80-128
o-Xylene	25.00	29.56	118	80-123

Surrogate	%REC	Limits	
Dibromofluoromethane	110	80-123	
1,2-Dichloroethane-d4	110	76-138	
Toluene-d8	110	80-120	
Bromofluorobenzene	84	80-120	

Type: BSD Lab ID: QC447215

Analyte	Spiked	Result	%REC	Limits	RPD	Lim
tert-Butyl Alcohol (TBA)	125.0	119.6	96	55-158	5	20
MTBE	25.00	23.57	94	60-136	0	20
Isopropyl Ether (DIPE)	25.00	26.41	106	63-122	1	20
Ethyl tert-Butyl Ether (ETBE)	25.00	25.46	102	62-133	2	20
1,2-Dichloroethane	25.00	23.92	96	77-125	5	20
Benzene	25.00	23.18	93	80-120	6	20
Methyl tert-Amyl Ether (TAME)	25.00	28.21	113	69-137	1	20
Toluene	25.00	27.78	111	80-121	8	20
1,2-Dibromoethane	25.00	23.94	96	80-120	10	20
Ethylbenzene	25.00	27.44	110	80-124	5	20
m,p-Xylenes	50.00	56.10	112	80-128	7	20
o-Xylene	25.00	28.14	113	80-123	5	20

Surrogate	%REC	Limits	
Dibromofluoromethane	110	80-123	
1,2-Dichloroethane-d4	110	76-138	
Toluene-d8	108	80-120	
Bromofluorobenzene	85	80-120	



Batch QC Report

BTXE & Oxygenates									
Lab #:	204067	Location:	Oakland Auto Works						
Client:	Stellar Environmental Solutions	Prep:	EPA 5030B						
Project#:	2003-43	Analysis:	EPA 8260B						
Type:	BLANK	Diln Fac:	1.000						
Lab ID:	QC447216	Batch#:	139438						
Matrix:	Water	Analyzed:	06/19/08						
Units:	ug/L								

Analyte	Result	RL	
tert-Butyl Alcohol (TBA)	ND	10	
MTBE	ND	0.5	
Isopropyl Ether (DIPE)	ND	0.5	
Ethyl tert-Butyl Ether (ETBE)	ND	0.5	
1,2-Dichloroethane	ND	0.5	
Benzene	ND	0.5	
Methyl tert-Amyl Ether (TAME)	ND	0.5	
Toluene	ND	0.5	
1,2-Dibromoethane	ND	0.5	
Ethylbenzene	ND	0.5	
m,p-Xylenes	ND	0.5	
o-Xylene	ND	0.5	

Surrogate	%REC	Limits
Dibromofluoromethane	95	80-123
1,2-Dichloroethane-d4	99	76-138
Toluene-d8	105	80-120
Bromofluorobenzene	100	80-120

Page 1 of 1 4.0

		204C	06			Chain of	f Cus	stody R	ec	ord					,	ζ	٠ ٢	þ			Lab joł	o no. QS	0617	BD/
Laboratory Address	Curtis and To 2323 Fifth St Berkeley, Ca	reet				ethod of Shipment Ha	and Deli		_		,	·		ていた	\ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \	~ SP	\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\	_	<u></u>		Date _ Page	<u>\(\begin{align*} / / \\ 1 \\ \\ \\ \\ \\ \\ \\ \\ \\ \\ \\ \</u>	7/0 of 1	8 - -
	510-486-090	0			Ai	rbill No.		W+	_				Ľ	7		Д	Analysis	Requ	uired			/		
Project Ow Site Addres	isi	Poy-Wing lacArthur Blv California	d.		Pr	ooler NoBruc oject ManagerBruc elephone No(510) 644-	e Ruck 3123	er			Pala	Somainers				/ ا		/	/	/				
Project Nar Project Nur	me Oakland mber 2003-	Auto Works 43			Fa	ax No. (510) 644- amplers: (Signature)	3859	2	– – /	//	/ şi	\\$\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\	Q'H'A	(A)					/	//	//	Ren	narks	
<u> </u>	Sample Number	Location/ Depth	Date	Time	Sample Type	Type/Size of Container	Cooler	Chemical	\bigvee	\angle	1	Y F	V/A	7 6	14		//		/ 					.
Mh	/-Z		717/09	1159	w	2NP IL AMBER	yes	NP	7	5	 	X	X	X	X	_		_	_					
M	1-4		1	1228		ZNPIL AMBEI	yes	NP	N	5	×	×	×	X	X			_						_
Mu	7-4		+	1110	W	3 40ml VOAS	yes yes	HCL	Ŋ	3	X						+	-						
							yes																	
							yes																	
							yes																	
																		+					·	
										-	_					_	-				, , , , , , , , , , , , , , , , , , ,			-
Relinquished Signature Printed	by Blokie		Date Ynla Time	Receive Signa Printe	ture	5. Doshie-	Date ///	Printed	ete	-Con		<u>1</u>		- - 	Date	Si	gnature	- / i	AQU 2	m(Rent	<u> </u>	Date - 18/0	28
	Time: 5 Day TA			Comp	any	<i>/</i> 3/	1645	Company Relinquished Signature	by:	<u> </u>					3 5 5 Date	Rece	ompany eived by ignature	<i>/</i> :	<u>₹</u>				Date	\dashv
Comments:								Printed		<u> </u>				-	Time	Pr	rinted _	-					- Time	e
l ——								Company						_		C	ompanı	<i>.</i>					_ 1	

COOLER RECEIPT CHECKLIST



Login #	204067	Date Received	10-18-08	Number of cooler:	s 2	
Client _	SES	Date Received	roject Oakland	Auto Works		
				. (1)		
Date Op	ened 6-18-08	By (print) F Nicho	(sign)	Suit - t		
Date Lo	gged in <u>V</u>	By (print) F Nicho By (print) V	(sign)_			
1. Did co		shipping slip (airbill, o	etc)?		. YES (NO
2A. Wer	e custody seals p	resent? TYES ((circle) on coole	er on samples) £ĵ	NO
2D W	low many	Name		Date		
		tact upon arrival?			NO.	NA
3. Were	custody papers di	ry and intact when rece	ived?		YES	NO
4. Were	custody papers fi	lled out properly (ink,	signed, etc)?		YES	NO
6. Indica	project identifiat	ole from custody papers cooler: (if other, descr	s? (If so till out to _l ribe)	p of torm)	YES.	NO
		☐ Foam blocks		☐ None		
Г	Cloth material	☐ Cardboard	□ Styrofoam	☐ Paner toy	wels	
7. If requ	iired, was sufficie	☐ Cardboard ent ice used? Samples	should be $< or = 6$	°CÆS) NO	N/A
Ţ	ype of ice used:	Wet □ Blue	□None	Temp(°C)		
7	Samples Receive	yed on ice & cold with	out a temperature l	blank		
		ed on ice directly from				_
8. Were	Method 5035 sar	npling containers prese	ent?		YES	(NO)
11	YES, what time	were they transferred t	to freezer?			
9. Did al	bottles arrive un	broken/unopened?		· - · - · · · · · · · · · · · · · · · ·	YES	NO
		propriate containers fo				NO
		sent, in good condition gree with custody paper				NO
12. Do u 13. Was	sufficient amount	t of sample sent for test	ts requested?)	(LE2)	NO
14 Are t	he samnles annro	priately preserved?	is requested:	VE	1 63	NO N/A
		osent in VOA samples?				N/A
		ed concerning this sam				NO
11	YES, Who was	called?	By	Date:	. 1 20	110
						•
COMME	ENTS					
				•		

SOP Volume:

Client Services

Section: Page:

1.1.2

Rev. 5 Number 1 of 3 Effective: 19 May 2008

1 of 1C:\Documents and Settings\carol\Local Settings\Temporary Internet Files\Content.IE5\Q6BXTRDB\Coole

APPENDIX C

Historical Groundwater Monitoring Well Analytical Data

 $Table \ C-1$ Historical Groundwater Monitoring Well Groundwater Analytical Results Petroleum and Aromatic Hydrocarbons (µg/L) 240 W. MacArthur Boulevard, Oakland, Alameda, California

Well Purged?	Sampling Event No.	Date Sampled	TVH-g	TEH-d	Benzene	Toluene	Ethylbenzene	Total Xylenes	MTBE
				M	W-1			Ţ.	
Yes	1	Aug-97	1,140	< 1,000	110	16	15	112	NA
Yes	2	Dec-97	ND	NA	ND	ND	ND	31	NA
Yes	3	Mar-98	370	NA	8.9	< 0.5	< 0.5	2.2	18
Yes	4	Jul-98	6,400	NA	1,300	23	3.7	58	97
Yes	5	Oct-98	2,500	NA	360	44	1.3	150	< 0.5
Yes	6	Jan-99	2,700	NA	1,200	28	140	78	130
(a)	7	Jun-00	27,000	NA	5,200	500	320	3,100	1,300
(a)	8	Dec-00	976,000	NA	2,490	1,420	3,640	10,100	< 150
(a)	9	Feb-01	NA	NA	NA	NA	NA	NA	NA
(a)	10	May-01	20,000	NA	2,900	310	230	1,900	< 30
(a)	11	Jul-01	92,000	NA	2,900	580	2,800	20,000	560
Pre"hi-vac"	12	Oct 22-01	20,000	NA	3,700	560	410	4,600	2,600
Post "hi-vac"	12	Oct 26-01	< 0.05	NA	< 0.5	< 0.5	< 0.5	< 0.5	< 0.5
(a)	13	Dec-01	3,300	NA	200	12	5.7	43	44
No	14	Mar-02	4,600	NA	820	4.4	100	300	210
No	15	May-02	1,600	NA	100	23	20	190	7.7
No	16	Jul-02	2,300	NA	250	15	13	180	180
No	17	Oct-02	1,820	NA	222	16	< 0.3	59	58
No	18	Jan-03	2,880	NA	188	< 50	< 50	157	20
No	19	Mar-03	6,700	NA	607	64	64	288	< 0.18
No	20	Aug-03	4,900	5,000	740	45	85	250	14
Yes	21	Dec-03	8,930	800	1,030	55	127	253	212
Yes	22	Mar-04	11,300	1,100	483	97	122	452	67
Yes	23	Jun-04	9,300	4,000	1,700	75	92	350	6.0
Yes	24	Sep-04	9,100	97	920	19	82	201	7.2
Yes	25	Dec-04	11,000	3,300	830	21	74	118	7.9
Yes	26	Mar-05	4,700	3,500	450	28	42	97	6.7
Yes	27	Jun-05	21,000	6,800	1,900	270	320	2,800	< 13
Yes	28	Sep-05	23,000	2,500	2,100	100	200	880	< 2.5
Yes	29	Dec-05	4,300	3,000	500	22	72	228	5.5
Yes	30	Mar-06	11,000	3,000	340	45	89	630	4.3
Yes	31	Jun-06	21,000	8,500	1,600	160	170	1,000	< 2.5
Yes	32	Sep-06	13,000	6,200	1,700	76	110	440	< 13
Yes	33	Dec-06	16,000	4,100	1,500	100	160	670	< 13
Yes	34	Mar-07	22,000	6,200	1,700	140	180	1,100	< 13
Yes	35	Jun-07	3,600	1,500	210	10	19	61	3.2
Yes	36	Sep-07	1,400	1,700	50	< 0.5	1.3	< 0.5	4.1
Yes	37	Dec-07	2,700	840	170	5.5	7.5	34.6	3.1
Yes	38	Mar-08	2,300	1,000	77	<2.5	8.2	10	<2.5
Yes	39	Jun-08	NS		NS	NS	NS	NS	NS

(table continued on next page; footnotes on final page)

Well Purged?	Sampling Event No.	Date Sampled	TVH-g	TEH-d	Benzene	Toluene	Ethylbenzene	Total Xylenes	MTBE
		<u> </u>	<u>l</u>	M	W-2	<u> </u>	•	•	
Yes	1	Aug-97	5,350	< 1,000	108	36	33	144	NA
Yes	2	Dec-97	1,600	NA	73	ND	ND	ND	NA
Yes	3	Mar-98	3,400	NA	830	100	210	240	870
Yes	4	Jul-98	3,100	NA	25	2.2	< 0.5	0.9	1,900
Yes	5	Oct-98	4,300	NA	< 0.5	1.2	< 0.5	1	4,200
Yes	6	Jan-99	2,900	NA	160	8.9	6.9	78.4	2,100
(a)	7	Jun-00	2,700	NA	200	17	30	16	680
(a)	8	Dec-00	3,020	NA	56.7	< 1.5	< 1.5	< 3.0	3,040
(a)	9	Feb-01	NA	NA	NA	NA	NA	NA	NA
(a)	10	May-01	720	NA	49	< 3.0	4.6	< 3.0	380
(a)	11	Jul-01	8,400	NA	350	44	77	78	550
Pre"hi-vac"	12	Oct 22-01	850	NA	170	4.9	5.1	14	260
Post "hi-vac"	12	Oct 26-01	770	NA	86	5.5	9.6	8.5	310
(a)	13	Dec-01	1,300	NA	9.2	< 2.0	< 2.0	< 2.0	370
No	14	Mar-02	1,300	NA	76	3.8	21	15	460
No	15	May-02	320	NA	12	1.1	4.6	4.8	160
No	16	Jul-02	1,300	NA	130	1	9.4	5.6	420
No	17	Oct-02	1,060	NA	12	2.2	4.2	3.5	270
No	18	Jan-03	581	NA	6.5	< 5.0	< 5.0	< 5.0	130
No	19	Mar-03	1,250	NA	< 0.22	< 0.32	< 0.31	< 0.4	155
No	20	Aug-03	2,200	730	58	9.2	< 0.5	28	240
Yes	21	Dec-03	1,980	100	29	22.0	7.4	13	295
Yes	22	Mar-04	2,700	100	12	16.0	9	12	249
Yes	23	Jun-04	1,200	370	42	0.7	2.6	0.9	170
Yes	24	Sep-04	1,500	280	14	< 0.5	< 0.5	0.6	130
Yes	25	Dec-04	1,400	540	26	1.1	1.8	3.5	91
Yes	26	Mar-05	2,300	420	5.3	< 1.0	3.7	< 2.0	120
Yes	27	Jun-05	1,600	500	14	< 0.5	1.8	0.68	66
Yes	28	Sep-05	1,400	210	30	1.3	12	26	58
Yes	29	Dec-05	1,300	800	4.9	0.6	0.7	0.8	74
Yes	30	Mar-06	1,300	400	3.2	< 0.7	< 0.7	< 1.4	120
Yes	31	Jun-06	1,400	1,200	33.0	1.3	3.5	<1.6	84
Yes	32	Sep-06	8,300	1,600	67.0	4.1	4.6	15.4	64
Yes	33	Dec-06	1,500	940	22.0	2.9	2.6	3.5	67
Yes	34	Mar-07	1,200	760	65	1.9	3.7	1.6	59
Yes	35	Jun-07	2,900	1,000	67	3.2	14.0	7.5	49
Yes	36	Sep-07	NS	NS	NS	NS	NS	NS	NS
Yes	37	Dec-07	1,200	510	14	< 0.5	< 0.5	0.5	33
Yes	38	Mar-08	1,100	3,800	13	0.9	0.9	2.3	61
Yes	39	Jun-08	2,400	4,300	3.9	2.2	3.0	9.4	73

Well Purged?	Sampling Event No.	Date Sampled	TVH-g	TEH-d	Benzene	Toluene	Ethylbenzene	Total Xylenes	MTBE
				M	W-3	•	•		
Yes	1	Aug-97	8,500	< 1,000	450	30	53	106	NA
Yes	2	Dec-97	5,200	NA	180	6	5	9.3	NA
Yes	3	Mar-98	1,000	NA	6	< 0.5	< 0.5	< 0.5	810
Yes	4	Jul-98	6,400	NA	490	57	23	78	220
Yes	5	Oct-98	2,100	NA	< 5.0	< 5.0	< 5.0	< 5.0	2,100
Yes	6	Jan-99	4,400	NA	450	65	26	42	1,300
(a)	7	Jun-00	1,700	NA	110	13	34	13	96
(a)	8	Dec-00	5,450	NA	445	< 7.5	23.8	< 7.5	603
(a)	9	Feb-01	NA	NA	NA	NA	NA	NA	NA
(a)	10	May-01	1,900	NA	180	12	< 3.0	19	330
(a)	11	Jul-01	10,000	NA	830	160	150	260	560
Pre"hi-vac"	12	Oct 22-01	1,400	NA	240	7.8	4.1	15	220
Post "hi-vac"	12	Oct 26-01	1,900	NA	200	16	51	30	290
(a)	13	Dec-01	5,800	NA	93	< 20	31	< 20	330
No	14	Mar-02	1,900	NA	220	16	31	24	400
No	15	May-02	1,600	NA	110	3.4	29	14	320
No	16	Jul-02	1,900	NA	210	27	30	55	200
No	17	Oct. 2002	3,030	NA	178	19	6.2	36	178
No	17 Oct. 2002 18 Jan-03		2,980	NA	47	< 5.0	7.6	6.3	105
No	19	Mar-03	3,620	NA	124	< 0.32	22	12	139
No	20	Aug-03	3,800	2,400	170 28		31	31	170
Yes	21	Dec-03	6,860	500	312	20	55	58	309
Yes	22	Mar-04	5,490	500	82	34	46	49	249
Yes	23	Jun-04	5,400	1,100	150	30	45	66	130
Yes	24	Sep-04	5,400	1,500	70	3.2	16	13	110
Yes	25	Dec-04	5,300	2,400	91	7.4	21	19	92
Yes	26	Mar-05	4,700	2,000	19	1.1	10	3.7	76
Yes	27	Jun-05	4,200	1,800	49	4.5	23	16	66
Yes	28	Sep-05	5,000	950	60	3.1	12	26	59
Yes	29	Dec-05	3,200	1,800	29	1.3	6.6	5.6	80
Yes	30	Mar-06	4,100	1,200	24	1.1	8.5	3.4	99
Yes	31	Jun-06	4,000	1,400	89.0	8.4	14.0	16.7	75
Yes	32	Sep-06	6,100	2,600	190	15.0	24.0	59.0	51
Yes	33	Dec-06	4,500	2,000	110	4.0	7.3	19.1	47
Yes	34	Mar-07	3,800	2,400	90	3.7	9.8	11.1	51
Yes	35	Jun-07	4,500	2,100	8.9	1.4	14.0	4.0	77
Yes	36	Sep-07	4,000	NA	4.6	< 0.5	1.3	< 0.5	75
Yes	37	Dec-07	1,400	2,600	11.0	0.8	0.7	3.9	84
Yes	38	Mar-08	1,700	9,600	19.0	< 0.5	< 0.5	0.6	100
Yes	39	Jun-08	2,100	1,200	7.9	< 0.5	< 0.5	0.8	86

Well Purged?	Sampling Event No.	Date Sampled	TVH-g	TEH-d	Benzene	Toluene	Ethylbenzene	Total Xylenes	MTBE
				M	W-4	•		•	
Yes	1	Aug-97	< 500	< 1,000	< 0.5	< 0.5	< 0.5	< 1.5	NA
Yes	2	Dec-97	ND	NA	ND	ND	ND	ND	NA
Yes	3	Mar-98	< 50	NA	< 0.5	< 0.5	< 0.5	< 0.5	< 0.5
Yes	4	Jul-98	< 50	NA	< 0.5	< 0.5	< 0.5	< 0.5	< 0.5
Yes	5	Oct-98	< 50	NA	< 0.5	< 0.5	< 0.5	< 0.5	< 0.5
Yes	6	Jan-99	< 50	NA	< 0.5	< 0.5	< 0.5	< 0.5	< 0.5
(a)	7	Jun-00	< 50	NA	< 0.5	< 0.5	< 0.5	< 0.5	< 0.5
(a)	8	Dec-00	< 500	NA	< 0.3	< 0.3	< 0.6	< 0.3	< 0.3
(a)	9	Feb-01	NA	NA	NA	NA	NA	NA	NA
(a)	10	May-01	< 50	NA	1.2	< 0.3	0.55	1.2	2.9
(a)	11	Jul-01	< 5.0	NA	< 0.5	< 0.5	< 0.5	< 0.5	< 0.5
Pre"hi-vac"	12	Oct 22-01	< 5.0	NA	< 0.5	< 0.5	< 0.5	< 0.5	< 0.5
Post "hi-vac"	12	Oct 26-01	< 5.0	NA	< 0.5	< 0.5	< 0.5	< 0.5	< 0.5
(a)	13	Dec-01	ND	NA	ND	ND	ND	ND	ND
No	14	Mar-02	< 50	NA	< 1	< 1	< 1	< 1	< 1
No	15	May-02	< 50	NA	< 0.5	< 0.5	< 0.5	< 0.5	< 0.5
No	16	Jul-02	< 50	NA	< 0.5	< 0.5	< 0.5	< 0.5	< 0.5
No	17	Oct-02	< 100	NA	< 0.3	< 0.3	< 0.3	< 0.6	< 0.3
No	18	Jan-03	< 100	NA	< 0.3	< 0.3	< 0.3	< 0.6	14
No	19	Mar-03	< 15	NA	< 0.4	< 0.02	< 0.02	< 0.06	5.2
No	20	Aug-03	< 50	NA	< 0.5	< 0.5	< 0.5	< 0.5	< 0.5
Yes	21	Dec-03	63	NA	< 0.3	< 0.3	< 0.3	< 0.6	< 5.0
Yes	22	Mar-04	< 50	NA	< 0.3	< 0.3	< 0.3	< 0.6	< 5.0
Yes	23	Jun-04	< 50	NA	< 0.5	< 0.5	< 0.5	< 0.5	0.9
Yes	24	Sep-04	< 50	NA	< 0.5	< 0.5	< 0.5	< 0.5	2.3
Yes	25	Dec-04	< 50	NA	NA	NA	NA	NA	NA
Yes	26	Mar-05	< 50	NA	NA	NA	NA	NA	NA
Yes	27	Jun-05	< 50	NA	NA	NA	NA	NA	NA
Yes	28	Sep-05	< 50	NA	NA	NA	NA	NA	NA
Yes	29	Dec-05	< 50	NA	NA	NA	NA	NA	NA
Yes	30	Mar-06	< 50	NA	NA	NA	NA	NA	NA
Yes	31	Jun-06	< 50	NA	NA	NA	NA	NA	NA
Yes	32	Sep-06	< 50	NA	NA	NA	NA	NA	NA
Yes	33	Dec-06	59	NA	NA	NA	NA	NA	NA
Yes	34	Mar-07	< 50	NA	NA	NA	NA	NA	NA
Yes	35	Jun-07	57	NA	NA	NA	NA	NA	NA
Yes	36	Sep-07	70	NA	NA	NA	NA	NA	NA
Yes	37	Dec-07	90	NA	NA	NA	NA	NA	NA
Yes	38	Mar-08	120	NA	NA	NA	NA	NA	NA
Yes	39	Jun-08	190	NA	NA	NA	NA	NA	NA

Well Purged?	Sampling Event No.	Date Sampled	TVH-g	TEH-d	Benzene	Toluene	Ethylbenzene	Total Xylenes	MTBE
_				M	W-5				
(a)	9	Feb-01	5,660	NA	76.9	21.1	47.3	312	< 0.3
(a)	10	May-01	22,000	NA	2,600	480	220	2,700	< 30
(a)	11	Jul-01	72,000	NA	3,500	1,100	4,300	22,000	2,500
Pre"hi-vac"	12	Oct 22-01	26,000	NA	2,800	980	6,000	950	2,300
Post "hi-vac"	12	Oct 26-01	17,000	NA	1,200	470	2,900	440	900
(a)	13	Dec-01	2,000	NA	620	190	110	910	< 20
No	14	Mar-02	8,800	NA	1,200	72	7.4	350	1,200
No	15	May-02	2,000	NA	150	38	21	260	13
No	16	Jul-02	4,200	NA	480	68	29	280	450
No	17	Oct-02	5,370	NA	236	45	23	39	135
No	18	Jan-03	8,270	NA	615	156	174	1,010	< 10
No	19	Mar-03	12,400	NA	824	195	213	1,070	< 0.18
No	20	Aug-03	18,000	10,000	950	290	330	1,820	< 2.0
Yes	21	Dec-03	11,900	800	627	263	288	1,230	595
Yes	22	Mar-04	20,700	850	867	266	305	678	145
Yes	23	Jun-04	12,000	1,700	920	240	260	1,150	< 3.1
Yes	24	Sep-04	13,000	1,900	580	240	260	1,260	< 4.2
Yes	25	Dec-04	16,000	3,300	730	200	250	1,100	< 4.2
Yes	26	Mar-05	6,300	4,600	190	28	42	280	< 1.7
Yes	27	Jun-05	16,000	4,100	1,100	260	380	1,590	< 7.1
Yes	28	Sep-05	15,000	3,600	810	210	300	1,300	< 1.3
Yes	29	Dec-05	9,600	3,600	270	80	110	710	< 1.7
Yes	30	Mar-06	9,800	5,100	240	47	97	590	< 2.0
Yes	31	Jun-06	28,000	4,900	920.0	250.0	350.0	1,480	< 2.0
Yes	32	Sep-06	12,000	2,400	580	170	230	980	< 3.6
Yes	33	Dec-06	15,000	3,400	510	160	260	1,190	< 3.6
Yes	34	Mar-07	20,000	4,600	910	230	360	1,560	< 3.6
No	35	Jun-07	NS	NS	NS	NS	NS	NS	NS
No	36	Sep-07	NS	NS	NS	NS	NS	NS	NS
No	37	Dec-07	NS	NS	NS	NS	NS	NS	NS
Yes	38	Mar-08	NS	NS	NS	NS	NS	NS	NS
Yes	39	Jun-08	NS	NS	NS	NS	NS	NS	NS

Well Purged?	Sampling Event No.	Date Sampled	TVH-g	TEH-d	Benzene	Toluene	Ethylbenzene	Total Xylenes	MTBE
	•		•	M	W-6				
(a)	9	Feb-01	1,340	NA	17	0.967	11.1	51.4	< 0.3
(a)	10	May-01	610	NA	15	0.97	< 0.5	46	< 0.5
(a)	11	Jul-01	2,500	NA	130	4.7	53	170	120
Pre"hi-vac"	12	Oct 22-01	280	NA	18	1.2	6.2	4.7	6
Post "hi-vac"	12	Oct 26-01	3,600	NA	210	20	170	62	120
(a)	13	Dec-01	5,300	NA	69	5.6	14	17	< 2.0
No	14	Mar-02	71	NA	54	4.2	27	17	8.5
No	15	May-02	150	NA	9.3	< 0.5	< 0.5	< 0.5	1.5
No	16	Jul-02	2,200	NA	98	32	46	150	66
No	17	Oct-02	786	NA	48	5.0	2.2	44	16
No	18	Jan-03	497	NA	6.8	< 5.0	< 5.0	11	< 1.0
No	19	Mar-03	258	NA	5.4	< 0.32	3.3	< 1.1	< 0.18
No	20	Aug-03	1,600	2,800	37	4	23	58	< 0.5
Yes	21	Dec-03	365	200	2.5	3.8	1.4	6.1	< 5.0
Yes	22	Mar-04	215	140	4.0	1.2	1.4	1.4	3.7
Yes	23	Jun-04	710	830	14.0	0.7	5.2	6.6	< 0.5
Yes	24	Sep-04	350	600	< 0.5	2.4	< 0.5	< 0.5	< 0.5
Yes	25	Dec-04	280	1,100	4.9	< 0.5	1.4	4.4	< 0.5
Yes	26	Mar-05	300	980	5.4	< 0.5	3.3	2.3	< 0.5
Yes	27	Jun-05	150	1,100	< 0.5	< 0.5	< 0.5	0.77	28
Yes	28	Sep-05	680	200	13	0.9	6.6	13	< 0.5
Yes	29	Dec-05	240	890	3.6	< 0.5	0.7	2.4	0.5
Yes	30	Mar-06	530	950	8.3	< 0.5	4.0	2.1	0.6
Yes	31	Jun-06	460	1,300	8.3	< 0.5	1.4	2.6	< 0.5
Yes	32	Sep-06	530	730	10.0	0.8	4.1	7.5	< 0.5
Yes	33	Dec-06	500	750	7.5	< 0.5	2.6	2.5	< 0.5
Yes	34	Mar-07	430	530	7.1	< 0.5	1.7	0.8	< 0.5
No	35	Jun-07	NS	NS	NS	NS	NS	NS	NS
No	36	Sep-07	NS	NS	NS	NS	NS	NS	NS
No	37	Dec-07	NS	NS	NS	NS	NS	NS	NS
Yes	38	Mar-08	NS	NS	NS	NS	NS	NS	NS
Yes	39	Jun-08	NS	NS	NS	NS	NS	NS	NS

Well Purged?	Sampling Event No.	Date Sampled	TVH-g	TEH-d	Benzene	Toluene	Ethylbenzene	Total Xylenes	MTBE
•		_	•	M	W-7				
(a)	9	Feb-01	ND	NA	ND	ND	ND	ND	ND
(a)	10	May-01	< 50	NA	0.75	0.77	0.48	2.4	1.1
(a)	11	Jul-01	< 5.0	NA	< 0.5	< 0.5	< 0.5	< 0.5	< 0.5
Pre"hi-vac"	12	Oct 22-01	< 5.0	NA	< 0.5	< 0.5	< 0.5	< 0.5	< 0.5
Post "hi-vac"	12	Oct 26-01	6,000	NA	170	550	110	120	970
(a)	13	Dec-01	< 50	NA	< 0.5	< 0.5	< 0.5	< 0.5	43
No	14	Mar-02	< 50	NA	< 1.0	< 1.0	< 1.0	< 1.0	< 1.0
No	15	May-02	< 50	NA	< 0.5	< 0.5	< 0.5	< 0.5	< 0.5
No	16	Jul-02	< 50	NA	< 0.5	< 0.5	< 0.5	< 0.5	< 0.5
No	17	Oct-02	< 100	NA	< 0.3	< 0.3	< 0.3	< 0.6	< 5.0
No	18	Jan-03	NA	NA	NA	NA	NA	NA	NA
No	19	Mar-03	< 15	NA	< 0.04	< 0.02	< 0.02	< 0.06	< 0.03
No	20	Aug-03	< 50	NA	< 0.5	< 0.5	< 0.5	< 0.5	< 0.5
Yes	21	Dec-03	< 50	NA	< 0.3	< 0.3	< 0.3	< 0.6	< 5.0
Yes	22	Mar-04	86	NA	< 0.3	< 0.3	< 0.3	< 0.6	57
Yes	23	Jun-04	< 50	NA	< 0.5	< 0.5	< 0.5	< 0.5	< 0.5
Yes	24	Sep-04	< 50	NA	< 0.5	< 0.5	< 0.5	< 0.5	< 0.5
Yes	25	Dec-04	< 50	NA	NA	NA	NA	NA	NA
Yes	26	Mar-05	< 50	NA	NA	NA	NA	NA	NA
Yes	27	Jun-05	< 50	NA	NA	NA	NA	NA	NA
Yes	28	Sep-05	< 50	NA	NA	NA	NA	NA	NA
Yes	29	Dec-05	< 50	NA	NA	NA	NA	NA	NA
Yes	30	Mar-06	< 50	NA	NA	NA	NA	NA	NA
Yes	31	Jun-06	< 50	NA	NA	NA	NA	NA	NA
Yes	32	Sep-06	< 50	NA	NA	NA	NA	NA	NA
Yes	33	Dec-06	< 50	NA	NA	NA	NA	NA	NA
Yes	34	Mar-07	< 50	NA	NA	NA	NA	NA	NA
No	35	Jun-07	NS	NA	NA	NA	NA	NA	NA
No	36	Sep-07	NS	NA	NA	NA	NA	NA	NA
No	37	Dec-07	NS	NA	NA	NA	NA	NA	NA
Yes	38	Mar-08	NS	NA	NA	NA	NA	NA	NA
Yes	39	Jun-08	NS	NS	NS	NS	NS	NS	NS

Well Purged?	Sampling Event No.	Date Sampled	TVH-g	TEH-d	Benzene	Toluene	Ethylbenzene	Total Xylenes	MTBE
•		_	•	M	W-8				
(a)	9	Feb-01	1,000	NA	3.97	< 0.3	3.78	1.63	620
(a)	10	May-01	< 50	NA	< 0.5	< 0.5	< 0.5	< 0.5	4.4
(a)	11	Jul-01	< 5.0	NA	< 0.5	< 0.5	< 0.5	< 0.5	< 0.5
Pre"hi-vac"	12	Oct 22-01	< 5.0	NA	< 0.5	< 0.5	< 0.5	< 0.5	< 0.5
Post "hi-vac"	12	Oct 26-01	< 5.0	NA	< 0.5	< 0.5	< 0.5	< 0.5	< 0.5
(a)	13	Dec-01	< 50	NA	< 0.5	< 0.5	< 0.5	< 0.5	< 0.5
No	14	Mar-02	< 50	NA	< 1.0	< 1.0	< 1.0	< 1.0	< 1.0
No	15	May-02	< 50	NA	< 0.5	< 0.5	< 0.5	< 0.5	< 0.5
No	16	Jul-02	< 50	NA	< 0.5	< 0.5	< 0.5	< 0.5	< 0.5
No	17	Oct-02	458	NA	1.7	< 0.3	< 0.3	< 0.6	233
No	18	Jan-03	< 100	NA	< 0.3	< 0.3	< 0.3	< 0.6	< 5.0
No	19	Mar-03	< 15	NA	< 0.22	< 0.32	< 0.31	< 0.4	< 0.18
No	20	Aug-03	190	< 50	< 0.5	< 0.5	< 0.5	0.6	< 0.5
Yes	21	Dec-03	163	< 100	< 0.3	< 0.3	< 0.3	< 0.6	66
Yes	22	Mar-04	412	< 100	1.2	< 0.3	1.7	3.9	66
Yes	23	Jun-04	320	68	< 0.5	< 0.5	< 0.5	< 0.5	120
Yes	24	Sep-04	280	2600	< 0.5	< 0.5	< 0.5	< 0.5	120
Yes	25	Dec-04	270	84	< 0.5	< 0.5	< 0.5	< 0.5	94
Yes	26	Mar-05	270	120	< 0.5	< 0.5	< 0.5	< 1.0	66
Yes	27	Jun-05	510	63	6.8	< 0.5	2.4	5.3	< 0.5
Yes	28	Sep-05	520	< 50	< 0.5	< 0.5	< 0.5	< 1.0	65
Yes	29	Dec-05	65	57	< 0.5	< 0.5	< 0.5	< 1.0	29
Yes	30	Mar-06	140	120	< 0.5	< 0.5	< 0.5	0.6	24
Yes	31	Jun-06	710	170	< 0.5	< 0.5	< 0.5	< 1.0	81
Yes	32	Sep-06	330	260	< 0.5	< 0.5	< 0.5	< 0.5	44
Yes	33	Dec-06	63	< 50	< 0.5	< 0.5	< 0.5	< 0.5	21
Yes	34	Mar-07	250	130	< 0.5	< 0.5	< 0.5	0.5	5
Yes	35	Jun-07	320	150	5.2	< 0.5	< 0.5	0.7	89
Yes	36	Sep-07	NS	NS	NS	NS	NS	NS	NS
Yes	37	Dec-07	NS	NS	NS	NS	NS	NS	NS
Yes	38	Mar-08	NS	NS	NS	NS	NS	NS	NS
Yes	39	Jun-08	NS	NS	NS	NS	NS	NS	NS

 $TVH-g = Total\ Volatile\ Hydrocarbons\ -\ gasoline\ range.\ TEH-d = Total\ Extractable\ Hydrocarbons\ -\ diesel\ range.$

NA = Not analyzed for this constituent in this event.

 $ND = Not \ Detected \ (method \ reporting \ limit \ not \ specified \ in \ the \ information \ available \ to \ SES.$

⁽a) Data not available to Ses as to whether the samples were collected "post-purge" or before purging.

[&]quot;No Purge" means no purging was conducted before the groundwater sample was collected.

TABLE~C-2 Historical Groundwater Monitoring Well Groundwater Analytical Results Fuel Oxygenates and VOCs $(\mu g/L)$

240 W. MacArthur Boulevard, Oakland, California

Well I.D.	Sampling Event No.	Date Sampled	EDB	EDC	1,2,4- TMB	1,3,5- TMB	t-Butanol	TBA	DIPE	Naphthalene	cis-1,2- DCE	TCE	PCE	Others
	7	Jun-00	< 5.0	< 5.0	51	< 5	< 1,000	< 1000	< 50	<5	< 5	< 5	< 5	ND
	14	Mar-02	< 1.0	< 1.0	< 1	1.6	< 10	NA	< 2	< 1	< 1	< 1	< 1	ND
	18	Jan-03	< 50	< 50	150	< 50	NA	68	< 10	< 50	< 50	< 50	< 50	ND
	19	Mar-03	< 0.26	< 0.17	373	< 0.49	NA	< 10	< 0.29	< 0.88	< 0.30	< 0.23	< 0.36	ND
	20	Aug-03	< 1.0	7.2	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA
	21	Dec-03	< 5.0	< 5.0	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA
	22	Mar-04	< 0.26	< 0.17	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA
	23	Jun-04	< 5.0	< 5.0	NA	NA	NA	270	< 5.0	NA	NA	NA	NA	NA
	24	Sep-04	< 5.0	< 5.0	NA	NA	NA	120	< 5.0	NA	NA	NA	NA	NA
	25	Dec-04	< 1.3	< 1.3	NA	NA	NA	< 25	< 1.3	NA	NA	NA	NA	NA
	26	Mar-05	< 0.50	< 0.50	NA	NA	NA	< 10	< 0.50	NA	NA	NA	NA	NA
MW-1	27	Jun-05	< 13	< 13	NA	NA	NA	< 250	< 13	NA	NA	NA	NA	NA
141 44 - 1	28	Sep-05	< 2.5	6.5	NA	NA	NA	240	< 2.5	NA	NA	NA	NA	NA
	29	Dec-05	< 1.3	< 1.3	NA	NA	NA	100	< 3.6	NA	NA	NA	NA	NA
	30	Mar-06	< 2.0	< 2.0	NA	NA	NA	83	< 2.0	NA	NA	NA	NA	NA
	31	Jun-06	< 2.5	< 2.5	NA	NA	NA	220	< 2.5	NA	NA	NA	NA	NA
	32	Sep-06	< 13	< 13	NA	NA	NA	320	< 13	NA	NA	NA	NA	NA
	33	Dec-06	< 13	< 13	NA	NA	NA	320	< 13	NA	NA	NA	NA	NA
	34	Mar-07	< 13	< 13	NA	NA	NA	<250	< 13	NA	NA	NA	NA	NA
	35	Jun-07	<1.7	<1.7	NA	NA	NA	37	<1.7	NA	NA	NA	NA	NA
	36	Sep-07	< 0.5	1.8	NA	NA	NA	66	< 0.5	NA	NA	NA	NA	NA
	37	Dec-07	< 1.0	< 1.0	NA	NA	NA	26	< 1.0	NA	NA	NA	NA	NA
	38	Mar-08	< 2.5	4.6	NA	NA	NA	66	<2.5	NA	NA	NA	NA	NA
	39	Jun-08	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS

Table C-2 Continued

Well I.D.	Sampling	Date	EDB	EDC	1,2,4-	1,3,5-	t-Butanol	TBA	DIPE	Naphthalene	cis-1,2-	TCE	PCE	Others
	Event No.	Sampled			TMB	TMB				•	DCE			
	7	Jun-00	< 0.5	< 0.5	< 0.5	< 0.5	< 100	< 100	< 5.0	< 0.5	< 0.5	< 0.5	< 0.5	
	14	Mar-02	< 1.0	< 1.0	< 1	< 1	220	NA	< 2	< 1	< 1	< 1	< 1	ND
	18	Jan-03	< 5	< 5	< 5	< 5	NA	34	< 1	< 5	24	< 5	< 5	ND
	19	Mar-03	< 0.26	< 0.17	< 0.49	< 0.26	NA	94	< 0.29	< 0.88	15	< 0.23	< 0.36	ND
	21	Dec-03	< 0.6	< 0.6	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA
	20	Aug-03	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA
	21	Dec-03	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA
	22	Mar-04	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA
	23	Jun-04	< 0.5	2.0	NA	NA	NA	190	1.1	NA	NA	NA	NA	NA
	24	Sep-04	< 0.5	1.2	NA	NA	NA	130	0.9	NA	NA	NA	NA	NA
	25	Dec-04	< 0.5	< 0.5	NA	NA	NA	< 10	0.8	NA	NA	NA	NA	NA
MW-2	26	Mar-05	< 1.0	< 1.0	NA	NA	NA	< 20	1.3	NA	NA	NA	NA	NA
IVI VV - 2	27	Jun-05	< 0.50	< 0.50	NA	NA	NA	200	0.79	NA	NA	NA	NA	NA
	28	Sep-05	< 0.50	0.6	NA	NA	NA	150	0.8	NA	NA	NA	NA	NA
	29	Dec-05	< 0.50	< 0.50	NA	NA	NA	54	1.0	NA	NA	NA	NA	NA
	30	Mar-06	< 0.7	< 0.7	NA	NA	NA	56	1.2	NA	NA	NA	NA	NA
	31	Jun-06	< 0.8	1.4	NA	NA	NA	56	< 0.8	NA	NA	NA	NA	NA
	32	Sep-06	< 0.5	1.3	NA	NA	NA	59	0.8	NA	NA	NA	NA	NA
	33	Dec-06	< 0.5	1.3	NA	NA	NA	59	0.8	NA	NA	NA	NA	NA
	34	Mar-07	< 0.5	2.5	NA	NA	NA	65	1.2	NA	NA	NA	NA	NA
	35	Jun-07	< 0.5	< 0.5	NA	NA	NA	24	6.1	NA	NA	NA	NA	NA
	37	Dec-07	< 0.5	< 0.5	NA	NA	NA	21	3.4	NA	NA	NA	NA	NA
	38	Mar-08	< 0.5	1.4	NA	NA	NA	87	17.0	NA	NA	NA	NA	NA
	39	Jun-08	< 0.5	1.9	NA	NA	NA	71	11.0	NA	NA	NA	NA	NA

Table C-2 Continued

Well I.D.	Sampling Event No.	Date Sampled	EDB	EDC	1,2,4- TMB	1,3,5- TMB	t-Butanol	TBA	DIPE	Naphthalene	cis-1,2- DCE	TCE	PCE	Others
	14	Mar-02	< 1.0	< 1.0	1.8	4.7	180	NA	< 2	2.2	< 1	< 1	< 1	ND
	18	Jan-03	< 5	< 5	< 5	5.0	NA	76	< 1	< 5	21	< 5	< 5	(a)
	19	Mar-03	< 0.26	< 0.17	< 0.49	< 0.26	NA	< 10	< 0.29	< 0.88	24	< 0.23	< 0.36	ND
	20	Aug-03	< 0.5	< 0.5	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA
	21	Dec-03	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA
	22	Mar-04	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA
	23	Jun-04	< 0.5	< 0.5	NA	NA	NA	130	1.9	NA	NA	NA	NA	NA
	24	Sep-04	< 0.5	< 0.5	NA	NA	NA	82	1.5	NA	NA	NA	NA	NA
	25	Dec-04	< 0.7	< 0.7	NA	NA	NA	< 14	1.3	NA	NA	NA	NA	NA
	26	Mar-05	< 1.0	< 1.0	NA	NA	NA	< 20	1.1	NA	NA	NA	NA	NA
	27	Jun-05	< 0.5	< 0.5	NA	NA	NA	160	1.4	NA	NA	NA	NA	NA
MW-3	28	Sep-05	< 0.5	1.5	NA	NA	NA	94	0.9	NA	NA	NA	NA	NA
	29	Dec-05	< 0.7	< 0.7	NA	NA	NA	67	1.2	NA	NA	NA	NA	NA
	30	Mar-06	< 0.5	< 0.5	NA	NA	NA	29	1.0	NA	NA	NA	NA	NA
	31	Jun-06	< 0.5	< 0.5	NA	NA	NA	52	2.2	NA	NA	NA	NA	NA
	32	Sep-06	<1.7	1.8	NA	NA	NA	53	1.7	NA	NA	NA	NA	NA
	33	Dec-06	<1.7	1.8	NA	NA	NA	53	1.7	NA	NA	NA	NA	NA
	34	Mar-07	< 0.5	< 0.5	NA	NA	NA	37	1.9	NA	NA	NA	NA	NA
	35	Jun-07	< 0.5	< 0.5	NA	NA	NA	10	1.0	NA	NA	NA	NA	NA
	36	Sep-07	< 0.5	< 0.5	NA	NA	NA	49	1.9	NA	NA	NA	NA	NA
	37	Dec-07	< 0.5	< 0.5	NA	NA	NA	71	8.6	NA	NA	NA	NA	NA
	38	Mar-08	< 0.5	1.9	NA	NA	NA	74	8.3	NA	NA	NA	NA	NA
	39	Jun-08	< 0.5	1.1	NA	NA	NA	22	3.2	NA	NA	NA	NA	NA

Table C-2 Continued

W-III D	Sampling	Date	EDD	EDC	1,2,4-	1,3,5-	C-2 Continu		DIDE	N 1- 41 1	cis-1,2-	TOE	DCE	Others
Well I.D.	Event No.	Sampled	EDB	EDC	TMB	TMB	t-Butanol	TBA	DIPE	Naphthalene	DCE	TCE	PCE	Others
	7	Jun-00	< 0.5	< 0.5	< 0.5	< 0.5	< 100	< 100	< 5.0	< 0.5	< 0.5	< 0.5	< 0.5	ND
	14	Mar-02	< 1.0	< 1.0	< 1	< 1	< 10	NA	< 2	< 1	2.9	3.7	5.0	ND
	18	Jan-03	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	ND
	19	Mar-03	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	ND
	20	Aug-03	< 0.5	< 0.5	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA
	21	Dec-03	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA
	22	Mar-04	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA
	23	Jun-04	< 0.5	< 0.5	NA	NA	NA	< 10	< 0.5	NA	NA	NA	NA	NA
	24	Sep-04	< 0.5	< 0.5	NA	NA	NA	< 10	< 0.5	NA	NA	NA	NA	NA
	25	Dec-04	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA
	26	Mar-05	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA
MW-4	27	Jun-05	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA
	28	Sep-05	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA
	29	Dec-05	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA
	30	Mar-06	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA
	31	Jun-06	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA
	32	Sep-06	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA
	33	Dec-06	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA
	34	Mar-07	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA
	36	Sep-07	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA
	37	Dec-07	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA
	38	Mar-08	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA
	39	Jun-08	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA

Table C-2 Continued

Well I.D.	Sampling Event No.	Date Sampled	EDB	EDC	1,2,4- TMB	1,3,5- TMB	t-Butanol	ТВА	DIPE	Naphthalene	cis-1,2- DCE	TCE	PCE	Others
	14	Mar-02	< 1.0	< 1.0	< 1	2.7	640	NA	< 2	< 1	< 1	< 1	< 1	ND
	18	Jan-03	< 50	< 50	512	122	NA	< 100	< 10	120	< 50	< 50	< 50	ND
	19	Mar-03	< 0.26	< 0.17	554	107	NA	< 10	< 0.29	251	< 0.3	< 0.23	< 0.36	(b)
	20	Aug-03	< 2.0	6.1	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA
	21	Dec-03	< 5.0	< 5.0	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA
	22	Mar-04	< 0.26	< 0.17	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA
	23	Jun-04	< 3.1	< 3.1	NA	NA	NA	120	< 3.1	NA	NA	NA	NA	NA
	24	Sep-04	< 4.2	18	NA	NA	NA	87	< 4.2	NA	NA	NA	NA	NA
	25	Dec-04	< 4.2	< 4.2	NA	NA	NA	< 83	< 4.2	NA	NA	NA	NA	NA
	26	Mar-05	< 1.7	< 1.7	NA	NA	NA	< 33	< 1.7	NA	NA	NA	NA	NA
	27	Jun-05	< 7.1	< 7.1	NA	NA	NA	< 140	< 7.1	NA	NA	NA	NA	NA
MW-5	28	Sep-05	< 1.3	7.7	NA	NA	NA	87	< 0.50	NA	NA	NA	NA	NA
	29	Dec-05	< 1.7	< 1.7	NA	NA	NA	< 33	< 1.7	NA	NA	NA	NA	NA
	30	Mar-06	< 2.0	< 2.0	NA	NA	NA	< 2.0	< 2.0	NA	NA	NA	NA	NA
	31	Jun-06	< 2.0	10	NA	NA	NA	61	< 2.0	NA	NA	NA	NA	NA
	32	Sep-06	< 3.6	5.5	NA	NA	NA	76	< 3.6	NA	NA	NA	NA	NA
	33	Dec-06	< 3.6	5.5	NA	NA	NA	76	< 3.6	NA	NA	NA	NA	NA
	34	Mar-07	< 3.6	< 3.6	NA	NA	NA	<71	< 3.6	NA	NA	NA	NA	NA
	35	Jun-07	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS
	36	Sep-07	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS
	37	Dec-07	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS
	38	Mar-08	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS
	39	Jun-08	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS

Table C-2 Continued

Well I.D.	Sampling Event No.	Date Sampled	EDB	EDC	1,2,4- TMB	1,3,5- TMB	t-Butanol	TBA	DIPE	Naphthalene	cis-1,2- DCE	TCE	PCE	Others
	14	Mar-02	< 1.0	< 1.0	< 1	2.2	< 10	NA	< 2	1.6	< 1	< 1	< 1	ND
	18	Jan-03	< 5.0	< 5.0	13	< 5	NA	46	< 1	< 5	< 5	< 5	< 5	ND
	19	Mar-03	< 0.26	6.9	< 0.49	< 0.26	NA	40	< 0.29	< 0.88	< 0.3	< 0.23	< 0.36	(c.)
	20	Aug-03	< 0.5	12.0	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA
	21	Dec-03	< 5.0	11 / 17.1 ^(d)	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA
	22	Mar-04	< 0.26	31	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA
	23	Jun-04	< 0.5	19	NA	NA	NA	54	1.0	NA	NA	NA	NA	NA
	24	Sep-04	< 0.5	31	NA	NA	NA	43	1.0	NA	NA	NA	NA	NA
	25	Dec-04	< 0.5	24	NA	NA	NA	32	0.7	NA	NA	NA	NA	NA
	26	Mar-05	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA
	27	Jun-05	< 0.50	< 0.50	NA	NA	NA	26	< 0.50	NA	NA	NA	NA	NA
MW-6	28	Sep-05	< 0.50	15	NA	NA	NA	43	0.7	NA	NA	NA	NA	NA
	29	Dec-05	< 0.50	13	NA	NA	NA	30	0.9	NA	NA	NA	NA	NA
	30	Mar-06	< 0.50	15	NA	NA	NA	19	0.6	NA	NA	NA	NA	NA
	31	Jun-06	< 0.50	28	NA	NA	NA	53	1.3	NA	NA	NA	NA	NA
	32	Sep-06	< 0.50	11	NA	NA	NA	46	0.7	NA	NA	NA	NA	NA
	33	Dec-06	< 0.50	11	NA	NA	NA	46	0.7	NA	NA	NA	NA	NA
	34	Mar-07	< 0.5	10	NA	NA	NA	25	< 0.5	NA	NA	NA	NA	NA
	35	Jun-07	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS
	36	Sep-07	NS	NS	NS	NS	NS	NS	NS		NS	NS	NS	NS
	37	Dec-07	NS	NS	NS	NS	NS	NS	NS		NS	NS	NS	NS
	38	Mar-08	NS	NS	NS	NS	NS	NS	NS		NS	NS	NS	NS
	39	Jun-08	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS

Table C-2 Continued

	Compling	Data			124		C-2 Contin	иси		1	aia 1 2			
Well I.D.	Sampling Event No.	Date Sampled	EDB	EDC	1,2,4- TMB	1,3,5- TMB	t-Butanol	TBA	DIPE	Naphthalene	cis-1,2- DCE	TCE	PCE	Others
	14	Mar-02	< 1.0	< 1.0	< 1	< 1	< 10	NA	< 2	< 1	< 1	< 1	< 1	ND
	18	Jan-03	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	ND
	19	Mar-03	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	ND
	20	Aug-03	< 0.5	< 0.5	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA
	21	Dec-03	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA
	22	Mar-04	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA
	23	Jun-04	< 0.5	< 0.5	NA	NA	NA	< 10	< 0.5	NA	NA	NA	NA	NA
	24	Sep-04	< 0.5	< 0.5	NA	NA	NA	< 10	< 0.5	NA	NA	NA	NA	NA
	25	Dec-04	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA
	26	Mar-05	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA
	27	Jun-05	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA
MW-7	28	Sep-05	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA
141 44-7	29	Dec-05	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA
	30	Mar-06	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA
	31	Jun-06	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA
	32	Sep-06	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA
	32	Sep-06	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA
	33	Dec-06	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA
	34	Mar-07	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA
	35	Jun-07	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA
	36	Sep-07	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA
	37	Dec-07	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA
	38	Mar-08	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA
	39	Jun-08	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS

Table C-2 Continued

Well I.D.	Sampling Event No.	Date Sampled	EDB	EDC	1,2,4- TMB	1,3,5- TMB	t-Butanol	TBA	DIPE	Naphthalene	cis-1,2- DCE	TCE	PCE	Others
	14	Mar-02	< 1.0	< 1.0	< 1	< 1	< 10	NA	< 2	< 1	< 1	< 1	< 1	ND
	18	Jan-03	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	ND
	19	Mar-03	< 0.26	< 0.17	< 0.49	< 0.26	NA	< 10	< 0.29	< 0.88	< 0.3	< 0.23	< 0.36	ND
	20	Aug-03	< 0.5	< 0.5	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA
	21	Dec-03	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA
	22	Mar-04	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA
	23	Jun-04	< 0.5	< 0.5	NA	NA	NA	61	1.0	NA	NA	NA	NA	NA
	24	Sep-04	< 0.5	< 0.5	NA	NA	NA	96	1.1	NA	NA	NA	NA	NA
	25	Dec-04	< 0.5	< 0.5	NA	NA	NA	< 10	1.0	NA	NA	NA	NA	NA
	26	Mar-05	< 0.5	< 0.5	NA	NA	NA	< 10	0.6	NA	NA	NA	NA	NA
	27	Jun-05	< 0.50	25.0	NA	NA	NA	42	1.1	NA	NA	NA	NA	NA
MW-8	28	Sep-05	< 0.50	< 0.5	NA	NA	NA	120	1.4	NA	NA	NA	NA	NA
	29	Dec-05	< 0.50	< 0.50	NA	NA	NA	27	< 0.50	NA	NA	NA	NA	NA
	30	Mar-06	< 0.50	< 0.50	NA	NA	NA	17	0.6	NA	NA	NA	NA	NA
	31	Jun-06	< 0.50	< 0.50	NA	NA	NA	20	0.9	NA	NA	NA	NA	NA
	32	Sep-06	< 0.50	< 0.50	NA	NA	NA	12	< 0.50	NA	NA	NA	NA	NA
	33	Dec-06	< 0.50	< 0.50	NA	NA	NA	12	< 0.50	NA	NA	NA	NA	NA
	34	Mar-07	< 0.50	< 0.50	NA	NA	NA	<10	< 0.50	NA	NA	NA	NA	NA
	35	Jun-07	< 0.5	< 0.5	NA	NA	NA	14	1.3	NA	NA	NA	NA	NA
	36	Sep-07	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS
	37	Dec-07	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS
	38	Mar-08	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS
	39	Jun-08	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS	NS

Table C-2 - Footnotes

Notes:

Table includes only detected contaminants.

EDB = Ethylene dibromide, aka 1,2-Dibromoethane (lead scavenger) DIPE = Isopropyl Ether (a.k.a. di-isopropyl ether)

EDC = Ethylene dichloride, aka 1,2-Dichloroethane (lead scavenger)

TBA = Tertiary butyl alcohol

PCE = Tetrachloroethylene

DCE = Dichloroethylene

NLP = No Level Published

TCE = Trichloroethyene TMB = Trimethylbenzene NA = Not analyzed for this constituent. ND = Not Detected

- (a) Also detected were: n-propylbenzene (5.4 mg/L); p-Isopropyltoluene (14 mg/L); sec-Butylbenzene (7.2 mg/L)
- (b) Also detected were: isopropylbenzene (38 mg/L); n-Butylbenzene (20 mg/L); n-propylbenzene (36 mg/L); p-Isopropyltoluene (14 mg/L).
- $(c.) \ Also \ detected \ were: is opropylbenzene \ (3.4 \ mg/L); \ n-propylbenzene \ (2.3 \ mg/L). \\ (d) \ \ Pre-purge \ / \ post-purge \ sampling, \ conducted \ in \ same \ event.$

NS = Not Sampled




Table D-1
Historical Water Levels in Monitoring Wells
240 W. MacArthur Boulevard, Oakland, Alameda, California

Well I.D.	Sampling Event No.	Date Measured	Water Level Depth (a)	Water Level Elevation (b)
	1	Aug-97	16.83	62.32
	2	Dec-97	NA	NA
	3	Mar-98	13.58	65.57
	4	Jul-98	15.55	63.60
	5	Oct-98	15.70	63.45
	6	Jan-99	15.21	63.94
	7	Jun-00	15.41	63.74
	8	Dec-00	NA	NA
	9	Feb-01	NA	NA
MW-1	10	May-01	15.57	63.58
	11	Jul-01	16.42	62.73
	12	Oct-01	16.82	62.33
	13	Dec-01	15.08	64.07
	14	Mar-02	14.53	64.62
	15	May-02	NA	NA
	16	Jul-02	16.39	62.76
	17	Oct-02	17.03	62.12
	18	Jan-03	14.91	64.24
	19	Mar-03	15.26	63.89
	20	Aug-03	16.24	62.91
	21	Dec-03	16.90	62.25
	22	Mar-04	14.33	64.82
	23	Jun-04	16.28	62.87
	24	Sep-04	17.03	62.12
	25	Dec-04	16.38	62.77
	26	Mar-05	14.30	64.85
	27	Jun-05	15.53	63.82
	28	Sep-05	16.42	62.73
	29	Dec-05	15.67	63.48
	30	Mar-06	12.75	66.40
	31	Jun-06	14.60	64.55
	32	Sep-06	16.52	62.63
	33	Dec-06	15.89	63.26
	34	Mar-07	15.50	63.65
	35	Jun-07	20.90	58.25
	36	Sep-07	23.30	55.85
	37	Dec-07	22.51	56.64
	38	Mar-08	20.70	58.45
	39	Jun-08	NM	Dry

(a) Feet below well top of casing.

(b) Relative to mean sea level.

NA = Data Not Available

Table D-1 (continued)

Well I.D.	Sampling Event No.	Date Measured	Water Level Depth (a)	Water Level Elevation (b)
	1	Aug-97	16.32	62.13
	2	Dec-97	NA	NA
	3	Mar-98	13.05	64.95
	4	Jul-98	14.95	63.50
	5	Oct-98	15.09	63.36
	6	Jan-99	14.61	63.84
	7	Jun-00	14.80	63.65
	8	Dec-00	NA	NA
	9	Feb-01	NA	NA
MW-2	10	May-01	14.98	63.47
	11	Jul-01	15.86	62.59
	12	Oct-01	16.69	61.76
	13	Dec-01	13.49	64.96
	14	Mar-02	13.07	65.38
	15	May-02	NA	NA
	16	Jul-02	15.86	62.59
	17	Oct-02	16.54	61.91
	18	Jan-03	14.37	64.08
	19	Mar-03	14.74	63.71
	20	Aug-03	15.75	62.70
	21	Dec-03	16.11	62.34
	22	Mar-04	13.83	64.82
	23	Jun-04	15.76	62.69
	24	Sep-04	16.48	61.97
	25	Dec-04	15.74	62.71
	26	Mar-05	13.48	64.97
	27	Jun-05	14.48	63.97
	28	Sep-05	16.00	62.45
	29	Dec-05	14.88	63.57
	30	Mar-06	12.20	66.25
	31	Jun-06	14.15	64.30
	32	Sep-06	16.00	62.45
	33	Dec-06	15.19	63.26
	34	Mar-07	14.78	63.67
	35	Jun-07	20.60	57.85
	36	Sep-07	23.80	54.65
	37	Dec-07	22.36	56.09
	38	Mar-08	20.15	58.30
	39	Jun-08	20.13	57.85
	37	Jun-00	20.00	37.03

(a) Feet below well top of casing.

(b) Relative to mean sea level.

NA = Data Not Available

Table D-1 (continued)

Well I.D.	Sampling Event No.	Date Measured	Water Level Depth (a)	Water Level Elevation (b)
	1	Aug-97	15.36	62.22
	2	Dec-97	NA	NA
	3	Mar-98	12.18	65.40
	4	Jul-98	14.08	63.50
	5	Oct-98	14.24	63.34
	6	Jan-99	13.74	63.84
MW-3	7	Jun-00	13.94	63.64
	8	Dec-00	NA	NA
	9	Feb-01	NA	NA
	10	May-01	14.08	63.50
	11	Jul-01	14.99	62.59
	12	Oct-01	16.26	61.32
	13	Dec-01	13.62	63.96
	14	Mar-02	13.19	64.39
	15	May-02	NA	NA
	16	Jul-02	14.97	62.61
	17	Oct. 2002	15.44	62.14
	18	Jan-03	13.49	64.09
	19	Mar-03	13.83	63.75
	20	Aug-03	14.90	62.68
	21	Dec-03	15.10	62.48
	22	Mar-04	12.93	64.65
	23	Jun-04	14.90	62.68
	24	Sep-04	15.61	61.97
	25	Dec-04	14.77	62.81
	26	Mar-05	12.60	64.98
	27	Jun-05	13.73	63.85
	28	Sep-05	15.14	62.44
	29	Dec-05	13.94	63.64
	30	Mar-06	11.25	66.33
	31	Jun-06	13.27	64.31
	32	Sep-06	15.12	62.46
	33	Dec-06	14.34	63.24
	34	Mar-07	13.96	63.62
	35	Jun-07	19.60	57.98
	36	Sep-07	22.90	54.68
	37	Dec-07	21.45	56.13
	38	Mar-08	19.20	58.38
	39	Jun-08	18.80	58.78

(a) Feet below well top of casing.

(b) Relative to mean sea level.

NA = Data Not Available

Table D-1 (continued)

		Date Measured	Depth (a)	Water Level Elevation (b)
	1	Aug-97	NA	NA
	2	Dec-97	NA	NA
	3	Mar-98	11.87	65.87
	4	Jul-98	13.90	63.84
	5	Oct-98	14.10	63.64
	6	Jan-99	13.56	64.18
	7	Jun-00	13.75	63.99
	8	Dec-00	NA	NA
	9	Feb-01	NA	NA
MW-4	10	May-01	13.65	64.09
	11	Jul-01	14.87	62.87
	12	Oct-01	15.78	61.96
	13	Dec-01	13.54	64.20
	14	Mar-02	13.02	64.72
	15	May-02	NA	NA
	16	Jul-02	14.81	62.93
	17	Oct-02	15.56	62.18
	18	Jan-03	13.39	64.35
	19	Mar-03	13.75	63.99
	20	Aug-03	14.75	62.99
	21	Dec-03	15.11	62.63
	22	Mar-04	12.78	64.96
	23	Jun-04	14.68	63.06
	24	Sep-04	15.17	62.57
	25	Dec-04	14.90	62.84
	26	Mar-05	12.57	65.17
	27	Jun-05	13.43	64.31
	28	Sep-05	15.13	62.61
	29	Dec-05	13.83	63.91
	30	Mar-06	10.90	66.84
	31	Jun-06	13.02	64.72
	32	Sep-06	15.16	62.58
	33	Dec-06	14.35	63.39
	34	Mar-07	13.85	63.89
	35	Jun-07	18.41	59.33
	36	Sep-07	19.36	58.38
	37	Dec-07	19.13	58.61
	38	Mar-08	17.91	59.83
	39	Jun-08	18.23	59.51

(a) Feet below well top of casing.

(b) Relative to mean sea level.

NA = Data Not Available

Table D-1 (continued)

Well I.D.	Sampling Event No.	Date Measured	Water Level Depth (a)	Water Level Elevation (b)
	9	Feb-01	NA	NA
	10	May-01	15.65	63.71
	11	Jul-01	16.50	62.86
	12	Oct-01	17.46	61.90
	13	Dec-01	15.28	64.08
MW-5	14	Mar-02	14.62	64.74
	15	May-02	NA	NA
	16	Jul-02	16.46	62.90
	17	Oct-02	17.18	62.18
	18	Jan-03	14.99	64.37
	19	Mar-03	15.33	64.03
	20	Aug-03	16.34	63.02
	21	Dec-03	16.90	62.46
	22	Mar-04	14.44	64.92
	23	Jun-04	16.43	62.93
	24	Sep-04	17.07	62.29
	25	Dec-04	16.59	62.77
	26	Mar-05	14.08	65.28
	27	Jun-05	15.33	64.03
	28	Sep-05	16.61	62.75
	29	Dec-05	15.81	63.55
	30	Mar-06	12.75	66.61
	31	Jun-06	14.65	64.71
	32	Sep-06	16.66	62.70
	33	Dec-06	16.10	63.26
	34	Mar-07	15.22	64.14
	35	Jun-07	19.29	60.07
	36	Sep-07	NM	Dry
	37	Dec-07	NM	Dry
	38	Mar-08	NM	Dry
	39	Jun-08	NM	Dry

(a) Feet below well top of casing. (b) Relative to mean sea level.

NA = Data Not Available NM = Not Measurable

Data prior to August 2003 are likely not valid as well elevations were not surveyed.

Table D-1 (continued)

Well I.D.	Sampling Event No.	Date Measured	Water Level Depth (a)	Water Level Elevation (b)
	9	Feb-01	NA	NA
	10	May-01	15.54	62.89
	11	Jul-01	15.56	62.87
	12	Oct-01	16.41	62.02
	13	Dec-01	14.37	64.06
MW-6	14	Mar-02	13.75	64.68
	15	May-02	NA	NA
	16	Jul-02	15.55	62.88
	17	Oct-02	16.24	62.19
	18	Jan-03	14.17	64.26
	19	Mar-03	14.52	63.91
	20	Aug-03	15.50	62.93
	21	Dec-03	16.19	62.24
	22	Mar-04	13.51	64.92
	23	Jun-04	15.42	63.01
	24	Sep-04	16.13	62.30
	25	Dec-04	15.40	63.03
	26	Mar-05	13.28	65.15
	27	Jun-05	14.14	64.29
	28	Sep-05	15.61	62.82
	29	Dec-05	14.90	63.53
	30	Mar-06	11.85	66.58
	31	Jun-06	13.73	64.70
	32	Sep-06	15.71	62.72
	33	Dec-06	15.15	63.28
	34	Mar-07	14.58	63.85
	35	Jun-07	19.40	59.03
	36	Sep-07	20.00	58.43 (Dry)
	37	Dec-07	NM	Dry
	38	Mar-08	NM	Dry
	39	Jun-08	NM	Dry

(a) Feet below well top of casing. (b) Relative to mean sea level. $NA = Data \ Not \ Available \qquad \qquad NM = Not \ Measurable$

Table D-1 (continued)

Well I.D.	Sampling Event No.	Date Measured	Water Level Depth (a)	Water Level Elevation (b)
	9	Feb-01	NA	NA
	10	May-01	15.04	62.23
	11	Jul-01	15.69	62.58
	12	Oct-01	16.59	61.68
	13	Dec-01	14.30	63.97
MW-7	14	Mar-02	13.87	64.40
	15	May-02	NA	NA
	16	Jul-02	15.72	62.55
	17	Oct-02	16.36	61.91
	18	Jan-03	14.22	64.05
	19	Mar-03	14.57	63.70
	20	Aug-03	15.61	62.66
	21	Dec-03	16.04	62.23
	22	Mar-04	13.57	64.70
	23	Jun-04	15.63	62.64
	24	Sep-04	16.33	61.94
	25	Dec-04	15.70	62.57
	26	Mar-05	13.42	64.85
	27	Jun-05	14.53	63.74
	28	Sep-05	15.81	62.46
	29	Dec-05	14.88	63.39
	30	Mar-06	13.00	65.27
	31	Jun-06	13.98	64.29
	32	Sep-06	15.82	62.45
	33	Dec-06	15.12	63.15
	34	Mar-07	14.66	63.61
	35	Jun-07	19.18	59.09
	36	Sep-07	19.96	Dry
	37	Dec-07	NM	Dry
	38	Mar-08	NM	Dry
	39	Jun-08	NM	Dry

(a) Feet below well top of casing.

(b) Relative to mean sea level.

NA = Data Not Available

NM = Not Measurable

Table D-1 (continued)

Well I.D.	Sampling Event No.	Date Measured	Water Level Depth (a)	Water Level Elevation (b)
	10	May-01	12.75	63.64
	11	Jul-01	13.84	62.55
	12	Oct-01	14.65	61.74
	13	Dec-01	12.39	64.00
	14	Mar-02	11.89	64.50
MW-8	15	May-02	NA	NA
	16	Jul-02	13.96	62.43
	17	Oct-02	14.48	61.91
	18	Jan-03	12.49	63.90
	19	Mar-03	12.85	63.54
	20	Aug-03	13.75	62.65
	21	Dec-03	14.50	61.89
	22	Mar-04	11.78	64.61
	23	Jun-04	13.71	62.68
	24	Sep-04	14.43	61.96
	25	Dec-04	13.64	62.75
	26	Mar-05	11.52	64.87
	27	Jun-05	12.50	63.89
	28	Sep-05	13.90	62.49
	29	Dec-05	12.75	63.64
	30	Mar-06	10.80	65.59
	31	Jun-06	12.10	64.29
	32	Sep-06	13.93	62.46
	33	Dec-06	13.12	63.27
	34	Mar-07	12.76	63.63
	35	Jun-07	18.40	57.99
	36	Sep-07	19.12	57.27 (Dry)
	37	Dec-07	NM	Dry
	38	Mar-08	NM	Dry
	39	Jun-08	NM	Dry

(a) Feet below well top of casing. (b) Relative to mean sea level.

NA = Data Not Available NM = Not Measurable

Data prior to August 2003 are likely not valid as well elevations were not surveyed.