

CARLAND CA 945 20 JAN '16 PM 5 L



No NIXIE

0002/01/15

66 Oal

RETURN TO SENDER REFUSED UNABLE TO FORWARD

BC: 94502654031 \*1505-00549-20-39

## ALAMEDA COUNTY HEALTH CARE SERVICES AGENCY



ALEX BRISCOE, Director

ENVIRONMENTAL HEALTH SERVICES ENVIRONMENTAL PROTECTION 1131 Harbor Bay Parkway, Suite 250 Alameda, CA 94502-6577 (510) 567-6700 FAX (510) 337-9335

January 19, 2016

Andrea Wing
Shell Oil Products US
20945 S. Wilmington Ave
Carson, CA 90810-1039
(Sent via E-mail to: andrea.wing@shell.com)

Rodney and Janet Kwan 1834 Alameda Ave. Alameda, CA 94501

Subject: Case File Review for Fuel Leak Case No. RO0000145 and GeoTracker Global ID T0600101876, Shell/Auto Tech West, 2703 Martin Luther King, Jr. Way, Oakland, CA 94612

Dear Ms Wing and Mr. and Ms. Kwan:

Alameda County Environmental Health (ACEH) staff has reviewed the fuel leak case file for the above-referenced site including the document entitled, "Human Health Risk Assessment," dated November 30, 2015 (HHRA). The HHRA, which was prepared on Shell's behalf by AECOM, uses existing data to assess risks for on-site and off-site current and future receptors. Based on this assessment, the HHRA recommends re-sampling of soil vapor probes VP-7 and VP-13 and preparation of a revised Corrective Action Plan (CAP) to replace the 2008 CAP submitted by Conestoga-Rovers & Associates. We concur with these recommendations and request that you submit a Revised CAP no later than April 29, 2016.

## **TECHNICAL REPORT REQUEST**

Please upload technical reports to ACEH ftp site (Attention: Jerry Wickham), and to the State Water Resources Control Board's GeoTracker website, in accordance with the specified naming convention below, according to the following schedule:

- April 17, 2016 First Quarter 2016 Groundwater Monitoring Report File to be named: GWM\_R\_yyyy-mm-dd\_RO145
- April 29, 2016 Revised Corrective Action Plan File to be named: CAP\_R\_yyyy-mm-dd

These reports are being requested pursuant to California Health and Safety Code Section 25296.10. 23 CCR Sections 2652 through 2654, and 2721 through 2728 outline the responsibilities of a responsible party in response to an unauthorized release from a petroleum UST system, and require your compliance with this request.