RECEIVED



8:44 am, Jan 17, 2012

Alameda County Environmental Health

Mr. Jerry Wickham Alameda County Environmental Health 1131 Harbor Bay Parkway, Suite 250 Alameda, California 94205-6577 Denis L. Brown Shell Oil Products US

HSE – Environmental Services 20945 S. Wilmington Ave. Carson, CA 90810-1039 Tel (707) 865 0251 Fax (707) 865 2542 Email denis.1.brown@shell.com

Re:

Shell-branded Service Station

1800 ½ Powell Street Emeryville, California SAP Code 135266 Incident No. 98995349

ACEH Case No. RO0000254

Dear Mr. Wickham:

The attached document is provided for your review and comment. Upon information and belief, I declare, under penalty of perjury, that the information contained in the attached document is true and correct.

As always, please feel free to contact me directly at (707) 865-0251 with any questions or concerns.

Sincerely,

Denis L. Brown

Senior Program Manager

5900 Hollis Street, Suite A, Emeryville, Calfornia 94608 Telephone: 510-420-0700 Facsimile: 510-420-9170 www.CRAworld.com

January 13, 2012

Reference No. 240894

Mr. Jerry Wickham Alameda County Environmental Health 1131 Harbor Bay Parkway, Suite 250 Alameda, California 94502-6577

Dear Mr. Wickham:

Re:

Attempted Well Reinstallation

Shell-branded Service Station

1800½ Powell Street Emeryville, California SAP Code 135266 Incident No. 98995349

Agency No. RO0000254

Conestoga-Rovers & Associates (CRA) prepared this letter on behalf of Equilon Enterprises LLC dba Shell Oil Products US (Shell) to describe our attempt to reinstall one on-site well (S-9) as conditionally approved in Alameda County Environmental Health's (ACEH's) June 27, 2011 letter. ACEH's October 11, 2011 electronic correspondence extended the due date for a report from October 20, 2011 to January 18, 2012. The site location is shown on Figure 1, and the site layout including the well location is shown on Figure 2.

CRA's June 2, 2011 Subsurface Investigation Work Plan proposed installing one well to replace groundwater monitoring well S-9 or reinstalling the well at its current location. Based on utility locations marked by Underground Service Alert (USA) member organizations and a private utility locator retained by CRA, CRA could not find any possible location to safely install a replacement well, and encroaching utilities were too close to the current well location to allow the well to be reinstalled safely. The attached photographs show the utilities marked by USA member organizations and the private utility locator.

Please call Peter Schaefer at (510) 420-3319 if you have any questions or comments.

Yours truly,

CONESTOGA-ROVERS & ASSOCIATES

Peter Schaefer, CEG, CHG



January 13, 2012

2

Reference No. 240894

PS/bc/2 Enclosures

Denis Brown, Shell Oil Products US (electronic copy) c.c.:

Au Energy LLC, c/o Nick Goyle, Vintners Distributors, Inc., 41805 Albrae Street, 2nd Floor, Fremont, CA 94538

Shell-branded Service Station


1800 1/2 Powell Street Emeryville, California



Vicinity Map

Site Plan

FIGURE









I:\Shell\6-chars\2408--\240894-Emeryville 1800 Powell\240894-FIGURES\240894 UTILITY PHOTOS (F5).DWG (12/26/2011)



I:\Shell\6-chars\2408--\240894-Emeryville 1800 Powell\240894-FIGURES\240894 UTILITY PHOTOS (F6).DWG (12/26/2011)