HEALTH CARE SERVICES





DAVID J. KEARS. Agency Director

ENVIRONMENTAL HEALTH SERVICES ENVIRONMENTAL PROTECTION 1131 Harbor Bay Parkway, Suite 250 Alameda, CA 94502-6577 (510) 567-6700 FAX (510) 337-9335

July 13, 2001 StID # 5552/ RO0000270

Mr. Ronn Simpson P.O. Box 3090 Berkeley, CA 94703

Re: Request for Well Closure at 489 43rd St., Oakland CA 94609

Dear Mr. Simpson:

Our office has received concurrence from the San Francisco Regional Water Quality Control Board on our recommendation for no further action regarding the former gasoline tank located at the above location. Prior to our issuance of the no further action letter, please provide evidence of the proper closure of the one (1) monitoring well installed at this property. You may contact the Water Resources Section of Public Works at 510-670-5554 to obtain the permit and specific requirements for this work.

You may contact me at (510) 567-6765 if you have any questions.

Sincerely,

Barney M. Chan

Hazardous Materials Specialist

Banez Ur Cha

C: B. Chan, files

Ms. M. Chamberlain, Weiss Associates, 5801 Christie Ave., Suite 600, Emeryville, CA 94608-1827

WlcI489 43rdSt

ENV. WROATED 3/30/01

Press [ESC] for the menu

UNDERGROUND STORAGE TANK CLEANUP SITE

--LOP:A---TRemov:I---SLIC:--

SOURCE OF FUNDS: F SITE ID: 5552 SUBSTANCE :8006619 SITE NAME: Ronn Simpson DATE REPORTED :09/18/1995

SITE ADDRESS: 489 -0 43rd St DATE CONFIRMED:09/18/1995

ZIP CODE: 94609 CITY: Oakland MULTIPLE RPs : N

CASE TYPE: S CONTRACT STAT: 4 PRIORITY: 2A4 DATE ER:-0-

RP SEARCH : S DATE END: 09/19/1995

PRELIM ASSESSMENT: - DATE BEGIN: -0REMEDIAL INVEST: - DATE BEGIN: -0REMEDIAL ACTION: - DATE BEGIN: -0POST REMED MONITOR: - DATE BEGIN: -0-DATE END: -0-DATE END: -0-DATE END: -0-DATE END: -0-

ENFORCEMENT TYPE: 2 DATE ENFORCEMENT ACTION TAKEN: 08/20/1996

LUFT CATEGORY: -0- CASE CLOSED: - DATE CASE CLOSED: -0
DT EXC START: -0- REMEDIAL ACTIONS TAKEN: -0-

PgDn for Screen #2

[ESC] Done [F2] Clear field [Shift-F2] Clear to end [Shift-F10] More Form: SITE Field: Source Page: 1

Form: SITE

STID: 5552 UNDERGROUND STORAGE TANK CLEANUP SITE - SCREEN #2

IN-HOUSE MANAGEMENT:

RISK ASSESSMENT :-0- LOC-CleanUp Fund? 02/16/2000 DATE LAST CORSP :09/14/1999 INSPECTOR INIT: BC

CONTACT/RESPONSIBLE PARTY INFORMATION:

RP #1: CONTACT: Ronn Simpson
RP COMPANY NAME: Ronn Simpson RP COST: \$0.00 RP COMPANY NAME: Ronn Simpson Ph: 510/658-9006

ADDRESS: P. O. Box 3090

CITY/ST/ZIP: Berkeley, C A 94703

COMMENT: transf. to PE 9/12/97, MTBE=ND

PqUp For Screen #1; PqDn For More RP'S

[ESC] Done [F2] Clear field [Shift-F2] Clear to end [Shift-F10] More Form: SITE Field: FlagDate Page: 2

Form: SITE

HEALTH CARE SERVICES





ENVIRONMENTAL HEALTH SERVICES

ENVIRONMENTAL PROTECTION

Alameda, CA 94502-6577

(510) 567-6700 FAX (510) 337-9335

1131 Harbor Bay Parkway, Suite 250

DAVID J. KEARS, Agency Director

August 2, 2000 StID # 5552

Mr. Ronn Simpson P.O. Box 3090 Berkeley, CA 94703

Re: Investigation at 489 43rd St., Oakland CA 94609

Dear Mr. Simpson:

Our office has received and reviewed the July 28, 2000 Second Quarter 2000 groundwater monitoring report for the above site, prepared by Weiss Associates, your consultant. This sampling event marks the third monitoring event for the site since the well's December 1999 installation. Low concentrations of diesel, gasoline and paint thinner were detected during the most recent, 6/29/00 sampling event. BTEX and MTBE were not detected. At this time, our office requests continuing quarterly groundwater monitoring, however, you may put your tank pit excavation on hold.

Our office will be requesting the evaluation of human health and environmental risk of the neighboring site, 490 43rd St., with the intent of verifying low risk and recommendation of site closure. Should this site be deemed a low risk, 489 43rd St. will likely also be viewed as a low risk site and also be recommended for closure. Your monitoring will confirm that the release from both sites is limited in extent and of low risk in terms of human health exposure.

You may contact me at (510) 567-6765 if you have any questions.

Sincerely,

Barney M. Chan

Hazardous Materials Specialist

Sawes M Cha

C: B. Chan, files

Ms. M. Chamberlain, Weiss Associates, 5801 Christie Ave., Suite 600, Emeryville, CA 94608-1827

Mr. D. Dement, ACC Environmental Consultants, 7977 Capwell Dr., Suite 100, Oakland, CA. 94621

Mr. J. Ward, Wells Fargo Trust, P. O. Box 63939, San Francisco, CA 94163 Mr. Ken Cheitlin Esq., McShane, Schnack & Cheitlin, 2033 N. Main St., Suite 700, Walnut Creek, CA 94596

Stat489 43rd



Protection

State Water Resources Control Board

Division of Clean Water Programs

2014 T Street • Sacramento, California 95814 • (916) 227-4366 Marling Address: P O Box 944212 • Sacramento, California • 94244-2120 FAX (916) 227-4530 • Internet Address: http://www.swrcb.ca.gov/~cwphome/ustcf



FEB 1 6 2000

L1:7 kd L183100

P O Box 3090 7 10310 7 1084

Berkeley, CA 94703

UNDERGROUND STORAGE TANK CLEANUP FUND, CLAIM NO. 014764, FOR SITE ADDRESS: 489 43RD ST, OAKLAND

The State Water Resources Control Board (State Board) is able to issue, pursuant to applicable regulations, the enclosed Letter of Commitment (LOC) in an amount not to exceed \$15,000. This LOC is based upon our review of the corrective action costs you reported to have incurred to date. The LOC may be modified by the State Board.

It is very important that you read the terms and conditions listed in the enclosed LOC. Claims filed with the Underground Storage Tank Cleanup Fund far exceed the funding available and it is very important that you make use of the funding that has been committed to your cleanup in a timely manner.

You are reminded that you must comply with all regulatory agency time schedules and requirements and you must obtain three bids for any required corrective action. Only corrective action costs required by the regulatory agency to protect human health, safety and the environment can be claimed for reimbursement. Unless waived in writing, you are required to obtain preapproval of costs for all future corrective action work (form enclosed). If you have any questions on obtaining preapproval of your costs or the three bid requirement, please call Mark Owens, our Technical Reviewer assigned to claims in your Region, at (916) 227-7883. Failure to obtain preapproval of your future costs may result in the costs not being reimbursed.

The following documents needed to submit your reimbursement request are enclosed: .

"Reimbursement Request Instructions" package. Retain this package for future reimbursement requests. These instructions must be followed when seeking reimbursement for corrective action costs incurred after January 1, 1988. Included in the instruction package are samples of completed reimbursement request forms and spreadsheets.

"Bid Summary Sheet" to list information on bids received which must be completed and returned.

"Reimbursement Request" forms which you must use to request reimbursement of costs incurred

"Spreadsheet" forms which you must use in conjunction with your reimbursement request.

* THIS IS IMPORTANT TO YOU, PLEASE NOTE:

You have 90 calendar days from the date of this letter to submit your first reimbursement request for incurred corrective action costs. NO EXTENSIONS CAN BE GRANTED. If you fail to do so, your LOC funds will automatically be reduced to zero (deobligated). Once this occurs, any future funds for this site are subject to availability when you submit your first reimbursement request. We continuously review the status of all active claims. You must continue to remain in compliance and submit a reimbursement request every 6 months. Failure to do so will result in the Fund taking steps to withdraw your LOC.

If you have any questions regarding the enclosed documents, please contact Anna Torres at (916) 227-4388.

Sincerely,

Bave Deaner, Manager UST Cleanup Fund Program

Enclosures

cc: Mr. Steve Morse RWQCB, Region 2 1515 Clay Street, Ste. 1400 Oakland, CA 94612

> Mr. Thomas Peacock Alameda County EHD 1131 Harbor Bay Pkway, 2nd Fl. Alameda, CA 94502-6577

ALAMEDA COUNTY **HEALTH CARE SERVICES**



DAVID J. KEARS, Agency Director

December 2, 1999 StID #5552

Mr. Ronn Simpson P.O. Box 3090 Berkeley, CA 94703

ENVIRONMENTAL HEALTH SERVICES ENVIRONMENTAL PROTECTION 1131 Harbor Bay Parkway Alameda, CA 94502-6577 (510) 567-6700 (510) 337-9432

Re: Soil and Groundwater Investigation at 489 43rd St., Oakland CA 94609

Dear Mr. Simpson:

Thank you for the submittal of the Weiss Associates November 29, 1999 Well Installation and Sampling report for your property referenced above. As you are aware, this report describes the installation of a monitoring well (MWA-1) in the rear of this property in the down-gradient direction of the tank on your property as well as those on 490 43rd St. Both soil and groundwater samples were taken during the installation of the well. Results of chemical analysis indicate low levels of gasoline, paint thinner and BTEX (gasoline components). The soil sample taken from the boring did not detect any petroleum hydrocarbons. This indicates that the contamination from the paint thinner tank from 490 43rd St. has migrated nearly 150 feet from its release. The gasoline detected may be from either of the sites.

Should these concentrations remain consistently low as during this sampling event, site conditions should be shown to be consistent with a low risk groundwater site. The results of sampling this well should be considered along with the results of sampling from the Blumert site since the releases are undoubtedly commingled. Your consultant should attempt to sample this well when the Blumert site wells are sampled. Groundwater elevations should also be taken at the same time, along with a combined map. I understand that the next monitoring event for the Blumert site will occur in December 1999. It is also assumed that the pending re-excavation of the tank pit will decrease groundwater concentrations that are migrating beneath your site.

You may contact me at (510) 567-6765 if you have any questions.

Sincerely,

Barney M. Chan

Hazardous Materials Specialist

Barney Ullan

C B Chan, files

Ms M Chamberlin, Weiss Associates, 5801 Christic Ave., Suite 600. Emergyille, CA 94608-1827

Mr. D Dement, ACC, 7977 Capwell Dr, Suite 100, Oakland CA 94621

Mon489 43rd

ALAMEDA COUNTY ENVIRONMENTAL HEALTH / HAZARDOUS MATERIALS DIVISION 1131 HARBOR BAY PKWY., RM. 250, ALAMEDA, CA 94502-6577 (510)567-6700 FAX (510) 337-9355

HAZARDOUS WASTE GENERATOR INSPECTION REPORT

· · · · · · · · · · · · · · · · · · ·	
STID#: SSS2 FACILITY NAME: ROM SIMM	PG. OF
SUPPLEMENTAL FORM AND SUPPLEMENTAL FORM AND SUPPLEMENTAL FORM AND SUPPLEMENTAL FORM	-d St
Observe the installation	of I-WW in near
Yard Well 10: 20' on	depte & screened from
Yard Weel is: 20' on 10-20! Will attempt.	to access Blunet wells
to take water elevations	dung sangle
Well is located in anistrar	deux samples as requested
of indicated in wp	
M. Ziminera Spyce Grego Drillers - well inst	Worsi Assec
Grego Drillers - well inst	talloi
· · · · · · · · · · · · · · · · · · ·	
Note: Warest Lop out	e 10 # 5774 (Closed) Ave
@ 4900 Telograph	Ave
<i>y y</i>	
PRINT NAME	INSPECTED BY CLARY
SIGNATURE	DATE () True for St
SCN/SUPPRIPE(REV. 7/94) INS /FCO	

HEALTH CARE SERVICES





ENVIRONMENTAL HEALTH SERVICES **ENVIRONMENTAL PROTECTION** 1131 Harbor Bay Parkway, Suite 250

Alameda CA 94502-6577 (510) 567-6700 FAX (510) 337-9335

October 7, 1999 StID # 5552

Mr. Ronn Simpson P.O. Box 3090 Berkeley, CA 94703

Re: Proposed Over-excavation and ORC Addition for 489 43rd St., Oakland CA 94609

Dear Mr. Simpson:

Our office has received and reviewed the October 1, 1999 Weiss Associates work plan for the over-excavation and subsequent addition of ORC (oxygen releasing compound) into the former underground tank at the above referenced site. These actions are meant to remove contaminated soils from the pit and increase the oxygen concentration in groundwater. The addition of ORC will supplement the ORC injections performed by Walter Blumert site at 490 43rd St.

This work plan is approved with the following conditions:

- Please insure that the excavation does compromise the recently installed Walter Blumert well, MW-4, located near the former tank pit.
- The sidewall samples collected after over-excavation should be taken above groundwater and analyzed for TPH as gasoline, TPH as diesel and TPH as mineral spirits, BTEX and MTBE.
- Please schedule the monitoring well installation either prior or concurrent to this work.

You may contact me at (510) 567-6765 if you have any questions.

Sincerely,

Barney M Che Barney M. Chan

Hazardous Materials Specialist

C: B. Chan, files

Ms. M. Chamberlin, Weiss Associates, 5801 Christie Ave . Suite 600. Emeryville, CA 94608 Mr J Ward, Wells Fargo Trust, P O Box 63939, San Francisco, CA 94163

2wpap489 43rd

HEALTH CARE SERVICES

AGENCY



DAVID J. KEARS, Agency Director

ENVIRONMENTAL HEALTH SERVICES

1131 Harbor Bay Parkway, Suite 250 Alameda, CA 94502-6577 (510) 567-6700 (510) 337-9335 (FAX)

15.

September 28, 1999 StID # 5552

Ms. Melissa Chamberlain Weiss Associates 5801 Christie Ave., Suite 600 Emeryville, CA 94608-1827

Re: Monitoring Well Installation at Mr. Ronn Simpson Property, 489 43rd St., Oakland CA 94609

Dear Ms. Chamberlin:

This letter responds to Weiss Associates' September 24, 1999 letter to our office. Your accompanying figure noted the actual location of the proposed well on this site, as opposed to the figure originally submitted. Please be aware that the figure that I provided and which Weiss reproduced in their letter is my rendition and is not an actual to scale drawing. Please provide an accurate to scale drawing on your future figures.

In regards to your request for information on the survey reference point for the Walter Blumert site wells, please be aware that, according to the Kapraelian Engineering June 2, 1993 report, the elevation of the tops of the well covers were surveyed to MSL relative to the City of Oakland Benchmark #2859. Please confirm that these elevations are truly to MSL, as the City of Oakland Benchmark are not typically surveyed to MSL. Obviously, the new well should be surveyed similarly to the Blumert wells so groundwater elevations are comparable. You are reminded to contact me prior to well installation.

You may contact me at (510) 567-6765 if you have any questions.

Sincerely,

Barney M. Chan

Hazardous Materials Specialist

Bainey Melic

C B Chan, files

Mr R Simpson, PO Box 3090, Berkeley, CA 94703

the 11489 43rd

HEALTH CARE SERVICES





DAVID J. KEARS, Agency Director

September 14, 1999 StID # 5552

Mr. Ronn Simpson P.O. Box 3090 Berkeley, CA 94703 **ENVIRONMENTAL HEALTH SERVICES** 1131 Harbor Bay Parkway, Suite 250 Alameda, CA 94502-6577 (510) 567-6700

(510) 337-9335 (FAX)

Re: Monitoring Well Installation Work Plan for 489 43rd St., Oakland CA 94609

Dear Mr. Simpson:

Our office has received and reviewed the September 1, 1999 work plan for the installation of one monitoring well at the above site. This well is intended to determine the limits of the soil and groundwater contamination from the former underground tank at this site. Additionally, it may also indicate the extent of the fuel release from 490 43rd St. (Walter Blumert Co.). Please be aware that the proposed well location is not where we discussed. It is too close to the former underground tank and would not likely be able to determine the extent of the contamination. As previously discussed, a better location for the well is in the rear driveway behind the building. Enclosed, please find an appropriate location designated "preferable location". I have also shown the location of monitoring well MW4, the well recently installed by the Walter Blumert Co. Please verify that this preferred location is acceptable to you. In all future reports please provide the footprint of the existing buildings and driveways for reference.

Our office also requests that this new well be surveyed to the same reference point as the four Blumert wells, so a consistent groundwater elevation and gradient map can be obtained for both sites. As you may be aware, the Blumert site also installed numerous borings in 43rd St. between the two sites and injected oxygen-releasing compound (ORC) into these borings. The effect of this should increase the dissolved oxygen content and bio-degradation of petroleum in groundwater. Therefore, our office requests that in addition to the chemical analysis prescribed in your work plan, please run the parameters dissolved oxygen and oxidation-reduction potential on your groundwater sample prior to sampling. Please install your well, within 45 days or no later than November 1, 1999.

Be aware that additional remediation will also likely be required in the former underground tank pit area. Either tank pit over-excavation or installation of a remediation well within the former pit should be considered. This assumes that the ORC borings already advanced will not be sufficient to treat the fuel release from the former tank on your property. Please contact me at (510) 567-6765 if you have any comments or questions.

Sincerely,

Barney M. Chan.

Hazardous Materials Specialist

Millian, dribba

c B Chan, files

Ms. M. Chamberlin, Weiss Associates, 5801 Christic Ave., Suite 600, Emeryville, CA 94608-1827

тимрар489 43






Figure 2 Soil Boring Location - 489 43rd Street, Oakland, California

HEALTH CARE SERVICES





DAVID J. KEARS, Agency Director

ENVIRONMENTAL HEALTH SERVICES 1131 Harbor Bay Parkway, Suite 250 Alameda, CA 94502-6577 (510) 567-6700 (510) 337-9335 (FAX)

July 15, 1999 StID # 5552

Mr. Ronn Simpson P.O. Box 3090 Berkeley, CA 94703

NOTICE OF VIOLATION

Re: Work Plan for Additional Investigation at 489 43rd St., Oakland CA 94609

Dear Mr. Simpson:

Our office requested that you submit a work plan for the installation of one monitoring well in my November 19, 1998 letter. This followed my on-site meeting with you and your consultant on October 1998. It was decided that a reasonable approach to investigate your site was the installation of one monitoring well in the rear of this site and either over-excavation of the tank pit or the installation of an extraction well within it.

Your work plan was requested to be submitted to our office by December 21, 1998. We have yet to receive this work plan. As you are aware, work is scheduled for the installation of a monitoring well and borings for the Blumert site at 490 43rd St. Your investigation is required to compliment their investigation since the petroleum releases from these sites is not distinguishable.

Please submit a work plan for your monitoring well installation within 30 days and schedule its installation within an additional 30 days or by September 15, 1999. Your delay in compliance will jeopardize your eligibility to Cleanup Fund reimbursement and subject you to potential civil liability.

You may contact me at (510) 567-6765 if you have any questions.

Sincerely,

Barney M Chan

Hazardous Materials Specialist

Fairey M Cho

C B Chan, files

Mr P Nuti, Weiss Associates, 5500 Shellmound St., Emeryville, CA 94608-2411 Mr D Dement, ACC Environmental, 7977 Capwell Dr., Suite 100, Oakland 94621

NOV 489 43rd

ALAMEDA COUNTY ENVIRONMENTAL HEALTH / HAZARDOUS MATERIALS DIVISION 1131 HARBOR BAY PKWY., RM. 250, ALAMEDA, CA 94502-6577 (510)567-6700 FAX (510) 337-9355

HAZARDOUS WASTE GENERATOR INSPECTION REPORT

STID#: FACILITY NAME: FACILITY NAME: SIMPSON 489-43-2 STIDBLEMENTAL BORM
SOLI EENILATAL FORM
Met with Mr Simpson and Paul Nuti of Weiss at lite. Discussed the work plan for 490 2489 43 od St Option's discussed:
Tie with Misimpson and Tunk Water 9 wests at the
Discussed The work plan for 490 2489 43rd ST
Option's decensed:
· the over excavation of tank pit
· the addition of old with tank backfull
· Installation of 1 mw in plan parking are a NOT NOCKERS
· The addition of ope into tank buchfull · Installation of I move in Man parking are a NOT NECESSAME. Lichard site.
- GALDERALD Massing to sail to Charle For a
- Recommend that they and a sporily law tank nit
Recommend that they analyze spoils from tank pit. Counder installing an extraction well into tank pit after averex awatur
after averexcavaturi
P. Nuti remmand enstabling well first before over-
excavatu y tak pit.
Very cerfined area. Former tenlar are ~35-40' apart
Thousand of the Street.
The mineral spirit release from Aliment site is
definitel minitere como the street work to 489-43ml
- Wiess will descis options + provide a W.P.
weeks well asless options + provide a W.p.
PRINT NAME INSPECTED BY RECTED BY RECTED BY
SIGNATURE DATE /0/20198
GEN/SUPP RPTG RFV 7/94: JNS /ECO

HEALTH CARE SERVICES





DAVID J. KEARS, Agency Director

November 19, 1998 StID # 5552

Mr. Ronn Simpson P.O. Box 3090 Berkeley, CA 94703 **ENVIRONMENTAL HEALTH SERVICES ENVIRONMENTAL PROTECTION (LOP)** 1131 Harbor Bay Parkway, Suite 250 Alameda, CA 94502-6577 (510) 567-6700 FAX (510) 337-9335

Re: Work Plan for Additional Subsurface Investigation at 489 43rd St., Oakland CA 94609

Dear Mr. Simpson:

This letter serves to summarize my meeting on-site with you and Mr. Paul Nuti of Weiss Associates on October 20, 1998. We discussed the work needed to achieve site closure. We also discussed the problem that exists when an additional source of contamination migrates and mixes with another release as has occurred in this case. I contend that it is extremely difficult to proportion the amount of contamination coming from each site and where the overlap of contamination starts. This question may not be settled until it is brought to court, at which time an independent arbitrator would render a decision.

My suggestion is to have both sites, 490 and 489 43rd St., work together to investigate the releases and hopefully the sites can use the same investigation and remediation approach which would lead to closure of both sites. To this end, we discussed what could be done on your site. It was concluded that over-excavation of the former tank pit and the installation of one monitoring well in the rear parking lot of your site was a reasonable investigation approach. We also mentioned the option of installing an extraction well within the former tank pit and/or the addition of oxygen releasing compound within the pit to enhance natural bio-degradation. Mr. Nuti suggested that the installation of the well be done first to see if the extent of groundwater contamination could be found. I agreed with this suggestion. As you may be aware, the Blumert site was requested to provide a work plan consisting of installing and sampling borings, adding oxygen releasing compound (ORC) into these borings and installing an off-site monitoring well.

We further suggested that you apply to the Underground Storage Tank Cleanup Fund (Cleanup Fund) to see if some of your investigation and remediation expenses could be reimbursable. You may contact the Fund at 1-800-813-3863.

Please submit an appropriate work plan for the above-mentioned investigation at your site within 30 days or by December 21, 1998. You may contact me at (510) 567-6765 if you have any questions.

Sincerely,

Barney M. Chan, Hazardous Materials Specialist

C B Chan, files

Mr. P Nuti, Weiss Associates, 5500 Shellmound St, Emervville, CA 94608-2411 Mr D. Dement, ACC Environmental Consultants, 7977 Capwell Dr., Suite 100,

> Oakland CA 94621 wpra489

HEALTH CARE SERVICES

AGENCY



DAVID J. KEARS, Agency Director

ENVIRONMENTAL HEALTH SERVICES ENVIRONMENTAL PROTECTION (LOP) 1131 Harbor Bay Parkway. Suite 250 Alameda, CA 94502-6577 (510) 567-6700 FAX (510) 337-9335

October 9, 1998 StID # 5552

Mr. Ronn Simpson P.O. Box 3090 Berkeley, CA 94703

Re: Subsurface Investigation at 489 43rd St., Oakland CA 94609

Dear Mr. Simpson:

Due to the continual re-organization of our office, I have been assigned the oversight duty for the above referenced site as well as the site across the street, 490 43rd St. aka the Blumert Trust site. Our office regrets any discontinuity this re-organization may have caused. I have reviewed the site history of both properties. I have concluded that, although there is a likelihood that the groundwater contaminant plume from the Blumert site has migrated and impacted the above referenced site, there is also clear evidence that a separate release of petroleum hydrocarbon has occurred from the underground tank from this property. This evidence consists of:

- Observed holes in the tank when the tank was removed
- Observed contaminated soil beneath the former tank
- The detection of the contaminants; total petroleum hydrocarbons as diesel and MTBE in soil, contaminants not expected to have come from the Blumert site. The diesel concentration in the soil sample from this site is higher than that found in samples near the tanks on the Blumert site, indicating separate releases.

There is, however, evidence that the petroleum plume from the Blumert site has impacted this site. This evidence consists of:

- Grab groundwater results from borings in 43rd St., down-gradient of the Blumert underground tanks detected elevated gasoline and paint thinner concentration.
- The grab groundwater sample from the boring advanced down-gradient of the 489 43rd St. tank also exhibited elevated paint thinner as well as gasoline concentrations.

Given this information, there is, likely, commingling of the each site's release. There is not enough information to estimate the proportion of the release being detecting on this site which may be coming from off-site. Nevertheless, both sites must complete the characterization of their site. It is clear that the Blumert site has performed considerable investigation and continues to provide a work plan to investigate and remediate their site

At a minimum, you are requested to install a permanent monitoring well down-gradient of the former UST at 489 43rd St and advance several additional temporary borings to determine the extent of the groundwater plume. You should also consider the addition of oxygen releasing

Mr. Ronn Simpson StID # 5552 489 43rd St., Oakland 94609 October 9, 1998 Page 2.

compound and/or any other necessary supplement to augment the oxygen supplement which will be added to the Blumert site. To this end, you should also test the installed well for the biodegradation parameters; dissolved oxygen, oxidation-reduction potential, alkalinity, nitrate, sulfate and ferrous iron. The monitoring well sample should be analyzed for total petroleum hydrocarbons as gasoline, as diesel and as paint thinner, BTEX (benzene, toluene, ethyl benzene, and xylenes), MTBE and soluble lead.

Please submit your work plan for the installation of one monitoring well and the advancement of several temporary borings at your site within 30 days or by November 10, 1998.

Our office encourages you to work with the Blumert Trust and Wells Fargo Trust who are handling the affairs of the Blumert Trust. Their contact is Mr. John Ward (415) 396-3019. In addition, Mr. Ken Cheitlin Esq has been retained to advise Well Fargo Trust on legal matters. To this end, I will copy correspondence to each party to keep them aware of what is happening on both sides.

You may contact me at (510) 567-6765 if you have any questions.

Sincerely,

Barney M. Chan

Hazardous Materials Specialist

Baney M Cha_

C: B. Chan, files

Mr. P. Nuti, Weiss Associates, 5500 Shellmound St., Emeryville, CA 94608-2411 Mr. John Ward, Wells Fargo, 420 Montgomery St., 3rd Floor, P.O. Box 63939,

San Francisco, CA 94163

Mr. Ken Cheitlin Esq., McShane, Schnack & Cheitlin, 2033 N. Main St., Suite 700, Walnut Creek, CA 94596

Mr. D. Dement, ACC Environmental Consultants, 7977 Capwell Dr., Suite 100, Oakland CA 94621

489-43rd

LOP - RECORD CHANGE REQUEST FORM

printed: 10/06/98

Mark Out What Needs Changing and Hand to LOP Data Entry (Name/Address changes go to Annual Programs Data Entry)

Insp: BC

AGENCY # : 10000 SOURCE OF FUNDS: F SUBSTANCE: 8006619

: 5552 LOC:
SITE NAME: Ronn Simpson
ADDRESS DATE REPORTED : 09/18/95 DATE CONFIRMED: 09/18/95 MULTIPLE RPs : N ADDRESS: 489 43rd St

94609 CITY/ZIP : Oakland

> SITE STATUS _____

CASE TYPE: S CONTRACT STATUS: 4 PRIOR CODE: 2A4 EMERGENCY RESP:

RP SEARCH: S

PRELIMINARY ASMNT: DATE UNDERWAY: DATE COMPLETED:
REM INVESTIGATION: DATE UNDERWAY: DATE COMPLETED:
REMEDIAL ACTION: DATE UNDERWAY: DATE COMPLETED:
POST REMED ACT MON: DATE UNDERWAY: DATE COMPLETED:

ENFORCEMENT ACTION TYPE: 2 LUFT FIELD MANUAL CONSID:

CASE CLOSED: DATE CASE CLOSED:

DATE EXCAVATION STARTED : REMEDIAL ACTIONS TAKEN:

RESPONSIBLE PARTY INFORMATION

DATE ENFORCEMENT ACTION TAKEN: 08/20/96

RP#1-CONTACT NAME: Ronn Simpson

COMPANY NAME: Ronn Simpson ADDRESS: P. O. Box 3090

CITY/STATE: Berkeley, C A 94703

		INSPECTOR VERIFICATION	ON:
NAME	<u></u>	SIGNATURE	DATE
Name/Address	Changes Only	DATA ENTRY INPUT:	Case Progress Changes
ANNPGMS	LOP	DATE	LOP DATE

of Alameda County

ERROR LIST OF DEPOSIT REFUND WORK RECORDS PLEASE INVESTIGATE AND CORRECT IN DAILIES for Tom Peacock

printed 09:11/98 pg 5

Pro_N Insp ActivDat Hours S Rate Earned Activity & Description / COMMENT *ERROR CODE:1 STID -0- Site#: 6 Business:-:-TP 06/17/98 1. 94.00 94. 79-Plan, Organize, Implement Pgm Comment-City of Fremont, Mission Blvd., drug bust STID:-0- Site#: 6 Business:-0-ΤP 05/21/98 1 94 00 94. 79-Plan, Organize, Implement Pqm. Comment-GSA w/Rod Freitag assign to SOS 66 ΨP 06/04/98 0.9 94.00 79-Plan, Organize, Implement Pgm. Comment-w/w/RW, what, when needs permits *ERROR CODE:2 STID:6852 Site#:-0- Business:-0--0-TP 06/26/98 0.4 94.00 37.6 77-Meetings, Consultations Comment-w/Saul Germanus for ML 06 *ERROR CODE:3 STID: 337 Site#: 169 Business:Golden State Linen Service 958 28th St Oakland CA 94608 169A TP 06/29/98 0.4 94.00 37.6 77-Meetings, Consultations Comment-w/Dick Herring w/SH Total Charges on 5 errored entries for 3.7 hours is \$347.80. DepRef Error Report Complete for Tom Peacock _ _ _ _ _ _ 1 = StID missing - need one
2 = StID/Proj# pair is not found in DepRef Database
3 = DepRef DB shows no more money. Investigate: see L.Peters. ERROR CODES:

GRAND TOTAL CHARGES FOR ERROR REPORT for \$1,950.80 from 14 entries. printed 09/11/98 20. hours is Report DRErrors Complete (Rev 6/97)

change ude tor non-

ALAMEDA COUNTY HEALTH CARE SERVICES

AGENCY

DAVID J. KEARS. Agency Director



To: Jerry Mc Hugh Weiss Associates ENVIRONMENTAL HEALTH SERVICES ENVIRONMENTAL PROTECTION 1131 Harbor Bay Parkway. Surte 250 Alameda CA 94502-6577 (510) 567-6700 FAX (510, 337-9336

RE: Ronn Simpson Property 2 489 - 43vd St. Oakland WA Job # 138-1231-01

DATE: 3/16/98

I just spoke with Mr. Simpson, proporty owner. Said the workplan dated 9/18/96, prepared by Weiss was not implemented because no approval letter was received by him from Alameda County. Also said Tom Fogut of weiss told him your company did not receive approval letter. Here is a copy of a letter written by Dale Keetke of my Office. I also faxed a copy to Mr. Simpson + told him it is necessary to implement the workplan with Dale's input integrated into the plan. This fax is FYI + for your file.

Thank you

1/100 1/1005

\ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \		1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1			Real Control	
Who of		MREOTY	EDENIČU	DAKING		
B. W.		HIDEK	ORDI	'BAKING ER	CO.	
Ch h	Bust	talia	No.	57 22.Jr	1. 11.7	4. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1.
194a	Name.	ltem	Weight	Returnel	Sold	
		Long Sticks	1 lb		à,	
Elst.	32 30	Long French	1 lb			/
21	139 139	Long French	1½ lb		\	
12	The state of the s	Long French		7	E,	
Ag.	89 80	Round "	1½ lb			
the s		Wine Ciucci	1 lb			
I I		Ciucci	1½ lb			
13 0)		Ciucci Long	11/2 lb			
the 105						
& Ke		Long Imm't Seed	1 lb			
n e	23	Long Imm't	1 lb	\\		
	235 201	Round "	1 16		91	12
)	47 47	Round "	1½ lb			
		Milk Seed	1 lb			
		Twist	1 16			
	,	Greek	1 lb			
		Stick Italian Michette	7 lb	· 		10.00
	1 1 1	Michette D.B.	1 16	- 	* ,	
(Round D. Break	11/2 lb		-	
) X M	Top To	4.				
163 2	7000		1			
13 3°		With Wheat Stick	s 1 lb	,		
18 4 W.D.		Rve	1 lb			
DA St			1 lb			
		Wine Slice	1 lb			
a hay	15	Brown and Serve	i i	_	1,	
g & gas			*			
20	<u> </u>	Doz. Lg. Sour Bu	 		W	
	76 78	Doz. (a. Sy. Bull	Rolls Pka			1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1
~ · · · · · · · · · · · · · · · · · · ·	19 14	Do Sm Rolls Bu	ılk			
6		1/2 Noz. Sm. Roll				
2	30+7	Pan Rolls Sesame	DUIK		2.	The way
- •			1		×0.	
			, 5.	<u> </u>	· B	
	- 24					
			, 'W.		4	463
			1			

HEALTH CARE SERVICES

AGENCY



DAVID J. KEARS, Agency Director

March 16, 1998

Ronn Simpson P.O. Box 3090 Berkeley CA 94703 ENVIRONMENTAL HEALTH SERVICES ENVIRONMENTAL PROTECTION 1131 Harbor Bay Parkway. Suite 250 Alameda, CA 94502-6577 (510) 567-6700 FAX (510) 337-9335

RE: Investigative Work Plan for 489 43rd St., Oakland 94609 (Our site # 5552)

Dear Mr. Simpson:

As a follow up to our telephone conversation today, I am sending the enclosed copy of Dale Klettke's letter approving the Investigative Work Plan for your site. The Work Plan was submitted by Weiss Associates and dated September 18, 1996. Dale Klettke's letter is dated October 7, 1996.

The Plan proposes to advance one soil boring in a down gradient direction from the former tank excavation. The boring will be advanced to groundwater, with soil samples collected at least every five feet for lithologic description and evaluation for possible laboratory analysis. A "grab" groundwater sample will be collected. Please implement Mr. Klettke's stipulation that MTBE (methyl-tertiary-butyl ether) be included among the compounds for analysis from both the soil and groundwater samples.

The Work Plan should be carried out within the next 45 days. I will expect a copy of the investigation report by June 15, 1998. You may contact me at (510)567-6770 with any questions about this letter.

Sincerely,

Pamela J. Evans

Senior Hazardous Materials Specialist

Camela J wans

eaclosure

c: Dick Pantages, Alameda County Environmental Health Services / Files-Jerry McHugh, Weiss Associates

HEALTH CARE SERVICES

AGENCY



DAVID J. KEARS, Agency Director

STID 5552

October 7, 1996

Mr. Ronn Simpson P. O. Box 3090 Berkeley, CA 94703 ENVIRONMENTAL HEALTH SERVICES ENVIRONMENTAL PROTECTION (LOP) 1131 Harbor Bay Parkway, Suite 250 Alameda, CA 94502-6577 (510) 567-6700 FAX (510) 337-9335

RE: INVESTIGATIVE WORKPLAN FOR 489 - 43RD STREET, OAKLAND, CA 94609

Dear Mr. Simpson:

This office is in receipt of and has completed review of the case file for this site, up to and including the Weiss Associates (WA) "Investigative Workplan" dated September 18, 1996.

The WA work plan proposes to advance one soil boring, in a down-gradient direction from the former UST excavation, to an approximate depth of 11 feet below ground surface (bgs). Soil samples will be collected at least every 5 feet, and a "grab" groundwater sample will be collected from the boring.

Selected soil samples will be analyzed for TPHg, BTEX and TPHpt (paint thinner). The "grab" groundwater sample will be analyzed for TPHg, BTEX, TPHpt and MTBE.

The workplan is approved with the following stipulation that soil samples also be analyzed for methyl-tert-butyl ether (MTBE).

Please call me at 510/567-6880 should you have any questions.

Sincerely,

Dale Klettke, CHMM

Hale Elette

Hazardous Materials Specialist

Thomas Peacock, LOP Manager--files
 Tom Fogut, Weiss Associates, 5500 Shellmound Street, Emeryville, CA 94608-2411
 5552wpok psa

ALAMEDA COUNTY HEALTH CARE SERVICES

AGENCY DAVID J. KEARS, Agency Director



RAFAT A. SHAHID, Assistant Agency Director

DEPARTMENT OF ENVIRONMENTAL HEALTH 80 Swan Way, Rm. 210 Oakland, CA 94621 (510) 271-4300

STID 5552

August 20, 1996

Mr. Ronn Simpson P. O. Box 3090 Berkeley, CA 94703

"NOTICE OF VIOLATION"

RE: UST REMOVAL AT 489 - 43RD STREET, OAKLAND, CA 94609

Dear Mr. Simpson:

This letter serves to follow-up to a Alameda County Health Care Services Agency (ACHCSA) letter from myself dated January 10, 1996. In this letter you were requested to submit-a work plan to perform a preliminary site assessment within 90 days. No work plan has been received by this office. A copy of this letter is enclosed for your review.

A confirmed release from the UST(s) has occurred at this site. The extent of petroleum hydrocarbon contamination is not adequately defined. Pursuant to provisions of Article 11, Title 23, California Code of Regulations (CCR), you are required to perform a preliminary site assessment (PSA) when a confirmed release from an UST has occurred. To facilitate this task, a PSA work plan must be submitted for review. This work plan is due within 30 days of the date of this letter, or no later than September 20, 1996.

Please be advised that this letter constitutes a formal request for technical reports pursuant to California Water Code Section 13267(b) and Health and Safety Code Sections 25299.37 and 25299.78.

Please call me at 510/567-6880 should you have any questions.

Sincerely,

Dale Klettke, CHMM

Hazardous Materials Specialist

Tale Kluther

enclosure

Thomas Peacock, LOP Manager--files
 Gil Jensen, Alameda County District Attorney's Office
 Tom Fogut, Weiss Associates, 5500 Shellmound St., Emeryville, CA 94608-2411



ACCUTITE Environmental Engineering

St South Linden Avenue, South San Francisco, CA 94080

Certification No.

95-03-002-8

Good Thru: 24 MAR 98

Joan A. Cellaglan

The formula instructory instructory.

- 184

Hazardous Waste Operations and Emergency Response

Certification of Completion and Current Compliance with 29 CFR 1910.120 Issued to:

Willie Green

Fight Hours Annual Refresher see dates on back 95-03-002-

ALAMEDA COUNTY **HEALTH CARE SERVICES**

AGENCY

DAVID J. KEARS, Agency Director



ARNOLD PERKINS, DIRECTOR

RAFAT A. SHAHID, DEPUTY DIRECTOR

STID 5552

January 10, 1996

Mr. Ronn Simpson P. O. Box 3090 Berkeley, CA 94703 DEPARTMENT OF PUBLIC HEALTH 499 Fifth Street Oakland, California 94607 (510)

UST REMOVAL AT 489 - 43RD STREET, OAKLAND, CA 94609 RE:

Dear Mr. Simpson:

The results of sample analysis and observations documented by Accutite during the September 1995 closure of one (1) 1000-gallon gasoline underground storage tank (UST) have been evaluated.

On September 18, 1995, Accutite removed the 1000-gallon UST which formerly contained regular (leaded) gasoline. After the UST removal, a total of four soil samples were collected. Soil sample GAW-1-10.5' was collected from the west end, approximately 10.5' below surface grade (approximately one foot below the bottom of the UST). Soil sample GAE-1-11' was collected from the east end, approximately 11' bgs. Soil sample GAM-1-13' was collected from the middle, approximately 13' bgs. Soil sample STOK-1 was collected from the soil stockpile generated from the UST removal. Laboratory analysis of soil samples collected from beneath the UST detected maximum concentrations of TPHg-1900 ppm*, TPHd-1300 ppm*, benzene-0.2 ppm, toluene-0.46 ppm, ethyl benzene- 17 ppm*, total xylenes-48 ppm* and MTBE-1300 ppm* < No 1.6 ppm Note: The asterisk* denotes concentrations detected in the sample collected from beneath the middle of the UST (sample GAM-1-13'). No groundwater was encountered in the UST pit.

A confirmed release from the UST(s) has occurred at this site. The extent of petroleum hydrocarbon contamination is not adequately defined. Pursuant to provisions of Article 11, Title 23, California Code of Regulations (CCR), you are required to perform a preliminary site assessment (PSA) when a confirmed release from an UST has occurred. To facilitate this task, a PSA work plan must be submitted for review. This work plan is due within 90 days of the date of this letter.

A report must be submitted within 45 days of the completion of field activities associated with this phase of work at the site. The referenced reports must describe the status of the investigation and include, among other elements, the following

Details and results of all work performed during the designated reporting period records of field observations and data, boring and well construction logs, water level data, chain-of-custody forms, laboratory results for all samples collected and analyzed (including QA/QC data), tabulations of free product thicknesses and dissolved fractions, etc

Mr. Ronn Simpson

RE: 489 43rd Street, Oakland

Page 2 of 2

- Status of ground water contamination and characterization.
- Interpretation of results: water level contour maps showing gradients, free and dissolved product plume definition maps for each target compound, geologic cross sections, etc.
- Recommendations for additional work.

Pursuant to provisions of the Business and Professions Code all work and reports which require geologic or engineering evaluations and/or judgements must be performed under the direction of an appropriately registered or certified professional. Therefore, all proposals must be submitted under seal of a California-registered geologist or civil engineer with the appropriate environmental background. Please include a statement of qualifications for each lead professional involved with this project.

Please be advised that this letter constitutes a formal request for technical reports pursuant to California Water Code Section 13267(b).

For your information, the Underground Storage Tank Cleanup Fund (Fund) is created pursuant to Chapter 6.75 of the California Health & Safety Code to help eligible owners and operators of petroleum underground storage tanks obtain reimbursement for costs of the cleanup of unauthorized releases of petroleum. You are encouraged to contact the SWRCB fund representative (916/227-4529) for more case-specific information and to obtain an application package. Please also bear in mind that, in order to maintain UST clean-up fund eligibility, specific bidding requirements and contracting criteria must be met.

Please call me at 510/567-6880 should you have any questions.

Sincerely,

Dall Klittle

Dale Klettke, CHMM

Hazardous Materials Specialist

Thomas Peacock, LOP Manager--files

Gil Jensen, Alameda County District Attorney's Office

Sami Maleab, Accutite, 35 So Linden Ave, S San Francisco, CA 94080

3994psal dkt

C.

Address: 489 - 43rd St Address: 260 Michele Ct

Address: 260 Michele Ct City: S San Francisco CA Zip: 94080

City: Oakland Zip: 94609 City: Contact: Contact:

Phone #: Phone #: 415/952-5551

Code: 1

Unauthorized Release? (y/n) Receipt #'s: 759006

Date Site Complete: / Type List:

Payor Links: 388-a T,R

Type: DATE DEP PROJ# DATE: RCPT#: CHECK #: \$AMOUNT R.I.M #TANKS COMPLETE

\$AMOUNT R,I,M RCPT#: CHECK #: **#TANKS COMPLETE** INSP 3306A 05/24/95 759006 1864 603.00 1 09/19/95 R CL 3306A T 09/19/95 CL

LOP - RECORD CHANGE REQUEST FORM

printed: 11/17/95

Mark Out What Needs Changing and Hand to LOP Data Entry (Name/Address changes go to Annual Programs Data Entry)

Insp: DK

AGENCY # : 10000 SOURCE OF FUNDS: F SUBSTANCE: 8006619

: 5552 StID LOC:

SITE NAME: Ronn Simpson DATE REPORTED: 09/18/95 DATE CONFIRMED: 09/18/95 ADDRESS: 489 43rd St

CITY/ZIP : Oakland 94609 MULTIPLE RPs : N

SITE STATUS

CASE TYPE: S CONTRACT STATUS: 4 PRIOR CODE: 2A4 EMERGENCY RESP:

RP SEARCH: S DATE COMPLETED: 09/19/95

DATE UNDERWAY: DATE UNDERWAY: PRELIMINARY ASMNT: DATE COMPLETED: REM INVESTIGATION: DATE COMPLETED: DATE UNDERWAY: DATE COMPLETED: REMEDIAL ACTION: POST REMED ACT MON: DATE UNDERWAY: DATE COMPLETED:

ENFORCEMENT ACTION TYPE: 1 DATE ENFORCEMENT ACTION TAKEN: 09/19/95

LUFT FIELD MANUAL CONSID: CASE CLOSED: DATE CASE CLOSED:

DATE EXCAVATION STARTED : REMEDIAL ACTIONS TAKEN:

RESPONSIBLE PARTY INFORMATION

RP#1-CONTACT NAME: Ronn Simpson COMPANY NAME: Ronn Simpson ADDRESS: P. O. Box 3090

CITY/STATE: Berkeley, C A 94703

INSPECTOR VERIFICATION:						
NAME		SIGNATURE			DATE	
Name/Address Changes	s Only	DATA ENTRY	INPUT:	Case	Progress Changes	
ANNPGMS LOI		DATE		LOP _	DATE	

	UNDERGROUND STORAGE TANK UNAUTHORIZED RELEASE (LEAK) / CONTAMINATION SITE REPORT							
EME	HAS STATE OFFICE OF EMERGENCY SERVICE: REPORT BEEN FILED? YES X NO YES X N	THEREBY CERTIFY THAT I AM A DESIGNATED GOVERNMENT EMPLOYER AND THAT I HAVE						
REP	DRT DATE CASE#	REPORTED THIS INFORMATION TO LOCAL OFFICIALS PURSUANT TO SECTION 25180.7 OF THE HEALTH AND SAFTY COOR						
0,	1941080945	SIGNED DATE						
BY	RONN SIMPSON	510) 658-9006 SIGNATURE Jour Luy Hor.						
REPORTED	REPRESENTING WNER/OPERATOR REGIONAL BO LOCAL AGENCY OTHER	Mr. Ronn Simpson						
3 4	P.O. ROX 3090	Berkeley CA 94703						
NSIBLE ITY	NAME UNKNO	CONTACT PERSON PHONE						
RESPOR	P.O. BOX 3090 Berkeley	CA 94703 STATE ZEP						
ž	FACILITY NAME (IF APPLICABLE) 489 43 43 rd STREET	OPERATOR PHONE						
ELOCATION	ADDRESS 489 43 VCl Street	Oakland Alameda 94609						
SIT	CROSS STREET TYPE OF AREA X TELEGRAPH AVENUE RESIDENTIAL	COMMERCIAL NDUSTRIAL RURAL TYPE OF BUSINESS RETAIL FUEL STATION OTHER FARM OTHER WORLD STATION						
ENTING	Alameda County Dept. Of Environm	contact person nemfal Ms. EVA CHU 1570) 567-6767						
MPLEM	REGIONAL BOARD BAY AREA RWOCB	PHONE (510) 286-0914						
S.	(1) NAN							
TANCES LVED	GASOLINE FUEL	🔀 niknomi						
88Z M¥								
S.	POSSIBLE DIS	EL FUEL DINKNOWN						
IENT SI	DATE DISCOVERED HOW DISCOVERED	INVENTORY CONTROL SUBSURFACE MONITORING NUISANCE CONDITIONS						
ATEMENT SI	DATE DISCOVERED HOW DISCOVERED O M 9 M / D 8 D 9 V 5 V TANK TEST	INVENTORY CONTROL SUBSURFACE MONITORING NUISANCE CONDITIONS TANK REMOVAL OTHER						
RY/ABATEMENT SI	DATE DISCOVERED HOW DISCOVERED TANK TEST DATE DISCHARGE BEGAN	INVENTORY CONTROL SUBSURFACE MONITORING NUISANCE CONDITIONS TANK REMOVAL OTHER METHOD USED TO STOP DISCHARGE (CHECK ALL THAT APPLY)						
COVERY/ABATEMENT SI	DATE DISCOVERED HOW DISCOVERED O M 9 M / D 8 D 9 V 5 V TANK TEST	INVENTORY CONTROL SUBSURFACE MONITORING NUISANCE CONDITIONS TANK REMOVAL OTHER METHOD USED TO STOP DISCHARGE (CHECK ALL THAT APPLY)						
DISCOVERY/ABATEMENT SI	DATE DISCOVERED OM 9M / D 8 D 9 V TANK TEST DATE DISCHARGE BEGAN M M D O V V UNKNOWN HAS DISCHARGE BEEN STOPPED? X YES NO IFYES, DATE OM 9 M / D 8 D 9 V	INVENTORY CONTROL SUBSURFACE MONITORING NUISANCE CONDITIONS TANK REMOVAL OTHER METHOD USED TO STOP DISCHARGE (CHECK ALL THAT APPLY) REMOVE CONTENTS REPLACE TANK CLOSE TANK REPAIR TANK REPAIR PIPING CHANGE PROCEDURE 5 Y OTHER						
-	DATE DISCOVERED OM 9 M 1 D 8 D 9 V TANK TEST DATE DISCHARGE BEGAN M M D O V V W WUNKNOWN HAS DISCHARGE BEEN STOPPED? WYES NO IF YES, DATE OM 9 M 1 D 8 D 9 V SOURCE OF DISCHARGE TANKS ONLY CAPACITY	INVENTORY CONTROL SUBSURFACE MONITORING NUISANCE CONDITIONS TANK REMOVAL OTHER METHOD USED TO STOP DISCHARGE (CHECK ALL THAT APPLY) REMOVE CONTENTS REPLACE TANK CLOSE TANK REPAIR TANK REPAIR PIPING CHANGE PROCEDURE TO THER MATERIAL CAUSE(S)						
-	DATE DISCOVERED OM 9 M D 8 D 9 V TANK TEST DATE DISCHARGE BEGAN M M D O V V W UNKNOWN HAS DISCHARGE BEEN STOPPED? X YES NO IF YES, DATE OM 9 M D 8 D 9 V SOURCE OF DISCHARGE TANK LEAK W UNKNOWN	INVENTORY CONTROL SUBSURFACE MONITORING NUISANCE CONDITIONS TANK REMOVAL OTHER METHOD USED TO STOP DISCHARGE (CHECK ALL THAT APPLY) REMOVE CONTENTS REPLACE TANK CLOSE TANK REPAIR TANK REPAIR PIPING CHANGE PROCEDURE OTHER MATERIAL CAUSE(S) ALL FIBERGLASS CAUSE(S) ALL RUPTURE/FAILURE						
-	DATE DISCOVERED OM 9 M 1 D 8 D 9 V TANK TEST DATE DISCHARGE BEGAN M M D O V V W WUNKNOWN HAS DISCHARGE BEEN STOPPED? WYES NO IF YES, DATE OM 9 M 1 D 8 D 9 V SOURCE OF DISCHARGE TANKS ONLY CAPACITY	INVENTORY CONTROL SUBSURFACE MONITORING NUISANCE CONDITIONS TANK REMOVAL OTHER METHOD USED TO STOP DISCHARGE (CHECK ALL THAT APPLY) REMOVE CONTENTS REPLACE TANK CLOSE TANK REPAIR TANK REPAIR PIPING CHANGE PROCEDURE OTHER MATERIAL CAUSE(S) OVERFILL RUPTURE/FAILURE RS STEEL CORROSION UNKNOWN						
SOURCE/CAUSE	DATE DISCOVERED OM 9 M OB 9 9 5 TANK TEST DATE DISCHARGE BEGAN M M D O Y Y W WINKNOWN HAS DISCHARGE BEEN STOPPED? X YES NO IF YES, DATE OM 9 M OB D 9 Y SOURCE OF DISCHARGE TANK LEAK W UNKNOWN PIPING LEAK W UNKNOWN AGE W 194-2 Y	INVENTORY CONTROL SUBSURFACE MONITORING NUISANCE CONDITIONS TANK REMOVAL OTHER METHOD USED TO STOP DISCHARGE (CHECK ALL THAT APPLY) REMOVE CONTENTS REPLACE TANK CLOSE TANK REPAIR TANK REPAIR PIPING CHANGE PROCEDURE OTHER MATERIAL CAUSE(S) OVERFILL RUPTURE/FAILURE RS STEEL CORROSION UNKNOWN						
-	DATE DISCOVERED OM 9 M 1 D 8 D 9 V TANK TEST DATE DISCHARGE BEGAN M M D D V Y UNKNOWN HAS DISCHARGE BEEN STOPPED? X YES NO IF YES, DATE OM 9 M 1 D 8 D 9 V SOURCE OF DISCHARGE TANK LEAK UNKNOWN PIPING LEAK UNKNOWN OTHER UNKNOWN	INVENTORY CONTROL SUBSURFACE MONITORING NUISANCE CONDITIONS TANK REMOVAL OTHER METHOD USED TO STOP DISCHARGE (CHECK ALL THAT APPLY) REMOVE CONTENTS REPLACE TANK CLOSE TANK REPAIR TANK REPAIR PIPING CHANGE PROCEDURE OTHER MATERIAL CAUSE(S) OVERFILL RUPTURE/FAILURE RS X STEEL CORROSION X UNKNOWN OTHER OTHER SPILL OTHER						
CASE SOURCE/CAUSE	DATE DISCOVERED OM 9 M D 8 D 9 S TANK TEST DATE DISCHARGE BEGAN M M D D S SUNKNOWN HAS DISCHARGE BEEN STOPPED? X YES NO IF YES, DATE OM 9 M D 8 D 9 SOURCE OF DISCHARGE TANK LEAK UNKNOWN PIPING LEAK OTHER UNKNOWN CHECK ONE ONLY GROUNDWATE CHECK ONE ONLY CHECK ONE ONLY	INVENTORY CONTROL SUBSURFACE MONITORING NUISANCE CONDITIONS TANK REMOVAL OTHER METHOD USED TO STOP DISCHARGE (CHECK ALL THAT APPLY) REMOVE CONTENTS REPLACE TANK CLOSE TANK REPAIR TANK REPAIR PIPING CHANGE PROCEDURE OTHER MATERIAL CAUSE(S) ALL FIBERGLASS CAUSE(S) ALL CORROSION NUISANCE CONDITIONS OTHER STEEL CORROSION NUISANCE CONDITIONS OTHER SPILL OTHER DRINKING WATER - (CHECK ONLY IF WATER WELLS HAVE ACTUALLY BEEN AFFECTED)						
CASE SOURCE/CAUSE	DATE DISCOVERED OM 9M OB OP STANK TEST DATE DISCHARGE BEGAN M D O V V V UNKNOWN HAS DISCHARGE BEEN STOPPED? SOURCE OF DISCHARGE TANK LEAK UNKNOWN TANK LEAK UNKNOWN OTHER UNKNOWN CHECK ONE ONLY SITE INVESTIGATION IN PROGRESS (DEFINING EXTENT OF PROBLE	INVENTORY CONTROL SUBSURFACE MONITORING NUISANCE CONDITIONS TANK REMOVAL OTHER METHOD USED TO STOP DISCHARGE (CHECK ALL THAT APPLY) REMOVE CONTENTS REPLACE TANK CLOSE TANK REPAIR TANK REPAIR PIPING CHANGE PROCEDURE OTHER CAUSE(S) ALL FIBERGLASS CAUSE(S) OVERFILL RUPTURE FAILURE RS STEEL CORROSION NINKNOWN OTHER SPILL OTHER DRINKING WATER - (CHECK ONLY IF WATER WELLS HAVE ACTUALLY BEEN AFFECTED) M) CLEANUP IN PROGRESS SIGNED OFF (CLEANUP COMPLETED OR UNNECESSARY)						
SOURCE/CAUSE	DATE DISCOVERED OM 9 M D 8 D 9 S TANK TEST DATE DISCHARGE BEGAN M M D D S SUNKNOWN HAS DISCHARGE BEEN STOPPED? X YES NO IF YES, DATE OM 9 M D 8 D 9 SOURCE OF DISCHARGE TANK LEAK UNKNOWN PIPING LEAK OTHER UNKNOWN CHECK ONE ONLY GROUNDWATE CHECK ONE ONLY CHECK ONE ONLY	INVENTORY CONTROL SUBSURFACE MONITORING NUISANCE CONDITIONS TANK REMOVAL OTHER METHOD USED TO STOP DISCHARGE (CHECK ALL THAT APPLY) REMOVE CONTENTS REPLACE TANK CLOSE TANK REPAIR TANK REPAIR PIPING CHANGE PROCEDURE OTHER CAUSE(S) ALL FIBERGLASS CAUSE(S) ALL STEEL CORROSION NINKNOWN OTHER SPILL OTHER DRINKING WATER - (CHECK ONLY IF WATER WELLS HAVE ACTUALLY BEEN AFFECTED) M) CLEANUP IN PROGRESS SIGNED OFF (CLEANUP COMPLETED OR UNNECESSARY)						
CURRENT CASE SOURCE/CAUSE STATUS TYPE SOURCE/CAUSE	DATE DISCOVERED OM 9 M OB 9 Y 5 Y TANK TEST DATE DISCHARGE BEGAN M D O Y Y W UNKNOWN HAS DISCHARGE BEEN STOPPED? SOURCE OF DISCHARGE TANK LEAK UNKNOWN PIPING LEAK UNKNOWN OTHER UNKNOWN CHECK ONE ONLY SITE INVESTIGATION IN PROGRESS (DEFINING EXTENT OF PROBLE NO ACTION TAKEN POST CLEANUP MONITORING IN PROGRESS	INVENTORY CONTROL SUBSURFACE MONITORING NUISANCE CONDITIONS TANK REMOVAL OTHER METHOD USED TO STOP DISCHARGE (CHECK ALL THAT APPLY) REMOVE CONTENTS REPLACE TANK CLOSE TANK REPAIR TANK REPAIR PIPING CHANGE PROCEDURE OTHER MATERIAL CAUSE(S) OVERFILE RUPTURE/FAILURE RS STEEL CORROSION NUISANCE OTHER SPILL OTHER DRINKING WATER - (CHECK ONLY IF WATER WELLS HAVE ACTUALLY BEEN AFFECTED) M) CLEANUP IN PROGRESS SIGNED OFF (CLEANUP COMPLETED OR UNNECESSARY) RESS NO FUNDS AVAILABLE TO PROCEED EVALUATING CLEANUP ALTERNATIVES						
CURRENT CASE SOURCE/CAUSE STATUS TYPE SOURCE/CAUSE	DATE DISCOVERED OM 9 M D 8 D 9 V TANK TEST DATE DISCHARGE BEGAN M M D O V V W UNKNOWN HAS DISCHARGE BEEN STOPPED? SOURCE OF DISCHARGE TANK LEAK W UNKNOWN PIPING LEAK UNKNOWN OTHER UNKNOWN CHECK ONE ONLY SITE INVESTIGATION IN PROGRESS (DEFINING EXTENT OF PROBLE NO ACTION TAKEN POST CLEANUP MONITORING IN PROGRECK APPROPRIATE ACTION(S) (SEE BACK FOR DETAILS)	INVENTORY CONTROL SUBSURFACE MONITORING NUISANCE CONDITIONS TANK REMOVAL OTHER METHOD USED TO STOP DISCHARGE (CHECK ALL THAT APPLY) REMOVE CONTENTS REPLACE TANK CLOSE TANK REPAIR TANK REPAIR PIPING CHANGE PROCEDURE OTHER CAUSE(S) OVERFILL RUPTURE/FAILURE RS STEEL CORROSION NUINKNOWN OTHER SPILL OTHER DRINKING WATER - (CHECK ONLY IF WATER WELLS HAVE ACTUALLY BEEN AFFECTED) M) CLEANUP IN PROGRESS SIGNED OFF (CLEANUP COMPLETED OR UNNECESSARY) RESS NO FUNDS AVAILABLE TO PROCEED EVALUATING CLEANUP ALTERNATIVES (ED) REMOVE FREE PRODUCT (FP) ENHANCED BIO DEGRADATION (IT) PUMP & TREAT GROUNDWATER (GT) REPLACE SUPPLY (RS)						
CASE SOURCE/CAUSE	DATE DISCOVERED OM 9 M OD 9 V TANK TEST DATE DISCHARGE BEGAN M M D O V V UNKNOWN HAS DISCHARGE BEEN STOPPED? SOURCE OF DISCHARGE TANK LEAK OTHER UNKNOWN CHECK ONE ONLY SITE INVESTIGATION IN PROGRESS (DEFINING EXTENT OF PROBLE NO ACTION TAKEN CHECK APPROPRIATE ACTION(S) (SEE BACK FOR DETAILS) CAP SITE (CD) CONTAINMENT BARRIER (CB) TREATMENT AT HOOKUP (HU) NO ACTION REQUIRED	INVENTORY CONTROL SUBSURFACE MONITORING NUISANCE CONDITIONS TANK REMOVAL OTHER METHOD USED TO STOP DISCHARGE (CHECK ALL THAT APPLY) REMOVE CONTENTS REPLACE TANK CLOSE TANK REPAIR TANK REPAIR PIPING CHANGE PROCEDURE OTHER MATERIAL CAUSE(S) ALL FIBERGLASS STEEL CORROSION UNKNOWN OTHER SPILL OTHER REPAIR WELLS HAVE ACTUALLY BEEN AFFECTED) M) CLEANUP IN PROGRESS SIGNED OFF (CLEANUP COMPLETED OR UNNECESSARY) RESS NO FUNDS AVAILABLE TO PROCEED EVALUATING CLEANUP ALTERNATIVES (ED) REMOVE FREE PRODUCT (FP) ENHANCED BIO DEGRADATION (IT) PUMP & TREAT GROUNDWATER (GT) REPLACE SUPPLY (RS) (NA) OTHER (OT) U.S.T. Remo Vel., No Furthern Actical						
REMEDIAL CURRENT CASE SOURCECAUSE	DATE DISCOVERED OM 9 M OD 9 V TANK TEST DATE DISCHARGE BEGAN M M D O V V UNKNOWN HAS DISCHARGE BEEN STOPPED? SOURCE OF DISCHARGE TANK LEAK OTHER UNKNOWN CHECK ONE ONLY SITE INVESTIGATION IN PROGRESS (DEFINING EXTENT OF PROBLE NO ACTION TAKEN CHECK APPROPRIATE ACTION(S) (SEE BACK FOR DETAILS) CAP SITE (CD) CONTAINMENT BARRIER (CB) TREATMENT AT HOOKUP (HU) NO ACTION REQUIRED	INVENTORY CONTROL SUBSURFACE MONITORING NUISANCE CONDITIONS TANK REMOVAL OTHER METHOD USED TO STOP DISCHARGE (CHECK ALL THAT APPLY) REMOVE CONTENTS REPLACE TANK CLOSE TANK REPAIR TANK REPAIR PPING CHANGE PROCEDURE OTHER MATERIAL CAUSE(S) ALL FIBERGLASS STEEL CORROSION UNKNOWN OTHER DRINKING WATER - (CHECK ONLY IF WATER WELLS HAVE ACTUALLY BEEN AFFECTED) M) CLEANUP IN PROGRESS SIGNED OFF (CLEANUP COMPLETED OR UNNECESSARY) RESS NO FUNDS AVAILABLE TO PROCEED EVALUATING CLEANUP ALTERNATIVES (ED) REMOVE FREE PRODUCT (FP) ENHANCED BIO DEGRADATION (IT) PUMP & TREAT GROUNDWATER (GT) REPLACE SUPPLY (RS) (NA) OTHER (OT) U.S.T. Removel, No Further Action (NA) CHARGE PROTECTION OTHER (OT) U.S.T. Removel, No Further Action OTHER (OT) U.S.T. Removel, No Further Action						
CURRENT CASE SOURCE/CAUSE STATUS TYPE SOURCE/CAUSE	DATE DISCOVERED OM 9 M OD 9 V TANK TEST DATE DISCHARGE BEGAN M M D O V V UNKNOWN HAS DISCHARGE BEEN STOPPED? SOURCE OF DISCHARGE TANK LEAK OTHER UNKNOWN CHECK ONE ONLY SITE INVESTIGATION IN PROGRESS (DEFINING EXTENT OF PROBLE NO ACTION TAKEN CHECK APPROPRIATE ACTION(S) (SEE BACK FOR DETAILS) CAP SITE (CD) CONTAINMENT BARRIER (CB) TREATMENT AT HOOKUP (HU) NO ACTION REQUIRED	INVENTORY CONTROL SUBSURFACE MONITORING NUISANCE CONDITIONS TANK REMOVAL OTHER METHOD USED TO STOP DISCHARGE (CHECK ALL THAT APPLY) REMOVE CONTENTS REPLACE TANK CLOSE TANK REPAIR TANK REPAIR PIPING CHANGE PROCEDURE OTHER CAUSE(S) ALL FIBERGLASS CAUSE(S) ALL STEEL CORROSION NUINKNOWN OTHER SPILL OTHER DRINKING WATER - (CHECK ONLY IF WATER WELLS HAVE ACTUALLY BEEN AFFECTED) M) CLEANUP IN PROGRESS SIGNED OFF (CLEANUP COMPLETED OR UNNECESSARY) RESS NO FUNDS AVAILABLE TO PROCEED EVALUATING CLEANUP ALTERNATIVES (ED) REMOVE FREE PRODUCT (FP) ENHANCED BIO DEGRADATION (IT) PUMP & TREAT GROUNDWATER (GT) REPLACE SUPPLY (RS)						

Contractor's License #643881

Accutite Environmental Engineering

35 So. Linden Avenue, South San Francisco, CA 94080-6407

Tel: (415) 952-5551 Fax: (415) 952-7631

Tank Testing: (415) 952-0327

September 19, 1995

Mr. Ronn Simpson P.O. Box 3090 Berkeley, California 94703

SUBJECT:

COMPLETION OF AN UNDERGROUND STORAGE TANK UNAUTHORIZED RELEASE (LEAK)/ CONTAMINATION REPORT FOR THE SITE LOCATED AT 489 43RD STREET

IN OAKLAND, CALIFORNIA

Dear Mr. Simpson:

Ms. Eva Chu of the Alameda County Department of Environmental Health requested the completion of an Underground Storage Tank Unauthorized Release (Leak)/ Contamination Report for the subject site. For your convenience, Accutite completed this form and prepared it for your signature. Please review the information provided in this form and sign in the indicated space. Keep a copy for your records and mail the original to Ms. Chu at:

Ms. Eva Chu Alameda County Department of Environmental Health 1131 Harbor Bay Parkway, 2nd Floor Alameda, CA 94502

Thank you for the opportunity to provide you with our services. If you have any questions, please call me at (415) 952-5551.

Sincerely,

Accutite Environmental Engineering

Sami Malaeb, P.E., R.E.A

Project Manager

Enc:

#5552 Was transferred 9-19-95 AB submitted

DATE: 9/19/95

TO : Local Oversight Program

FROM: evadu

SUBJ: Transfer of Eligible Local Oversight Case

Site name: Ronn Simpson
Address: 489 - 43rd st city Oak _ Zip 94609
TO BE ELLIGIBLE FOR LOP A CASE MUST MEET 3 QUALIFICATIONS:
1 Number of Tanks: removed? V N Pate of removal 9(18/9)
2. Samples received? Y N Contamination level: US(w) (arguinates, (ppm and type of test) Styne oder in Sell samples (ppm TPH to qualify for LOP contamination should be over 100 ppm TPH to qualify for LOP
Contamination should be over 100 ppm TPH to qualify for LOP
3. Petroleum Y N Types: Avgas Jet leaded unleaded Diesel fuel oil waste oil kerosene solvents
DepRef remaining \$ Closed with Candace/Leslie? Y N (If no explain why?)
THE ABOVE QUALIFICATIONS YOU SHOULD DO THE

IF YOUR SITE MEETS ALL OF THE ABOVE QUALIFICATIONS YOU SHOULD DO THE FOLLOWING TO TRANSFER THE SITE:

- 1. YOU MUST CLOSE THE DEPOSIT REFUND CASE AT THIS TIME. YOU MUST ACCOUNT FOR ALL TIME YOU HAVE SPENT ON THE CASE AND TURN IN THE ACCOUNT SHEET TO LESLIE. IF THERE ARE FUNDS STILL REMAINING IT IS STILL BETTER TO TRANSFER THE CASE TO LOP AS THE RATE FOR LOP ALLOWS THE ADDITION OF MANAGEMENT AND CLERICAL TIME. DO NOT ATTEMPT TO CONTINUE TO OVERSEE THE SITE SIMPLY BECAUSE THERE ARE FUNDS REMAINING!
- 2. COMPLETE THE A AND B PERMIT APPLICATION FORMS AND GIVE TO COMPLETE THE A
- 3. GIVE THE ENTIRE CASE TO THE PROPER LOP STAFF UPSTAIRS FOR THEM TO DO THE REST OF THE TRANSFER AND YOU ARE DONE!

office corp

These closure/removal plans have been received and four distance be acceptable and essentially most the requirements of States.

These closure/removal plans have been received and four distance be acceptable and essentially most the requirements of States.

By this Department are to assure compliance with State and the project proposed Lorein is now released for issued by the equired building permits for contraction, destruction of any required building permits for contraction, destruction and the received of the acceptable is on the contractions of any changes of a state of contractions and the received of the submitted to the form of the received of the contraction of any changes of the contraction of a state of the received of the submitted to the form of the received of the submitted to the form of the received of the submitted to the form of the received of the received of the submitted to the form of the received of the second of the submitted to the form of the received of the second of the sec 1131 HARBOR BAY PARKWAY, STE 250

Notify this Department at least 72 hours proc to the following

requirements of State and to at 1 15.

required inspections: *

Removal of Tank(s) and Piping

Final Inspection

is dependant on compliance with accepted plans and all aprical *THERE IS A FINANCIAL PENALTY FOR NOT OBTAINING THESE INSPECTIONS plicable laws and regulations.

Issuance of a) permit to operate, b) pormanont site closuro.

UNDERGROUND TANK CLOSURE PLAN Complete according to attached instructions * * *

1.	Business Name Brand X Ronn Sumpson
	Business Owner Ronn C Simpson
2.	Site Address 491-43rd Street, 489-43rd St.
	City Oakland, CA Zip 94609 Phone (510) 658-9006
3.	Mailing Address P.O. Box 3090 / 491-43 rdst.
	City Berkeley, California Zip 94703 Phone (510) 658-9006
4.	Land Owner Bucate Plata/DBA Brand X Huaraches Rown Sungson
	Address P.O. Box 3090 City, State Berkeley, CA Zip 94703
5.	Generator name under which tank will be manifested Brand X
	FRA I D. No. under which tank will be manifestedCAC001041648

lotalle 0/13/95

Underground Storage Tank Closure Permit Application

ACCEPTED

Alameda County Division of Hazardous Materials

80 Swan Way, Suite 200,

6.	Contractor _	Accutite Environ	mentar			
	Address	35 So. Linden Av	enue			
	city	So. San Francisc	o, CA 9408	0		415) 952-555
	License Ty	Lic. #643881 pe*B,C36,C61/D40	HAZ ID	# <u>94-3</u>	074925	
	*Effective January 1	, 1992, Business and Profestification issued by the Staddition, to holding the appo	sional Code Section	on 7058.7 re icense Board	quires prime conti . Indicate that	ractors to also hold the certificate has
7.	Consultant _	Accutite Environ	nmental			
	Address	35 So. Linden A	venue			
		San Francisco, C		one (415) 952-5	551
8.		son for Investiga				
	Name <u>Wi</u>	lie Green		Title _	Project Fo	reman
	Phone (4)	15) 952-5551 PAG	2 v :			
9.	. Number of t	anks being closed	l under thi	s plan	One	
	Length of p	iping being remov	ved under t	his pla	n None	
		r of tanks at fac				
10.	. State Regis instruction	tered Hazardous N s).	Naste Trans	sporters	s/Facilitie	s (see
	** Undergro	und tanks are ha as ha	zardous was zardous was	ste and ste	must be ha	indled **
	a) Product	/Residual Sludge	/Rinsate Ti	canspor	ter	
	Name _	Erickson		EPA :	I.D. No. <u>C</u>	AD009466392
	Hauler	License No. #0	019	_ Licen	se Exp. Dat	e _7/31/95
		s <u>255 Parr Boul</u>				
		Richmond		State _	CA Zip	94801
	▼	:/Residual Sludge				Cannn9466392
		Erickson				CIII) 0 0 1 0 0 0 7 2
		ss <u>255 Parr Bou</u> l				
	City .	Richmond		State _	CA Zip	94801

C	C) Tank and Fibring Transported	
	Name <u>Erickson</u> EPA I.D. No. <u>CAD009</u>	466392
	Hauler License No. #0019 License Exp. Date _	7/31/95
	Address _255 Parr Boulevard	· · · · · · · · · · · · · · · · · · ·
	City Richmond State CA Zip 94	
	d) Tank and Piping Disposal Site	
	Name <u>Erickson</u> EPA I.D. No. <u>CAD009</u>	466392
	Address _255 Parr Boulevard	
	City Richmond State CA Zip 9480	1
11.	. Experienced Sample Collector Name Geoffrey Garrison or Sami Malaeb	
	Company Accutite Environmental Engineering	
	Address 35 So. Linden Avenue	
	City So. San Francisco State CA Zip 94080 Phone (415)	
10	. Tabawatawa	
12.	Name Sequoia Analytical Laboratory	•
	Address 680 Chesapeake Drive	
	City Redwood City State CA Zip 940	163
	State Certification No. #145	
13.	If yes, describe*(Unknown to Accutite)	

14. Describe methods to be used for rendering tank inert

Dry	Ice_	_	改	hast	15 Us/	1000 galan tank
					•	•

Before tanks are pumped out and inerted, all associated piping must be flushed out into the tanks. All accessible associated piping must then be removed. Inaccessible piping must be plugged.

The Bay Area Air Quality Management District (771-6000), along with local Fire and Building Departments, must also be contacted for tank removal permits. Fire departments typically require the use of explosion proof combustible gas meters to verify tank inertness. It is the contractor's responsibility to bring a working combustible gas meter on site to verify tank inertness.

15. Tank History and Sampling Information

Ta	nk	Material to be sampled	Location and Depth of Samples	
Capacity	Use History (see instructions)	(tank contents, soil, ground- water, etc.)		
500 1,000	Regular Gasoline	TPH-G & BTE&X Soil, and groundwater if encountered	2' beneath the tank. in nature soil.	

One soil sample must be collected for every 20 feet of piping that is removed. A ground water sample must be collected should any ground water be present in the excavation.

Excavated/Stockpiled Soil					
Stockpiled Soil Volume (Estimated) 3 yards	Sampling Plan Samples will be taken 2' beneath the tank. Samples will be collected in a brass tube and sealed with Teflon tape and placed on ice. Samples will be transported to an Analytical Laboratory. Sample strapped 1/50 cy for disposal or				

Stockpiled soil must be placed on bermed plastic and must be completely covered by plastic sheeting.

16. Chemical methods and associated detection limits to be used for analyzing samples

The Tri-Regional Board recommended minimum verification analyses and practical quantitation reporting limits should be followed. Se attached Table 2.

Contaminant Sought	EPA, DHS, or Other Sample Preparation Method Number	EPA, DHS, or Other Analysis Method Number	Method Detection Limit
TPH-G & BTE&X and MTBE	GCF1D 5030 8020 or 8240	-	5.0 0.5
Total lead	AA		

17. Submit Site Health and Safety Plan (See Instructions)

TO ': PHONE NO. : 14159527631 FROM : BUCATE PLATA

MAY.23.1995 11:55AM P 1

PHONE NO. : 5106589006

MAY. 23. 1995 11:10AM P 2 PHONE NO. : 4159525551

FROM : ACCUTITE

8. Submit Worker's Compensation Certificate copy

Name of Insurer California Indemnity Ins. Co.

- 9. Submit Plot Plan (See Instructions)
- O. Enclose Deposit (See Instructions)
- Report any leaks or contamination to this office within 5 days of discovery. The report shall be made on an Underground Storage Tank Unauthorized Leak/Contamination Site Report form. (see Instructions)
- 2. Submit a closure report to this office within 60 days of the tank removal. This report must contain all the information listed in item 22 of the instructions.

declare that to the best of my knowledge and belief the statements and nformation provided above are correct and true.

understand that information in addition to that provided above may be seeded in order to obtain an approval from the Department of invironmental Health and that no work is to begin on this project until his plan is approved.


understand that any changes in design, materials or equipment will void his plan if prior approval is not obtained.

understand that all work performed during this project will be done in compliance with all applicable OSHA (Occupational Safety and Health dministration) requirements concerning personnel health and safety. I understand that site and worker safety are solely the responsibility of the property owner or his agent and that this responsibility is not thated nor assumed by the County of Alameda.

the project Hazardous Materials Specialist at least three working days is

ignature of Contractor	
Name (please type) <u>Willie Green</u>	
Signature Wille Stee	
Date	
ignature of Site Owner or Operator	
Name (please type) Mr. Ronn Simpson	<u> </u>
signature Konn Simpson	
Date 5/23/95	
· · · · · · · · · · · · · · · · · · ·	•

- 6 -



white -env.health yellow -facility pink -files

ALAMEDA COUNTY, DEPARTMENT OF ENUIRONMENTAL HEALTH

Hazardous Materials Inspection Form

1131 Harbor Bay Pkwy Alameda CA 94502 510/567-6700

II, III

Site ID # Site	e Name	mSimpson Today	's Date 9 / 18/95
Site Address \89	1.43rd St.		
City <u>Oalcland</u>	Zip 94609 P	hone	
i	MT stored > 500 lbs, 55 gal.,	200 cft.?	Ran
	<u>1 Categories:</u> at/Waste GENERATOR/TRANSP	ORTER	658-9006
II. Hazard	ous Materials Business Plan, Acround Storage Tanks	utely Hazardous Materia	ls .
* Calif. Administration	on Code (CAC) or the Health & S	afety Code (HS&C)	
Comments: ~09d	EL 10% 0.	tog larry	James OFD
1000 caller	- gasolines / has	time ail (?)	7
Tanks seve	roly corrodor - So	weral large li	oles noted
- Tank or	asder printered wil	scrapping to	, L
	@ SS tollon	at 10/2' dept	h-dass w/ mod
dan	ded gas alor.	Partially tain	ed
9	<u> </u>		
3 590	2 53 taken at	+ 11' deathsl	stained clays w/
Consul	s-mod darado	Lous old	
	3) ss token at	13' Depth - st	me odal
Exampled	tom 13' depth	where day	1 1
			7
_ Soil will be	put tack into of	and will be 1	enamed when
·		ded milk	extremed in the
want frame		0 4 P I	
Analyze >	enues for -111:	2. THO 15	e (11.100)
			The state of the s
		——————————————————————————————————————	7° 1770 for
		200000000000000000000000000000000000000	
Contact	ada um ranasamanap a mammi sia mm		
Title	ra diana o carin menani in a siste a sena	Inspector	202 cla
Signature	aaanaa raaaaaa manaanaa madaa aa	Signature	W744 L
		or received	e of experience contrate to a teller conservation for teller teller teller to the conservation of the conservation of the contrate teller tell

HEALTH CARE SERVICES

AGENCY DAVID J. KEARS, Agency Director

RAFAT A. SHAHID. Assistant Agency Director

March 8, 1995

Mr. Ronn Simpson P.O. Box 3090 Berkeley, California 94703 ALAMEDA COUNTY-ENV. HEALTH DEPT. ENVIRONMENTAL PROTECTION DIV. 1131 HARBOR BAY PKWY., #250 ALAMEDA CA 94502-6577 (510)567-6700

NOTICE OF LEGAL OBLIGATION

RE: Underground Storage Tank at 491 43rd Street, Oakland, California 94609

Dear Mr. Simpson:

This office conducted a site visit of the subject facility last June, 1994. The inspection was initiated to evaluate placement of downgradient groundwater monitoring wells related to the groundwater investigation of a nearby site located at 490 43rd Street which is directly across your property.

During this visit, an abandoned underground storage tank underneath the sidewalk on 43rd Street was discovered. This tank is subject to permanent closure requirements as stated in Title 23 of the California Code of Regulations Section 2670 (c). The tank in which the storage of hazardous substances have ceased and the tank will not be used, or are not intended for use to store hazardous substances within the next twelve consecutive months must be removed. The tank must be properly closed as required by Section 25298, Chapter 6.7 of the California Health and Safety Code. Failure to properly close the tank is subject to civil penalty per Section 25299.

Enclosed are guidance documents and forms you will need for the removal of the underground storage tank which include the following:

- 1) Underground Storage Tank Removal Process in Alameda County
- 2) Underground Tank Closure Plan Application
- 3) Forms A and B
- 4) Underground Storage Tank Fee Schedule
- 5) Site Account Refund Recipient Form

Response to the issues mentioned above must be submitted to this office no later than April 30, 1995.

Mr. Ronn Simpson RE: 491 43rd Street, Oakland, CA 94609 March 8, 1995 Page 2 of 2

I have also enclosed information materials regarding the Underground Storage Tank Cleanup Fund and the low interest loan program RUST.

Please contact me at (510) 567-6780 if you have any questions concerning this letter.

Sincerely,

Suran L. Hugo

Senior Hazardous Materials Specialist

Enclosures

cc: Rafat A. Shahid, Director, Environmental Health Gordon Coleman, Acting Chief, Environmental Protection Div/file Gil Jensen, Alameda County District Attorney's Office