

#### Nahas Company, LLC

Real Estate Services

1111 Stone Valley Rd. Alamo, CA 94507 P. O. Box 3059 San Ramon, CA 94583 925-855-1978 Fax. 925-855-1414

#### **RECEIVED**

9:36 am, Feb 25, 2011

Alameda County

Environmental Health

January 31, 2011

Alameda County Environmental Health Attn: Barbara Jakub, P.G. 1131 Harbor Bay Parkway, Suite 250 Alameda, CA 94502-6577

Subject: Status Report
First Half 2010
Former Unocal Service Station
20405 Redwood Road
Castro Valley, California

well flater

Dear Ms. Jakub:

Enclosed please find a copy of the subject Status Report dated January 14, 2011, prepared by BSK Associates.

I declare, under penalty of perjury, that the information and/or recommendations contained in the attached document or report is true and correct to the best of my knowledge.

Sincerely,

Randall Nahas



# STATUS REPORT FIRST HALF 2010

## FORMER UNOCAL SERVICE STATION 20405 REDWOOD ROAD CASTRO VALLEY, CALIFORNIA

**BSK PROJECT E0805401S** 

PREPARED FOR:

MR. RANDALL NAHAS P.O. BOX 3049 SAN RAMON, CA 94583

**JANUARY 14, 2011** 

# STATUS REPORT FIRST HALF 2010 FORMER UNOCAL SERVICE STATION 20405 REDWOOD ROAD CASTRO VALLEY, CALIFORNIA

Prepared for:

Mr. Randall Nahas P.O. Box 3059 San Ramon, CA 94583

BSK Project: E0805401S

January 14, 2011

Jeffrey Yeazell, P.E.

Project Engineer

Kurt Balasek, P.G., C.H.G.

Senior Geologist

**BSK Associates** 

3140 Gold Camp Drive, Suite 160 Rancho Cordova, CA 95670 (916) 853-9293 (916) 853-9297 FAX www.bskinc.com C 76869
EXP. VI 31 / 1

© BSK Associates, 2011. All rights reserved.

#### **TABLE OF CONTENTS**

1.0	INTRODUCTION	1
2.0	PROJECT SITE DESCRIPTION AND HISTORY	1
3.0	PURPOSE AND SCOPE	4
4.0	GROUNDWATER FLOW DIRECTION	4
5.0	GROUNDWATER SAMPLING AND ANALYTICAL RESULTS	5
6.0	DISCUSSION AND RECOMMENDATIONS	5
7.0	LIMITATIONS	5
8.0	REFERENCES	6
Tabl Tabl Tabl Tabl Tabl	e 1: Soil Sample Analytical Results e 2: Soil Sample Analytical Results – Volatile and Semi-Volatile Organic Compounds e 3: Groundwater Monitoring Analytical Results – Petroleum Hydrocarbon Constituents e 4: Groundwater Monitoring Analytical Results – Volatile Organic Compounds e 5: Summary of Groundwater Elevation Data e 6: Summary of Groundwater Flow Direction and Gradient Data	
	URES re 1: Site Vicinity Map	
1.151	IC I. OHG VICHILVIVIAU	

Figure 2: Site Plan

Figure 3: Extent of Excavations and Excavation Soil Sample Locations

Figure 4: Generalized Groundwater Elevation Map - August 2010

Figure 5: MW-2 Time Series Plots

Figure 6: MW-3 Time Series Plots

Figure 7: MW-6 Time Series Plots

Figure 8: MW-7 Time Series Plots

Figure 9: MW-101 Time Series Plots

#### **APPENDICES**

Appendix A: Water Sample Logs

Appendix B: Laboratory Data Reports and Chain-of-Custody Documentation



# STATUS REPORT FIRST HALF 2010 FORMER UNOCAL SERVICE STATION 20405 REDWOOD ROAD CASTRO VALLEY, CALIFORNIA

#### 1.0 INTRODUCTION

At the request of Mr. Randall Nahas, BSK Associates performed groundwater monitoring and prepared this report summarizing data collected from the semi-annual monitoring of six groundwater monitoring wells located at the Former Unocal Service Station, 20405 Redwood Road, Castro Valley, California (the site). The site vicinity is shown on Figure 1.

#### 2.0 PROJECT SITE DESCRIPTION AND HISTORY

**December 1989, Soil Investigation and Monitoring Well Installation:** In December 1989, three groundwater monitoring wells (MW-2, MW-3 and MW-4) were installed at the locations shown on Figure 2. Soil samples were collected from soil borings MW-1 and MW-1A; however, they were not converted to monitoring wells (BSK, 1995). Summaries of soil sample analytical results are presented in Table 1 (petroleum hydrocarbons) and Table 2 (volatile and semi-volatile organic compounds). Monitoring well groundwater sample analytical results are summarized in Table 3.

March 1991, Soil Investigation: Thirteen soil borings (SB-1 through SB-13) were advanced at the locations shown on Figure 2 to depths ranging between approximately 10 and 20 feet bgs (BSK, 1996). Soil sample analytical results are summarized in Table 1.

March through April 1992, Soil Borings and Monitoring Well Installation: Soil borings MW-5, MW-6, MW-7, SB-14, and SB-15 were drilled at the locations shown on Figure 2. A summary of soil sample analytical results is presented in Table 1. Borings MW-5, MW-6, and MW-7 were completed as groundwater monitoring wells.

October 1992, Chromatograph Evaluation: BSK identified a non-standard peak in the chromatograph from a groundwater sample from well MW-7. The peak was not typical of petroleum hydrocarbons.

November 1992, Groundwater Sampling: Groundwater samples from monitoring well MW-7 were analyzed for volatile halocarbons by EPA Method 601. Analytical results are summarized in Table 3. Tetrachloroethylene (PCE) and trichloroethylene (TCE) were detected in groundwater samples from well MW-7 at concentrations of 14,000  $\mu$ g/L and 660  $\mu$ g/L, respectively. BSK Associates attributed the previous concentrations of TPHg to the presence of PCE and concluded gasoline contamination may not occur in a significant quantity in monitoring well MW-7. As a result, BSK Associates recommended ceasing any further investigation of the gasoline plume south of well MW-7 (BSK, 1992b).



**November 1993, Soil Borings:** Soil borings SP-1 and SP-2 were advanced at the locations shown on Figure 2. Soil and groundwater samples were collected from each boring. Summaries of soil sample analytical results are presented in Table 1 (petroleum hydrocarbons) and Table 2 (volatile and semi-volatile organic compounds). Monitoring well groundwater sample analytical results are summarized in Table 3 (Philip Environmental, 1996).

**December 1995, Feasibility Study:** Excavation and on-site treatment of excavated soil was selected as the remedial alternative for soil impacts. As a part of the feasibility study, an aquifer pump test was conducted. Groundwater extraction well MW-101 was installed at the location shown on Figure 2. Pump-and-treat was determined to be a feasible remedial alternative for groundwater impacts at the site. (BSK, 1995).

June 1996, Revised Corrective Action Plan: Philip Environmental prepared a Revised Corrective Action Plan. The plan stated that the site operator and property owner planned to cease operation of the site as a service station, which would require closure of the underground storage tanks. Philip Environmental recommended removal of the USTs, soil excavation and limited groundwater extraction (Philip Environmental, 1996).

As part of the Revised Corrective Action Plan, Tier I and Tier II Risk Assessments were conducted. Results of the Tier I Risk Assessment show benzene levels in soil at the site exceeded the risk based screening levels for volatilization from soil to outdoor air, vapor intrusion from soil to on-site buildings, soil ingestion, and leachate from soil to water exposure pathways. Toluene levels in soil at the site exceeded the risk based screening levels for the vapor intrusion from soil to on-site buildings exposure pathway. Results of the Tier II Risk Assessment indicated that concentrations of phase separated hydrocarbons and benzene in soil and groundwater exceed Tier II site specific screening levels in the area adjacent to the USTs and the southern property boundary (Philip Environmental, 1996).

Summer 1997, Service Station Building Demolition: The service station building was demolished and fuel dispensers removed (Life Springs Environmental Inc., 1999).

**November 1998, UST Removal:** The concrete slabs and foundation of the building, fueling area, and pump islands, were broken up and hauled to a recycling facility. The three USTs and associated piping were removed and transported to Ecology Control Industries (ECI) in Richmond, California. Two hydraulic hoists and clarifier sump were also removed. No holes were observed in the gasoline USTs, but small holes were observed in the waste oil UST. The excavated soil (approximately 175 cubic yards) was stockpiled. Figure 3 shows the approximate extent of the excavation.

Soil samples were collected after excavation. Sample locations are shown on Figure 3. Tables 1 and 2 provide summaries of soil sample analytical results. The release of petroleum hydrocarbons at the site appears to have primarily impacted the backfill material surrounding the two 10,000 gallon gasoline USTs (Life Springs Environmental Inc., 1999).

The UST pit was backfilled with aggregate base to within 5 feet of ground surface. Winter weather conditions led Life Springs Environmental Inc. to place impacted soil back in the excavations of the waste oil UST and clarifier sump (Life Springs Environmental Inc., 1999).



April 1999, Stockpiled Soil Remediation: Beginning in April 1999, impacted soil from the main UST excavation was laid out in shallow beds and aerated by periodic tilling.

May 1999, Soil Re-Excavation and Sampling: The waste oil UST and clarifier sump areas were re-excavated, with the second excavation extending slightly deeper then the first. Excavated soil from the waste oil UST and clarifier sump pits was disposed of at Vasco Road Sanitary Landfill in Livermore, California (Life Springs Environmental Inc., 2000). Soil samples were collected from native soil in both pits and analyzed for TPHd and total oil and grease. A section of the pipe trench area was excavated to a depth of 3 feet bgs. Excavated soil from the trench was laid out in shallow beds for aeration. A soil sample was collected from the trench re-excavation (sample name: GASLINE). The sample was analyzed for TPHg/BTEX and MTBE. Table 1 provides a summary of soil sample analytical results. Figure 3 shows the approximate extent of re-excavation and sample locations.

August 1999, Waste Oil and Clarifier Sump Pit Sampling and Soil Stockpiling: The aerated soil from precious excavations was stockpiled. Soil samples were collected from the bottom of the waste oil and clarifier sump pits at depths of 10 and 7 feet bgs respectively (Life Springs Environmental Inc., 1999). Table 1 provides a summary of soil sample analytical results, Figure 3 shows the approximate sample locations.

**September 1999, Waste Oil Pit Sampling:** A soil sample was collected from within the waste oil pit at a depth of 11.5 bgs and analyzed for chlorinated hydrocarbons and TPHd. Table 1 provides a summary of soil sample analytical results, Figure 3 shows the approximate sample location.

October 1999, Clarifier Sump Pit Sampling: A soil sample was collected within the clarifier sump pit at a depth of 9.5 feet bgs. Table 1 provides a summary of soil sample analytical results, Figure 3 shows the approximate sample location.

November 1999, Permission to Re-Use Stockpiled Soil: Permission was granted by Alameda County Environmental Health Services for the re-use of the stockpiled soil that had been remediated by aeration (Life Springs Environmental Inc., 2000).

December 1999, Waste Oil and Clarifier Sump Pit Deepening and Sampling: The waste oil pit was deepened to 10 feet bgs and the clarifier sump pit was deepened to 14 feet bgs. Soil removed from the over-excavation was also transported to the Vasco Road Sanitary Landfill in Livermore, California. Approximately 36.1 tons of soil were removed from both the waste oil pit and the clarifier sump pit during both re-excavation and over-excavation events. Soil samples were collected from the native soil in the bottom of each pit. The two excavations along with the final five feet of the main excavation were filled in with the remediated soil from the main excavation. Table 1 provides a summary of soil sample analytical results. Figure 3 shows the approximate extent of the over-excavation and sample locations.

Monitoring well MW-4 was abandoned by pressure grouting and drilling out. The vault boxes for monitoring wells MW-2 and MW-101 were replaced (Life Springs Environmental Inc., 2000).



Groundwater Monitoring Program: From August 1990 through 1999, groundwater monitoring activities were performed on a quarterly basis. Groundwater monitoring was performed semi-annually starting in 1999 through September 2003. Groundwater monitoring was not conducted from the third quarter of 2003 through the third quarter of 2008. Groundwater monitoring analytical data are summarized in Table 3 (petroleum hydrocarbon constituents) and Table 4 (volatile organic hydrocarbons). Groundwater elevation data are summarized in Table 5. Currently, groundwater monitoring is conducted on a semi-annual basis.

#### 3.0 PURPOSE AND SCOPE

The purpose of quarterly monitoring is to collect data on groundwater quality, groundwater depths, and direction of flow beneath the subject property with the intention of evaluating residual hydrocarbon contamination in groundwater beneath the site. BSK performed the following tasks:

- Measured depth to groundwater in three of the six monitoring wells on August 4, 2010.
   At the time of sampling, monitoring wells MW-2 and MW-3 were inaccessible.
   Monitoring wells MW-2 and MW-3 were covered by a layer of mulch and could not be located.
- Purged and sampled four of the six groundwater monitoring wells.
- Analyzed groundwater samples from each accessible monitoring well, for:
  - o Total petroleum hydrocarbons as diesel (TPHd)
  - o Total petroleum hydrocarbons as gasoline (TPHg)
  - o Benzene, toluene, ethylbenzene, and xylenes (BTEX)
  - o Fuel Oxygenates
  - o Lead Scavengers
- Prepared this status report summarizing the condition of the wells, depth to groundwater, groundwater flow direction, and laboratory analytical results.

#### 4.0 GROUNDWATER FLOW DIRECTION

Groundwater depths were measured in the four accessible monitoring wells prior to purging and sampling on August 4, 2010. Depths were measured relative to the north side of the top of each well casing.

Based on our measurements, groundwater generally flowed east with an approximate hydraulic gradient of 0.01 feet/foot. Figure 4 presents a groundwater elevation contour map for the recent monitoring event, and includes a rose diagram depicting a summary of groundwater flow directions since 1992. Table 5 summarizes groundwater elevations recorded during the investigation. Table 6 summarizes associated groundwater gradient and flow direction data.



#### 5.0 GROUNDWATER SAMPLING AND ANALYTICAL RESULTS

Groundwater sampling was conducted on August 4, 2010. Each well was purged of a minimum of three casing volumes using an electric submersible pump. Water temperature, pH, and conductivity were measured after removal of each approximate casing volume. Water sample logs are included in Appendix A.

After purging, water samples were collected from each well using a clean disposable bailer. The samples were labeled with the sample identification, date and time collected, and project identification. Samples were preserved in a chilled cooler and transported with completed chain-of-custody forms to BSK's state-certified analytical laboratory. The samples were analyzed for TPHd and TPHg by EPA Method 8015B, BTEX by EPA Method 8021B, and fuel oxygenates and lead scavengers by EPA Method 8260B. Equipment used during purging and sampling activities was cleaned with non-phosphate detergent wash and rinsed prior to use at each well location. The purged groundwater was stored in appropriately-labeled 55-gallon drums at the site.

Tables 3 and 4 summarize past quarterly monitoring analytical results. Figures 5 through 9 present time series plots for monitoring wells MW-2, MW-3, MW-6, MW-7, and MW-101 respectively. Appendix B contains laboratory data reports and chain-of-custody documentation for the samples collected this quarter.

#### 6.0 DISCUSSION AND RECOMMENDATIONS

BSK has had significant difficulties in efficiently locating monitoring wells MW-2 and MW-3. Between sampling events, the wells become covered with bark and debris, and we have had minimal success in locating them with GPS devices and metal detectors.

BSK recommends the following:

1. Locate monitoring wells MW-2 and MW-3 and install a crash post next to their vault boxes. The crash posts will allow us to readily locate the wells in the future and also help in protecting the vault boxes from potential damage in the future.

#### 7.0 LIMITATIONS

This report has been prepared for the exclusive use of Mr. Randall Nahas. Unauthorized use of or reliance on the information contained in this report by others, unless given the express written consent by BSK Associates, is prohibited.

The conclusions presented in this report are professional opinions based on the indicated data described in this report. This report has been prepared in accordance with generally accepted methodologies and standards of professional practice. No other warranties, either expressed or implied, are made as to the findings or conclusions included in the report. Conclusions and recommendations are intended only for the purpose, site location and project indicated.



Opinions presented in this report apply to site conditions existing at the time of our study and those reasonably foreseeable. They cannot necessarily apply to site changes of which this office is not aware and has not evaluated. Changes in the conditions of the subject property may occur with time, because of natural processes or the works of man, on the subject site or on adjacent properties.

#### 8.0 REFERENCES

- BSK 1992a, Off Site Soil and Groundwater Contamination Characterization and Seventh Quarterly Groundwater Monitoring Report, Unocal Service Station 20405 and 20629 Redwood Road, Castro Valley, California, May 29, 1992.
- BSK 1992b, Letter Report, Well MW-7 Special Sampling, Unocal Service Station/Safeway Parking Lot, 20405 and 20629 Redwood Road, Castro Valley, California, December 23, 1992.
- BSK 1995, Feasibility Study, Soil and Groundwater Remediation, Tien's Unocal Station, 20405 Redwood Road, Castro Valley, California, December 11, 1995.
- BSK, 1996, Semi-Annual Groundwater Monitoring Report, Unocal 76 Service Station, 20405 and 20629 Redwood Road, Castro Valley, California, BSK Associates, May 14, 1996.
- Philip Environmental 1996, Revised Corrective Action Plan, R.T. Nahas Property/Tien Unocal 76 Service Station, 20405 Redwood Road, Castro Valley, California, June 14, 1996.
- Life Springs Environmental, Inc. 1999, Technical Report, Tank Closure, Underground Fuel Tank Site, R.T. Nahas Company Property, Formerly Frank Tien Unocal 76 Service Station, 20405 Redwood Road, Castro Valley, California, 94546, February 18, 1999.
- Life Springs Environmental, Inc. 1999, Soil Remediation Status Report, R.T. Nahas Property, Castro Valley, August 17, 1999.
- Life Springs Environmental, Inc. 1999, Soil Remediation Status Report #2, R.T. Nahas Property, Castro Valley, October 26, 1999.
- Life Springs Environmental, Inc. 2000, Technical Report, Soil Remediation Closure Report, Underground Fuel Tank Site, R.T. Nahas Company Property, Formerly Frank Tien Unocal 76 Service Station, 20405 Redwood Road, Castro Valley, California, 94546, April 13, 2000.
- Graymer, R.W., 2000, Geologic map and map database of the Oakland metropolitan area, Alameda, Contra Costa, and San Francisco Counties, California: U.S. Geological Survey, Miscellaneous Field Studies Map MF-2342, scale 1:50000.
- BSK, 2003, Report, Eighth Semi-Annual Groundwater Monitoring (Third Quarter 2003), Former Unocal 76 Service Station, 20405 and 20629 Redwood Road, Castro Valley, California, BSK Associates, May 14, 1996.



### **TABLES**

### Table 1 Soil Sample Analytical Results Petroleum Hydrocarbon Constituents Former Unocal Service Station 20405 Redwood Road, Castro Valley, California (Concentrations in mg/kg)

r						1				
Location	Depth (feet)	TPHg	TPHd	Benzene	Толиепе	Ethylbenzene	Xylenes	Oil and Grease	Total Lead	MTBE
December 19	89. Soil I	nvestigat	ion and Monito	ring Well	Installation	on				
MW-1	5	<10	(#:	< 0.02	< 0.02	< 0.02	< 0.02	-	-	-
1.2.1.	10	89		1.8	7.8	3.8	20	-	-	
	15	<10	-	0.09	< 0.02	< 0.02	< 0.02	-	-	-
	19	<10	::=:::::::::::::::::::::::::::::::::::	< 0.02	< 0.02	< 0.02	< 0.02	-		-
MW-1A	5	<10	<10	< 0.02	< 0.02	< 0.02	< 0.02	-	<2.0	-
	10	110	50 <sup>b</sup>	2.2	11	5.4	25	2	<2.0	26
	13	11	<10	0.64	0.71	0.64	3.5	9	<2.0	20
	16.5	<10	<10	< 0.02	< 0.02	< 0.02	< 0.02	5	<2.0	3
MW-2	5	<10		< 0.02	< 0.02	< 0.02	< 0.02		-	
	10	<10	-	0.05	< 0.02	<0.02	0.03	:-:	-	980
	15	<10	ne ne	< 0.02	< 0.02	< 0.02	< 0.02	940	₩:	:=:
	20	<10	ë	< 0.02	< 0.02	< 0.02	< 0.02	28	=0	-
MW-3	5	<10	_	< 0.02	< 0.02	< 0.02	< 0.02	9	- E	-
	10	<10		< 0.02	< 0.02	< 0.02	< 0.02	5-0	-	
	15	92	-	ND	ND	0.97	4.0			
	19	<10		< 0.02	< 0.02	< 0.02	< 0.02	-	<del></del>	
MW-4 <sup>a</sup>	5	121	<10	< 0.02	< 0.02	< 0.02	< 0.02	<100		:=:
	8.5	-	<10	< 0.02	< 0.02	< 0.02	< 0.02	<100	-	: <b>-</b>
	13	-	<10	< 0.02	< 0.02	< 0.02	<0.02	<100	1435	
March 1991,	Soil Inve	stigation					· · · · · · · · · · · · · · · · · · ·			
SB-1	14.5	<10	=	0.05	0.03	< 0.02	0.06			
SB-2	10.5	440	<u> </u>	4.5	18	11	55	-	<2.0	:•::
	13	810	340 <sup>b</sup>	5.3	4.2	13	76	2	-	<u>~</u>
SB-3	13.5	15	<10	0.09	0.18	0.19	1.1	•	<2.0	- 6
	17	<10	-	< 0.02	< 0.02	< 0.02	< 0.02	-	=	
SB-4	14	<10	<10	< 0.02	< 0.02	< 0.02	0.1	: • :		250
SB-5	14.5	<10	2	< 0.02	< 0.02	< 0.02	< 0.02	_ =	:#3	360
SB-6	15	310	=	0.8	15	6.2	36	**	-	·
SB-8	20.5	<10	<del>1</del>	< 0.02	< 0.02	< 0.02	< 0.02			
SB-10	16	<10	+	< 0.02	< 0.02	< 0.02	< 0.02			
SB-11	10.5	31	2	0.09	0.03	0.49	1.8	) <del>=</del> :		(#X)
SB-12	15.5	<10	Ē	< 0.02	< 0.02	< 0.02	< 0.02	**		
SB-13	10.5	1100	-	5.5	67	27	140	-	•	•
	14	530	<u> </u>	7.8	48	14	73		299	: <b>•</b> :



## Table 1 Soil Sample Analytical Results Petroleum Hydrocarbon Constituents Former Unocal Service Station 20405 Redwood Road, Castro Valley, California (Concentrations in mg/kg)

	(Concentrations in ing/kg)											
Location	Depth (feet)	TPHg	ТРНа	Benzene	Toluene	Ethylbenzene	Xylenes	Oil and Grease	Total Lead	MTBE		
March throu	gh April	1992. Soi	l Borings and N	/Ionitoring	Well Ins	tallation						
SB-14	21	<1	<1	< 0.005	< 0.005	< 0.005	< 0.005	i i	2	=		
SB-15	20.5	<1	3	<0.005	0.007	< 0.005	< 0.008			-		
MW-5	21	<1	<1	< 0.005	< 0.005	< 0.005	< 0.005		*	-		
MW-6	16	<1	<1	< 0.005	< 0.005	< 0.005	< 0.005	-	-	(4)		
MW-7	15.5	<1	<1	< 0.005	< 0.005	< 0.005	< 0.005		-	-		
November 19			7									
SP-2	14	9		0.14	0.52	0.19	1.0	2	=	20		
SP-1	16		: 0	0.18	< 0.005	0.075	0.055	-	-	:=:::		
		toring W	ell Installation									
MW-101	10	120		< 0.005	0.95	2.1	11	-	-	148		
	15	63		ND	1.5	0.87	9.8	-				
November 1998, UST Removal												
WO	8	<1.0	270	< 0.005	0.0061	0.027	0.079	2300	9.0	< 0.005		
PIT NE COR	12	47	14	<0.62	<0.62	0.74	3.4	-		<0.62		
PIT NE BOT	13	14	- E	<0.62	<0.62	<0.62	<0.62	· ·	200	< 0.62		
PIT SE	12	31	-	< 0.62	1.8	< 0.62	3.0		H.C	< 0.62		
PIT SE	unk	100	a -	<2.5	<2.5	2.6	14	<b></b> €0	9400	<2.5		
PIT SW	11.5	22	-	< 0.62	< 0.62	< 0.62	3.0	-	2	< 0.62		
PIT NW	12	2.6	-	0.088	0.0054	0.11	0.52		20	0.014		
WL NW	2	<1.0	_	< 0.005	< 0.005	< 0.005	< 0.005	æ;.		0.018		
WL J	2	<1.0	=	< 0.005	< 0.005	< 0.005	< 0.005	:#S	(A)	< 0.005		
WIS S	2	410	<del>,</del>	3.6	11	12	72	220	-2	0.80		
WIS N	2	<1.0	-	< 0.005	< 0.005	< 0.005	< 0.005	100 C	-/	< 0.005		
EJ	2	<1.0	=	< 0.005	< 0.005	< 0.005	< 0.005			< 0.005		
EIS S	2	<1.0		< 0.005	< 0.005	<0.005	< 0.005	140	745	< 0.005		
EIS N	2	<1.0		<0.005	< 0.005	< 0.005	< 0.005	(2)	- 1	< 0.005		
CJ	2	<1.0	-	< 0.005	< 0.005	< 0.005	< 0.005		-	<0.005		
WEST HOIST <sup>3</sup>	8.5		1000*,1	選		14	:=:	120	-	:=:		
EAST HOIST <sup>3</sup>	8.5		<1.0**	UT.		<b>.</b>	2	8	36	*		
SUMP	4.5	<1.0	120 <sup>1</sup>	< 0.005	< 0.005	< 0.005	<0.005	96	7.9	<0.005		



#### Table 1

#### Soil Sample Analytical Results Petroleum Hydrocarbon Constituents

#### Former Unocal Service Station

#### 20405 Redwood Road, Castro Valley, California

(Concentrations in mg/kg)

Location	Depth (feet)	TPHg	TPHd	Benzene	Toluene	Ethylbenzene	Xylenes	Oil and Grease	Total Lead	MTBE
May 1999, Soil Re-excavation and Sampling										
GASLINE	3	<1.0	-	< 0.005	< 0.005	< 0.005	< 0.005	-	-	<b></b>
SUMP	4	-	2700 <sup>1/</sup> 4800 <sup>c</sup>	7 <b>-</b> :	-	-	-	- 1	-	·+:
WO 9 - 38 <sup>1</sup> 140										
August 1999.	, Waste O	il and Cl	arifier Sump P	it Samplin	ıg					
SUMP	7	-	84	344	-	-	-	88	-	-
wo	10	- [	560	. <del></del>	· ·	-	- 6	1400	7	<u>=1</u>
September 1	999, Was	te Oil Pit	Sampling					-		
wo	11.5	<1.0	1.21	< 0.005	< 0.005	< 0.005	< 0.005	<50	¥6	¥:
October 1999	, Clarific	r Sump	Pit Sampling							
SUMP <sup>3</sup>	9.5	71 <sup>1</sup>	270 <sup>2</sup>	< 0.62	< 0.62	< 0.62	< 0.62	220	<b>:</b> #60	< 0.62
December 19	99, Wast	e Oil and	Clarifier Sump	Pit Deep	ening and	Sampling	3			
WO <sup>3</sup>	11	<1.0	<1.0	< 0.005	< 0.005	< 0.005	< 0.005	<50	HR();	<0.005
SUMP <sup>3</sup>	15	6.3 <sup>1</sup>	690 <sup>1</sup>	< 0.005	<0.005	0.14	0.25	1200	*	<0.005

#### Notes:

-: Not analyzed.

#### unk: Unknown.

- <sup>1</sup>: Hydrocarbon reported does not match the pattern of Chromalab, Inc. standard.
- <sup>2</sup>: Estimated concentration reported due to overlapping fuel patterns.
- 3: Exact location not mapped.
- \* West Hoist also had 2000 mg/kg hydraulic oil.
- \*\*East Hoist <50 mg/kg hydraulic oil.
- <sup>a</sup>: Soil samples at were also analyzed for VOCs by EPA method 8010. None were detected.
- b: Sample contains lower molecular weight hydrocarbons.
- c: Reported as motor oil



#### Table 2

# Soil Sample Analytical Results Volatile and Semi-Volatile Organic Compounds Former Unocal Service Station

20405 Redwood Road, Castro Valley, California

- 7	C		240		11
- (	Concentr	anons	ın	mg/	KQ)
١,	COLLECTION	CCCT CLAY		***	~~~

Well	Depth	Phenanthrene	Fluoranthene	Pyrene	bis(2-Ethylhexyl) phthalate						
December 19	89, Soil Inves	tigation and N	Ionitoring We	ll Installation							
MW-4*	<b>MW-4*</b> 5		( e	·=0	=						
	8.5		-	(=5)	+						
	13	=	-	8	=						
November 19	993, Soil Borin	igs									
SP-2*	1	2			-						
SP-1*	16		₩.	.5	8						
November 1	998, UST Rem	oval									
wo	8	0.10	0.17	0.22	0.6						
SUMP	4.5	< 0.10	< 0.10	< 0.10	< 0.50						
August 1999	, Waste Oil an	d Clarifier Su	mp Pit Sampl	ing							
SUMP	7	<0.10	< 0.10	< 0.10	< 0.50						
wo	10	<0.10	0.13	0.20	0.82						
September 1	September 1999, Waste Oil Pit Sampling										
wo	11.5	<0.10	< 0.10	< 0.10	< 0.50						
Matag			•								

#### Notes:



<sup>-:</sup> Not analyzed

<sup>\*:</sup> Samples were analyzed for VOCs by EPA Method 8260 only; none were detected above reportable detection limits

Table 3
Groundwater Monitoring Analytical Results
Petroleum Hydrocarbon Constituents
Former Unocal Service Station
20405 Redwood Road, Castro Valley, California

	(Concentrations in Eging)										
Well	Date	TPHg	ТРНА	Total Oil and Grease	Benzene	Toluene	Ethylbenzene	Xylenes	MTBE		
MW-2	12/89	72		_	< 0.5	<0.5	< 0.5	<0.5	-		
11211	8/90	180	_	5-2	21	3.9	7.2	28	-		
	1/91	430	_	-	50	33	22	110	-		
	4/91	4,800	*	-	640	520	140	790	2#2		
	7/91	220	- 4	100	14	1	17	8	(#)		
	10/91	170	2	~	2.9	ND	2.5	6	: <del>*</del> )		
	1/92	5,200	2	74	480	870	160	860	X <del>=</del> 3		
	4/20/92	300	-	<u> </u>	70	0.3	15	7			
	7/9/92	84		-	10	ND	0.6	2.3	-		
	10/8/92	ND		-	2,3	ND	2.3	3	-		
	1/12/93	170		-	11	5.1	1.4	6.3	( <u>1</u> =)		
	3/4/93	720	-	3 <b>:</b>	110	32	67	28	-		
	7/1/93	220	¥	R#I	17	1.1	6	12	:( <del>=</del> )		
	10/19/93	98	÷	24	4.0	ND	2.3	3.1	:=		
	1/12/94	130	2	14	13	3,4	4.9	9.2	11 <b>4</b> 1		
	4/25/94	270	ŝ	14	23	1.1	8.2	17	- 1		
	7/28/94	180	-	. T	14	0.7	5.8	12	( <u>a</u>		
	10/13/94	97		<u>.</u> =	2.8	ND	2.9	1.8			
	1/10/95	440	*	oe:	48	2.8	15	27	V <del>e</del> z		
	4/19/95	480	-	:(₩:	72	2.8	47	22	;:=:		
	10/12/95	450	-	::e:	7.4	ND	5.1	5.5	. <del></del>		
	4/12/96	690	*	-	41	2.8	27	50	ne		
	10/8/96	180	<u>=</u>	-	9.4	0.5	7.2	9.4	1,400		
	4/9/97	470	<u>a</u>	12	23	1.6	21	31.4	1,800		
	11/5/97	360	-		6.8	0.64	4.7	8.2	1,200		
	3/1/00	560	-	1.2	14	0.92	16	24	1,400		
	9/00	180	-	5.00	0.89	ND	1	0.65	620		
	3/22/01	1,000	*	:#:	ND	ND	ND	ND	1,300 <sup>1</sup> /1,200		
	8/23/01	160	·#	( <del>m</del>	22	1.5	17	27	690 <sup>1</sup> /820		
	3/02	140	<b>4</b>	-	2.6	0.31	2	1.7	420		
	10/02	92	2	-	ND	ND	ND	ND	280		
	03/03	IA	IA	IA	IA	IA	IA	IA	IA		
	9/17/03	IA	IA	IA	IA	IA	IA	IA	IA		
	11/20/08	IA	IA	IA	IA	IA	IA	IA	IA		
	2/11/09*	<50	<50	-	<0.3	<0.3	<0.3	<0.3	62		
	8/25/09	CNL	CNL	CNL	CNL	CNL	CNL	CNL	CNL		
	8/4/10	CNL	CNL	CNL	CNL	CNL	CNL	CNL	CNL		



Table 3
Groundwater Monitoring Analytical Results
Petroleum Hydrocarbon Constituents
Former Unocal Service Station
20405 Redwood Road, Castro Valley, California

,	(Concentrations in µg/kg)										
Well	Date	TPHg	PHdT	Total Oil and Grease	Benzene	Toluene	Ethylbenzene	Xylenes	MTBE		
MW-3	12/89	<50	-	(e:	< 0.5	< 0.5	<0.5	< 0.5	(*)		
1,1,1,	8/90	290	2	: E	55	3.8	20	59	-		
	1/91	110	2	-	29	3.3	9.7	34	5 <b>=</b> 6		
	4/91	3,600	- 	-	450	270	150	760	-		
	7/91	220		-	14	14	33	8.0	944		
	10/91	ND	ND	ND	ND	ND	ND	ND	*		
	1/92	60	*	-	4.0	10	2.0	8.0			
	4/20/92	ND	-	0#1	1.0	0.4	ND	0.9	S=2		
	7/9/92	ND	2	-	1.3	0.40	ND	1.3	ije:		
	10/8/92	ND	¥	-	2.1	ND	ND	0.30	:=:		
	1/12/93	ND	-	020	1.2	1.0	0.60	4.1	:=		
	3/4/93	330	<u> </u>	-	32	0.90	64	13	:=		
	7/1/93	330	=	-	24	11	14	82	020		
	10/19/93	ND			5.0	ND	0.60	1.2	(%)		
	1/12/94	69	*	0€	13	3.4	4.9	9.2			
	4/25/94	62	*	( <del>6</del> )	17	1.0	4.9	24	38		
	7/28/94	52	·	100	7.2	0.4	1.6	4.6	-		
	10/13/94	ND	ω_	24	0.9	ND	ND	ND	1040		
	1/10/95	250	<u>=</u>	TE .	26	0.60	14	45	(#		
	4/19/95	450	<u> </u>	12	26	0.60	40	19	-		
	10/12/95	340	-	1-	9.0	3.9	8.5	34	-		
	4/12/96	170	-	4.5	41	2.8	27	50	-		
	10/8/96	79	-	-	3.8	1.5	2.1	6.8	55		
	4/9/97	120	*	-	7.3	ND	3.3	5.4	230		
	11/5/97	62	: <del>-</del>	-	1.7	1.4	2.3	8.3	65		
	3/1/00	96	<u>=</u>		0.61	ND	ND	ND	240		
	9/00	ND	-	-	ND	ND	ND	ND	98		
	3/22/01	ND	=	-	ND	ND	ND	ND	190		
	8/23/01	ND		<u> </u>	ND	ND	ND	ND	26		
	3/02	ND	=		ND	ND	ND	ND	26		
	10/02	ND		7:	ND	ND	ND	ND	15		
	3/03	IA	IA	IA	IA	IA	IA	IA	IA		
	9/17/03	ND	-	-	ND	ND	ND	ND	13		
	11/20/08	IA	IA	IA	IA	IA	IA	IA	IA		
	2/11/09*	<50	<50	#	< 0.3	<0.3	<0.3	<0.3	12		
	8/25/09	CNL	CNL	CNL	CNL	CNL	CNL	CNL	CNL		
	8/4/10	CNL	CNL	CNL	CNL	CNL	CNL	CNL	CNL		



Table 3
Groundwater Monitoring Analytical Results
Petroleum Hydrocarbon Constituents
Former Unocal Service Station
20405 Redwood Road, Castro Valley, California

	(Concentations in µg/kg)									
Well	Date	TPHg	рнал	Total Oil and Grease	Benzene	Toluene	Ethylbenzene	Xylenes	MTBE	
MW-4	12/89	<50	<100	<5,000	< 0.5	< 0.5	< 0.5	<0.5	-	
	08/90	ND	ND	ND	ND	ND	ND	ND	:=:	
	1/91	9/	ĝ	-	-	-	<u>=</u>	=	-	
	4/91	ND	ND	ND	ND	ND	ND	ND	120	
	7/91	**		-	-	<del>.</del>	=	12		
	10/91	ND	ND	ND	ND	ND	ND	ND	188	
	1/92	90	-	-	-	-	-	S-2.	.=	
	4/20/92	ND	ND	ND	ND	ND	ND	ND	3e-	
	7/9/92	-	-	-	-	(# ):	-		:=:	
	10/8/92	ND	120	ND	ND	ND	ND	ND	::=:	
	1/12/93	ND	ND	ND	ND	ND	ND	ND	:==	
	3/4/93	ND	ND	ND	ND	ND	ND	ND	-	
	7/1/93	ND	ND	1,000	ND	ND	ND	ND	=	
	10/19/93	ND	ND	ND	0.40	ND	ND	0.40	-	
	4/25/94	ND	ND	ND	ND	ND	ND	0.40	).e.	
	7/28/94	ND	86	ND	ND	0.60	ND	ND	· •	
	10/13/94	70	ND	ND	ND	36	ND	1.3	1.0	
	1/10/95	ND	ND	2,000	ND	ND	ND	ND	ne:	
	4/19/95	ND	ND	ND	ND	ND	ND	ND	-	
	10/12/95	ND	ND	-	ND	ND	ND	ND	-	
	4/12/96	ND	ND	=	ND	ND	ND	ND	-	
	10/8/96	ND	ND	-	ND	ND	ND	ND	ND	
	4/9/97	ND	ND	=:	ND	ND	ND	ND	ND	
	11/5/97	ND	ND	-	ND	ND	ND	ND	ND	
	Abandoned I	December 1	999.							



Table 3
Groundwater Monitoring Analytical Results
Petroleum Hydrocarbon Constituents
Former Unocal Service Station
20405 Redwood Road, Castro Valley, California

					ono m pg				
Well	Date	ТРНg	TPHd	Total Oil and Grease	Benzene	Toluene	Ethylbenzene	Xylenes	MTBE
MW-5	4/13/92	ND	-	(e.	ND	ND	ND	ND	:#:
	4/27/92	ND		re.	ND	ND	ND	ND	250
	7/9/92	ND	2	-	ND	ND	ND	ND	S <del>-</del> 1
	10/8/92	ND	2	12	ND	0.40	ND	ND	: <del>-</del> :
	1/12/93	ND	9	-	ND	ND	ND	ND	: e:
	3/4/93	ND	=		ND	ND	ND	ND	-
	7/1/93	ND		-	ND	ND	ND	ND	-
	10/19/93	ND	× .	35	ND	ND	ND	ND	- 1
	4/25/94	ND	*		ND	0.40	ND	1.0	-
	7/94	-	÷	06	380	-	-	3€	-
	10/13/94	87	ND	ND	ND	36	ND	1.3	-
	1/95	-	-	i iii	- 1	-	-	-	-
	4/19/95	ND	<u>a</u>	- 4	ND	ND	ND	ND	-
	10/12/95	ND	à	18	ND	ND	ND	ND	-
	4/12/96	ND	-	-	ND	ND	ND	ND	-
	10/8/96	ND	-	-	ND	ND	ND	ND	ND
	4/9/97	ND	-		ND	ND	ND	ND	ND
	11/5/97	ND	ND	#:	ND	ND	ND	ND	ND
	3/1/00	ND	-	#	ND	ND	ND	ND	ND
	9/00	ND	2	<u>=</u>	ND	ND	ND	ND	ND
	3/22/01	ND	3	-	ND	ND	ND	ND	ND
	8/23/01	NS	NS	NS	NS	NS	NS	NS	NS
	3/02	NS	NS	NS	NS	NS	NS	NS	NS
	10/02	NS	NS	NS	NS	NS	NS	NS	NS
	3/03	NS	NS	NS	NS	NS	NS	NS	NS
	9/17/03	NS	NS	NS	NS	NS	NS	NS	NS
	11/20/08*	<50	<50	÷	0.31	<0.3	<0.3	0.38	<5.0
	2/6/09*	<50	<50	~	<0.3	<0.3	<0.3	<0.3	<5.0
	8/25/09	<50	<50	ĕ	<0.5	<0.5	<0.5	< 0.5	<5.0
	8/4/10	<50	<100		<0.3	< 0.3	< 0.3	< 0.3	<1.0



Table 3 Groundwater Monitoring Analytical Results Petroleum Hydrocarbon Constituents **Former Unocal Service Station** 20405 Redwood Road, Castro Valley, California
(Concentrations in μg/kg)

P	(Concentrations in µg/kg)									
Well	Date	TPHg	PHdl	Total Oil and Grease	Benzene	Toluene	Ethylbenzene	Xylenes	MTBE	
MW-6	4/13/92	ND		0+:	ND	0.30	ND	ND	-	
1,1,1,0	4/27/92	ND	₩	24	ND	ND	ND	ND	:=:	
	7/9/92	ND	=	22	ND	ND	ND	ND	:=:	
	10/8/92	ND	2	7≦:	ND	ND	ND	ND	5 <b>.=</b> 5	
	1/12/93	ND	2	( <u>@</u>	ND	ND	ND	ND	· ·	
	3/4/93	ND	=		ND	ND	ND	ND	-	
	7/1/93	ND		:#:	ND	ND	ND	ND	差	
	10/19/93	ND	*	XH.	ND	ND	ND	ND	15	
	4/25/94	ND	¥	(e)	ND	0.30	ND	0.40		
	7/94	( <b>4</b> )	¥	-	580	-	-	-	::5	
	10/13/94	160	8	2₩	0.40	140	0.5	2.3	: <u>=</u>	
	1/95	-	2	-	-	-	-	-	-	
	4/19/95	ND	<u> </u>	-	ND	ND	ND	ND		
	10/12/95	ND	₹	1-	ND	ND	ND	ND	-	
	4/12/96	ND	5	-	2.9	2.9	ND	ND	-	
	10/8/96	ND	*	-	ND	ND	ND	ND	17	
1	4/9/97	ND	*	-	ND	ND	ND	ND	ND	
	11/5/97	ND	ND	-	ND	ND	ND	ND	9.0	
	3/1/00	78	=	E.	ND	0.49	ND	ND	260	
	9/00	54	<u>u</u>	10	ND	ND	ND	ND	170	
	3/22/01	130	9	2	ND	ND	ND	ND	440	
	8/23/01	79	ĕ	- 1	ND	ND	ND	ND	280 <sup>1</sup> /350	
	3/02	91	-	-	ND	ND	ND	ND	370	
	10/02	83	=	<del>-</del>	ND	ND	ND	ND	260	
	3/03	61	:=	==	ND	ND	ND	ND	200	
	9/17/03	140	<b>34</b>	#:	ND	ND	ND	ND	440	
	11/20/08*	<50	<50	#	0.81	<0.3	<0.3	<0.3	300	
	2/6/09*	97	<50	-	<0.3	<0.3	<0.3	<0.3	200	
	8/25/09	NS	NS	NS	NS	NS	NS	NS	NS	
	8/4/10	<50	<100	-	<0.3	<0.3	<0.3	< 0.3	54	



Table 3
Groundwater Monitoring Analytical Results
Petroleum Hydrocarbon Constituents
Former Unocal Service Station
20405 Redwood Road, Castro Valley, California

(Concentrations in Eging)									
Well	Date	TPHg	TPHd	Total Oil and Grease	Benzene	Toluene	Ethylbenzene	Xylenes	MTBE
MW-7	4/13/92	1,300	2	92	0.40	0.30	0.30	0.9	2 <b>-</b> 2
	4/27/92	1,100	2	36	ND	ND	ND	ND	:=:
	7/9/92	830	9	-	ND	ND	ND	ND	:=:
	10/8/92	3,900	=		ND	ND	ND	ND	- 1
	11/30/92	2,700	ND	-	- 1	-	2	-	-
	1/12/93	Ú	U	U	U	U	U	U	U
	1/93	1,900	-	-	ND	ND	ND	ND	
	3/4/93	830	-	( <b>*</b>	ND	ND	ND	ND	-
	7/1/93	680	-	=	ND	ND	ND	ND	15
	10/19/93	360	<u>=</u>	<u>=</u>	ND	ND	ND	0.70	-
	1/12/94	330	-	<u>=</u>	ND	ND	ND	ND	38
	4/25/94	360	ž.	8	ND	ND	ND	ND	2
	7/28/94	-	-	<b></b>	-	- 3	=	-	=
	10/13/94	:0:	-	E-	-		š	-	€
	1/95	æ.	-	#	-	-	-	-	· ·
	4/19/95	(#)	-	*	ND	ND	ND	ND	. 5
	10/12/95	-	20	¥	ND	ND	ND	ND	-
	4/12/96		4	2	ND	ND	ND	ND	*
	10/8/96	-	27	<u>=</u>	22	-	940	-	-
	4/9/97	-	<b>4</b> S	2	92	126	#:	-	<u>~</u>
	11/5/97	-	. <del></del>	-	-	-	20	-	=
	3/1/00	ND			890	ND	ND	ND	ND
	9/00	770	:=x		3.0	0.32	13	27	ND
	3/22/01	630	90	-	ND	ND	ND	ND	ND
	8/23/01	800	-	~	ND	ND	ND	ND	7.3 <sup>1</sup> /ND
	3/02	280	-	-	0.35	ND	0.91	2.2	7.7
	10/02	IA	IA	IA	IA	IA	IA	IA	IA
	3/03	IA	IA	IA	IA	IA	IA	IA	IA
	9/17/03	IA	IA	IA	IA	IA	IA	IA	IA
	11/20/08	520	70	-	< 0.3	<0.3	< 0.3	< 0.3	<5.0
	2/6/09*	400	<50	-	<0.3	<0.3	<0.3	<0.3	<5.0
	8/25/09	IA	IA	IA	IA	IA	IA	IA	IA
	8/4/10	430	<100	3	<0.3	<0.3	<0.3	<0.3	<1

# Table 3 Groundwater Monitoring Analytical Results Petroleum Hydrocarbon Constituents Former Unocal Service Station 20405 Redwood Road, Castro Valley, California

(Concentrations in µg/kg)

Well	Date	TPHg	TPHd	Total Oil and Grease	Benzene	Toluene	Ethylbenzene	Xylenes	MTBE
MW-101	9/95	9,400	2	96	170	94	150	710	
	3/01/00	40,000	=	· ·	2,500	490	4,300	10,000	2,400 <sup>1</sup> /1,400
	9/00	770	≘	2	3.0	0.32	13	27	-
	3/01	34,000	8	鑩	1,400	62	3,400	7,700	970
	8/23/01	12,000	-	.=	630	ND	1,500	480	1,400
	3/02	19,000	<u>.</u>	<u>u</u> =:	600	25	1,600	3,100	1,600 <sup>1</sup> /870
	10/02	5,200	-	<del>.</del> (€)	240	0.74	230	76	1,500 <sup>1</sup> /1,400
	3/03	6,300	×	:(€:	330	ND	440	370	1,400 <sup>1</sup> /840
	9/17/03	3,000	*		150	ND	100	110	850 <sup>1</sup> /1,100
	11/20/08*	2,800	5,400		61	<0.3	38	1.6	570
	2/6/09*	<50	3,600	-	<0.3	< 0.3	<0.3	<0.3	630
	8/25/09	2,200	1,500	-	9.9	< 0.5	14	5.6	440
	8/4/10	1,100	<100	-	11	< 0.3	12	4.8	280
SP-1	11/1993	49,000		H	3,900	13,000	2,800	15,000	
SP-2	11/1993	1,400	ä	€	54	240	87	390	

#### Notes:

ND: Not detected.

<: Not detected above laboratory's indicated reportable detection limit.

NS: No sample collected.

IA: Well inaccessible at time of sampling.

CNL: Could not locate well.

U: Unavailable.

-: Not analyzed.

\*: Other fuel oxygenates and 1,2-DCA not detected above 5  $\mu$ g/L (50  $\mu$ g/L for TBA).

1: MTBE by EPA method 8015/8020; otherwise by EPA Method 8260.



Table 4
Groundwater Monitoring Analytical Results
Volatile Organic Compounds
Former Unocal Service Station
20405 Redwood Road, Castro Valley, California

		Chlorobenzene	Chloroform	cis-1,2- Dichloroethene	- ethene	1,2-Dichloroethane	Tetrachloroethene	Trichloroethene
Well	Date	Chlor	Chlor	cis-1,2 Dichlo	trans-1,2 Dichloro	1,2-D	Tetra	Trich
MW-2	3/4/93	<0.5	<0.5	<0.5	< 0.5	0.6	< 0.5	< 0.5
	10/19/93	< 0.5	< 0.5	< 0.5	< 0.5	<0.5	<0.5	<0.5
MW-4	12/14/89	< 0.5	< 0.5	=	< 0.5	< 0.5	< 0.5	< 0.5
	3/4/93	< 0.5	<0.5	< 0.5	< 0.5	< 0.5	< 0.5	< 0.5
	10/19/93	< 0.5	< 0.5	< 0.5	< 0.5	< 0.5	0.7	0.9
MW-5	3/4/93	<0.5	< 0.5	< 0.5	< 0.5	< 0.5	0.8	< 0.5
MW-6	3/4/93	< 0.5	< 0.5	< 0.5	< 0.5	< 0.5	3.5	< 0.5
MW-7	11/30/92	2.0	2.0	180	1.5	-	14,000	660
	3/4/93	-	<20	20	<20	<20	3,700	210
SP-1	11/18/93	unknown	unknown	28	15	12	22	20
SP-2	11/18/93	unknown	unknown	ND	ND	ND	ND	ND

#### Notes:



<sup>&</sup>lt;: Not detected above laboratory's indicated reportable detection limit.

<sup>-:</sup> Not analyzed

Table 5
Summary of Groundwater Elevation Data
Former Unocal Service Station
20405 Redwood Road, Castro Valley, California

Depth to Date **Casing Elevation** Groundwater **Groundwater Elevation** Well Measured (Feet above MSL) (Feet) (Feet above MSL) 09/95 U MW-101 3/1/00 9.75 09/00 U 03/01 U 08/23/01 9.70 03/02 U U 10/02 U 03/03 9.80 9/17/03 10.69 11/20/08 10.46 2/6/09 10.53 8/25/09 8/4/10 11.47 U MW-2 12/89 U U 08/90 U 01/91 U 04/91 07/91 U 10/91 U U 01/92 172.74 183.10 10.36 4/20/92 172.45 7/9/92 10.65 171.87 10/8/92 183.47 11.60 1/12/93 9.11 174.36 9.28 174.19 3/4/93 173.10 10.37 7/1/93 172.65 10.82 10/19/93 10.66 172.81 1/12/94 173.24 10.23 4/25/94 172,77 10.70 7/28/94 169.28 14.19 10/13/94 1/10/95 8.12 175,35 4/19/95 9.24 174.23 172.81 10.66 10/12/95 173.42 4/12/96 10.05 172.86 10/8/96 10.61 173.07 4/9/97 10.40 172.59 10.88 11/5/97 8.49 174.98 3/1/00 U 09/00 173.82 3/22/01 9.65 9.65 173.82 8/23/01 U 03/2002 U 10/2002 03/2003 IA 9/17/03 IA 11/20/08 IA 2/11/09 U 8/25/09 CNL CNL 8/4/10



Table 5
Summary of Groundwater Elevation Data
Former Unocal Service Station
20405 Redwood Road, Castro Valley, California

			Depth to	
	Date	Casing Elevation	Groundwater	<b>Groundwater Elevation</b>
Well	Measured	(Feet above MSL)	(Feet)	(Feet above MSL)
MW-3	12/89	U	U	=
	08/90		U	*
	01/91		U	<u>=</u>
	04/91		U	:=
	07/91		U	<u> </u>
	10/91		U	2
	01/92		U	-
	4/20/92	183.52	10.34	173.18
	7/9/92		10.84	172.68
	10/8/92	184.03	11.96	172.07
	1/12/93		9.28	174.75
	3/4/93		9.53	174.50
	7/1/93		10.56	173.47
	10/19/93		11.04	172.99
	1/12/94		10.90	173.13
	4/25/94		10.37	173.66
	7/28/94		10.95	173.08
	10/13/94		14.37	169.66
	1/10/95		8.23	175.80
	4/19/95		9.54	174.49
	10/12/95		10.97	173.06
	4/12/96		10.06	173.97
	10/8/96		10.87	173.16
	4/9/97		10.40	173.63
	11/5/97		10.97	173.06
	3/1/00		8.68	175.35
	09/00		U	<b>=</b> 0
	3/22/01		10.22	173.81
	8/23/01		10.02	174.01
	03/02		U	<b>*</b> :
	10/02		U	(=)
	03/03		U	3
	9/17/03		10.00	174.03
	11/20/08		IA	æ.;
	2/11/09		U	蒙
	8/25/09		CNL	-
	8/4/10		CNL	<del>(2</del> )



Table 5
Summary of Groundwater Elevation Data
Former Unocal Service Station

20405 Redwood Road, Castro Valley, California

		403 Reuwood Road, Cas	, , , , , , , , , , , , , , , , , , , ,	
Well	Date Measured	Casing Elevation (Feet above MSL)	Depth to Groundwater (Feet)	Groundwater Elevation (Feet above MSL)
MW-4	12/89	U	U	
	08/90		U	=
	01/91		U	-
	04/91		U	
	07/91	,	U	≅
	10/91		U	÷
	01/92		U	
	4/20/92		10.89	<u> </u>
	7/9/92	184.33	10.65	173.68
	10/8/92	184.61	12.78	171.83
	1/12/93		9.67	174.94
	3/4/93		10.20	174.41
	7/1/93		11.41	173.20
	10/19/93		11.92	172.69
	4/25/94		10.94	173.67
	7/28/94		11.74	172.87
	10/13/94		15.31	169.30
	1/10/95		8.02	176.59
	4/19/95		9.97	174.64
	10/12/95		11.70	172.91
	4/12/96		10.33	174.28
	10/8/96		11.65	172.96
	4/9/97		10.93	173.68
	11/5/97		11.82	172.79

MW-4 abandoned December 1999.



Table 5
Summary of Groundwater Elevation Data
Former Unocal Service Station
20405 Redwood Road, Castro Valley, California

			Depth to	
	Date	Casing Elevation	Groundwater	Groundwater Elevation (Feet
Well	Measured	(Feet above MSL)	(Feet)	above MSL)
MW-5	4/27/92	183.62	11.72	171.90
	7/9/92		12.24	171.38
	10/8/92	183.92	13.24	170.68
	1/12/93		10.30	173.62
	3/4/93		10.53	173.39
	7/1/93		11.85	172.07
	10/19/93		12.32	171.60
	4/25/94		11.58	172.34
	07/94		U	
	10/13/94		15.71	168.21
	01/95		U	-
li .	4/19/95		10.41	173.51
	10/12/95		12.12	171.80
	4/12/96		10.85	173.07
	10/8/96		12.00	171.92
	4/9/97		11.40	172.52
	11/5/97		12.19	171.73
	3/1/00		9.45	174.47
	09/00		U	-
	3/22/01		11.04	172.88
	8/23/01		11.06	172.86
	03/02		NS	:#c
	10/02		NS	==0
	03/03		NS	
	9/17/03		11.03	172.89
	11/20/08		11.80	172.12
	2/6/09		11.56	172.36
	8/25/09		11.90	172.02
	8/4/10		11.61	172.31



Table 5
Summary of Groundwater Elevation Data
Former Unocal Service Station
20405 Redwood Road, Castro Valley, California

Well	Date Measured	Casing Elevation (Feet above MSL)	Depth to Groundwater (Feet)	Groundwater Elevation (Feet above MSL)
MW-6	4/27/92	U	11.90	171.80
	7/9/92	183.70	12.34	171.36
	10/8/92	183.96	13.3	170.66
	1/12/93	183.60	10.59	173.01
	3/4/93		10.86	172.74
	7/1/93		12.00	171.60
	10/19/93		12.48	171.12
	4/25/94		11.86	171.74
	07/94		U	
	10/13/94		15.87	167.73
	01/95		U	*
	4/19/95		10.70	172.90
	10/12/95		12.32	171.28
	4/12/96		11.09	172.51
	10/8/96		12.19	171.41
	4/9/97		11.70	171.90
	11/5/97		12.33	171.27
	3/1/00		9.73	173.87
	09/00		U	E
	3/22/01		11.01	172.59
	8/23/01		11.21	172.39
	03/02		U	<del>.</del>
	10/02		U	-
	03/03		U	-
	9/17/03		11.50	172.10
	11/20/08		12.10	171.50
	2/6/09		11.83	171.77
	8/25/09		Dry	-
	8/4/10		12.85	170.75

Table 5
Summary of Groundwater Elevation Data
Former Unocal Service Station
20405 Redwood Road, Castro Valley, California

			Depth to	
	Date	Casing Elevation	Groundwater	Groundwater Elevation (Feet
Well	Measured	(Feet above MSL)	(Feet)	above MSL)
MW-7	4/27/92	182.52	10.97	171.55
	7/9/92		11.43	171.09
	10/8/92	182.78	12.40	170.38
	11/30/92		12.00	170.78
	1/12/93		9.51	173.27
	01/93		U	<u>=</u> 1
	3/4/93		9.88	172.90
	7/1/93		11.07	171.71
	10/19/93		11.55	171.23
	1/12/94	182.42	11.36	171.06
	4/25/94		10.85	171.57
	7/28/94		NS	550
	10/13/94		NS	=
	01/95		U	5 <b>4</b> 9
	4/19/95		9.66	172.76
	10/12/95		11.34	171.08
	4/12/96		10.06	172.36
	10/8/96		11.16	171.26
	4/9/97		11.70	170.72
	11/5/97		11.36	171.06
	3/1/00		8.72	173.70
	09/00		U	-
	3/22/01		10.04	172.38
	8/23/01		10.18	172.24
	03/02		U	3#3
	10/02		IA	( <u>a</u> )
	03/03		IA	· ·
	9/17/03		IA	: <b>:</b> ::::::::::::::::::::::::::::::::::
	11/20/08		11.05	171.37
ľ	2/6/09		10.76	171.66
	8/25/09		IA	:#0
	8/4/10		10.76	171.66

Notes:

IA: Well Inaccessible CNL: Could not locate well NS: Well Not Sampled U: Data Unavailable

-: Unable to calculate elevation




Table 6 **Summary of Groundwater Flow Direction and Gradient Data Former Unocal Service Station** 20405 Redwood Road, Castro Valley, California

Date	Flow Direction	Gradient (Feet/Foot)	
11/1/92	Southeast	0.006	
1/27/93	Southeast	0.01	
3/4/93	Southeast	0.01	
7/1/93	Southeast	0.01	
10/19/93	South	0.005	
1/12/94	South	0.001	
5/13/94	Southwest	0.007	
10/13/94	South	0.001	
1/31/95	South	0.002	
5/17/95	South	0.009	
10/30/95	South	0.007	
4/12/96	South	0.008	
11/5/96	South	0.008	
4/9/97	South	0.01	
8/23/01	South	0.008	
9/17/03	Southeast	0.01	
11/20/08	Southeast	0.01	
2/5/09	South-southeast	0.01	
8/25/09	-	u,	
8/4/10	East-southeast	0.01	

-: Unable to calculate flow direction



#### **FIGURES**






### SITE VICINITY

FORMER UNOCAL SERVICE STATION 20405 REDWOOD ROAD CASTRO VALLEY, CALIFORNIA FIGURE 1

PROJECT: E0805401S





BSK Associates Engineers Laboratories

FORMER UNOCAL SERVICE STATION 20405 REDWOOD ROAD CASTRO VALLEY, CALIFORNIA

PROJECT: E0805401S

DATE: 1/6/10





#### **LEGEND**

- Soil Sample Location
  - Approximate Extent of Excavation
- Monitoring Well Location
- Abandoned Monitoring Well Location





# EXTENT OF EXCAVATIONS AND EXCAVATION SOIL SAMPLE LOCATIONS

FORMER UNOCAL SERVICE STATION 20405 REDWOOD ROAD CASTRO VALLEY, CALIFORNIA FIGURE 3

**PROJECT: E0805401S** 

DATE: 2/12/09








#### **MW-2 TIME-SERIES PLOTS**

FORMER UNOCAL SERVICE STATION 20405 REDWOOD ROAD CASTRO VALLEY, CALIFORNIA FIGURE 5

PROJECT: E0503102S

DATE: 1/6/11






## **MW-3 TIME-SERIES PLOTS**

FORMER UNOCAL SERVICE STATION 20405 REDWOOD ROAD CASTRO VALLEY, CALIFORNIA

PROJECT: E0503102S

DATE: 1/6/11






## **MW-6 TIME-SERIES PLOTS**

FORMER UNOCAL SERVICE STATION 20405 REDWOOD ROAD CASTRO VALLEY, CALIFORNIA

FIGURE 7

PROJECT: E0503102S

DATE: /6/11






## **MW-7 TIME-SERIES PLOTS**

FORMER UNOCAL SERVICE STATION 20405 REDWOOD ROAD CASTRO VALLEY, CALIFORNIA

PROJECT: E0503102S

DATE: 1/6/10



FORMER UNOCAL SERVICE STATION 20405 REDWOOD ROAD CASTRO VALLEY, CALIFORNIA

PROJECT: E0503102S

DATE: 1/6/11

## APPENDIX A

Project Na	ame: Un	ocal	`	Job #:	EOS	305	4015	Field Personnel: E. Basel						
Day: Mor	ı Tu Wed	Thur Fi	ri Sat Sun	Date:	8/	4110	5	Weather: Clear Partly Cloudy Overcast Rain (circle) Cold Cool Warm Hot Very Hot						
Well:			HW.	101				asurement Technique:						
Static Dep	th to Water	-Ft. (A)	11.4	7		Pur	ge Method:	Grundfos Submersible Pump Pneumatic Pump						
Total Dep	th of Casing	g-Ft. (B)	29.3	1		(Ci	ircle)	Clectric Panp Hand Bailed						
Total Ft. o	f Water	(B-A		4				Other						
Casing Dia	a-in.	12,00	2" (43)	6" 8"			Dedicated System: Yes							
Casing Ca	pacity-gal/f	t (C)	.163 653	1.46 2.50			edicated System: Yes X No							
Gallons pe	er Casing V	olume	(B-A)*C	12		pН	H Calibration: 4.0 7.0 10.0 EC Calibration(μmhos) 10.0							
Time	Gallons Purged	Casin Volume		EC (µmhos)	Ten (EF) (		Turbidity NTU or D.O.mg/l	Remarks (Color, Odor, Turbidity, etc.)						
10:05	0	0	2000			-		Started Purge/Opened Sample Port						
10:12	12	1	6.41	803	67.	5	-	clear HC adas						
10:19	24	2	6.82	795	68.		-	clear, HC odor						
10:25	36	3	6.95	788	68.		_	<sup>ζ</sup> 1 12						
					_			347						
								Sampled/Stopped	, i					
Chloride Sulfate				Nitrate		X4.4		Other Field Results:						
Purge Pun	np On		0:05 I	ischarge Me	asurem	ent: (	(Circle) (Bi	cket Tank Flowmeter						
Purge Pun	np Off	100	0:25 s	ample Collec	ction Mo	ethod:		t From Discharge Hose						
Total Galle	ons Purged	811				=	Teflor	BailerDisposable Bailer						
Purge Rate	e (gpm)	500	r	ce Chest Coo	lant _<	<u> </u>	Crushed Ice	Blue Ice	-					
Sample Time			Analys	es				Amount/Container Used Sam Descrip						
10:32							4 × 40	Muoac						
							1 * 2	M voas so amber hyso	4					
									-					
				_ X										
Well Vault	Туре:	4	Phish					roduct: Yes No NA						
Lock Num	ber/Type:							Le						
Drums Fill	ed/Used:	1.	125				Descriptio	n:						
			9											
Notes:														
-														
									-					
									$\equiv$					

Project Na	ıme: Un	ocal		Job #:	E08	05	405	Field Personnel: E, Basel				
Day: Mon		Thur Fri ircle one)	Sat Sun	Date:	8/2	//10	)	Weather: Clear Partly Cloudy Overcast Rain (circle) Cold Cool Warm Hot Very Hot				
Total Dept Total Ft. o Casing Dis Casing Ca Gallons pe Time	th to Water th of Casing f Water a-in. pacity-gal/f r Casing Vo Gallons Purged 0 3.75 7.5	r-Ft. (A) y-Ft. (B) (B-A)  t (C) clume  Casing Volumes  0	11.6 34.3 22.6 29 4" (63).653 (B-A)*C PH	6" 8" 1.46 2.50 3.75  EC (µmhos)  561 553	Tem (EF) (1	Wa (Ci	ater Level Measurement Technique: ircle) Electric Sounder Ser # Not Measured rge Method: Grundfos Submersible Pump Pneumatic Pump Grircle) Electric Pump Hand Bailed Other Dedicated System: Yes No Calibration: Yes No Calibration: Yes No Turbidity Remarks (Color, Odor, Turbidity, etc.)  Turbidity NTU or D.O.mg/l Started Purge/Opened Sample Port  Clear odor US  V 11					
12:56	11.25	3	6.91	547	709	2		N - N				
Chloride		Sulfate		Nitrate	>	(4.4		Other Field Results:				
Purge Pum Purge Pum Total Gallo Purge Rate	np Off		Sa	mple Collec	tion Me	thod	:Direc	t From Discharge Hose BailerDisposable BailerBlue Ice				
Sample Time		ar Ve	Analyses					Amount/Container Used Sample Description				
13:05							1×9	one voos 50 amber H2504				
Well Vault Lock Numl Drums Fill	er/Type:	n	ush nasterlo	cle			Thickness	roduct: Yes No NA  n:				
Notes:			<del>)</del>									

Project N	Iame: UNO	cal		Job #:	E06	054	HOIS	Field Personnel: E. Bacol						
Day: Mo	n Tu Wed	Thur Fri	Sat Sun	Date:	8/4			Weather: Clear Partly Cloudy Overcast Rain (circle) Cold Cool Warm Hot Very Hot						
Well:			MW-	6		Wate (Cir		asurement Technique: Clectric Sounder Ser # Not Measured						
Static De	pth to Water	-Ft. (A)	12.8			Purg	ge Method:	Grundfos Submersible Pump Pneumatic Pump						
Total Dep	oth of Casing	;-Ft. (B)	26.5			(Cir	cle)	Electric Pump Hand Bailed						
Total Ft.	of Water	(B-A)	13.6	9				Other						
Casing D	ia-in.		(2) 4"	6" 8"			Dedicated System: Yes Ng							
Casing C	apacity-gal/f	t (C)	163).653	1.46 2.50		Dedi	cated Syste	m:Yes ×No						
Gallons p	er Casing V	olume	(B-A)*C	2.23		pH C	Calibration: × 4.0 × 7.0 10.0 EC Calibration(μmhos)							
Time	Gallons Purged	Casing Volumes	РН	EC (µmhos)	Tem (EF) (I		Turbidity NTU or D.O.mg/I	Remarks (Color, Odor, Turbidity, etc.)						
8:58	0	0				-		Started Purge/Opened Sample Port						
9:00	2.25	1	5.85	658	67.	,		clear oder/oss						
9:01	4,5	2	5.97	463	68.	4	_	clear odorless						
9:02	<b>6</b> 75	2	6.19	67.4	68.	5	_	(, ,,						
						+								
						Ħ		Sampled/Stopped						
Chloride	Chloride Sulfate I				,	X4.4		Other Field Results:						
				scharge Me	harge Measurement: (Circle) Bucker Tank Flowmeter									
Purge Pu	mp Off			mple Collec	ction Me	ethod:	× Direc	et From Discharge Hose						
Total Gal	lons Purged		75		Teflon BailerDisposable Bailer									
Purge Rat				e Chest Coo	lant _>	Cr	rushed Ice	Blue Ice						
Sample Time			Analyses					Amount/Container Used Sample Description						
9:10							4 V	0A5 40ML						
								250 amber H1504						
								N. N.						
Well Vaul Lock Num		+1	uch laster 10	de			Thickness	roduct: Yes No NA :						
Drums Fil	The state of the s		125				Descriptio	n:						
Notes:														

Project N	ame: Und	seal		Job #:	<b>E08</b>	305	4015	Field Personnel: E.Basel					
Day: Mo	n Tu Wed	Thur Fri	Sat Sun	Date:	8/	4/1	0	Weather: Clear Partly Coudy Overcas (circle) Cold Cool Warm Hot Vo	t Rain ery Hot				
Well:		banker Make	MW-	<b>ી</b>			iter Level Mea ircle) E	asure <u>ment T</u> echnique: :lectric <del>So</del> under Ser # Not M	easured				
Static Dep	th to Water	-Ft. (A)	10.76			Pu	rge Method:	Grundfos Submersible Pump Pneumation	Pump				
Total Dep	th of Casing	g-Ft. (B)	27.07			(C	ircle)	Electric Bump Hand Bail	ed				
Total Ft.	of Water	(B-A)	16.33					Other					
Casing Di	a-in.		<b>25</b> 4"	633 833			Dedicated System: Yes No						
Casing Ca	pacity-gal/f	t (C)	(163) .653	1.46 2.50		De	dicated System	n:Yes <u>&gt;</u> No	12/107				
Gallons p	er Casing V	olume	(B-A)*C			pН	H Calibration: 8 4.0 × 7.0 10.0 EC Calibration(μmhos)						
Time	Gallons Purged	Casing Volumes	РН	EC (µmhos)	Ten (EF) (		Turbidity NTU or D.O.mg/l	Remarks (Color, Odor, Turbidity	/, etc.)				
13:30	0	0		:( <del>*****</del> ):		-		Started Purge/Opened Sample Port					
13:31	275		7.24	617	72	9	_	cloor the sediment or	dorlest				
13:32		2	7.04	640	71.		_	clear to sediment adorless					
13:34	825	3	7.02	631	70.		_	,	, l				
			1					Sampled/Stopped					
Chloride	Chloride Sulfate					X4.4		Other Field Results:					
	np Off ons Purged	13:	34 Sa	mple Collec	ction M	ethod	Teflon	t From Discharge Hose Bailer Disposable Bailer					
Purge Rat	e (gpm)		Ic	e Chest Coo	lant _>	(	Crushed Ice	Blue Ice					
Sample Time			Analyses				H.	Amount/Container Used	Sample Description				
13:36								nul Voas					
							1×2	250ml amber	HOSOY				
			Luš										
Well Vault	Type:	Fu	ush			_		roduct: Yes No NA					
Lock Num	ber/Type:	14	a stella	e				n:					
Drums Fill	led/Used:	پال	US				Description						
Notes:			-										
	- 8												



A0H1054

08/31/2010

Jeff Yeazell BSK Associates - Sacramento 3140 Gold Camp Drive Suite 160 Rancho Cordova, CA 95670

Dear Jeff Yeazell,

Thank you for selecting BSK Analytical Laboratories for your analytical testing needs. We have prepared this report in response to your request for analytical services. Enclosed are the results of analyses for samples received by the laboratory on 08/12/2010 08:00.

If additional clarification of any information is required, please contact your Client Services Representative, Julio Morales at (800) 877-8310 or (559) 497-2888.

**BSK ANALYTICAL LABORATORIES** 

Julio Morales

Client Service Representative

## APPENDIX B



### **Case Narrative**

08/31/2010

### **Work Order Information**

**Client Name:** 

BSK Associates - Sacramento

Submitted by:

Erin Basel

Client Code:

BSKAs9293

Shipped by:

**ONTRAC** 

Work Order:

Project:

A0H1054

**COC Number:** 

**TAT: 10** 

Client Project: E0805401S

**Unocal Castro Valley** 

PO #:

## **Sample Receipt Conditions**

Cooler:

**Default Cooler** 

Temp. °C:

0

Containers Intact COC/Labels Agree

Received On Wet Ice

Packing Material - Bubble Wrap

Packing Material - Foam

Sample(s) were received in temperature range.

Initial receipt at BSK-SAC

Report Manager

Jeff Yeazell Jeff Yeazell Report Format

FAL Final MultiOrder.rpt FAL Final MultiOrder.rpt

A0H1054 FINAL 08312010 1411



Jeff Yeazell BSK Associates - Sacramento 3140 Gold Camp Drive Suite 160 Rancho Cordova, CA 95670 Report Issue Date: 8/31/2010 14:11 Received Date: 08/12/2010 Received Time: 08:00

Lab Sample ID:

A0H1054-01

Sample Date:

08/04/2010 09:10

Sample Type:

Grab

Client Project: E0805401S

Sampled by:

Matrix: Water

Sample Description: MW-6

### **Organics**

Analyte	Method	Resu	ult RL	Units	Dil,	Batch	Prepared	Analyzed	Qualifiers
BTEX and TPH-Gasoline by E	PA 8015B/8021E	3							
*Benzene	8015/8021	ND	0.30	ug/L	1	A007269	08/16/10	08/16/10	
*Ethylbenzene	8015/8021	ND	0.30	ug/L	1	A007269	08/16/10	08/16/10	
*Toluene	8015/8021	ND	0.30	ug/L	1	A007269	08/16/10	08/16/10	
*TPH as Gasoline	8015/8021	ND	50	ug/L	1	A007269	08/16/10	08/16/10	
*Xylene (Total)	8015/8021	ND	0.30	ug/L	1	A007269	08/16/10	08/16/10	
VOCs by EPA 8260B						Samp	le Qualifiers:	: SC07	
*1,2-Dibromoethane (EDB)	EPA 8260B	ND	1.0	ug/L	1	A007267	08/13/10	08/13/10	
*1,2-Dichloroethane	EPA 8260B	ND	1.0	ug/L	1	A007267	08/13/10	08/13/10	
*Di-isopropyl ether (DIPE)	EPA 8260B	ND	1.0	ug/L	1	A007267	08/13/10	08/13/10	
*Ethyl tert-Butyl Ether (ETBE)	EPA 8260B	ND	1.0	ug/L	1	A007267	08/13/10	08/13/10	
*Methyl-t-butyl ether	EPA 8260B	54	1.0	ug/L	1	A007267	08/13/10	08/13/10	
*tert-Amyl Methyl Ether (TAME)	EPA 8260B	ND	1.0	ug/L	1	A007267	08/13/10	08/13/10	
tert-Butyl alcohol (TBA)	EPA 8260B	ND	50	ug/L	1	A007267	08/13/10	08/13/10	
Total Petroleum Hydrocarbon	s by EPA 8015B								
*TPH as Diesel	8015B	ND	100	ug/L	1	A007279	08/16/10	08/17/10	
			Method	Result					
Surrogate: Fluorobenzene			8015/8021	100 %	Acceptable :	range: 70-1	30 %		
Surrogate: Toluene-d8			EPA 8260B	104 %	Acceptable	range: 80-1	30 %		
Surrogate: Tetracosane			8015B	77.4 %	Acceptable	range: 45-1	89 %		

Lab Sample ID:

A0H1054-02

Sample Date:

08/04/2010 10:32

Sample Type:

Grab

Client Project: E0805401S

Sampled by:

Matrix: Water

Sample Description: MW-101

#### **Organics**

- Crgamos									
Analyte	Method	Result	RL	Units	Dil.	Batch	Prepared	Analyzed	Qualifiers
BTEX and TPH-Gasoline	by EPA 8015B/8021	В							
*Benzene	8015/8021	11	0.30	ug/L	1	A007269	08/16/10	08/16/10	
*Ethylbenzene	8015/8021	12	0.30	ug/L	1	A007269	08/16/10	08/16/10	
*Toluene	8015/8021	ND	0.30	ug/L	1	A007269	08/16/10	08/16/10	

A0H1054 FINAL 08312010 1411

1414 Stanislaus Street

Fresno, CA 93706

(559) 497-2888

FAX (559) 485-6935

www.bsklabs.com



Jeff Yeazell **BSK Associates - Sacramento** 3140 Gold Camp Drive Suite 160 Rancho Cordova, CA 95670

Report Issue Date: 8/31/2010 14:11 Received Date: 08/12/2010 Received Time: 08:00

Lab Sample ID:

A0H1054-02

08/04/2010 10:32

Sample Date: Sample Type:

Grab

Client Project: E0805401S

Sampled by:

Matrix: Water

Sample Description: MW-101

#### **Organics**

Analyte	Method	Result	RL	Units	Dil.	Batch	Prepared	Analyzed	Qualifiers
TPH as Gasoline	8015/8021	1100	50	ug/L	1	A007269	08/16/10	08/16/10	
Xylene (Total)	8015/8021	4.8	0.30	ug/L	1	A007269	08/16/10	08/16/10	
VOCs by EPA 8260B						Samp	le Qualifiers:	SC07	
*1,2-Dibromoethane (EDB)	EPA 8260B	ND	1.0	ug/L	1	A007267	08/13/10	08/13/10	
1,2-Dichloroethane	EPA 8260B	ND	1,0	ug/L	1	A007267	08/13/10	08/13/10	
Di-isopropyl ether (DIPE)	EPA 8260B	ND	1.0	ug/L	1	A007267	08/13/10	08/13/10	
*Ethyl tert-Butyl Ether (ETBE)	EPA 8260B	ND	1.0	ug/L	1	A007267	08/13/10	08/13/10	
Methyl-t-butyl ether	EPA 8260B	280	20	ug/L	20	A007267	08/13/10	08/13/10	
tert-Amyl Methyl Ether (TAME)	EPA 8260B	ND	1.0	ug/L	1	A007267	08/13/10	08/13/10	
tert-Butyl alcohol (TBA)	EPA 8260B	ND	50	ug/L	1	A007267	08/13/10	08/13/10	
Total Petroleum Hydrocarbons	s by EPA 8015E	3							
TPH as Diesel	8015B	1300	100	ug/L	1	A007279	08/16/10	08/17/10	
		Meth	nod	Result					
Surrogate: Fluorobenzene		8015	5/8021	110 %	Acceptable	range: 70-1	30 %		
Surrogate: Toluene-d8		EPA	8260B	102 %	Acceptable	range: 80-1	30 %		

Surrogate: Tetracosane

8015B 112 %

Acceptable range: 45-189 %

Lab Sample ID:

A0H1054-03

Sample Date:

08/04/2010 13:05

Sample Type:

Grab

Client Project: E0805401S

Sampled by:

Matrix: Water

Sample Description: MW-5

### **Organics**

Analyte	Method	Result	RL	Units	Dil,	Batch	Prepared	Analyzed	Qualifiers
BTEX and TPH-Gasoline by EPA	8015B/8021B								
*Benzene	8015/8021	ND	0.30	ug/L	1	A007269	08/16/10	08/16/10	
*Ethylbenzene	8015/8021	ND	0.30	ug/L	1	A007269	08/16/10	08/16/10	
*Toluene	8015/8021	ND	0.30	ug/L	1	A007269	08/16/10	08/16/10	
*TPH as Gasoline	8015/8021	ND	50	ug/L	1	A007269	08/16/10	08/16/10	
*Xylene (Total)	8015/8021	ND	0.30	ug/L	1	A007269	08/16/10	08/16/10	
VOCs by EPA 8260B						Samp	le Qualifiers: So	C07	
*1,2-Dibromoethane (EDB)	EPA 8260B	ND	1.0	ug/L	1	A007267	08/13/10	08/13/10	

A0H1054 FINAL 08312010 1411



Jeff Yeazell BSK Associates - Sacramento 3140 Gold Camp Drive Suite 160 Rancho Cordova, CA 95670 Report Issue Date: 8/31/2010 14:11 Received Date: 08/12/2010 Received Time: 08:00

Lab Sample ID:

A0H1054-03

C

08/04/2010 13:05

Sample Date: Sample Type:

Grab

Client Project: E0805401S

Sampled by:

Matrix: Water

Sample Description: MW-5

#### **Organics**

Analyte	Method	Result	RL	Units	Dil.	Batch	Prepared	Analyzed	Qualifiers
*1,2-Dichloroethane	EPA 8260B	ND	1.0	ug/L	1	A007267	08/13/10	08/13/10	
*Di-isopropyl ether (DIPE)	EPA 8260B	ND	1.0	ug/L	1	A007267	08/13/10	08/13/10	
*Ethyl tert-Butyl Ether (ETBE)	EPA 8260B	ND	1.0	ug/L	1	A007267	08/13/10	08/13/10	
*Methyl-t-butyl ether	EPA 8260B	ND	1.0	ug/L	1	A007267	08/13/10	08/13/10	
*tert-Amyl Methyl Ether (TAME)	EPA 8260B	ND	1.0	ug/L	1	A007267	08/13/10	08/13/10	
*tert-Butyl alcohol (TBA)	EPA 8260B	ND	50	ug/L	1	A007267	08/13/10	08/13/10	
Total Petroleum Hydrocarbons	by EPA 8015B								
*TPH as Diesel	8015B	ND	100	ug/L	1	A007279	08/16/10	08/17/10	

Surrogate: Fluorobenzene Surrogate: Toluene-d8 
 Method
 Result

 8015/8021
 102 %

 EPA 8260B
 102 %

 8015B
 107 %

Acceptable range: 70-130 %
Acceptable range: 80-130 %
Acceptable range: 45-189 %

Lab Sample ID:

Surrogate: Tetracosane

A0H1054-04

Sample Date:

08/04/2010 13:36

Sample Type:

Grab

Client Project: E0805401S

Sampled by:

Matrix: Water

Sample Description: MW-7

#### **Organics**

O i guilliou									
Analyte	Method	Result	RL	Units	Dil.	Batch	Prepared	Analyzed	Qualifiers
BTEX and TPH-Gasoline by Ef	PA 8015B/ <u>8021</u> E	<u>3</u>							
*Benzene	8015/8021	ND	0.30	ug/L	1	A007269	08/16/10	08/16/10	
*Ethylbenzene	8015/8021	ND	0.30	ug/L	1	A007269	08/16/10	08/16/10	
*Toluene	8015/8021	ND	0.30	ug/L	1	A007269	08/16/10	08/16/10	
*TPH as Gasoline	8015/8021	430	50	ug/L	1	A007269	08/16/10	08/16/10	
*Xylene (Total)	8015/8021	ND	0.30	ug/L	1	A007269	08/16/10	08/16/10	
VOCs by EPA 8260B						Samp	le Qualifiers:	SC07	
*1,2-Dibromoethane (EDB)	EPA 8260B	ND	1.0	ug/L	1	A007267	08/13/10	08/13/10	
*1,2-Dichloroethane	EPA 8260B	ND	1.0	ug/L	1	A007267	08/13/10	08/13/10	
*Di-isopropyl ether (DIPE)	EPA 8260B	ND	1:0	ug/L	1	A007267	08/13/10	08/13/10	
*Ethyl tert-Butyl Ether (ETBE)	EPA 8260B	ND	1.0	ug/L	1	A007267	08/13/10	08/13/10	
*Methyl-t-butyl ether	EPA 8260B	ND	1,0	ug/L	1	A007267	08/13/10	08/13/10	
*tert-Amyl Methyl Ether (TAME)	EPA 8260B	ND	1.0	ug/L	1	A007267	08/13/10	08/13/10	

A0H1054 FINAL 08312010 1411



Jeff Yeazell BSK Associates - Sacramento 3140 Gold Camp Drive Suite 160 Rancho Cordova, CA 95670 Report Issue Date: 8/31/2010 14:11
Received Date: 08/12/2010
Received Time: 08:00

Lab Sample ID:

A0H1054-04

Sample Date:

08/04/2010 13:36

Sample Type:

Grab

Client Project: E0805401S

Sampled by:

Matrix: Water

Sample Description: MW-7

#### **Organics**

Analyte	Method	Resul	lt RL	Units	Dil.	Batch	Prepared	Analyzed	Qualifiers
tert-Butyl alcohol (TBA)	EPA 8260B	ND	50	ug/L	1	A007267	08/13/10	08/13/10	
Total Petroleum Hydrocarbon	s by EPA 8015B								
TPH as Diesel	8015B	ND	100	ug/L	1	A007279	08/16/10	08/17/10	
			Method	Result					
Surrogate: Fluorobenzene			8015/8021	101 %	Acceptable re	ange: 70-1	30 %		
Surrogate: Toluene-d8			EPA 8260B	102 %	Acceptable re	ange: 80-1	30 %		
Surrogate: Tetracosane			8015B	97.5 %	Acceptable n	ange: 45-1	89 %		



## **Organics Quality Control Report**

				Spike	Source		%REC		RPD		
Analyte	Result	RL	Units	Level	Result	%REC	Limits	RPD	Limit	Qualifiers	
Batch: A007267				Ana	alyst: AMN		Prepared 8	& Analyze	d: 8/13/201	0	
Blank (A007267-BLK1)	ty Control										
1,2-Dibromoethane (EDB)	ND	1.0	ug/L								
1,2-Dichloroethane	ND	1.0	ug/L								
Di-isopropyl ether (DIPE)	ND	1.0	ug/L								
Ethyl tert-Butyl Ether (ETBE)	ND	1.0	ug/L								
Methyl-t-butyl ether	ND	1.0	ug/L								
tert-Amyl Methyl Ether (TAME)	ND	1.0	ug/L								
tert-Butyl alcohol (TBA)	ND	50	ug/L								
Surrogate: Toluene-d8	13			12		102	80-130				
Blank Spike (A007267-BS1)	Quality Con	trol									
1,2-Dibromoethane (EDB)	14	1.0	ug/L	12		114	70-130				
1,2-Dichloroethane	17	1.0	ug/L	12		133	70-130			BS01	High
Di-isopropyl ether (DIPE)	15	1.0	ug/L	12		121	70-130				_
Ethyl tert-Butyl Ether (ETBE)	15	1.0	ug/L	12		123	70-130				
Methyl-t-butyl ether	16	1.0	ug/L	12		125	70-130				
tert-Amyl Methyl Ether (TAME)	16	1.0	ug/L	12		125	70-130				
tert-Butyl alcohol (TBA)	140	50	ug/L	120		115	60-140				
Surrogate: Toluene-d8	13			12		103	80-130				
Blank Spike Dup (A007267-BSD1) EPA 82	60B - Qualit	y Contro	N.								
1,2-Dibromoethane (EDB)	14	1.0	ug/L	12		115	70-130	0,6	30		
1,2-Dichloroethane	16	1.0	ug/L	12		130	70-130	2	30		
Di-isopropyl ether (DIPE)	15	1.0	ug/L	12		117	70-130	3	30		
Ethyl tert-Butyl Ether (ETBE)	15	1.0	ug/L	12		118	70-130	4	30		
Methyl-t-butyl ether	15	1.0	ug/L	12		123	70-130	2	30		
tert-Amyl Methyl Ether (TAME)	15	1.0	ug/L	12		122	70-130	3	30		
tert-Butyl alcohol (TBA)	160	50	ug/L	120		126	60-140	9	30		
Surrogate: Toluene-d8	13	00	ugri	12		104	80-130				
Batch: A007269				Δn	alyst: PYA		Prepared .	& Analyze	d: 8/16/201	0	
				7111	alyst. 1 17t		1 repared	or mary 20			
Blank (A007269-BLK1) 8015/8021 - Quality											
Benzene	ND	0.30	ug/L								
Ethylbenzene	ND	0.30	ug/L								
Toluene	ND	0,30	ug/L								
TPH as Gasoline	ND	50	ug/L								
Xylene (Total)	ND	0.30	ug/L								
Surrogate: Fluorobenzene	31			30		104	70-130				
Blank Spike (A007269-BS1) 8015/8021 - Q	uality Contr	ol									
Benzene	19	0.30	ug/L	20		93	70-130				
Ethylbenzene	18	0.30	ug/L	20		92	70-130				
Toluene	19	0.30	ug/L	20		94	70-130				
	400	50	ug/L	500		98	70-130				
TPH as Gasoline	490		_								
TPH as Gasoline  Xylene (Total)  Surrogate: Fluorobenzene	56 28	0.30	ug/L	60 30		93 94	70-130 70-130				

1414 Stanislaus Street

Fresno, CA 93706

(559) 497-2888

FAX (559) 485-6935

www.bsklabs.com

Page 7 of 13



## **Organics Quality Control Report**

Analyte										
Analyte				Spike	Source		%REC		RPD	
	Result	RL	Units	Level	Result	%REC	Limits	RPD	Limit	Qualifiers
Batch: A007269				Ana	alyst: PYA		Prepared 8	& Analyze	d: 8/16/201	0
Blank Spike Dup (A007269-BSD1) 8015/802	21 - Quality	Control								
Benzene	20	0.30	ug/L	20		102	70-130	9	20	
Ethylbenzene	20	0.30	ug/L	20		101	70-130	10	20	
oluene	21	0.30	ug/L	20		103	70-130	10	20	
(ylene (Total)	60	0.30	ug/L	60		101	70-130	8	20	
Surrogate: Fluorobenzene	30			30		102	70-130			
Matrix Spike (A007269-MS1) 8015/8021 - Q	uality Conti	ol					Source: /	A0H1054-0	01	
Benzene	10	0.30	ug/L	10	ND	102	70-130			
Ethylbenzene	10	0.30	ug/L	10	ND	102	70-130			
oluene	10	0.30	ug/L	10	ND	103	70-130			
(ylene (Total)	30	0.30	ug/L	30	ND	101	70-130			
Surrogate: Fluorobenzene	30			30		101	70-130			
Batch: A007279				Ana	alyst: PYA		Prepared:	8/16/2010	) Analyzed	8/17/2010
Blank (A007279-BLK1) 8015B - Quality Cor	ntrol									
PH as Diesel	ND	100	ug/L							
Surrogate: Tetracosane	41			50		81.2	45-189			
Blank Spike (A007279-BS1) 8015B - Quality	y Control									
PH as Diesel	2500	100	ug/L	2500		100	70-130			
Purrogata: Tatragagaga	69			50		138	45-189			
Surrogate: Tetracosane										
	Quality Cor	trol								
	Quality Cor 2500	itrol 100	ug/L	2500		98.1	70-130	2,04	30	
Blank Spike Dup (A007279-BSD1) 8015B -			ug/L	2500 50		98.1 130	70-130 <i>45-189</i>	2,04	30	
Blank Spike Dup (A007279-BSD1) 8015B -	2500 65		ug/L				45-189	2.04 <b>A0H0796-</b>		
Blank Spike Dup (A007279-BSD1) 8015B - PH as Diesel Surrogate: Tetracosane	2500 65		ug/L ug/L		77		45-189			



08/31/2010

#### Notes:

- The Chain of Custody document and Sample Integrity Sheet are part of the analytical report,
- Any remaining sample(s) for testing will be disposed of one month from the final report date unless other arrangements are made in
- Sample(s) received, prepared, and analyzed within the method specified criteria unless otherwise noted within this report,
- The results relate only to the samples analyzed in accordance with test(s) requested by the client on the Chain of Custody document. Any analytical quality control exceptions to method criteria that are to be considered when evaluating these results have been flagged and are defined in the data qualifiers section.
- All results are expressed on wet weight basis unless otherwise specified.
- All positive results for EPA Methods 504.1, 502.2, and 524.2 require the analysis of a Field Reagent Blank (FRB) to confirm that the results are not a contamination error from field sampling steps. If Field Reagent Blanks were not submitted with the samples, this method requirement has not been performed.
- Results contained in this analytical report must be reproduced in its entirety.
- Samples collected by BSK Analytical Laboratories were collected in accordance with the BSK Sampling and Collection Standard Operating Procedures
- BSK Analytical Laboratories certifies that the test results contained in this report meet all requirements of the NELAC Standards for applicable certified drinking water chemistry analyses unless qualified or noted in the Case Narrative.
- Analytical data contained in this report may be used for regulatory purposes to meet the requirements of the Federal or State drinking water, wastewater, and hazardous waste programs.
- J-value is equivalent to DNQ (Detected, not quantified) which is a trace value. A trace value is an analyte detected between the MDL and the laboratory reporting limit. This result is of an unknown data quality and is only qualitative (estimated). Baseline noise, calibration curve extrapolation below the lowest calibrator, method blank detections, and integration artifacts can all produce apparent DNQ values, which contribute to the un-reliability of these values.
- (1) Residual chlorine and pH analysis have a 15 minute holding time for both drinking and waste water samples as defined by the EPA and 40 CFR 136, Waste water and ground water (monitoring well) samples must be field filtered to meet the 15 minute holding time for dissolved metals. Samples submitted to the laboratory have been analyzed outside of this holding time requirement.
- This is not a NELAP accredited analyte.
- Summations of analytes (i.e. Total Trihalomethanes) may appear to add individual amounts incorrectly, due to rounding of analyte values occurring before or after the total value is calculated, as well as rounding of the total value.
- (2) The digestion used to produce this result deviated from EPA 200.2 by excluding hydrochloric acid in order to produce acceptable recoveries for affected metals.

#### Certifications:

%:

SC07

State of California - CDPH - ELAP State of California - CDPH - NELAP 1180 04227CA

M:

RL:

ND:

pCi/L:

State of New Mexico - NMED-DWB State of Nevada - NDEP

CA000792009A

#### **Definitions and Flags for Data Qualifiers**

Percent Recovered (surrogates)

Milligrams/Liter (ppm) mg/L: mg/Kg: Milligrams/Kilogram (ppm) Micrograms/Liter (ppb) μg/L: μg/Kg: Micrograms/Kilogram (ppb)

Method Detection Limit Reporting Limit :DL x Dilution None Detected at RL

Picocuries per Liter

MDA: Min. Detected Activity MPN: Most Probable Number CFU: Colony Forming Unit Less than 1 CFU/100mLs Absent: Present: 1 or more CFU/100mLs

Sample received and analyzed without chemical preservation.

BS01 The associated blank spike recovery was above acceptance limits. Results were accepted based on duplicate spike.

A0H1054 FINAL 08312010 1411

Page 9 of 13

# A0H1054

# **BSK Associates - Sacramento**

# **BSKAs9293**

08122010

Erik Ringerburg

No Project

Turnaround:

Standard

Due Date:

08/26/2010

Sample ID	Sample Description	Date Sampled	Lab Notes
A0H1054-01	MW-6	08/04/2010	O.K. to run on Non-Preserved as per Jeff Y.
A0H1054-02	MW-101	08/04/2010	O.K. to run on Non-Preserved as per Jeff Y.
A0111054-03	MW-5	08/04/2010	O.K. to run on Non-Preserved as per Jeff Y,
A0H1054-04	MW-7	08/04/2010	O.K. to run on Non-Preserved as per Jeff Y.

Printed: 08/12/2010 19:28:34

10	က
	틸
AND DA	=
<u>@</u>	<sup>2</sup> age

1414 Stanislau 559) 497-288	A N A L LABO  us, Fresno CA 93 8, (800) 877-831	3706 0, FAX (559) 48	C A L BSK Submission COC Number Global ID Number Cock Affection COC Number Cock States of the Cock States of	per:		00010			of (W015M)	1		Anal) (8092)	A0H10 BSKA	s9293		2/2010 10 	Page 11 of 13
Address  City, State, Zip  Phone  Lab Use Only	Samp	oling info	BSK Job No.: E0805401S Copy to:  FAX Sampled by E. Bosel Field Point Name	- DH	HNO3	H2SO4	NONE	OTHER (List)	BTEX/TPH-G (8020/8015M)	TPH-Diesel (8015M)	Fuel Oxygenates (8260B)	Lead Scavengers (8260B)				Rush Priority (1-Day, 2-6	
3 1 4 1	814/10 814/10	9:10 10:32 13:05	Hure Furtos Hurs	22:005				7	×	× × × ×	XXXXX	X X X					
OC Report Ty	rpe: Level [X] 2	[ ] 3 [ ] 4	Formal COC	 C Required	 1: [ ]			1			1	<u>.                                    </u>	LL		 ·	 	

Electronic Data Format Required: [X] Email	EDF To:jyeazell@bskinc.com	Low Level Fuel Oxygenats Detection Lin	
Signature	Print Name	Company	Date/Time-
Received / Reliquished by:	ErwRasel	RSKS	8/5/10/205
Received / Reliquished by:			
Received / Reliquished by:			
Received / Reliquished by:			*
Received / Reliquished by:	- Sumentra Ba	The Popular	81410 M

Sample Integrity Pg. 1 of 2 WORK BSKA



جارات م	, – –						
Date Received 8141							
Section 1- Receiving Information							_
Sample Transport: ONTRAC							_
Samples arrived at lab on same of	łay sampled: Yes	N	lo <u>X</u> (If Yes-	Temperature is	s not need	led)	
Coolers/Ice Chests Description/	Comperature(s); (if	more than 4 re	ecived, list information in	comment section)			
1.1							
Was Temperature In Range: (Y						•	$\overline{\mathbb{N}}$
Describe type of packing materi	als: Bubble Wra	Poam	Packing Ponti	its Paper	Other:		
Initial Receipt: BSK-Visalia					BSK-FAL		
Were ice chest custody seals pro	sent? Y	Intact: Y	W				
					- 7/5		
Section 2- COC Info.	Completed Yes No	Info From Container			Comp Yes	oleted No	Info From Container
Was COC Received	103	Conginer	Analysis Reque	sted	1	1	
Date Sampled			Any hold times le			1=	
Time Sampled	(		Client Name				
Sample ID			Address				
Special Storage/Handling Ins.	-		Telephone #			•	
Section 3- Bottles / Analysis				Yes	No	N/A	Comment
Did all bottles arrive unbroken ar							
Were bottle custody scals present							
Were bottle custody seals intact?							
Did all bottle labels agree with C		10		<u> </u>			
Were correct containers used for			<del></del>				<del></del>
Were correct preservations used							
Was a sufficient amount of samp					_		
Were bubbles present in VOA Vi Were Ascorbic Acid Bottles rece			шу)			202	
Wele Ascolute Acid Bottles lece	ived with the VO	JAS:				···	
Section 4- Comments / Discrepance	ies						
	<b>Y</b>						
Sample(s) Split/Preserve: Yes	Container:		Preservation:		_ Dt/Tii	me/Init	
					<b>5</b>	ly !	
	Container:	_	Preservation: _		Dt/Tir	ne/Init_	
Was Client Service Rep. notified of	discrepancies (	Yes No	N/A CS	RE JULIO	Notifie	d By:	31-
Explanations / Comments	discrepancies.		1471 05	0000	- Trouing	ou Dj.	06
			- C1 -ch /	٠٥٠١٠٥	1100	,	
* Ke(eive ur	ipreserve	VUUS	, turtest r	eques	11.8		
				\ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \			
Over do	Z\ 11A Z Z	1117 25	8/41	T.	100		
- villy 48	run uu	TALES	as per	jest \	Ka	20	مار
Report Comment Entered:				<b>_</b>		-	
Tepart Comment Effered.		-1/0	Challer	·•			

Labels checked by: 514 @ 18:12

10

Sample Integrity Pg 2 of 2 BSK Bottles Yes

250ml (A) 500ml (B) 1Liter (C) Amber Glass (AG)					
Container(s) Received	1-4				
Bacti Na <sub>2</sub> S <sub>2</sub> O <sub>3</sub>					
			3 3 3 3 3		
None (p) White Cap					
None (p) Blue Cap w/NH4 + Buffer					
None (p) Blue Cap w/NH4 + Buffer HNO <sub>3</sub> (p) Red Cap				90	
H-SO, (n) Yellow Cap					
NaOH (p) Green Cap					
Other:					
Dissolved Oxygen 300ml (g)				1	
Centrifuge Tube HNO <sub>3</sub>					7
250ml (AG) None				_\_	
250ml (AG) H <sub>2</sub> SO <sub>4</sub> COD Yellow Label				\	
250ml (AG) Na <sub>2</sub> S <sub>2</sub> O <sub>3</sub> 515,547 Blue Label					
250ml (AG) Na <sub>2</sub> S <sub>2</sub> O <sub>3</sub> - MCAA 531.1 Orange Label 250ml (AG) NH <sub>4</sub> Cl 552 Purple Label					
250ml (AG) NH <sub>4</sub> Cl 552 Purple Lauci			-		
250ml (AG) EDA DBPs Brown Laber					
250ml (AG) Other:					
500 177 (0.5)			<del>                                     </del>		
500ml (AG) None			+	L	
500ml (AG) H <sub>2</sub> SO <sub>4</sub> TPH-Diesel Yellow Libet			4		
I I'M MACINAL	ļ		1		
1 Liter (AG) None					
1 Liter (AG) H <sub>2</sub> SO <sub>4</sub> O&G Yellow Labet 1 Liter (AG) Na <sub>2</sub> S <sub>2</sub> O <sub>3</sub> 548 / 525 / 521 Blue Labet			+ + -		Z1101-
1 Liter (AO) NajojOj 340 / 525 / 521			+}		966
1 Liter (P) Na <sub>2</sub> S <sub>2</sub> O <sub>3</sub> + H <sub>2</sub> SO <sub>4</sub> 549	<del> </del>		+		
1 Liter (AG) NaOH+ZnAc Sulfide 1 Liter (AG) Ascorbic/EDTA/Pot Citrate 527 Grey Label			1		
1 Liter (AG) CuSO4/Trizma 529 Turquoise Libel	i		<del></del>		
1 Liter (AG) Na <sub>2</sub> SO <sub>3</sub> / HCL 525 UCMR Neon Green Label			-	<del> </del>	
1 Liter (AG) Ammonium Chloride 535 Purple Label				1	
Diet (1997) thiniointin Chorice 355	<del>                                     </del>		-	1	
40ml VOA Vial Clear – HCI.		-		1	
40ml VOA Vial Amber – Na <sub>2</sub> S <sub>2</sub> O <sub>3</sub>	†				
40ml VOA Vial Clear - None	4		1		
40ml VOA Vial Clear - Na <sub>2</sub> S <sub>2</sub> O <sub>3</sub> 504, 505	<del>                                     </del>		-		
40ml VOA Vial Clear – H <sub>1</sub> PO <sub>4</sub>					
Other:			17		
Asbestos ILiter Plastic/Foil		1			/
Radon 200ml Clear (g)				/	
Low Level Hg/Metals Double Baggie					
Bioassay Jug					
250 Clear Glass Jar					
500 Clear Glass Jar					
Liter Clear Glass Jar					
Plastic Bag					
Soil Tube Brass / Steel / Plastic					
Fedlar Bags	2 100	T <sub>2</sub>	•		