

April 12, 2004

R0318

Alamada County

APR 1 # 2004

Enviorent de l'ocem

Mr. Amir Gholami Hazardous Materials Specialist Alameda County Department of Environmental Health 1131 Harbor Bay Parkway, Suite 250 Alameda, CA 94502-6577

Re:

First Quarter 2004 Status Report Former BP Service Station # 11266 1541 Park Street Alameda, California URS Project # 38486813

Dear Mr. Gholami:

On behalf of Atlantic Richfield Company (ARCO- a BP affiliated company), URS Corporation (URS) is submitting the *First Quarter 2004 Status Report* for the Former BP Service Station #11266, located at 1541 Park, Alameda, California. URS requests a response to the *Request for Site Closure* submitted February 21, 2003.

NO.HG357

If you have any questions regarding this submission, please call me at (510) 874-1720.

Sincerely,

URS CORPORATION

Leonard P. Niles, R.G./C.H.G.

Senior Geologist

Enclosure:

First Quarter 2004 Status Report

cc:

Mr. Paul Supple, ARCO, (electronic copy uploaded to ENFOS)

Mr. Chris Jimmerson, Delta Environmental Consultants, 3146 Gold Camp Dr. Suite 200, Rancho Cordova, Ca 95670-6021

BP GEM QUARTERLY STATUS REPORT	
Former Facility No.: 11266 Address	: 1541 Park Street, Oakland, CA
BP Environmental Business Manager:	Paul Supple
Consulting Co./Contact Person:	URS Corporation / Leonard P. Niles
Consultant Project No.:	38486831
Primary Agency:	Alameda County Health Care Services Agency (ACHCSA)
<ol> <li>WORK PERFORMED THIS QUARTER (First – 2004):</li> <li>No environmental activities took place during this quarter.</li> <li>Prepared and submitted first quarter 2004 status report.</li> </ol>	
WORK PROPOSED FOR NEXT QUARTER (Second- 2004):	
1. Prepare and submit second quarter 2004 status report.	
Current Phase of Project:	GW monitoring/sampling
Frequency of Groundwater Sampling:	No Ongoing Sampling
Frequency of Groundwater Monitoring:	No Ongoing Monitoring

Date:

Quarter:

April 12, 2004

1Q 04

## DISCUSSION:

On February 21, 2003, URS submitted a request for site closure. At the time of this status report, URS has not received a response regarding this request. No groundwater monitoring activities are scheduled for this site.