PROTECTION 97 JAN 22 AM 9: 22

2116

SITE ASSESSMENT REPORT

1/10/97

CREDIT WORLD AUTO SALES 2345 E. 14TH STREET OAKLAND, CA 94601

Prepared For:

MESSRS. AARON AND STANLEY WONG
2200 E. 12TH STREET
OAKLAND, CA 94606


Submitted By:
TANK PROTECT ENGINEERING
Of Northern California, Inc.
2821 WHIPPLE ROAD
UNION CITY, CA 94587
(510) 429-8088

January 10, 1997

Project Number 267

Lee Hickins

Lee N. Huckins Registered Geologist



Expiration Date 5/31/97

Jeff J. Farhoomand, M.S. Principal Engineer

SITE ASSESSMENT REPORT

CREDIT WORLD AUTO SALES 2345 E. 14TH STREET OAKLAND, CA 94601

Prepared For:
MESSRS. AARON AND STANLEY WONG
2200 E. 12TH STREET
OAKLAND, CA 94606

January 10, 1997

This report has been prepared by the staff of Tank Protect Engineering of Northern California, Inc. under direction of an Engineer and/or Geologist whose seal(s) and/or signature(s) appear hereon.

The findings, recommendations, specifications or professional opinions are presented, within the limits prescribed by the client, after being prepared in accordance with generally accepted professional engineering and geologic practice. We make no other warranty, either expressed or implied.

TABLE OF CONTENTS

)	INVESTIGATION AND REMEDIATION OF CONTAMINATED						
	VADOSE ZONE SOIL						
	3.1 TPE's Methodologies of Soil Excavation, Verification						
	Soil Sampling and Chemical Analyses						
	3.1.1 Method of Excavation of Contaminated Soil						
	3.1.2 Method of Verification Soil Sampling						
	3.1.3 Method of Chemical Analyses						
	3.1.4 Method of Stockpile Soil Sampling						
	3.1.5 Method of Stockpile Soil Remediation						
	3.1.6 Method of Verification Stockpile Sampling						
	3.1.7 Method of Excavation Backfilling						
	3.2 Summary of Excavation, Remediation, Soil Sampling and						
	Analytical Results						
	3.2.1 December 1994						
	3.2.2 January 1995						
	3.2.3 February, 1995						
	3.2.4 April, 1995						
	3.2.5 May, 1995						
	3.2.5.1 Groundwater Sampling						
	3.2.5.2 Letter from ACHCSA						
	3.2.6 June 1995						
	3.2.6.1 Floating Product Removal System						
	3.2.7 July 1995						
	3.2.8 August, 1995						
	3.2.8.1						
	3.2.9 September 1995						
	3.2.10 October 1995						
	3.2.10.1 Groundwater Investigation						
	3.2.11 December 1995						
	3.2.12 May 1996						

	3.2.12.1 Methyl t-	Butyl Ether	(MTBE)	 		13
3.2.13	June 1996			 		13
3.2.14	July 1996			 		14
3.2.15	August 1996			 		14
3.2.16	September 1996			 		14
3.2.17	October 1996 .			 		15
	3.2.17.1 Excavatio	n Closure .	• • • • •	 	• • • •	16
4.0 QUARTERLY	GROUNDWATER	MONITO	RING .	 		16
5.0 CONCLUSIONS				 	· • • • •	17
6.0 RECOMMENDA	TIONS			 		17
7.0 STUDY LIMIT.	ATIONS			 		18

• ,

FIGURES

- 1. SITE VICINITY MAP
- 2. SITE PLAN
- 3. EXCAVATION (12/15/94)
- 4. VERIFICATION STOCKPILE SAMPLING (5/12/95)
- 5. EXCAVATION (6/30/95 THROUGH 7/5/95)
- 6. LOCATION OF VERIFICATION STOCKPILE SAMPLING (7/12/95)
- 7. VERIFICATION STOCKPILE SAMPLING (7/12/95)
- 8. EXCAVATION (7/28/95)
- 9. VERIFICATION STOCKPILE SAMPLING (10/2/95)
- 10. EXCAVATION (5/24/96)
- 11. EXCAVATION (5/29 AND 5/30/96)
- 12. STOCKPILE SOIL SAMPLING (7/30/96)
- 13. EXCAVATION (9/16/96 AND 9/17/96)
- 14. VERIFICATION STOCKPILE SAMPLING (10/4/96)
- 15. GROUNDWATER GRADIENT MAP (9/24 AND 9/30/96)
- 16. LOCATION OF FINAL VERIFICATION SOIL SAMPLING

TABLES

- 1. SUMMARY OF SOIL SAMPLE ANALYTICAL RESULTS
- 2. SUMMARY OF EXCAVATION GROUNDWATER SAMPLE ANALYTICAL RESULTS
- 3. SUMMARY OF GROUNDWATER SAMPLE ANALYTICAL RESULTS
- 4. SUMMARY OF FLOATING PRODUCT THICKNESS

APPENDICES

A. ALAMEDA COUNTY HEALTH CARE SERVICE AGENCY, LETTER DATED AUGUST 4, 1994

- . ALAMEDA COUNTY HEALTH CARE SERVICES AGENCY, LETTER DATED SEPTEMBER 7, 1994
- . ALAMEDA COUNTY HEALTH CARE SERVICES AGENCY, LETTER DATED JANUARY 25, 1995
- . ALAMEDA COUNTY HEALTH CARE SERVICES AGENCY, LETTER DATED MAY 17, 1995
- . TPE LETTER TO THE OAKLAND FIRE PREVENTION BUREAU DATED JUNE, 15, 1995
- . ALAMEDA COUNTY HEALTH CARE SERVICES AGENCY, LETTER DATED OCTOBER 26, 1995
- . ALAMEDA COUNTY HEALTH CARE SERVICES AGENCY, LETTER DATED OCTOBER 3, 1996
- B. SAMPLE HANDLING PROCEDURES
- C. WASTE HANDLING AND DECONTAMINATION PROCEDURES
- D. QUALITY ASSURANCE AND QUALITY CONTROL PROCEDURES
- E. CERTIFIED ANALYTICAL REPORTS AND CHAIN-OF-CUSTODY DOCUMENTATION

1.0 INTRODUCTION

The subject site is located at 2345 E. 14th Street in the city of Oakland in Alameda County, California (see Figure 1) and is owned by Messrs. Aaron and Stanley Wong [(Wong), telephone number (510) 532-1672]. The site is occupied by a used car dealership known as Credit World Auto Sales. The only onsite structure is a building which includes an office and automotive service bay (see Figure 2). Previous work by others and Tank Protect Engineering of Northern California, Inc. (TPE) has documented soil and groundwater contamination apparently due to leaks or spills associated with a former underground gasoline tank complex.

This <u>SITE ASSESSMENT REPORT</u> (SAR) documents work conducted by TPE, describes details on overexcavation activities at the site, provides analytical data for soil and groundwater samples and presents recommendations for further investigations.

2.0 REQUEST FOR WORK PLAN ADDENDUM

A workplan was requested by the ACHCSA in an August 4, 1994 letter Request for Workplan Addendum for Further Investigation and Remediation of 2345 E. 14th St., former Taxi Taxi to Wong (see Appendix A). TPE responded with a August 26, 1994 WORKPLAN FOR EXCAVATION OF CONTAMINATED SOIL AND INSTALLATION OF GROUNDWATER MONITORING WELLS, CREDIT WORLD AUTO SALES, 2345 E. 14TH STREET, OAKLAND, CA 94601 (WP).

The WP was approved September 7, 1994 by ACHCSA in a letter to Wong, <u>Comment on August 26, 1994 Workplan for the Excavation of Soil and the Installation of Monitoring Wells at 2345 E. 14th St., Oakland CA 94601</u>. ACHCSA noted that overexcavation and groundwater extraction be initiated. The installation of additional monitoring wells would be postponed until the effects of overexcavation and groundwater extraction were seen (see Appendix A).

3.0 INVESTIGATION AND REMEDIATION OF CONTAMINATED VADOSE ZONE SOIL

As a further investigation and preliminary remediation of vadose zone soil and groundwater contamination, TPE performed the following scope of work:

- Excavated contaminated soil from the location of the former underground gasoline tank complex.
- After excavating contaminated soil in the above task, collected verification soil samples from the sidewalls and floor of the excavation for chemical analysis for total petroleum hydrocarbons as gasoline (TPHG) and benzene, toluene, ethylbenzene and xylenes (BTEX).
- . Remediated contaminated stockpiled soil for reuse.
- . Backfilled the excavation with remediated stockpiled soil.
- . Prepared this SAR.

Details of the work conducted are presented below.

- 3.1 TPE's Methodologies of Soil Excavation, Verification Soil Sampling and Chemical Analyses
- 3.1.1 Method of Excavation of Contaminated Soil

TPE conducted excavation of contaminated soil with an excavator and backhoe. The purpose of excavating was to remove TPHG and BTEX contaminated soil documented by TPE and others. Excavated soil was segregated using field screening methods. Horizontal excavation was conducted to the limits based on field-screening methods and

soil analytical results. Vertical excavation was conducted to the limit imposed by machinery and to the depth of groundwater.

The horizontal and vertical extent of excavation was determined by field-screening methods that included the detection of apparent soil contamination as evidenced by visible hydrocarbon stains, odors, and headspace field screening of excavated soil samples for volatile organic compounds using a Gastech Inc., Trace-Techtor hydrocarbon vapor tester (HVT).

Headspace analysis was conducted on vadose zone soil samples collected to determine if apparent contamination is present. The analysis was performed by sealing each sample in a quart-size plastic bag and warming the bagged sample in the sun to promote volatilization of any hydrocarbons that may be present in the soil. After allowing for volatilization, the sample was tested by inserting the probe of a HVT into the headspace of the plastic bag (while minimizing the entry of new air into the bag) and recording the response in ppm.

Excavated soil was stockpiled on site on top of plastic sheeting unless the ground surface was covered with asphalt or concrete.

3.1.2 Method of Verification Soil Sampling

When the horizontal and vertical extent of contaminated vadose zone soil had been reached, based on the above field-screening, or the horizontal and vertical limits discussed above had been reached, verification soil samples were collected for chemical analysis to document cleanup concentrations of TPHG and BTEX chemicals.

Soil samples were collected from the sidewalls of the excavation by removing about 1 foot of soil to expose a fresh surface and driving a clean 2-inch diameter by 6-inch long brass tube into the newly exposed surface with a slide-hammer corer. Samples were also collected by excavating soil with the bucket of excavator or a backhoe and collecting a sample in a brass tube from soil in the bucket. After collecting each sample, the brass tube ends were quickly covered with Teflon sheeting and capped with plastic end-caps. The tubes were labeled to show site name, project number, sample.

name and depth, time and date collected, and sampler name; sealed in quart size plastic bags; and placed in an iced-cooler for transport to a Department of Health Services (DHS) certified laboratory accompanied by chain-of-custody documentation. The DHS laboratories for the project were Trace Analysis Laboratories, Inc. of Hayward CA, Priority Environmental, Inc. of Milpitas CA and Hull Development Labs, Inc. of Sunnyvale CA.

Appendix B documents TPE's protocol relative to sample handling procedures.

3.1.3 Method of Chemical Analyses

All verification soil samples were analyzed for TPHG by the DHS Method and the United States Environmental Protection Agency (EPA) Method 8015M and for BTEX chemicals by EPA Method 8020.

3.1.4 Method of Stockpile Soil Sampling

Stockpile soil samples were collected for laboratory compositing such that 4 discrete samples were composited into 1 for chemical analysis to characterize the stockpile for TPHG and BTEX chemicals.

The stockpile samples were collected directly into brass tubes driven by a slide-hammer corer at depths of about 1.0 to 3.0 feet below the stockpile's surface.

After collecting each sample, the samples were handled as described in Section 3.1.2 <u>Verification Soil Sampling</u>. See Appendices B, C, and D for TPE's protocols relative to sample handling procedures, waste handling and decontamination procedures, and quality assurance and quality control procedures, respectively.

3.1.5 Method of Stockpile Soil Remediation

TPE submitted a January 24, 1995 <u>WORKPLAN FOR STOCKPILED SOIL REMEDIATION</u>, <u>CREDIT WORLD AUTO SALES</u>, 2345 E 14TH STREET, <u>OAKLAND</u>, <u>CA 94601</u> (WPSSR). The workplan discussed stockpile soil remediation and verification stockpile soil sampling methods. ACHCSA approved the workplan on January 25, 1995 (see Appendix A). All contaminated stockpiled soil was remediated in accordance with TPE's WPSSR.

3.1.6 Method of Verification Stockpile Sampling.

All remediated stockpiled soil was sampled in accordance with TPE's WPSSR dated January 24, 1995. All samples were handled as described in TPE's WPSSR and in Section 3.1.2 <u>Verification Soil Sampling</u>. All stockpile soil samples were analyzed in accordance with the WPSSR and in Section 3.1.3 <u>Method of Chemical Analysis</u>.

3.1.7 Method of Excavation Backfilling

The excavation was backfilled with an excavator/backhoe with clean remediated soil. The soil was placed into the excavation in 2 to 3 foot compacted lifts to ground surface. Concrete was disposed of offsite.

3.2 Summary of Excavation, Remediation, Soil Sampling and Analytical Results

The subject site's history prior to December, 1994 is summarized in TPE's August 26, 1994 WP and TPE's January 24, 1995 WPSSR. This report presents a summary of events that took place during excavation activities.

3.2.1 December 1994

Excavation and Collection of Verification Soil Samples

Prior to beginning excavation activities, TPE notified the Bay Area Air Quality Management District (BAAQMD) and conducted an Underground Service Alert location request to minimize the potential for encountering any buried utilities or underground objects while conducting excavation activities.

On December 5, 6 and 15, 1994, TPE excavated about 600 cubic yards (cyds) of contaminated vadose zone soil from the area of the former underground gasoline tank complex and associated piping. On December 6, 1994 TPE collected discrete soil samples VS-1 through VS-5 from the sidewalls of the excavation and VS-6 from beneath the former piping to evaluate remaining concentrations of TPHG and BTEX chemicals in the in-situ soil. All samples were collected under the supervision of an inspector from the ACHCSA.

Twenty-two discrete soil samples were collected from the stockpiled soil for laboratory compositing to characterize the stockpile for TPHG and BTEX contamination. Twenty of the samples were composited into 5 samples and 2 of the samples were composited into 1 sample.

Soil sample locations and depths are shown in Figure 3.

Soil samples collected from the excavation sidewalls detected TPHG at concentrations ranging from 1.3 ppm to 210 ppm. Soil sample VS-6, collected beneath the former piping, detected TPHG at a concentration of 2.7 ppm.

The 6 composite stockpile soil samples detected TPHG at concentrations ranging from 5.3 ppm to 78 ppm.

Some or all BTEX chemicals were detected in all soil samples analyzed.

Results of chemical analyses are documented in Table 1 with certified analytical reports and chain-of-custodies in Appendix E.

3.2.2 January 1995

Letter From ACHCSA

ACHCSA approves TPE's January 24, 1995 WPSSR in a letter to Wong titled Review of Work Plan for Stockpiled Soil Remediation at 2345 E. 14th St., Oakland CA 94601. Credit World Auto Sales (see Appendix A).

3.2.3 February, 1995

Stockpile Soil Remediation

On February 14, 17, 21, 22, 23, 24 and 27, 1995 TPE conducted stockpile soil remediation as described in Section 3.1.5 Method of Stockpile Soil Remediation.

3.2.4 April, 1995

Stockpile Soil Remediation

On April 20 through 29, 1995 TPE conducted stockpile soil remediation as described in Section 3.1.5 Method of Stockpile Soil Remediation.

3.2.5 May, 1995

Stockpile Soil Remediation and Collection of Verification Stockpile Soil Samples

On May 3, 4 and 8, 1995 stockpile soil remediation was conducted as described in Section 3.1.5 Method of Stockpile Soil Remediation.

On May 12, 1995 TPE conducted verification stockpile sampling as described in Section 3.1.6 Method of Verification Stockpile Soil Sampling. About 606 cyds were sampled (see Figure 4).

Chemical results for verification samples, VSP-1A through VSP-10B, were nondetectable for TPHG and BTEX chemicals.

Results of chemical analyses are documented in Table 1 with certified analytical reports and chain-of-custodies in Appendix E.

3.2.5.1 Groundwater Sampling

One groundwater "grab" sample GB-1, was collected directly from the excavation. The sample was collected with a dedicated disposable bailer and stored in a 2-40 milliliter glass vials. The vials were stored in an iced-cooler for transport to a DHS laboratory accompanied by chain-of-custody documentation and analyzed for TPHG and BTEX by EPA Methods 8015M and 8020, respectively.

Chemical analyses for groundwater sample GB-1 were nondetectable.

Analytical results are summarized in Table 2 and documented with a certified analytical report and chain-of-custody in Appendix E.

3.2.5.2 Letter from ACHCSA

On May 17, 1995 ACHCSA issued a letter to Wong titled Status of Subsurface Investigation at 2345 E. 14th St. Oakland CA 94601, Former Taxi Taxi requesting the removal of floating product from the groundwater monitoring wells (see Appendix A).

3.2.6 June 1995

Backfilling and Excavation of Contaminated Soil

On June 26, 1995 TPE partially backfilled the excavation with remediated soil to make additional room for excavation activities. The excavation was backfilled as described in Section 3.1.7 Method of Excavation Backfilling

On June 30, 1995 TPE conducted overexcavation in the area of VS-3. Overexcavation activities are described in Section 3.1 Method of Excavation (see Figure 5).

3.2.6.1 Floating Product Removal System

TPE responded to ACHCSA letter of May 14, 1995 with a June 14, 1995 letter titled Status of Subsurface Investigation at 2345 E. 14th Street, Oakland, CA 94601. This letter documented the procedure that TPE implemented to remove the free product from the wells. The product removal system consisted of a selective oil skimmer, a controllerless, down-well mounted, air-operated, resilient bladder product pump and a product storage tank that shuts off automatically when the product tank is full. In order to permit the system, TPE submitted a letter to the Oakland Fire Prevention Bureau on June 15, 1995 titled Operation of a Product Removal System at 2345 E. 14th Street, Oakland CA 94601. The system was permitted on June 19, 1995 (see Appendix A).

3.2.7 July 1995

Excavation and Collection of Verification Soil Samples, Floating Product Removal

Excavation activities continued through July 5, 1995 (see Figure 5). Excavated soil was segregated into two stockpiles (apparently clean and contaminated). On July 5, 1995 TPE conducted verification soil sampling in the presence of ACHCSA. All verification soil sampling was conducted as described in Section 3.1.2 <u>Verification Soil Sampling</u>. Stockpile soil sampling was conducted on July 12, 1995 as described in Section 3.1.4 <u>Stockpile Soil Sampling</u>.

Analytical results detected TPHG in verification soil samples VS-6(6/30/95) through VS-13(7/05/95) ranging from nondetectable to 130 ppm. TPHG was detected in stockpile soil samples STK7(1-4) through STK10(1,2,3,4) at concentrations ranging from 22 ppm to 290 ppm. Some or all BTEX chemicals were detected in verification and stockpile soil sampling. Stockpile soil sample STK11(1,2,3,4), collected from segregated apparently clean material, was nondetectable for TPHG and BTEX.

Results of chemical analyses are documented in Table 1 with certified analytical reports and chain-of-custodies in Appendix E.

Based on the nondetectable analytical results of stockpile soil sample STK11(1,2,3,4), TPE conducted verification stockpile soil sampling as described in Section 3.1.6 Method of Verification Stockpile Soil Sampling to document that the stockpile was suitable for reuse. About 200 cyds were sampled (see Figures 6 and 7).

On July 20, 1995 ACHCSA verbally approved the reuse of the clean stockpile.

On July 27, 1995 TPE installed a floating product removal system at the site. TPE removed floating product from MW-1. TPE removed the floating product removal system, because of overexcavation activities.

On July 28, 1995 limited excavation activities continued in the area of VS-10 in order to cleanup the sidewalls of the excavation (see Figure 8). Verification soil sampling was conducted as described in Section 3.1.2 <u>Verification Soil Sampling</u>. Stockpile soil sampling was conducted as described in Section 3.1.4 <u>Stockpile Soil Sampling</u>.

Analytical results detected TPHG in verification soil samples VS-14 through VS-18 in concentrations ranging from 2.8 ppm to 590 ppm. TPHG was detected in stockpile soil samples, STK12(A-D) and STK13(A-D), at concentrations of 87 ppm and 58 ppm. BTEX chemicals were also detected in verification and stockpile soil samples.

Results of chemical analyses are documented in Table 1 with certified analytical reports and chain-of-custodies in Appendix E.

3.2.8 August, 1995

Stockpile Soil Remediation

On August 3 through 10, 1995, TPE conducted stockpile soil remediation as described in Section 3.1.5 Method of Stockpile Soil Remediation.

3.2.8.1 Floating Product Removal

On August 2 and 18, 1995 TPE removed floating product from wells MW-1 and MW-2. TPE removed floating product removal system, because of soil remediation activities. TPE began removing floating product from the wells on a quarterly basis upon sampling the wells. Quarterly removal of floating product was initiated and conducted until soil remediation activities at the site had been concluded (see Section 4.0 Quarterly Groundwater Monitoring).

3.2.9 September 1995

Stockpile Soil Remediation

On September 11 and 12, 1995 TPE conducted stockpile soil remediation as described in Section 3.1.5 Method of Stockpile Soil Remediation.

3.2.10 October 1995

Verification Soil Sampling

On October 3, 1996 TPE conducted verification stockpile sampling as described in Section 3.1.6 Method of Verification Stockpile Soil Sampling. About 660 cyds were sampled (see Figure 9).

Analytical results for verification stockpile soil samples, VSP 11A(10/03/95) through VSP 21C(10/03/95) for TPHG and BTEX chemicals were nondetectable.

Results of chemical analyses are documented in Table 1 with certified analytical reports and chain-of-custodies in Appendix E.

On October 10, 1995 ACHCSA verbally approved the remediated stockpiled soil for reuse.

3.2.10.1 Groundwater Investigation

On October 4, 1995 TPE submitted a <u>WORKPLAN FOR GROUNDWATER</u> INVESTIGATION 2345 E. 14TH STREET, OAKLAND, CA 94601. The workplan proposed the advancement of nine soil borings to groundwater along with soil and groundwater sampling. ACHCSA conditionally approved the workplan with their letter dated October 26, 1995 <u>Comment Of August 4, 1995 Workplan For Soil And Groundwater Investigation At 2345 E. 14Th Street, Oakland, CA 94601</u> (see Appendix A).

3.2.11 December 1995

Excavation Backfilling

On December 5, 1995 TPE partially backfilled the excavation with remediated soil to make additional room for excavation activities. The excavation was backfilled as described in Section 3.1.7 Method of Excavation Backfilling

3.2.12 May 1996

Excavation Backfilling, Excavation and Collection of Verification Soil Samples, Stockpile Soil Remediation

On May 21, 22, and 23, 1996 TPE partially backfilled the excavation with remediated soil to make additional room for excavation activities. The excavation was backfilled as described in Section 3.1.7 Method of Excavation Backfilling

On May 24, 28, and 29, 1996 overexcavation activities continued in the area of VS-18. Excavation activities were conducted as described in Section 3.1 Method of Excavation (see Figures 10 and 11). Excavated soil was segregated into two stockpiles (apparently clean and contaminated). All verification soil sampling was conducted as described in Section 3.1.2 Verification Soil Sampling. Stockpile soil sampling was conducted as described in Section 3.1.4 Stockpile Soil Sampling.

Analytical results detected TPHG in verification soil samples VF-1, VS-2D and VS-22 through VS-29 in concentrations ranging from nondetectable to 470 ppm. TPHG was also detected in stockpile soil samples STK-1A,B,C,D(05/24/96), STK-2A,B,C,D(05/24/96), STK-1A,B,C,D(05/29/96), and STK-2A,B,C,D(05/29/96) collected from apparently contaminated soil, at concentrations of 170 ppm, 320 ppm, 1.7 ppm and 140 ppm, respectively. Some or all BTEX chemicals were detected in verification and stockpile soil samples. Stockpile soil samples STK-3 A,B,C,D(05/30/96) through STK-6 A,B,C,D(05/30/96) collected from apparently clean segregated soil, were nondetectable for TPHG and BTEX.

Results of chemical analyses are documented in Table 1 with certified analytical reports and chain-of-custodies in Appendix E.

Because stockpile soil samples STK-3A,B,C,D(05/30/96) through STK-6A,B,C,D(05/30/96) were nondetectable for TPHG and BTEX chemicals, ACHCSA verbally approved 200 cyds of stockpiled soil for backfilling.

On May 30 and 31, 1996 TPE conducted stockpile soil remediation as described in Section 3.1.5 Method of Stockpile Soil Remediation.

3.2.12.1 Methyl t-Butyl Ether (MTBE)

ACHCSA requested that MTBE be analyzed for in conjunction with BTEX chemicals. MTBE has been analyzed for since May 1996. MTBE has not been detected in any soil sample during excavation activities.

3.2.13 June 1996

Stockpile Soil Remediation

On June 1 and June 3 through 7, 1996 TPE conducted stockpile soil remediation as described in Section 3.1.5 Method of Stockpile Soil Remediation.

3.2.14 July 1996

Stockpile Soil Remediation and Stockpile Verification Soil Sampling

On July 22 through 25, 1996 TPE conducted stockpile soil remediation as described in Section 3.1.5 Method of Stockpile Soil Remediation.

On July 30, 1996 TPE conducted verification stockpile sampling as described in Section 3.1.6 Method of Verification Stockpile Soil Sampling. About 394 cyds were sampled (see Figure 12).

Analytical results for verification stockpile samples VSP-20A(7/30/96) through VSP-29(7/30/96) for TPHG and BTEX chemicals were nondetectable.

Results of chemical analyses are documented in Table 1 with certified analytical reports and chain-of-custodies in Appendix E.

3.2.15 August 1996

On August 1, 1996 ACHCSA verbally approved the reuse of remediated stockpiled soil.

3.2.16 September 1996

Excavation and Collection of Verification Soil Samples, Excavation Backfilling, and Stockpile Soil Remediation

On September 16, 17, and 18, 1996 TPE partially backfilled the excavation with remediated stockpiled soil as described in Section 3.1.7 Method of Excavation Backfilling. Excavation activities continued in the area of VS-28 and VS-29. Excavation activities were conducted described in Section 3.1 Method of Excavation. Excavated soil was segregated into two stockpiles (apparently clean and contaminated). All verification soil sampling was conducted as described in Section 3.1.4 Verification Soil

<u>Sampling</u>. Stockpile soil sampling was conducted as described in Section 3.1.4 <u>Stockpile</u> <u>Soil Sampling</u> (see Figure 13).

Analytical results detected TPHG in verification soil samples VS-30 through VS-35 in TPHG was also detected in concentrations ranging from 8.2 ppm to 110 ppm. stockpile soil samples STK-20A,B,C,D(09/16/96), STK-21A,B,C,D(09/17/96), STK-26A,B,C,D(09/17/96) collected from apparent 25A,B,C,D(09/17/96) and contaminated soil at concentrations of 44 ppm, 90 ppm, 210 ppm, and 31 ppm, respectively. Some or all BTEX chemicals were detected in verification and stockpile STK-22A,B,C,D(09/16/96), STKsamples soil soil samples. Stockpile 23A,B,C,D(09/16/96) and STK-24A,B,C,D(09/17/96) collected from apparently clean segregated soil, were nondetectable for TPHG and BTEX.

Results of chemical analyses are documented in Table 1 with certified analytical reports and chain-of-custodies in Appendix E.

ACHCSA verbally approved clean segregated stockpiled soil for backfilling.

On September 18 and 19, 1996 TPE partially backfilled the excavation with remediated soil to make additional room for remediation activities. The excavation was backfilled as described in Section 3.1.7 Method of Excavation Backfilling

On September 20, 26 through 30, 1996 TPE conducted stockpile soil remediation as described in Section 3.1.5 Method of Stockpile Soil Remediation.

3.2.17 October 1996

Stockpile Soil Remediation and Verification Stockpile Soil Sampling

On October 1 through 3, 1996 TPE conducted stockpile soil remediation as described in Section 3.1.5 Method of Stockpile Soil Remediation.

ACHCSA issued a October 3, 1996 letter to WONG titled Status of Subsurface Investigation at 2345 E. 14th St., Oakland CA 94601, Former Taxi, Taxi requesting no

further soil excavation be conducted until the offsite investigation is completed (see Appendix A).

On October 4, 1996 TPE conducted verification stockpile sampling as described in Section 3.1.6 Method of Verification Stockpile Soil Sampling. About 405 cyds were sampled (see Figure 14).

Analytical results for verification stockpile soil samples, VSP-30A through VSP-39D were nondetectable for TPHG and BTEX chemicals.

Results of chemical analyses are documented in Table 1 with certified analytical reports and chain-of-custodies in Appendix E.

ACHCSA verbally approved 405 cyds of stockpiled soil for backfilling.

3.2.17.1 Excavation Closure

Excavation Backfilling

On October 28, 1996 TPE backfilled the excavation. The excavation was backfilled as described in Section 3.1.7 Method of Excavation Backfilling. The excavation was backfilled to grade awaiting asphalt in the near future.

4.0 QUARTERLY GROUNDWATER MONITORING

TPE has conducted quarterly groundwater monitoring on March 31, 1994 through September 30, 1996. The reader is referred to Table 3 for a summary of TPHG and BTEX chemical concentrations detected in the wells during the quarterly events.

Figure 15 is a groundwater gradient map constructed from the data collected on September 24 and 30, 1996. Groundwater flow direction was to the northwest with a gradient about 0.018 feet per foot.

Table 4 summarizes the thickness of floating product measured in each well. The floating product was removed during purging at the time of each quarterly sampling.

5.0 CONCLUSIONS

Figure 16 shows names, location, depths, and analytical results of final verification soil samples. Final verification soil samples are those samples collected when the sidewalls were excavated to their furthest horizontal and vertical extent and the floor was excavated to its greatest depths.

Final verification soil samples, depicted in Figure 16, detected TPHG concentrations ranging from nondetectable to 110 ppm TPHG in sidewall samples. Verification soil samples collected from the floor of the excavation detected TPHG and BTEX concentrations ranging from nondetectable to 66 ppm.

TPE believes that low concentrations of TPHG and BTEX remain within the former tank excavation. These concentrations have minimal impact to the groundwater.

6.0 RECOMMENDATIONS

TPE recommends no further remediation of vadose zone soil in the area of the former tank excavation area.

Figure 16 also shows soil samples collected during monitoring well installation. In MW-1 and MW-2, vadose zone soil samples collected during installation detected TPHG and BTEX at concentrations of 225 ppm and 4.320 ppm, and 1.505 ppm and 7.275 ppm, 4.225 ppm and 6.620 ppm, 4.015 ppm and 3.470 ppm and 4.270 ppm and 13.815 ppm, respectively. TPE recommends excavation of vadose zone soils in the area around MW-1 and MW-2 to further site remediation.

TPE also recommends that the soil boring program be conducted to determine the horizontal limits of the groundwater contaminate plume and the free product limits.


TPE recommends that free product removal be continued to limit the spread of such contamination into formerly uncontaminated zones. TPE recommends that quarterly monitoring be conducted to assess the remediation activities efforts.


7.0 STUDY LIMITATIONS


This report describes the subsurface exploration and laboratory analyses of soil and groundwater samples. The chemical analytical results for the samples are considered applicable to that location from which they were collected. The soil encountered in the excavation is believed to be representative of the site; however, the soil may vary in character between observation points. The conclusions contained herein are based on the field observations, analytical data and professional judgement which is in accordance with current standards of professional practice. Representations made of soil and groundwater conditions between sample locations are extrapolations based on professional opinions and judgements and accepted industry practice. Therefore, TPE cannot and will not provide guarantees, certifications or warranties that the subject property is or is not free of all contaminated soil or groundwater and such assessments are provided so that the client may make an informed decision.


The extent of testing and data collection directly affects the statistical confidence level of all work performed. As a practical matter, to reach or even approach a 100 percent statistical confidence level would be prohibitively expensive. Therefore, if a reassessment of the subject property becomes necessary in the future, TPE will not reassess the area at its own cost. No other warranty is expressed or implied.


The findings and conclusions of this report are valid as of the present time; however, the passing of time could change the conditions of the subsurface due to natural processes or the influence of man. Accordingly, the findings of this report may be invalidated, wholly or partly, by changes beyond TPE's control. Therefore, this report should not be relied upon after an extended period of time without being reviewed by a Civil Engineer or Registered Geologist.


















NDTE: TOTAL VOLUME OF STOCKPILE 42X17X6 = 4284 CFT 4284 CFT / 27 CFT/ CYD = 158.66 CYDS EACH CELL = 19.83 CYDS

L.EGEND

VSPI-A NAME AND APPROXIMATE LOCATION

* OF SOIL SAMPLE





TANK PROTECT ENGINEERING


SITE PLAN: VERIFICATION STOCKPILE SAMPLING (7/12/95)


CREDIT WORLD AUTO SALES 2345 E. 14TH STREET DAKLAND, CA 94601


	DATE	12/11/96				
	FIGURE	7				
	FILE #	267-7N				
	DRAVN BY	VK				
	CHECKED BY	LNH				
	LHEUKED BY	LINT				























TABLE 1
SUMMARY OF SOIL SAMPLE ANALYTICAL RESULTS
(ppm¹)

Sample ID Name	Date	Depth (Feet)	ТРНС	Methyl t- Butyl Ether	Benzene	Toluene	Ethyl- benzene	Xylenes
B-1	10/03/88	15.0	3.4	NA ⁴	.310	< 0.1	< 0.1	.140
B-2	10/03/88	15.0	83	NA	1.6	1.1	1.8	9.6
B-3	10/03/88	15.0	NA	NA	.360	.650	.470	.850
MW-1	05/22/91	10.0	150	NA	.460	.365	.305	.960
MW-1	05/22/91	15.0	255	NA	1.505	4,255	4.015	4.270
TH-1	08/21/91	15.0	2,775	NA	1.235	1.060	1.625	5.280
TH-2	08/21/91	10.0	360	NA	< 0.005	< 0.005	< 0.005	0.770
TH-2	08/21/91	30.0	50	NA	< 0.005	< 0.005	< 0.005	< 0.005
MW-2	08/21/91	10.0	4,320	NA	7.275	6.620	3.470	13.815
MW-2	08/21/91	15.0	160	NA	< 0.005	< 0.005	< 0.005	< 0.005
TH-3 ²	08/22/91	10.0	10	NA	< 0.005	< 0.005	< 0.005	< 0.005
TH-3 ²	08/22/91	19.0	10	NA	< 0.005	< 0.005	< 0.005	< 0.005
TH-4 ²	08/22/91	10.0	25	NA	< 0.005	< 0.005	< 0.005	0.175
TH-4 ²	08/22/91	20.0	450	NA	< 0.005	< 0.005	< 0.005	< 0.005
MW-3 ²	08/22/91	10.0	50	NA	< 0.005	< 0.005	< 0.005	< 0.005
MW-3 ²	08/22/91	15.0	25	NA	< 0.005	< 0.005	< 0.005	< 0.005
TH-5	08/22/91	10.0	10	NA	< 0.005	< 0.005	< 0.005	< 0.005
TH-5	08/22/91	18.0	<5	NA	< 0.005	< 0.005	< 0.005	< 0.005
TMW-4	07/22/93	5.5-6.0	<.500	NA	< 0.005	< 0.005	< 0.005	<.015
TMW-4	07/22/93	10.5-11.0	<.500	NA	< 0.005	< 0.005	< 0.005	<.015
TMW-4	07/22/93	15.5-16.0	.940	NA	< 0.005	< 0.005	< 0.005	<.015
TMW-5	07/23/93	5.5-6.0	2.4	NA	.026	< 0.005	< 0.005	.053
TMW-5	07/23/93	10.5-11.0	14	NA	.900	< 0.005	1.6	<.140
TMW-5	07/23/93	15.5-16.0	16	NA	.840	< 0.005	.690	1.3
VS-1	12/06/94	19.5	1.3	NA	.010	.061	.027	.190
VS-2	12/06/94	14.5	51	NA	.61	.100	1.3	.940
VS-3	12/06/94	16.5	210	NA	1.1	.300	4.5	140

TABLE 1
SUMMARY OF SOIL SAMPLE ANALYTICAL RESULTS
(ppm¹)

Sample ID Name	Date	Depth (Feet)	TPHG	Methyl t- Butyl Ether	Benzene	Toluene	Ethyl- benzene	Xylenes
VS-4	12/06/94	14.5	20	NA	1.2	.094	.470	2.4
VS-5	12/06/94	13.5	100	NA	.440	<.150	2.2	8.5
VS-6	12/06/94	4.0	2.7	NA	.046	< 0.005	< 0.005	< 0.015
STK1-A,B,C,D	12/06/94	2.0-2.5	5.3	NA	<.014	<.014	.023	.12
STK2-A,B,C,D	12/06/94	2.0-2.5	9.2	NA	.015	<.014	.084	.300
STK3-A,B,C,D	12/06/94	3.5-4.0	45	NA	<.140	.180	.710	4.4
STK4-A,B,C,D	12/06/94	3.0-3.5	40	NA	.380	.140	.750	2.5
STK5-A,B,C,D	12/06/94	4.0-4.5	78	NA	.200	.780	1.2	8.1
STK6-A,B	12/06/94	2.0-2.5	9.8	NA	.052	< 0.015	.046	.240
VSP-1A	05/12/95	1.0-1.5	<1.0	NA	< 0.005	< 0.005	< 0.005	< 0.005
VSP-2B	05/12/95	2.0-2.5	<1.0	NA	< 0.005	< 0.005	< 0.005	< 0.005
VSP-3C	05/12/95	3.5-4.0	<1.0	NA	< 0.005	< 0.005	< 0.005	< 0.005
VSP-4D	05/12/95	1.0-1.5	<1.0	NA	< 0.005	< 0.005	< 0.005	< 0.005
VSP-5A	05/12/95	2.0-2.5	<1.0	NA	< 0.005	< 0.005	< 0.005	< 0.005
VSP-6B	05/12/95	3.5-4.0	<1.0	NA	< 0.005	< 0.005	< 0.005	< 0.005
VSP-7C	05/12/95	1.0-1.5	<1.0	NA	< 0.005	< 0.005	< 0.005	< 0.005
VSP-8D	05/12/95	2.0-2.5	<1.0	NA	< 0.005	< 0.005	< 0.005	< 0.005
VSP-9A	05/12/95	3.5-4.0	<1.0	NA	< 0.005	< 0.005	< 0.005	< 0.005
VSP-10B	05/12/95	1.0-1.5	<1.0	NA	< 0.005	< 0.005	< 0.005	< 0.005
VS-6	06/30/95	21.0	< 0.5	NA	< 0.005	< 0.005	< 0.005	< 0.015
VS-7	06/30/95	14.0	50	NA	.370	.070	.990	3.3
STK7(1-4)	07/03/95	3.0-3.5	290	NA	.560	.970	3.0	11.0
STK8(1-4)	07/03/95	2.0-2.5	49	NA	.100	.100	.550	1.8
STK9(1-4)	07/03/95	2.0-2.5	78	NA	.052	.036	.520	1.6
STK10(1,2,3,4)	07/03/95	3.0-3.5	22	NA	.012	.012	.032	.089
STK11(1,2,3,4) ³	07/03/95	3.0-3.5	<1.0	NA	< 0.005	< 0.005	< 0.005	< 0.005
VS-8	07/03/95	16.0	33	NA	.036	.022	.066	.099

SUMMARY OF SOIL SAMPLE ANALYTICAL RESULTS (ppm^1)

Sample ID Name	Date	Depth (Feet)	ТРНС	Methyl t- Butyl Ether	Benzene	Toluene	Ethyl- benzene	Xylenes
VS-9	07/05/95	15.0	42	NA	.060	.036	.089	.120
VS-10	07/05/95	15.0	130	NA	.180	.085	.250	.370
VS-11	07/05/95	16.0	81	NA	.073	.086	.160	.210
VS-12	07/05/95	21.0	<1.0	NA	< 0.005	< 0.005	< 0.005	< 0.005
VS-13	07/05/95	16.0	75	NA	.048	.040	.078	.180
VSP 1A	07/12/95	1.0-1.5	<1.0	NA	< 0.005	< 0.005	< 0.005	< 0.005
VSP 2B	07/12/95	2.0-2.5	4.0	NA	< 0.005	.017	.026	.099
VSP 3C	07/12/95	3.5-4.0	<1.0	NA	< 0.005	< 0.005	< 0.005	<0.005
VSP 4D	07/12/95	1.0-1.5	<1.0	NA	< 0.005	< 0.005	< 0.005	< 0.005
VSP 5A	07/12/95	2.0-2.5	<1.0	NA	< 0.005	< 0.005	< 0.005	< 0.005
VSP 6B	07/12/95	3.5-4.0	<1.0	NA	< 0.005	< 0.005	< 0.005	< 0.005
VSP 7C	07/12/95	1.0-1.5	<1.0	NA	< 0.005	< 0.005	< 0.005	< 0.005
VSP 8D	07/12/95	2.0-2.5	<1.0	NA	< 0.005	< 0.005	< 0.005	< 0.005
VS-14	07/28/95	19.0	2.8	NA	.300	.016	.094	.140
VS-15	07/28/95	15.0	61	NA	.470	.042	1.2	.730
VS-16	07/28/95	16.0	38	NA	.400	.043	.420	.590
VS-17	07/28/95	19.0	14	NA	.120	.018	.150	.110
VS-18	07/28/95	14.0	590	NA	3.1	2.4	10	52
STK12(A-D)	07/28/95	2.0-2.5	87	NA	.260	.140	1.6	3
STK13(A-D)	07/28/95	3.0-3.5	58	NA	.210	.097	.630	2.3
VSP 11A	10/03/95	1.5-2.0	<1.0	NA	< 0.005	< 0.005	< 0.005	< 0.005
VSP 12B	10/03/95	2.0-2.5	<1.0	NA	< 0.005	< 0.005	< 0.005	< 0.005
VSP 13C	10/03/95	3.0-3.5	<1.0	NA	< 0.005	< 0.005	< 0.005	< 0.005
VSP 14D	10/03/95	1.5-2.0	<1.0	NA	< 0.005	< 0.005	< 0.005	< 0.005
VSP 15A	10/03/95	2.0-2.5	<1.0	NA	< 0.005	< 0.005	< 0.005	< 0.005
VSP 16B	10/03/95	3.0-3.5	<1.0	NA	< 0.005	< 0.005	< 0.005	< 0.005
VSP 17C	10/03/95	1.5-2.0	<1.0	NA	< 0.005	< 0.005	< 0.005	< 0.005

TABLE 1 SUMMARY OF SOIL SAMPLE ANALYTICAL RESULTS (ppm¹)

Sample ID Name	Date	Depth (Feet)	ТРНС	Methyl t- Butyl Ether	Benzene	Toluene	Ethyl- benzene	Xylenes
VSP 18D	10/03/95	2.0-2.5	<1.0	NA	< 0.005	< 0.005	< 0.005	< 0.005
VSP 19A	10/03/95	3.0-3.5	<1.0	NA	< 0.005	< 0.005	< 0.005	< 0.005
VSP 20B	10/03/95	1.5-2.0	<1.0	NA	< 0.005	< 0.005	< 0.005	< 0.005
VSP 21C	10/03/95	2.0-2.5	<1.0	NA	< 0.005	< 0.005	< 0.005	< 0.005
STK-1 A,B,C,D	05/24/96	2.0-3.0	170	< 0.005	.110	.160	.710	2.6
VS-2D	05/24/96	18.0	140	< 0.005	.170	.210	.280	1.5
VF-1	05/24/96	21.0	10	< 0.005	< 0.005	.0074	.0095	.037
STK-2 A,B,C,D	05/24/96	2.0-3.0	320	< 0.005	.100	.095	1.2	2.1
STK-1,A,B,C,D	05/29/96	2.5-3.0	1.7	< 0.005	< 0.005	< 0.005	.005	.017
STK-2A,B,C,D	05/29/96	2.5-3.0	140	< 0.005	.013	.026	.047	.094
VS-22	05/29/96	14.0	22	< 0.005	.0065	< 0.005	.020	.031
VS-23	05/29/96	19.0	<1.0	< 0.005	< 0.005	< 0.005	< 0.005	< 0.005
VS-24	05/29/96	14.0	<1.0	< 0.005	< 0.005	< 0.005	< 0.005	< 0.005
VS-25	05/29/96	19.0	<1.0	< 0.005	< 0.005	< 0.005	< 0.005	< 0.005
VS-26	05/29/96	14.0	66	< 0.005	.0063	.022	.024	.130
VS-27	05/29/96	18.0	3.9	< 0.005	< 0.005	< 0.005	< 0.005	.033
VS-28	05/29/96	12.5	450	< 0.005	.170	.120	.280	.390
STK-3A,B,C,D	05/30/96	2.5-3.0	<1.0	< 0.005	< 0.005	< 0.005	< 0.005	< 0.005
STK-4A,B,C,D	05/30/96	2.5-3.0	<1.0	< 0.005	< 0.005	< 0.005	< 0.005	< 0.005
STK-5A,B,C,D	05/30/96	2.5-3.0	<1.0	< 0.005	< 0.005	< 0.005	< 0.005	< 0.005
STK-6A,B,C,D	05/30/96	2.5-3.0	<1.0	< 0.005	< 0.005	< 0.005	< 0.005	< 0.005
VS-29	05/30/96	12.5	470	< 0.005	.049	.085	.250	.760
VSP-20A	07/30/96	1.5-2.0	<1.0	< 0.005	< 0.005	< 0.005	< 0.005	< 0.005
VSP-21B	07/30/96	2.5-3.0	<1.0	< 0.005	< 0.005	< 0.005	< 0.005	< 0.005
VSP-22C	07/30/96	3.5-4.0	<1.0	< 0.005	< 0.005	< 0.005	< 0.005	< 0.005
VSP-23D	07/30/96	1.5-2.0	<1.0	< 0.005	< 0.005	< 0.005	< 0.005	< 0.005
VSP-24A	07/30/96	2.5-3.0	<1.0	< 0.005	< 0.005	< 0.005	< 0.005	< 0.005

TABLE 1
SUMMARY OF SOIL SAMPLE ANALYTICAL RESULTS
(ppm¹)

Sample ID Name	Date	Depth (Feet)	TPHG	Methyl t- Butyl Ether	Benzene	Toluene	Ethyl- benzene	Xylenes
VSP-25B	07/30/96	3.5-4.0	<1.0	< 0.005	< 0.005	< 0.005	< 0.005	< 0.005
VSP-26C	07/30/96	1.5-2.0	<1.0	< 0.005	< 0.005	< 0.005	< 0.005	< 0.005
VSP-27D	07/30/96	2.5-3.0	<1.0	< 0.005	< 0.005	< 0.005	< 0.005	< 0.005
VSP-28A	07/30/96	3.5-4.0	<1.0	< 0.005	< 0.005	< 0.005	< 0.005	< 0.005
VSP-29B	07/30/96	1.5-2.0	<1.0	< 0.005	< 0.005	< 0.005	< 0.005	< 0.005
STK-20A,B,C,D	09/16/96	2.0-2.5	44	< 0.005	.075	.090	.110	.170
STK-22A,B,C,D	09/16/96	1.5-2.0	<1.0	< 0.005	< 0.005	< 0.005	< 0.005	< 0.005
STK-23A,B,C,D	09/16/96	1.0	< 1.0	< 0.005	< 0.005	< 0.005	< 0.005	< 0.005
VS-30	09/16/96	15	8.2	< 0.005	.040	.054	.250	.210
VS-31	09/16/96	14	110	< 0.005	.280	.210	.460	.490
STK-25A,B,C,D	09/17/96	1.0	210	< 0.005	.180	.098	.120	.240
STK-26A,B,C,D	09/17/96	1.0	31	< 0.005	.050	.063	.084	.250
VS-32	09/17/96	12	20	< 0.005	.120	.120	.130	.280
VS-33	09/17/96	12	7.5	< 0.005	.019	.034	.060	.200
VS-34	09/17/96	12	52	< 0.005	.190	.140	.630	.660
VS-35	09/17/96	12	29	< 0.005	.023	.130	.072	.500
STK-21A,B,C,D	09/17/96	1.0	90	< 0.005	.120	.084	.190	.320
STK-24A,B,C,D	09/17/96	1.5-2.0	< 1.0	< 0.005	< 0.005	< 0.005	< 0.005	< 0.005
VSP-30A	10/04/96	1.0-1.5	<1.0	< 0.005	< 0.005	< 0.005	< 0.005	< 0.005
VSP-31B	10/04/96	1.5-2.0	<1.0	< 0.005	< 0.005	< 0.005	< 0.005	< 0.005
VSP-32C	10/04/96	2.0-2.5	<1.0	< 0.005	< 0.005	< 0.005	< 0.005	< 0.005
VSP-33D	10/04/96	1.0-1.5	<1.0	< 0.005	< 0.005	< 0.005	< 0.005	< 0.005
VSP-34A	10/04/96	1.5-2.0	<1.0	< 0.005	< 0.005	< 0.005	< 0.005	< 0.005
VSP-35B	10/04/96	2.0-2.5	<1.0	< 0.005	< 0.005	< 0.005	< 0.005	< 0.005
VSP-36A	10/04/96	1.5-2.0	<1.0	< 0.005	< 0.005	< 0.005	< 0.005	< 0.005
VSP-37B	10/04/96	1.5-2.0	<1.0	< 0.005	< 0.005	< 0.005	< 0.005	< 0.005
VSP-38C	10/04/96	1.5-2.0	<1.0	< 0.005	< 0.005	< 0.005	< 0.005	< 0.005

TABLE 1 SUMMARY OF SOIL SAMPLE ANALYTICAL RESULTS (ppm¹)

Sample ID Name	Date	Depth (Feet)	ТРНС	Methyl t- Butyl Ether	Benzene	Toluene	Ethyl- benzene	Xylenes
VSP-39D	10/04/96	1.5-2.0	<1.0	< 0.005	< 0.005	< 0.005	< 0.005	< 0.005

¹ PARTS PER MILLION.

² ALSO ANALYZED FOR TOTAL RECOVERABLE HYDROCARBONS BY ESE; SEE ESE 12/23/91 REPORT FOR ANALYTICAL RESULTS.

³ ALSO ANALYZED FOR TOTAL PETROLEUM HYDROCARBONS AS DIESEL: ALL ANALYTICAL RESULTS WERE NONDECTABLE.

⁴ NOT ANALYZED.

TABLE 2 SUMMARY OF EXCAVATION GROUNDWATER SAMPLE ANALYTICAL RESULTS (ppb^1)

Sample ID Name	Date	TPHG	Benzene	Toluene	Ethyl- benzene	Xylenes
GB-1 ²	05/12/95	< 50.0	<0.5	<0.5	< 0.5	<0.5

¹ PARTS PER BILLION.

² EXCAVATION SAMPLE

TABLE 3
SUMMARY OF GROUNDWATER SAMPLE ANALYTICAL RESULTS (ppb¹)

Sample ID Name	Date	ТРНС	Methyl t- Butyl Ether	Benzene	Toluene	Ethyl- benzene	Xylenes
MW-1	08/17/93	110,000	NA ²	270	690	730	3,100
	03/28/94	34,000	NA	4,900	1,800	1,200	4,000
	06/27/94	21,000	NA	12,000	810	760	2,500
	09/16/94	37,000	NA	7,900	2,400	1,300	3,300
	03/31/95	43,000	NA	8,100	1,900	1,000	4,200
	06/28/95	80,000	NA	7,900	3,200	1,800	7,300
	09/28/95	24,000	<1,200	4,900	470	470	1,700
	12/26/95	61,000	<1,200	12,000	4,200	1,500	5,500
	03/22/96	19,000	<2,500	6,000	47	260	< 750
	06/20/96	15,000	910	2,900	100	240	98
	09/24/96	20,000	340	4,800	220	300	770
MW-2	08/17/93	49,000	NA	94	240	250	980
	03/28/94	14,000	NA	4,200	<250	910	1,400
	06/27/94	24,000	NA	4,400	72	1,100	1,700
	09/16/94	40,000	NA	2,300	250	2,000	4,100
	03/31/95	28,000	NA	4,000	< 120	1,100	1,400
	06/28/95	40,000	NA	2,700	130	1,700	2,900
	09/28/95	7,500	< 62	420	14	250	190
·	12/26/95	22,000	<250	1,300	88	950	1,800
	03/22/96	9,800	<1,200	2,200	< 120	400	< 380
	06/20/96	35,000	550	770	<0.5	240	< 0.5
	09/30/96	58,000	< 5.0	1,600	230	2,200	4,000
MW-3	08/17/93	9,600	NA	4.1	17	28	54
	03/28/94	8,400	NA	2,400	56	67	200
	06/27/94	9,900	NA	3,300	<22	<25	73
	09/16/94	16,000	NA	2,300	80	620	240
	03/31/95	16,000	NA	2,800	70	<25	920

TABLE 3
SUMMARY OF GROUNDWATER SAMPLE ANALYTICAL RESULTS (ppb¹)

Sample ID Name	Date	TPHG	Methyl t- butyl ether	Benzene	Toluene	Ethyl- benzene	Xylenes
MW-3	06/28/95	11,000	NA	2,300	32	81	240
	09/28/95	6,300	<420	1,900	<42	200	< 120
	12/26/95	25,000	<250	3,800	97	94	1,600
	03/22/96	16,000	250	3,100	75	69	350
	06/20/96	8,500	220	1,400	28	140	15
	09/24/96	12,000	<5.0	2,400	87	340	110
TMW-4	08/17/93	150	NA	< 0.50	0.8	1.4	3.7
	03/28/94	<50	NA	< 0.50	< 0.50	< 0.50	<1.5
	06/27/94	< 50	NA	< 0.50	< 0.50	< 0.50	<1.5
	09/16/94	< 50	NA	< 0.50	< 0.50	< 0.50	<1.5
	03/31/95	< 50	NA	< 0.50	< 0.50	< 0.50	<1.5
	06/28/95	<50	NA	< 0.50	< 0.50	< 0.50	<1.5
	09/28/95	<50	< 5.0	< 0.50	< 0.50	< 0.50	<1.5
	12/26/95	< 50	< 5.0	< 0.50	< 0.50	< 0.50	<1.5
	03/22/96	< 50	< 5.0	< 0.50	< 0.50	< 0.50	<1.5
	06/20/96	<50	< 5.0	< 0.50	< 0.50	< 0.50	< 0.50
	09/24/96	<50	< 5.0	< 0.50	< 0.50	< 0.50	< 0.50
TMW-5	08/17/93	120,000	NA	340	730	790	3,600
	03/28/94	70,000	NA	23,000	1,500	4,100	15,000
	06/28/94	56,000	NA	26,000	940	5,500	26,000
	09/16/94	96,000	NA	17,000	720	3,500	12,000
	03/31/95	64,000	NA	13,000	470	2,800	6,100
	06/28/95	65,000	NA	9,000	240	2,600	5,300
	09/28/95	79,000	<1,200	17,000	1,800	2,700	7,000
	12/26/95	110,000	<1,200	24,000	2,300	4,100	10,000
	03/22/96	56,000	<2,500	11,000	800	2,300	4,500
	06/26/96	30,000	830	4,000	180	1,500	2,500
	09/30/96	6,900	< 5.0	1,600	79	130	370

TABLE 3 SUMMARY OF GROUNDWATER SAMPLE ANALYTICAL RESULTS (ppb1)

Sample ID Name	Date	TPHG	Methyl t- butyl ether	Benzene	Toluene	Ethyl- benzene	Xylenes
MW-6 ⁴	03/22/96	< 50	<5.0	< 0.50	< 0.50	< 0.50	<1.5
	06/20/96	< 50	<5.0	<0.5	<0.5	< 0.5	< 0.50
	09/24/96	<50	<5.0	< 0.5	< 0.5	< 0.5	< 0.5
	09/30/96	<50	<5.0	< 0.5	< 0.5	< 0.5	< 0.5

PARTS PER BILLION.

² NOT ANALYZED.
³ TRIP BLANK.

⁴ SAME AS TMW-6 (TRIP BLANK).

TABLE 4
SUMMARY OF FLOATING PRODUCT THICKNESS

Well Name	Date	Depth-to-Water From TOC ¹ (Feet)	Depth-to-Product From TOC (Feet)	Product Thickness (Feet)
MW-1	04/16/92 ²	16.66	11.54	5.12
	06/11/93	12.61	12.60	0.01
	08/17/93	14.40	13.63	0.77
	03/31/94	12.64	ND	
	06/27/94	14.32	13.16	1.16
	09/16/94	15.86	13.64	2.22
	03/31/95	11.82	9.48	2.34
	06/28/95	13.50	12.60	0.90
	09/28/95	14.27	13.96	0.31
	12/26/95	11.77	11.62	0.15
	03/22/96	10.52	10.44	0.08
	06/20/96	13.38	12.49	0.089
	09/24/96	14.60	13.40	1.20
MW-2	04/16/92 ²	15.38	12.57	2.81
	06/11/93	13.185	ND ³	
	08/17/93	14.04	14.03	0.01
	03/31/94	13.61	13.07	0.54
	06/27/94	14.24	13.44	0.80
	09/16/94	17.82	13.36	4.46
	03/31/95	16.72	9.28	7.44
	06/28/95	13.50	12.77	0.73
	09/28/95	14.63	14.09	0.54
	12/26/95	12.58	11.68	0.90
	03/22/96	11.46	11.31	0.15
	06/20/96	13.08	12.71	0.37
	09/30/96	16.67	12.92	3.75

TABLE 4
SUMMARY OF FLOATING PRODUCT THICKNESS

Well Name	Date	Depth-to-Water From TOC ¹ (Feet)	Depth-to-Product From TOC (Feet)	Product Thickness (Feet)
MW-3	04/16/92 ²	14.14	13.98	0.16
	06/11/93	14.275	ND	
	08/17/93	15.77	ND	
	03/31/94	14.35	ND	
	06/27/94	14.77	ND	
	09/16/94	15.42	15.37	
	03/31/95	12.98	12.52	0.46
	06/28/95	14.20	14.15	0.05
	09/28/95	15.7	ND	
	12/26/95	13.33	13.27	0.06
	03/22/96	12.81	12.77	0.04
	06/20/96	13.95	13.88	0.07
	09/24/96	14.86	14.82	0.04
TMW-4	08/17/93	13.26	ND	
	03/31/94	12.40	ND	
-	06/27/94	12.84	ND	
	09/16/94	13.58	ND	p===
	03/31/95	10.23	ND	
	06/28/95	12.21	ND	
	09/28/95	13.38	ND	
	12/26/95	11.32	ND	
	03/22/96	10.54	ND	
	06/20/96	12.14	ND	
	09/24/96	13.01	ND	
TMW-5	08/17/93	12.98	12.95	0.03
	03/31/94	11.39	ND	
	06/27/94	12.24	ND	

TABLE 4
SUMMARY OF FLOATING PRODUCT THICKNESS

Well Name	Date	Depth-to-Water From TOC ¹ (Feet)	Depth-to-Product From TOC (Feet)	Product Thickness (Feet)	
TMW-5	09/16/94	13.02	12.97	0.05	
	03/31/95	7.38	ND		
	06/28/95	11.31	11.25	0.06	
	09/28/95	14.42	ND		
	12/26/95	10.16	10.11	0.05	
	03/22/96	7.59	7.54	0.05	
	06/20/96 ¹¹	7.12	ND		
	09/30/9611	7.42	ND		

¹ TOP-OF-CASING.

² RELATIVE TO SITE DATUM ESTABLISHED BY ESE.

BLEVATION CORRECTED FOR FLOATING PRODUCT USING 0.75 DENSITY FOR GASOLINE.

⁴ MEAN SEA LEVEL

⁵ WATER LEVEL MEASUREMENTS BY ESE.

⁶ WATER LEVEL MEASUREMENTS BY NKJ.

⁷ TOC SURVEYED 8/10/93 BY PROFESSIONAL ENGINEER.

⁸ CORRECTED GROUNDWATER ELEVATION BY TANK PROTECT ENGINEERING.

⁹ NOT AVAILABLE.

¹⁰ NOT DETECTED.

¹¹ WELL TOP DESTROYED DURING REMEDIATION

APPENDIX A

- A. ALAMEDA COUNTY HEALTH CARE SERVICES AGENCY, LETTER DATED AUGUST 4, 1994
- . ALAMEDA COUNTY HEALTH CARE SERVICES AGENCY, LETTER DATED SEPTEMBER 7, 1994
- . ALAMEDA COUNTY HEALTH CARE SERVICES AGENCY, LETTER DATED JANUARY 25, 1995
- . ALAMEDA COUNTY HEALTH CARE SERVICES AGENCY, LETTER DATED MAY 17, 1995
- . TPE LETTER TO THE OAKLAND FIRE PREVENTION BUREAU DATED JUNE 15, 1995
- . ALAMEDA COUNTY HEALTH CARE SERVICES AGENCY, LETTER DATED OCTOBER 26, 1995
- . ALAMEDA COUNTY HEALTH CARE SERVICES AGENCY, LETTER DATED OCTOBER 3, 1996

ALAMEDA COUNTY HEALTH CARE SERVICES AGENCY

DAVID J. KEARS, Agency Director

August 4, 1994 StID # 2116

Mr. Stanley Wong 2200 E. 12th St. Oakland CA 94606 RAFAT A. SHAHID, ASST. AGENCY DIRECTOR

DEPARTMENT OF ENVIRONMENTAL HEALTH

Alameda County Health Care Services Agency Dept. Of Environmental Health 1131 Harbor Bay Pkwy 2nd Flr. Alameda Ca 94502-6577

NOTICE OF VIOLATION

Re: Request for Work Plan Addendum for the Further Investigation and Remediation of 2345 E. 14th St., former Taxi Taxi

Dear Mr. Wong:

Our office has received and reviewed the July 29, 1994 report prepared by Tank Protect Engineering (TPE). This report indicates that significant groundwater contamination still exists on this site and potentially offsite. Remediation of this contamination must be initiated immediately. Certainly, the free fuel product being found in monitoring wells MW-1 and MW-2 must be removed on a regular basis as required by Section 2655 of Article 5, Chapter 16 of the Underground Storage Tank Regulations. Please describe what will be done to satisfy this requirement.

Recall, the November 4, 1993 Preliminary Site Assessment (PSA) for this site prepared by TPE recommended the following future actions:

- a. Limited overexcavation of contaminated soils and possible removal of contaminated water from the excavation pit;
- b. Installation of three additional monitoring wells and
- c. Institute quarterly groundwater monitoring.

Our office agreed with this approach and requested that a specific work plan be submitted to perform this work by March 21, 1994. Although quarterly monitoring has been initiated, our office has not received the specific work plan. Please submit the requested report to our office within 30 days or by August 8, 1994. This report should also include a time schedule for implementation.

You are reminded that this letter constitutes a formal request for technical reports pursuant to the California Water Code Section 13267 (b). Failure to submit and complete the work plan may subject you to civil liability.

Please be aware that our offices have recently moved to: 1131 Harbor Bay Parkway, Room 250, Alameda CA 94502.

Mr. Stanley Wong StID # 2116 2345 E. 14th St. August 4, 1994 Page 2.

You may reach me at (510) 567-6700 if you have any questions.

Sincerely,

Barney M. Chan

Hazardous Materials Specialist

arner in Cha

cc: G. Jensen, Alameda County District Attorney Office

J. Mrakovich, Tank Protect Engineering, 2821 Whipple Rd., Union City, CA 94587-1233

E. Howell, files

NOV2345

ALAMEDA COUNTY HEALTH CARE SERVICES AGENCY

DAVID J. KEARS, Agency Director

RAFAT A. SHAHID, ASST. AGENCY DIRECTOR

DEPARTMENT OF ENVIRONMENTAL HEALTH
State Water Resources Control Board
Division of Clean Water Programs
UST Local Oversight Program
80 Swan Way, Rm 200
Oakland, CA 94621
(510) 271-4530

September 7, 1994 StID # 2116

Mr. Stanley Wong 2200 E. 12th St. Oakland CA 94606

Re: Commant on August 26, 1994 Work Plan for the Excavation of Soil and Installation of Monitoring Wells at 2345 E. 14th St., Oakland CA 94601.

Dear Mr. Wong:

Our office has received and reviewed the above referenced work plan as prepared by your consultant, Tank Protect Engineering (TPE). Recall, this work plan calls for the excavation of soils around the former underground tank pit, the extraction of groundwater from the pit and the installation of three additional monitoring wells. After discussion with Mr. John Mrakovich of TPE, it was agreed that you should initiate the overexcavation and groundwater extraction as soon as possible. Please contact our office at least 48 working hours prior to your field work so we may be present to witness any confirmatory soil sampling.

It was noted that groundwater extraction should be done if there is any evidence of petroleum contamination. The high concentration of gasoline and BTEX detected in monitoring well TMW-5 indicates the likelihood of encountering contaminated groundwater during the excavation. Bioremediation of groundwater within the pit and within the existing wells was also discussed. Our office will confer with the RWQCB to see if any permitting requirements exist. We will inform your consultant with our findings.

In regards to the location of the additional monitoring wells, it was agreed that it would be best to see what affect the soil excavation and groundwater extraction has on the existing wells prior to committing to the additional well locations. With this in mind, the installation of the additional wells will be put on hold. You may contact me at (510) 567-6765 should you have any questions.

Sincerely,

Barney M. Chan

Barrer Ula_

Hazardous Materials Specialist

cc: J. Mrakovich, TPE, 2821 Whipple Rd., Union City CA 94587-1233

E. Howell, files wpap2345

ALAMEDA COUNTY HEALTH CARE SERVICES

AGENCY DAVID J. KEARS, Agency Director



RAFAT A. SHAHID, ASST, AGENCY DIRECTOR

DEPARTMENT OF ENVIRONMENTAL HEALTH ALAMEDA COUNTY CC4580 DEPT. OF ENVIRONMENTAL HEALTH ENVIRONMENTAL PROTECTION DIV. 1131 HARBOR BAY PKWY., #250 ALAMEDA CA 94502-6577

January 25, 1995 StID # 2116

Mr. Stanley Wong 2200 E. 12th St. Oakland CA 94606

Re: Review of Work Plan for Stockpiled Soil Remediation at 2345 E. 14th St., Oakland CA 94601, Credit World Auto Sales

Dear Mr. Wong:

Our office has received and reviewed the January 24, 1995 report prepared by Tank Protect Engineering. Recall this report details the history of the above site, gives the results of recent confirmatory soil samples after overexcavation and proposes to chemically treat for reuse the excavated stockpiled soils.

I have discussed the work plan with Mr. John Mrakovich of TPE and it is acceptable. Work may proceed as soon as possible. Please contact me at least 48 hours prior to initial soil sampling so I may arrange to be present to witness this work, if possible.

You may contact me at (510) 567-6765 if you have any questions.

Sincerely,

Barney M. Chan

Hazardous Materials Specialist

cc: J. Mrakovich, Tank Protect Engineering, 2821 Whipple Rd., Union City, CA 94587

E. Howell, file

Samer de Cha-

wpsp2345

ALAMEDA COUNTY HEALTH CARE SERVICES AGENCY

DAVID J. KEARS, Agency Director



RAFAT A. SHAHID, DIRECTOR

DEPARTMENT OF ENVIRONMENTAL HEALTH
State Water Resources Control Board
Division of Clean Water Rrograms
UST Local Oversight Program
1131 Harbor Bay Parkway
Alameda, CA 94502-6577
(510) 567-6700

May 17, 1995 StID # 2116

Mr. Stanley Wong 2200 E. 12th St. Oakland CA 94606

Re: Status of Subsurface Investigation at 2345 E. 14th St., Oakland CA 94601, Former Taxi Taxi

Dear Mr. Wong:

Thank you for the submission of the May 3, 1995 quarterly monitoring report for the above site. Currently, the excavated soil from the site has been treated and sampled. Upon verifying successful treatment, this soil is proposed for reuse.

The continuing detection of both floating petroleum product and high dissolved levels of gasoline in monitoring wells at this site will require immediate action. The California Underground Tank Regulations, Title 23, Division 3, Chapter 16, Section 2655 requires the removal of free product to limit the spread of such contamination into previously uncontaminated zones. Because of this, you should inform our office what steps are being done to remove free product on a regular basis. You should also update your quarterly monitoring reports with the total cumulative volume or pounds of free product which have been removed from this site.

Based on the groundwater contamination being detected, additional groundwater investigation must be performed to determine the extent of such contamination. Either temporary or permanent subsurface investigation may be performed, however, the installation of permanent monitoring wells will be required to verify the limits of the hydrocarbon plume.

It is agreed that one would expect decreasing levels of contamination in groundwater due to the excavation of the contaminated soils, but the immediate removal of free product is a priority.

You should also investigate the types of remedial actions available for this site. This is done in the form of a feasibility study which examines at least two alternatives to restore or protect the beneficial uses of the groundwater beneath this site. The alternative should also propose cleanup levels for soil and groundwater.

Mr. Stanley Wong StID # 2116 2345 E. 14th St. May 17, 1995 Page 2.

Your immediate comment regarding the removal of free product is requested within 30 days or by June 19, 1995. A work plan for additional groundwater investigation should be submitted with your next groundwater monitoring report ie June 1995. Based on the levels of groundwater contamination being found at that time, a feasibility study should be submitted. Please have your consultant mention their remedial alternatives in your next groundwater monitoring report.

You may contact me at (510) 567-6765 if you have any questions.

Sincerely,

Barney M. Chan

Hazardous Materials Specialist

cc: J. Mrakovich, TPE, 2821 Whipple Rd., Union City, CA 94587-1233

B. Raynolds, files

add2345

June 15, 1995

Mr. Jerry E. Blueford, Fire Marshall Fire Prevention Bureau 421 14th Street, First Floor Oakland, CA 94612

RE: Operation of a product removal system at 2345 E. 14th Street, Oakland, CA 94601

Dear Mr. Blueford:

This letter gives a description of a product (gasoline) removal system that Tank Protect Engineering of Northern California, Inc. (TPE) wishes to install and operate at the subject site. The system will pump gasoline from groundwater monitoring wells into two 55-gallon drums located outside and adjacent to an onsite building (see attached Site Plan). With the exception of an electric air compressor, the system is operated by compressed air making it explosion proof.

The drums have dual sensors (backup) that detect when they are near full to shut the system off. The system must be restarted manually. Vapors from the drums will be vented back into the wells to minimize potential hazardous accumulations. The drums will be double contained by placing them on top of 6-mil plastic sheeting that will be bermed to contain their contents if overfilling or leaking occurs.

When the 55-gallon drums are full, the gasoline will be removed by a vacuum truck and transported under manifest to a recycling facility. No more than 2 full drums will be on site at any time.

The following discusses the technical aspects of the system, its method of operation, and TPE's operation and maintenance procedure (see attached Schematic).

Mr. Jerry E. Blueford, Fire Marshall Fire Prevention Bureau

Product Removal System

TPE will obtain a product only recovery system that consists of a selective oil skimmer and a controllerless, down-well mounted, air-operated, resilient bladder product pump and two product storage tanks (55-gallon drums) that shut off automatically when near full. The system removes free-floating product down to a sheen (< 0.01 inch).

Method of Operation

A selective oil skimmer is placed in the well. The skimmer has a floating intake head that follows the fluctuating water table and automatically adjusts to any groundwater fluctuation within its travel range (about 3 feet). Hydrocarbons enter the skimmer and pass through an intake having an outer debris screen. The hydrocarbons then pass through an inner oileophilic hydrophobic screen, through a flexible tube, and into the bladder pump. The oileophilic hydrophobic screen allows liquid hydrocarbons to pass and repels water.

Compressed air collapses the bladder and pushes the hydrocarbons up a product hose and into a surface mounted holding tank (55-gallon drum). Intake and discharge check valves prevent back flow of fluids. This process repeats itself automatically at a rate determined by settings on a pressure relief screw.

The holding tank has two product sensors (a bubbler sensor and a float sensor) that shut the system off when the tank is nearing full. When product reaches a high level in the holding tank, one of the two tank-full shut-off's level sensors automatically turns off the entire system until manually reset. The holding tank also has a fume return line that directs fumes back into the well to avoid potential hazardous accumulations.

All hoses used in the system are industrial grade. The product hose is urethane covered, braided-steel reinforced, nylon-cored hose having 18,000 pounds per square inch burst pressure with swaged-on connectors and double shut-off quick connects. The product hose provides static ground running its entire length through the steel-braided reinforcement and the brass (non-sparking) double shut-off quick connects.

Page 3 of 3

Mr. Jerry E. Blueford, Fire Marshall Fire Prevention Bureau

The above system can pump up to 100 gallons per day. TPE anticipates that only a few gallons per day will be pumped at the subject site.

Operation and Maintenance

TPE personnel will install and operate the product recovery system.

TPE will install the skimmer system, bladder pump, and two product holding tanks (55-gallon drums). The holding tanks will be installed outside the northwest-end of the onsite building (see attached Figure). The site's perimeter chain-link fencing, onsite guard dog, and onsite security guard will provide protection for the public and security for the system against vandalism.

TPE will start up and operate the system to ensure proper operation of all components. When the storage tanks are full, the tanks will be emptied by vacuum truck and the product will be manifested and hauled off site to a permitted recycling facility.

If you have any questions, please call me at (510) 429-8088.

Sincerely,


John V. Mrakovich


Senior Registered Geologist

STERED GEOLG

4665

Expiration Dates Spril 30, 1996





June 14, 1995

Mr. Barney M. Chan
Hazardous Materials Specialist
Alameda County Health Care Services Agency
1131 Harbor Bay Parkway
Alameda, CA 94502-6577

RE: Status of Subsurface Investigation at 2345 E. 14th Street, Oakland, CA 94601

Dear Mr. Chan:

In a May 17, 1995 letter to Mr. Stanley Wong, you requested that free product be removed on a regular basis from groundwater monitoring wells at the subject property. Mr. Wong has authorized Tank Protect Engineering of Northern California, Inc. (TPE) to remove the free product pursuant to your request. This letter documents the procedure that TPE will implement to remove the free product on a regular basis.

Product Removal System

TPE will obtain a product only explosion proof recovery system that consists of a selective oil skimmer and a controllerless, down-well mounted, air-operated, resilient bladder product pump and a product storage tank that shuts off automatically when the product tank is full. The system removes free-floating product down to a sheen (< 0.01 inch).

Mr. Barney M. Chan Alameda County Health Care Services Agency

Method of Operation

A selective oil skimmer is placed in the well. The skimmer has a floating intake head that follows the fluctuating water table and automatically adjusts to any groundwater fluctuation within its travel range (about 3 feet). Hydrocarbons enter the skimmer and pass through an intake having an outer debris screen. The hydrocarbons then pass through an inner oileophilic hydrophobic screen, through a flexible tube, and into the bladder pump. The oileophilic hydrophobic screen allows liquid hydrocarbons to pass and repels water.

Compressed air collapses the bladder and pushes the hydrocarbons up a product hose and into a surface mounted holding tank (55-gallon drum). Intake and discharge check valves prevent back flow of fluids. This process repeats itself automatically at a rate determined by settings on a pressure relief screw.

Compressed air well be supplied to the bladder pump by an electric 1 horsepower compressor providing 3.5 cubic feet of air per minute.

The holding tank has two product sensors (a bubbler sensor and a float sensor) that shut the system off when the tank is nearing full. When product reaches a high level in the holding tank, one of the two tank-full shut-off's level sensors automatically turns off the entire system until manually reset. The second product sensor is a backup to the first to provide overflow protection if the first sensor fails. The holding tank will be double-contained by placing the tank on top of plastic sheeting that is bermed to contain any product that may overflow in the event that both overflow sensors fail. The holding tank will be sealed with a lid and have a fume return line that directs fumes back into the well to avoid potential hazardous accumulations.

All hoses used in the system are industrial grade. The product hose is urethane covered, braided-steel reinforced, nylon-cored hose having 18,000 pounds per square inch burst pressure with swaged-on connectors and double shut-off quick connects. The

Mr. Barney M. Chan

Alameda County Health Care Services Agency

product hose provides static ground running its entire length through the steel-braided reinforcement and the brass (non-sparking) double shut-off quick connects.

The above system can pump up to 100 gallons per day.

Operation and Maintenance

TPE personnel will install and operate the product recovery system. A permit to operate the system will be required by the City of Oakland Fire Department (COFD).

On the approval of the COFD, TPE will install the skimmer system, bladder pump, and two product holding tanks. TPE proposes to install the holding tanks outside the northwest-end of the onsite building. The site's perimeter chain-link fencing, onsite guard dog, and onsite security guard will provide protection for the public and security for the system against vandalism.

TPE will start up and operate the system to ensure proper operation of all components. When the storage tanks are full, the tanks will be emptied by vacuum truck and the product will be manifested and hauled off site to a permitted recycling facility. TPE will maintain a record of all manifests and the volume of product pumped from the wells and hauled off site; this information will be documented and reported in quarterly groundwater monitoring reports.

TPE personnel will visit the site as frequently as necessary to ensure that product removal is continuous from the wells. The skimmer and bladder pump will be moved from well to well until no further product is available for pumping. TPE anticipates that the column of product in each well will be removed quickly by pumping and will recharge slowly. When a column of product is found to have recharged into any well, the product removal system will be re-installed and the product pumped out.

Page 4 of 4

Mr. Barney M. Chan Alameda County Health Care Services Agency

Time Schedule

TPE anticipates to select a product removal system by June 16, 1995. An application will be made to the COFD to install and operate the system by June 23, 1995. When a permit is received from the COFD, TPE will order and immediately install and operate the system. Delivery of the system from that manufacturer is expected to take 3 to 6 weeks.

If you have any questions, please call me at (510) 429-8088.

Sincerely,

John V. Mrakovich

Senior Registered Geologist



Expiration Date April 30, 1996

cc: Mr. Stanley Wong, 2200 E. 12th Street, Oakland, CA 94606

CITY OF					
그는 그 살았다. 그 그 그는 그는 살에 바꿨다는 그 병에는 그는 그는 그를 그리고 그 모든 그를 그 그를 그 그를 그 그를 그리고 그로 그리고 그를 그리고 그리고 그를 그리고 그리고 그를 그리고	OAI	KLAND		Tani	k Permit
Permit to Excavate and Install, Repa	ir, or Re	move Infla	mmable Liquid 1	<mark>'anks.</mark> No.	9931
	Oakland,	California,	June 19		
PERMISSION IS HEREBY GRANTED TO MANNE remove	XXXXX	CANALINA tank an	d excavate commencing	feet in	side property
• •	reet renue	feet	of		Stree
TO AND LAND WE HOPED TO CANCELL TO	reet renue	Present Storage	<u>, , , , , , , , , , , , , , , , , , , </u>		
Owner Stanley Wong	dress 220	0 E. 12th	St., Oakland	Phone	535-1672
Applicant Tank Protect Engineering of Northern CA Ad	dress 282	1 Whipple	Rd. Union City	Phone	4298088
Dimensions of street (sidewalk) surface to be disturbed X	Nu		Capacity	94587	
Romarts:		<u>.</u>			· · · · · · · · · · · · · · · · · · ·
3pproved	_	,	1 7 7	1 1	
Approved	- - -	er en	The second of the second		<u>evil</u>
Fire Membal	- - - - -	The second secon			
Approved Orainage Division Engineering Dept			W .		8.4
Oralinage Division Engineering Dept EXCAVATING PERMIT					
Oralinage Division Engineering Dept EXCAVATING PERMIT Issued in accordance with Ord. No. 278 CMS, Sec. 6-2.04					
Approved Oralnege Division Engineering Dept EXCAVATING PERMIT	.	TIFICATE (S OF TANK AND EG	E	INSPECTION
Drainage Division Engineering Dept EXCAVATING PERMIT Issued in accordance with Ord. No. 278 CMS, Sec. 6-2.84 square feet of digging or removal granted The receipt of \$special deposit is hereby acknowledged	l. CE	RTIFICATE (E	INSPECTION
Orainage Division Engineering Dept EXCAVATING PERMIT Lassed in accordance with Ord. No. 278 CMS, Sec. 6-2.84 square feet of digging or removal granted	l. CE			E	INSPECTION
Drainage Division Engineering Dept EXCAVATING PERMIT Issued in accordance with Ord. No. 278 CMS, Sec. 6-2.04 square feet of digging or removal granted The receipt of \$special deposit is hereby acknowledged GENERAL DEPOSIT.	l. CE			E	INSPECTION 19
Drainage Division Engineering Dept EXCAVATING PERMIT Issued in accordance with Ord. No. 278 CMS, Sec. 6-2.04 square feet of digging or removal granted The receipt of \$special deposit is hereby acknowledged GENERAL DEPOSIT.	l. CE				10

THIS PERMIT MUST BE LEFT ON THE WORK AS AUTHORITY THEREFOR.

638.58 (5.67)

भिन्ने विकास के अपने के किस के कि







421 FOURTEENTH STREET + OAKLAND, CALIFORNIA 94612

Fire Prevention Bureau

(510) 238-3851 TDD 839-6451

FAX TRANSMITTAL SHEET

Fire Prevention Bureau

421 - 14TH Street Oakland, CA 94617

Telephone: (510) 238-3851 Fax: (510) 238-6739

TO:	John	DATE: 6/2/195
COMPANY:	Tank Protect Engineering	PRONE: 429-8089
FROM:	Fixe Down hon Buccay	PAGES:
_	No enclosures - message only For your information & file Flease review and comment In accordance with your request	Please handle Advise of status URGERT ! ! ! For your signature
Comments	·	-

opy for FIRE MARSHAL	£ac	evation Permit	Granted	l	Ne
CIT	YOFO	AKLA	ND		lank Permit
Permit to Excavate and Insta	ıli, Repair, o	r Remove	Inflammable Li	quid Tanks.	ło
	-		•, <u> </u>		
PERMISSION IS HEREBY GRANTED TO MININ	remove \integral	Gas Nr. Saplica	tank and excevate com	mencingfoo	t inside
theide of	Street	- fact			Street
No. 2345 E. 14th St., Ookland 946/il	Chank		Sterage		
weer the section works			_		
plicest Tank Proposit Engineering of Norther					
nonsions of street (sidewalk) surface to be disturbed	×	Number of	TenksCep	94587	Gellons, each
neris:					·
Drainage Division Engis	eering Dept.		w		-
EXCAVATING PERMIT					,,,,,,
lessed in accordance with Ord. No. 278 CMS, Sec. 4-2.	94			·	
square feat of digging or tem	oval granted.			S	w **********
to receipt of \$special deposit is hereby a	złnowiedaed.		ATE OF TANK A		
GENERAL DEPOSIT.		•	pessed on		
BUREAU OF PERMITS AN	D LICENSES.	Ву			Fire Membel
repoction Fee Paid 8	. 	Dofor 4	N O Covering Tenks, Al	TICE	dont Ba Sianad
tebeved by	<u>t</u>		Lovering Jenus, me or inspection notify Mr		_
PINE PREVENTION BUREAU		***************************************	ahaeinau mailià am		

THIS PERMIT MUST BE LEFT ON THE WORK AS AUTHORITY THEREFOR.

	City of Oakland
--	-----------------

Cash Receipt No. 725322

Cash Check D487

DIRECT CASH CRE	Fund/SF	Organization	Account	Proj/Grant/ Cost Ctr./WC	Yr	Loc	Task	Dept Specific	Fixed Asset No	Trans ID	Revenue Source	Amount .
1 Dil Remova		20310	42412		5							\$100.0
2		<u> </u>			\sqcup		-					•
3			ļ		igwdapprox					-	 	•
4		 		<u> </u>	╂┼					 	 	
xillary Receipt Reference			<u> </u>		<u> </u>	<u> </u>		7-		SUE	TOTAL	\$100 C
0000111011 <u>-</u>												
		Description	on			in the		Custon	ier Number	Invoice I	Number 3	Amount
	Kalendari da Salada	Description	on _{ye wa}			1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	A Section	⇒ Custon	ier Number	Invoice I	Number 3	Amount 500 . C
lem		Descripti	on ,			8 1 1 1 1		Custon	jer Number	Invoice	Number :	Amount 500 . C
tem 1		Description	on _{years}					Custon	jer Number	Invoice	Number 3	Amount 5 2
tem 1 2 3 4		Description	on ,					Custon	jer Number	Invoice I	Number :	Amount 5 2
tem 1 2 3		Description	on ,					Custon	jer Number		OTAL	Amount 5
1 2 3 4		Description					ntered k		ier Number		OJAL:	400 . (
1 2 3 4	Andrew Control	/ Description		eived by:			ntered t		jer Number	SMET	OJAL:	400 . (

61/695

ALAMEDA COUNTY HEALTH CARE SERVICES AGENCY

DAVID J. KEARS, Agency Director

RAFAT A. SHAHID, DIRECTOR

DEPARTMENT OF ENVIRONMENTAL HEALTH
State Water Resources Control Board
Division of Clean Water Programs
UST Local Oversight Program
1131 Harbor Bay Parkway
Alameda, CA 94502-6577
(510) 567-6700

October 26, 1995 StID # 2116

Mr. Stanley Wong 2200 E. 12th St. Oakland, CA 94606

Re: Comment on August 4, 1995 Work Plan for Soil and Groundwater Investigation at 2345 E. 14th St., Oakland CA 94601

Dear Mr. Wong:

Our office has received and reviewed the above report as prepared by your consultant, Tank Protect Engineering. This work plan calls for the advancement of nine borings to groundwater and the sampling of both selected soil and grab groundwater samples in an attempt to verify the horizontal limits of the gasoline contamination from the former underground storage tanks. This work plan is accepted and field work may commence as soon as possible. Please note that borings SB-6 and SB-1 may not be necessary if the borings closer to the site indicate that the petroleum plume has been defined.

Based on the results of these borings you should prepare a work plan for the installation of additional well(s) to define the limits of the petroleum plume.

Please contact me at least 48 hours prior to your field activities. I may be reached at (510) 567-6765.

Sincerely,

Barney M. Chan

Hazardous Materials Specialist

CC: L. Huckins, Tank Protect Engineering, 2821 Whipple Rd., Union City, CA 94587-1233

G. Coleman, files

wp2345

ALAMEDA COUNTY

HEALTH CARE SERVICES

AGENCY

DAVID J. KEARS, Agency Director



October 3, 1996 StID # 2116

Mr. Stanley Wong 2200 E. 12th St. Oakland CA 94606 ENVIRONMENTAL HEALTH SERVICES ENVIRONMENTAL PROTECTION (LOP) 1131 Harbor Bay Parkway, Suite 250 Alameda, CA 94502-6577 (510) 567-6700 FAX (510) 337-9335

. 激色式-

e Marin.

Re: Status of Subsurface Investigation at 2345 E. 14th St., Oakland CA 94601, Former Taxi Taxi

Dear Mr. Wong:

This letter serves to recount a recent conversation with Mr. Lee Huckins of Tank Protect Engineering (TPE). Among the items discussed was the continued offsite investigation at the above site. The overexcavation activities has delayed the offsite investigation proposed in TPE's August 4, 1995 workplan. I would like to inform you of the significant items of our conversation as well approve and request implementation of the offsite investigation.

At this time, no further soil excavation is requested. I am aware that soil contamination may still exist in the northern portion of the property, however, offsite investigation should be performed prior to any additional soil excavation.

Monitoring well TMW-5 was being considered for closure since it had been damaged during the excavation activities. It was decided that this well should remain since it is nearest the source of the release and could be used in future remediation.

Your consultant was requested to investigate the various options for free product removal and implement an appropriate one. Several of the monitoring wells have consistently detected free product, therefore, a removal system must be implemented as soon as possible.

In regards to the previously proposed offsite investigation, the proposal to install up to nine offsite borings is accepted by our office. Please be aware that since the August 1995 proposal date, additional boring techniques are commonly in use. Therefore, you are encouraged to use any of the rapid site assessment techniques ie Geoprobe, Hydropunch etc. In addition, you should begin your offsite investigation radially outward from the former tank pit area. The extreme borings on E. 14th St. and Miller Ave. should be done only if necessary. Based on the boring locations, permits will be required to gain drilling access. Please initiate the permit procedures as soon as possible. You should also be aware that offsite monitoring wells

Mr. Stanley Wong StID # 2116 2345 E. 14th St. October 3, 1996 Page 2.

will be required to determine the extent of the groundwater plume. You may want to consider installing permanent wells immediately after the initial investigation so this could be done under the same permit.

Please include a status of the above items in your future quarterly monitoring reports.

You may contact me at (510) 567-6765 if you have any questions.

Sincerely,

Barney M. Chan .

Barney M Cha

Hazardous Materials Specialist

C: Mr. L. Huckins, TPE, 2821 Whipple Rd., Union City, CA 94587 B. Chan, files

ssi2345

APPENDIX B

SAMPLE HANDLING PROCEDURES

APPENDIX B

SAMPLE HANDLING PROCEDURES

Soil and groundwater samples will be packaged carefully to avoid breakage or contamination and will be delivered to the laboratory in an iced-cooler. The following sample packaging requirements will be followed.

- . Sample bottle/sleeve lids will not be mixed. All sample lids will stay with the original containers and have custody seals affixed to them.
- Samples will be secured in coolers to maintain custody, control temperature and prevent breakage during transportation to the laboratory.
- . A chain-of-custody form will be completed for all samples and accompany the sample cooler to the laboratory.
- . Ice, blue ice or dry ice (dry ice will be used for preserving soil samples collected for the Alameda County Water District) will be used to cool samples during transport to the laboratory.
- . Water samples will be cooled with crushed ice. In the Alameda County Water District, water samples will be buried in the crushed ice with a thermometer, and the laboratory will be requested to record thermometer temperature at the time of receipt.
- Each sample will be identified by affixing a pressure sensitive, gummed label or standardized tag on the container(s). This label will contain the site identification, sample identification number, date and time of sample collection and the collector's initials.
- Soil samples collected in brass tubes will be preserved by covering the ends with Teflon tape and capping with plastic end-caps. The tubes will

be labeled, sealed in quart size bags and placed in an iced-cooler for transport to the laboratory.

All groundwater sample containers will be precleaned and will be obtained from a State Department of Health Services certified analytical laboratory.

Sample Control/Chain-of-Custody: All field personnel will refer to this workplan to verify the methods to be employed during sample collection. All sample gathering activities will be recorded in the site file; all sample transfers will be documented in the chain-of-custody; samples will be identified with labels; all sample bottles will be custody-sealed. All information is to be recorded in waterproof ink. All TPE field personnel are personally responsible for sample collection and the care and custody of collected samples until the samples are transferred or properly dispatched.

The custody record will be completed by the field technician or professional who has been designated by the TPE project manager as being responsible for sample shipment to the appropriate laboratory. The custody record will include, among other things, the following information: site identification, name of person collecting the samples, date and time samples were collected, type of sampling conducted (composite/grab), location of sampling station, number and type of containers used and signature of the TPE person relinquishing samples to a non-TPE person with the date and time of transfer noted. The relinquishing individual will also put all the specific shipping data on the custody record.

Records will be maintained by a designated TPE field employee for each sample: site identification, sampling location, station number, date, time, sampler's name, designation of the sample as a grab or composite, notation of the type of sample (e.g., groundwater, soil boring, etc.), preservatives used, onsite measurement data and other observations or remarks.

APPENDIX C

WASTE HANDLING AND DECONTAMINATION PROCEDURES

APPENDIX C

WASTE HANDLING AND DECONTAMINATION PROCEDURES

<u>Decontamination</u>: Any drilling, sampling or field measurement equipment that comes into contact with soil or groundwater will be properly decontaminated prior to its use at the site and after each incident of contact with the soil or groundwater being investigated. Proper decontamination is essential to obtain samples that are representative of environmental conditions and to accurately characterize the extent of soil and groundwater contamination. Hollow-stem auger flights and the drill bit will be steam-cleaned between the drilling of each well.

All sample equipment, including the split-spoon sampler and brass tubes, will be cleaned by washing with trisodium phosphate or alconox detergent, followed by rinsing with tap water. Where required by specific regulatory guidelines, a nonphosphate detergent will be used.

Waste Handling: Waste materials generated during site characterization activities will be handled and stored as hazardous waste and will be stored on site in appropriately labeled containers. Waste materials anticipated include excavated soil, drill cuttings, development and purge water, water generated during aquifer testing, water generated during decontamination and used personnel protection equipment such as gloves and Tyvek. The site owner will be responsible for providing the storage containers and will be responsible for the disposal of the waste materials. Drill cuttings from individual borings will be stored separately in drums or covered by plastic sheeting, and the appropriate disposal procedure will be determined by the site owner or TPE following receipt of the soil sample analytical results. Drums will be labeled to show material stored, known or suggested contaminant, date stored, expected removal date, company name, contact and telephone number.

APPENDIX D

QUALITY ASSURANCE AND QUALITY CONTROL PROCEDURES

APPENDIX D

QUALITY ASSURANCE AND QUALITY CONTROL PROCEDURES

The overall objectives of the field sampling program include generation of reliable data that will support development of a remedial action plan. Sample quality will be checked by the use of proper sampling, handling and testing methods. Additional sample quality control methods may include the use of background samples, equipment rinsate samples and trip and field blanks. Chain-of-custody forms, use of a qualified laboratory, acceptable detection limits and proper sample preservation and holding times also provide assurance of accurate analytical data.

TPE will follow a quality assurance and quality control (QA/QC) program in the field to ensure that all samples collected and field measurements taken are representative of actual field and environmental conditions and that data obtained are accurate and reproducible. These activities and laboratory QA/QC procedures are described below.

<u>Field Samples</u>: Additional samples may be taken in the field to evaluate both sampling and analytical methods. Three basic categories of QA/QC samples that may be collected are trip blanks, field blanks and duplicate samples.

Trip blanks are a check for cross-contamination during sample collection, shipment, and laboratory analysis. They are water samples that remain with the collected samples during transportation and are analyzed along with the field samples to check for residual contamination. Analytically confirmed organic-free water will be used for organic parameters and deionized water for metal parameters. Blanks will be prepared by the laboratory supplying the sample containers. The blanks will be numbered, packaged and sealed in the same manner as the other samples. One trip blank will be used for sets greater than 20 samples. The trip blank is not to be opened by either the sample collectors or the handlers.

The field blank is a water sample that is taken into the field and is opened and exposed at the sampling point to detect contamination from air exposure. The water

sample is poured into appropriate containers to simulate actual sampling conditions. Contamination due to air exposure can vary considerably from site to site.

The laboratory will not be informed about the presence of trip and field blanks, and false identifying numbers will be put on the labels. Full documentation of these collection and decoy procedures will be made in the site log book.

Duplicate samples are identical sample pairs (collected in the same place and at the same time), placed in identical containers. For soils, adjacent sample liners will be analyzed. For the purpose of data reporting, one is arbitrarily designated the sample, and the other is designated as a duplicate sample. Both sets of results are reported to give an indication of the precision of sampling and analytical methods.

The laboratory's precision will be assessed without the laboratory's knowledge by labeling one of the duplicates with false identifying information. Data quality will be evaluated on the basis of the duplicate results.

Laboratory OA/QC: Execution of a strict QA/QC program is an essential ingredient in high-quality analytical results. By using accredited laboratory techniques and analytical procedures, estimates of the experimental values can be very close to the actual value of the environmental sample. The experimental value is monitored for its precision and accuracy by performing QC tests designed to measure the amount of random and systematic errors and to signal when correction of these errors is needed.

The QA/QC program describes methods for performing QC tests. These methods standards, check standards (both blanks, calibration involve analyzing method Protection Agency-certified independent and the United States Environmental Internal QC also requires standards), duplicates, replicates and sample spikes. adherence to written methods, procedural documentation and the observance of good laboratory practices.

APPENDIX E

CERTIFIED ANALYTICAL REPORTS AND CHAIN-OF-CUSTODY DOCUMENTATION

LOG NUMBER: DATE SAMPLED: 4993 12/06/94

DATE RECEIVED:

12/07/94

DATE EXTRACTED:

12/07/94

DATE ANALYZED:

12/08/94

DATE REPORTED:

12/12/94

CUSTOMER:

Tank Protect Engineering

REQUESTER:

Jeff Farhoomand

PROJECT:

No. 267-120694, Credit World Auto Sales, 2345 East 14th Street

	Sample Type: Soil										
		٧	S-1		VS-2	v	S-3				
Method and Constituent:	<u>Units</u>	Concen- tration	Reporting Limit	Concen- tration	Reporting Limit	Concen- tration	Reporting <u>Limit</u>				
DHS Method:											
Total Petroleum Hydro- carbons as Gasoline	ug/kg	1,300	500	51,000	3,700	210,000	7,400				
Modified EPA Method 8020	for:	• -									
Benzene	ug/kg	10	5.0	610	74	1,100	150				
Toluene	ug/kg	61	5.0	100	74	300	150				
Ethylbenzene	ug/kg	27	5.0	1,300	74	4,500	150				
Xylenes	ug/kg	190	15	940	220	14,000	440				
		٧	S-4	\	/S-5		/S-6				
Method and Constituent:	<u>Units</u>	Concen- tration	Reporting Limit	Concen- tration	ReportingLimit	Concen- tration	Reporting <u>Limit</u>				
DHS Method:											
Total Petroleum Hydro- carbons as Gasoline	ug/kg	20,000	740	100,000	7,400	2,700	500				
Modified EPA Method 8020	for:										
Benzene	ug/kg	1,200	15	440	150	46	5.0				
Toluene	ug/kg	94	15	ND	150	ND	5.0				
Ethylbenzene	ug/kg	470	15	2,200	150	ND	5.0				
Xylenes	ug/kg	2,400	44	8,500	440	ND	15				

Concentrations reported as ND were not detected at or above the reporting limit.

Trace Analysis Laboratory, Inc.

LOG NUMBER: 4993
DATE SAMPLED: 12/06/94
DATE RECEIVED: 12/07/94
DATE EXTRACTED: 12/07/94
DATE ANALYZED: 12/08/94
DATE REPORTED: 12/12/94
PAGE: Two

Sampi	le	Type:	<u>Soil</u>

		STK1-A.	site of B,C, and D	STK2-A,	site of B,C, and D	<u>STK3-A,</u>	Composite of STK3-A,B,C, and D		
Method and Constituent:	Units	Concen-	Reporting Limit	Concen- tration	Reporting Limit	Concen- <u>tration</u>	Reporting Limit		
constituent.	DILLES	<u>tration</u>	<u>LIMIU</u>	<u>cracion</u>	LIMIC	<u>ci ac ion</u>	<u>L I (III] U</u>		
DHS Method:									
Total Petroleum Hydro- carbons as Gasoline	ug/kg	5,300	710	9,200	720	45,000	7,200		
Modified EPA Method 8020	for:								
Benzene	ug/kg	ND	14	15	14	ND	140		
Toluene	ug/kg	ND	14	ND	14	180	140		
Ethylbenzene	ug/kg	23	14	84	14	710	140		
Xylenes	ug/kg	120	43	300	43	4,400	430		
			site of		site of B,C, and D		site of and STK6-B		
Method and Constituent :	<u>Units</u>	Concentration	B,C, and D Reporting Limit	Concen- tration	Reporting Limit		Reporting Limit		
DHS Method:									
Total Petroleum Hydro- carbons as Gasoline	ug/kg	40,000	7,200	78,000	7,100	9,800	730		
Modified EPA Method 8020	for:								
Benzene	ug/kg	380	140	200	140	52	15		
Toluene	ug/kg	ND	140	780	140	ND	15		
Ethylbenzene	ug/kg	750	140	1,200	140	46	15		
Xylenes	ug/kg	2,500	430	8,100	420	240	44		

Concentrations reported as ND were not detected at or above the reporting limit.

Trace Analysis Laboratory, Inc.

LOG NUMBER: 4993
DATE SAMPLED: 12/06/94
DATE RECEIVED: 12/07/94
DATE EXTRACTED: 12/07/94
DATE ANALYZED: 12/08/94
DATE REPORTED: 12/12/94
PAGE: Three

Sample Type: Soil

·		Metho	d Blank
Method and Constituent:	<u>Units</u>	Concen- tration	Reporting <u>Limit</u>
DHS Method:			
Total Petroleum Hydro- carbons as Gasoline	ug/kg	ND	500
Modified EPA Method 8020	for:		
Benzene	ug/kg	ND	5.0
Toluene	ug/kg	ND	5.0
Ethylbenzene	ug/kg	ND	5.0
Xylenes	ug/kg	ND	15

OC Summary:

% Recovery: 96

% RPD: 4.6

Concentrations reported as ND were not detected at or above the reporting limit.

Louis W. DuPuis

Quality Assurance/Quality Control Manager

TANK PROTECT ENGINEERING

2821 WHIPPLE ROAD UNION CITY, CA 94587 (415)429-8088 (800)523-8088 FAK(415)429-8089

4993

LAB:	AL
------	----

TURNAROUND: 3 DAYS

P.O. #: 477

CHAIN OF CUSTODY

PAGE ___ OF ____

PROJECT	T NO		SIT	E NAME &	ADDRESS		Ì	Т		_	7	7	7	7	7///
}		1/	_ 100 K	itu	ADDRESS LIMST	Saler	1	AHAY.	B,	3/	<u> </u>	./	/		/_///
267/10	694		2345	EI	44154		(1)	ا څ	181		'/&	/ _{\cu}	/ z. /		
SAMPLER	NAME,	WULLEY	י אינוע כ	ELECTIONS	1.0410-11		TYPE OF	₩	3/.	\$/	<i>ن</i> اري	13	7/\	/ع	/// REMARKS
2821 UHTD	<i>دل</i> Die Roai	90 H	M CITY	775 945	87 (415) 4	29-8088	CON-		/, 🤄	1/5/	/\$\/	(3)	3/	/ ~ /	./ /
ID NO.	DATE	TIME	SOIL	VATER	SAMPLING I		TAINER		\$\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\	3/3			8/8/	9/	/ /
								Γ	/₹	<u> </u>		4	~~	_{	
VSP-1	12/6	1512	¥	· · · · · · · · · · · · · · · · · · ·	19.5	- ALL	Bres	人		•	Ц	\perp		_	
V58-Z	1	1574			14.5		Briss	7	7			4			
	17/4	1533	+		16.5		Bas	1	*	Ŀ		_	1		•
V58-4		1540	4		14.5		ጛሎሄ	7	×			_	_		
V5₽-5	12/4	1550	1		13.5		Briss	1	7		Ц	\bot	4	_	
V58-6	12/6	DIS-	4	ļ.	H.O _		BRW	¥	×				_		
		-						Π	Γ			T	1		
	 		,					\vdash			П	十	1		
Repinquish	ed by	(Sign	ature)	/ D4	e / Time	Received b	y : (Signa	tur	=)	Rol	ngu	ishe	d b	39	: (Signature) Date / Time Received by : (Signature)
Lead	' V	•		12/1	H19:00	Mari.	Mu	Ca		7	38.6	'n	T	γ	al 14/9/43/05
Relinquish			atura)	Dat	o / Time	Received_b	y(Signă	tur	ιKe	2eli	រាញបរ	she	d by	у :	: (Signature) (Date / Time Received by : (Signature)
Relinquish	ed by	(51an	ature)	Date	o / Time	Received for t	aboratory by	:	+	Đ	2)0	/ Ti	NO.		Remarks
Kelindalsu				1-	1	[Signature] [[4	47	14	3:0	5		A

plu, soil, y-8, i-BT each, 3-Day

DATE: 17 794

TANK PROTECT ENGINEERING

2821 WHIPPLE ROAD UNION CITY, CA 94587 (415)429-8088 (800)523-8089 FAX(415)429-8089 4993

LAB:	race	
TURNAROUNI	: 3 days	
P.O. #:9	77 (

PAGE $\frac{2}{}$ of $\frac{4}{}$

CHAIN OF CUSTODY

											, ,			
PROJECT	r no.	C	517 62,4	E NAHE &	address auto Saler	>			£1			Ζ.	//	////
267 JZC	694	12	345	F. 14 th	Street		(1)	ا غ	729	?/;¥	15/3	// ب	<u>/</u> :	
SAMPLER	NAME,	ADDRES	S AND T	ETERRONE	NUMBER		TYPE OF	*	§/	\$/.	& /A	[3]		/// REMARKS
3034 18170	Lee	HU	يدلمن	ا <u>ٽ</u> 150 %	87 (415) 42	0.11088	CON-		7.3	7/5	/\$] /		₹/ ₂	//
ID NO.		TIME		VATER	SAMPLING LO		TAINER	1/3			\$/ ₂ ,	[4]		/ /
. טא ענ	DATE		5011					<u> </u>	/3	Z.			%	
STKI-A	12/4	1015	*		2.5		Bass	×	i.			\perp		
STKI-B		200	7		2.5		Brass	×	+			$oldsymbol{\perp}$		Composite into Isample
STKI-C	Ser.	1015	7		Z.5		13,2cus S	1	4	·		\perp		
STRI-D		1015			25		Bress	1	4					
STA-A	12/6		4		35		Bass	4	*		П	T		
51/2-B	1		1		35		Bress	Т	~			T		Composite into Isanote
1	1	1	I .		 			1	1	П	H	十	1	
STK2-C	196	1118	1	ļ	35		Brass	1	۴		$oxed{oxed}$	丄		
	1		1		3.5	-	Books	+	1					J
								П	Γ					
	<u> </u>	<u> </u>	<u> </u>	<u> </u>	e / Time	Dendinad b	w · (Sign	tur		Rali	ihoui	shad	l by	: (Signature) Date / Time Received by : (Signature)
Redinquish	of by	(5190	iatu ro /	12/7/2	419:00	Drog	200	ا	1	,	Ale	<u>ب</u> ل	γ	1794-3:05 \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \
Relinquish	ed by	: (Sign	aturs)	DAL	o / Timo	Received b	y : (Signa	tur	e)	Reli	nquis	hed	by	: (Signature) Date / Time Received by : (Signature)
	****								4					
Relinquish	ed by	: (Sign	natura)	Dat	e / Time	Received for [Signature]/			,		1541			Remarks
<u></u>						~وياس	- FELL	,	<u> </u>		<i>!</i>		-6	17 7 64

DATE: 127

TANK PROTECT ENGINEERING

2821 WHIPPLE ROAD UNION CITY, CA 94587 (415)429-8088 (800)523-8088 FAX(415)429-8089 4993

TURNAROUND: 3 days

P.O. #: 977

PAGE $\frac{2}{3}$ of $\frac{4}{3}$

CHAIN OF CUSTODY

PROJECT PROJECT SAMPLER 2821 WHIPP ID NO.	694 NAME.	ADDRES	345 T DNA 2	E 14	ADDRESS MST (415) 429-8088 SAMPLING LOCATION	(1) TYPE OF CON- TAINER	TANA PER						REMARKS
STK3-A	P/6	1047	イ		35	Bres	ᆺ	1 .					
51X3-B	14/	1040	イ		35	Bress	<u>بر</u>	7	L	\coprod			Composite into I sample
STK3-C	146	ilas	X		3%	Bress	ナ	*					
5713-D		11:11	7		35	Brass	*	¥					<u> </u>
	12/6		1 1		35	Boos	*	7			1		
ST K4-B		1033	j		35	Bross	7	~					Composite into Isample
STA4-C		1050	4		35	Bass	+	4					
STK4-D			7		3.5	Bress	*	*		П	T		
							Τ	Γ			T		
Relinquish Relinquish	leet	eus		1476	4 9:00 Dela	by: (\$igna	Atur	-1	R€1	P U inquis	hed) by	y: (Signature) Page / Time Received by: (Signature) 27443.05 y: (Signature) Date / Time Received by: (Signature)
Relinquish	ed by	(Sign	ature)	Dat	Received for (Signature)	Laboratory by		_	1	7/44			Remarks

DATE: 2 7494-

TANK PROTECT ENGINEERING

2821 WHIPPLE ROAD UNION CITY, CA 94587 (415)429-8088 (880)523-8088 FAX(415)429-8089

4993

LAB: Trace analysis labs

P.O. #: 977

PAGE $\frac{4}{1}$ of $\frac{4}{1}$

CHAIN OF CUSTODY

PROJECT		C	SII SII	TE HAME A	ADDRESS Sale	S		4/1/4/2	Æ,	<u> </u>] /:			/	
267 1200	694	7	745	F. 14	th Sheet		(1)	4	2.6	?/ ડ્	18	16.1	Ι,	/.5	6///
SAMPLER	NAKE,	ADDRES	S AND 1	ELEPHONE	H Sheet		TYPE	₹	3	5/		7/6	9/	?/	/// REMARKS
		zo. 44	uckir	75			OF	Ψá	Y /.	3/,4	٤/٤		\ <u>\</u>	/	
2821 WHIPP	LE ROAL	D, UNIC	ON CITY	, CA 945	87 (415) 4	29-8088	CON-	/	/ <u>`</u> ~	/٢,	/\$/		!	/ م	//
ID NO.	DATE	TIME	SOIL	VATER	SAMPLING I	OCATION	TAINER	Æ	1						
SIKS-A	12/4	1618	*		40		Bass	٨							
SKS-B	17/6	1616	~		4.0		Bruss	×	Y						
		1614	L L		4.0		Bess	Y	4				\perp		Composite into I sample
57K5D	17/6	1612	×		4,0	·	Bau	¥	¥				1		
51X-6-8	12/6	1623	4		25	•	Brass	×	~	Ц			1		
5140-B	12/6	1628	×		2.5		Bres	×	×						S Compaste in Isample
													\perp	1	
Rainquishe	المحالة		ature)	1276	449:00/	Recalived by	(Signa	C		Reji J)()	ished	1 ь _ў	$\dot{\gamma}$	(Signature) Pate / Time Received by : (Signature)
Relinquishe	d by:	(Sign	atura)	Date	/ Time	Received by	/ (Signa	tur	र्गाः	1170	nqui	shed	by	7	(Signature) Date / Time Received by : (Signature)
Relinquishe	d by:	(Sign	aturo)	Dat	e / Time	Received for L	aboratory by:		Τ	Pa	te /	Ti	10		Remarks
						(Signature)	- /		1/-	رکر ہ	اريدكم	3:	^ ~~	ماہ	, ~ l
						1	uccon		ĭ'	74	47		~	М.,	

DATE: 12 7 94

525 Del Rey Avenue, Suite E • Sunnyvale, CA 94086 • (408) 735-1550 • Fax (408) 735-1554

Tank Protect Engineering 2821 Whipple Road Union City, CA 94587 Attn: Jeff Farhoomand

Date:	5/22/95
Date Received:	5/16/95
Date Analyzed:	5/18/95
Project #:	Credit World 267051295
P.O. #:	1048
Sampled By:	Client

Certified Analytical Report

Soil Sample Analysis:

Sample ID	Sample	Sample	Lab#	DF	TPH-	Benzene	Toluene	Ethyl	Xylene
	Date	Time			Gas			Benzene	
VSP-1A 1.0-1.5	5/12/95	1032	B5158	1	ND	ND	ND	ND	ND
VSP-2B 2.0-2.5	5/12/95	1038	B5159	1	ND	ND	ND	ND	ND
VSP-3C 3.5-4.0	5/12/95	1042	B5160	1	ND	ND	ND	ND	ND
VSP-4D 1.0-1.5	5/12/95	1047	B5161	1	ND	ND	ND	ND	ND
VSP-5A 2.0-2.5	5/12/95	1051	B5162	1	ND	ND	ND	ND	ND
VSP 6B 3.5-4.0	5/12/95	1055	B5163	1	ND	ND	ND	ND	ND
VSP-7C 1.0-1.5	5/12/95	1101	B 5164	1	ND	ND	ND	ND	ND
VSP 8D 2.0-2.5	5/12/95	1105	B5165	1	ND	ND	ND	ND	ND
VSP 9A 3.5-4.0	5/12/95	1112	B5166	1	ND	ND	ND	ND	ND
VSP 10B 1.0-1.5	5/12/95	1117	B5167	1	ND	ND	ND	ND	ND

- 1. PQL=Dilution Factor x MDL
- 2. Analysis performed by Hull Development Labs, Inc. (CAELAP #1369)

Summary of Methods and Detection Limits:

	TPH-Gas	Benzene	Toluene	Ethylbenzene	Xylenes
EPA Method #	8015M	8020	8020	8020	8020
Units	mg/kg	mg/kg	mg/kg	mg/kg	mg/kg
MDL	1.0 mg/kg	0.005 mg/kg	0.005 mg/kg	0.005 mg/kg	0.005 mg/kg

Michael N. Golden, Lab Director

DF=Dilution Factor
MDL=Method Detection Limit

PQL=Practical Quantitation Limit ND=None Detected at or above PQL

525 Del Rey Avenue, Suite E • Sunnyvale, CA 94086 • (408) 735-1550 • Fax (408) 735-1554

Tank Protect Engineering 2821 Whipple Road Union City, CA 94587 Attn: Jeff Farhoomand

Date:	5/22/95
Date Received:	5/16/95
Date Analyzed:	5/18/95
Project #:	Credit World
	267051295
P.O. #:	1048
Sampled By:	Client

Certified Analytical Report

Water Sample Analysis:

Sample ID	Sample Date	Sample	Lab#	DF	TPH- Gas	Benzene	Toluene	Ethyl Benzene	Xylene
GB-1	5/12/95	855	B5168	1	ND	ND	ND	ND	ND

1. PQL=Dilution Factor x MDL

2. Analysis performed by Hull Development Labs, Inc. (CAELAP #1369)

Summary of Methods and Detection Limits:

	TPH-Gas	Benzene	Toluene	Ethylbenzene	Xylenes
EPA Method #	8015M	8020	8020	8020	8020
Units	μg/liter	μg/liter	μg/liter	μg/liter	μg/liter
MDL	50.0 μg/liter	0.5 µg/liter	0.5 μg/liter	0.5 µg/liter	0.5 μg/liter

Michael N. Golden, Lab Director

DF=Dilution Factor
MDL=Method Detection Limit

PQL=Practical Quantitation Limit ND=None Detected at or above PQL

QUALITY CONTROL RESULTS SUMMARY BTKX

QC sample No.: BLANK SPIKE & DUP Date analyzed: 05-18-95

Matrix: WATER

Units: ug/L Dilution factor: 1

COMPOUND	SA ug/L	SR ug/L		HS PR	MSD ug/L	MSD PR	RPD		IMITS ISORY) ; PR
BKNZKNE	20	0	18.	90	15	75	18	25	50-150
TOLUENE	20	0	20	100	20	100	0	25	50-150

MS = Spike sample

MSD = Spike sample duplicate

SR = Sample result

SA = Spike added

NC = Not calculated

** = Out of limits

 $RPD = 100 \times (MS-MSD)/((MS+MSD)/2)$

 $PR = 100 \times ((MS \text{ or } MSD) - SR)/SA$

FORM III VOL

QUALITY CONTROL RESULTS SUMMARY FOR GASOLINE ANALYSIS

GASOLINE

QC sample No.: BLANK SPIKE & DUP Date analyzed: 05-18-95

> Matrix: WATER

Units: ug/L Dilution factor:

COMPOUND	SĄ ug/L	 SR ug/L	MS ug/L	HS	MSD ug/L	¦ ¦MSD ¦PR	RPD	QC L (ADV RPD	IMITS ISORY) PR
GASOLINE	347	О	376	108	354	102	6	25	 50-150

MS = Spike sample

MSD = Spike sample duplicate

SR = Sample result
SA = Spike added

= Not calculated

= Out of limits

 $RPD = 100 \times (MS-MSD)/((MS+MSD)/2)$

 $PR = 100 \times ((MS \text{ or } MSD) - SR)/SA$

FORM III VOL

Engineering Environmental Menagement

TANK PROTECT ENGINEERING

2821 WHIPPLE ROAD UNION CITY, CA 94587 (415)429-8088 (800)523-8088 FAK(415)429-8089

LAB:	11	
TURNAROUND:	NORMAL	
P.O. #: 104	8_	

CHAIN OF CUSTODY

PAGE 1 OF 2

								_			7	7	7		
PROJECT	r no.		SIT	E NAME 4	address anto Soles				B	ନ/		/	/ /	////	
2670512	105						(1)	4	۲,6	%.	[R	[/	/ /.	/B/ / /	
		V Z	345 T	ELEPHONE	NUKRER		TYPE	A. A	<i>(§</i> /		تاريخ ماريخ	7/&		F/// REMARKS	ļ
SARPLEK	NAME,	LL	e anu i	etel uan	TURNEH		OF	4	\$/.\$	7/4		J/.	(S)]
2821 WHIPE	Lee Huckins 2821 WHIPPLE ROAD, UNION CITY, CA 94587 (415) 429-8088						CON-		(~) !!	\\$\\.	\$/.;	*/\$}	1/2	./ /	1
ID NO.	DATE		SOIL	VATER	SAMPLING LO	CATION	TAINER	Ź	Š	\$ 5		\\ \\			
1.3 1.5							77			$\widetilde{}$	十	十	f	85158	
1.0-1.5 VSP-1A	5/12	1032	X		1.0-1.5		Bras	4				上	\sqcup		-
Z0-2.5	5/12				2.0-2.5		Bruss	¥	Y					85159	
757-2B	E.	1038							+	1	十	T	T	BS160	
USP-3C	5/12	DHZ	X		3.5-4	3	Buss	4	<u> </u>	dash	+	+-	╂╾		
14-15	5/12	1047	X		1.0-1.5		Bruss	4	4			1_		8516	•
v57-5A			1 7		Z.0-2.5		Brass	4	4					85162	
		1021	 				1		—	H	+	十	†	B5163	
757.53 35-40	5/12	MSS	1⊀.		3.4 -4.0		Brass	4	٣	Ш			\bot		
ソジアープム	SIZ	1001	¥		1.0-1.5		Bryss	4	4] [B564	
10-15 VSP 80			 	 			8-44	1	ı	Ħ	7	1		B5165	
20-25	5/12	1102	7		Z.0 -Z:	<u> </u>	Bruss	+	7	┝╼┤		4-	+	1 185166	_
VSPAA	5/R	MZ	×		35-40	1	Brass	1+				L			
3.5-4.0 Relanquish	ed by	(Sign	nature)	Da	e / Time	Received b	y : (Signa	tur	•	Reli	nquie	shed	by	(Signature) Date / Time Recovered by : (Signature)	
deed?		,		13/15	9510:00	Tari	YY	08_	1	N	<u>ر ا</u>		YY.	116/99 1:34 2 11000	}-
Relinquish	ed by	(Sign	ature)		e / Time	Received b	y : (Signa	Eure	7	161 iz	nquis	hed	рà	: (Signature) Date / Time Received by : (Signature)	
				1_											
Relinquish	ed by :	(Sign	naturs)	Dal		Received for [Signature]	Laboratory by	r:		Da	te /	Tin	.0	Remarks	
	(Signature)						ı		1						

DATE: 5-15-95

TANK PROTECT ENGINEERING

2021 WHIPPLE ROAD UNION CITY, CA 94587 (415)429-8088 (800)523-8088 FAX(415)429-8089

LAB:	H411	
TURNA	ROUND:	NORMAL

P.O. #: 1048

CHAIN OF CUSTODY

PAGE Z OF Z

PROJECT 267 OS) SAMPLER 2821 WHIP	ر <u>صرا</u> PLE ROA	ADDRES JUNIO TIME	N CITY	E NAME (LUONE E 14 th ELEPHONE CA 945 VATER	ADDRESS AUG SA Street NUMBER 687 (415) 4 SAMPLING I	29-8088	(1) TYPE OF CON- TAINER	S. S						
								<u> </u>	/ 3	Ĥ	4	7	\mathcal{T}_{1}	B5167
59-10 B	3/12	1117	又		İ		Brass	Ľ	χ			1		B5167 B5168
GB-1	SIZ	৪১১		¥			zyome	Y	×					85168
	1	 						T			\top	T	T	
	-	<u> </u>		<u> </u>			 	╁╴	┢╌	H	十	十	十	
	1	<u> </u>	<u> </u>				<u> </u>	╀	-	Н	+	╫	╁	
		<u> </u>	<u> </u>					╀-	<u> </u>	Н	+	+	+-	
			Į.	ł				1_			·			·
	╁┈╌	1						T	Π					
	 	ļ <u> </u>				· · · · · · · · · · · · · · · · · · ·	 	十	t	Н	\top	╅	+	
	<u> </u>	ļ	ļ	ļ			 	╁	┞	Н	-	十	╁	
	1			l			1	Ļ	Ļ					: (Signature) Date / Time Repoided by A (Signature)
Relinquis	31. ±) `. `	ature)		7	<i>I</i> 1	y : (Signa	atur O	"		Dqui.	~	֓֓֓֓֓֓֓֓֓֓֓֓֓֓֓֓֓֓֓֓֓֓֓֓֓֓֓֓֓֓֓֓֓֓֓֓֓	ne 916/59 11:30 Jouda 1 100
Relinquis		: (Sign	ature)	Dai	het 10100	Received h	y : (Sign	atur	3	ReY1	nouls	shed	by	: (Signature) Date / Time Received by : (Signature)
Relinquis	ned by	: (Sign	aturo)	Da	to / Time	Fleceived for [Signature]	aboratory by	<i>y</i> :	1	Da	te /	Ti	<u></u>	Remarks

DATE: 5-15-95

LOG NUMBER:

5658

06/30/95 and 07/03/95 DATE SAMPLED:

DATE RECEIVED:

07/05/95

DATE EXTRACTED:

07/07/95

DATE ANALYZED:

07/08/95 and 07/11/95

DATE REPORTED:

07/12/95

CUSTOMER:

Tank Protect Engineering

REQUESTER:

Jeff Farhoomand

PROJECT:

No. 267-070395, Credit Auto World, 2345 East 14th Street

			Sample	Type:	Soil			
		V	/S-6	٧	/S-7	Composite of STK7(1-4)		
Method and Constituent:	<u>Units</u>	Concen- tration	Reporting Limit	Concen- tration	Reporting <u>Limit</u>	Concen- tration	Reporting <u>Limit</u>	
DHS Method:	• •							
Total Petroleum Hydro- carbons as Gasoline	ug/kg	ND	500	50,000	740	290,000	7,200	
Modified EPA Method 8020) for:	**						
Benzene	ug/kg	ND	5.0	370	15	560	140	
Toluene	ug/kg	ND	5.0	70	15	970	140	
Ethylbenzene	ug/kg	ND	5.0	990	15	3,000	140	
Xylenes	ug/kg	ND	15	3,300	44	11,000	430	

Concentrations reported as ND were not detected at or above the reporting limit.

Trace Analysis Laboratory, Inc.

LOG NUMBER: 5658
DATE SAMPLED: 07/03/95
DATE RECEIVED: 07/05/95
DATE EXTRACTED: 07/07/95
DATE ANALYZED: 07/11/95
DATE REPORTED: 07/12/95
PAGE: Two

....

Sample Type: Soil

	,		site of (8(1-4)		site of (9(1-4)	Method Blank		
Method and Constituent:	<u>Units</u>	Concen- tration	Reporting Limit	_	Reporting Limit	Concen- tration	Reporting Limit	
DHS Method:								
Total Petroleum Hydro- carbons as Gasoline	ug/kg	49,000	3,500	78,000	500	ND	500	
Modified EPA Method 8020) for:				,			
Benzene	ug/kg	100	70	52	5.0	ND	5.0	
Toluene	ug/kg	100	70	36	5.0	ND	5.0	
Ethylbenzene	ug/kg	550	70	520	5.0	ND	5.0	
Xylenes	ug/kg	1,800	210	1,600	15	ND	15	

OC Summary:

% Recovery: 111, 104 % RPD: 1.8, 5.4

Concentrations reported as ND were not detected at or above the reporting limit.

Louis W. DuPuis

Quality Assurance/Quality Control Manager

TANK PROTECT ENGINEERING

2821 WHIPPLE ROAD UNION CITY, CA 94587 (415)429-8088 (800)523-8089 FAX(415)429-8089

LAB:	TAL		
TURNA	ROUND:	5day	
P.O.	#: <u>1077</u>		

CHAIN OF CUSTODY

PAGE _) OF ______

PROJECT NO. SITE NAME & ADDRESS Credit Audic world Z345 E 1444 SAMPLER NAME, ADDRESS AND TELEPHONE NUMBER Lee Huckins 2821 WHIPPLE ROAD, UNION CITY, CA 94587 (415) 429-80 ID NO. DATE TIME SOIL VATER SAMPLING LOCATION	TYPE OF CONTAINER TAINER TO THE	
STX7-1 7/3 1611 X 3.0	Brass XX	
57107-2 7/3 1610 4 30	XX Composite into 1 xample	
51X7-3 7/3 1608 L 3.0	74	
57174 7/3 1606 4 3.6	XX	
5118-1 7/3 Kg11 X 20	4×	
5718-2 7/3 1612 1 Z.6	x x	
508-3 7/3 W4 X ZO	Composite into I sample	·
51084 7/3 1616 L ZO	X M	·.
Relinquished by: (Signature) 10 Date / Time Rece	d by : (Signature) Relinquished by : (Signature) Date / Time Received by : (Signature)	gnature)
Relinquished by : (Signature) Date / Time Rece	1 by : (Signature) Relinquished by : (Signature) Date / Time Received by : (Si	gnaturo)
(Sign	or Laboratory by: Date / Time Remarks 15/95 9!5/or	

DATE	٠	
DWIT	٠	

TANK PROTECT ENGINEERING

2821 WHIPPLE ROAD UNION CITY, CA 94587 (415)429-8088 (800)523-8088 FAX(415)429-8089

LAB:	TAL		
TURNA	AROUND:	5 day	

CHAIN OF CUSTODY

PAGE Z OF Z

P.O. #: 1077

1	0395 NAME. LE ROA	ADDRES	SYS AND THE	E 14th Telephone	87 (415) 42	29-8088 OCATION	(1) TYPE OF CON- TAINER	TOWN OF THE PERSON						//		RE	MARKS
3729-1	7/3	1649	X		2.0		Brass	*	1 1								
01X9-Z	7/3	1621	4		Zo		Brass	*	7.					Com	posite	into 1	sample.
5169-3		1628			70		BTUSS	1	*						·		
STK94		1625			20		Brass	~	4								
	4/30	1	4		21'		Bress	*	4								
·VS-7		1325			14		Brass	1	*			Τ					
										·							
									Γ		П	T					
							1	T				T				·	
Relinquish	uch	, , ,		7/5/93	19:51 AM	_ ~			土					: (Signature)		/ Time	Received by : (Signature)
Rolinquish	ed by :	(Sign	ature)	Dat	e / Time	Received b	y : (Signe	ature	<u>" </u>	Reli	nquis	hed	by :	(Signature)	Date	/ Time	Received by : (Signature)
Relinquish	ed by :	(Sign	atura)	Dat	e / Time	Received for [Signature]		<i>ī</i> : 		/5-/5) to /	Tine 1!57		Remarks	<u> </u>		

DATE		
DELL	•	



PRIORITY ENVIRONMENTAL LABS

Precision Environmental Analytical Laboratory

July 10, 1995

PEL # 9507004

TANK PROTECT ENGINEERING, INC.

Attn: Lee Huckins

Re: Eight soil samples for Gasoline/BTEX and Diesel analyses.

Project name: Credit World Auto

Project location: 2345 East 14th St.

Project number: 267070595

Date sampled: Jul 05, 1995

Date extracted: Jul 06-08, 1995

Date submitted: Jul 06, 1995 Date analyzed: Jul 06-08, 1995

RESULTS:

SAMPLE	Gasoline	Diesel	Benzene	Toluen	Total Xylene	
I.D.	(mg/Kg)	(mg/Kg)	(ug/Kg)	(ug/Kg)	Benzene (ug/Kg)	(ug/Kg)
STK10-1,2,3,	4* 22		12	12	32	89
STK11-1,2,3,		N.D.	N.D.	N.D.	N.D.	N.D.
VS-8	33		36	22	66	99
VS-9	42		60	36	89	120
VS-10	130		180	85	250	370
VS-11	81		73	86	160	210
VS-12	N.D.		N.D.	N.D.	N.D.	N.D.
VS-13	75		48	40	78	180
Blank	N.D.	N.D.	N.D.	N.D.	N.D.	N.D.
Spiked Recovery	94.6%	88.1%	81.2%	85.8%	80.1%	98.3%
Detection limit	1.0	1.0	5.0	5.0	5.0	5.0
Method of Analysis	5030 / 8015	3550 / 8015	8020	8020	8020	8020

*Composited soil samples.

David Duong Laboratory Director

1764 Houret Court Milpitas, CA. 95035

Tel: 408-946-9636

Fax: 408-946-9663

TANK PROTECT

Environmental Management

TANK PROTECT ENGINEERING

2821 WHIPPLE ROAD UNION CITY, CA 94587 (415)429-8088 (80D)523-8088 FAX(415)429-8089

LAB:	Priority	Enu

TURNAROUND: NORMAL

P.O. #: 1078

CHAIN OF CUSTODY

PAGE	OF	

267 07 SAMPLE	R NAME, La PPLE ROA	ADDRES Se H	S AND T WCKIT W CITY	TELEPHONE 75 CA 945	Address Number Number 87 (415) 429-8 Sampling Loca		(1) TYPE OF CON- TAINER	THE SERVICE SE						REMARKS
vs-8	7/5	1550	Y		16		Bruss	×	¥					
VS-9	7/5	Nool,	¥		15		Bruss	-	¥					
V5-10	7/5	1119	¥		15		Brass	8	4					
V5-11	-7 /	1611	7		量 16		Brass	人	4					
V5-12	7/5	1549	¥		21		Brass	DC	¥					
V5-13	7/5	Vaz B	×		# 16		13/455	~	¥					
	1	·												
Relinquished by: (Signature) Date / Time Received by:									/	M	<u> </u>	_ 	10ms 7/6/98/2:44	
	Relinquished by : (Signature) Date / Time Received by						y: (Signa	ture	"					: (Signature) / Date / Time Received by : (Signature)
Relinquis	Relinquished by : (Signature) Date / Time Received for Lat [Signature]						aboratory by	:	T	Da	te /	Tim		Remarks

|--|

TANK PROJECT ENGINEERING

Environmental Management

TANK PROTECT ENGINEERING

2821 WHIPPLE ROAD UNION CITY. CA 94587 (415)429-8088 (800)523-8088 FAX(415)429-8089

LAB:	Priorite	
	3	1

TURNAROUND: SIOR MAC

P.O. #: 1078

CHAIN OF CUSTODY

PAGE 7 OF Z

		NAME. LE ROA	Z. ADDRES	s and the fuck is an elity, when the sum of	ELEPHONE	AUTO SO LES AUTO SO LES HUNBER 87 (415) 429-8 SAMPLING LOCA		(1) TYPE OF CON- TAINER	ATTEN TO									RI	ЕМА	RKS	;			
	STK10-1	%	Поі	¥		3.6			ے	₹				I	\overline{Z}									
	STK 10 - 2	7/5	1459	X		7.0	1		<u> </u>	4			Ц			-Car	nposi†	e int	<u>. /</u>	sam	ple			
	STK 10-3	か	15	7		3.6			人	4	1													
	STK10-4	7/5	188	7		3.6			Ž	<u>~</u>					_)									
1	シ ガとハー!	7/5	145	4		3.6			¥	4	*		Ш)								
	合とリーム	7/5	1447	7		3.6			4	4	4	T				50	ems	xite:	inb	150	amol	e_		
	STK#-3	7/5	1449	4		3.0			Ž.	~	×			T			· • •							
	STEN-4	-,	KAI	4		3.6			4	×	4			T			,							•
										1				T		`								
	Relinquish Relinquish	uck	ma		7/1/9	51800	ceived by			(W	<u>/ </u>	10	W	<i>y</i>		2/6/9	Time	y			: (Signa		
	verridaten	. us us	(mr3m		K. A	21/4:45	there	Lam	ブ	 				`		- ,	/ = = -	. [-		-	
	Relinquished by : (Signature) Date / Time Received for La [Signature]						Laboratory by:			Date / Time Remarks									:					



PRIORITY ENVIRONMENTAL LABS

Precision Environmental Analytical Laboratory

July 17, 1995

PEL # 9507022

TANK PROTECT ENGINEERING, INC.

Attn: Lee Huckins

Re: Eight soil samples for Gasoline/BTEX analysis.

Project name: Credit World

Project location: 2345 E. 14th Oakland

Project number: 267

Date sampled: Jul 12, 1995
Date extracted: Jul 13-15, 1995

Date submitted: Jul 13, 1995 Date analyzed: Jul 13-15, 1995

RESULTS:

SAMPLE I.D.	Gasoline	Benzene	Toluene	Ethyl Benzene	Total Xylene
1.2.	(mg/Kg)	(ug/Kg)	(ug/Kg)	(ug/Kg)	(ug/Kg)
VSP 1A	N.D.	N.D.	N.D.	N.D.	N.D.
VSP 2B	4.0	N.D.	17	26	99
VSP 3C	N.D.	N.D.	N.D.	N.D.	N.D.
VSP 4D	N.D.	N.D.	N.D.	N.D.	N.D.
VSP 5A	N.D.	N.D.	N.D.	N.D.	N.D.
VSP 6B	N.D.	N.D.	N.D.	N.D.	N.D.
VSP 7C	N.D.	N.D.	N.D.	N.D.	N.D.
VSP 8D	N.D.	N.D.	N.D.	N.D.	N.D.
Blank	N.D.	N.D.	N.D.	N.D.	N.D.
Spiked Recovery	87.1%	87.4%	94.8%	104.9%	96.7%
Detection limit	1.0	5.0	5.0	5.0	5.0
Method of Analysis	5030 / 8015	8020	8020	8020	8020

David Duong Laboratory Director

1764 Houret Court Milpitas, CA. 95035

Tel: 408-946-9636 Fa

Fax: 408-946-9663

TANK PROTECT

Environmental Management

TANK PROTECT ENGINEERING

2821 WHIPPLE ROAD UNION CITY, CA 94587 (415)429-8088 (800)523-8088 FAX(415)429-8089

LAB:	PRH	MISSE		
TIRNA	ROUND:	FORWARD	N	orno

P.O. #: 1093

7207 / 07 /

CHAIN OF CUSTODY

												.,-		
PROJECT NO. SITE NAME & ADDRESS CREDIT WORLD 2345 E. 14th OAKLAND SAMPLER NAME. ADDRESS AND TELEPHONE NUMBER MARK VARNEY / LEE HUCKINS 2821 WHIPPLE ROAD, UNION CITY, CA 94587 (415) 429-8088						(1) TYPE OF CON- TAINER	A PART OF THE PART							/· /
ID NO.		TIME		VATER	SAMPLING LOCATION	IMINER	/\$	/\$	3/5 5		\\\{\bar{\}_{2}^{\bar{\}_{2}}	'\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\	<i>\$</i>	/
VSP IA	7/12	11-12	X		1.0	BRASS	X	X						
VSP 2B	- 	11:15	.,		20'	11	X	X						
VSP3C	η	11:17	Х		3.5'	**	X	X						
VSP4A	1)	11:19	X		1.0'	14	X	X						· · · · · · · · · · · · · · · · · · ·
VSP5B	11	11:21	Х		2.0	"	X	X						
VSP68		11:23	Χ		3.5 '	/-	N	X						
VSP7A		11:25	Х		1.0	11	X	X						
VSP8		וניגיו	×		z.0'	"	X	X						
									L			/	1	
Muly	Relinquished by (Signature) Date / Time Received by : (Signature) Relinquished by : (Signature) Date / Time Received by : (Signature) Property (Signature) Relinquished by : (Signature) Relinquished by : (Signature) Date / Time Received by : (Signature) Relinquished by : (Signature) Date / Time Received by : (Signature) Relinquished by : (Signature)													
Rolinquish	Relinquished by : (Signature) Date / Time Received for Labor [Signature]								D	ato	/ T	ino		Remarks

DATE:		
-------	--	--

LOG NUMBER: DATE SAMPLED: 5726

DATE RECEIVED:

07/28/95 07/31/95

DATE EXTRACTED:

08/03/95

DATE ANALYZED:

08/05/95 and 08/06/95

DATE REPORTED:

08/07/95

CUSTOMER:

Tank Protect Engineering

REQUESTER:

Jeff Farhoomand

PROJECT:

No. 267-072895, Credit World Auto Sales, 2345 East 14th Street

	····		Sample	Type:	Soil			
		v	S-14	<u>y</u>	S-15	VS-16		
Method and <u>Constituent</u> :	<u>Units</u>	Concen- tration	Reporting Limit	Concen- tration	Reporting <u>Limit</u>	Concen- <u>tration</u>	Reporting <u>Limit</u>	
DHS Method:								
Total Petroleum Hydro- carbons as Gasoline	ug/kg	2,800	500	61,000	1,800	38,000	1,400	
Modified EPA Method 8020	for:							
Benzene	ug/kg	300	5.0	470	37	400	28	
Toluene	ug/kg	16	5.0	42	37	43	28	
Ethylbenzene	ug/kg	94	5.0	1,200	37	420	28	
Xylenes	ug/kg	140	15	730	110	590	87	
							site of	
Method and Constituent:	<u>Units</u>	Concen- tration	/S-17 Reporting <u>Limit</u>		S-18 Reporting <u>Limit</u>		(2(A-D) Reporting Limit	
DHS Method:								
Total Petroleum Hydro- carbons as Gasoline	ug/kg	14,000	500	590,000	73,000	87,000	3,600	
Modified EPA Method 8020	for:							
Benzene	ug/kg	120	5.0	3,100	1,500	260	72	
Toluene	ug/kg	18	5.0	2,400	1,500	140	72	
Ethylbenzene	ug/kg	150	5.0	10,000	1,500	1,600	72	
Xylenes	ug/kg	110	15	52,000	4,400	3,000	220	

Trace Analysis Laboratory, Inc.

LOG NUMBER: 5726
DATE SAMPLED: 07/28/95
DATE RECEIVED: 07/31/95
DATE EXTRACTED: 08/03/95
DATE ANALYZED: 08/05/95
DATE REPORTED: 08/07/95
PAGE: Two

Sample	Tyne:	Soi]
Janio i C	17001	

		Compo STK1	Method Blank			
Method and <u>Constituent</u> :	<u>Units</u>	Concen- tration	Reporting <u>Limit</u>	Concen- tration	Reporting <u>Limit</u>	
DHS Method:						
Total Petroleum Hydro- carbons as Gasoline	ug/kg	58,000	3,500	ND	500	
Modified EPA Method 8020	for:					
Benzene	ug/kg	210	70	ND	5.0	
Toluene	ug/kg	97	70	ND	5.0	
Ethylbenzene	ug/kg	630	70	ND	5.0	
Xylenes	ug/kg	2,300	210	ND	15	

OC Summary:

% Recovery: 71

% RPD: 4.0

Concentrations reported as ND were not detected at or above the reporting limit.

Louis W. DuPuis

Quality Assurance/Quality Control Manager

Environmental Management

TANK PROTECT ENGINEERING

2821 WHIPPLE ROAD UNION CITY, CA 94587 (415)429-8088 (800)523-8088 FAX(415)429-8089

LAB:	TAL			
TURNA	ROUND:	57	Dog	

P.O. #: 102

CHAIN OF CUSTODY

PAGE _/ OF _Z_

										,		7	,	, , , , ,		
PROJECT ZG7 Q72 SAMPLER	NO.	C	الم. الحري الم. الحري	e name a	AUTO Siles		(1)	18 A	E.	3/s/			/. /.			
261012	33 32	2 NDD000	340 1	TT FORM	MINGRED		TYPE	3	8/	6/.	~/.¥/	[& [.	V,	' / /	DEN	(ARKS
SARPLEK	MARK,	چههاسم ا	ני עוקא כ מ'י'ג	STEL HOUR	HORDAN.		OF	44	?/ <u>\</u>	*/**/	/\$/å	Ĭ/\`	/	//	I/LII	MACO
2821 UH1PP	NE ROM	e Hi	uckin	CA 945	87 (415) 42	9-8088	CON-	1/	('			[3]	/ &/	′ /		
ID NO.		TIME		WATER	SAMPLING L	OCATION	TAINER	/2	\$		8	/8/		<u>/</u>	<u>, ,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,</u>	
vs-14	7/28	1400)9'		Brace	*	×					···		
	7/28	1418			151			K	1		\perp	Ц	_			
V5-16	1/28	<i>(</i> 458			16			7	7	_	1	Ц				
VS-17	7)28	1635			19		L /	X	7	_	1		_			
V5-18	7/28	1650			<i>1</i> 4 (X	X							
V5 10				<u> </u>				4							_	
	 	 	╁┈╴				1	Ť		T	1					
		_						1		1	1	П				
	 				<u> </u>			\dagger		\top	1				. <u></u>	
	<u> </u>	,		<u> </u>	te / Time	Received h	y : (Sign	atur	5	Relin	quis	ad b	7	(Signature) Dat	o / Timo	Received by : (Signature)
Relinquish			eemaj	-17.1	9514:30	•			1						1	
Relinquish	ed by	(Sign	ature)	7/3/ Dai	e / Time	Received b	y ; (Sign	atur	2	Relinquished by : (Signature) Date / Time Received by : (Signature)				Received by : (Signature)		
				1					1							
Relinquish	ed by	(Sign	ature)	Da		Received for (Signature)			- 7		5 4		P	Romarks		

DATE	:	
------	---	--

Environmental Management

TANK PROTECT ENGINEERING

2821 WHIPPLE ROAD UNION CITY, CA 94587 (415)429-8088 (800)523-8088 FAX(415)429-8089

LAB:	TRACE
	-

TURNAROUND: 5 doc

DATE:

P.O. #: //OZ

CHAIN OF CUSTODY

PAGE <u>Z</u> OF <u>2</u>

	PLE ROA	Z ADDRESS	365 S AND T N CITY,	ELEPEONE CA 945	ADDRESS AUD SCHEL MUNBER 87 (415) 42 SAMPLING D	9-8088 OCATION	TYPE OF CON- TAINER	TAMPA CAMPA							REMARKS
STK1Z-A	7/28	Flos	X		<i>z</i> .o		Brass	¥	1					\sum	·
5TKBB	-				Z.0		1	X	X	Ц				1	Composite into I sample
STURC	1_	1705	4		2.6			X	-	Ц		_			
SKIZ-D		120	7		Z.0		1.\	X	 			L		/	
574.13-A		720	4		3,0			X.	K	Ш	4	1	 		
STK13-B		7720	4		3.8			K	X			L	<u> </u>		Composite into I sample
311113e		1720	X_		3,0			K	K	Ц		╀-	<u> </u>		
STUBD	1	1 172	X		30		1	K	X				_		<u> </u>
Relinquish	elinquished by : (Signature) Date / Time Received by : (Signature) Pate / Time Received by : (Signature) elinquished by : (Signature) Date / Time Received for Laboratory by: [Signature]						B) 1	Roli		ned Time	by	(Sig			

TANK PROTECT

Environmental Management

TANK PROTECT ENGINEERING

2821 WHIPPLE ROAD UNION CITY, CA 94587 (415)429-8088 (80D)523-8088 FAX(415)429-8089

LAB:	Priority	Enu

TURNAROUND: NORMAL

P.O. #: 1078

CHAIN OF CUSTODY

PAGE	OF	

267 07 SAMPLE	R NAME, La PPLE ROA	ADDRES Se H	S AND T WCKIT W CITY	TELEPHONE 75 CA 945	ADDRESS NUMO Sales NUMBER 87 (415) 429-1 SAMPLING LOCA		(1) TYPE OF CON- TAINER	THE SERVICE SE						REMARKS
vs-8	7/5	1550	Y		16		Bruss	×	Υ.					
VS-9	7/5	Nool,	¥		15		Bruss	-	7					
V5-10	7/5	1119	¥		15		Brass	8	4	Ц				
V5-11	-7 /	1611	٦		量16		Brass	人	4					
V5-12	7/5	1549	¥		21		Brass	DC	¥					
V5-13	7/5	Vaz B	×		# 16		13/455	~	¥					
	1										\Box	\overline{I}		
	Relinquished by: (Signature) Date / Time Received by:								/	M	1	_ 	10ms 7/6/98/2:44	
	Relinquished by: (Signature) Date Time Received by: (Signature)						ture			/			: (Signature) / Date / Time Received by : (Signature)	
Relinquis	hed by	(Sign	ture)		o / Timo Rec	nature)	aboratory by	:	T	Da	to /	Tim		Remarks

|--|

TANK PROJECT ENGINEERING

Environmental Management

TANK PROTECT ENGINEERING

2821 WHIPPLE ROAD UNION CITY. CA 94587 (415)429-8088 (800)523-8088 FAX(415)429-8089

LAB:	Priorite	
	3	1

TURNAROUND: SIOR MAC

P.O. #: 1078

CHAIN OF CUSTODY

PAGE 7 OF Z

		NAME. LE ROA	Z. ADDRES	S AND T fuck in m city,	ELEPHONE	AUTO Soles AUTO Soles NUMBER 87 (415) 429-8 SAMPLING LOCA		(1) TYPE OF CON- TAINER	TOTAL REPLY									R	(EM)	ARK	ເຮ		
	STK10-1	7/5	Поі	メ		3.6			ے	₹				I	\overline{Z}						-		
	STK 10 - 2	7/5	1459	×		7.0			y	4			Ц			<u>-Ca</u>	nposi ¹	e in	61	59	mple		 ,
	STK 10-3	ント	15	7		3.6			人	4			Ц									·	
	STK10-4	7/5	188	J.		3.6			3	<u>~</u>					_)								 ****
1	シ ガとハー!	7/5	145	4		3.6			¥	4	*)				_			
	合とリーム	7/5	1447	7		3.6			4	4	4	T				50	emp	xite	int	<u>, /</u> :	Some	ole_	
	STK#-3	7/5	1449	*		3.0			ų.	~	×			T		(.	Ψ.						
	STEN-4	- ,	KAI	4		3.6			4	×	*		П	T			,						 •,
										1				T		`							
	Relinquish Relinquish	uck	ma		7/1/9	51800		; (Signa		(U	<u>/ </u>	10	W	1		2/4/9	Time Time	14			y : (Si	
	verridaten	-Charl	Lim	ブ	 				`		,												
	Relinquished by : (Signature) Date / Time Received for							aboratory by:	~		Dat	s / I	ins	R	enark	3						:	

TANK PROTECT

Environmental Management

TANK PROTECT ENGINEERING

2821 WHIPPLE ROAD UNION CITY, CA 94587 (415)429-8088 (800)523-8088 FAX(415)429-8089

LAB:	PRH	MISSE		
TIRNA	ROUND:	FORWARD	N	orno

P.O. #: 1093

7207 / 07 /

CHAIN OF CUSTODY

												.,		
PROJECT 26 SAMPLER MAI	NAME.	ADDRES VAR	345 5 AND 1 NEV	E. 14 ELEPHONE LET	ADDRESS ORUD H OAKUAND NUMBER E HUCKINS 87 (415) 429-8088	CON-	TO THE PARTY							
	DATE		SOIL	VATER	SAMPLING LOCATION	TAINER	15	\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\					\$ /	
VSP IA	7/12	11:12	X		1.0	BRASS	X	X						
VSP ZB	ħ	mas.	X		20'	"	X	X.						·
VSP3C	ŋ	1 1:17	Х		3.5'	<i>"</i>	Ŋ	X.						·
VSP4A	Đ	H: IS	Х		1.0,	"	X	Х	L					
VSP5B	11	11:21	Χ		2.0	,,	X	Δ						
VSP68	1/	11:23	X	<u> </u>	3.5 \	"	$[\lambda]$	X	_	<u> </u>				
VSP7A	4	11:25	X		1.0	11	X	X	_	_				
VSP8	ij	וניגרן	Х		2.01	"	ĮΧ	X	$oxed{}$					
						101							<i>)</i> (4	: (Signature) / Date / Time Received by : (Signature)
Relipquish	P	Sign	ature)	2/12/	9818:00 74A	UHLA	11_	-1	1	1	/ (1,0	anne 7/13/95(3:00
Relinquishe	d by	(Sign	ature)	7 Dat	e Time puReceived !	Sign	ature	•7	Rel	ingli	ish	eal	oy :	: (Signature) / Date / Time Received by : (Signature)
Rolinquishe	ed by	(Sign	ature)		Time Received for (Signature)	Laboratory by	<i>y</i> :		D	ato	/ I	ino		Remarks

DATE:	·	
-------	---	--

Environmental Management

TANK PROTECT ENGINEERING

2821 WHIPPLE ROAD UNION CITY, CA 94587 (415)429-8088 (800)523-8088 FAX(415)429-8089

LAB:	TAL			
TURNA	ROUND:	57	Dog	

P.O. #: 102

CHAIN OF CUSTODY

PAGE _/ OF _Z_

										,		7	,	, , , , ,		
PROJECT ZG7 Q72 SAMPLER	NO.	C	الم. الحري الم. الحري	e name a	AUTO Siles		(1)	18 A	E.	3/s/			/. /.			
261012	33 32	2 NDD000	340 1	TT FORM	MINGRED		TYPE	3	8/	6/.	~/.¥/	[& [.	V,	' / /	DEN	(ARKS
SARPLEK	MARK,	چههاسم ا	ני עוקא כ מ'י'ג	STEL HOUR	HORDAN.		OF	44	?/ <u>\</u>	*/**/	/\$/å	Ĭ/\`	/	//	I/LII	MACO
2821 UH1PP	NE ROM	e Hi	uckin	CA 945	87 (415) 42	9-8088	CON-	1/	('			[3]	/ &/	′ /		
ID NO.		TIME		WATER	SAMPLING L	OCATION	TAINER	/2	\$		8	/8/		<u>/</u>	<u>, ,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,</u>	
vs-14	7/28	1400)9'		Brace	*	×					···		
	7/28	1418			151			K	1		\perp	Ц	_			
V5-16	1/28	<i>(</i> 458			16			7	7	_	1	Ц				
VS-17	7)28	1635			19		L /	X	7	-	1		_			
V5-18	7/28	1650			<i>1</i> 4 (X	X							
V5 10				<u> </u>				4							_	
	 	 	╁┈╴				1	Ť		T	1					
		_						1		1	1	П				
	 				<u> </u>			\dagger		\top	1				. <u></u>	
	<u> </u>	,		<u> </u>	te / Time	Received h	y : (Sign	atur	5	Relin	quis	ad b	7	(Signature) Dat	o / Timo	Received by : (Signature)
Relinquish			eemaj	-17.1	9514:30	•			1						1	
RMinquish	Minquished by : (Signature) Date / Time Received							atur	2	olin	quisb	ed by	7 :	(Signature) Dat	e / Time	Received by : (Signature)
				1					1							
								Date / Time Remarks								

DATE	:	
------	---	--

Environmental Management

TANK PROTECT ENGINEERING

2821 WHIPPLE ROAD UNION CITY, CA 94587 (415)429-8088 (800)523-8088 FAX(415)429-8089

LAB:	TRACE
	-

TURNAROUND: 5 doc

DATE:

P.O. #: //OZ

CHAIN OF CUSTODY

PAGE <u>Z</u> OF <u>2</u>

	PLE ROA	Z ADDRESS	365 S AND T N CITY,	ELEPEONE CA 945	ADDRESS AUD SCHEL MUNBER 87 (415) 42 SAMPLING D	9-8088 OCATION	TYPE OF CON- TAINER	TAMPA CAMPA							REMARKS
STK1Z-A	7/28	Flos	X		<i>z</i> .o		Brass	¥	1					\sum	·
5TKBB	-				Z.0		1	X	X	Ц				1	Composite into I sample
STURC	1_	1705	4		2.6			X	-	Ц		_			
SKIZ-D		120	7		Z.0		1.\	X	 			L		/	
574.13-A		720	4		3,0			X.	K	Ш	4	1	 		
STK13-B		7720	4		3.8			K	X			L	<u> </u>		Composite into I sample
311113e		1720	X_		3,0			K	K	Ц		╀-	<u> </u>		
STUBD	1	1 172	X		30		1	K	X				_		<u> </u>
Relinquish Relinquish	er Ru	PA : (Sign	ature)	7/3i) Dat	95 4:30pm	Received Received Received for [Signature]	by : (Sign	atur	B) 1	Roli		ned Time	by	(Sig	



Precision Environmental Analytical Laboratory

October 06, 1995

PEL # 9510011

TANK PROTECT ENGINEERING

Attn: Lee Huckins

Re: Eleven soil samples for Gasoline/BTEX analysis.

Project name: Credit World Auto Sales Project location: 2345 E. 14th St.

Project number: 267100395

Date sampled: Oct 03, 1995

Date extracted: Oct 04-05, 1995

Date submitted: Oct 04, 1995 Date analyzed: Oct 04-05, 1995

RESULTS:

SAMPLE I.D.	Gasoline	Benzene	Toluene	Ethyl Benzene	_
1.0.	(mg/Kg)	(ug/Kg)	(ug/Kg)	(ug/Kg)	(ug/Kg)
VSP 11A	N.D.	N.D.	N.D.	N.D.	N.D.
VSP 12B	N.D.	N.D.	N.D.	N.D.	N.D.
VSP 13C	N.D.	N.D.	N.D.	N.D.	N.D.
VSP 14D	N.D.	N.D.	N.D.	N.D.	N.D.
VSP 15A	N.D.	N.D.	N.D.	N.D.	N.D.
VSP 16B	N.D.	N.D.	N.D.	N.D.	N.D.
VSP 17C	N.D.	N.D.	N.D.	N.D.	N.D.
VSP 18D	N.D.	N.D.	N.D.	N.D.	N.D.
VSP 19A	N.D.	N.D.	N.D.	N.D.	N.D.
VSP 20B	N.D.	N.D.	N.D.	N.D.	N.D.
VSP 21C	N.D.	N.D.	N.D.	N.D.	N.D.
Blank	N.D.	N.D.	N.D.	N.D.	N.D.
Spiked Recovery	85.1%	92.2%	94.9%	107.4%	109.9%
Detection limit	1.0	5.0	5.0	5.0	5.0
Method of Analysis	5030 / 8015	8020	8020	8020	8020

David Duong Laboratory Director

1764 Houret Court Milpitas, CA, 95035

Tel: 408-946-9636

Fax: 408-946-9663

Environmental Management

TANK PROTECT ENGINEERING

2821 WHIPPLE ROAD UNION CITY, CA 94587 (415)429-8088 (800)523-8088 FAX(415)429-8089

LAB: Priority	·
TURNAROUND:	
P.O. #: //25	••

CHAIN OF CUSTODY

PAGE _) OF ____

PROJECT 267 > 100 SAMPLER 2821 WHIPP ID NO.	895 NAME. Lee PLE ROA	ADDRES - UC	SAND T Livys W CITY,	RIEPHONE	ADDRESS TO COLLEGE NUMBER 87 (415) 429-8088 SAMPLING LOCATION	(1) TYPE OF CON- TAINER	1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1									EL :	#	9510011 26396		/ ₂
vsp 14A	10/3	Œ	K		1.5-2.0	Bess	×	¥			\bot						•			
VSP 12B		Par			20-25	Bruss	*	¥			_	4							.	
	10/3	1044	*		30-35	Brass	*	*	Ц		_	_								
	10/3	1049	1		1.5 - ZG	Beass	۲	*	Ц		_	4					·			
	10/3		1		Z.a - Z. 5	Base	*	4		Ц	_	_								
KP16B	10/3	,CSt	*		3.0-35	Boss	1	4				_	_				<u> </u>			
USPITC	19/3	1053	+		15-2.0	Brass	+	4				_					<u>-</u> -		 	
USPAS D		1057	4		Z.0-Z.5	Brus	+	1			_	_			·		<u>.</u>			
USP 19A	10/3	8W	X		3.0-3.5	BUSI	+	*		Ш				(Cianatura)	Date	/ Time	Rece	oived by : (Signatur	e)
Relinquished by: (Signature) Deta Time Received by Chapter 1415					Lin		1	Relinquished by : (Signature) Date / Time Received by : (Signature) Relinquished by : (Signature) Date / Time Received by : (Signature)												
Relinquished by : (Signature) Date / Time Received by						oy: (Signa NH しん		- 1	KO11	nqu	sne	NU 01	y :	(Stylerate)					-	
Relinquish	ed by	(Sign	aturo)	Dal XX	Peczyed for [Signature]	Laboratory by	ŗ.	T	De	ate .	Ti	10		Remarks			-			

DA7	TE:	
~	. — .	

LE C #	9510011	- ₹/ <u>2</u>
--------	---------	-------------------

Engineering Engineering Environmental Management

TANK PROTECT ENGINEERING

2821 WHIPPLE ROAD UNION CITY, CA 94587 (415)429-8088 (800)523-8088 FAX(415)429-8089

LAB:	Priority	
TURNA	ROUND:	
P.O.	#:1125	٠,

CHAIN OF CUSTODY

PAGE C OF C

PROJECT JOS SAMPIER 2821 WHIPPID NO.	D395 HAKE. PLE ROA	ADDRES	343 B S AND T ACKINS M CITY,	KLEPHONI	Andress Andress (4) Sales (4) Miniber 687 (415) 429-8088 SAMPLING LOCATION	(1) TYPE OF CON- TAINER	18 A						REMARKS	
VSP ZOB	193	1102	X	66	1.5-20	Bais	1	1						
USPZIC	193	1	\nearrow	Ø	20-25	Brass	×	¥			\downarrow			
							}_	-	-	\sqcup		+		
	 	-					╀	\vdash	╀	H	-	+		
		 	· -			 	十	-	╁	H		+	·	
		 	┼	 			十	t	t	H	\dashv	十		
	 	 	-				T	T	T			1		
	+-	-		1			T	T	T	П		1		
10400 1415 N					repor		ı	Relinquished by : (Signature) Date / Time Received by : (Signature						
Relinquis	and by	: (Sign	ature)		te / Time Received !			ग	Rol	Inqu	lshe	d by	y : (Signature) Date / Time Received by : (Signature)	
Relinquish	ned by	: (Sign	aturo)	10/0/4	to / Time Received for [Signature]	I who entorse by			D	ate	/ T:	20	Remarks	



Precision Environmental Analytical Laboratory

May 30, 1996

PEL # 9605061

TANK PEORTECT ENGINEERING

Attn: Louis Travis III

Re: Four soil samples for Gasoline/BTEX with MTBE analysis.

Project name: Credit World Auto Sales

Project location: 2345 E. 14th St., - Oakland, CA.

Project number: 267-052496

Date sampled: May 24, 1996

Date extracted: May 28-29, 1996

Date submitted: May 28, 1996 Date analyzed: May 28-29, 1996

RESULTS:

SAMPLE	Gasoline	MTBE	Benzene	Toluene	Ethyl Benzene	Total Xylene (ug/Kg)	
I.D.	(mg/Kg)	(ug/Kg)	(ug/Kg)	(ug/Kg)	(ug/Kg)		
STK-1 A,B,C, STK-2 S,B,C, VF-1 VS-2D		N.D. N.D. N.D.	110 100 N.D. 170	160 95 7.4 210	710 1200 9.5 280	2600 2100 37 1500	
Blank	N.D.	N.D.	N.D.	N.D.	N.D.	N.D.	
Spiked Recovery	87.8%		77.5%	91.7%	101.9%	111.1%	
Detection limit	1.0	5.0	5.0	5.0	5.0	5.0	
Method of Analysis	5030 / 8015	8020	8020	8020	8020	8020	


*Composited soil samples.

David Duong Laboratory Director

1764 Houret Court Milpitas, CA. 95035

Tel: 408-946-9636

Fax: 408-946-9663



LAB: P.E.L

TURNAROUND: Utral

P.O. #: 1304


(510) 429.8088 • (800) 523.8088 • Fax (510) 429.8089

CHAIN OF CUSTODY

PAGE 1 OF 2

علاور	HAME.	HE. ADDRESS AND TRIEPHONE NUMBER				(1) TYPE OF CON- TAINER	ANT LE							
27K1-A	styla,	7:10	'		Stellale	Beass tube	~	1	L)
57K1-B		3:05			STRITE BLEZE		4	\coprod	<u> </u>			_		5 Compaite
عا الآو		3.1			Stakpik		$\!$	\coprod	1_					
SIK 1-D		3115			str 1-D 620'	 	$\downarrow \downarrow$	\coprod	╄	\square			Ц	J
at -2k		4.0			side nyar evadore		$\!$	\coprod	╁-	$ar{\parallel}$	Н	_		
VF-1		4.79			HOOF SAMPLE	 	$\!$	Ц	╀					
CTV2-A		4,10		<u></u>	STUZ-A E 2-0'		#	\coprod	1	H	Щ			
STLAB		415			Steeling 8.2.	<u> </u>	\parallel	Ц	1	Ц	Ц		Н	4 Composite
Sn2-c	1	4:20			STR 1-C e 3.0 Shockpile Received l	₩	*	1				-1	שכ	: (Signature) Date / Time Received by : (Signature)
Relinquis Relinquis		Sign		S/2/ Dat	6/4- 12: Va 12	y (Sign	•tur	آ ً	Rol		ish	ed 1	by :	: (Signature) Date / Time Received by : (Signature) Remarks

DATE:	
-------	--



[510] 429-8088 = [800] 523-8088 = Fox (510) 429-8089

LAB: P.	£.C
TURNAROUND:	Pormi
P.O. #: 1304	

CHAIN OF CUSTODY

PAGE L OF 2

257 - Otay	MPTER NAME, ADDRESS AND TELEPHONE NUMBER ONLY TRANS. UT 1 MMIPPLE ROAD, UNION CITY, CA 94587 (415) 429-8088					(1) TYPE OF CON- TAINER	A STATE OF THE PARTY OF THE PAR						REMARK	s	
57K2-D	z feulge	4:25	/		STK 1-De Strong	20'	BIASS TUBE		7					Compaile a STK2-A	thru C
					Ţ			Ц			_				
						·			_	1	1				
						·	<u> </u>		_		\downarrow				
,							ļ	\sqcup		-	+		-		
				<u> </u>							╀		<u> </u>		
				ļ				\vdash	\dashv	+	╇		Ļ		
							ļ	H	\vdash	+	-				
Relinquish	1 \	(Sign	atur)	Da			myn		1						ived by : (Signature)
Refinitional by : (Signature) Date / Time Received b				y : (Signa	ture) R	olin	quish	ed 1	by :	(Signature) Date / Time Reco				
Relinquished by : (Signature) Date / Time Received for Labora Signature Page Page			P =	6	1	Dat	. / T	ize		Romarks					

DATE	:	<u></u> .
	_	



Precision Environmental Analytical Laboratory

June 01, 1996

PEL # 9605070

TANK PROTECT ENGINEERING

Attn: Mark R. Varney

Re: Fourteen soil samples for Gasoline/BTEX with MTBE analysis.

Project name: Credit World Auto Sales

Project location: 2345 E. 14th St., - Oakland, CA.

Project number: 267053096

Date sampled: May 30, 1996

Date extracted: May 30-Jun 01,1996

Date submitted: May 30, 1996

Date analyzed: May 30-Jun 01,1996

RESULTS:

SAMPLE	Gasoline	MTBE	Benzene	Toluene	Ethyl Benzene	Total Xylene
I.D.	(mg/Kg)	(ug/Kg)	(ug/Kg)	(ug/Kg)	(ug/Kg)	(ug/Kg)
CMV 1 A P C	D+ 1 7	N D	N.D.	N.D.	5.0	 17
STK 1 A,B,C, STK 2 A,B,C,		N.D.	13	26	47	94
STK 3 A,B,C,		N.D.	N.D.	N.D.	N.D.	N.D.
STK 4 A,B,C,		N.D.	N.D.	N.D.	N.D.	N.D.
STK 5 A,B,C,		N.D.	N.D.	N.D.	N.D.	N.D.
STK 6 A,B,C,		N.D.	N.D.	N.D.	N.D.	N.D.
VS-22	22	N.D.	6.5	N.D.	20	31
VS-23	N.D.	N.D.		N.D.	N.D.	N.D.
VS-24	N.D.	N.D.	N.D.	N.D.	N.D.	N.D.
VS-25	N.D.	N.D.		N.D.	N.D.	N.D.
VS-26	66	N.D.		22	24	130
VS-27	3.9	N.D.		N.D.	N.D.	33
VS-28	450	N.D.	170	120	280	390
VS-29	470	N.D.		85	250	760
Blank Spiked	N.D.	N.D.	N.D.	N.D.	N.D.	N.D.
Recovery Detection	82.4%		88.2%	92.9%	99.8%	102.2%
limit Method of	1.0	5.0	5.0	5.0	5.0	5.0
Method of Analysis	5030 / 8015	8020	8020	8020	8020	8020

^{*}Composited soil samples.

1764 Houret Court Milpitas, CA. 95035 Tel: 408-946-9636 Fax: 408-946-9663

Environmental Management

TANK PROTECT ENGINEERING

2821 WHIPPLE ROAD UNION CITY, CA 94587 (415)429-8088 (800)523-8088 FAX(415)429-8089

LAB:	PRIDRITY	ENVIRON MENTAL LABS

TURNAROUND: REGULAR

P.O. #: 1266

PAGE | OF 4

CHAIN OF CUSTODY

					LDDDECC			1		7	7	7	7 7	77	7							• [
PROJECT		1	tie Ogst	it mor	ADDRESS	SAUES		TO WAY	BI	9/	61	/ /		///	7							ı
267 05 ?		2	345	E. 141	6 ST. OA	とくてマンント	(1)	ا جُ	2	/\&/	[E].		[**/	///							•	1
SAMPLER	NAME.	ADDRESS	AND T	ELEPHONE	NUMBER		TYPE OF	₹,		\$/¥				//			RE	MAR	KS.			
	<u>, , , , , , , , , , , , , , , , , , , </u>	LAR	KR	VAR	いとり	0-9099	CON-	1 /	(.∼	/ <i>i></i> /	y /		/./									I
	LE ROAD	TTYE	SOIL	VATER	B7 (415) 42 SAMPLING LO	CATION	TAINER	Ź	¥/\$		\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\	[8] 8]	9/ /	/								!
ID NO.	DATE	IIAE	3012	*******					<u> </u>	<u> </u>	0/4	/2/										
STK 3A	5/30/9	.(เ:५ย	×		2.5		BRASS	X	X		\perp	Ц	\perp	7					·			
STK3B		11:45			2.5		1,1	X	X		╧	Ц	\perp									
STK3 C	11	11:50	×	·	2.5		"	X	X		1	\coprod	_	/ _	೭	omp	OSIT	<u> </u>	4 70	1		
STK3D	1	11:55	X		2.5		N	X	X		1	Ц	4	<u> </u>	·		· .					
STK4A	4	12:10	X		2.5		"	ΙX	X	Ц	\perp	\sqcup	4	7								
STK4B	"	12:15	Х		2.5		"	<u>IX</u>	<u>X</u>	Ц	\bot		_	· \	હ	omp	SITE	5	4 70	1		
STK4C	"	12:05	X		2.5		"	X	X		_	Ц	4	-								
STK4D	W	12>00	Х		2.5		"	X	X	Ц			٠,			<u></u>						
V5-29	"	11:02	×		12.5	Received b	(f)	ĺΧ	X	5-1 i v		had t	יטר	D)	1201	STS Date	7 Time	AM Re	posived b	y : (S	ignature	,
Relinquich	ed by	(Gign	ature)					/	"	WOY YE	ides.	.,,,,,,	-, .	\ <u>-</u>				-		•		
	IUL				9415:25	The	man and a second		1					/Clamptur	. 	Date	/ Time	P-	ceived b	v : (S	ignature	,
Relinquish	ed by :	(Sign	ature)	Date	e / Time	Received b	A : (2731)	tur	֓֓֓֓֓֓֓֓֓֓֓֓֓֓֓֓֓֓֓֓֓֓֓֓֓֓֓֓֓֓֓֓֓֓֓֓֓	kolin	iqu18i	iea D	ıy ;	(atangente	"		1			, , ,-		
			- 1 1	1	e / Time	Received for I	aboratory by	<i>/</i> :	+	Dat	te /	Timo	11	Remarks								
Relinquish	ed by :	(Sign	ature)	5/50		(Signature)	PC	(-						_						·	

DATE: 5/30/96

TANK PROTECT

Environmental Management

TANK PROTECT ENGINEERING

2821 WHIPPLE ROAD UNION CITY, CA 94587 (415)429-8088 (800)523-8088 FAX(415)429-8089

LAB:	PRIORITY	ENVIRONMENTAL LA	ßç
LAB:	PRIORITY	EMIRONNEW LY	

TURNAROUND: REGULAR

P.O. #: 1266

CHAIN OF CUSTODY

PAGE 2 OF 4

PROJECT 267 OS SAMPTER 2821 WHIPP ID NO.	30 9 Name.	ADDRESS ARK O, UNIO	345 3 AND 1	E. 144L	ADDRESS AUTO SAUES ST GA KLAND NUMBER 87 (415) 429-8088 SAMPLING LOCATION	(1) TYPE OF CON- TAINER	Trans de la constant					 		REMARKS
STKSA	5/30/9	12:25	X			BRASS	X)
STKSB	,	12:30				*	X	Χ						
STKSU	"	१२:५०	-			Н	X	X			Ш		L	2 COMPOSITE 4 to 1
SUKZD	11	12:45				"	X	X					L	V.
STKOA	"	13125				~	X	X	1				L	
STK68	N	13:35				"	Х	X						COMPOSITE 4 40
STKOC	"	13:45				~	TX	X	1					
STK6D		13:53	1			"	X	1						
Rolinquint			ature		e / Time Received	by : (Sign	I atur	-)	Rel	inq	uish	ed	рй	y: (Signature) Date / Time Received by: (Signature)
Relinquish				Dat	e / Time Received		atur	0)						: (Signature) Date / Time Received by : (Signature)
Relinquish	ed by	: (Sign	aturo)	5/30	Time Received for [Signature]	P E			D	ate	/ T	186		Remarks

DATE: 5/30/96

TANK PROTECTION ENGINEERING

Environmental Management

TANK PROTECT ENGINEERING

2821 WHIPPLE ROAD UNION CITY, CA 94587 (415)429-8088 (800)523-8089 FAX(415)429-8089

LAB:	PRIORITY	ENVIRONMENTAL	LABS
	· · · · · · · · · · · · · · · · · · ·	-	

TURNAROUND: REGULAR

P.O. #: 1266

PAGE 3 of 4

CHAIN OF CUSTODY

							T -		7		7	7	
PROJECT	r no.		SII	e name c	ADDRESS LD AUTO SAUES	1	l	£7.1	ନ/	/_ /	' /		' / / /
267052	2096				T. OAKLAND	(1)	A WALE	36	7. s /	\$ /.		/.5	///
						TYPE	<i>₹</i>	\$/			(tr /	(§*/	/// REMARKS
SAMPLER	NAKE.	ADDRES	SANDT	ELEPHONE	NUMBER *	OF	~ 6	7/.{	3/4/	\\$\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\	7/\`	٦/	
	ΜД	RK	K, V	というめ	07 (/15) /30,9099	CON-	1	/ 47	/&/4	9/G	[3]	/ /	′ /
2821 WHIPF					87 (415) 429-8088 SAMPLING LOCATION	- TAINER	ŹŚ	₹/ {	\$ /. ¥	/ /s		9/	/
ID NO.	DATE	TIME	SOIL	VATER	SARPLING DOCATION		/ ≈	/\$		3/4	<u> </u>		
	-1							σ					
STICIA	5/29/96	16:18	ΙXΙ		_	BRASS	X	X				_	
711C 174	-1.114						L^A	()		1	1	- {)
STK 1B	11	16:16	I X			11	$\Box \Delta$	Д		4		4	
						"	X	X	1			- 1	COMPOSITE 4 TO 1
STKIC	"	16.22	X				13	4		-	\vdash	-	
	u					"	ΙX	١٧I				1	
STKID		16:26	<u>1 X </u>	<u> </u>		_	14	М	┝┼	-	-	+	
	"		Х	ļ		"	Iγ	Įχ	ļ	1		1	
STKIA		16:32	1				 (``	/	 	+			- //
	-	16:34	X	1		· ~	I X	K	1				Composite 4401
STK 2B	ļ		_	<u> </u>			1.		H	1	П	7	
	1	16:40	ΙX		·	"	IX	IX				1	
STK 2C	ļ	10.1	7	<u> </u>			to			7			
STKZD	"	16:47	4 X			"	\mathbf{X}	X					
31K 67	 	 	+ / -	 			Т						·
	1	l	1	i					ш	لباب	إلبيا		(Signature) Date / Time Received by : (Signature)
Relinguis	ad by	:/NSig	nature)	Da	e / Time Received	by : (Sign	ature	•>	Relin	quist	ed 1	by :	(Signature) Date / Time Received by : (Signature)
Ker 7/7.	ACT.	\mathcal{O}_{-}			· · · · · · · · · · · · · · · · · · ·	Am		-					
	AK K				76 13 03			٠,	Pal (n	mu1 sh	ed t	10	(Signature) Date / Time Received by : (Signature)
Relinquish	red by	: (Sig	natura)	Dat	a / Time Received	DA : fardu	a turt	"[[VQT TIII	daran		., .	
				[]	1			\perp					
Relinquish	and by	: (Sig	nature)	Da		r Laboratory b		T	Dat	0/1	ino		Remarks
rarriidars,		. ,				PE	6	ł		1		1	
				130	194 /5:29 (Signature)	, <u> </u>						اا	

DATE: 5/29/96

Engineering Engineering Environmental Management

TANK PROTECT ENGINEERING

2821 WHIPPLE ROAD UNION CITY. CA 94587 (415)429-8088 (800)523-8088 FAX(415)429-8089

LAB:	PRIORITY	ENVIR	DUMEN	TAL	LAB:	5

TURNAROUND: REGULAR

P.O. #: 1266

PAGE $\frac{4}{}$ of $\frac{4}{}$

CHAIN OF CUSTODY

PROJECT 267 OT SAMPLER 2821 WHIPP ID NO.	299	ADDRESS ACU UNIO	345 3 AND T	ELEPHONE	ADDRESS D AUTO SALES L ST OAKLAND NUMBER 87 (415) 429-8088 SAMPLING LOCATION	(1) TYPE OF CON- TAINER	TO THE TE						
VS-22	5/29/90	[[150	X		14'	BRASS	X	X				L	ALL SAMPLES DISCREET
VS-23		11:59	¥		19'	\$4	Х	X			\bot	_	
V5-24	"	いめ	¥		14'	11	X	X,		Ц	┸	_	
VS-25	,	14:52	×		19'	11	X	X		Ц	\perp	_	
VS-26	u	14:59	X		14'	"	ĬΧ	X		Ц	_	╀	
VS-27	*	17:0	X		ା ଚ'	"	X	X	_	Ц		┸	
V5-28	"	17:04	X		(2.5)	11	X	X	_			Ļ	4
							_	L	L		\perp	$oldsymbol{\perp}$	
Relinquish	AIC			5 30 Date	GU (5:25 M	by : (Signa	stur	ı	Rel	inqui	shed	by	: (Signature) Date / Time Received by : (Signature) : (Signature) Date / Time Received by : (Signature)
Relinquish	ed by	(Sign	ature)	1.32	Time Heceived for [Signature]	PE	; 			ate /	Tim		Remarks

DATE: 5/29/96



Precision Environmental Analytical Laboratory

July 31, 1996

PEL # 9607072

TANK PROTECT ENGINEERING

Attn: Lee Huckins

Re: Ten soil samples for Gasoline/BTEX with MTBE analysis.

Project name: Credit World Auto Sales Project location: 2345 E. 14th St.

Project number: 267073096

Date sampled: Jul 30, 1996 Date extracted: Jul 31, 1996 Date submitted: Jul 31, 1996 Date analyzed: Jul 31, 1996


RESULTS:

SAMPLE I.D.	Gasoline	MTBE B	enzene	Toluene	Ethyl Benzene	Total Xylene
1.5.	(mg/Kg)	(ug/Kg) (ug/Kg)	(ug/Kg)	(ug/Kg)	(ug/Kg)
VSP-20A	N.D.	N.D.	N.D.	N.D.	N.D.	N.D.
VSP-21B	N.D.	N.D.	N.D.	N.D.	N.D.	N.D.
VSP-22C	N.D.	N.D.	N.D.	N.D.	N.D.	N.D.
VSP-23D	N.D.	N.D.	N.D.	N.D.	N.D.	N.D.
VSP-24A	N.D.	N.D.	N.D.	N.D.	N.D.	N.D.
VSP-25B	N.D.	N.D.	N.D.	N.D.	N.D.	N.D.
VSP-26C	N.D.	N.D.	N.D.	N.D.	N.D.	N.D.
VSP-27D	N.D.	N.D.	N.D.	N.D.	N.D.	N.D.
VSP-28A	N.D.	N.D.	N.D.	N.D.	N.D.	N.D.
VSP-29B	N.D.	N.D.	N.D.	N.D.	N.D.	N.D.
Blank	N.D.	N.D.	N.D.	N.D.	N.D.	N.D.
Spiked Recovery	89.4%		85.1%	90.5%	100.2%	88.8%
Detection limit	1.0	5.0	5.0	5.0	5.0	5.0
Method of Analysis	5030 / 8015	8020	8020	8020	8020	8020

David Duong Laboratory Director

1764 Houret Court Milpitas, CA. 95035

Tel: 408-946-9636 Fax: 408-946-9663



(510) 429-8088 **(800)** 523-8088 **Fax** (510) 429-8089

LAB:	Priorita Env.

TURNAROUND: 48 hr


P.O. #: 1323

CHAIN OF CUSTODY

PAGE / OF Z

PROJECT ZGOOT SAMPLER 2821 WKIPP ID NO.	NAME,	Z ADDDES	Huck Huck	E 1440	HUMBER 87 (415) 42	9-8088	(1) TYPE OF CON- TAINER	THE LEE						//			RE	EMARKS
VSP-ZOA	7/30	1115	X		15-Z.6		Brass	8	メ					ne	zed t	> 100	lide 1	MTBE.
VSP21B	-17	4.	×		25-3.0		Brows	1	Υ_			1	\perp					
USPZZL			×		35-4.0		Brass	¥	人		Ц	1	1					
VSP23D			V		18-2.0		Brass	<	×					<u> </u>				
V5724A			<u> </u>		28-30		Brass	K	K							•		
VSP28B		7	├ ──	1	35-40	 -	Bruss	V	K	Γ	П	Т			,···			
				<u> </u>			13 car S	レ	Į	T	Ħ	1						·
V3826C			T	 	1.5-2.		Brass	┿	f-,	十	H	\dagger	\dagger					
VSPZ7D	130	<u> </u>	1	<u> </u>	2.5 - 3.9	<u> </u>	13/43	丫	۴	├	╁┼	+	╁		<u> </u>			٠.
Relinquieh	17	•		Da	te / Time	Received h	by : (Signa	tur	e)]	Re1	ingui	.she	d by	: (Sig	gnature)	Dat	o / Timo	·
Rolinquish	Huc ed by	Sign	ature)	Dat	o / Time	Received b	y : (Signa	tur	->	Roll	lnqul	she	1 by	: (S1g	nature)	Dat	o / Timo	Received by : (Signature)
Relinquish	ed by	: (Sign	ature)	Da	ts / Time	Received for [Signature]	Labpratury by		k	7/3/	1/16	7.9	30 A	Rose	rks			

DATE:_____



(510) 429-8088 m (800) 523-8088 m Fax (510) 429-8089

LAB:	Prioris	e En.	
		 	

TURNAROUND: 48 hr

DATE:

P.O. #: 1323

CHAIN OF CUSTODY

PAGE 2 OF 7

PROJECT OTS SAMPLER 2821 UNID NO.	NAME,	IDDEE	CWA 2345 S AND 1 CAIDS W CITY	S E 14 ⁴⁰	87 (415)	429-8088 LOCATION	(1) TYPE OF CON- TAINER	ANG A						REMARKS
VSTZBA	1/30	1137	X		圣 公-	W. 0	Brass	×	×			Ц		
VSP29B					1.5~	2.0	Brass	×	K					
- C			3						_					
		-	 		<u> </u>			╁╴	╁╌	H	\vdash	H		
,	├						 	╁	t		H	$\dagger \dagger$		
	╂	 						十	T		H	Ħ		
	 	 	-	 			 	十	╁╴	П		П		
	 -	 	-	 -	ļ <u> </u>	<u> </u>	 	十	╁	Н	H	T		
Rel (pquie)	11	, ,	ature)	Da	to / Time	Received	by : (Sign	atur	9	Reli	inquis	hed	by	y : (Signature) Date / Time Received by : (Signature)
Rélinquisi	had by	: (Sign	ature)	Day	o / Timo	Received	by ; (Sign	atur	->	Roli	nquis	hed i	ο¥ :	: (Signature) Date / Time Roccived by : (Signature)
Relinquish	hed by	: (Sign	aturo)	Da	to / Time	Received for [Signature]	Laboratory by	-2	ļ	D. 7/	1195	Time 7:50	4n	Remarks



Precision Environmental Analytical Laboratory

September 17, 1996

PEL # 9609032

TANK PROTECT ENGINEERING

Attn: Lee Huckins

Re: Five RUSH soil samples for Gasoline/BTEX with MTBE analysis.

Project name: CWAS

Project location: 2345 E. 14th St.

Project number: 267091696

Date sampled: Sep 16, 1996

Date extracted: Sep 16-17, 1996

Date submitted: Sep 16, 1996 Date analyzed: Sep 16-17, 1996

RESULTS:

SAMPLE I.D.	Gasoline (mg/Kg)	MTBE (ug/Kg)	Benzene (ug/Kg)	Toluene (ug/Kg)	Ethyl Benzene (ug/Kg)	Total Xylene (ug/Kg)	
STK-20A,B,C	=	N.D.	75 N.D.	90 N.D.	110 N.D.	170 N.D.	
STK-23A,B,C	•	N.D.	N.D. 40	N.D. 54	N.D. 250	N.D. 210	
VS-31	110	N.D.	280	210	460	490	
Blank	N.D.	N.D.	N.D.	N.D.	N.D.	N.D.	
Spiked Recovery	80.2%		85.6%	84.3%	83.3%	81.7%	
Detection limit	1.0	5.0	5.0	5.0	5.0	5.0	
Method of Analysis	5030 / 8015	8020	8020	8020	8020	8020	


^{*}Composited soil samples.

David Duong Laboratory Director

1764 Houret Court Milpitas, CA. 95035

Tel: 408-946-9636

Fax: 408-946-9663



(510) 429-8088 = (800) 523-8088 = Fax (510) 429-8089

TURNAROUND: Zyhr

P.O. #: 1337

CHAIN OF CUSTODY

PAGE / OF Z

2821 WHIP	1696 NAME. PLE ROA	ADDRES O, UNIT	S AND 1 UCh? W City)) (, CA 945	MC	9-8088 OCATION	(1 TYPE OF CON- TAINER						REMARKS
ID NO.	DATE	TIME	SOIL	VAIER	SANFLING L			<u>/~</u>	<u> </u>	&\ _{&} \	×/	<u>Z</u> .	Report MIBE
VS-30	7/16	405	X		151		Brow	7	/				
V5-31	ì	1400			141			×	1				
574 ZUA		1445	۸/		7			1	4	11			
-	╂╌┼╌	1			70			+	Л				(Comparte into I sample
STH20B	1-	1445					1 - 	+-	r .t	-1-1	+	╁┈	7
STUZOC	11	445	1X		Z.c.		11	+	╀	╅	╌	╁╴	
57420D	*	1441	·		2.6		<u>*</u>	_ <u></u> ≠			_	╀-	
				1			i				\perp	L	
ļ	 	1	 					T	П				
	 	 	 	 			 	+	 	++	1	忊	
		<u></u>	<u> </u>			Paraivad	ov : (Sign	natur) R	lingu	shed	by	: (Signature) Date / Time Received by : (Signature)
Relinquie				3/11.12	6 / Time					-			
Rolinquis	Lu	18//v	ature	7/14/9	6 / Time	Received b	y : (Sign	natur	e) Re	linqui	shed	by	: (Signature) Date / Time Received by : (Signature)
Kerrudara	mar wy	. ,	- •		1961 16:21	THAN H	LAN		1_				
Relinquis	hed by	: (5 i gi	naturo)		is / Time	Received for	Caboratory	by:		Date /	Time		Remarks

DATE:	·
-------	---



(510) 429-8088 = (800) 523-8088 = Fax (510) 429-8089

LAB: Fronty

TURNAROUND: ZYhr

P.O. #: 1337

PAGE Z OF Z

CHAIN OF CUSTODY

	PROJECT	1690	Anness	SITTE	TEPHONE TEPHONE	HONBER 4~24 7? YDOUESE		(1) TYPE	ا ئۇرۇ ئۇرۇ					7/		REM	IARKS	
	2821 WHIPF	LE RON	e H	w city,	LA 9458	37 (415) 429	-8088	OF CON- TAINER	Ž,				//	,	\	. •		
┢	ID NO.	DATE	TIME	SOIL	VATER	SAMPLING LOC	ATION		/ <u>^</u>	/ \$ /&	5/5/A	7%		16 bou	1 m	TBE_		
[374240	9/16	びり	4		1,5		Bars	4	4	$\downarrow \downarrow$		_	}				
s	14 ZZB	9/4	120	Y		1.5			+	4	\vdash	-	_	Cor	Noon.	de indo	Sample	
ع	14ZZC	9/16	140	1		1.7			4		╀┼	╂╌╂╾	} 					
Ţ	742ZD	9/16.	11/2	K		1.5			1	1	++	╁╌╁╌	 	<u> </u>				
Į	94234	9/16	180	K		7.6			14		╀╂		├	}-			·	
	51 ZSB					1, 4			上	91		11	ļ					
	14 Z8C					1.0			4	4				<u> </u>	z wba	deir	do Sample	
4	TK ZSD	9/1	KK	+),6		T y	4	4								
1	A LEGICAL OF THE PARTY OF THE P	 '*		-					Π		\prod					- 	Received by :	(Signature)
•	Relinquia			nature)		6 /6Z)	Received b	y : (Sign	ur	o) Res	Linguis	hed by	: (Sig	gnatura)	Date	/ Time		
Y	Relinquish	1 57	بر (Sign	ature)	Date	7 Time	Received b	y : (Sign) Rel	inquis	hed by	: (Sig	mature)	Date	/ Time	Received by : (Signaturo)
1	Relinquish			·	9116	96 16:20 a / Time	Received for Signature)	H CAM Laboratory by PEL	e		Date /	Time	Remo	rka		J		

DATE	·
------	---

P E

PRIORITY ENVIRONMENTAL LABS

Precision Environmental Analytical Laboratory

September 19, 1996

PEL # 9609041

TANK PROTECT ENGINEERING

Attn: Lee Huckins

Re: Six RUSH composited soil samples for Gasoline/BTEX

with MTBE analysis.

Project name: CWAS

Project location: 2345 E. 14th St.

Project number: 267091796

Date sampled: Sep 17, 1996

Date extracted: Sep 18-19, 1996

Date submitted: Sep 18, 1996
Date analyzed: Sep 18-19, 1996

M-4-1

RESULTS:

SAMPLE	Gasoline	MTBE	Benzene	Toluene	Ethyl Benzene	Total Xylene (ug/Kg)	
I.D.	(mg/Kg)	(ug/Kg)	(ug/Kg)	(ug/Kg)	(ug/Kg)		
STK-25A,B,C,	D* 210	N.D.	180	98	120	240	
STK-26A,B,C,		N.D.	50	63	84	250	
VS-32	20	N.D.	120	120	130	280	
VS-33	7.5	N.D.	19	34	60	200	
VS-34	52	N.D.	190	140	630	660	
VS-35	29	N.D.	23	130	72	500	
Blank	N.D.	N.D.	N.D.	N.D.	N.D.	N.D.	
Spiked Recovery	91.5%		94.3%	104.3%	87.6%	101.8%	
Detection limit	1.0	5.0	5.0	5.0	5.0	5.0	
Method of Analysis	5030 / 8015	8020	8020	8020	8020	8020	


*Composited soil samples.

David Duong Laboratory Director

1764 Houret Court Milpitas, CA. 95035

Tel: 408-946-9636

Fax: 408-946-9663



(510) 429-8088 = (800) 523-8088 = Fax (510) 429-8089

LAB:	trionity	Env	
			

TURNAROUND: ZYAr


P.O. #: 1339

CHAIN OF CUSTODY

PAGE ___ OF ___

	PROJECT Z6709/ SAMPLER 2821 WHIPP ID NO.	796 HANE,	ADDRESS D. UNIO	AND THE	ILEPEONE CA 9458	ADDRESS Street NUMBER 17 (415) 42	9-8088 CATION	(1 TYPE OF CON- TAINER) 3							REMARKS Pepord mysse
Ī	V5-32	9/17		1		12'		Bras	K	Y		_		<u> </u>	 	·
	US~33			X)71			14	N.	11		_	\bot		
	V>-34	9/17		4		17'		<u> </u>	X	<u> </u> \	4		_	\downarrow		
	US -35			ン		1.51		 	אַן	X	44	Ц		+		
54	415-E	9/17	1340	4		10		 	1	×	1	Н	+	+	├ ─	
med .	275 3	9/17	345	7		٥. ١			 *	$\frac{1}{\lambda}$		Н	+	+	-	Composite into I sample
314	ZSC	7/17	1330	4		1.0				<u> </u>	\Box	Н	+	╀	-	
51	KZSD	9/1	/35 X	8		1.0		\ \\ \\ \\ \\ \\ \\ \\ \\ \\ \\ \\ \\ \	1	K	1	\sqcup	+	╀	_	1
ļ	Relinquish Relinquish Relinquish	ed by	Rima : (Sign	ature)	Date 9/18/	76 /4.00	Received by Received by THANA HARCEIVED for [Signature]	y : (Sign	satu:	1	Roli	nqui		by	: (Sig	

DATE	::	
------	----	--



(510) 429-8088 m (800) 523-8088 m Fox (510) 429-8089

	-) 1	
LAB:	1 coris	y En

TURNAROUND: 24 hr

P.O. #:1339

CHAIN OF CUSTODY

PAGE Z OF Z

PROJECT SAMPLER 2821 UNIP	NAI PLE	76 E.	Z	SCHA!	P/HT	ADDRESS NUMBER 87 (415) 429 SAMPLING LO	9-8088 CATION	(1) TYPE OF CON- TAINER	18.00						REMARKS
STUZ6A	9/	7	16ZC	¥		1.0		Bonz	×	12		_	Ļ	_	
STICZGIS	9/	77	Kozo	4		7.0		11	X	》			1	\downarrow	Composite & into I sample
strz6c	9/	17	1480	A		0.1			X	χ.			╀	igspace	
stk-260	9/	נו	ريتن	*		1,0		4	X	×		-	\downarrow	╀	
,	-												1	1	
	T												Ŀ	L	
	T													1.	
	╁╴														(Signature) Date / Time Recoived by : (Signature)
9/18/06/1/2:01 THANH					by: (Signal	atur	1	Roli		hed	by	: (Signature) Date / Time Received by : (Signature) : (Signature) Date / Time Received by : (Signature) Remarks			

DATE	:	
------	---	--



Precision Environmental Analytical Laboratory

September 18, 1996

PEL # 9609037

TANK PROTECT ENGINEERING

Attn: Lee Huckins

Re: Two RUSH composited RUSH soil samples for Gasoline/BTEX

with MTBE analysis.

Project name: CWAS

Project location: 2345 E. 14th St.

Project number: 267091796

Date sampled: Sep 17, 1996

Date extracted: Sep 17-18, 1996


Date submitted: Sep 17, 1996 Date analyzed: Sep 17-18, 1996

RESULTS:

SAMPLE I.D.	Gasoline (mg/Kg)	MTBE	Benzene (ug/Kg)	Toluene (ug/Kg)	Ethyl Benzene (ug/Kg)	Total Xylene (ug/Kg)
STK-21A,B,C,I STK-24A,B,C,I		N.D.	120 N.D.	84 N.D.	190 N.D.	320 N.D.
Blank	N.D.	N.D.	N.D.	N.D.	N.D.	N.D.
Spiked Recovery	94.4%		86.6%	97.1%	101.3%	96.6%
Detection limit	1.0	5.0	5.0	5.0	5.0	5.0
Method of Analysis	5030 / 8015	8020	8020	8020	8020	8020

David Duong Laboratory Director

1764 Houret Court Milpitas, CA. 95035 Tel: 408-946-9636 Fax: 408-946-9663



(510) 429.8088 = [800] 523.8088 = Fax (510) 429.8089

LAB:	Pranty Enu
	J

TURNAROUND: 24hr

P.O. #:<u>/338</u>

CHAIN OF CUSTODY

SITE NAME & ADDRESS PROJECT NO. (1)2345 E1444 Street 267091796 TYPE SAMPLER HAME. ADDRESS AND TELEPHONE NUMBER REMARKS 2821 WHIPPLE ROAD, UNION CITY, CA 94587 (415) 429-8088 OF COH-TAINER DATE TIME SOIL WATER SAMPLING LOCATION Bauss STEZ4A 1.5 Composite into Samo 1.5 1.5 15 1.0 Composite into I sample \$1x-2/B 19/11 1025 ۵.(BTK-ZIC J.G 1.0 \$TK-210 9/17 1025 Received by : (Signature) Date / Time Received by : (Signature) Relinquished by : (Signature) Date / Time Relinquished by : (Signature) Received by : (Signature) Date / Time Received by : (Signature) Relinquished by : (Signature) Date / Time RElinquished by : (Signature) THAYHLAM Date / Time Romarks Received for Laboratory by Relinquished by : (Signature) [Signature]



Analytical Laboratory Precision Environmental

October 09, 1996

PEL # 9610009

TANK PROTECT ENGINEERING , INC.

Attn: Lee Huckins

Re: Ten soil samples for Gasoline/BTEX with MTBE analysis.

Project name: Credit World Auto Sale Project location: 2345 E. 14th St.

Project number: 267100496

Project location: 9770 Monterey Rd., - Coyote, CA.

Date sampled: Oct 04, 1996

Date submitted: Oct 07, 1996 Date extracted: Oct 07-09, 1996 Date analyzed: Oct 07-09, 1996


RESULTS:

SAMPLE I.D.	Gasoline	MTBE	Benzene	Toluene	Ethyl Benzene	Total Xylene
1.0.	(mg/Kg)	(ug/Kg)	(ug/Kg)	(ug/Kg)		(ug/Kg)
VSP-30A	N.D.	N.D.	N.D.	N.D.	N.D.	N.D.
VSP-31B	N.D.	N.D.	N.D.	N.D.	N.D.	N.D.
VSP-32C	N.D.	N.D.	N.D.	N.D.	N.D.	N.D.
VSP-33D	N.D.	N.D.	N.D.	N.D.	N.D.	N.D.
VSP-34A	N.D.	N.D.	N.D.	N.D.	N.D.	N.D.
VSP-35B	N.D.	N.D.	N.D.	N.D.	N.D.	N.D.
VSP-36A	N.D.	N.D.	N.D.	N.D.	N.D.	N.D.
VSP-37B	N.D.	N.D.	N.D.	N.D.	N.D.	N.D.
VSP-38C	N.D.	N.D.	N.D.	N.D.	N.D.	N.D.
VSP-39D	N.D.	N.D.	N.D.	N.D.	N.D.	N.D.
Blank Spiked	N.D.	N.D.	N.D.	N.D.	N.D.	N.D.
Recovery Detection	105.6%		87.5%	101.7%	101.7%	105.9%
limit Method of	1.0 5030 /	5.0	5.0	5.0	5.0	5.0
Analysis	8015	8020	8020	8020	8020	8020

Duong Laboratory Director

1764 Houret Court Milpitas, CA. 95035

Fax: 408-946-9663 Tel: 408-946-9636



TURNAROUND:

P.O. #: 1357


(510) 429-8088 **a** (800) 523-8088 **a** Fax (510) 429-8089

CHAIN OF CUSTODY

PAGE / OF Z

	HAHE. LEE PLE ROA	ADDRESS	Kin CITY,	2 Tielwas	AUDRESS Aurb Sches HUKBER 87 (415) 428 SAMPLING LO	-8088	(1) TYPE OF CON- TAINER	TA TANKE					REMA	RKS	
VSP-30A	104	5249	×		1.0-15		4	M					include MTBE		
USP-318		1252	X		15-ZC	>		X	4	4		\downarrow		· · · · · · · · · · · · · · · · · · ·	
VSP-32C			X		Z0-Z0			凶			_	-			
V58-53D	16)4	RSB	X		1.0-1.5			凶	4		Ц	_			
J5P-34A		300	K_		1.5-20			M	_		Ц	4		<u></u>	
15P-35B					20-2	5		X	凶		Ц	\perp			
VSP-36A			7		15-2.0)		K	\forall		Ц	\perp	:		
VSP-37B	10/4	1315	V		15-20	>	1	K	X						
							/Si		31 B	ling	i sha	d by	: (Signature) Date / Time	Received by : (Signature)	
Relinquished by: (Signature) Date / Time Received by Park 1505 Uny						•									
Relinquis	ed by	: (Sign	atura)	Dat	e / Time	Kecerved I	od : (průpe	rura	7	e tuda	- 				
Relinquished by : (Signature) Date / Time (Signature) (J. 196 / J.					PC (Date	/ Ti	NO	Romarks				

DATE	:	
------	---	--



[510] 429.8088 • (800) 523.8088 • Fax (510) 429.8089

LAB:	Priority Env
------	--------------

TURNAROUND: 🛲

P.O. #: 1357

CHAIN OF CUSTODY

PAGE Z OF Z

PROJECT NO. SITE NAME & ADDRESS CRECIT WORLD SOLE 267 100496 2345 E14454 SAMPTER NAME, ADDRESS AND TELEPHONE NUMBER 2821 UNIPPLE ROAD, UNION CITY, CA 94587 (415) 429-8088 ID NO. DATE TIME SOIL VATER SAMPLING LOCATION					(1) TYPE OF CON- TAINER	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1					REMARKS	
VSP-38 C	10/4	34	X		1.5-20	Bass	メ	K				Include MTBJE
USP-39D			X		1.5-2.0	Bruss	χ.	¥	\sqcup	\perp	4	
	}			<u> </u>			_	-	H	+	+	
<u> </u>			 			 	\vdash	-	H		1	
-	 	╁	1									
						ļ	L	L		_ _	4	
Relanquished by: (Signature) Date / Time Received by						Som		1				y : (Signature) Date / Time Received by : (Signature)
Relinquish	and by	: (Sign	nature)	Dat	e / Time Received	y ; (Signa		2)				: (Signature) Date / Time Received by : (Signature)
Relinquish	ed by	: (Sign	ature)	10/7/	46/5:07 Received for [Signature]	P E			Da	to / T	ino	Remarks

DATE	•	