April 13, 2004

Mr. Amir Gholami Alameda County Health Care Services Agency 1131 Harbor Bay Parkway, Suite 250 Alameda, CA 94502-6577

Alexander of granding

APR 1 6 2004

Part of the House

Re:

Site Assessment Work Plan

Credit World Auto Sales

2345 International Boulevard (formerly E. 14th Street)

Oakland, California

ACHCS Case No. RO0000327 Cambria Project No. 513-1000

9

Dear Mr. Gholami:

On behalf of Mr. Stanley Wong, Cambria Environmental Technology, Inc. (Cambria) has prepared this *Site Assessment Work Plan* for the above-referenced site.

If you have any questions or comments regarding this work plan, please call me at (510) 420-3305.

Sincerely,

Cambria Environmental Technology, Inc.

Gretchen Hellmann

Project Engineer

Attachment: Site Assessment Work Plan

(wehler Hellmann

cc: Mr. Stanley Wong, 2200 E. 12th Street, Oakland, California 94606

H:\Wong (Credit Auto), Oakland\Site Assessment Work Plan\Site Assessment Work Plan.doc

Cambria Environmental Technology, Inc.

5900 Hollis Street Suite A Emeryville, CA 94608 Tel (510) 420-0700 Fax (510) 420-9170

SITE ASSESSMENT WORK PLAN

Credit World Auto Sales
2345 International Boulevard
(Formerly E. 14th Street)
Oakland, California 94601
ACHCS Case No. RO0000327
Cambria Project No. 513-1000

April 13, 2004

 ${\it Prepared for:}$

Mr. Stanley Wong 2200 East 12th Street Oakland, California 94606

Prepared by:

Cambria Environmental Technology, Inc. 5900 Hollis Street, Suite A Emeryville, California 94608

Written by:

No. 6842

Gretchen Hellmann

Project Engineer

Ron Scheele, R.G.

Senior Geologist

SITE ASSESSMENT WORK PLAN Credit World Auto Sales 2345 International Boulevard (Formerly E. 14th Street) Oakland, California

TABLE OF CONTENTS



1.0	INTRODUCTION
2.0	SITE BACKGROUND
2.1	SITE DESCRIPTION
2.2	REGIONAL AND LOCAL GEOLOGY
2.3	REGIONAL AND LOCAL HYDROGEOLOGY
	SENSITIVE RECEPTORS
3.0	PREVIOUS INVESTIGATIONS
4.0	PREVIOUS SITE REMEDIATION
4.1	SOIL EXCAVATION
4.2	SPH REMOVAL
4.3	BIO-REMEDIATION SYSTEM
4.4	VACUUM TRUCK OPERATIONS
5.0	PROPOSED SCOPE OF WORK
5.1	OBJECTIVE
5.2	SITE HEALTH AND SAFETY PLAN
5.3	PERMITS
5.4	OFF-SITE ACCESS
5.5	UTILITY CLEARANCE
5.6	SOIL SAMPLING AND ANALYSIS
5.7	MONITORING WELL INSTALLATION
5.8	WELL DEVELOPMENT
5.9	WELL SURVEY
	MONITORING WELL SAMPLING AND ANALYSIS
5.11	INVESTIGATION DERIVED WASTE (IDW)
6.0	REPORTING
7.0	SCHEDULE

FIGURES

Figure 2	
	TABLES
Table 2	
	Groundwater Elevation and Analytical DataSeparate-Phase Hydrocarbon Removal
	APPENDIX
Appendix BStandard Field F	Procedures for Soil Boring and Monitoring Well Installations Soil Boring Logs and Well Construction Details

SITE ASSESSMENT WORK PLAN

Credit World Auto Sales 2345 International Boulevard (Formerly E. 14th Street) Oakland, California

April 13, 2004

1.0 INTRODUCTION



On behalf of Mr. Stanley Wong, Cambria Environmental Technology, Inc. (Cambria) has prepared this *Site Assessment Work Plan* (Work Plan) for the above-referenced site. In a letter dated February 25, 2004, Mr. Amir Gholami of the Alameda County Health Care Services Agency (ACHCSA) approved the recommendations proposed in Cambria's *Site Summary Report* including a work plan to further delineate the extent of hydrocarbons and abandon all improperly constructed wells (Appendix A). The site background, previous investigations and remediation, proposed scope of work, reporting, and schedule are described below.

2.0 SITE BACKGROUND

2.1 Site Description

The site is located in a commercial/residential area at the southwest corner of the intersection of International Boulevard (formerly East 14th Street) and Miller Avenue in Oakland, California (Figure 1). The site is at an elevation of approximately 23 feet above mean sea level, based on City of Oakland datum. The site is currently operated by Credit World Auto Sales, a used car dealership. One building occupies the site and is used as an office and automotive service bay. The remainder of the site is a paved parking area (Figure 2).

The site is located in a mixed commercial and residential area and is bound by International Boulevard to the northeast, Miller Avenue to the southeast, a car repair shop to the southwest, and a restaurant with second floor apartments to the northwest. Adjacent to the restaurant is a hotel and a residential dwelling.

2.2 Regional and Local Geology

The site is located within the Coast Range geomorphic province of California. In general, the

Coast Range province consists of Jurassic eugeosynclinal basement rocks and Cretaceous and Cenozoic sedimentary and volcanic rocks that have been faulted and folded with a northwest-southeast trend. The site lies within the Bay Plains Basin. Sediments beneath the site consist of coalescing alluvial deposits from the Diablo Range to the east known as the San Leandro Cone. According to the USGS Professional paper 943, the site is located on quaternary age alluvial deposits consisting of medium-grained, unconsolidated, moderately sorted, and permeable, fine sand, silt, and clayey silt with thin beds of coarse sand.



Previous investigations at the site encountered low to moderate permeability clays and silts with interbedded higher permeability sand and gravel layers to the total depth explored of 36 feet below ground surface (bgs). Approximately one-foot of asphalt and aggregate base material (fill) is underlain by a clay layer extending to approximately 11 to 17 feet bgs. This clay layer is underlain by a moderately permeable layer of silty to clayey sand to approximately 27 feet bgs and a gravelly clay layer to approximately 36.0 feet bgs. A highly permeable sand and/or gravel layer is sometimes present at depths ranging from 30.5 to 35.0 feet bgs.

2.3 Regional and Local Hydrogeology

Major water-bearing zones beneath the Bay Plain Basin occur at depths ranging from 50 feet to more than 1,000 feet bgs. Groundwater from these zones is presently used largely for irrigation and industrial purposes. Regionally, groundwater flow is generally from the Diablo Range toward San Francisco Bay. The nearest surface water body to the site is Brooklyn Basin Tidal Canal located ½ mile to the west.

Two water-bearing zones are present beneath the site. The upper water-bearing zone exists from approximately 17 to 23 feet bgs (up to 27 feet bgs in well MW-1), and the lower water-bearing zone exists from approximately 30.5 to 35 feet bgs. The upper water-bearing zone appears to be under semi-confined or confined conditions and the two water-bearing zones are possibly hydraulically connected. Since 1991, the depth to groundwater beneath the site has ranged from approximately 6.6 to 17.8 feet bgs, but typically fluctuates between approximately 10 to 15 feet bgs. Historically, the groundwater flow direction has varied significantly, with groundwater appearing to flow to the northwest or radially outward from the center of the site. The apparent radial groundwater flow direction may be explained by water mounding within the underground storage tank (UST) cavity (from August 1993 to September 1994) and within the UST excavation (after December 1994). The apparent radial groundwater flow direction may also be explained by

wells (MW-1, MW-3, and TMW-4) that are screened across two water-bearing zones. Well completion and groundwater level data are summarized on Table 1.

2.4 Sensitive Receptors

The Alameda Harbor to the San Francisco Bay is located approximately 1.5 miles west of the site and the closest body of surface water is the Brooklyn Basin Tidal Canal is located ½ mile to the west of the site. A well survey has not been completed for the site.

9

3.0 PREVIOUS INVESTIGATIONS

Several phases of soil and groundwater assessments have been conducted at the site since the USTs were removed in 1988. Groundwater and soil analytical results from these investigations is summarized in Tables 2 and 3, respectively.

August 1988: On August 5, 1988, one 8,000-gallon gasoline UST, two 6,000-gallon gasoline USTs, one 1,000-gallon waste oil UST, two dispenser islands, and associated piping were removed from the site by West Coast Tank Company of Campbell, California (Figure 2). Soil samples from the fuel UST cavity were impacted by total petroleum hydrocarbons as gasoline (TPHg) and benzene (Table 2). Soil samples from the used oil excavation area were impacted by total petroleum hydrocarbons as diesel (TPHd) and total oil and gas (TOG). The excavations were backfilled "with the stockpiled spoils and imported fill, compacted, graded to surface contours and capped with concrete" (see the *Phase I Soil and Groundwater Assessment Report* dated December 23, 1991 by Earth Systems Environmental Inc.)

November 1988: California Environmental Consultants (CEC) advanced three soil borings (B-1 to B-3) to assess the extent of hydrocarbon impact in the soil and groundwater in the vicinity of the former UST locations. Borings B-1 and B-2 were advanced adjacent to the former fuel USTs. TPHg and benzene, toluene ethylbenzene, and xylenes (BTEX) concentrations were detected in soil and groundwater samples from both borings (Tables 2 and 3). Soil and groundwater samples from boring B-3, located near the former used oil UST location, were impacted by BTEX and TOG.

May to August 1991: Earth Systems Environmental advanced five onsite borings (TH-1 through TH-5) and installed three groundwater monitoring wells (MW-1 through MW-3) at the site to further delineate the onsite hydrocarbon impact. Borings B-1 and B-2 were advanced adjacent to the former fuel USTs. TPHg and BTEX concentrations were detected in the soil and groundwater

(Tables 2 and 3). Soil and groundwater samples from boring B-3, located near the former used oil UST location, were impacted by TOG and BTEX. Groundwater was encountered at 19 feet bgs during this assessment.

July 1993: Tank Protect Engineering (Tank Protect) installed two monitoring wells (TMW-4 and TMW-5) at the site. No petroleum hydrocarbons were detected in soil samples from borings for wells TMW-4 and TMW-5. Separate-phase hydrocarbons (SPH) were observed in wells MW-1, MW-2 and TMW-5. The groundwater flow direction beneath the site was inferred to be north-northeast to west-southwest with an average gradient of 0.029 ft/ft. Tank Protect concluded that unconfined and confined groundwater is present beneath the site, and that wells MW-2 and MW-3 monitor an upper, unconfined water-bearing zone while MW-1, TMW-4, and TMW-5 monitor both the upper unconfined water-bearing zone and a lower confined water-bearing zone. Tank Protect concluded that sands logged in well MW-2 are characteristic of a buried stream channel, trending north-south beneath and across the site.

April 1997 to May 1997: Tank Protect advanced five borings (SB-1 through SB-5) to assess the offsite hydrocarbon impact. TPHg concentrations were detected in soil and water samples from boring SB-5 and benzene concentration were detected in boring SB-2 (Tables 2 and 3). Benzene and methyl tert-butyl ether (MTBE) concentrations were detected in groundwater from boring SB-5. No petroleum hydrocarbons or MTBE were detected in soil and groundwater samples from borings SB-1, SB-3, and SB-4. Tank Protect concluded that the northern and southern extent of the hydrocarbon plume was defined.

May 2001: Sequoia Environmental (Sequoia) advanced seven onsite borings (SB-1 through SB-7), converting boring SB-7 into monitoring well MW-6. No MTBE was detected in any soil samples (Table 2). SPH was detected in wells MW-1, MW-2, MW-3 and TMW-5, and 4.5 gallons of SPH was removed by hand bailing from the monitoring wells (Table 4). MTBE was not detected in any groundwater samples. Sequoia reported groundwater flow to the west-southwest during this assessment.

May 2003: Cambria completed a conduit study to evaluate the potential for subsurface utility conduits to serve as preferential pathways for hydrocarbon migration. The depth to nearby utilities ranged from approximately 3 to 18 feet bgs. Site groundwater has historically fluctuated between approximately 6.5 and 17 feet bgs.

Groundwater Monitoring: Groundwater monitoring of site wells was conducted on a quarterly basis between August 1991 and December 1999, and only once in 2001 and 2002. Quarterly



monitoring events were initiated again in March of 2003. Groundwater elevation and analytical data is summarized in Table 2 and presented in Figure 3.

4.0 PREVIOUS SITE REMEDIATION

In August 1988, SCS removed four USTs, two dispensers and associated piping from the site (Figure 2). Several remedial activities have been conducted since the USTs were removed.

4.1 Soil Excavation



December 1994 through October 1996: Tank Protect conducted multiple phases of soil excavation and verification sampling at the site. As shown on Figure 2, the soil excavation was conducted around the UST area in the center of the site. The depth of the soil excavation ranged from 12 feet to 19 feet bgs. A total of 1,550 cubic yards (cy) of soil was removed. Approximately 1,019 cy of the excavated soil was stockpiled on site, remediated via aeration and hydrogen peroxide treatment, and placed back into the excavation cavity with the approval of the ACHCSA. Approximately 531 cy of soil was removed from the site and disposed of at a licensed disposal facility. The final verification soil sampling indicated a maximum TPHg concentration of 110 milligrams per kilogram (mg/kg) from the UST sidewall, and 66 mg/kg from the excavation bottom.

4.2 SPH Removal

Due to the presence of SPH in site wells, Tank Protect installed a free product recovery system and bailed site wells during groundwater monitoring events. Groundwater monitoring and sampling results and SPH thickness information is presented in Table 3.

The free product removal system first consisted of a selective oil skimmer, down-well mounted bladder product pump, and two product storage drums. Tank Protect reported that trace quantities of free product were removed during between July 27 and August 18, 1995. To enhance free product recovery, Tank Protect installed a continuously operating free product recovery system in August 1997. Tank Protect reported removing 3 to 5 gallons of SPH between August 20, 1997 and January 14, 1998. SPH removal by manual bailing has been conducted by Cambria since October 2002 (Table 4).

4.3 Bio-Remediation System

A bio-remediation system was installed and operated at the site by Sequoia between March 2002 and July 2002. According to Sequoia, this system pumped water from four wells (MW-1, MW-2, MW-3, and TMW-5) into four "bioreactor" tanks containing microbes, nutrients, and hydrogen peroxide. The treated, microbe-rich water was then injected into the subsurface through an infiltration well (MW-1). Monthly project updates submitted by Sequoia do not provide detailed information about system layout, startup, or operation. Between March 2002 and July 2002, four bio-treatment events were reported where treated, microbe-rich water was injected into well MW-1. The system was shut down and removed in July 2002. Groundwater samples collected by Sequoia on June 20, 2002 after the initiation of bio-remediation activities were generally consistent with historical groundwater hydrocarbon concentration levels.



4.4 Vacuum Truck Operations

Vacuum truck operations were conducted by Sequoia on July 20, 2002 as an interim remedial measure. Vacuum truck operations were performed to remove the SPH found in wells MW-2, MW-3, and TMW-5. Details are not available describing the length of vacuum truck operations or amount of SPH and groundwater recovered.

5.0 PROPOSED SCOPE OF WORK

5.1 Objective

The primary objective of the proposed scope of work is to define the extent of the SPH and dissolved-phase hydrocarbon plumes. A *Feasibility Test Work Plan* will be prepared following the submittal of this *Site Assessment Work Plan*.

Cambria is proposing the reconstruction of three existing wells (MW-1, MW-3, and TMW-4) because they are screened across two water-bearing zones. Each well will be over-drilled and replaced with a shallower well with an appropriate screen interval within the same boring. The reconstructed wells (MW-1a, MW-3a, and TMW-4a) will assist with site assessment and feasibility testing (Figure 4).

Cambria is also proposing the installation of six offsite monitoring wells. Two monitoring wells will be installed in Miller Avenue to delineate the plume to the south and east and to determine if the storm drain is influencing plume migration. Two monitoring wells will be installed along

International Boulevard to delineate the plume to the north and northeast. And two monitoring wells will be installed on neighboring properties to delineate the plume to the northwest and west. See Figure 4 for the proposed monitoring well locations.

5.2 Site Health and Safety Plan

A comprehensive site safety plan will be prepared to protect site workers. The plan will be kept onsite during all field activities and signed by each site worker.



5.3 Permits

Drilling permits will be obtained from the Alameda County Public Works Agency, and an encroachment permit will be obtained from the City of Oakland Community and Economic Development Agency, as needed.

5.4 Off-Site Access

Off-site access agreements will be obtained, as necessary, prior to the installation of the monitoring wells proposed offsite to the west and northwest.

5.5 Utility Clearance

The proposed drilling locations will be marked and Underground Service Alert will be notified of Cambria's activities. A private subsurface utility locating contractor will be used to identify any conflicting subsurface utilities and each location will be cleared by hand auger or air knife prior to drilling.


5.6 Soil Sampling and Analysis

During drilling, soil samples will be collected at 5-foot intervals to the total depth of approximately 26 feet bgs (15 feet below first-encountered groundwater). Soil samples may be collected continuously from 15 to 25 feet bgs to assist with determining the top of the upper water-bearing zone. Field screening of hydrocarbons and volatile organic compounds will include visual and olfactory observations, and/or photo-ionization detector (PID) readings. See Appendix B for Cambria's standard procedures for soil sampling. Select soil samples will be analyzed for TPHg by modified EPA Method 8015, and benzene, toluene, ethylbenzene, and toluene (BTEX) and MTBE by EPA method 8021B. Samples will be submitted to a California-certified analytical

laboratory for analysis. Soil samples will not be collected during the reconstruction of wells MW-1, MW-3, and TMW-4.

5.7 Monitoring Well Reconstruction / Installation

Cambria will reconstruct the three onsite monitoring wells (MW-1, MW-3, and TMW-4) by over-drilling the 2-inch diameter wells with 10-inch diameter hollow-stem augers. Over-drilling will be conducted by inserting a pilot drill bit down the center of the well to help guide the augers as they drill out the well. After the total depth of the well is removed, the bottom 5 to 10 feet will be filled with bentonite chips, and new 4-inch diameter, 0.010-inch slotted, PVC well casing will be installed. The reconstructed wells will be screened from approximately 12 to 27 feet. A filter pack consisting of No. 2/12 sand will be installed to 6 inches above the top of the well screen, overlain by one foot of bentonite, and the remaining annulus filled with bentonite-cement grout to the surface. Each well will be protected by a traffic-rated vault and a locking well cap. Cambria's Standard Field Procedures for Soil Borings and Monitoring Wells is included as Appendix B.



5.8 Well Development

Cambria will develop the wells by surge block agitation and evacuation. Groundwater evacuation will continue until approximately ten well-casing volumes of water have been removed or the turbidity of water has been significantly reduced.



5.10 Monitoring Well Sampling and Analysis

Following well development activities, Cambria will monitor and sample all site wells, including the newly installed wells as part of a quarterly groundwater monitoring event. See Appendix B for Cambria's standard procedures for groundwater sampling. Groundwater samples will be analyzed for TPHg by modified EPA Method 8015, and BTEX by EPA method 8021B, with confirmation analysis for any MTBE concentrations by EPA Method 8260. Groundwater samples will be submitted to a California-certified analytical laboratory for analysis.



5.11 Investigation Derived Waste (IDW)

Investigation derived waste (IDW) generated during field activities will be temporarily stored onsite. Following review of analytical results and disposal profiling, the IDW will be transported to an appropriate facility for disposal/recycling.

6.0 REPORTING

Cambria will prepare and submit a *Site Assessment Report* to the ACHCSA detailing the findings of the above investigation phases. At a minimum, this report will contain:

- The findings and conclusions of the plume delineation activities;
- Descriptions of the soil boring/monitoring well installation methods;
- Descriptions of the soil and groundwater sampling methods;
- Figures depicting the lateral extent of the hydrocarbon plume and groundwater flow direction;
- Tabulated soil and groundwater analytical results;
- Boring logs and well construction diagrams for the soil borings and monitoring wells;
- Updated hydrogeological cross sections;
- Analytical reports and chain-of-custody forms; and
- Soil and groundwater disposal methods.


7.0 SCHEDULE

Upon receiving written work plan approval from the ACHCSA, Cambria will prepare a project budget and obtain client approval of the proposed activities. Cambria anticipates completing the planned investigation and report within approximately 12 to 14 weeks, however, off-site access agreements could delay the proposed activities.

H:\Wong (Credit Auto), Oakland\Site Assessment Work Plan\Site Assessment Work Plan.doc



Figures




Credit World Auto Sales

2345 E. 14th Street Oakland, California




Vicinity Map



2345 International Boulevard Oakland, California

Credit World Auto Sales



● SB-4 (1997)

Restaurant with Second Floor

Apartments,

® TH-4

office

SB-2(1997)

SB-5 (2001)

SB-3 (2001)

SB-3 ③ (1997)

/ gate ×

former USTs

Phone save C. S. Carriel

SB-6 (2001)

TMW-4 •

TH-2 ®

⊚ SB-1 (1997)

SB-1 (2001)

B-2

TMW-5

fenceline

→ MW-1

SB-7/MW-6

TH-5 ®

B-1 @

SB-2 ® (2001)

building

grass

⊚TH-3

garage

former waste

B-3 ⊚

◆ MW-3

building

oil UST

\$B-5 **●**

(1997)

asphalt

SB-4 (2001)

lot

+

asphalt

+

building

Residence

building

EXPLANATION

Proposed monitoring well location

MW-1 - Monitoring well location

Electrical line

Storm drain

Water line

Gas line

Flow direction

Sanitary sawer

Phone and utility services

(75") Known conduit diameter in parenthesis

Approximate limits of excavation Paved Parking

Scale (ft)

Flow line elevation for sanitary sewer and storm drain, City of Oakland datum

SB-1

Soil boring location



Credit World Auto Sales

FIGURE

2345 International Boulevard Oakland, California

O



Tables

Table 1. Well Completion Data - Credit World Auto Sales, 2345 International Boulevard, Oakland, California

Well No.	Installation Date	Boring Diameter (inches)	Well Diameter (inches)	Screen Size (inches)	Total Depth (feet bgs)	Surface Seal (feet bgs)	Sand Pack Interval (feet bgs)	Screened Interval (feet bgs)	First Encountered GW Depth (feet bgs)	Static GW Depth (feet bgs/date)
MW -1	5/22/1991	8	2	0.010	35	0-12	12-35	15-35	17.5	15.42 (8/23/91)
MW-2	8/21/1991	.8	2	0.010	35	0-12	12-35	15-35	17.5	13.77 (8/23/91)
MW-3	8/22/1991	8	2	0.010	35	0-12	12-35	15-35	19.0	15.07 (8/23/91)
TMW-4	7/22/1993	8	2	0.010	36	0-12	12-34	14-34	~17	13.26 (8/17/93)
TMW-5	7/23/1993	8	2	0.010	27	0-15	15-24	17-24	~18	12.98 (8/17/93)
MW-6	5/22/2001	6.75	4	0.020	20	0-13	13-20	15-20	~20	12.47 (5/23/01)

bgs = below ground surface

GW = groundwater

Table 2. Soil Analytical Data - Credit World Auto Sales 2345 International Boulevard, Oakland, California

Sample Location	Date Sampled	Depth (feet)	TPHg (mg/kg)	TPHd (mg/kg)	TOG (mg/kg)	Benzene (mg/kg)	Toluene (mg/kg)	Ethylbenzene (mg/kg)	Xylenes (mg/kg)	MTBE (mg/kg)		HVOCs (mg/kg)
SCS Engineers (UST Removal	Sampling)										
B-1	8/25/1988	15	360			0.3	2.2	3.4	31			
B-2	8/25/1988	15	1,500			3.0	6.4	2.5	160			
B-3	8/25/1988	15	130			0.17	0.4	1.3	10			
B-4	8/25/1988		150			0.8	1.9	8.7	86			
B-5	8/25/1988		790			61	1.3	4.8	30			
B-6	8/25/1988		1,300			1.5	4.7	9.6	75			
B-7	8/25/1988		·	110	570	(<5.0)	(<5.0)	(5.0)	(48)		ND*	
B-8	8/25/1988			65	780	(<5.0)	(<5.0)	(5.0)	(12)		ND*	
California Enviro	nmental Cons	ultants										
B-1	10/3/1988	15	3.4			0.31	< 0.1	< 0.1	0.14			
B-2	10/3/1988	15	83			1.6	1.1	1.8	9.6			
B-3	10/3/1988	15			88	(0.36)	(0.65)	(0.47)	(0.85)		ND*	ND
Earth Systems Er	nvironmental											
TH-1	8/21/1991	15-15.5	2,775			1.235	1.060	1.625	5.280			
TH-2	8/21/1991	10-10.5	360			< 0.005	< 0.005	< 0.005	0.770			
TH-2	8/21/1991	29.5-30	50			< 0.005	< 0.005	< 0.005	< 0.005			
TH-3	8/22/1991	10-10.5	10		60	< 0.005	< 0.005	< 0.005	< 0.005			
TH-3	8/22/1991	18.5-19	10		20	< 0.005	< 0.005	< 0.005	< 0.005			
TH-4	8/22/1991	10-10.5	25		40	< 0.005	< 0.005	< 0.005	0.175			
TH-4	8/22/1991	19.5-20	450		1,600	< 0.005	< 0.005	< 0.005	< 0.005			
TH-5	8/22/1991	10-10.5	10			< 0.005	< 0.005	< 0.005	< 0.005			
TH-5	8/22/1991	18-18.5	<5.0			< 0.005	< 0.005	< 0.005	< 0.005			
MW-1	5/22/1991	10-10.5	150			0.460	0.365	0.305	0.960			
MW-1	5/22/1991	15-15.5	255			1.505	4.255	4.015	4.270			
MW-2	8/21/1991	10-10.5	4,320			7.275	6.620	3.470	13.815			
MW-2	8/21/1991	15-15.5	160			< 0.005	< 0.005	< 0.005	< 0.005			
MW-3	8/22/1991	10-10.5	50		90	< 0.005	< 0.005	< 0.005	< 0.005			
MW-3	8/22/1991	15-15.5	25		40	< 0.005	< 0.005	< 0.005	< 0.005			

Table 2. Soil Analytical Data - Credit World Auto Sales2345 International Boulevard, Oakland, California

Sample Location	Date Sampled	Depth (feet)	TPHg (mg/kg)	TPHd (mg/kg)	TOG (mg/kg)	Benzene (mg/kg)	Toluene (mg/kg)	Ethylbenzene (mg/kg)	Xylenes (mg/kg)	MTBE (mg/kg)	VOCs (mg/kg)	HVOCs (mg/kg)
ank Protect Eng	ineering											
TMW-4	7/22/1993	5.5-6	< 0.500			< 0.0050	< 0.0050	< 0.0050	< 0.015			
TMW-4	7/22/1993	10.5-11	< 0.500			< 0.0050	< 0.0050	< 0.0050	< 0.015			
TMW-4	7/22/1993	15.5-16	0.940			< 0.0050	< 0.0050	< 0.0050	< 0.015			
TMW-5	7/23/1993	5.5-6	2.4			0.026	< 0.0050	< 0.0050	0.053			
TMW-5	7/23/1993	10.5-11	14			0.900	< 0.0050	1.6	< 0.140			
TMW-5	7/23/1993	15.5-16	16			0.840	< 0.0050	0.690	1.3			
SB-1	4/21/1997	26.5-27	<1.0			< 0.005	< 0.005	< 0.005	< 0.005	< 0.05		
SB-2	4/21/1997	16.5-17	3.7			0.012	0.0071	0.042	< 0.005	< 0.05		
SB-3	5/1/1997	21.5-22	<1.0			< 0.005	< 0.005	< 0.005	< 0.005	< 0.05		
SB-4	5/1/1997	21.5-22	<1.0			< 0.005	< 0.005	< 0.005	< 0.005	< 0.05		
SB-5	5/1/1997	11.5-12	91			<0.005	< 0.005	< 0.005	<0.005	<0.05		
equoia Environn	ental									4		
SB-1	5/22/2001	10	2 40			< 0.04	0.19	0.19	0.45	< 0.20		
SB-1	5/22/2001	15	3.0			< 0.005	0.005	0.009	0.013	< 0.05		
SB-2	5/22/2001	10	89			< 0.005	< 0.005	0.033	0.25	< 0.10		
SB-2	5/22/2001	15	<1.0			< 0.005	< 0.005	< 0.005	< 0.005	< 0.05		
SB-2	5/22/2001	20	<1.0			< 0.005	< 0.005	< 0.005	< 0.005	< 0.05		
SB-3	5/22/2001	10	300			< 0.01	< 0.01	0.76	1.2	< 0.20		
SB-3	5/22/2001	15	1,800			3.3	5.5	48	53	<2.0		
SB-3	5/22/2001	20	8.5			0.009	0.023	0.10	0.12	< 0.05		
SB-4	5/22/2001	10	<1.0			< 0.005	< 0.005	< 0.005	< 0.005	< 0.05		
SB-4	5/22/2001	15	230			0.23	< 0.005	1.5	1.1	< 0.10		
SB-4	5/22/2001	20	<1.0			< 0.005	< 0.005	< 0.005	< 0.005	< 0.05		
SB-5	5/22/2001	15	25			0.035	< 0.005	0.10	0.11	< 0.05		
SB-5	5/22/2001	20	1.9			0.62	< 0.005	< 0.005	< 0.005	< 0.05		
SB-6	5/22/2001	10	<1.0			< 0.005	< 0.005	< 0.005	< 0.005	<0.05		
SB-7 (MW-6)	5/22/2001	10	18			< 0.005	< 0.005	0.056	0.11	< 0.05		
SB-7 (MW-6)	5/22/2001	15	68			0.28	0.25	0.36	0.35	< 0.10		
SB-7 (MW-6)	5/22/2001	20	<1.0			< 0.005	< 0.005	< 0.005	< 0.005	< 0.05		

Table 2.

Soil Analytical Data - Credit World Auto Sales

2345 International Boulevard, Oakland, California

Sample	Date	Depth	TPHg	TPHd	TOG	Benzene	Toluene	Ethylbenzene	Xylenes	MTBE VO	Cs HVOCs
Location	Sampled	(feet)	(mg/kg)	(mg/kg)	(mg/kg)	(mg/kg)	(mg/kg)	(m g/kg)	(mg/kg)	(mg/kg) (mg	/kg) (mg/kg)

Abbreviations and Notes:

1,300 = concentrations exceeding commercial final RBSLs shown in bold.

TPHg = Total petroleum hydrocarbons as gasoline

Benzene, Toluene, Ethylbenzene, Xylenes by EPA Method 8020, and by 8260 if in parenthesis

MTBE methyl tert butyl ether by EPA Method 8020

VOCs = volatile organic compounds by EPA Method 8260

ND = not detected above laboratory detection limits

ND* = not detected with the exception of reported concentrations for benzene, toluene, ethylbenzene and xylenes

HVOCs = halogenated volatile organic compounds by EPA Method 8010

mg/kg = Milligrams per kilogram

<n = Below detection limit of n mg/kg

-- = Not analyzed

Residential RBSLs = Table B-1 - Risk Based Screening Level Components for Surface Soil (Potentially Impacted Groundwater is not a Current or Potential Source

of Drinking Water) for commercial/industrial reuse for established by the SFBRWQCB, Interim Final December 2001. (The risk driver is also shown). MTBE RBSL for coarse soil (fine soil).

Commercial RBSLs = Table B-2 - Risk Based Screening Level Components for Surface Soil (Potentially Impacted Groundwater is not a Current or Potential Source

of Drinking Water) for commercial/industrial reuse for established by the SFBRWQCB, Interim Final December 2001. (The risk driver is also shown). MTBE RBSL for coarse soil (fine soil).

RBSLs for indoor air = Tables B-1 and B-2 from SFBRWQCB above, Interim Final December 2001

Table 3. Groundwater Elevation and Analytical Data - Credit World Auto Sales, 2345 International Boulevard, Oakland, California

Well ID FOC	Date Sampled	Depth to GW (ft)	SPH Thickness (ft)	GW Elevation (ft)	TPHg (µg/L)	Benzene (µg/L)	Toluene (μg/L)	Ethylbenzene (µg/L)	Xylenes (μg/L)	MTBE (µg/L)
MW-1	12/30/1997	10.96	0.17	16.51	61,000	4,300	1,800	1,600	6,900	1,400
100.000°	3/24/1998	9.33	0.00	18.00	24,000	1,000	1,000	1,300	4,300	2,000
27.33 ^b	6/29/1998	12.20	0.00	15.13	130,000	3,800	370	1,200	4,200	3,300
	10/2/1998	13.46	0.00	13.87	22,000	66	21	26	140	<0.50
	12/10/1998	10.49	0.00	16.84	32,000	4,600	970	1,700	4,900	<250
	3/26/1999	9.44	0.00	17.89	230,000	370	290	280	720	< 0.50
	6/11/1999	12.56	0.01	14.78	180,000	210	170	220	400	< 0.50
	9/15/1999	14.85	1.00	13.28	21,000	3,800	280	590	2,200	<250
	12/28/1999	14.50	1.32	13.89	27,000	48	36	46	83	<0.5
	6/13/2001	15.83	4.36	12.03						
	12/27/2002	8.31	0.16	16.19			**			
	3/23/2003	10.65	0.05	16.72			-			
	5/29/2003	12.11	0.28	15.44			~			
	9/26/2003	12.84	0.29	14.72						
	12/4/2003	12.50	0.10	14.91	~					٠
MW-2	8/23/1991	13.77	0.00	84.82	10,000	<5	<5	<5	<5	***
98.585	4/16/1992	15.38	2.81	12.79				-		
25.92 b	6/11/1993	13.19	0.00	12.74						
	8/17/1993	14.04	0.01	11.89	49,000	94	240	250	980	
	3/28/1994	13.61	0.54	12.74	14,000	4,200	<250	910	1,400	
	6/27/1994	14.24	0.80	12.32	24,000	4,400	72	1,100	1,700	
	9/16/1994	17.82	4.46	11.67	40,000	2,300	250	2,000	4,100	
	3/31/1995	16.72	7.44	15.15	28,000	4,000	<120	1,100	1,400	
	6/28/1995	13.50	0.73	13.00	40,000	2,700	130	1,700	2,900	
	9/28/1995	14.63	0.54	11.72	7,500	420	14	250	190	<62
	12/26/1995	12.58	0.90	14.06	22,000	1,300	88	950	1,800	<250
	3/22/1996	11.46	0.15	14.58	9,800	2,200	<120	400	<380	<1,200
	6/20/1996	13.08	0.37	13.14	35,000	770	<0.50	240	<0.50	550
	9/30/1996	16.67	3.75	12.25	58,000	1,600	230	2,200	4,000	<5.0
	12/27/1996	15.74	7.57	16.24	29,000	2,100	<0.50	1,200	1,800	<5.0
	3/7/1 9 97	12.55	0.00	13.37	13,000	1,300	37	290	180	<5.0
	6/28/1997	11.98	0.04	13.97	12,000	840	< 0.50	640	360	<5.0
	9/18/1997	13.44	0.00	12.48	12,000	680	<0.50	320	84	<5.0
	12/30/1997	11.31	0.00	14.61	13,000	1,100	40	350	220	<5.0
	3/25/1998	10.02	0.00	15.90	8,100	1,300	51	410	230	670
	6/29/1998	11.96	0.00	13.96	12,000	880	13	180	72	430

Table 3. Groundwater Elevation and Analytical Data - Credit World Auto Sales, 2345 International Boulevard, Oakland, California

Well ID TOC	Date Sampled	Depth to GW (ft)	SPH Thickness (ft)	GW Elevation (ft)	TPHg (µg/L)	Benzene (µg/L)	Toluene (µg/L)	Ethylbenzene (µg/L)	Xylenes (µg/L)	MTBE (µg/L)
MW-2	10/2/1998	13.74	0.00	12.18	47,000	140	100	110	200	<0.50
(cont'd)	12/10/1998	12.91	2.10	14.69	26,000	1,000	210	1,500	1,900	<1,000
	3/26/1999	9.06	0.20	17.02	110,000	190	150	120	380	<0.50
	6/11/1999	12.18	0.00	13.74	190,000	310	250	320	540	<0.50
	9/15/1999	15.59	3.00	12.73	25,000	720	<100	1,300	1,600	<1,000
	12/28/1999	16.81	4.50	12.71	75,000	130	98	130	230	< 0.50
	6/13/2001	14.84	3.15	10.84				-		
	6/20/2002	14.80	0.70	8.92	53,000	2,200	140	3,300	3,000	<1,000
	10/21/2002	16.98	0.24	6.37						
	12/27/2002	13.58	0.43	9.92						
	3/23/2003	15.49	0.29	10.66				**		
	5/29/2003	16.08	0.44	10.19						
	9/26/2003	17.14	0.87	9.48		**				
	12/4/2003	16.75	1.01	9.98					••	
MW-3	8/23/1991	15.07	0.00	84.18	<5,000	ব	<5	<5	<5	
99.25 °	4/16/1992	14.14	0.16	13.56		_				
27.57 ^b	6/11/1993	14.28	0.00	13.30						
	8/17/1993	15.77	0.00	11.80	9,600	4.1	17	28	54	
	3/28/1994	14.35	0.00	13.22	8,400	2,400	56	67	200	
	6/27/1994	14.77	0.00	12.80	9,900	3,300	<22	<25	73	
	9/16/1994	15.42	0.05	12.19	16,000	2,300	80	620	240	
	3/31/1995	12.98	0.46	14.96	16,000	2,800	70	<25	920	
	6/28/1995	14.20	0.05	13.41	11,000	2,300	32	81	240	
	9/28/1995	15.17	0.00	12.40	6,300	1,900	<42	200	<120	<420
	12/26/1995	13.33	0.06	14.29	25,000	3,800	97	94	1,600	<250
	3/22/1995	12.81	0.04	14.79	16,000	3,100	75	69	350	250
	6/20/1996	13.95	0.07	13.68	8,500	1,400	28	140	15	220
	9/24/1996	14.86	0.04	12.74	12,000	2,400	87	340	110	<5.0
	12/27/1996	11.04	0.06	16.58	5,800	1,700	28	<0.50	42	240
	3/10/1997	13.80	0.00	13.77	9,000	1,700	<0.50	110	<0.50	<5.0
	6/28/1997	13.72	0.06	13.90	15,000	2,200	<0.50	160	190	<5.0
	9/18/1997	14.76	0.00	12.81	28,000	3,800	< 0.50	100	<0.50	<5.0
	12/30/1997	12.97	0.00	14.60	21,000	2,200	< 0.50	31	<0.50	300
	3/24/1998	11.75	0.00	15.82	2,300	870	7.2	20	< 0.50	85
	6/29/1998	13.38	0.00	14.19	6,500	1,300	12	62	14	140
	10/2/1998	14.42	0.00	13.15	11,000	31	27	35	69	<0.50

Table 3. Groundwater Elevation and Analytical Data - Credit World Auto Sales, 2345 International Boulevard, Oakland, California

Well ID TOC	Date Sampled	Depth to GW (ft)	SPH Thickness (ft)	GW Elevation (ft)	TPHg (µg/L)	Benzene (µg/L)	Toluene (µg/L)	Ethylbenzene (µg/L)	Xylenes (μg/L)	MTBE (µg/L)
MW-3	12/10/1998	12.55	0.00	15.02	<2,500	2,800	68	42	55	-250
	3/26/1999	10.54	0.00	17.03	10,000	2,800 21	14	42 10		<250
(cont'd)	6/15/1999	13.91	0.00			90			41	< 0.50
	9/15/1999	14.70	0.00	13.66 12.87	87,000 8,700		71 71	92 110	180	<0.50
	12/28/1999	15.16	0.00	12.87	4,300	2,100 7.7	5.2	7.2	66	<100
	6/13/2001								13	<0.50
		14.70	0.40	13.19	8,400	1,300	25	64	32	<20
	6/20/2002	14.68	0.02	12.91	7,800	1,100	23	66	15	<50
	12/27/2002	11.37	0.17	16.34		-				
	3/23/2003									
	5/29/2003	13.99	0.08	13.64		**		==		
	9/26/2003	14.51	0.05	13.10			-			
	12/4/2003	14.28	0.10	13.37	-				-	••
TMW-4	8/17/1993	13.26	0.00	13.24	150	<0.50	0.8	1.4	3.7	
26.50 ^b	3/28/1994	12.40	0.00	14.10	<50	< 0.50	< 0.50	< 0.50	<1.5	
	6/27/1994	12.84	0.00	13.66	<50	< 0.50	<0.50	< 0.50	<1.5	
	9/16/1994	13.58	0.00	12.92	<50	< 0.50	<0.50	<0.50	<1.5	
	3/31/1995	10.23	0.00	16.27	<50	< 0.50	< 0.50	< 0.50	<1.5	
	6/28/1995	12.21	0.00	14.29	<50	< 0.50	<0.50	<0.50	<1.5	
	9/28/1995	13.38	0.00	13.12	<50	< 0.50	< 0.50	<0.50	<1.5	<5.0
	12/26/1995	11.32	0.00	15.18	<50	<0.50	< 0.50	<0.50	<1.5	<5.0
	3/22/1996	10.54	0.00	15.96	<50	< 0.50	< 0.50	< 0.50	<1.5	<5.0
	6/20/1996	12.14	0.00	14.36	<50	< 0.50	< 0.50	<0.50	< 0.50	<5.0
	9/24/1996	13.01	0.00	13.49	<50	<0.50	<0.50	< 0.50	<0.50	<5.0
	12/27/1996	9.51	0.00	16.99	<50	<0.50	<0.50	<0.50	<0.50	<5.0
	3/10/1997	11.92	0.00	14.58	<50	<0.50	<0.50	<0.50	<0.50	<5.0
	6/27/1997	10.70	0.00	15.80	<50	<0.50	<0.50	<0.50	<0.50	<5.0
	9/18/1997	12.94	0.00	13.56	<50	<0.50	<0.50	<0.50	<0.50	<5.0
	12/30/1997	10.92	0.00	15.58	<50	<0.50	<0.50	<0.50	<0.50	<5.0
	3/25/1998	9.60	0.00	16.90	<50	<0.50	<0.50	<0.50	<0.50	<5.0
	6/29/1998	11.32	0.00	15.18	<50	<0.50	<0.50	<0.50	<0.50	<5.0
	10/2/1998	12.56	0.00	13.94	<50	<0.50	<0.50	<0.50	<0.50	<0.50
	12/10/1998	10.44	0.00	16.06	<50	<0.50	<0.50	<0.50	<0.50	< 0.50
	3/26/1999	9.38	0.00	17.12	<50	<0.50	<0.50	<0.50	<0.50	<0.50
	6/15/1999	11.58	0.00	14.92	<50	<0.50	<0.50	<0.50	<0.50	<0.50
	9/15/1999	12.89	0.00	13.61	· <50	<0.50	<0.50	<0.50	<0.50	<5.0
	12/28/1999	12.92	0.00	13.58	<50	<0.50	<0.50	<0.50	<0.50	<0.50

Table 3. Groundwater Elevation and Analytical Data - Credit World Auto Sales, 2345 International Boulevard, Oakland, California

Well ID TOC Date Sampled Depth to GW (ft) SPH (ft) GW (ft) TPHg (ft) Benzene (μg/L) Toluene (μg/L) TMW-4 10/21/2002 12.70 0.00 13.80 (cont'd) 12/27/2002 9.07 0.12 17.53 - 5/29/2003 10.73 0.03 15.79 - 9/26/2003 13.27 0.06 13.28 - 12/4/2003 13.07 0.10 13.51 - - TMW-5 8/17/1993 12.98 0.03 13.55 120,000 640 730 26.51b 3/28/1994 11.39 0.00 15.12 70,000 23,000 1,500 9/16/1994 13.02 0.05 13.53 96,000 26,000 940 9/16/1994 13.02 0.05 13.53 96,000 17,000	(μg/L) 790	Xylenes (μg/L) 	MTBE (μg/L)
(cont'd) 12/27/2002 9.07 0.12 17.53 — — — 3/23/2003 10.73 0.03 15.79 — — — 5/29/2003 12.50 0.02 14.02 — — — 9/26/2003 13.27 0.06 13.28 — — — 12/4/2003 13.07 0.10 13.51 — — — TMW-5 8/17/1993 12.98 0.03 13.55 120,000 640 730 26.51 ^b 3/28/1994 11.39 0.00 15.12 70,000 23,000 1,500 6/28/1994 12.24 0.00 14.27 56,000 26,000 940 9/16/1994 13.02 0.05 13.53 96,000 17,000 720 3/31/1995 7.38 0.00 19.13 64,000 13,000 470 6/28/1995 11.31 0.06 15.25 65,000 9,000 240 <	 790	 	
(cont'd) 12/27/2002 9.07 0.12 17.53 — — — 3/23/2003 10.73 0.03 15.79 — — — 5/29/2003 12.50 0.02 14.02 — — — 9/26/2003 13.27 0.06 13.28 — — — 12/4/2003 13.07 0.10 13.51 — — — TMW-5 8/17/1993 12.98 0.03 13.55 120,000 640 730 26.51 ^b 3/28/1994 11.39 0.00 15.12 70,000 23,000 1,500 6/28/1994 12.24 0.00 14.27 56,000 26,000 940 9/16/1994 13.02 0.05 13.53 96,000 17,000 720 3/31/1995 7.38 0.00 19.13 64,000 13,000 470 6/28/1995 11.31 0.06 15.25 65,000 9,000 240 <	 790	 	
3/23/2003 10.73 0.03 15.79 —	 790	 	
5/29/2003 12.50 0.02 14.02 9/26/2003 13.27 0.06 13.28 12/4/2003 13.07 0.10 13.51 TMW-5 8/17/1993 12.98 0.03 13.55 120,000 640 730 26.51b 3/28/1994 11.39 0.00 15.12 70,000 23,000 1,500 6/28/1994 12.24 0.00 14.27 56,000 26,000 940 9/16/1994 13.02 0.05 13.53 96,000 17,000 720 3/31/1995 7.38 0.00 19.13 64,000 13,000 470 6/28/1995 11.31 0.06 15.25 65,000 9,000 240 9/28/1995 14.42 0.00 12.09 79,000 17,000 1,800 12/26/1995 10.16 0.05 16.39 110,000 11,000 800	 790	 	
9/26/2003 13.27 0.06 13.28	 790		
TMW-5 8/17/1993 12.98 0.03 13.55 120,000 640 730 26.51b 3/28/1994 11.39 0.00 15.12 70,000 23,000 1,500 6/28/1994 12.24 0.00 14.27 56,000 26,000 940 9/16/1994 13.02 0.05 13.53 96,000 17,000 720 3/31/1995 7.38 0.00 19.13 64,000 13,000 470 6/28/1995 11.31 0.06 15.25 65,000 9,000 240 9/28/1995 14.42 0.00 12.09 79,000 17,000 1,800 12/26/1995 10.16 0.05 16.39 110,000 11,000 800 3/22/1996 7.59 0.05 18.96 6/26/1996 ^d 7.12 0.00 30,000 4,000 180 9/30/1996 7.42 0.00 6,900 1,600 79 <	 790		
TMW-5 8/17/1993 12.98 0.03 13.55 120,000 640 730 26.51b 3/28/1994 11.39 0.00 15.12 70,000 23,000 1,500 6/28/1994 12.24 0.00 14.27 56,000 26,000 940 9/16/1994 13.02 0.05 13.53 96,000 17,000 720 3/31/1995 7.38 0.00 19.13 64,000 13,000 470 6/28/1995 11.31 0.06 15.25 65,000 9,000 240 9/28/1995 14.42 0.00 12.09 79,000 17,000 1,800 12/26/1995 10.16 0.05 16.39 110,000 11,000 800 3/22/1996 7.59 0.05 18.96 6/26/1996 7.12 0.00 30,000 4,000 180 9/30/1996 7.42 0.00 6,900 1,600 79	790	••	
26.51b 3/28/1994 11.39 0.00 15.12 70,000 23,000 1,500 6/28/1994 12.24 0.00 14.27 56,000 26,000 940 9/16/1994 13.02 0.05 13.53 96,000 17,000 720 3/31/1995 7.38 0.00 19.13 64,000 13,000 470 6/28/1995 11.31 0.06 15.25 65,000 9,000 240 9/28/1995 14.42 0.00 12.09 79,000 17,000 1,800 12/26/1995 10.16 0.05 16.39 110,000 11,000 800 3/22/1996 7.59 0.05 18.96 6/26/1996 7.12 0.00 30,000 4,000 180 9/30/1996 7.42 0.00 6,900 1,600 79			
6/28/1994 12.24 0.00 14.27 56,000 26,000 940 9/16/1994 13.02 0.05 13.53 96,000 17,000 720 3/31/1995 7.38 0.00 19.13 64,000 13,000 470 6/28/1995 11.31 0.06 15.25 65,000 9,000 240 9/28/1995 14.42 0.00 12.09 79,000 17,000 1,800 12/26/1995 10.16 0.05 16.39 110,000 11,000 800 3/22/1996 7.59 0.05 18.96 6/26/1996 7.12 0.00 30,000 4,000 180 9/30/1996 7.42 0.00 6,900 1,600 79		3,600	
9/16/1994 13.02 0.05 13.53 96,000 17,000 720 3/31/1995 7.38 0.00 19.13 64,000 13,000 470 6/28/1995 11.31 0.06 15.25 65,000 9,000 240 9/28/1995 14.42 0.00 12.09 79,000 17,000 1,800 12/26/1995 10.16 0.05 16.39 110,000 11,000 800 3/22/1996 7.59 0.05 18.96 6/26/1996 7.12 0.00 30,000 4,000 180 9/30/1996 7.42 0.00 6,900 1,600 79	4,100	15,000	
3/31/1995 7.38 0.00 19.13 64,000 13,000 470 6/28/1995 11.31 0.06 15.25 65,000 9,000 240 9/28/1995 14.42 0.00 12.09 79,000 17,000 1,800 12/26/1995 10.16 0.05 16.39 110,000 11,000 800 3/22/1996 7.59 0.05 18.96 6/26/1996 7.12 0.00 30,000 4,000 180 9/30/1996 7.42 0.00 6,900 1,600 79	5,500	26,000	
6/28/1995 11.31 0.06 15.25 65,000 9,000 240 9/28/1995 14.42 0.00 12.09 79,000 17,000 1,800 12/26/1995 10.16 0.05 16.39 110,000 11,000 800 3/22/1996 7.59 0.05 18.96 6/26/1996 7.12 0.00 30,000 4,000 180 9/30/1996 7.42 0.00 6,900 1,600 79	3,500	12,000	
9/28/1995 14.42 0.00 12.09 79,000 17,000 1,800 12/26/1995 10.16 0.05 16.39 110,000 11,000 800 3/22/1996 7.59 0.05 18.96 6/26/1996 7.12 0.00 30,000 4,000 180 9/30/1996 7.42 0.00 6,900 1,600 79	3,500	6,100	
12/26/1995 10.16 0.05 16.39 110,000 11,000 800 3/22/1996 7.59 0.05 18.96 6/26/1996 7.12 0.00 30,000 4,000 180 9/30/1996 7.42 0.00 6,900 1,600 79	2,600	5,300	
3/22/1996 7.59 0.05 18.96 6/26/1996 7.12 0.00 30,000 4,000 180 9/30/1996 7.42 0.00 6,900 1,600 79	2,700	7,000	<1,200
6/26/1996 ^d 7.12 0.00 30,000 4,000 180 9/30/1996 7.42 0.00 6,900 1,600 79	2,300	4,500	<1,200
9/30/1996 7.42 0.00 6,900 1,600 79		**	
	1,500	2,500	830
12/27/1996 6.38 0.00 78,000 12,000 1,900	130	370	<5.0
	2,900	9,700	<5.0
3/10/1997 11.12 0.00 84,000 9,900 1,100	2,600	8,800	<5.0
8/17/1997 12.98 0.03			
9/18/1997 12.00 0.00 65,000 8,000 <0.5	2,000	4,700	<5.0
12/30/1997 8.97 0.00 79,000 6,400 340	2,300	5,500	<5.0
3/25/1998 7.32 0.00 20,000 6,000 260	2,700	5,800	2,400
6/29/1998 11.50 0.00		**	
10/8/1998 12.56 0.00 46,000 120 98	120	240	< 0.50
12/8/1998 10.14 0.00 46,000 5,900 320	2,200	5,400	<1,200
3/26/1999 7.08 0.00 35,000 69 61	37	120	<0.50
6/11/1999 11.40 0.00 26,000 29 32	43	72	< 0.50
9/15/1999 12.52 0.00 37,000 7,300 400	2,400	6,000	<1,000
12/28/1999 12.44 0.00 25,000 44 32	41	75	<0.50
5/23/2001 11:31 0:00 12:54			
6/20/2002 11.29 0.05 12.60 51,000 5,100 290	2,300	5,800	<250
10/21/2002 13.60 0.10 10.33			
12/27/2002 6.60 0.07 17.31			
3/23/2003 9.79 0.04 16.75	**		

Table 3. Groundwater Elevation and Analytical Data - Credit World Auto Sales, 2345 International Boulevard, Oakland, California

Well ID TOC	Date Sampled	Depth to GW (ft)	SPH Thickness (ft)	GW Elevation (ft)	TPHg (µg/L)	Benzene (µg/L)	Toluene (µg/L)	Ethylbenzene (µg/L)	Xylenes (μg/L)	MTBE (µg/L)
TMW-5	5/29/2003	11.29	0.04	15.25	_					
(cont'd)	9/26/2003	12.47	0.07	14.10						
	12/4/2003	12.35	0.10	14.24						
MW-6	5/23/2001	12.47	0.00	11.34	_					
23.81°	6/13/2001	12.47	0.00	11.34	7,600	1,400	42	19	14	<10
	6/20/2002	12.45	0.00	11.36	79	5.7	<0.5 ⋅	<0.5	<0.5	<5.0
	12/27/2002	7.24	0.04	16.60						
	3/23/2003									
	5/29/2003	11.95	0.02	11.88			-	_		
	9/26/2003	13.11	0.03	10.72				-		
	12/4/2003	13.14	0.10	10.75						

Abbreviations and Methods:

TOC = elevation measured in feet below top of casing

Depth to GW = Depth to groundwater relative to top of casing

(ft) = measured in feet

SPH = Separate phase hydrocarbons

GW Elevation = Groundwater elevation in relation to mean sea level; calculated according to the relationship GW elevation = TOC - DTW + (0.8)(SPH thickness)

(ug/L) = micrograms per Liter

TPHg = Total petroleum hydrocarbons as gasoline by modified EPA Method 8015

Benzene, Toluene, Ethylbenzene, Xylenes by EPA Method 8020, and by 8260 if in parenthesis

MTBE = methyl tertiary butyl ether by EPA Method 8020

VOCs = volatile organic compounds by EPA Method 8260

a = Relative to site datum established by Earth Systems Engineering surveyed August 1981

b = Top of casing elevation surveyed 8/10/93 by professional engineer (unknown datum)

c = Top of casing elevation surveyed 6/13/01 to City of Oakland datum by Renner Survey Company of Burlingame, CA. for Sequoia Environmental.

Table 4. Separate-Phase Hydrocarbon Removal - Credit World Auto Sales, 2345 International Blvd, Oakland, California

Sample ID/ Well ID	Date Sampled	Depth to SPH (feet bgs)	Depth to GW (feet bgs)	SPH Thickness (feet)	Hydrocarbons Removed (liters)	Hydrocarbons Removed (gallons)	Cumulative Hydrocarbon Removed (gallons)
MW-1	12/30/1997	10.79	10.96	0.17	0.10	0.03	0.03
	6/11/1999	12.55	12.56	0.01	0.01	0.00	0.03
	9/15/1999	13.85	14.85	1.00	0.60	0.16	0.19
	12/28/1999	8.15	8.31	0.16	0.10	0.03	0.21
	6/13/2001	8.15	8.31	0.16	0.10	0.03	0.24
	12/27/2003	8.15	8.31	0.16	3.00	0.79	1.03
	3/23/2003	10.60	10.65	0.05	1.26	0.33	1.36
	4/4/2003	10.19	10.23	0.04	0.94	0.25	1,61
	5/1/2003	9.80	9.85	0.05	0.49	0.13	1.74
	5/29/2003	11.83	12.11	0.28	1.00	0.26	2.00
	7/25/2003	11.99	12.24	0.25	0.50	0.13	2.13
	8/11/2003	12.07	12.37	0.30	0.50	0.13	2.27
	8/29/2003	12.07	12.40	0.33	0.50	0.13	2.40
	9/12/2003	12.59	12.90	0.31	0.48	0.13	2.53
	9/26/2003	12.55	12.84	0.29	0.50	0.13	2.66
	10/10/2003	12.61	12.72	0.11	0.11	0.03	2.69
	10/30/2003	12.68	12.75	0.07	0.08	0.02	2.71
	11/25/2003	12.59	12.69	0.10	0.10	0.03	2.73
	12/4/2003	12.40	12.50	0.10	0.10	0.03	2.76
	12/23/2003	11.97	12.08	0.11	0.10	0.03	2.79
MW-2	6/28/1995	12.77	13.50	0.73	0.44	0.12	2.12
	9/28/1995	14.09	14.63	0.54	0.32	0.09	2.20
	12/26/1995	11.68	12.58	0.90	0.54	0.14	2.35
	3/22/1996	11.31	11.46	0.15	0.09	0.02	2.37
	6/20/1996	12.71	13.08	0.37	0.22	0.06	2.43
	9/30/1996	12.92	16.67	3.75	2.25	0.59	3.02
	12/27/1996	8.17	15.74	7.57	4.54	1.20	4.22
	6/28/1997	11.94	11.98	0.04	0.02	0.01	4.23
	9/18/1997	13.44	13.44	0.00	0.00	0.00	4.23
	12/10/1998	10.81	12.91	2.10	1.26	0.33	4.56
	3/26/1999	8.86	9.06	0.20	0.12	0.03	4.59
	9/15/1999	12.59	15.59	3.00	1.80	0.48	5.07
	12/28/1999	12.31	16.81	4.50	2.70	0.71	5.78
	6/13/2001	11.69	14.84	3.15	1.89	0.50	6.28
	6/20/2002	14.10	14.80	0.70	0.42	0.11	6.39
	10/21/2002	16.74	16.98	0.24	0.14	0.04	6.43
	12/27/2002	13.15	13.58	0.43	3.00	0.79	7.22
	3/23/2003	15.20	15.49	0.29	5.68	1.50	8.72
	4/4/2003	14.72	14.80	0.08	3.78	1.00	9.72
	5/1/2003	13.59	13.63	0.04	0.49	0.13	9.85
	5/29/2003	15.64	16.08	0.44	1.00	0.26	10.11
	7/25/2003	15.81	16.31	0.50	0.50	0.13	10.24
	8/11/2003	15.99	16.44	0.45	0.50	0.13	10.38
	8/29/2003	15.92	16.75	0.83	0.50	0.13	10.51
	9/12/2003	16.29	17.10	0.81	0.95	0.25	10.76
	9/26/2003	16.27	17.14	0.87	1.90	0.50	11.26
	10/10/2003	16.35	17.10	0.75	1.89	0.50	11. 76
	10/30/2003	16.41	17.03	0.62	0.95	0.25	12.01
	11/25/2003	16.08	16.98	0.90	3.79	1.00	13.01
	12/4/2003	15.74	16.75	1.01	3.79	1.00	14.01
	12/11/2003	15.81	16.90	1.09	3.79	1.00	15.01

Table 4. Separate-Phase Hydrocarbon Removal - Credit World Auto Sales, 2345 International Blvd, Oakland, California

Sample ID/ Well ID	Date Sampled	Depth to SPH (feet bgs)	Depth to GW (feet bgs)	SPH Thickness (feet)	Hydrocarbons Removed (liters)	Hydrocarbons Removed (gallons)	Cumulative Hydrocarbon Removed (gallons)
MW-3	4/16/1992	12.09	14.14	. 0.46	0.10	0.02	0.02
IVI VY-3	9/16/1994	13.98	14.14	0.16	0.10	0.03	0.03
	3/31/1995	15.37	15.42	0.05	0.03	0.01	0.03
		12.52	12.98	0.46	0.28	0.07	0.11
	6/28/1995	14.15	14.20	0.05	0.03	0.01	0.11
	12/26/1995	13.27	13.33	0.06	0.04	0.01	0.12
	3/22/1995	12.77	12.81	0.04	0.02	0.01	0.13
	6/20/1996	13.88	13.95	0.07	0.04	0.01	0.14
	9/24/1996	14.82	14.86	0.04	0.02	0.01	0.15
	12/27/1996	10.98	11.04	0.06	0.04	0.01	0.16
	6/28/1997	13.66	13.72	0.06	0.04	0.01	0.17
	12/28/1999	14.91	15.16	0.25	0.15	0.04	0.21
	6/13/2001	14.30	14.70	0.40	0.24	0.06	0.27
	6/20/2002	14.66	14.68	0.02	0.01	0.00	0.27
	12/27/2002	11.20	11.37	0.17	3.00	0.79	1.07
	5/29/2003	13.91	13.99	0.08	0.01	0.03	1.09
	7/25/2003	14.02	14.12	0.10	0.20	0.05	1.14
	8/11/2003	14.25	14.35	0.10	0.15	0.04	1.18
	8/29/2003	14.18	14.33	0.15	0.15	0.04	1.22
	9/12/2003	14.41	14.55	0.14	0.10	0.03	1.25
	9/26/2003	14.46	14.51	0.05	0.15	0.04	1.29
	10/10/2003	14.50	14.58	0.08	0.20	0.05	1.34
	10/30/2003	14.59	14.63	0.04	0.12	0.03	1.37
	11/25/2003	14.30	14.40		0.12	0.03	1.40
	12/4/2003	14.30	14.28	0.10 0.10	0.11	0.03	
	12/23/2003	13.81	13.91	0.10	0.10	0.03	1.43 1.44
TMW-4	12/27/2002	8.95	9.07	0.12	1.50	0.40	0.40
	3/23/2003	10.70	10.73	0.03	0.95	0.25	0.65
	4/4/2003		10.40	0.05	0.95	0.25	0.90
	5/1/2003	10.07	10.09	0.02	0.49	0.13	1.02
	5/29/2003	12.48	12.50	0.02	0.00	0.00	1.02
	7/25/2003	12.61	12.67	0.02	0.05	0.00	1.03
	8/11/2003	14.49	14.59				
	8/29/2003			0.10	0.10	0.03	1.06
		12.93	12.95	0.02	0.05	0.01	1.07
	9/12/2003	13.24	13.29	0.05	0.03	0.01	1.08
	9/26/2003	13.21	13.27	0.06	0.04	0.01	1.09
	10/10/2003	13.31	13.40	0.09	0.05	0.01	1.11
	10/30/2003	13.30	13.38	80.0	0.04	0.01	1.12
	11/25/2003	13.09	13.19	0.10	0.02	0.01	1.12
	12/4/2003	12.97	13.07	0.10	0.05	0.01	1.14
	12/23/2003	13.59	13.69	0.10	0.05	0.01	1.15
TMW-5	8/17/1993	12.95	12.98	0.03	0.02	0.00	0.00
	9/16/1994	12.97	13.02	0.05	0.03	0.01	0.01
	6/28/1995	11.25	11.31	0.06	0.04	0.01	0.02
	12/26/1995	10.11	10.16	0.05	0.03	0.01	0.03
	3/22/1996	7.54	7.59	0.05	0.03	0.01	0.04
	8/17/1997	12.95	12.98	0.03	0.02	0.00	0.04
	5/23/2001		11.31	0.00	0.00	0.00	0.04
	6/20/2002	11.24	11.29	0.05	0.03	0.01	0.05
	10/21/2002	13.50	13.60	0.10	0.06	0.02	0.07
	12/27/2002	13.50	13.60	0.10	1.50	0.40	0.46
	3/23/2003	9.75	9.79	0.04	0.95	0.25	0.71

Table 4. Separate-Phase Hydrocarbon Removal - Credit World Auto Sales, 2345 International Blvd, Oakland, California

Sample ID/ Well ID	Date Sampled	Depth to SPH (feet bgs)	Depth to GW (feet bgs)	SPH Thickness (feet)	Hydrocarbons Removed (liters)	Hydrocarbons Removed (gallons)	Cumulative Hydrocarbon Removed (gallons)	
MW-5	4/4/2003	9.40	9.45	0.05	0,49	0.13	0.84	
(con't)	5/1/2003	8.93	8.95	0.02	0.38	0.10	0.94	
	5/29/2003	11.25	11.29	0.04	0.01	0.01	0.95	
	7/25/2003	11.33	11.37	0.04	0.02	0.01	0.96	
	8/11/2003	11.47	11.49	0.02	0.01	0.003	0.96	
	8/29/2003	12.10	12.17	0.07	0.02	0.01	0.96	
	9/12/2003	12.45	12.50	0.05	0.03	0.01	0.97	
	9/26/2003	12.40	12.47	0.07	0.02	0.01	0.98	
	10/10/2003	12.51	12.61	0.10	0.02	0.01	0.98	
	10/30/2003	12.65	12.70	0.05	0.01	0.003	0.99	
	11/25/2003	12.39	12.49	0.10	0.01	0.003	0.99	
	12/4/2003	12.25	12.35	0.10	0.01	0.001	0.99	
	12/23/2003	13.78	13.88	0.10	0.01	0.003	0.99	
MW-6	12/27/2002	7.20	7.24	0.04	1.50	0.39	0.39	
	5/29/2003	11.93	11.95	0.02	0.01	0.01	0.40	
	7/25/2003	12.05	12.07	0.02	0.02	0.01	0.41	
	8/11/2003	12.18	12.20	0.02	0.01	0.003	0.41	
	8/29/2003	12.74	12.77	0.03	0.05	0.01	0.42	
	9/12/2003	13.09	13.15	0.06	0.05	0.01	0.44	
	9/26/2003	13.08	13.11	0.03	0.05	0.01	0.45	
	10/10/2003	13.27	13.43	0.16	0.08	0.02	0.47	
	10/30/2003	13.32	13.40	0.08	0.05	0.01	0.49	
	11/25/2003	13.09	13.24	0.15	0.04	0.01	0.50	
	12/4/2003	13.04	13.14	0.10	0.02	0.01	0.50	
	12/23/2003	13.50	13.60	0.10	0.01	0.003	0.50	
			Hydro	Hydrocarbons removed by bailing or purging (gallons) =				

Hydrocarbons removed by Tank Protect (see below) (gallons) = 5.0

> 25.88Total estimated hydrocarbons removed (gallons) =

Note = approximately 3 to 5 gallons reported removed by Tank Protect between 8/20/97 and 1/14/98 with continuous free product removal system.

bgs = below ground surface

SPH = Separate phase hydrocarbons

SPH removal volumes were provided for 5/23/01, 6/13/01, and 12/27/02 data.

The volume of hydrocarbons removed prior to 12/27/2002 were estimated by multiplying the well casing volume (2" diameter casing = 0.60L/ft) by the SPH thickness (feet)



Appendix A

Agency Correspondence

ALAMEDA COUNTY HEALTH CARE SERVICES

AGENCY



DAVID J. KEARS, Agency Director

ENVIRONMENTAL HEALTH SERVICES ENVIRONMENTAL PROTECTION 1131 Harbor Bay Parkway Alameda, CA 94502-6577 (510) 567-6700 Fax (510) 337-9335

February 25, 2004

Mr. Stanley Wong 2200 E. 12th St. Oakland CA 94606

Dear Mr. Wong:

Subject: Fuel Leak Case No. R00000327, 2345 E. 14th St., Oakland, CA94601

Alameda County Environmental Health, Local Oversight Program (LOP), has received and reviewed the Site Summary Report document dated April 30, 2003, regarding the above referenced site, prepared by Mr. Robert Clark-Riddell of Cambria Environmental. I have also called and discussed with Mr. Ron Scheele of Cambria Environmental. As you are aware, there had been a verbal approval of the recommendations and interim remedial activities per my discussions with Ms. Mary Holland-Ford of Cambria Environmental.

This office requests that you address the following technical comments, perform the proposed work, and send us the technical reports requested below:

TECHNICAL COMMENTS

This site summary report recommends continual monitoring, interim remedial activity, further assessment or investigation of the plume, along with feasiblity studies.

This office concurs with your recommendations as specified above.

TECHNICAL REPORT REQUEST

Please submit the following technical reports to Alameda County Department of Environmental Health (Attention: Amir K. Gholami):

March 31, 2004 Work Plan

Should you have any questions, please do not hesitate to call me at (510) 567-6876.

Sincerely,

Amir K. Gholami Hazardous Materials Specialist

C: A.gholami, D.Drogos Mr. Robert Clark-Riddell of Cambria Environmental, 5900 Hollis St., Suite A, Emeryville, CA 94608



Appendix B

Standard Field Procedures for Soil Boring and Monitoring Well Installations

STANDARD FIELD PROCEDURES FOR SOIL BORING AND MONITORING WELL INSTALLATIONS

This document presents standard field methods for drilling and sampling soil borings and installing, developing and sampling groundwater monitoring wells. These procedures are designed to comply with Federal, State and local regulatory guidelines. Specific field procedures are summarized below.

SOIL BORINGS

Objectives

Soil samples are collected to characterize subsurface lithology, assess whether the soils exhibit obvious hydrocarbon or other compound vapor or staining, and to collect samples for analysis at a State-certified laboratory. All borings are logged using the Unified Soil Classification System by a trained geologist working under the supervision of a California Registered Geologist (RG).

Soil Boring and Sampling

Soil borings are typically drilled using hollow-stem augers or direct-push technologies such as the Geoprobe®. Soil samples are collected at least every five ft to characterize the subsurface sediments and for possible chemical analysis. Additional soil samples are collected near the water table and at lithologic changes. Samples are collected using lined split-barrel or equivalent samplers driven into undisturbed sediments at the bottom of the borehole.

Drilling and sampling equipment is steam-cleaned prior to drilling and between borings to prevent cross-contamination. Sampling equipment is washed between samples with trisodium phosphate or an equivalent EPA-approved detergent.

Sample Analysis

Sampling tubes chosen for analysis are trimmed of excess soil and capped with Teflon tape and plastic end caps. Soil samples are labeled and stored at or below 4° C on either crushed or dry ice, depending upon local regulations. Samples are transported under chain-of-custody to a State-certified analytic laboratory.

Field Screening

One of the remaining tubes is partially emptied leaving about one-third of the soil in the tube. The tube is capped with plastic end caps and set aside to allow hydrocarbons to volatilize from the soil. After ten to fifteen minutes, a portable volatile vapor analyzer measures volatile hydrocarbon vapor concentrations in the tube headspace, extracting the vapor through a slit in the cap. Volatile vapor analyzer measurements are used along with the field observations, odors, stratigraphy and groundwater depth to select soil samples for analysis.

CAMBRIA

Water Sampling

Water samples, if they are collected from the boring, are either collected using a driven Hydropunch® type sampler or are collected from the open borehole using bailers. The groundwater samples are decanted into the appropriate containers supplied by the analytic laboratory. Samples are labeled, placed in protective foam sleeves, stored on crushed ice at or below 4°C, and transported under chain-of-custody to the laboratory. Laboratory-supplied trip blanks accompany the samples and are analyzed to check for cross-contamination. An equipment blank may be analyzed if non-dedicated sampling equipment is used.

Grouting

If the borings are not completed as wells, the borings are filled to the ground surface with cement grout poured or pumped through a tremie pipe.

MONITORING WELL INSTALLATION, DEVELOPMENT AND SAMPLING

Well Construction and Surveying

Groundwater monitoring wells are installed to monitor groundwater quality and determine the groundwater elevation, flow direction and gradient. Well depths and screen lengths are based on groundwater depth, occurrence of hydrocarbons or other compounds in the borehole, stratigraphy and State and local regulatory guidelines. Well screens typically extend 10 to 15 fee below and 5 feet above the static water level at the time of drilling. However, the well screen will generally not extend into or through a clay layer that is at least three feet thick.

Well casing and screen are flush-threaded, Schedule 40 PVC. Screen slot size varies according to the sediments screened, but slots are generally 0.010 or 0.020 inches wide. A rinsed and graded sand occupies the annular space between the boring and the well screen to about one to two feet above the well screen. A two feet thick hydrated bentonite seal separates the sand from the overlying sanitary surface seal composed of Portland type I,II cement.

Well-heads are secured by locking well-caps inside traffic-rated vaults finished flush with the ground surface. A stovepipe may be installed between the well-head and the vault cap for additional security.

The well top-of-casing elevation is surveyed with respect to mean sea level and the well is surveyed for horizontal location with respect to an onsite or nearby offsite landmark.

CAMBRIA

Well Development

Wells are generally developed using a combination of groundwater surging and extraction. Surging agitates the groundwater and dislodges fine sediments from the sand pack. After about ten minutes of surging, groundwater is extracted from the well using bailing, pumping and/or reverse air-lifting through an eductor pipe to remove the sediments from the well. Surging and extraction continue until at least ten well-casing volumes of groundwater are extracted and the sediment volume in the groundwater is negligible. This process usually occurs prior to installing the sanitary surface seal to ensure sand pack stabilization. If development occurs after surface seal installation, then development occurs 24 to 72 hours after seal installation to ensure that the Portland cement has set up correctly.

All equipment is steam-cleaned prior to use and air used for air-lifting is filtered to prevent oil entrained in the compressed air from entering the well. Wells that are developed using air-lift evacuation are not sampled until at least 24 hours after they are developed.

Groundwater Sampling

Depending on local regulatory guidelines, three to four well-casing volumes of groundwater are purged prior to sampling. Purging continues until groundwater pH, conductivity, and temperature have stabilized. Groundwater samples are collected using bailers or pumps and are decanted into the appropriate containers supplied by the analytic laboratory. Samples are labeled, placed in protective foam sleeves, stored on crushed ice at or below 4°C, and transported under chain-of-custody to the laboratory. Laboratory-supplied trip blanks accompany the samples and are analyzed to check for cross-contamination. An equipment blank may be analyzed if non-dedicated sampling equipment is used.

Waste Handling and Disposal

Soil cuttings from drilling activities are usually stockpiled onsite and covered by plastic sheeting. At least three individual soil samples are collected from the stockpiles and composited at the analytic laboratory. The composite sample is analyzed for the same constituents analyzed in the borehole samples in addition to any analytes required by the receiving disposal facility. Soil cuttings are transported by licensed waste haulers and disposed in secure, licensed facilities based on the composite analytic results.

Groundwater removed during development and sampling is typically stored onsite in sealed 55-gallon drums. Each drum is labeled with the drum number, date of generation, suspected contents, generator identification and consultant contact. Upon receipt of analytic results, the water is either pumped out using a vacuum truck for transport to a licensed waste treatment/disposal facility or the individual drums are picked up and transported to the waste facility where the drum contents are removed and appropriately disposed.

F:\PROCEDURES\TEMPLATE\SOPs\GW Installation2.doc



Appendix C

Soil Boring Logs and Well Construction Details

WELL CONSTRUCTION TPH PID (pg/Kg) (pgm) SOIL DESCRIPTION Organic Cley truce sitt sand bark preproblems, very sign medium lense, good plastic reador Destante 150 35 10, 10 304-1 OL Same as above miner oilt, s noderate hydrocarbor like	toward.
N S 5 5 OL Organic Chex track silt send bank pray to black, way slip medium dense, good plant is in a solar	toward.
N S S S S S S S S S S S S S	& grand,
N S S S O Organic Clay trace silt soul fact pray to black, vary slip medium dense, good plast in reader	& grand,
5 5 5 Or Organis Clay trace sitt sand bark gray to black, very sign medium dense, good plant in a conformal surface.	famously
5 5 5 Or Organis Clay trace sitt sand bank gray to black, very sign medium dense, good plant in a conformal surface.	famuel,
5 5 5 Or Organis Clay track silt said bark graves black, very slip medium dense, good plant in its order	Egravel.
moderne, good destin	1.11 1-4
roador	my mars y
	ty, and stains
Bertonite 150 35 10-10 804-1 OL Same as above, miner oilt, s moderate histocarbon like	
Bentourite 150 35 10 1 804-1 Same as above, minor eilt, s	
1) 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	hell tragments
	. 60/0/
9 15 Part Char trace sitt, gray is to	4004 MO : 87,
2.55 1751 80/4-4 - WENT MANGE GOOD MARKEN	y gray stancy
N Strong oder	
15 120 5: Hy Gravelly Sand gray, sat	reted, losse,
12 79 20 3M graystain, maderate al	ar
3 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5	4
5 M Same as above, brown, 105	tain, no add
CC Fat colar, minor saind bir sum.	saferated.
- Marieny, we	JANIA, NO OOU
o' sw well graded sand	
35 ou well graded Grave!	
	<u>.</u>
 - - - - - - - - - 	
GeologistiESE - Mark Maganger, 1.6. Or: 11ex: Consolidated Testing	PLATE
LOG of BORING	
Wong's Taxi MW-/	
Project Number. 68-8014-1 5/2/91	Page / of /
Troice Number. 60-8014-4 1/4111	

), majorista (

.

WELL CONSTRUCTION THE PLD #0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0	WELL	CHEMICAL ANA	PID 20	SAMPLE STATE BE STATE STATE STATE BE STATE STATE BE STATE STATE BE STATE STATE BE STATE ST	U.S.C.S.	SOIL DESCRIPTION
Secretary: 556 Mark Magazar, A. 6. Dillot: 7017 Cong's Taris: Co	CONSTRUCTION	4	1 .	35 5	9.0	SOIL DESCRIPTION
The state of the s	GERCEON CO.	(rg/69)	1473'	0	<u> </u>	
description of the state of the	F-1-6]	
description of the state of the				!] :	
description of the state of the			<u> </u>	! !	!	5'14 d'1 11 11 11 11 11 11 11 11 11 11 11 11 1
description of the state of the	") B		1	5	66/5M	3, 17, Chy a Marico granes sale, day
Coologistics of make Maganger, A. O. Priller: 1815 Coologistics of ma			190 176			alouge and about the wastering
augustic 4320 160 173 10 1011-6 507 END hard stightspaces dark gray, and the gray stage and the consequent fight and the consequence f				! 	i	very slight bufocardor like afor
Seologistics & Mark Maganger, R. S. Priller: 50/5 Worg's Taxi 100 150/10 150/71 100 150/10 150/71 100 150/10 150/71 100 150/10 150/71 100 150/10 150/71 100 150/10 150/71 100 150/10 150/71 100 150/10 150/71 100 150/10 150/71 100 150/10 150/71 100 150/10 150/71 100 150/10 150/71 100 150/10 150/71 100 150	1 1		1		-	
Seologistics & Mark Maganger, R. S. Priller: 50/5 Worg's Taxi 100 150/10 150/71 100 150/10 150/71 100 150/10 150/71 100 150/10 150/71 100 150/10 150/71 100 150/10 150/71 100 150/10 150/71 100 150/10 150/71 100 150/10 150/71 100 150/10 150/71 100 150/10 150/71 100 150/10 150/71 100 150/10 150/71 100 150			17	//	}	
Seologistics & Mark Maganger, R. S. Priller: 50/5 Worg's Taxi 100 150/10 150/71 100 150/10 150/71 100 150/10 150/71 100 150/10 150/71 100 150/10 150/71 100 150/10 150/71 100 150/10 150/71 100 150/10 150/71 100 150/10 150/71 100 150/10 150/71 100 150/10 150/71 100 150/10 150/71 100 150/10 150/71 100 150	C and the	437.0	160 173	8014-6	3M	5:11 Sand stightly maist dark gray,
Sense as above 10 10 10 10 10 10 10 1	1				L	
Sense as above 10 10 10 10 10 10 10 1	*				}	
Sense as above 10 10 10 10 10 10 10 1			1	1		
Sense as above 10 10 10 10 10 10 10 1	4		1 7	15		5:/th Clave Sand or the minor grove, light
Sense as above 10 10 10 10 10 10 10 1	,0,	160	1250 20	80/4-7	1/62	greenish gray, mist, and underse,
Seologistiess. Mark Magarger, R. G. Prillet. 50/5 LOG of, BORING May sum and a strategraph of the sum of the strategraph of the sum of the su	4		! !	<u> </u>		no stain, very slight of or
Geologistics & nach Magazar, 2.6. Priller: 50 15 Wong's Taxi LOG of BORING MW-Z	N		1	! -	=	
Geologistics & nach Magazar, 2.6. Priller: 50 15 Wong's Taxi LOG of BORING MW-Z		<u> </u>	!	 		and the state of t
Geologistics & Mark Magazer, A. G. Prillet: 10/5 Wong's Taxi LOG of BORING MW-Z				20	3M/CL	seme as about, servine to, no sour
Geologistics & Mark Magazor, A. 6. Prillet: 50/5 Wong's Taxi LOG of BORING MW-2	2 0					
Geologistiess-such Myanger, R. G. Prillet: 50/5 LOG of. BORING May 2	$\frac{2}{2}$	<u> </u>	!			
Geologistiess-such Myanger, R. G. Prillet: 50/5 LOG of. BORING May 2	 \ 		 	<u> </u>		
Geologistiess-such Myanger, R. G. Prillet: 50/5 LOG of. BORING May 2	 			12611		Fat Clar receist brown, saturated
Geologistiess-mak Mynger, A.G. Prillet: 50/5 Wong's Taxi LOG of BORING MW-2	1 2 - 5		1 1	123.11	CL	medium donse good plasticity na
Geologistiess-mak Mynger, A.G. Prillet: 50/5 Wong's Taxi LOG of BORING MW-2	-\\-\ \ -\		1			stair, no oder
Geologisties B. Mark Magarger, R.G. Critter: 18/5 LOG of, BORING May 2 May 2	\ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \		1			
Geologisties B. Mark Magarger, R.G. Critter: 18/5 LOG of, BORING May 2 May 2	7. 6.		•	! !!		
Geologisties B. Mark Magarger, R.G. Critter: 18/5 LOG of, BORING May 2 May 2	3			30 !!	c L	d'and the same of
Geologistiess-Mark Magarger, R.G. Priller: 10/5 Wong's Taxi LOG of BORING MW-2	1			<u> </u>	3 -	same as a pour
Geologistiess-Mark Magarger, R.G. Priller: 10/5 Wong's Taxi LOG of BORING MW-2			-			
Geologistiess-Mark Magarger, R.G. Priller: 10/5 Wong's Taxi LOG of BORING MW-2				 		
Geologistiess-Mark Magarger, R.G. Priller: 10/5 Wong's Taxi LOG of BORING MW-2			 	1	C 4	same as about
Geologistiess-Mark Magarger, R.G. Priller: 10/5 Wong's Taxi LOG of BORING MW-2	00			35	~~	7.035'
Geologistiess-Mark Magazer, R.G. Priller: 18/5 LOG of. BORING MW-2	<u> </u>		 			
Geologistiess-Mark Magazer, R.G. Priller: 18/5 LOG of. BORING MW-2	 					
Geologistiess-Mark Magarger, R.G. Prillet: 50/5 Wong's Taxi LOG of. BORING MW-2			-	! 		
Geologistiess-Mark Magarger, R.G. Prillet: 50/5 Wong's Taxi LOG of. BORING MW-2			1			
Geologistiess-Mark Magarger, R.G. Prillet: 50/5 Wong's Taxi LOG of. BORING MW-2			!			
Wong's Taxi LOG of BORING NW-2			 	<u></u>		
Wong's Taxi LOG of BORING NW-2			} 	╏╌╌╏┠┈╼╼┤	-	
Wong's Taxi LOG of BORING NW-2			}	 		
Wong's Taxi LOG of BORING NW-2	 		╂╼╼┼╼═┤	! 		
Wong's Taxi LOG of BORING NW-2	} 	<u> </u>	} - -	 		
Wong's Taxi LOG of BORING NW-2			 			
Wong's Taxi LOG of BORING NW-2	 		1			
Wong's Taxi LOG of BORING NW-2	<u> </u>	 				
Wong's Taxi LOG of BORING NW-2						
Wong's Taxi LOG of BORING NW-2						
Wong's Taxi LOG of BORING NW-2			<u> </u>	 		
Wong's Taxi LOG of BORING NW-2		!	 	 		
Wong's Taxi LOG of BORING NW-2		 	!!	 		
Wong's Taxi LOG of BORING NW-2	Geologist: Ke	! E = 49 21 149	<u> </u>	1.6. 10	://0/1: 3	1015
$m\omega-2$	1	s - minerie mi	And an			PLAIE
$m\omega-2$			-	•	100	C OF BORING
$m\omega$ -2	Word	5 Touse			LU	3 01. 0 0 1/1 1/10
Project Number: 69-8014-1 8/2/91				ł	٠	mu-2
	Project Number -	A-801U-	#	12/91	. /	Popol d/
		J-0017-7				

Ï

ă

1

WELL CONSTRUCTION	CHEMICAL ANALYSE Laboratory (Fini TPH PII (09/Kg) (814	BLOU COURT	CTOSTIC CTOSTIC THIERDACK NUMBER	U. 8. C. 9.	SOIL DESCRIPTION
n h		2			tet Chex, trace grown the gill Sand, Sank
	70			c /sm	medindense, good destisity, no store
Bestonite	50 M	1 8,	10 30141	2 06	Organic Chy, preside from, moist, nedium dense good sketicity, no stain no obor
N N	2.5 70	179	<u> </u>	_	silty send dark gray, moist, loose, most
			20	37/66	5: Ity Clayery Sand gray saturated, ned: um louse, no stain, no of or
			25	-	tat Clay greenish from seturates ned inchesse, good plasticity, no stain, no Dar
0 h		1	30	CL	Same as aboug
562			35	500	5: 14 Sand light grosen saturated lose, costain a
Geologisties		wy ee	A. 6.	er://er: LO	G of BORING
Wong Project Number: E	8-8014-1	8	12/2/		nw-3 Page/of.

:

LOG OF EXPLORATORY BORING PROJECT NUMBER 267 BORING NO. TMW-4 PROJECT NAME 2345 EAST 14TH STREET, DAKLAND CA. BY LNH DATE 7/22/93 SURFACE ELEV. 27 FT PENETRA-LITHO-RECOVERY OVA GROUND WATER LEVELS TION GRAPHIC DESCRIPTION (FT/FT) (PPM) (BLOWS/FT) COLUMN ASPHALT AGGREGATE BASE (GW): brown, dry, no odor. CLAY (CL): black, scattered sand, dry, no odor. .75/1.5 CLAY (CL): brown, scattered sand, stiff to very stiff, dry, no odor. .75/1.5 20 CLAY (CL): mottled green/blue, scattered sand, gravelly at 14.5', very stiff. Z dry, slight odor, 1.5/1.5 26 15 CLAY (CL): brown, very stiff, moist to wet. no odor. 1.5/1.5 36 20 CLAY (CL): brown, gravelly, sandy, very 1.5/1.5 46 stiff to hard, moist, no odor. 1.5/1.5 43 1.5/1.5 33 25 1.5/1.5 44 1.0/1.5 SAND (SP): brown, scattered gravel, medium dense, wet, no odor. .1.0/1.5 22 CLAY (CL): brown, gravelly, very stiff, 30 dry, no odor. Boring terminated @ 34.5'. Sampled to 36.0'. 1.5/1.5 29 35 Boring drilled with continuous-flight, hollow-stem. REMARKS:

EMARKS: Boring drilled with continuous-flight, hollow-stem,
8-inch O.D. augers. Samples collected in a 2.0-inch

I.D. California and standard penetration sampler.

ក្នុ ភូមិ 00000 FT TMW-4 0 ASPHAL I DRILLED HOLE AGGREGATE BASE IGHT brown dry no odor. CLAY (CL): black, scattered sand. dry. CEMENT VAULT BOX 5 CLAY (CL): brown, scattered sand, stiff to very stiff, dry, no odor. LOCKING CAP CEMENT BLANK CASING 10 _ BENTONITE CLAY (CL): mottled green/blue, scattered sand, gravelly at 14.5°, very stiff, dry, slight oddr. m. 13 15 CLAY (CL): brown, very stiff, moist to wet, CLAY (CL): brown, gravelly, sandy, very stiff to hard, moist, no odor. 20 __ GRAVEL PACK __ SLOTTED SCAEEN 0.01 25 30 SAND (SP): brown, scattered grave).
medium dense, wet, no odor. CLAY (Ct.); brown, gravelly, very stiff, dry, no odor. BENTONITE 35 Boring terminated @ 34.5'. Sampled to 35.0'. LEGEND Static Water Level ASPHALT 2345 EAST 14TH STREET, DAKLAND, CA WELL ID : TMM-4 TANK PROTECT ENGINEERING Figure:

PROJECT NUMBER 267

BORING NO. TMW-5

PROJECT NAME

2345 EAST 14TH STREET, OAKLAND CA.

BY LNH

DATE 7/23/93 SURFACE ELEV.

27 FT


ECOVERY FT/FT]	OVA (PPM)	PENETRA- TION (BLOWS/FT)	GROUND NATER LEVELS	DEPTH IN FT.	SAMPLES	LITHO- GRAPHIC COLUMN	DESCRIPTION
							ASPHALT AGGREGATE BASE (GW): brown, dry, no odor.
							CLAY (CL): grey to black, scattered sand, firm to very stiff, dry, slight odor.
.75/1.5	0	7		5			
1.5/1.5	>1000	50	1	o			
			ZZ				CLAY (CL): light green to grey, gravelly @ 15.0', hard, damp, slight odor.
1.2/1.5	>1000	>50	1	5			ţ
-	750		,				SAND (SP): green to grey, clayey, silty, small layers 1" to 2" clay, scattered gravel, very dense, wet, slight odor.
.5/1.5		>50	2	0			graves, tory denote, not, original odor.
.5/1.5		>50		-			CLAY (CL): brown, gravelly, sandy, hard, dry, no odor.
.2/1.5		39					/ Boring terminated @ 24.0'. Sampled to 27.0
:5/1.5		>50	2	5			
.5/1.5		49					

REMARKS:

Boring drilled with continuous-flight, hollow-stem,

 θ -inch 0.D. augers. Samples collected in a 2.0-inch

I.D. California and standard penetration sampler.



Borrne a word for the light with PROJECT NAME: --Stanley World CLEMT:-May 22, 2001 2345 International Boulevard, Oaldand, California DATE DRULED: ROJECT ADDRESS: CA Split Spoon Sempler SAMPLER TYPE:-Hollow Stem Auger DRILLING METHOD: 6 3/4 - inches 20 Feet ... WIDTH OF BORING: TOTAL DEPTH OF BORING: DEPTH TO GROUNDWATER AT THE TIME OF DRILLING: N/A STATIC WATER LEVEL: -4 inchee 15 feet 4 inches SCREEN DIAMETER: CASING LENGTH: -ASING DIAMETER: 0.02 Inch 5 feet - SLOT SIZE: ---CREEN LENGTH: C57-522125 DRILLING COMPANY: BRY Area Exploration DRILLING LIC :-Disturbed No Recovery CORE SAMPLE CONDITION LEGEND: Undisturbed CONSTRUCTION SOIL PID RECOVERY RÉVIEWED BY: Ola Balogus DEPTHTYPE (ppm) OGGED BYICHIE Webuzoh CASING SCREEN SEAL ASPHALT covering SANDY CLAY: Dark brown; about 40% coarse to fine, hard angular to subrounded sarid; 3 CL about 60% ctay, moderate plasticity; moist; no bydrocerbon odor; no reaction with HCL. 2.2.3 CEMENT 5 GROUT 36 SANDY CLAY: Gray, shout 30% coarse to fine, hard subangular to rounded sand, about 60% clay, moderate to high plasticity; moist; has hydrocarbon odor; no reaction with HCL CŁ 4,5,8 10 370 CLAYEY SAND: Gray, about 30% clay, moderate to high plasticity, about 60% coasts to SC fine, hard rounded eand; about 10% gravel size about 1/4 inch; moist; has hydrocarbon 15 odor, no reaction with HCL. 6,10,12 SANDY CLAY: Brown, about 35% coarse to very fine, hard rounded sand; about 60% clay 2 moderate to high plasticity, about 5% gravel size about 1/4 inch; molet to saturated; no CL hydrocarbon odor, no reaction with HCL. 5,7,8 20 25

Field	in The last of the		ORAT	ORY	BC	ORING	CLIENT West Coals Tank Testing LOCATION 2345 East 14th Street LOGGED BY DRILLEN Hew Drilling Drilling method Solid Stem Auger CME-55 Mobile Drill Riq Moledta 6 Inc. Cosing Installation data			
Pocket Torrene Ter	Peckel Fonstrameter TSF	Blows/ft. or Preseure PBt		inch hrass	41000 F	Sett Group Symbol	Water level V 19 ft TO 16 (i) Time 8.30 AM Date 10.03.23 DESCRIPTION 0-9" Asphalt/Base reck			
		3 3 6	R1-5		5_	Cr	Damp silty clay. Soft and Blackish Blackish silty clay, soft to med. stiff with gasoline odor.			
		4 8 10	B1=1(CL	Damp greenish to Black silty clay w/ some sand content. Slight discoloration observed.Med. stiff w/ gasoline odor.			
		13 18	B1-1\$	1	5	CL &SM	Moist greenish silty sandy clay w/ fines Med.stiff to stiff w/ slight discoloration Ground water encountered at 19 feet. Boring bottom.			
CAI	L			V	NVI	RON	MENTAL CONSULTANTS			

EXPLORATE FIRM PORTED FOR PRINCE PRIN		RING	PROJECT No CEC/SBW 28 2 Oct 3,88 BORING CLIENT West Coast Tank Testing B2 LOCATION 2345 East 14th Street LOGGED BY TS DRILLER Hew Drilling of Drilling method Solid Stem Auger
Ground Electric Change	Entre 18	(x.1) (x.2)	CME-55 Mobile Drill Rig Hote dis Sinch
Tar Torrena 1 1 94 dia. sleev	Ft.	Soff Group Bymbol (U.S.C.S.)	Water level V 19 ft 16 ft. Time 9.30 AM Date 10.03.88 DESCRIPTION 0-9" Asphalt/Base rock
3 4 7 B2-5	5	Control of the contro	Black silty clay w/ gasoline odor.Dan Black to greenish silty clay w/ gasoli odor. Damy, soft to mod.Still.
3 8 10 B2-10	10		Greenish, soft to med stiff silty clay w/ some sand. Slight discoloration and damp.
10 15 15 B2-1	15		reenish to brown silty clay w/ some sa Med. stiff and Damp.Slight discolorati observed.
		V	Water encountered at 19 feet.Boring bo

Cating installation cats Cating installation cats Cating installation cats		LOG)(LORATORY	BOR	ing	PROJECT No.CFC/S 19 56 90 2 Oct 3,88 DURING No. CLIENWest Coals Tank Testing B3 LOCATION 2345 East 14th Street 1 LOCATION TS DRILLER Hew Drilling 61				
Time 10.35 Mm OSYT Desire 10.03.88 11.94 inchedia hrass sloeves CL Dry to damy black sitty clay w/ Sind: Some discoloration (reddish) k city od Some discoloration (reddish) k city od Many Some reddish sand. CL Dry to damy black sitty clay w/ Sind: Some discoloration (reddish) k city od Many Some reddish sand. CL Damp.brown sitty clay w/ reddish sand. CL Damp.brown sitty clay w/ reddish sand. CL Damp.greenish and brown sitty clay w/ hed stiff. Oily odor Damp.greenish and brown sitty clay w/ hed stiff. Oily odor. Some discoloration observed. CALIFORNIA ENVIRONMENTAL CONSULTANTS		Towns (Oriting mathod Solid Strin Auger CME-55 Mobile Drill Rig Mole dis Ginche Ceeing Installation Ceta				
CL Damp.brown silty clay w/ readist sand. CL Damp.greenish and brown silty clay w/ readist sand. Wed stiff. oily odor. Some discoloration abserved. CALIFORNIA ENVIRONMENTAL CONSULTANTS	Pocket Torr vane TSF Pocket Penetremeter TSF Blows/11.	Type of Bampie Mumber		Soli Greup Symbol (U.S.C.S.)	Time 10.35 AM Date 10.03.88				
CL Dry to damp black silty clay w/ sind: Some discoloration(reddish) & city od 2 2 3 B3-5 5 CL Blackish to brown damp silty clay, soft: w/ some reddish sand. CL Damp brown silty clay w/ reddish sand. CL Damp greenish and brown silty clay w/ reddish sand. CL Damp greenish and brown silty clay w/ reddish sand. Water encountered at 21 feet. Boring bot CALIFORNIA ENVIRONMENTAL CONSULTANTS					0-9" Asphalt/Base rock, dry.				
Some discoloration(reddish) & ofly od 2 2 3 83-5 5 CL Blackish to brown damp silty clay, soft. W/ some reddish sand. 2 3 7 83-1 10 CL Damp, brown silty clay W/ reddish sand. 2 5 8 8 8 8 8 8 8 8 8 8 8 8 8 8 8 8 8 8									
2 2 3 83-5 5 CL Blackish to brown damp silty clay, soft: W/ some reddish sand. 2 3 7 83-1 10 CL Damp.brown silty clay W/ readish sand soft to med.stiff. Oily odor 3 8 12 83-15 15 CL Damp.greenish and brown silty clay W/ reddish sand soft to med.stiff. Oily odor 4 Med.stiff. Oily odor. Some discoloration observed. 4 Water encountered at 21 feet.Boring bot CALIFORNIA ENVIRONMENTAL CONSULTANTS			$\{ \cdot \}$	CL					
3 R3-5 CL Blackish to brown damp silty clay, soft. 2 W/ some reddish sand. 10 CL Damp brown silty clay w/ reddish sand. 10 Soft to med stiff. Oily odor 11 Soft to med stiff. Oily odor 12 R3-15 CL Damp greenish and brown silty clay w/ reddish sand. 14 Soft to med stiff. Oily odor 15 Soft to med stiff. Oily odor 16 Soft to med stiff. Oily odor 17 Water encountered at 21 feet. Boring bot CALIFORNIA ENVIRONMENTAL CONSULTANTS					Some discoloration (reduish) a only take				
3 B3-5 CL Blackish to brown damp silty clay, soft. w/ some reddish saud. 2 3 7 B3-11 10 CL Damp.brown silty clay w/ reddish saud soft to med.stiff. Oily odor 5 8 7 B3-15 CL Damp.greenish and brown silty clay w/ reddish saud soft to med.stiff. Oily odor 15 CL Damp.greenish and brown silty clay w/ reddish saud soft to med.stiff. Oily odor Wed.stiff. Oily odor. Some discoloration observed. Water encountered at 21 feet.Boring bot CALIFORNIA ENVIRONMENTAL CONSULTANTS				}					
W/ some reddish sand. 2 3 7 83-11 10 CL Damp.brown silty clay w/ reddish sand solf to med.stiff. Only odor 5 8 17 83-15 15 CL Damp.greenish and brown silty clay w/ med.stiff. Only odor. Some discoloration observed. Water encountered at 21 feet.Boring bot CALIFORNIA ENVIRONMENTAL CONSULTANTS									
CL Damp.brown silty clay w/ reddish sand soft to med.stiff. Oily odor 12 B3-15 CL Damp.greenish and brown silty clay w/ med.stiff. Oily odor. Some discoloration observed. Water encountered at 21 feet.Boring bot CALIFORNIA ENVIRONMENTAL CONSULTANTS		B3-5	- 5-	CL					
Damp.brown silty clay w/ reddish shud soft to med.stiff. Oily odor Damp.brown silty clay w/ reddish shud soft to med.stiff. Oily odor Damp.greenish and brown silty clay w/ med.stiff. Oily odor. Some discoloration observed. Water encountered at 21 feet.Boring bot CALIFORNIA ENVIRONMENTAL CONSULTANTS					W. Dome Teacher				
Damp.brown silty clay w/ reddish shud soft to med.stiff. Oily odor Damp.brown silty clay w/ reddish shud soft to med.stiff. Oily odor Damp.greenish and brown silty clay w/ med.stiff. Oily odor. Some discoloration observed. Water encountered at 21 feet.Boring bot CALIFORNIA ENVIRONMENTAL CONSULTANTS			┨ ├─						
Damp.brown silty clay w/ reddish shud soft to med.stiff. Oily odor Damp.brown silty clay w/ reddish shud soft to med.stiff. Oily odor Damp.greenish and brown silty clay w/ med.stiff. Oily odor. Some discoloration observed. Water encountered at 21 feet.Boring bot CALIFORNIA ENVIRONMENTAL CONSULTANTS		·							
Damp.brown silty clay w/ reddish shud soft to med.stiff. Oily odor Damp.brown silty clay w/ reddish shud soft to med.stiff. Oily odor Damp.greenish and brown silty clay w/ med.stiff. Oily odor. Some discoloration observed. Water encountered at 21 feet.Boring bot CALIFORNIA ENVIRONMENTAL CONSULTANTS			1 +						
Soft to med.stiff. Oily odor Soft to med.stiff. Oily odor	2								
Soft to med.stiff. Oily odor Soft to med.stiff. Oily odor	3 7	B3-11	10	CL	Damp.brown silty clay w/ reddish sand				
Damp, greenish and brown silty clay w/ i Med stiff. Oily odor. Some discoloration observed. Water encountered at 21 feet.Boring bot CALIFORNIA ENVIRONMENTAL CONSULTANTS									
Damp, greenish and brown silty clay w/ i Med stiff. Oily odor. Some discoloration observed. Water encountered at 21 feet.Boring bot CALIFORNIA ENVIRONMENTAL CONSULTANTS			1 +-						
Damp, greenish and brown silty clay w/ i Med stiff. Oily odor. Some discoloration observed. Water encountered at 21 feet.Boring bot CALIFORNIA ENVIRONMENTAL CONSULTANTS									
15 CL Damp, greenish and brown silty clay w/ T Med. stiff. Oily odor. Some discoloration observed. Water encountered at 21 feet.Boring bot CALIFORNIA ENVIRONMENTAL CONSULTANTS									
15 CL Damp, greenish and brown silty clay w/ T Med. stiff. Oily odor. Some discoloration observed. Water encountered at 21 feet.Boring bot CALIFORNIA ENVIRONMENTAL CONSULTANTS	5								
Med.stiff. Oily odor. Some discoloration observed. Water encountered at 21 feet.Boring bot CALIFORNIA ENVIRONMENTAL CONSULTANTS	8								
Observed. Water encountered at 21 feet.Boring bot CALIFORNIA ENVIRONMENTAL CONSULTANTS		B3=15	-	CL	Damp, greenish and brown silty clay w/ I				
CALIFORNIA ENVIRONMENTAL CONSULTANTS									
CALIFORNIA ENVIRONMENTAL CONSULTANTS			H	}					
CALIFORNIA ENVIRONMENTAL CONSULTANTS				Ì					
CALIFORNIA ENVIRONMENTAL CONSULTANTS		The second secon	$\left\{ \right.$	ŀ					
CALIFORNIA ENVIRONMENTAL CONSULTANTS		Angel Carlo Car		Ţ					
CALIFORNIA ENVIRONMENTAL CONSULTANTS			H = H	· · · · · ·					
CALIFORNIA ENVIRONMENTAL CONSULTANTS									
			 	V	Water encountered at 21 feet.Boring bot				
	CALIEODA	NA E	1	ط د م	GEFAITAL COLLEGE				
	VALIFUM		INV	KUN	MENIAL CONSULTANIS				

	CHEMICAL ANA	LYSES			SAMPL	식		
WELL CONSTRUCTION	TPH (1)	PID	BLOU	DEPTH (feat)	NUMBER	U.S.C.S.	SOIL DESCRIPTION	0N
	(ng/Kg)	(een)	<u> </u>	0	<u>н</u> П	-		
	 ··· 	 	<u>'</u>	<u></u>		7		·
		i i	1	i	i	1		
	····]	Sand Sitt to Silty Sand with mi	morcher.
			4	5		Melen	Sand, 5.Ht to 5:14, Sand with mi burkgroenish gray, loose, as stain, very slight o	dry.
		120	6 2] '''''	as stain, very slight o	Por
		!			<u> </u>	 		
					<u> </u>	-		
		 				목:	Ground water in book filled Chape, silt to Silt, Chap, do gray, wet, loose, no st	ait @ 9
		20		10		MYCL	Chya, SiH 10 Silty Chy, do	urk groov
		~2				1 /	gray, Net, 1005E, NO 17	412,200
		; 				1		
- i					1	1		
<u> </u>		1		15		nu		
i	2775	100		13	2014	MYCC		
						1	TO 16'	
		1 1	·		1]		
		<u> </u>		!	<u> </u>	4		
		<u> </u>			<u> </u>			
		<u>! </u>	<u></u> !	!	 	-{		
		!!		<u>!</u>	 	-		
<u> </u>		!	 ¦	 ¦	!	-		
1 1	· · · · · · · · · · · · · · · · · · ·	 	<u></u>		!	-		
		 	 		'	1 1		
- -		 	- i	- i	 	1		
- i i	-	i	1	- i	 	1		
		1 1			1			
1			- 1	-	Ī]		
		<u> </u>			<u> </u>]		
! !		!!			<u>!</u>	!		
		! !		<u> </u>	<u> </u>	{		
	-				!			
						1		
					 	1	3	····
-}						1 1		
		- 1	-		-		···	
		1	i	一				
<u> </u>			<u> </u>		\Box			
				\Box		. [
			_ !		<u> </u>		-	<u> </u>
		1	_!	 -	<u> </u>			
		<u>-</u>	<u></u> ļ-			}		<u></u>
			!	!	ļ			
					<u> </u>		-	
 -						 		
- -								
			- -			 		
	i					ŀ		
	5	1				[
1 - 1 - 1 - 1	!	!	1		<u></u>			
ologistiESE	-Mark May	gung	ee,	7 . 6.	0	://er: 5	815	PLAT
Wong's	7	-				LOG	of.BORING	}
- ong s	1 and so 1						•	
	-8014-1				_	-	アハーノ	•

	CHEMICAL ANA	1 YSES	<u> </u>		SAMPLE	1 .	1
WELL CONSTRUCTION	Laboratory TPH	PID	SL DU COUNT	OEPTH (feet)	NUMBER 1	U.S.C.S. Design,	SOIL DESCRIPTION
	(rg/Kg)_	(ppm)	<u> </u>	0			
	<u> </u>]	
		!			!	!	
					 		
•		30	9,	5		mi	filty Clay with trace line, sand, dark greenish gray, slightly moist medium denne good plassicity we stain, trace horocorbanlike abor
			7.7		<u> </u>		malium deure cond planticity
						-	No stain trace horocarbon like after
			6	10		ارمدت	
	360	1050	16		8014-4	> m/mL	Silty Sand with minor clay.
		 				L	light gray sh preen, strong abor
		 					laose, no stain, strong abor
		i	2	10		24	the Cher marsilt war is brown moist, good
		1200	72	15			particity, no stain motorate alor
		1			1	SMEL	Graveth Sand significant clay and sift.
		<u>! </u>					yellowish brown, elightly maist, we stain
		! 		<u> </u>		字? 一	very dight about
		100	19	20			Batcher was it might a serient
	 	100	27				For Clay minor sitt, gravish house, moist,
		i i	i				7,000,000
		1					
		!	9	اعد			
		20	201			CL	Same as emore, moist, no ofor
		!	 ;				
		<u> </u>	- i		 		
			7 1	20	1	Ì	
	50	50	10/7	8	8014-5	CC	Same as above
		!!	!	!	!	<i>,</i>	1031'
			 				
	<u> </u>	-			!		
			i				
					 		
1-1			- 1		 		
		-	- 		1	ł	
 					 	ŀ	
			<u></u> i			· [
			<u>- Ī</u>				
					 	ļ	
!			<u> </u>	!	 		
 					1	.	
					 	ŀ	
			<u>i</u>		<u> </u>	ŀ	
			!		<u> </u>	1	
 		- +					
				-	 	-	
Geologistiess	- Mark Ma		62	1.6	100	://er: 5	015
							PLATE
		-				Loc	of.BORING
Wong's	Tours				J		
1					1	• .	TH-2 Page / ol /
Project Number. 60	-8014-1		8/	2/19	<u>/ [</u>	· ·	Lafe v st
	 	-					

	WELL CONSTRUCTION	CHEMICAL ANA Laboratory TPH (ng/Kg)	LYSES IField PID	BLOU	OEPTH (feet)	SAMPL!	U. S. C. S. Destan.	SOIL DESCRIPTION
				<u> </u>		 	1	
					!			
			NO	8,,	5		CYM4	Clay, trace sandy silt, yellowish browness dents greenish gray,
							<u> </u>	
-			NO	6	10		04	Again Clay Sark graceist gray
		10	20	7,4		9014-8		as ofor
			70	135	15		دد	rediredence, good plusticity,
-						1		no staring as nor distocerder like a Dor
				/2 20 20	20			
		10	70	20		80/4-9	でし 型。ア 二	same as above, light browwish youllow
			פת		25		دد	same as chare, very moist no abor
				!				
			~0	<i>u</i> 1	30		201	5: 1th Gravelly hand significant chery light
			20	122			7/62	5:1ty Gravelly bead significant chery light xellowish brown, very maist malinadore so stain would TD31
							,	
<u> </u>								
				_¦				
				_				
							-	
1		·		-			<u> </u>	
			- 1		-	-	Ĺ	
7					_			
							-	
							- [
			- †	-		!		
<u>.</u> '	seologisties &	-Mark May	pany	40,	P. G.	Or	iller: 5	PLATE
F	Wong's	Tases	:				LOG	of. BORING
F	roiect Number.			#/	17/19		• •	TH-3 Page/41
	Market .	00177		0/	<u>.,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,</u>	<u> </u>		

WELL CONSTRUCTION TPH	Field PID (194) 80 1/40	147		80/4-10	 cc	SOIL DESCRIPTION Clay Lork growish gray, slightly maist, medium danse, geod plasticit, we stain Gravell, Chary Sand, dant graytokick, Elightly minist, slightly leave, forth stain, maken to histocarbon like ober For Chy, minorsilt light green, moist, medium buse, good plasticity, no stai slight odor
CONSTRUCTION TPH (Aq/Kg)	(194) 80 140	4 7g	5 10	80/4-10	sm/cc	Clay fork growish gray, slightly maist, medium danse, geof plasticit, wo stain Generally Chary Send, dant graytoblack Elightlymist, slightly dence fort stain, mosterie hydrocarbon like ofor
(Aq/Kg)	(194) 80 140	4 7g	5 10	80/4-10	sm/cc	Clay look groenish gray, slightly no ist, madium downse, geolphusticit, no stain Generally Chary Send, down graytoblack, Slightlymist, slightly lease, but stain, makenit histocarlow like abor
Z. 5	1/40	4 9 9 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	5 10	80/4-10	5m/cc	Clay look groenish gray, slightly no ist, madium downse, geolphusticit, no stain Generally Chary Send, down graytoblack, Slightlymist, slightly lease, but stain, makenit histocarlow like abor
2.5	/%	4 9 9 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	15		5m/cc	Generally Charry Sand, Sant grayto black, Slightly mist, & lightly Some, Sort stairy, maderate hydrocaster like abor
2.5	/%	4 9 9 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	15		5m/cc	Generally Charry Sand, Sant grayto black, Slightly mist, & lightly Some, Sort stairy, maderate hydrocaster like abor
	/%	4 9 9 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	15		5m/cc	Generally Charry Sand, Sant grayto black, Slightly mist, & lightly Some, Sort stairy, maderate hydrocaster like abor
	/%	4 9 9 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	15		5m/cc	Generally Charry Sand, Sant grayto black, Slightly mist, & lightly Some, Sort stairy, maderate hydrocaster like abor
	20	79	15		 cc	Generally Charry Send down grayto black, Statistically Sense but stairs, maderate histocastan like alor
	20	79	15		 cc	The Charles of the control of the control
	20	79	15		 cc	The Charles and the contract of the contract o
	20	/4 //4 //2	15		 cc	The Charles and the contract of the contract o
						Earth with with amount moist.
450						Fat Chy, mirersilt, light green, noist, medium beuse, good plassicity, us startight adar
450						For Chy, minorsilt lightgreen, noist, medinadouse, good plansticity, us son
450						mediumberse, good plasticity, no sta
450						slight alor
450	20	6	<u> </u>	1		
450	20	6	<u> </u>		i	
450	20	8		1.	<u> </u>	Chren 5:11 Sand Copt areas, saturated.
730		- /7	20	8014-11	5007	course sitt send, cight green, saturded,
		- //-	i			TOU'
				1	1	
	<u>!</u>	!	<u> </u>	 	1	
	<u> </u>	<u>!</u>	<u>; </u>	-	İ	
		-	i 			
		1		1	ł	
		<u>! —</u>	<u> </u>	!!	ł	
	! _	 -	<u> </u>	-	İ	
	 	 	- -	i	j	
	<u> </u>			<u> </u>]	
	1	<u> </u>	!	!!	ł	
	 -	!	<u> </u>	! 	ł	
	-	 	 	11	1	
	 		Ť_]	
	<u> </u>		<u> </u>	 		
	<u> </u>	ļ	!	 	{	
		 	!	 	1	
	1-	 	-	 	1	
	İ		1	·]	
		1	<u> </u>	 	4	
	<u> </u>	<u> </u>	<u> </u>	 	-	
	! - -	 	! 	 	1	
	1	╁─	;	ii —	1	
	Ĺ		j]	
				!	-{	
	! -	 	1-	 	┨	
	-	!	 	 	j	
		i	i_]	
	1			11		
GeologistiESE-Mark Ma	agen	70	r, 18. (s.	-://07:	PLATE
					1.0	CALBORING
Wong's Tax.	· -			1		G of. BORING
wong.	-					TH-4 Page/de
Project Number: 68-8014-1		1	*/z/	191		

I

WELL CONSTRUCTION TPH PID (Ag/Kg) (pp) 20 20 20 20 20 20 20 20 20 2	
CL Fat Clay miner time said destinates 20 57 5 CL Stiphtly moist, medium deutes, pomplets into silt, said dent green, as all 7 10 20 20 10 10 10 10 10 10 10 10 10 10 10 10 10	
20 57 CL Fat Clay miner time same destroyees 20 57 CL Stightly moist, medium device, good planticity, no strice, we all 20 10 10 20 10 2014-14 (no. 25/14 sand, dark green) 10 10 10 10 10 10 10 10 10 10 10 10 10 1	
20 32 5 CL/SM Emagrained End, Chy, Caption and The sold of the sol	
20 32 5 CL/SM Emagrained End, Chy, Caption and The sold of the sol	
20 32 5 CL/SM Emagrained End, Chy, Caption and The sold of the sol	
10 10 20 19 2014-14 (m2 Sightly moist, no stain, no add 10 10 120 10 3014-14 (m2 Sightly moist, no stain, no add 10 13 15 CL/1 M Emagneired End, Clay, Capit gree 10 13 15 CL/1 M poist, and completely as stain, no 20 13 1 5 Silly Clayer Sand, cight pellowed green 20 12 20 3014-15 2 m Septential and cight pellowed green 20 10 10 10 10 10 10 10 10 10 10 10 10 10	
10 10 20 19 2014-14 (m2 Sightly moist, no stain, no add 10 10 120 10 3014-14 (m2 Sightly moist, no stain, no add 10 13 15 CL/1 M Emagneired End, Clay, Capit gree 10 13 15 CL/1 M poist, and completely as stain, no 20 13 1 5 Silly Clayer Sand, cight pellowed green 20 12 20 3014-15 2 m Septential and cight pellowed green 20 10 10 10 10 10 10 10 10 10 10 10 10 10	
20 32 15 CL/3M Europeined Early Clay, light gree moist, medium deurs, an stria, and	forey,
20/32 15 CC/3M Europeined Early Clay, light gree mist, medium deurs, as stria, as	faray,
20/32 15 CC/3M Europeined Early Clay, light gree mist, medium deurs, as stria, as	200
20/32 15 CC/3M Europeined Early Clay, light gree mist, medium deurs, as stria, as	
2 20 Silty Charact Sand, cight yallowsh green	
2 20 Silty Charact Sand, cight yallowsh green	ļ
2 20 Silty Charact Sand, cight yallowsh green	ر
7 20 Silk Chron Sand, light yellowed grace	Dar
7 20 Silk Chron Sand, light yellowed grace	
10 Jul 50/4-15 Serverte an analysis de morte in marche 10 10 10 10 10 10 10 10 10 10 10 10 10	
10 July 50/4-15 Sectional marking the waste in ma	
V 7021'	Dor
]
GeologistiESE-Mark Magarger, R.G. Oriller: 58/5 PL	TE
LOG of BORING	
7115	
Project Number 60-80144 8/2/81 TH-5 Pose/	

: N

PROJECT NUMBER 267

BORING NO. SB-1

PROJECT NAME 2345 E. 14th Street, Oakland CA

PAGE 1

BY LNH

DATE 4/21/97

SURFACE ELEV. 27 FT

RECOVERY (FT/FT)	OVA (PPM)	PENETRA- TION (BLOWS/FT	GROUND WATER LEVELS	DEPTH IN PT.	SAMPLES	GRAPHIC COLUMN	DESCRIPTION
						ייייייייייייייייייייייייייייייייייייייי	ASPHALT AGGREGATE BASE (GW): Brown, dry, no odor.
							CLAY (CL): Black mottled green, scattered sand, silty, dry, no odor.
1.3/2.0	10			5			SAND (SP): Brown, fine-grained, moist to very moist, no odor.
.50/2.0				10			
1.5/2.0	10	1		15			
							CLAYEY SAND (SC/SP): Brown, medium-grained, dry to moist, no odor.
2.0/2.0	8	-		20			
1.5/2.0				25			
2.0/2.0	2	-		30			Boring terminated at 32 feet. Boring sampled to 32 feet. No water level was obtained due to caving.

REMARKS:

Drilled using the "GeoProbe method", 2.0 inch

diameter boreholes. Samples collected in 1.0-inch

LOG OF EXPLORATORY BORING PROJECT NUMBER 267 BORING NO. SB-2 PROJECT NAME 2345 E. 14th Street, Oakland CA PAGE 1 BY LNH DATE 4/21/97 SURFACE ELEV. 27 FT PENETRA-LITHO-RECOVERY OVA TION GRAPHIC DESCRIPTION (FT/FT) (PPM) (BLOWS/F1 COLUMN ASPHALT AGGREGRATE BASE (GW): Brown, dry, no odor. CLAY (CL): Brown, green at 11.5 feet, silty, stiff, dry to moist, hydrocarbon ordor at 11.5. 1.3/2.0 2.0/2.0 46 CLAYEY SAND (SC/CL): Green, fine to medium-grained, moist, hydrocarbon odor. 2.0/2.0 340 2.0/2.0 SAND (SP): Brown, clayey, fine-grained, moist, no odor. 1.0/2.0 CLAYEY SAND (SC/SP): Brown, fine-grained, wet, no odor. Boring terminated at 32.0 feet. Boring sampled to 2.0/2.0 21 32.0 feet.

REMARKS:

Drilled using the "GeoProbe method", 2.0 inch

diameter boreholes. Samples collected in 1.0-inch

PROJECT NUMBER 267

BORING NO. SB-3

PROJECT NAME 2345 E. 14th Street, Oakland CA

PAGE 1

BY LNH

DATE 5/1/97

SURFACE ELEV. 27 FT

ECOVERY	OVA (PPM)	PENETRA- TION (BLOWS/FT	GROUND WATER LEVELS	DEPTH IN PT.	SAMPLES	LITHO- GRAPHIC COLUMN	DESCRIPTION
							ASPHALT
						77777	COBBLESTONE: Light brown, hard
							CONCRETE
						V////	
1.0/2.0	39	-		3			CLAY (CL): Grey to black, sandy, stiff to very stiff, moist, no odor.
			SZ				CLAYEY SAND (SC/CL): Brown, scattered gravel, medium-grained, dry to moist, no odor.
1.0/2.0	40	-		10			
1.5/2.0	16	-		15			
				20			
1.5/2.0	56	-		20			
				25			
1.5/2.0	29	-					
]::::::	SAND (SP): Brown, scattered gravel, fine-grained, moist to wet, no odor.
2.0/2.0	18			30			Boring terminated at 32.0 feet. Boring sampled to 32.0 feet.
					- _		•••
	<u>i</u>			35			

REMARKS:

Drilled using the "GeoProbe method", 2.0 inch

diameter boreholes. Samples collected in 1.0-inch

PROJECT NUMBER 267

BORING NO. SB-4


PROJECT NAME 2345 E. 14th Street, Oakland CA

PAGE 1

BY LNH

DATE 5/1/97

SURFACE ELEV. 27 FT



REMARKS:

Drilled using the "GeoProbe method", 2.0 inch

diameter boreholes. Samples collected in 1.0-inch

PROJECT NUMBER 267

BORING NO. SB-5

PROJECT NAME 2345 E. 14th Street, Oakland CA

PAGE 1

BY LNH

DATE 5/1/97

SURFACE ELEV. 27 FT

RECOVERY (FT/FT)	OVA (PPM)	PENETRA- TION (BLOWS/FT	GROUND WATER LEVELS	DEPTH IN PT.	SAMPLES	LITHO- GRAPHIC COLUMN	DESCRIPTION
						7////	CONCRETE
							AGGREGATE BASE (GW): Brown, dry, no odor.
							CLAY (CL): Grey to black, sandy, soft, no odor.
1.0/2.0	12	-		5			
							CLAYEY SAND (SC/CL): Green, fine-grained, dry, hydrocarbon odor.
2.0/2.0	67	_		10			
			◩	٠			
				15			
2.0/2.0	6	7-					CLAYEY SAND (SC/CL): Brown, fine-grained, moist, no odor.
					<u></u> -		SANDY CLAY (CL/SC): Brown, organics, stiff, dry
				20			no odor.
2.0/2.0	11						
				25			CLAYEY SAND (SC/CL): Brown, fine-grained, wet at 27.0 feet, no odor.
2.0/2.0	6	_					·
						././././ -	Boring terminated at 27.0 feet. Boring sampled to 27.0 feet. A hydrocarbon sheen on the groundwater
		1		30		-	was observed.
				JV			
:						1	•
						1	
				35		1	

REMARKS:

Drilled using the "GeoProbe method", 2.0 inch

diameter boreholes. Samples collected in 1.0-inch

BORING SEMONITORING WELL-LOG WELL-FREE

						• •	ŀ
CLEINT: Stanley Wong		- PROJ	ECT N	AME:	Oakland		
COAP but I Destruct Cultions Collings		C	ATE D	RILLED:	May 22	2001	
The second of th	- SAMPL	ER TYF	'E:	CA Split	Spoon S	ampler	
15 Feet	/IDTH OF			6 3/4 - inc	hes		
DEPTH TO GROUNDWATER AT THE TIME OF DRILLING: N/A				? FVFI	N/A		
ing and the control of the control o					N/A		1
CASING DIAMETER: CASING LENGTH:			EN U	AMETER:-			
SCREEN LENGTH: N/A SLOT SIZE:					C57-5	22125	
DRILLING COMPANY: _Bay Area Exploration		Df	SILLING	3 LIC.:			
CORE SAMPLE CONDITION LEGEND: Undisturbed	Dist	lurbed			No Reco	very	
Berger (1997) Berger					COI	ISTRUC	TION
LOGGED BY Chris Wabuzoh REVIEWED BY: Ola Balogun		SOIL		RECOVERY			
Complete de Carlos de Carlos de Carlos de Carlos de Carlos de Carlos de Carlos de Carlos de Carlos de Carlos d	DEPTH	TYPE	(ppm)		SEAL	CASING	SCREEN
ASPHALT covering							
SANDY CLAY: Brown; about 40% coarse, coarse to fine; hard angular to rounded sand; about 60% clay; moderate plasticity, dry to moist; no hydrocarbon odor, no reaction with		<u>.</u>	0	2,3,5			
hydrochloric acid (HCL).	5	CL					
Maring Commence of the Commenc		,					
		1					
SANDY CLAY: Greenish; about 40% coarse to fine, hard subangular to rounded sand; about 60% clay; moderate to high plasticity, moist; has hydrocarbon odor; no reaction with	.	CL	264				
HCL Mark Comments	10	1		5,11,17			
			١.				
	-			annous e		1	
CLAYEY SAND: Brown; about 40% clay, moderate to high plasticity, about 50% coaste to	, -	CL	4	ļ 1			
fine, hard rounded sand; about 10% gravel size about 1/4 inch; moist to saturated; no hydrocarbon odor; Groundwater water encountered.	15	ŧ					
1	"	1		5,11,13			
4 (2) (2) (2) (2) (2) (2) (2) (2) (2) (2)							
	\vdash						
	20	-					
가득하는 것 같다. 사용하는 것 같은 사용하는 것 같은 사용하는 것 같은 사용하는 것 같은 사용하는 것 같은 것 같은 것 같은 것 같은 것 같은 것 같은 것 같은 것 같							
의 (1994년 - 1985년 - 1985년 - 1985년 - 1985년 - 1984년 - 1985년 - 1985년 - 1985년 - 1985년 - 1985년 - 1985년 - 1985년 - 198 - 1985년 - 1985년 - 1985년 - 1985년 - 1985년 - 1985년 - 1985년 - 1985년 - 1985년 - 1985년 - 1985년 - 1985년 - 1985년 - 1985	<u> </u>	1					1
가 보다 하는 것이 되었다. 19 : 10 : 10 : 10 : 10 : 10 : 10 : 10 :	13	1					
A MORAN TO CONTROL OF THE CONTROL OF	25	1					

BORING-SAMONITORING-WELLOG-WE

Stanley Wong		- PRO.	ECT N	AME:	Oakland	<u>i</u>	
ROJECT ADDRESS: 2345 International Boulevard, Oakland, California		(DATE E	ORILLED:	May 2	2, 2001	
RILLING METHOD: Hollow Stem Auger	- SAMPL	ER TY	PE:	CA Split	Spoon S	ampler	
70TAL DEPTH OF BORING: W	MDTH OF	BORII	VG:	6 3/4 - inc	hes		
DEPTH TO GROUNDWATER AT THE TIME OF DRILLING: NVA				R LEVEL:	N/A		
CASING DIAMETER: N/A CASING LENGTH: N/A				AMETER:	N/A		
SCREEN LENGTH: N/A SLOT SIZE:							
DRILLING COMPANY: Bay Area Exploration			RII L INA	3 LIC :	C57-5	22125	
Milling Company					· 		
CORE SAMPLE CONDITION LEGEND: Undisturbed	Dist	urbed			No Reco	very	
					COI	VSTRUC	TION
LOGGED BY Chris Wabuzoh REVIEWED BY: Ola Balogun	DEPTH	SOIL TYPE		RECOVER	SEAL	CASING	SCREEN
ASPHALT covering	1,						
				<u> </u> 		<u> </u> 	
SANDY CLAY: Brown; about 40% coarse to fine, hard angular to subrounded sand; about 60% clay, moderate plasticity; dry to moist; no hydrocarbon odor; no reaction with hydrochloric acid (HCL).	5	CL	0	4,6,9			
	_		270				
SANDY CLAY: Gray with Iron staining; about 40% coarse to fine, hard subangular to rounded sand; about 60% clay, moderate to high plasticity, moist; has hydrocarbon odor; no reaction with HCL.		ĆL	2.0				
	10			4,10,12	ļ		
		" ,	٠.				
	<u> </u>		* ",				
CLAYEY SAND: Brown, about 30% clay, moderate to high plasticity, about 60% coasre to fine, hard rounded sand; about 10% gravel size about 1/4 inch; moist; no hydrocarbon		sc	1				
odor; no reaction with HCL.	15			8,11,15			
	1						
PROVING ACTION DESIGNATION AND ADDRESS AND							
SANDY CLAY: Brown; about 30% coarse to very fine, hard rounded sand; about 70% cla moderate to high plasticity; moist to saturated; no hydrocarbon odor; no reaction with HCL		sc	0				
	20			5,10,15			
		1					
	7						
	25						

BORING & MONITORING WELL LOS WEIRSES

Charles Marie							l			
CLEINT:		PRO.	JECT N	IAME:	Oaldani May 2					
PROJECT ADDRESS: 2345 International Boulevard, Oaldand, California		· 1	DĂTE (ORILLED:		2, 2001				
DRILLING METHOD: Hollow Stem Auger	CA Spilt Spoon Sampler									
TOTAL DEPTH OF BORING:	WIDTH O	F BORR	NG:	6 3/4 - In	:hee					
DEPTH TO GROUNDWATER AT THE TIME OF DRILLING: N/A	5	TATIC	WATE	R LEVEL:	NA					
CASING DIAMETER: N/A CASING LENGTH:N/A		- SCR	EEN OI	AMETER:	N/A					
SCREEN LENGTH: N/A SLOT SIZE:	<u>.,</u>	N/A		· · · · · · · · · · · · · · · · · · ·						
ORILLING COMPANY: Bay Area Exploration		DI	RELLEN	G LIC.:	C57-5	22125				
	<u> </u>				!- -					
CORE SAMPLE CONDITION LEGENO: Undisturbed	⊠ ⊅•	turbed			No Reco	wery				
					COI	VSTRUC	CTION			
LOGGED BY:Chris Wabuzoh REVIEWED BY: Ole Balogun		SOIL	PID	RECOVERY	1					
ASPHALT covering	DEPTH	TYPE	(ppm)		SEAL	CASHIO	SCREEN			
TOP: I PAGE OF THE										
				<u> </u>	1	•				
NO RECOVERY			,o							
	5			4,6,11						
					1					
				1		1				
SANDY CLAY: Gray; about 30% coarse to fine, hard subangular to rounded sand; about 60% clay, moderate to high pleaticity, moist; has hydrocarbon odor; no reaction with HCL		CL	346	1						
	10			4,8,11						
CLAYEY SAND: Gray, about 30% clay, moderate to high plasticity; about 60% coases to		sc	400							
fine, hard rounded sand; about 10% gravel size about 1/4 inoh; moist; has hydrocarbon odor; no reaction with HCL.	15	1		7,11,18						
		1								
SANDY CLAY: Brown; about 35% coarse to very fine, hard rounded sand; about 60% cl	ay -	1	5							
moderate to high plasticity; about 5% gravel size about 1/4 inch; moist to saturated; no hydrocarbon odor; no reaction with HCL.		SC		4,18,14						
	20	1		4,10,14						
		ľ								
	-	1					İ			
	7				1		1			
	25			1		<u> </u>				

Bioff increasion for the business by Stanley Wong Oakland CLENT: PROJECT NAME: 2345 International Boulevard, Caldend, California May 22, 2001 ROJECT ADDRESS: DATE DRILLED: CA Spik Spoon Sampler Hollow Stem Auger DRILLING METHOD: SAMPLER TYPE:-20 Fest 6 3/4 - Inches TOTAL DEPTH OF BORING:-WIDTH OF BORING:-N/A DEPTH TO GROUNDWATER AT THE TIME OF DRILLING:-STATIC WATER LEVEL: -N/A MA CASING DIAMETER: - CASING LENGTH: -SCREEN DIAMETER:~ SCREEN LENGTH: - SLOT SIZE: --C57-522125 DRILLING COMPANY: Bay Area Exploration -- DRILLING LIC.:--Disturbed CORE SAMPLE CONDITION LEGEND: Undisturbed No Recovery CONSTRUCTION SOIL PID RECOVERY OGGED BY Chris Wabuzon REVIEWED BY: Ole Belogun DEPTHTYPE (ppm) SEAL CASING SCREEN ASPHALT covering SANDY CLAY: Dark brown; about 40% coarse to fine, hard, angular to subrounded sand; 0 about 60% clay, moderate plasticity, moist; no hydrocarbon odor, no reaction with HCL. CL 2,2,3 5 100 SANDY CLAY: Dark gray, about 30% course to fine, hard subangular to rounded sand; about 70% clay, moderate to high pleaticity, moiet; has slight hydrocarbon odor, no CL no reaction with HCL. 10 4,8,10 169 CLAYEY SAND: Greenish gray, about 40% coarse to fine, hard subangular to rounded SC sand, about 50% clay, moderate to high plasticity; moist; has hydrocarbon odor; no reaction WITH HCL 15 8,12,15 CLAYEY SAND: Light brown; about 40% coarse to very fine, hard rounded sand; about Ð SC 50% clay, moderate to high plasticity; some gravel size about 1/4 brich; most to suturated; groundwater encountered; no hydrocarbon odor, no reaction with HCL. 3.6.8 20

n i

EORING & MIONITOR NEW EEL OF AMELIE

Stanley Wong		nino.	ect N	16'085'	Oaldane	,	
ROJECT ADDRESS: 2345 International Boulevard, Cultured, California				ORULLED:	May 2	2, 2001	
PRILLING METHOD: Hollow Stern Auger				CA Split	Spipon 8	ampler	
20 Feet				6 3/4 - inc	hos		
OTAL DEPTH OF BORING: W					N/A		
PEPTH TO GROUNDWATER AT THE TIME OF DRILLING: N/A	S	TATIC	WATE	r Level:	N/A		
CASING DIAMETER:			EEN DI	AMETER:			
CREEN LENGTH: N/A SLOT SIZE: -							
RELING COMPANY: Bay Area Exploration		DI	RILLIN	G LIC.:	<u> C57-5</u>	22125	
CORE SAMPLE CONDITION LEGEND: Undisturbed	Z Dis	turbed			No Reco	rvery	
					CO	ISTRU	STION
		SOIL					
OGGED BY:Chris Waburch REVIEWED BY: Ola Balogun	DEPTH		PiD (ppm)	RECOVERY		CASING	erecen
ASPHALT covering					3CAL	Charles	
		•					
SANDY CLAY: Dark brown; about 40% coarse to fine, hard, singular to subrounded sand;							
about 60% clay, moderate plasticity; moist; no hydrocarbon odor; no reaction with HCL.		CŁ	0	2,3,5			
	-5		-				
				NAME .			
SANDY CLAY; Dark brown; about 30% coarse to fine, hard subangular to rounded sand;	-	* 44	0			l	
about 70% clay, moderate to high plasticity, moist; no hydrocarbon odor; no reaction with		CL	ł	-			
	10		_	4,5,10			
	_						
CLAYEY SAND: Greenlah; shout 30% coarse to fine, hard subangular to rounded send; 70% clay; moderate to high plasticity; some gravel; moist; has hydrocarbon odor; no		5C	40	1			
reaction with HCL	15			5,13,16			
PRINCIPLY CANDY OF A V. C.		1					
GRAVELLY SANDY CLAY: Brown; about 30% coarse to very fine, hard rounded sand; 50% clay, moderate to high plasticity; about 20% gravel size about 1/4 inch; moist to		CL	7				
saturated; groundwater encountered; no hydrocarbon odor; no reaction with HCL.	20		Ì	4,9,11	Ì		
		1					
	7						
	25						
		<u> </u>		<u> </u>	<u></u>		

BORDUCTO WONE TO HAVE MESSES SOR SUBSES MW-6 CLEINT: Stanley Wong **Dakland** ROJECT NAME: 2345 International Boulevard, Oaldand, California May 22, 2001 DATE DRILLED: --Hollow Stern Auger ORILLING METHOD: CA Spit Spoon Sampler 10 Feet TOTAL DEPTH OF BORING: 6 3/4 - inches - WIDTH OF BORING: DEPTH TO GROUNDWATER AT THE TIME OF DRILLING:-STATIC WATER LEVEL: -CASING DIAMETER: N/A - CASING LENGTH: SCREEN DIAMETER: SCREEN LENGTH:-SLOT SIZE: --DRELING COMPANY: BEY Area Exploration C57-522125 CORE SAMPLE CONDITION LEGEND: Disturbed Undisturbed No Recovery CONSTRUCTION SOIL LOGGED BY Chris Wabuzoh PÌD REVIEWED BY: Ola Balogun RECOVERY DEPTHTYPE (ppm) SEAL CASING SCREEN ASPHALT covering SANDY CLAY: Dark brown; about 40% coarse to fine, hard, angular to subrounded sand; about 60% clay, moderate plasticity; moist, no hydrocarbon odor, no reaction with HCL. 0 CL 2.2.2 5 SANDY CLAY: Dark brown; about 30% coarse to fine, hard subangular to rounded sand; Đ about 70% clay, moderate to high pleaticity, moist; no hydrocarbon odor, no reaction with HCL CL 10 1,2,2 15 20