

70500

UNICAL ENGINEER: TINA BERRY

DATE: 12/18/97

SITE # 7376 ADDRESS 4191 First Street CITY Pleasanton

WELLS

DESCRIPTION OF REPAIRS NEEDED: MWH - the well casing has to be trimmed & made shorter, as the well cap is breaking from the pressure of the well lid (Christy lost cover).

PICTURES

Spoke w/ Deanna 1/23/98.
Will coord resurveying of MWH casing
w/ surveying of new wells to be installed.

FILE #	<u>7376</u>	SS	<input checked="" type="checkbox"/>	BP	<input type="checkbox"/>
RPT	<input type="checkbox"/>	QM	<input type="checkbox"/>	TRANSMITTAL	<input type="checkbox"/>
1	<input type="checkbox"/>	2	<input type="checkbox"/>	3	<input type="checkbox"/>
	<input type="checkbox"/>	4	<input type="checkbox"/>	5	<input type="checkbox"/>
	<input type="checkbox"/>		<input type="checkbox"/>	6	<input checked="" type="checkbox"/>

If any modifications or repairs are to be done please advise Mr. Nubar Sabian (MPDS) via FAX (510) 689-1918.

DRUMS OF UNKNOWN ORIGIN
OBSERVED BY MPDS, SERVICES, INC.
DURING ROUTINE MONITORING/SAMPLING

UNOCAL SERVICE STATION NO.	LOCATION	ADDRESS
7376	4191, 1 st Str.	Pleasanton
- DESCRIPTION OF DRUMS -		
NUMBER OF DRUMS: 1		
DRUM TYPE: E-Type.		
LABELING: HAZARDOUS YELLOW LABEL - LIQUID WASTE FROM SUMP.		
CONTENTS: 32 gals water This is dealer's responsibility.		
DATE: 12/18/97 UNOCAL PROJECT ENGINEER: Tina Berry		