



GROUNDWATER TECHNOLOGY, INC.

4057 Port Chicago Highway, Concord, CA 94520 (415) 671-2387

FAX: (415) 685-9148

January 7, 1993

Project No. 020501659

Ms. Anne Lunt
Safety-Kleen Corporation
P.O. Box 1429
San Pedro, CA 90733-1421

RE: Product Recovery Volume-December 1992
Safety-Kleen Facility
400 Market Street
Oakland, California

Dear Ms. Lunt:

The purpose of this letter is to report the product recovery volume during the month of December 1992 for the site referenced above. The recovery well (RW) and monitoring well MW-9 have been monitored for product thickness and has been removed from the wells by hand balling on a weekly basis.

Table 1 (attached) provides a tabulation of product thickness measurements for the two wells and the approximate product volumes removed from the wells. Please note that on December 22, a tanker truck was parked over the wells for loading so the wells were not accessible on that day.

Please contact me if you have any questions or require additional information. I can be reached in our Concord office at (510) 671-2387.

Sincerely,
GROUNDWATER TECHNOLOGY, INC.

Michael J. Wray
Project Manager

MJW:lbw
Attachment

cc: Vicki Ness
C:\wp51\files\mikew\L1659A.MW

TABLE 1
WEEKLY PRODUCT RECOVERY VOLUME
SAFETY-KLEEN CORPORATION FACILITY
400 MARKET STREET, OAKLAND, CALIFORNIA

	RW			MW-9		
	Depth-to-Product (ft)	Product Thickness (ft)	Approx. Product Volume Bailed (gals)	Depth-to-Product (ft)	Product Thickness (ft)	Approx. Product Volume Bailed (gals)
12/01/92	8.19	0.54	1	9.50	1.0	.5
12/09/92	7.56	0.26	.5	8.45	0.87	.5
12/15/92	7.15	0.49	1	8.00	0.74	<.5
12/22/92	NM	NM	--	NM	NM	--
12/29/92	6.82	0.43	.5	7.75	0.85	.5

NM = Not measured; tanker truck parked over both wells
 -- = Product not recovered