Ultramar

Ultramar Inc. P.O. Box 466 525 W. Third Street Hanford, CA 93232-0466 (209) 582-0241

Telecopy: 209-585-5685 Credit 209-583-3330 Administrative 209-583-3302 Information Services 209-583-3358 Accounting

5/99 - were add't air sponge wells pampled across street (Sateway parting)

Cont. ange of mu. 2, Mw-6 and NW-7

when we get & gtro of < 300 ppb bergene, then can May 17, 1999

mother dosine. Have we looked at bis earameters at site?

Ms. Eva Chu Department of Environmental Health Alameda County Health Care Services 1131 Harbor Bay Parkway, Room 250 Alameda, CA 94502-6577

SUBJECT:

BEACON STATION NO. 604, 1619 FIRST STREET, LIVERMORE,

CALIFORNIA

Dear Ms. Chu:

Enclosed is a copy of the Fourth Quarter 1998 Ground Water Monitoring Report for the above-referenced Ultramar facility. Also included is a copy of the Quarterly Status Report

Please call if you have any questions regarding this site.

Sincerely,

ULTRAMAR INC.

Terrence A. Fox

Senior Project Manager

Marketing Environmental Department

Enclosures

cc w/encl:

Mr. Cecil Fox, San Francisco Bay Region, RWQCB

Walter and Dorothy Anderson, 1091 Buckingham Drive, Los Altos,

CA 94024

SE : 4 Md 61 X4M 66

PROTECTION



Ultramar

Ultramar Inc. P.O. Box 466 525 W. Third Street Hanford, CA 93232-0466 (209) 582-0241 Telecopy: 209-585-5685 Credit 209-583-3330 Administrative 209-583-3302 Information Services 209-583-3358 Accounting

ENVIRONMENTAL PROJECT QUARTERLY STATUS REPORT

DATE REPORT SUBMITTED: May 17, 1999 QUARTER ENDING: December 31, 1998

SERVICE STATION NO.: 604

ADDRESS: 1619 First Street, Livermore, CA

COUNTY: Alameda

ULTRAMAR CONTACT: Terrence A. Fox TEL. NO: 559-583-3345

BACKGROUND:

In November 1992, three underground storage tanks were removed. Hydrocarbons were detected and the excavation was extended to a depth of 27 feet in the southwest corner. Hydrocarbons were detected in the sample collected from the base of the overexcavation.

In May and June 1993, three monitoring wells (MW-1 through MW-3), three vapor wells (VW-1 through VW-3), and one boring were drilled. The soil plume has been defined.

The site has been placed on a quarterly monitoring program.

In March 29 and 30, 1994, four additional offsite wells (MW-4 through MW-7) were installed. The ground-water plume is not defined downgradient.

In June 1994, performed assessment on the Livermore Arcade Shopping Center Property by drilling borings and collecting ground-water samples using a Hydropunch tool.

In June 1994, performed vapor extraction and ground-water extraction tests.

In September and October 1995, installed of vapor extraction and air sparging wells.

In January, 1997, discontinued operation of the remediation system.

In August 1997, submitted RBCA.





Beacon Station 604 Quarterly Status Report Page 2

ÇT + 15 K

SUMMARY OF THIS QUARTER'S ACTIVITIES:

Performed quarterly monitoring on November 30, 1998.

RESULT OF QUARTERLY MONITORING:

Monitoring data indicates that the benzene concentrations were not detected in MW-1 and MW-5. The benzene concentrations were detected MW-2, MW-6, and MW-7. MW-3 and MW-4 were not sampled this quarter.

PROPOSED ACTIVITY OR WORK FOR NEXT QUARTER:

ACTIVITY

ESTIMATED COMPLETION DATE

Continue quarterly monitoring program.

Awaiting response on request for closure.