ALAMEDA COUNTY

HEALTH CARE SERVICES





DAVID J. KEARS, Agency Director

Certified Mail #: 7002 2030 0006 9574 2638

January 13, 2009

Site Name & Address:

Oakland, CA 94607

SHELL #13-5700

105 5TH ST

ENVIRONMENTAL HEALTH SERVICES

ENVIRONMENTAL PROTECTION 1131 Harbor Bay Parkway, Suite 250

Alameda, CA 94502-6577

(510) 567-6700 FAX (510) 337-9335

NOTICE OF RESPONSIBILITY

Local ID:

RO0000487

Related ID:

3849

RWQCB ID:

01-2300

Global ID:

T0600102116

Responsible Party:

ARTHUR R & MARY A. HANSEN ARTHUR & MARY HANSEN TRUST ETAL 820 LOYOLA DR LOS ALTOS CA 94024-5919 Date First Reported: 5/14/1998

Substance:

8006619 Gasoline-Automotive (motor gasoline

and additives), leaded & unleaded

Funding for Oversight: LOPS - LOP State Fund

Multiple RPs?: Yes

Pursuant to sections 25297.1 and 25297.15 of the Health and Safety Code, you are hereby notified that the above site has been placed in the Local Oversight Program and the individual(s) or entity(ies) shown above, or on the attached list, has (have) been identified as the party(ies) responsible for investigation and cleanup of the above site. Section 25297.15 further requires the primary or active Responsible Party to notify all current record owners of fee title before the local agency considers cleanup or site closure proposals or issues a closure letter. For purposes of implementing section 25297.15, this agency has identified SHELL OIL PRODUCTS US as the primary or active Responsible Party. It is the responsibility of the primary or active Responsible Party to submit a letter to this agency, within 20 calendar days of receipt of this notice that identifies all current record owners of fee title. It is also the responsibility of the primary or active Responsible Party to certify to the local agency that the required notifications have been made at the time a cleanup or site closure proposal is made or before the local agency makes a determination that no further action is required. If property ownership changes in the future, you must notify this local agency within 20 calendar days from when you are informed of the change.

Any action or inaction by this local agency associated with corrective action, including responsible party identification, is subject to petition to the State Water Resources Control Board. Petitions must be filed within 30 days from the date of the action/inaction. To obtain petition procedures, please FAX your request to the State Water Board at (916) 341-5808 or telephone (916) 341-5650.

Pursuant to section 25296.10(c)(6) of the Health and Safety Code, a responsible party may request the designation of an administering agency when required to conduct corrective action. Please contact this office for further information about the designation process.

Please contact your caseworker WICKHAM, JERRY, at this office at (510)567-6791 if you have questions regarding your site.

ARIU LIEVI, Difector Contract Project Director Date: JAN14, 2009

Action: Add

Reason: Add RP

ALAMEDA COUNTY ENVIRONMENTAL HEALTH LUFT LOCAL OVERSIGHT PROGRAM

ATTACHMENT A - RESPONSIBLE PARTIES DATA SHEET

January 14, 2009

Site Name & Address: SHELL #13-5700 105 5TH ST Oakland, CA 94607 Local ID: RO0000487
Related ID: 3849
RWQCB ID: 01-2300

Global ID: T0600102116

All Responsible Parties

RP has been named a Primary RP - DENIS BROWN SHELL OIL PRODUCTS US

20945 S WILMINGTON AVE | CARSON, CA 90810-1039 | Phone (707) 865-0251

RP has been named a RP - ARTHUR R & MARY A HANSEN ARTHUR & MARY HANSEN TRUST ETAL


820 LOYOLA DR | LOS ALTOS, CA 94024-5919 | Phone No Phone Number Listed

Responsible Party Identification Background

Alameda County Environmental Health (ACEH) names a "Responsible Party," as defined under 23 C.C.R Sec. 2720. Section 2720 defines a responsible party 4 ways. An RP can be:

- 1. "Any person who owns or operates an underground storage tank used for the storage of any hazardous substance."
- 2. "In the case of any underground storage tank no longer in use, any person who owned or operated the underground storage tank immediately before the discontinuation of its use."
- 3. "Any owner of property where an unauthorized release of a hazardous substance from an underground storage tank has occurred."
- 4. "Any person who had or has control over an underground storage tank at the time of or following an unauthorized release of a hazardous substance."

ACEH has named the responsible parties for this site as detailed below.



UNITED	STATES	POSTAL	SERVICE



First-Class Mali Postage & Fees Paid USPS Permit No. G-10

• Sender: Please print your name, address, and ZIP+4 this box •

22

Environmental Health Services Environmental Protection 1131 Harbor Bay Parkway Alameda, CA 94502-6577 Attn: Jerry, RQ#487

پ 28

Mandalahahahahahahallmakahall

COMPLETE THIS SECTION ON DELIVERY SENDER: COMPLETE THIS SECTION A. Signature ■ Complete items 1, 2, and 3. Also complete □ Agent item 4 if Restricted Delivery is desired. **∡√**□ Addressee Print your name and address on the reverse so that we can return the card to you. C. Date of Delivery Attach this card to the back of the mailpiece, or on the front if space permits. D. Is delivery address different from item 1? ☐ Yes 1. Article Addressed to: If YES, enter delivery address below: ☐ No ARTHUR R & MARY A. HANSEN ARTHUR & MARY HANSEN TRUST **ETAL** 3. Service Type **820 LOYOLA DRIVE** ☐ Certified Mail □ Express Mail ☐ Return Receipt for Merchandise LOS ALTOS, CA 94024-5919 □ Registered ☐ C.O.D. ☐ Insured Mail 4. Restricted Delivery? (Extra Fee) ☐ Yes 2. Article Number 7002 2030 0006 9574 **2638** (Transfer from service label) 102595-02-M-1540 PS Form 3811, February 2004 Domestic Return Receipt

ATTACHMENT A - RESPONSIBLE PARTIES DATA SHEET (Continued)

January 14, 2009

Responsible Party Identification

Existence of Unauthorized Release

During removal of five gasoline dispensers, two diesel dispensers, and associated piping in November and December 1996, eight soil samples were collected. Total petroleum hydrocarbons as gasoline were detected in all eight soil samples at concentrations up to 3,500 parts per million. Total petroleum hydrocarbons as diesel were detected in three of eight soil samples at concentrations up to 14,000 parts per million. Based on the soil sampling results, an Underground Storage Tank Unauthorized Release Form was filed on December 5, 1996.

Responsible Party Identification

Shell Oil Products is a responsible party for the fuel leak because they were the business owner, tank owner, and tank operator at the time of the unauthorized release (Definition 1) and had control of the UST at the time of or following an unauthorized release (Definition 4).

The Arthur R. and Mary A. Hansen Trust et al purchased the property in May 1995. The Arthur R. and Mary A. Hansen Trust et al is a responsible party because they are the current owner of the property where an unauthorized release occurred (Definition 3).