AGENCY

DAVID J. KEARS, Agency Director



ENVIRONMENTAL HEALTH SERVICES ENVIRONMENTAL PROTECTION (LOP) 1131 Harbor Bay Parkway, Suite 250 Alameda, CA 94502-6577 (510) 567-6700 FAX (510) 337-9335

REMEDIAL ACTION COMPLETION CERTIFICATION

StID 3946 - 921 98th Ave, Oakland, CA 94603 (2-25,000 gallon diesel USTs removed in August 6, 1990)

March 6, 1997

Mr. Rod Trabert Fleichmann Yeast 921 98th Ave Oakland, CA 94603

Dear Mr. Trabert:

This letter confirms the completion of site investigation and remedial action for the underground storage tank(s) formerly located at the above-described location. Thank you for your cooperation throughout this investigation. Your willingness and promptness in responding to our inquiries concerning the former underground storage tanks are greatly appreciated.

Based on information in the above-referenced file and with the provision that the information provided to this agency was accurate and representative of site conditions, no further action related to the underground tank release is required.

This notice is issued pursuant to a regulation contained in Title 23, Section 2721(e) of the California Code of Regulations.

Please contact our office if you have any questions regarding this matter.

Sincerely,

Mee Ling Tung, Director

enclosure

cc: Chief, Division of Environmental Protection

Kevin Graves, RWQCB

Lori Casias, SWRCB (with attachment)

Cheryl Gordon, UST Cleanup Fund

files-ec (fleichs)

01-0644

CHALLY CONTROL BOARD CLOSURE SUMMARY Leaking Underground Fuel Storage Tank Program

i. AGENCY INFORMATION

į,

Date: November 6, 1996

Agency name: Alameda County-HazMat Address: 1131 Harbor Bay Pkwy

City/State/Zip: Alameda, CA 94502 Phone: (510) 567-6700

Responsible staff person: Eva Chu Title: Hazardous Materials Spec.

II. CASE INFORMATION

Site facility name: Fleichmann Nabisco Brand, Inc

Site facility address: 921 98th Ave, Oakland, CA 94603

RB LUSTIS Case No: N/A Local Case No./LOP Case No.: 3946

URF filing date: 8/22/90 SWEEPS No: N/A

Responsible Parties: Addresses: Phone Numbers:

Rod Trabert 921 98th Ave 510/633-2245

Fleichmann Yeast Oakland, CA 94603

Closed in-place Date: Tank Size in Contents: No: gal.: or removed?: 8/6/90 1 25,000 Diesel #2 Removed 2 Diesel #6 Removed 8/6/90 25,000

III. RELEASE AND SITE CHARACTERIZATION INFORMATION

Cause and type of release: Leaking diesel #6 UST

Site characterization complete? YES

Date approved by oversight agency: 9/17/96

Monitoring Wells installed? Yes Number: 5 (4 monitoring wells, 1

extraction well)

Proper screened interval? Yes

Highest GW depth below ground surface: 9.55' Lowest depth: 12.2'bgs in MW-2

Flow direction: W, SW

Most sensitive current use: Industrial

Are drinking water wells affected? No Aquifer name: Unknown Is surface water affected? No Nearest affected SW name: NA Off-site beneficial use impacts (addresses/locations): None

Report(s) on file? YES Where is report(s) filed? Alameda County
1131 Harbor Bay Pkwy
Alameda, CA 94502

Treatment and Disposal of Affected Material:

<u>Material</u>	Amount (include units)	Action (Treatment or Disposal w/destination)	<u>Date</u>
Tank Piping	2 USTs	Erickson, in Richmond	8/6/90
Free Prod	uct 133 gal.	Refinery Services, in Patterso Gibson Oil, in Redwood City	n, and
	~860 cy er 10,000 gal. 3 million gal.	GSX Services L.F. in Buttonwillow, Refinery Services Treated and used as make-up water c from June 1991 to June 1995.	Sep 1990

Maximum Documented Contaminant		ncentrations (ppm) <u>After</u>	Before <u>Water</u> <u>Before</u>	(ppb)	Cleanup
TPH (Gas) TPH (Diesel)	NA 6,760	NA 6,760	26 4 FP	71 3,900	
Benzene Toluene Ethylbenzene Xylenes	ND 0.08 0.07 2.6	ND 0.08 0.07 2.6	10 10 10 31	1.2 ND ND 0.81	
Oil & Grease	43,550	43,550	73ppi	m 34ppm	
Other HVOCs SVOCs			ND ND		

NOTE: 1 Dissolved phase from well MW-3

IV. CLOSURE

Does completed corrective action protect existing beneficial uses per the Regional Board Basin Plan? **Undetermined**Does completed corrective action protect potential beneficial uses per the Regional Board Basin Plan? **Undetermined**Does corrective action protect public health for current land use? **YES**Site management requirements: **None**

Should corrective action be reviewed if land use changes? YES
Monitoring wells Decommissioned: None, pending site closure
Number Decommissioned: 0 Number Retained: 5
List enforcement actions taken: None

List enforcement actions rescinded: NA

V. LOCAL AGENCY REPRESENTATIVE DATA

Name: Eva Chu

Title: Haz Mat Specialist

Signature: Stull

Date: 12/4/94

Reviewed by

Name: Madhulla Logan

Title: Haz Mat Specialist

Signature:

Date: ///6/96

Name: Thomas Peacock

Title: Supervisor

Signature:

Date: 11-9

VI. RWQCB NOTIFICATION

Date Submitted to RB: 12/5/36

RB Response:

RWQCB Staff Name/: Kevin Graves

Title: AWRCE

Signature:

Date: IVilal

VII. ADDITIONAL COMMENTS, DATA, ETC.

Two 25,000 gallon USTs (one containing Diesel #2, one containing diesel #6) were in a common pit and were supported by four concrete saddles. When the diesel #6 UST failed a tank pressure test, it was decided to removed both USTs. Actual tank removal occurred on August 6, 1990.

At the time of the tank removal, groundwater was encountered at 13' below ground surface (bgs). Approximately three inches of floating product was present on top of the water. A sheet pile shoring system was installed along the northeast and northwest sides of the tank pit to protect the integrity of the railroad tracks. Visibly stained soil (~700 cy) below the tanks was removed to the extent possible (to a depth of 13' to 17' bgs, concurrently with dewatering). Six discrete soil samples (SS1 through SS6) were collected from the base and sidewalls of the tank pit at ~13' bgs. A "grab" groundwater sample was also collected.

Analytical results identifed elevated levels of Total Petroleum Hydrocarbons as Diesel (TPHd) and Total Oil and Grease (TOG), and low to non-detectable levels of benzene, toluene, ethylbenzene, and xylenes (BTEX) in soil and groundwater. (See Figs 1, 2, and Table 1)

In September 1990 three groundwater monitoring wells (MW-1 through MW-3) and five soil borings (SB-1 through SB-5) were installed to delineate the extent of the contaminant plume in soil and groundwater. Soil samples taken around the perimeter of the excavation indicate that the 100 ppm TPHd isoconcentration boundary for the hydrocarbons in soil appears to be within

12' of the excavation. (See Fig 3, Table 2.) Further excavation was not possible without compromising the integrity of the railroad spur to the north, and Building 16 to the southwest. Elevated levels of hydrocarbons in groundwater were identified from well MW-3. It appeared the hydrocarbon plume was pooling in the tank field and possibly influenced by Building 16. (See Fig 3, Table 4)

In December 1990, when the excavation was backfilled, an extraction well EW-1 was installed within the former tank field, near Building 16. The pit bottom was filled with drain rocks (from 11 to 17' bgs) to facilitate groundwater extraction. (See Fig 4.) Monitoring well MW-4 and soil boring SB-6 were installed to further delineate the extent of groundwater contamination downgradient of the tank excavation, and soil contamination southeast of the tank pit, respectively. Boring SB-6 contained up to 1,700 ppm TPHd and low levels of total BTEX at 10' bgs. It was not possible to identify the 100 ppm TPH boundary in the southeast direction since the railroad tracks, Building 19, and storage tanks prohibited further soil borehole drilling. (See Fig 3, Table 3)

The groundwater extraction system consisted of a 3,000 gallon oil/water separator, four 55-gallon carbon adsorption canisters, and a 3,000 gallon filtrate tank. Filtrated water was pumped to cooling towers as makeup water. Continuous groundwater extraction began in February 1992 and was discontinued in June 1993 due to the discovery of D-NAPL in groundwater. Quarterly monitoring of onsite wells began in May 1992. Approximately three million gallons of water was extracted and treated from February 1992 to June 1993. However, groundwater extraction/treatment did not seem very effective in removing hydrocarbons since the original four carbon-canisters were only changed once.

In June 1993 well MW-3 and the extraction well were found to contain a dense, non-aqueous phase liquid (D-NAPL). The D-NAPL was analyzed and found not to contain volatile or semi-volatile compounds, was non-reactive, non-corrosive, and non-ignitable. The sample appeared to be highly viscous and resembled weathered No. 2 or No. 6 diesel fuel, with peaks eluting in the C10 to beyond C35 range, with a maximum near C28. D-NAPL was removed by vacuum pumping at two week intervals. A total of approximately 133 gallons of product was removed from June 1993 to March 1994, at which time the D-NAPL recovery rate decreased to below pratical levels. D-NAPL recovery was discontinued in April 1994. There is currently approximately 4" to 6" of D-NAPL in well MW-3.

A review of the boring logs indicate that the site is underlain by a thin upper fill layer of sands and gravels. Clays and silts underlie the fill with silt concentrations increasing with depth. Sands were encountered beginning 15' to 20' bgs in wells MW-2 and MW-3. Groundwater was encountered at ~15' bgs in the wells during installation and stablilized at ~12' bgs, suggesting that the aquifer is confined, or semi-confined. Depth to water has ranged from 8.01' to 12.20' bgs. (See boring/well logs)

Soil contamination appears to be limited to a depth of 10' to 15' bgs, and the 100ppm TPHd isoconcentration boundary is within 12 lateral feet of the excavation.

Groundwater from well MW-3 continues to contain elevated levels of dissolved TPHd and TOG, as well as D-NAPL. However, only low levels of TPHg and BTEX have been identified. PNAs have not been detected in well MW-3. Low levels of TPHd and TPHg have been detected in well MW-2, located ~12' west of the former UST excavation. Wells MW-1 and MW-4 have not identifed detectable concentrations of petroleum hydrocarbons.

D-NAPLs do not migrate with groundwater flow as dissolved and floating products do. Instead, they follow geologic contours, moving through the most permeable substrata. Since this site is underlain by clays and silts to 15'bgs, it is likely that D-NAPL will migrate towards the permeable backfill material (drain rocks) within the former tank excavation, from 11' to 17' bgs, rather than away from the drainage gallery. This appears to be the case since D-NAPL has not been identified in well MW-2.

In summary, case closure is recommended because:


- o the leak and ongoing sources have been removed;
- o the site has been adequately characterized;
- the dissolved plume is not migrating;
- no water wells, surface water, or other sensitive receptors are likely to be impacted.


There is a production well onsite ~420' south of the former tank excavation. Impact to this cross-gradient well is not likely; and,


 the site presents no significant risk to human health or the environment, based on ASTMs RBCA Tier 1 Look-up Table.


Although residual TPHd is still in groundwater, the chemicals of concern, BTEX and PNAs, have not been detected at levels which would pose a risk to human health.


fleich6

















 $\frac{\text{TABLE 1}}{\text{Summary of Soil and Groundwater Analytical Results}}$

Concentration (ppm)

Sample Number	Oil & Grease	TPH (as <u>Diesel)</u>	Benzene	<u>Toluene</u>	Ethyl- <u>benzene</u>	Xylene
SS1	29,000	199430	ND _{0.03}	0.08	ND _{0.03}	ND _{0.06}
SS2	345	80	ND _{0.03}	ND _{0.03}	ND _{0.03}	ND _{0.06}
223	2,230	390	ND _{0.03}	ND _{0.03}	ND _{0.03}	ND _{0.06}
SS4	41,385	~-6<3°,200⊛	ND _{0.03}	ND _{0.03}	0.04	2.6
SS5	€::10°,720°	~3,600 _{3%}	ND _{0.03}	0.06	0.03	0.5
SS6	***43°,550	· · 6 ₃ 760·	ND _{0.03}	ND _{0.03}	0.07	0.5
*	17,825	4,700	ND _{0.15}	ND _{0.15}	ND 0.15	ND 0.3
8-1	NA .	30	0.022	0.022	0.015	0.048

 ND_{χ} - not detected at x limit of detection

NA - not analyzed

** - composite of samples CS1 to CS8

TABLE 2 SOIL SAMPLE ANALYTICAL RESULTS

Sample ID	Date Collected	Sample Depth (ft)	Total BTEX (ppm)	TPH-D (ppm)	Oil and Grease (ppm)	TRPH (ppm)
SS1	08/06/90	13	0.08	1,430	29,000	NA
SS2	08/06/90	13	ND	80	345	NA
SS3	08/06/90	13	ND	390	2,230	NA
SS4	08/06/90	13	2.64	3,200	41,385	NA
SS5	08/06/90	13	0.53	3,600	10,720	NA
SS6	08/06/90	13	0.57	6,760	43,550	NA
CS	08/06/90	13	ND	4,700	17,825	NA
MW2	09/14/90	15	ND	ND	ND	ND
MW3	09/14/90	15	ND	ND	ND	ND
SB1	09/13/90	15	ND	ND	ND	ND
SB2	09/13/90	10	0.072	1,000	140	730
SB3	09/13/90	15	ND	5	ND	ND
SB4	09/13/90	15	ND	3.4	ND	ND
SB5	09/14/90	15	0.033	110	ND	80
SB6	12/17/90	10	0.25	1,700	NA	1,200
SB6	12/17/90	15	ND	14	NA	ND

Notes:

ND = not detected at the method detection limit

NA = not analyzed

TABLE • 3
HISTORICAL GROUNDWATER ELEVATION DATA

Well I.D.	Date	Datum (ft AMSL)	Depth of Groundwater (ft)	Groundwater Elevation (ft AMSL)	NAPL Thickness (inches)
MW-1	11/30/92	22.92	12.11	10.81	277.6
1	03/03/93	1	9.41	13.51	NM
	06/02/93	ĺ	10.74		NM
	08/31/93	ł	11.44	12.18	NM
	11/30/93			11.48	NM
	03/02/94	Í	10.66 9.61	12.26	NM
	06/07/94	ļ		13.31	NM
	04/14/95		11.09	11.83	0
	07/11/95	İ	9.72	13.20	0
	10/19/95	}	10.60	12.32) 0
	01/10/96		11.16	11.76	0
	06/12/96		10.44	12.48	0
	50/12/90		10.36	12.56	ļ <u> </u>
MW-2	11/30/92	22.76	12.20	10.56	NM
	03/03/93		9.55	13.21	NM
	06/02/93		10.86	11.90	NM
	08/31/93		11.56	11.20	NM
	11/30/93		10.70	12.06	NM
	03/02/94		9.72	13.04	NM
	06/07/94		11.20	11.56	o o
	04/14/95		9.89	12.97	ľ
	07/11/95		10.72	12.04	l ŏ
	10/19/95		11.28	11.48	ď
	01/10/96		10.58	12.18	ŏ
	06/12/96		10.50	12.26	ŏ
MW-3	11/30/92	22.26	11.62	10.64	17.6
	03/03/93		9.15	13.11	. NM
	06/02/93		8.01		NM
	08/31/93		NM	14.25	NM
	11/30/93	1	10.07	10.10	NM
	03/02/94	.	9.17	12.19	NM
	06/07/94		11.15	13.09	NM
	04/14/95	ļ.		11.11	6
	07/11/95		9.29	12.99	NM
	10/19/95		10.23	12.03	5
	01/10/96		10.68	11.58	3.6
	06/12/96	_	9.96 9.90	12.30 12.36	4 4
MW-4		01.71			4
147 44 (11/30/92	21.71	11.26	10.45	NM
	03/03/93		8.61	13.10	NM
	06/02/93	1	9.87	11.84	NM
	08/31/93	1	10.66	11.05	NM
	11/30/93		9.78	11.93	NM
	03/02/94	ĺ	8.85	12.86	NM
	06/07/94		10.25	11.46	0
	04/14/95		9.01	12.70	0
	07/11/95	Ì	9.82	11.89	Ō
	10/19/95		10.36	11.35	Ŏ
	01/10/96	1	9.67	12.04	ŏ
	06/12/96	_ 1	9.59	12.12	Ö

Notes:

ft = feet


ft AMSL = feet above mean sea level

NM = not measured

NAPL = Non-aqueous phase liquid

TABLE **6 4**ANALYTICAL RESULTS FOR GROUNDWATER SAMPLES

Sample I.D.	Date Sampled	TPH-G (ppb)	TPH-D (ppb)	Benzene (ppb)	Toluene (ppb)	Ethyl Benzene (ppb)	Total Xylenes (ppb)	Oil & Grease (ppm)
B-1	08/12/90	NAN	30,000	22	22	15	48	NAN
MW-1	09/26/90	<50	51	<0.5	<0.5	<0.5	<0.5	NAN
	11/30/92	<50	<50	<0.5	<0.5	<0.5	<0.5	0.03
	03/03/93	<50	<50	5.0 ¹	5.0¹	5.0¹	5.01	<0.01
	06/02/93	<50	<50	<0.5	<0.5	<0.5	<0.5	<0.01
	08/31/93	<50	<50	<0.5	<0.5	<0.5	<0.5	<1.0
	11/30/93	<50	<50	<0.5	<0.5	<0.5	<0.5	<5.0
	03/02/94	<50	<50	<0.5	<0.5	<0.5	<0.5	<5.0
	06/07/94	<50	<50	<0.5	<0.5	<0.5	<0.5	<0.5
	04/14/95	<50	<50	<0.5	<0.5	<0.5	<0.5	<1.0
	07/11/95	NA	NA	NA	NA.	NA NA	NA	NA
	10/19/95	NA NA	NA	NA	NA	NA	NA NA	NA
MW-2	09/26/90	<50	89	<0.5	<0.5	<0.5	<0.5	NAN
	11/30/92	100	<50	12¹	12¹	12 ¹	12¹	0.03
	03/03/93	<50	<50	12.4 ^t	12.4 ¹	12.4 ^t	12.4 ¹	<0.01
	06/02/93	<50	<50	<0.5	<0.5	<0.5	<0.5	<0.01
	08/31/93	<50	<50	<0.5	<0.5	<0.5	<0.5	<1.0
	11/30/93	60	460	<0.5	<0.5	<0.5	<0.5	<5.0
	03/02/94	<50	<50	<0.5	<0.5	<0.5	<0.5	<5.0
	06/07/94	<50	<50	<0.5	<0.5	<0.5	<0.5	<0.5
	04/14/95	<50	110	<0.5	<0.5	<0.5	<0.5	<1.0
	07/11/95	NA	NA	NA	NA	NA.	NA	NA
	10/19/95	81	77	<0.5	<0.5	<0.5	<0.5	<1.0
	06/12/96	<50	86	<0.5	<0.5	<0.5	<0.5	<5.0



(CONTINUED)

Sample I.D.	Date Sampled	TPH-G (ppb)	TPH-D (ppb)	Benzene (ppb)	Toluene (ppb)	Ethyl Benzene (ppb)	Total Xylenes (ppb)	Oil & Grease (ppm)
MW-3	09/26/90 11/30/92 03/03/93 06/02/93 08/31/93 11/30/93 03/02/94 06/07/94 04/14/95 07/11/95 10/19/95 01/10/96 06/12/96	200 <50 NS NS NS <50 260 2,300 120 190 1700 130 71 NAN	1,900 290 NS NS NS NS 19,000 1,300 4,500 1300 3,200 67,000 19,000 3,900 38,000	19.4 ¹ 8.9 ¹ NS NS NS S S S S S S S S S S S S S S S	19.4 ¹ 8.9 ¹ NS NS NS 2.9 ¹ 330 ¹ 0.8 <0.5 0.51 0.52 <0.5 <0.5 NAN	19.4 ¹ 8.9 ¹ NS NS NS 2.9 ¹ 330 ¹ 1.8 <0.5 <0.5 1.1 <0.5	19.4 ¹ 8.9 ¹ NS NS NS NS 2.9 ¹ 330 ¹ 16 1.6 2.4 4.0 0.84 0.81	NAN 0.17 NS NS NS 36 23 15 45 68 73 12 <5.0
MW-4	11/30/92 03/03/93 06/02/93 08/31/93 11/30/03 03/02/94 06/07/94 04/14/95 07/11/95 10/19/95	<50 <50 350 <50 <50 <50 <50 <50 NA	<50 <50 <50 <50 <80 <50 <50 <50 NA	<0.5 6.0 ¹ <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 NA NA	<0.5 6.0¹ <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 NA NA	<0.5 6.0 ¹ <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 NA	NAN <0.5 6.0¹ <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 NA NA	0.01 <0.01 <0.01 <1.0 <5.0 <5.0 <0.5 <1.0 NA

< = less than listed detection limits


^{1 =} result is a total BTEX for this sampling event

NS = not sampled due to presence of heavy viscous petroleum product at bottom of well

NA = no sample collected due to revised sampling plan

NAN = not analyzed

^{06/07/94} samples were collected by Environmental Science Engineering, Inc.



DRILLING CO.: Kvilhaug Well Drilling and Pump Co., Inc. DRILL METHOD: Hollow Stem Auger, Mobile B-61

SAMPLING METHOD: Split Spoon Sampler

PROJECT NO.: 142222.3 CLIENT: Fleischman's Yeast LOCATION: 921 98th Street

Oakland, CA

FY-MW-1(*FY2)

PAGE 1 OF 1

SEE LEGEND FOR LOGS AND TEST PITS FOR EXPLANATION OF SYMBOLS AND TERMS



O DEPTH IN FEET	SAMPLE TYPE & NUMBER	RECOVERY/DRIVE (In.)	Old)		BLOWS PER FOOT (N)	SOSN	PROFILE	BORING NO. MW-2 FIELD GEOLOGIST D. Dunn EDITED BY C. Bean DATE SEGAN 9-14-90 CHECKED BY G. Reid DATE FINISHED 9-14-90 TOTAL DEPTH 25.0 ft. GROUND SURFACE EL ~ 23.0'
5 -	MW2-1	8/18	0.3	G-5 Christy Box Portland Cement 3/8" Bentonite Pellets	55	CL.		ASPHALT - 0.4' CLAY (20% SILT): Dark brown to black, moderate dry strength, no dilatancy, law plasticity, finely homogenous, dry
-10-	MZ-2	12/18	0.5	2" Sch. 40 PVC Casing #3 Lonestar	55	СĽ		CLAY (30% SILT): Brown, low dry strength, low dilatancy, moderate plasticity, homogenous, dry. EQUILIBRIUM WATER LEVEL (9/26/90)
	MW2-3 MW2-4	16/18 5/18	0.3	2" dia. Sch. 40 S.S. Screen .020" Slot	80 N/A	мн		GROUNDWATER ENCOUNTERED 15.0' - SILT (30% CLAY): Brown, low dry strength, low dilatancy, low plasticity, homogenous, damp.
- 25-		12/18	0.3	Visible hydrocarbons in soil pores	50	SP		SAND WITH INTERBEDDED GRAVEL: clasts to 1-2cm, silty clar lenses, visible hydrocarbons, no dry strength, no dilatancy, very wet. SILT WITH (35% CLAY): Brown, moderate dry strength, low dilatancy, low plasticity, wet. 25.0' TOTAL DEPTH 25.0 FEET
-30-								TOTAL DEFIN 25.0 FEE!

DRILLING CO.: Kvilhaug Well Drilling and Pump Co., Inc. DRILL METHOD: Hollow Stem Auger, Mobile B-61

SAMPLING METHOD: Split Spoon Sampler

PROJECT NO.: 142222.3 CLIENT: Fleischman's Yeast LOCATION: 921 98th Street

Oakland, CA

FY-MW-2(*FY2)

SEE LEGEND FOR LOGS AND TEST PITS FOR EXPLANATION OF SYMBOLS AND TERMS



PAGE 1 OF

BORING NO. MW—3 SEE SEE SEE SEE SEE SEE SEE SEE SEE SE	WELL SUMMARY FIELD GEOLOGIST D. Dunn COORDINATES N. 45 61 53.3 E 151 44 92: DATE BEGAN 9-14-90 CHECKED BY G. Reid TOTAL DEPTH 25.0 ft. GROUND SURFACE EL. ~ 22 CONCRETE CAP - 0.4' CLAY (20% SAND): Dark brown to black, no dry strengt no dilatancy, low plasticity, fine sand, dry 3.5 Portland Cement COORDINATES N. 45 61 53.3 E 151 44 92: COORDINATES N. 45 61 53.3 E 151 44 92: DATE BEGAN 9-14-90 CHECKED BY G. Reid TOTAL DEPTH 25.0 ft. GROUND SURFACE EL. ~ 22 CONCRETE CAP - 0.4' CLAY (20% SAND): Dark brown to black, no dry strengt no dilatancy, low plasticity, fine sand, dry										
3.5 Portland Cement 6 C. Septiment 7 CLAY (80% FINE/20% SILT): Brown, low dry strength, low dilatancy, moderate plasticity, fine silt, damp. CLAY (80% FINE/20% SILT): Brown, low dry strength, low dilatancy, moderate plasticity, fine silt, damp. CLAY (80% FINE/20% SILT): Brown, low dry strength, low dilatancy, moderate plasticity, fine silt, damp. CLAY (80% FINE/20% SILT): Brown, low dry strength, low dilatancy, moderate plasticity, fine silt, damp. CLAY (80% FINE/20% SILT): Brown, low dry strength, low dilatancy, moderate plasticity, fine silt, damp. CLAY (80% FINE/20% SILT): Brown, low dry strength, low dilatancy, moderate plasticity, fine silt, damp. CLAY (80% FINE/20% SILT): Brown, low dry strength, low dilatancy, moderate plasticity, fine silt, damp. CLAY (80% FINE/20% SILT): Brown, low dry strength, low dilatancy, moderate plasticity, fine silt, damp. CLAY (80% FINE/20% SILT): Brown, low dry strength, low dilatancy, moderate plasticity, fine silt, damp. CLAY (80% FINE/20% SILT): Brown, low dry strength, low dilatancy, low dilatancy, low dilatancy, very moderate plasticity, fine silt, damp. CLAY (80% FINE/20% SILT): Brown, low dry strength, low dilatancy, low dilatancy, low dilatancy, low dilatancy, low dilatancy, low dilatancy, very moderate plasticity, low dilatancy, ver	3.5 Portland Cement	1	- 1	TYPE & NUMBER	RECOVERY/DRIVE (In.)	Gld)	WELL SUMMARY	BLOWS PER FOOT (N)	nscs	PROFILE	FIELD GEOLOGIST D. Dunn EDITED BY C. Bean CHECKED BY G. Reid TOTAL DEPTH 25.0 ft. COORDINATES N.45.61 53.3 E 151 44 92 2 DATE BEGAN 9-14-90 DATE FINISHED 9-14-90 GROUND SURFACE EL. ~ 22.5
- 35	Bentonite Pellets 3.2" Sch. 40 Casing 10 3.3 Lonestor and 3.4 Lonestor and 3.5 Sereen .020" Slot 15 16 17 18 17 18 19 19 10 10 10 10 10 10 10 10	-10	- LING-4	114	8/18	9.3	Portland Cement 3/8" Bentonite Pellets 2" Sch. 40 casing 2" dia. Sch. 40 S.S. Screen .020" Slot Free product fuel oil/Diesel	10	C. C		CONCRETE CAP — 0.4' CLAY (20% SAND): Dark brown to black, no dry strength, no dilatancy, low plasticity, fine sand, dry CLAY (80% FINE/20% SIL!): Brown, low dry strength, low dilatancy, moderate plasticity, fine silt, damp. CLAY (80% FINE/20% SIL!): Brown, low dry strength, low dilatancy, moderate plasticity, fine silt, damp. CLAY (80% FINE/20% SIL!): Brown, low dry strength, low dilatancy, moderate plasticity, fine silt, damp. CLAY (80% FINE/20% SIL!): Brown, low dry strength, low dilatancy, fine silt, damp. CLAY (80% FINE/20% SIL!): Brown, low dry strength, low dilatancy, no dilatancy, wishing low dry strength, low plasticity, low dilatancy, very moist.

DRILLING CO.: Kvilhaug Well Drilling and Pump Co., Inc. DRILL METHOD: Hollow Stem Auger, Mobile B-24

PAGE 1 OF 1

SAMPLING METHOD: Split Spoon Sampler

PROJECT NO.: 142222.3 CLIENT: Fleischman's Yeast LOCATION: 921 98th Street Oakland, CA

SEE LEGEND FOR LOGS AND TEST PITS FOR EXPLANATION OF SYMBOLS AND TERMS



	_		_						
13	H.	<u>≅</u>							BORING NO. SB-1
JEPTH IN FEET	SAMPLE TYPE & NUMBER	RECOVERY/DRIVE (In.)	ءَ ا			BLOWS PER FOOT (N)	S	I.F.	FIELD GEOLOGIST C. Bean COORDINATES N. 456.145.1
돈	¥ %	VER.	윤선	WELL SUMMAR	₹Y	SWS SOT	SOSO	PROFILE	EDITED BY C. Begn DATE BEGAN 9-13-90
E E	, 9F	22	Ĭ			A S		۵	CHECKED BY G. Reld DATE FINISHED 9-13-90
- 0 -	_	~	L				i		TOTAL DEPTH 17 ft. GROUND SURFACE EL ~ 23.0'
]						IIII	ASPHALT — 0.4' CLAY: Dark green gray, low plasticity, moderate dry
									strength, no dilatancy, slightly silty, dry.
† 1			2.0						
-		12/18				52	CL		
- 5 -	SB1-1			Backfill 8" hole					
				to grade with	1.1. 1				
				neat Portland		:			7.0
			110		1.				SILTY CLAY: Gray brown, low plasticity, low to moderate dry strength, stained mattled tarry patched eligible
ן ן				l E	, " 				petroleum odor.
- 10 -	S81-2	6/8				45	CL		
104									
1				[*					
† †			115						CLAY: Green, low plasticity, low dry strength, no dilatancy,
┝╶┤		18/18				74			moist, heavily stained with tarry patches, moist.
	SB1-3			[A		34 48	CL		
- 15 -	S81-4		31	Groundwater level encountered at		#0			
- 4				16.5					16.0'
Ļļ							мн		∑ SILT (40% CLAY): Brown to green gray, plasticity, moderate dry strength, low to occasionally moderate toughness.
ĹJ									riodling hydrocarbon on water surface.
				ļ	ļ				TOTAL DEPTH 17.0 FEET
[]					J				
-20-									
					Ī				
				1	Ì				
				1	- 1				-
-					1				
-25-					- 1				
<u> </u>									
	l								
	1	1	•]	1				
]					1				
-30-									
┞╶	İ								
┞ -	ł								
┞ -	ł								
┡ -	ł								
L 35_	<u> </u>	<u> </u>	<u> </u>					<u> </u>	

DRILLING CO.: Kvilhaug Well Drilling & Pump Company, Inc. DRILL METHOD: Hollow Stem Auger, Mobile B—61

SAMPLING METHOD: Split Spoon Sampler

PROJECT NO.: 142222.3 CLIENT: Fleischmann's Yeast LOCATION: 921 98th Street

Oakland, California FY-SB-1(*FY2)

PAGE 1 OF 1

SEE LEGEND FOR LOGS AND TEST PITS FOR EXPLANATION OF SYMBOLS AND TERMS



O DEPTH IN FEET	SAMPLE TYPE & NUMBER	RECOVERY/DRIVE (In.)	Old)	WELL SUMMARY	BLOWS PER	root (N)	SOCO CONTRACTOR	PROFILE	BORING NO. SB-2 FIELD GEOLOGIST C. Bean CHECKED BY C. Reid CHECKED BY G. Reid CHECKED BY G. Reid CHECKED BY G. Reid GROUND SURFACE EL ~ 23.0'
5-	S82-1	9/18	9		42	c			ASPHALT — 0.4 CLAY: Dark gray brown, moderate plasticity, moderate dry strength, no dilatancy, dry, unstained.
- 10 -	S82-2	13/18	41	Backfill 8" hole to grade with neat Portland Cement	51	C			CLAY: Gray brown, moderate plasticity, low dry strength, moist, slightly silty, very slightly stained, moist.
			70			Mi			SILT: Brown, 30% clay, low dilatancy, moderate plasticity.
-15 -									SILT: Brown, 30% clay, low dilatancy, moderate plasticity. Floating hydrocarbon on water surface. GROUNDWATER ENCOUNTERED AT 15.0' TOTAL DEPTH 15.0 FEET
-20-									
- 25 -									
-30-									
35									

DRILLING CO.: Kvilhaug Well Drilling & Pump Co., Inc. DRILL METHOD: Hollow Stem Auger, Mobile B-61 SAMPLING METHOD: Split Spoon Sampler

PAGE 1 OF

PROJECT NO.: 142222.3 CLIENT: Fleischmann's Yeast LOCATION: 921 98th Street

SEE LEGEND FOR LOGS AND TEST PITS FOR EXPLANATION OF SYMBOLS AND TERMS

Oakland, California





O DEPTH IN FEET	SAMPLE TYPE & NUMBER	RECOVERY/DRIVE (In.)	PID (ppm)	WELL SUMMARY	BLOWS PER FOOT (N)	nscs	PROFILE	BORING NO. SB-4 FIELD GEOLOGIST C. Bean COORDINATES N 456206.5 E 1514465.0 EDITED BY C. Bean DATE BEGAN 9-13-90 CHECKED BY G. Reid DATE FINISHED 9-13-90 TOTAL DEPTH 20 ft. GROUND SURFACE EL. ~23 ft.
	334- 1	12/18	5		18	GW	000000000000000000000000000000000000000	ASPHAL - 0.4' SAND/GRAVEL FILL (70% fines): Brown to green, loose .5 to 2cm clasts, angular to subangular coarse sand.
		12/18	10	Backfill 8" hole to grade with neat Portland cement		CL	5.5	SILTY CLAY: Brown, low plasticity, moderate dry strength, no dilatancy, dry, no apparent staining.
-10-		14 /19	5		43			SILT (40% CLAY): Brown to gray green, low plasticity, moderate dry strength, no dilatancy, wet. SILT (40% CLAY): Brown to gray green, low plasticity, moderate dry strength, no dilatancy, wet.
-15 - 	S84~3				58	мн		-
-20 - 								TOTAL DEPTH 20.0 FEET
25-								
-30-								
35								

DRILLING CO.: Kvilhaug Well Drilling & Pump Co., Inc. DRILL METHOD: Hollow Stem Auger, Mobile B—61

SAMPLING METHOD: Split Spoon Sampler

PROJECT NO.: 142222.3 CLIENT: Fleischmann's Yeast LOCATION: 921 98th Street Oakland, California

SEE LEGEND FOR LOGS AND TEST PITS FOR EXPLANATION OF SYMBOLS AND TERMS



PAGE 1 OF

O DEPTH IN FEET	SAMPLE TYPE & NUMBER	RECOVERY/DRIVE (in.)	(mdd)	WELL SUMM.	ARY	BLOWS PER FOOT (N)	uscs	PROFILE	BORING NO. SB-5 FIELD GEOLOGIST D. Dunn EDITED BY C. Begn CHECKED BY G. Reid TOTAL DEPTH 15.5 ft. COORDINATES N 456166.5 E 1514480.3 DATE BEGAN 9-14-90 DATE FINISHED 9-14-90 GROUND SURFACE EL. ~23 ft.
- 5 -	S85-1	15/18	17.6	Backfill 8" hole to grade with neat Portland cement		7	C. C.		CONCRETE CAP - 0.4 CLAY (20% SILT): Dark brown to black, moderate dry strength, no dilatancy, low plasticity, homogenous, dry.
10-	S85 −2	17/18 16/18	5			10	CL		CLAY (20% SILT): Dark brown, moderate dry strength, law dilatancy, moderate plasticity, homogenous, damp, slight petroleum odor. SILT (35% CLAY): Dark brown, moderate to high dry strength, of week product odor.
- 20 -									GROUNDWATER ENCOUNTERED AT 15.0' TOTAL DEPTH 15.0 FEET
-25-									
-30-									

DRILLING CO.: Kvilhaug Well Drilling & Pump Co., Inc. DRILL METHOD: Hollow Stem Auger, Mobile B-24

SAMPLING METHOD: Split Spoon Sampler

PROJECT NO.: 142222.3 CLIENT: Fleischmann's Yeast LOCATION: 921 98th Street Oakland, California SEE LEGEND FOR LOGS AND TEST PITS FOR EXPLANATION OF SYMBOLS AND TERMS



PAGE 1 OF 1