PROPOSAL
FOR
SUBSURFACE INVESTIGATION

DOUGHERTY FIRE STATION #1
7494 DONOHUE DRIVE
DUBLIN. CA

DOUGHERTY REGIONAL FIRE AUTHORITY

I. INTRODUCTION

The proposed scope of work involves the installation of three groundwater monitoring wells as the result of subsurface contamination found at the time three (3) underground storage tanks were removed from this site.

The site location is 7494 Donohue Drive, Dublin, CA. The Dougherty Regional Fire Authority maintains a fire station on the property. In conjunction with this operation, the site has historically operated two underground gasoline storage tanks and one undergorund diesel tank for a number of years.

On November 11, 1989, three underground storage tanks were removed. These tanks were:

one 4,000 gallon gasoline tank one 550 gallon diesel tank one 550 gallon gasoline tank The tank removals were conducted by Hageman-Shank, Inc. under permit from the Alameda County Environmental Health Department. Analytical results and other data pertaining to the previous tank removals are included as Attachment A. The 550 gallon gasoline tank was discovered during the removals of the other two tanks. This tank was filled with concrete, and obviously had been abandoned due to product loss and/or infiltration of groundwater into the tank. During the tank removals, the steel was peeled away, and the cylinder of concrete was allowed to remained in the excavation.

II. SITE DESCRIPTION


Vicinity Description and Hydrogeologic Setting


The location of the site is shown on the vicinity map (Figure 1). The soils beneath the site consist of Quaternary Alluvium overlying a bedrock consisting of Middle and/or Lower Pliocene nonmarine deposits as found in the Dougherty and San Ramon Hills, or else Upper Miocene marine deposits found in portions of the San Ramon Hills (Geologic Map of California, San Francisco Sheet, State of California Division of Mines and Geology, 1980). Bedrock is likely to occur at a depth of thirty or more feet beneath the site. During the borings for the well installations, varying amounts of clay, sand, gravel can be expected to be encountered.

Based upon the surface topography, as well as the various hydrologic features shown on the vicinity map, the general regional shallow groundwater can be expected to flow from the Dougherty and San Ramon Hills (areas of groundwater recharge), into the aquifer system of the San Ramon Valley, then move southward toward the Livermore Valley. Although the placement of the proposed monitoring wells are based upon this assumption of groundwater flow direction, water level data from the three wells will determine the exact flow direction of the shallow groundwater beneath the site. The close proximity of the site to the nearby creek, as shown in Figure 1, may influence the groundwater flow direction beneath the site.

Site Description

A map of the site is shown in Figure 2. This map shows the layout of the facility, along with the location of the previous tank excavation.





DONOHUE DRIVE

FIGURE 2. Site Map.

III. EXTENT OF SOIL CONTAMINATION ON SITE

The results of the analyses performed on soil samples collected during the tank excavations are presented in Attachment A. These results indicated the presence of Gasoline in the soil at levels up to 1,500 mg/kg (ppm).

After approval by Alameda County Environmental Health Department, soil removed during the previous tank excavations was spread and aerated on-site under permit by the Bay Area Air Quality Management District (BAAQMD). The analytical results of composite sampling of the aerated soil is included in Attachment A. The Alameda County Environmental Health Department has approved the backfilling of the tank excavation with this aerated soil.

The plan for determining groundwater contamination, as discussed in Section IV of this proposal, provides for the analysis of all soil and groundwater samples for 1) total petroleum hydrocarbons as gasoline, and 2) Benzene, Toluene, Xylenes, and Ethylbenzene (BTXE). An attempt will be made to determine the concentrations and extent of these petroleum hydrocarbons that may be present in the soil and shallow groundwater beneath the site.

IV. PLAN FOR DETERMINING GROUNDWATER CONTAMINATION


Placement of Monitoring Wells

The purpose of the proposed groundwater investigation is to install and sample three on-site monitoring wells in order to 1) determine the direction of shallow groundwater flow beneath the site, and 2) define the extent of any petroleum constituents that may be present in the shallow groundwater beneath the site.

The proposed locations of the wells are shown in Figure 3. The locations have been selected based upon 1) known locations of soil contamination during previous tank removals, 2) the expected shallow groundwater flow direction, and 3) what is believed to be good spacing between data points in order to achieve reasonable plume definitions of any contaminants that may be present in the shallow groundwater beneath the site.

Monitoring Well Installations

Well installation will begin as soon as possible, following approval by the appropriate regulatory agencies. Each well will be installed with a truck-mounted drill rig using 8-inch hollow-stem augers. During the drilling, soil samples for chemical analyses will be collected at 5-foot intervals until the shallow water table is encountered at a depth of approximately 5 to 10 feet below the ground surface. Each soil sample will be collected by driving a split-barrel sampler fitted with clean brass liners. All samples will be immediately placed on ice, then transported under chain-of-custody to the laboratory by the end of the work day.



DONOHUE DRIVE

Figure 3.
Proposed Locations of
Shallow Monitoring Wells.

The well borings will extend to approximately 10 feet below the shallow water table or until a competent clay layer is encountered (a thickness greater than 5 feet). Each well will be cased to approximately five feet above the shallow water table with 2-inch PVC slotted screen pipe (0.02" slots). The annular space of each well will be packed to one foot above the slotted section with #3 Monterey Sand. At least one foot of wetted bentonite pellets will be placed upon the sand pack, followed by a neat cement/bentonite seal up to the ground surface. Each well will be fitted with a locking steel traffic lid. The borings will be logged in the field by Gary Aguiar, registered civil engineer #34262 (a statement of qualifications is included as Attachment B). A typical well construction diagram is shown in Figure 4.

Prior to the installation of each well, all drilling equipmenmt, including augers, drill stem, and split barrel samplers, will be steam-cleaned on-site.

All drill cuttings will be drummed and stored on-site until the results of laboratory analyses are obtained. Depending upon these results, the cuttings will be disposed of as either a non-hazardous waste, or else as a hazardous waste under proper manifest to an appropriate TSD facility.

In order to determine groundwater flow direction, the top-of-casing elevation at each monitoring well will be surveyed to within 0.01 foot of an established on-site benchmark.

Groundwater Sampling Plan

Within three days of installation, each well will be developed by removing water with a teflon bailer until the water is relatively clear, or until the aparent turbidity of the water being removed has stabilized.

Prior to sampling, each well will be purged by bailing at least 5 casing




FIGURE 4.
Typical Monitoring Well Construction.

volumes of water. After a well has been adequately purged, a groundwater sample will be bailed and placed in the appropriate containers, as required by the particular laboratory method protocols. All samples will then be immediately placed on ice, then transported under chain-of-custody to the laboratory by the end of each work day.

At the time each monitoring well is sampled, the following information will be recorded in the field: 1) depth-to-water prior to purging, using an electrical well sounding tape, 2) identification of any floating product, sheen, or odor prior to purging, using a clear teflon bailer, 3) sample pH, 4) sample temperature, and 5) specific conductance of the sample.

All analyses will be conducted by a California State DOHS certified laboratory in accordance with EPA recommended procedures. All soil and groundwater samples will be analyzed for 1) total petroleum hydrocarbons as gasoline, and 2) Benzene, Toluene, Xylenes, and Ethylbenzene (BTXE).

All water removed from the well during development and purging will be drummed and stored on-site until the results of laboratory analyses are obtained. Depending upon these results, the water will be sewered as a non-hazardous liquid waste, or else it will be transported as a hazardous liquid waste under proper manifest to an appropriate TSD facility for treatment and disposal.

V. SITE SAFETY PLAN


A set of health and safety operating procedures for field investigations of underground spills of motor oil and petroleum distillate fuel is provided in Attachment C. In order to maintain a safe working environment for field personnel, a copy of these operating procedures will be kept on-site during the field operations, and will be followed in accordance with the magnitude of petroleum contamination encountered.

No. C-34262	EN THE THE PROPERTY OF THE PRO
Gary Aguiar	RCE 34262

Bruce Hageman

ATTACHMENT A

Analytical Results and Other Data
Pertaining to
Previous Tank Removals



2239 Omega Road,#1 • San Ramon, California 94583 415/831-1788 • Facsimile 415/831-8798

Chain of Custod

	-							_								DA	TE				_ PAG	Ε		OF	
PROJ. MGR. B	uce r	heen	HA										ANA	LYSI	SREC	UEST	7								Γ.
COMPANY - 1993	<u>GEMAN</u> 723	<u>l - Se</u> Casa	HANK Como	W.C.		628		l g	SMS		S C						ន			T			T		
Solution Solution	723 .	mon				ne (5030) 602, 6020)	S S	AATIC 2, 80	OCARB	SOCS	6, ACIDS	REASE	B S	80%0)			G. B.	9	UTANT						
SAMPLERS ISIGNATUR	(E)	,	(PH	ONE NO.)	Casoline 5030)	TPH - Casoline w/8TEX (EPA 60	TPH - Diesel (EPA 3510, 3550)	PURGEABLE ARCHATICS BTEX (EPA 602, 8020)	PURGEABLE HALDCARBONS (EPA 601, 8010)	VOLATILE ORGANICS (EPA 624, 8240)	BASE/NEUTRALS, (EPA 624/627, 8	TOTAL OIL & GREASE (EPA 5030&E)	PESTICIDES/PCB (EPA 608, 8080)	K.S 604, 80			3	CAN NETALS (PRICRITY POLUTANT						
SAMPLE ID.	DATE	TIME	MATRIX	LAB IG.	単型	TPH -	TPH CEPA	PURGE	PURGE (EPA	VOLAT	BASE/ (EPA	TOTAL	PEST1	PHEMOLS (EPA 604,			NETALS:	35	PRIOR						
DFD SSEI	HZ	1250	Sou		-	X																<u> </u>			
DFD SS #Z	1/2	1246	Sonc			1/2	X							<u> </u>				·							
DFD 55 tg	1/2	193	SouL			1	ļ																		
DFD 55 4	11/2	15	Seel			X																			
:																									L
																									<u></u>
																				<u> </u>					<u></u>
																									!
							•												Ĺ.,	L	<u> </u>				
PROJECT INFORI	MATION	TOTAL	SAMPL NO. OF C	E RECEIP		4	REL	INDUIS		//	eur	•	1. 6	RELING	CUISH	ED BY	•		2.	RELI	NQUIS	HED BY	•		:
PQ NO.	•		OF CUSTO			<u>/. </u>	(Signa	(C)(I)		1890	m		ne) (S	ignatu	re)			(Ti	me)	(Signat	turel			{T.	me
SHIPPING ID. NO.			GOOD CO		OLD		(Print	ed Nam	16)	/		(Da	te) (f	Printed	Name)	}		(D	ate)	(Prints	ed Nam	(e)		(0	ate
VIA:		LAB NO	RMS TO R O.	ECOND			(Com	pany)					- 10	Compai	ny)					(Comp	pany}				
VIA:	·							IVED	BY					ECEN		<u> </u>						BY (LA	BORAT	rory)	3
SPECIAL INSTRUCTION							- X	100	a			16	ca.						ŀ			•			
24	HOUR	TUR	M AR	ansz	>		{Signa	ture)		<u> </u>		1710		(Signature) (Time)			me)) (Signature) (Time			ıme				
								A C				(Dai		rinted	Name)			(0:	ate)	Printe	rd Name	e)	-	(0)	ATE
							(Comp		MICIC	- CII			((Compa	lyi				7	(LAB)			 _		

Analytical Laboratory Specializing In GC-GC/MS

- Environmental Analysis
- · Hazardous Waste
- Drinking Water
- Waste Water
- Research and Method Development
- Consultation

November 3, 1989

ChromaLab File # 1189009

Hageman-Schank, Inc.

Attn: Bruce Hageman

Re: Four RUSH soil samples for Gasoline/BTEX and Diesel

Project Name: N/A

Duration of Analysis: Nov. 2-3, 1989

Results:

Sample No.	Gasoline (mg/Kg)	Benzene (µg/Kg)	Toluene (µg/Kg)	Ethyl Benzene (Ug/Kg)	Total Xylenes (Ug/Kg)
DFD SS#1	980	2400	540	2500	2760
DFD SS#2	810	1100	290	4400	4500
DFD SS#3	130	N.D.	170	180	51
DFD SS#4	1500	2500	2800	10000	20000
BLANK SPIKE RECOVERY DETECTION LIMIT METHOD OF ANALYSIS MO	N.D.	N.D.	N.D.	N.D.	N.D.
	95.9%	86.6%	87.9%	100.6%	95.1%
	2.5	5.0	5.0	5.0	5.0
	D.8015	8020	8020	8020	8020
Sample Me					

Sample No. Diesel (mg/Kg)

DFD SS#2

N.D.

BLANK SPIKE RECOVERY DETECTION LIMIT METHOD OF ANALYSIS

N.D. 99.1%

5.0

MOD.8015

ChromaLab, Inc.

David Duong

Senior Chemist


Eric Tam

Laboratory Director

2239 Omega Road,#1 • San Ramon, California 94583 415/831-1788 • Facsimile 415/831-8798

Chain of Custod

																0A3	re <u>/</u> /	1-7-	89		_ PAGI	E	<u>, </u>	0F_	,
PROJ. MGR. Bey	ICE H	AGEN	AU	2 is la	ANALYSIS REQUEST																				
PROJ. MGR. Bey COMPANY HA ADDRESS 222 STE	6EMA 13 CRA 7 210	(x) C.A.	niyew N	2, 1W.		TPH - Gasoline (5030) W/BTEX (EPA 602, 8020)	(0)	PURGEABLE ARCHATICS BTEX (EPA 602, 8020)	DCARBONS 0)	NICS D)	, ACIDS 8270)	REASE	# Q	6			Cr, Pb, Zn	3	UTANT						STATE OF THE STATE
SAMPLERS (SIGNATURE) (PHONE NO.)			ONE NO.)	. Gasol in 1 5030)	Gasolin EX (EPA	TPH - Diesel (EPA 3510, 3550)	ABLE ARG	EABLE HAL	11LE ORIA 624, 824	BASE/NEUTRALS, ACIDS (EPA 624/627, 8270)	TOTAL OIL & GREASE (EPA 5030&E)	1CTDES/PC 608, 808	PHEMOLS (EPA 604, 8040)			g	CAN NETALS (18) W/CF VI	PRIORITY POLLUTANT						0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0	
SAMPLE ID.	DATE	TIME	MATRIX	LAB IO.	1 - 2	TP# 1/87	E P	PURG BTEX	PERG	E VOLA	BASE (EPA	TOTAL	PEST (EPA	E PE			HETALS:	3 \$	PR 10	<u> </u>	<u> </u>				1
DFD#5	1/1/89	1200	SOIL			\geq								<u> </u>								<u> .</u>	<u> </u>		
DFD #6	4/7/89	1215	Soil			X												Ŀ							
DEDET	1/7/89		SUIL			\sum								<u> </u>											
Ź.																									
				i																					
							-		ŕ											 					
PROJECT INFOR	MATION		SAMPL	E RECEIPI	r		REL	พดีบาร	HED	BY /		······································	1. F	RELING	DUISH	ED BY			2.	RELI	NQUISI	HED B	Y		3
PROJECT: DOUCHERT, PO NO.	FIRE DE	TOTAL	NO. OF C				/	<u> </u>	1110	1	240														
PO NO.		CHAIN	OF CUSTO				(Signa	aire. Zunč	- 1/4	i EM	D)	(Tin) (S	ignatu	re)			(Ti	me)	{Signa	(ure)			(1	(me
SHIPPING ID. NO.			RMS TO R				(Print	ed Nam	ie)	·	- •	10a	(F	Printed	Namel	•		(D	ate)	(Print	ed Nam	e)		(0)ate)
VIA:		LAB NO).			(Company) / 5/ (Compan			ny)					(Comp	anyl										
SPECIAL INSTRUCTIONS/COMMENTS:						RECE	INED	BY	e		********	1. R	ECEIV	/ED B	·			2.	RECE	IVED B	Y (LA	BORAT	ORY	3	
•				(Signature) DUONG 11/3/19 (Signature)						Signature) (Time)			me)	(Signature) (Time)											
								Named be		3 0/2/0	· · · ·	(Dat		rinted				(0:	ite)	(Printe	d Name	e)		(0)	ATE
•							(Comp	pany) (>HK(AMC	LAB.	IN	2 10	Сотра	ny)					(LAB)					_



感感, 独, 生生 严忌

CHROMALAB, INC.

Analytical Laboratory Specializing in GC-GC/MS

- Environmental Analysis
- Hazardous Waste (#238)
- Drinking Water

(#955)

- Waste Water
- Consultation

November 15, 1989

ChromaLab File # 1189037

Hageman-Schank, Inc.

Attn: Bruce Hageman

RE: Three soil samples for BTEX and Gasoline analysis

Project Name: DOUGHAERTY FIRE DEPARTMENT Duration of Analysis: November 10-14, 1989

RESULTS:

Sample No.	Gasoline (mg/Kq)	Benzene (µq/Kg)	Toluene (µg/Kg)	Ethyl Benzene (µg/Kg)	Total Xylenes (µg/Kg)
DFD #5	N.D.	8.1	N.D.	N.D.	N.D.
DFD #6	560	2200	1700	3300	6500
DFD #7	220	280	930	1200	230
BLANK	N.D.	N.D.	N.D.	N.D.	N.D.
SPIKE RECOVERY	94.9%	82.8%	85.7%	96.3%	104.8%
DETECTION LIMI METHOD OF	T 2.5	5.0	5.0	5.0	5.0
	OD.8015	8020	8020	8020	8020

ChromaLab, Inc.

David Duong

Senior Chemist

Eric Tam

Laboratory Director



BAY AREA AIR QUALITY MANAGEMENT DISTRICT

209 EULIS STREET SAN FFANC'SCO DAUFORNIA 34 (19) 415/77/2000

REGULATION 8, RULE 40 Aeration of Contaminanted Soil and Removal of Underground Storage Tanks

NOTIFICATION FORM

	Removal or Replacement of Tanks
X.	Excavation of Contaminated Soil

	SITE INFORMATION							
SITE ADDRESS 7494 DONOHUE DRIVE								
CITY, STATE, ZIP DUBLIN, CA 94568								
OWNER NAME DOUGHERTY REGIONAL FI	IRE AUTHORITY							
SPECIFIC LOCATION OF PROJECT DRIECTLY	BEHIND MAIN FIRE STATION BUILDING							
TANK REMOVAL	CONTAMINATED SOIL EXCAVATION							
SCHEDULED STARTUP DATE	SCHEDULED STARTUP DATE 11/8/89							
VAPORS REMOVED BY:	STOCKPILES WILL BE COVERED? YES X NO							
[] WATER WASH [] VAPOR FREEING (CO ²)	ALTERNATIVE METHOD OF AERATION (DESCRIBE BELOW): AERATION OF APPROX 40 CUBIC YARDS OF							
[] VENTILATION	SOIL FROM GASOLINE TANK EXCAVATION, AVG. CONTAMINATION LEVEL LESS THAN 1000 ppm							
CONTRACTOR INFORMATION								
NAME	CONTACT							
	PHONE ()							
CITY, STATE, ZIP								
СО	NSULTANT INFORMATION (IF APPLICABLE)							
NAME_HAGEMAN-SCHANK, INC.	CONTACT BRUCE HAGEMAN - GARY AGUIAR							
ADDRESS 2321 CROW CANYON ROAD	PHONE (415) 887-2926							
CITY, STATE, ZIP SAN RAMON, CA 94583	3							
FOR OFFICE USE ONLY								
DATE RECEIVED	BY							
CC: INSPECTOR NO.	DATE BY (INIT.)							
TELEPHONE UPBATE: CALLER	· · ·							

HAGEMAN-SCHANK, INCORPORATED TPH) AS GASCINE 2723 CROW CANYON ROAD, SUITE 210 DOUGHERRY FIRE SAN RAMON, CALIFORNIA 94583 NORMAL TURN AROUND PROJECT NO. SOIL AGRATION 415/837-2926 COMPOSITE CSS # 1 THEY CSS#5 AS ONE SAMPLE CHAIN OF CUSTODY RECORD Composite 6 to Med to Field Record 15 ONE SAME Soil Sample Type Laboratory Record Container Type Beas Lines Contract Laboratory Record Lab No. Laboratory Name umple ID Sampled By Date Received By Date Condition Received By Date Condition DFD C55#2 DFD BH C\$5#3 COMPOSITE AS ONE D.RP BIXE & TPH AS GASLING 255 FU D.F.D. C55 #5 0.FO 655#6 COMPOSITE AS ONE BREETDHAS GASKINE DPI 15548 2450 08549 235410 Released to Courier By Field Personnel Released To Lab by Courier Released to Lab by Courier ence Hopmen Received by Courier_____ Received by Lab_____ Received by Lab_____

Analytical Laboratory Specializing in GC-GC/MS

- Environmental Analysis
- Hazardous Waste (#238)
- Drinking Water

(#955)

- Waste Water
- Consultation

December 4, 1989

ChromaLab File # 1189127

Hageman-Schank, Inc.

Attn: Bruce Hageman

Re: Two composited soil samples for Gasoline/BTEX analyses

Project Name: Doughery Fire Station #1, soil aeration

Duration of Analysis: Nov. 28, Dec. 4, 1989

Results:

Sample No.	Gasoline (mg/Kg)	Benzene (µq/Kg)	Toluene (µg/Kg)	Ethyl Benzene (µg/Kg)	Total Xylenes (µg/Kg)
DFD CSS #1-5	5.6	N.D.	N.D.	N.D.	N.D.
DFD CSS #6-10	2.9	N.D.	N.D.	N.D.	N.D.
BLANK	N.D. \	N.D.	N.D.	N.D.	N.D.
SPIKE RECOVERY	102.2%	103.1%	94.7%	81.9%	96.8%
DETECTION LIMIT	r 2.5	5.0	5.0	5.0	5.0
	DD.8015	8020	8020	8020	8020

ChromaLab, Inc.

David Buong

Senior Chemist

Eric Tam

Laboratory Director

telepole parale

	UNDERGROUND STORAGE TANK UNAUTHORIZED RELEASE (LEAK) / CONTAMINATION SITE REPORT										
_[MERGENCY HAS STATE OFFICE OF EMERGENCY SERVICES REPORT BEEN FILED? YES NO PORT DATE CASE #	FOR LOCAL AGENCY USE ONLY LHEREBY CERTIFY THAT I AM A DESIGNATED GOVERNMENT EMPLOYEE AND THAT I HAVE REPORTED THIS INFORMATION TO LOCAL OFFICIALS PURSUANT TO SECTION 25180.7 OF THE HEALTH AND SAFTY COOK									
1	NAME OF INDIVIDUAL FILING REPORT	SIGNED DATE									
REPORTED BY	BRUCE HAGEMAN (415										
"	7494 DONOHUE DRIVE	DUDI IN									
-		CONTACT PERSON PHONE 945-68									
S S	DOUGHERTY REGIONAL FIRE AUTHORITY	TOM HATHCOX, FIRE MARSHAL 415-829-233									
RESPONSIBLE	BIFEET	CITY SAN RAMON STATE CA 94582									
$ _{_{-}}$	FACILITY NAME (IF APPLICABLE)	OPERATOR PHONE									
LOCATION	DOUGHERTY FIRE STATION # 1	F. M. TOM HATHCOX (415) 829-2333									
18	7494 DONOHUE DRIVE	GITY DUBLIN ALAMEDA 94568									
F. F.	CROSS STREET TYPE OF AREA TO COMM										
_	TAME WHENDOW ANDRED DUADAY	THER OTHER FIRE STA.									
2	LOCAL AGENCY AGENCY NAME	CONTACT PERSON PHONE									
MPLEMENTING	ALAMEDA COUNTY HEALTH REGIONAL BOARD	MR. GIL WISTAR (415271-4320									
3	SAN FRANCISCO BAY	LES FELDMAN ()									
ا ي ي	440	QUANTITY LOST (GALLONS)									
SUBSTANCES	GASOLINE REGULAR	X_ UNKNOWN									
88		UNKNOWN									
눍	DATE DISCOVERED HOW DISCOVERED INVEST	NTORY CONTROL SUBSURFACE MONITORING NUISANCE CONDITIONS									
Ā	1 M 1 M O D 19 8 V G V TANK TEST TO TANK	REMOVAL OTHER									
DISCOVERY/ABATEMENT	LINKNOWN HAS DISCHARGE BEEN STOPPED?	METHOD USED TO STOP DISCHARGE (CHECK ALL THAT APPLY) REMOVE CONTENTS REPLACE TANK CLOSE TANK REPAIR TANK REPAIR PIPING CHANGE PROCEDURE									
å	\blacksquare YES \blacksquare NO FYES, DATE $1_{\sf M}$ $1_{\sf M}$ $0_{\sf O}$ $2_{\sf O}$ $8_{\sf F}$ $9_{\sf V}$	OTHER									
3	SOURCE OF DISCHARGE TANKS ONLY/CAPACITY TANK LEAK UNKNOWN GAL	MATERIAL CAUSE(S) FIBERGLASS CMEREIL SUPTLINE CAULUSE									
8	ZY TANKLEAK UNKNOWN GAL. PIPING LEAK AGE YRS	FIBERGLASS OVERFILL RUPTURE/FAILURE X STEEL X CORROSION UNKNOWN									
SOURCEICAUSE	OTHER UNKNOWN	OTHER OTHER									
3 55	CHECK ONE ONLY SOIL ONLY GROUNDWATER	DRIMKING WATER - (CHECK ONLY IF WATER WELLS HAVE ACTUALLY BEEN AFFECTED)									
STATUS	CHECK ON'S ONLY SITE INVESTIGATION IN PROGRESS (DEFINING EXTENT OF PROBLEM) NO ACTION TAKEN POST CLEANUP MONITORING IN PROGRESS	CLEANUP IN PROGRESS SIGNED OFF (CLEANUP COMPLETED OR UNINECESSARY) NO FUNDS AVAILABLE TO PROCEED EVALUATING CLEANUP ALTERNATIVES									
	CHECK APPROPRIATE ACTION(S) (SEE BACK FOR DETAILS)										
30	CAP SITE (CD) EXCAVATE & DISPOSE (ED)	REMOVE FREE PRODUCT (FP) ENHANCED BIO DEGRADATION (IT)									
REMEDIA: ACTON		PUMP & TREAT GROUNOWATER (GT) REPLACE SUPPLY (RS)									
	TREATMENT AT HOOKUP (HU) NO ACTION REQUIRED (NA)	OTHER (OT) TO BE DETERMINED									
COMMENTS	•	•									

ATTACHMENT B

Statement of Qualifications

STATEMENT OF QUALIFICATIONS

Gary Aguiar:

- B.S., Chemical Engineering, University of California, Berkeley, 1977
 M.S., Sanitary Engineering, University of California, Berkeley, 1981
- o Registered Civil Engineer, California, C.E. 34262 Registered Civil Engineer, Oregon, C.E. 13353 Registered Civil Engineer, Alaska, C.E. 7769
- Over the past ten years, has participated in all aspects of hydrogeological investigations, groundwater pollution investigations, water resource studies, and hazardous waste management.
- o His extensive teaching experience includes the following:

UNIVERSITY OF CALIFORNIA

1/82 - present EXTENSION, Berkeley, Ca.

Instructor: Develop and teach courses on the
principles of groundwater hydrology, groundwater
pollution, and hazardous waste management.

Advisory Committe member: Member of advisory committee for U.C. Berkeley Hazardous Materials Management Certificate Program.

CALIFORNIA STATE UNIVERSITY

9/83 - 12/83 CONSORTIUM, Hayward, Ca. Assistant Professor: Developed and taught a course on the engineering aspects of environmental planning.

RESOURCE SEMINARS,

1/81 - 9/83 Berkeley, Ca.

Lecturer: Lectured on the principles of groundwater hydrology at seminars given in various U.S. cities.

o Other Qualifications:

Water Treatment Plant Operator Grade III Certificate, California State Department of Health.

Basic Qualified Earth Shorer Certificate, American Society of Safety Engineers.

Radiation Safety / Nuclear Soils Gauge Operator Certificate, Campbell Pacific Nuclear Corp.

o Professional Affiliations:

Member, American Chemical Society
Member, American Water Works Association
Member, National Water Well Association

Gary Aguiar began a private consulting practice in 1984. The first project was the installation of three deep monitoring wells within the drinking water aquifer beneath McKesson Chemical Company's Union City chemical packaging facility. This project involved casing a highly contaminated upper zone prior to drilling through the Newark aquitard. After supervising the drilling operations, properly disposing of the drilling spoils, and sampling the wells, a detailed report was prepared that presented an analysis of the data, as well as an assessment of the impact that shallow groundwater contamination has had upon the quality of the drinking water in the area.

To date, Gary Aguiar has provided services for a total of fifteen clients. Typical work has included:

- o Assessment of local hydrogeology around solvent recycling sites located in Denver, Co. and Azusa, Ca., prior to purchase by a national chemical recycler.
- o Consultation to a local geologic firm concerning the design of a dewatering and contaminant removal system in tight clays at an electronics factory site located in Santa Clara County.
- o Design of a pump test to determine aquifer characteristics prior to design of an extraction system for the removal of gasoline from an underground tank site in Morgan Hill, Ca.
- o Hydrogeologic analysis and design of a recovery system for the remediation of gasoline contamination that threatened a drinking water supply in Woodside, Ca.
- o Data analysis and professional representation in negotiations with the Regional Water Quality Control Board for a commercial property owner in Santa Clara County. Solvent contamination had been discovered beneath the site.

- o In association with a local hydrogeologic consulting firm, a site assessment of a laser manufacturing plant in Palo Alto, Ca. is currently in progress. This project involved assessing the local hydrogeology, sampling surface and groudwaters, formulating a risk assessment in terms of contaminants that may enter the groundwater due to factory processes, and removing hazardous wastes that have been left from past operations.
- o Consultation to a local geologic firm concerning the results of soil and groundwater sampling at a large oil refinery in Hanford, Ca. This project has involved assessing the local hydrogeology, relating the presence of subsurface contaminants to specific above-ground refinery processes, and recommending specific chemical analyses to be performed. An assessment of the impact of subsurface contamination was made in terms of the potential for deep migration. In addition, an assessment of the legal impact was made in terms of applicable hazardous waste laws (Title 22 and 40CFR).
- o Analysis of hydrogeologic/groundwater quality data for a chemical facility in Freeport, Grand Bahama Island. This project currently involves an assessment of potential contaminant migration, as well as remedial action plan development. The assessment is complicated by karst geology, a strong tidal influence and the occurence of groundwater in a freshwater lens.
- o Project management of a soil and groundwater study in and around the chrome plating shop at Mare Island Naval Base, Vallejo, CA. This project has included the installation of a number of monitoring wells, collection of soil samples, and determining the influence of nearby tidal action. The study is complicated by hard-rock geology, a significant tidal influence, the occurence of groundwater in confined gravel lenses, and the heterogeneity of soils within fill areas.

o Analysis of hydrogeologic/groundwater quality data for production facilities in Clarecastle, Ireland, and in Cuernavaca, Mexico. The work is part of an in-house program of environmental auditing and regulatory compliance being conducted by a large pharmaceuticals company at all of their facilities.

By providing education for the professional community, Gary Aguiar has maintained close contact with the University of California. Through this contact, experts in particular fields can be easily networked, while maintaining low operating overhead costs. In addition, the latest technologies in sampling and contamination remediation are continually evaluated and made available to the client.

DEPARTMENT OF CONSUMER AFFAIRS

BOARD OF REGISTRATION FOR PRUFESSIONAL ENGINEERS AND LAND SURVEYORS

CIVIL ENGINEER
LICENSE NO. C 034262
AGUIAR GARY HENRY
280 HOWLAND ST \$308
REDWOOD CITY CA

REFERENCE # N 097297

~09/30/91

CA 94953 Expiration Date

ATTACHMENT C

Site Safety Plan

HEALTH AND SAFETY PROCEDURES

FOR

FIELD INVESTIGATION OF UNDERGROUND SPILLS OF MOTOR OIL AND PETROLEUM DISTILLATE FUEL

1.0 PURPOSE

This operating procedure established minimum procedures for protecting personnel against the hazardous properties of motor oil and petroleum distillate fuels during the performance of field investigations of known and suspected underground releases of such materials. The procedure was developed to enable health and safety personnel and project managers to quickly prepare and issue site safety plans for investigations of such releases.

2.0 APPLICABILITY

This procedure is applicable to field investigations of underground releases of the substances listed below and involving one or more of the activities listed below.

Substances

Motor oil (used and unused)
Leaded and unleaded gasoline
No. 1 Fuel oil (kerosene, JP-1)
No. 1-D Fuel oil (light diesel)
No. 2 Fuel oil (home heating oil)
No. 2-D Fuel oil (medium diesel)
No. 4 Fuel oil (residual fuel oil)
No. 5 Fuel oil (residual fuel oil)
No. 6 Fuel oil (Bunker C fuel oil)
JP-3, 4 & 5 (jet fuels)
Gasahol

Activities

Collection of samples of subsurface soil with aid of truck-mounted drill rig, hand-held power auger or hand auger.

Construction, completion and testing of groundwater monitoring wells.

Collection of groundwater samples from new and existing wells.

Observing removal of underground fuel pipes and storage tanks.

This procedure must not be used for confined space entry (including trench entry) or for installing or operating pilot and full-scale fuel recovery systems.

No safety plans needed for non-intrusive geophysical surveys, reconnaissance surveys and collection of surface soil, surface water and biota.

3.0 RESPONSIBILITY AND AUTHORITY

Personnel responsible for project safety are the Business Unit Health and Safety Officer (HSO), the Project Manager (PM) and the Site Safety Officer (SSO).

The HSO is responsible for reviewing and approving site safety plans and any addenda and for advising both PM and SSO on health and safety matters. The HSO has the authority to audit compliance with the provisions of site safety plans. suspend work or modify work practices for safety reasons, and to dismiss from the site any individual whose conduct on site endangers the health and safety of others.

The PM is responsible for having site safety plans prepared and distributing them to all field personnel and to an authorized representative of each firm contracted to assist with on-site work. The PM is also responsible for ensuring that the provisions of safety plans and their addenda are carried out.

The SSO is responsible for assisting the PM with on site implementation of site safety plans. Responsibilities include:

- 1. Maintaining safety equipment supplies.
- 2. Performing or supervising air quality measurements.
- 3. Directing decontamination operations and emergency response operations.
- 4. Setting up work zone markers and signs if such zones are specified in the site safety plan.
- 5. Reporting all accidents, incidents and infractions of safety rules and requirements.
- 6. Directing other personnel to wear protective equipment when use conditions described in Section 5.0 are met.

The SSO may suspend work anytime he/she determines that the provisions of the site safety plan are inadequate to ensure worker safety and inform the PM and HSO of individuals who on-site behavior jeopardizes their health and safety or the health and safety of others.

4.0 HAZARD EVALUATION

Motor oil and petroleum distillate fuels are mixtures of aliphatic and aromatic hydrocarbons. The predominant classes of compounds in motor oil, gasoline, kerosene and jet fuels are the paraffins (e.g., benzene, toluene). Gasoline contains about 80 percent paraffins, 6 percent naphthenes, and 14 percent aromatic. Kerosene and jet fuels contain 42-48 percent paraffins, 36-38 percent naphthenes, and 16-20 percent aromatic. Diesel fuels and heating oils contain less than 10 percent paraffins, 14-23 percent naphthenes, and 68-78 percent non-volatile aromatic. These heavier fuels contain almost no volatile aromatic compounds. Chemicals are usually added to automotive and aviation fuels to improve their burning properties. Examples are tetraethyl-lead and ethylene dibromide. Most additives are proprietary materials.

Flammability

Crude oil and petroleum distillate fuels possess two intrinsic hazardous properties, namely, flammability and toxicity. The flammable property of the oil and fuels presents a far greater hazard to field personnel than toxicity because it is difficult to protect against and can result in catastrophic consequences. Being

flammable, the vapors of volatile components of crude oil and the fuels can be explosive when confined.

The lower flammable or explosive limits (LFL or LEL) of the fuels listed in SEction 508.2 range from 0.6 percent for JP-5 to 1.4 percent for gasolines. LFL and LEL are synonyms. Flash points range from -36°F for gasoline to greater than 150°F for No. 6 fuel oil. JP-5 has a flash point of 140°F. Although it has a lower LEL than gasoline, it can be considered less hazardous because its vapors must be heated to a higher temperature to ignite.

Crude oil and petroleum distillate fuels will not burn in the liquid form; only the vapors will burn and only if the vapor concentration is between the upper and lower flammable limits, sufficient oxygen is present, and an ignition source is present. If these conditions occur in a confined area an explosion may result.

The probability of fire and explosion can be minimized by eliminating any one of the three factors needed to produce combustion. Two of the factors -- ignition source and vapor concentration -- can be controlled in many cases. Ignition can be controlled by prohibiting open fires and smoking on site, installing spark arrestors on drill rig engines, and turning the engines off when LELs are approached. Vapor concentrations can be reduced by using fans. In fuel tanks, vapor concentrations in the head space can be reduced by introducing dry ice (solid carbon dioxide) into the tank; the carbon dioxide gas will displace the combustible vapors.

Toxicity

Crude oil and petroleum distillate fuels exhibit relatively low acute inhalation and dermal toxicity. Concentrations of 160 to 270 ppm gasoline vapor have been reported to cause eye, nose and throat irritation after several hours of exposure. Levels of 500 to 900 ppm can cause irritation and dizziness in one hour, and 2000 ppm produces mile anesthesia in 30 minutes. Headaches have been reported with exposure to 25 ppm or more of gasoline vapors measured with a photoionization meter. Most fuels, particularly gasoline, kerosene and jet fuels are capable of causing skin irritation after several hours contact with the skin.

Petroleum fuels exhibit moderate oral toxicity. The lethal dose of gasoline in children has been reported to be as low as 10-15 grams (2-3 teaspoons). In adults, ingestion of 20-50 grams of gasoline may produce severe symptoms of poisoning. If liquid fuel aspirated (passed in to the lungs) gasoline and other petroleum distillate fuels may cause secondary pneumonia.

Some of the additives to gasoline, such as ethylene dichloride, ethylene dibromide, and tetraethyl and tetramethyl lead, are highly toxic; however, they are present in such low concentrations that their contribution to the overall toxicity of gasoline and other fuels is negligible in most instances.

OSHA has not developed permissible workplace exposure limits for crude oil and petroleum distillate fuels. It recommends using permissible exposure limits for individual components, such as benzene. ACGIH has established a permissible exposure limit of 300 ppm for gasoline. The limit took into consideration the average concentration of benzene in gasoline (one percent) as well as its common additives. Exposure limits established by other countries range from 250 to 500 ppm. Chemical data sheets, prepared for the U.S. Coast Guard's Chemical Hazard Information System (CHRIS), list 200 ppm as the permissible exposure limit for kerosene and jet fuels. This limit was not developed by NIOSH/OSHA or ACGIH.

5.0 HEALTH AND SAFETY DIRECTIVES

5.1 <u>Site-Specific Safety Briefing</u>

Before field work beings, all field personnel, including subcontractor employees, must be briefed on their work assignments and safety procedures contained in this document.

5.2 <u>Personal Protective Equipment</u>

The following equipment should be available on-site to each member of the field team:

- NIOSH-approved full or half-face respirator with organic vapor cartridges (color coded black)
- Saranex or polyethylene-coated Tyvek coveralls
- Splash-proof safety goggles
- Nitrile or neoprene gloves
- Neoprene or butyl boots, calf-length with steel toe and shank
- Hardhat

Equipment Usage

Chemical-resistant safety boots must be worn during the performance of work where surface soil is obviously contaminated with oil or fuel, when product quantities of oil or fuel are likely to be encountered, and within 10 feet of operating heavy equipment.

Respirators must be worn whenever total airborne hydrocarbons levels in the breathing zone of field personnel reach or exceed a 15-minute average of 25 ppm. If total airborne hydrocarbons in the breathing zone exceeds 100 ppm, work must be suspended, personnel directed to move a safe distance from the source, and the HSO or designee consulted.

Chemical resistant gloves must be worn whenever soil or water known or suspected of containing petroleum hydrocarbons is collected or otherwise handled.

Chemical resistant coveralls must be worn whenever product quantities of fuel are actually encountered and when oil or fuel-saturated soil is handled.

Safety goggles must be worn when working within 10 feet of any operating heavy equipment (e.g., drill rig, backhoe). Splash-proof goggles or face shields must be worn whenever product quantities of oil or fuel are encountered.

Hardhats must be worn when working within 10 feet of an operating drill rig, backhoe or other heavy equipment.

Operators of some facilities, such as refineries, often require all personnel working within facility boundaries to wear certain specified safety equipment. Such requirements shall be strictly observed

5.3 Vapor Monitoring

Required Equipment

--- Organic vapor meter with flame or photoionization detector --- Combustible gas meter

Monitoring Requirements and Guidelines

Vapor monitoring shall be performed as often as necessary and whenever necessary to protect field personnel from hazardous vapors. Monitoring must be performed by individuals trained in the use and care of the monitoring equipment.

During drilling operations, vapor emissions from boreholes must be measured whenever the auger is removed from the boring and whenever flights are added or removed from hollow-stem augers. This requirement does not apply to borings less than five feet deep and borings of any depth made to install monitoring wells in uncontaminated soils. Measurements should be made initially with an organic vapor meter, followed with a combustible gas meter if vapor levels exceed the highest concentration measurable with the organic vapor meter.

Initially measurements shall be made about 12 inches from the bore hole, both upwind and downwind positions. If the total hydrocarbon concentrations exceed the respirator use action level (See Section 508.5.2), measurements must be made in the breathing zone of the individual(s) working closest to the borehole. Decisions regarding respiratory protection should be made using vapor concentrations in the breathing zone.

Organic vapor meters capable of being operated continuously without attention may be operated in that fashion if desired. However, the instrument must be equipped with an alarm set to sound when vapor concentrations reach 25 ppm and must be protected against physical damage and soilage.

If total organic vapor concentrations within 12 inches of the borehole exceed the capacity of the organic vapor meter, a combustible gas meter (CGM) must be used to determine if explosive conditions exist. Operations must be suspended, the drill rig motor shut down, and corrective action taken if combustible gas concentrations reach 40 percent of LEL within a 12-inch radius of

the borehole or 10 percent of LEL at a distance greater than 24 inches from the borehole. This procedure must also be followed whenever the organic vapor meter goes offscale at its highest range and no CGM is available. If corrective action cannot be taken, field personnel and all other individuals in the vicinity of the borehole must be directed to move to a safe are and the local fire department and facility management must be alerted.

Organic vapor meters with flame ionization detectors (FID) are much more sensitive to paraffins, with the major component of gasoline, kerosene, and jet fuels, then are meters with 10.0 or 10.2 eV photoionization detectors. As the data in Table 1 show, an FID instrument, such as the Century Systems OVA (Foxboro Analytical), will detect 70-90 percent of actual paraffin concentrations, whereas PID instruments, such as the HNU Model PI-101, AID Model 580, and Photovac TIP with 10.0 to 10.2 eV lamp will detect only 17-25 percent of actual paraffin concentrations when calibrated with benzene and only 24-35 percent when calibrated isobutylene. Both types of meters are equally sensitive to most aromatic, including benzene, toluene, xylene and ethylbenzene. For these compounds, meter readings equal or exceed 100 percent of actual concentrations. PIDs with 11.7 eV lamps are extremely to paraffins sensitive and aromatic. When calibrated isobutylene, an 11.7 eV PID will register about twice actual paraffin concentrations and 100 percent or more of concentrations of benzene, toluene, and xylene.

An FID meter, recently calibrated with methane and in good working condition, can be expected to provide readings close enough to actual petroleum hydrocarbon concentrations to make corrections unnecessary. Value obtained with a PID must be corrected when measuring for paraffins. For 10.0 and 10.2 eV PIDs, the meter reading should be multiplied by 5 if the instrument is calibrated with benzene. If the instrument is calibrated with isobutylene, the meter readings should be multiplied by 3. If the instrument is equipped with an 11.7 eV probe and is calibrated with isobutylene, the meter reading should be divided by 2.

5.4 Area Control

Access to hazardous and potential hazardous areas of spill sites must be controlled to reduce the probability of occurrence of physical injury and chemical exposure of field personnel, visitors and the public. A hazardous or potentially hazardous area includes any area where

- Field personnel are required to wear respirators.
- Borings are being drilled with powered augers.

3. Excavating operations with heavy equipment are being performed.

The boundaries of hazardous and potentially hazardous areas must be identified by cordons, barricades, or emergency traffic cones or posts, depending on conditions. If such areas are left unattended, signs warning of the danger and forbidding entry must be placed around the perimeter if the areas are accessible to the public. Trenches and other large holes must be guarded with wooded or metal barricades spaced no further than 20 feet apart and connected with yellow or yellow and black nylon tape not less and 3/4-inches wide. The barricades must be placed no less than two feet from the edge of the excavation or hole.

Entry to hazardous areas shall be limited to individuals who must work in those areas. Unofficial visitors must not be permitted to enter hazardous areas while work in those areas is in progress. Official visitors should be discouraged from entering hazardous areas, but may be allowed to enter only if they agree to abide by the provisions of this document, follow orders issued by the site safety officer and are informed of the potential dangers that could be encountered in the areas.

5.5 <u>Decontamination</u>

Field decontamination of personnel and equipment is not required except when contamination is obvious (visually or by odor). Recommended decontamination procedures follow:

Personnel

Gasoline, kerosene, jet fuel, heating oil, gasahol and diesel oil should be removed from skin using a mild detergent and water. Hot water is more effective than cold. Liquid dishwashing detergent is more effective than hand soap. Motor oil and the heavier fuel oils (No. 4-6) can be removed with dishwashing detergent and hot ware also; however, if weathered to an asphaltic condition, mechanic's waterless hand cleaner is recommended for initial cleaning followed by detergent and water.

Equipment

Gloves, respirators, hardhats, boots and goggles should be cleaned as described under personnel; however, if boots do not become clean after washing with detergent and water, wash them with a strong solution of trisodium phosphate and hot water and, if this fails, clean them with diesel oil followed by detergent and water to remove diesel oil.

Sampling equipment, augers, vehicle undercarriages and tires should be steam cleaned. The steam cleaner is a convenient source of hot water for personnel and protective equipment cleaning.

5.6 Smoking

Smoking and open flames are strictly prohibited at sites under investigation.

TABLE 1
RELATIVE SENSITIVITIES OF FID AND PID INSTRUMENTS TO
SELECTED COMPONENTS OF OILS AND PETROLEUM DISTILLATE FUELS

**************************************	Sensitivity	in Percent of Stand			
	FID	PII			
Component		10.2 eV	11.7 eV		
Paraffins					
Pentane	65	milit opin	141		
Hexane	70	22 (31)	189		
Heptane	75	17 (24)	221		
Octane	80	25 (35)	Feb 400		
Nonane	90		***		
Decane	75				
<u>Napthenes</u>					
Cyclopentane		440 444	*** (***		
Methylcyclopentane	80				
Cyclohexane	85	34 (40)			
Methylcyclohexane	100				
Aromatic					
Benzene	150	100 (143)	122		
Toluene	110	100 (143)	100		
Ethylbenzene	100	the ten			
p-Xylene	116	114 (60)			
Cumene	100				
n-Propylbenzene					
Napthaeine	-				

Values are relative to benzene standard. Values in parentheses are relative to isobutylene standard and were calculated.

Values are relative to isobutylene standard.

	UNDERGROUND STORAGE TANK UNAUTHORIZED RELEASE (LEAK) / CONTAMINATION SITE REPORT										
	HAS STATE OFFICE OF EMERIGENCY SERVICES REPORT BEEN FILED? YES Y NO ORT DATE CASE #	FOR LOCAL AGENCY USE ONLY. 1 HEREBY CERTIFY THAT I AM A DESIGNATED GOVERNMENT EMPLOYEE AND THAT I HAVE REPORTED THIS INFORMATION TO LOCAL OFFICIALS PURSUANT TO SECTION 25180.7 OF THE HEALTH AND SAFTY CODE.									
1.	1 1 4 0 4 5 8 8 9	SKIGNED	DATE								
	NAME OF INDIVIDUAL FILING REPORT PHONE	SIGNATORE /	1								
<u>_</u>	BRUCE HAGEMAN (415		leque								
8	REPRESENTING WNER/OPERATOR REGIONAL BOARD	COMPANY OR AGENCY MANE	<i>' (</i>								
REPORTED BY	LOCAL AGENCY OTHER	HAGEMAN-SCHANK, INC									
"	7494 DONOHUE DRIVE	Dimi tar	04.500								
 	NAME	CITY DUBLIN	BTATE CA 94568								
3.80E	DOUGHERTY REGIONAL FIRE AUTHORITY	TOM HATHCOX, FIRE MARSH	AL 415-829-2333								
RESPONSIBLE PARTY	ADDRESS										
Ä	9399 STREET FIRCREST LANE	CHY SAN RAMON	STATE CA 94582								
	FACILITY NAME (# APPLICABLE)	OPERATOR	PHONE								
Š	DOUGHERTY FIRE STATION # 1	F. M. TOM HATHCOX	415) 829-2333								
OCA	DOUGHERTY FIRE STATION # 1 T. M. TOM HATHCOX Q1578 ADDRESS 7494 DONOHUE DRIVERT COUNTY CROSS STREET TYPE OF AREA COMMERCIAL NOUSTRIAL RURAL TYPE OF BUSINESS RE										
Ĕ	7494 DONOHUE DRIVE		COUNTY ZIP								
"	1	THER FARM	OTHER FIRE STA.								
g	LOCAL AGENCY AGENCY NAME	CONTACT PERSON ,	PHONE								
MPLEMENTING AGENCIES	ALAMEDA COUNTY HEALTH	MR. GIL WISTAR	(415271-4320								
A GE	REGIONAL BOARD		PHONE								
3	SAN FRANCISCO BAY	LES FELDMAN	QUANTITY LOST (GALLONS)								
88	14		W UNKNOWN								
SUBSTANCES INVOLVED	GASOLINE REGULAR		<u> </u>								
88.¥			UNKNOWN								
复		NTORY CONTROL SUBSURFACE MONITORING	NUISANCE CONDITIONS								
RY/ABATEMENT	IM IM () 01 21 8 41 9 41	K REMOVAL OTHER	PRI VA								
Y/ABA	DATE DISCHARGE BEGAN	REMOVE CONTENTS REPLACE TANK	CLOSE TANK								
ш	M M p p y y SC UNKNOWN HAS DISCHARGE BEEN STOPPED ?	REPAIR TANK REPAIR PIPING	CHANGE PROCEDURE								
DISCOVI	\mathbb{R} YES \mathbb{R} NO FYES, DATE 1_{ul} 1_{ul} 0_{ul} 2_{ul} 8_{il} 9_{ul}	OTHER									
w	SOURCE OF DISCHARGE TANKS ONLY/CAPACITY	MATERIAL CAUSE(S)									
SOURCECAUSE	TANKLEAK UNKNOWN GAL.	FIBERGLASS OVERF									
UBC	PIPING LEAK AGE YRS	X STEEL X CORRO									
	OTHER UNKNOWN CHECK ONE ONLY	OTHER SPILL	OTHER								
ZASE TA	MUNDETERMINED SOILONLY GROUNDWATER	DRINKING WATER - (CHECK ONLY IF WATER WELLS	HAVE ACTUALLY BEEN AFFECTED)								
—	CHECK ON 5 ONLY										
CURRENT STATUS	SITE INVESTIGATION IN PROGRESS (DEFINING EXTENT OF PROBLEM)	CLEANUP IN PROGRESS SIGNED OFF (CLEANUF	COMPLETED OR UNNECESSARY)								
ঠু৯	NO ACTION TAKEN POST CLEANUP MONITORING IN PROGRESS	NO FUNDS AVAILABLE TO PROCEED EVAL	LUATING CLEANUP ALTERNATIVES								
- I	CHECK APPROPRIATE ACTION(S) (SEE BACK FOR DETAILS)	DELICATE CONT. PROPERTY CO.	ENHANCED BIO DEGRADATION (IT)								
REMEDIAL ACTION	CAP SITE (CD) EXCAVATE & DISPOSE (ED) CONTAINMENT BARRIER (CB) EXCAVATE & TREAT (ET)		REPLACE SUPPLY (R8)								
₩ X	TREATMENT AT HOOKUP (HU) NO ACTION REQUIRED (NA)	OTHER (OT) TO BE DETERM	• •								
 		OSVELENM	2 ET 232								
5	, The state of the	•									
COMMENTS											
ו א											

HSC 05 (4/67)