| on the reverse side? | • Complete items 1 and/or 2 for additional services. • Complete items 3, and 4a & b. • Print your name and address on the reverse of this form so the return this card to you. • Attach this form to the front of the mailpiece, or on the back does not permit. • Write "Return Receipt Requested" on the mailpiece below the art • The Return Receipt will show to whom the article was delivered a delivered. | if space 1. $\square$ Addressee's Address of icle number 2. $\square$ Restricted Delivery  |
|----------------------|--|--|
| ADDRESS completed o  | 3. Article Addressed to: #5009 A. LEECH OWNER INTERTRADE IMPORT-EXPORT, INC.   | 4a. Article Number  Z 196 176 898  4b. Service Type  Registered Insured  COD  Express Mail Return Receipt for Merchandise  7. Date of Delivery |
| our RETURN /         | Signature (Addressee)     Signature (Agent)  | 8. Addressee's Address (Only if requested and fee is paid)  2-714 DOMESTIC RETURN RECEIPT  |


### **CERTIFIED**



ALAMEDA COUNTY
HEALTH CARE SERVICES AGENC'

Department Of Environmental Health Environmental Protection Division 1131 Harbor Bay Parkway, Suite 250 Alameda, CA 94502-6577 Z 196 176 898

MAIL





OWNER
INTERTRATION IMPORT-EXPORT, INC.
1650 NORTHLEY DRIVE
LORENZO CA 94580

| SENDER:  • Complete items 1 and/or or additional services.  • Complete items 3, and 4  • Print your name and address on the reverse of this form so that return this card to you.  • Attach this form to the front of the mailpiece, or on the back if does not permit.  • Write "Return Receipt Requested" on the insiplece below the article was delivered.  3. Article Addressed to:  Mr Abdi Mirra  Auto Tech  6008 Dougherty Rd  Dublin CA 94568  6. Signature (Addressee) | f space  1. Addressee's Address  icle number. and the date  Consult postmaster for fee.  4a. Article Number |
|---|---|
|---|---|

•

Certified Mail #

04/06/94

STID# 3604

P 386 338 149

DAVID J. KEARS, Agency Director

RAFAT A. SHAHID, ASST. AGENCY DIRECTOR

DEPARTMENT OF ENVIRONMENTAL HEALTH State Water Resources Control Board

> Division of Clean Water Programs 80 Swan Way, Rm 200 Oakland, CA 94621

**UST Local Oversight Program** (510) 271-4530

### Notice of Requirement to Reimburse

Richard Ernest Crown Metal Mrg. Co. Inc. 765 South State Route 83 Elmhurst, Il 60126-4700

Responsible Party #1 Property Owner

Elise Varon n/a 765 S. Route 83 Elmhurst, Illinois 60126

Responsible Party #2 Contact Person Contact Company

C M M & Pacific Int'l Steel 16525 Worthley Dr San Lorenzo, CA 94580

SITE

Date First Reported 02/01/87

Substance: Gasoline Petroleum: (X) Yes

The federal Petroleum Leaking Underground Storage Tank Trust Fund (Federal Trust Fund) provides funding to pay the local and state agency administrative and oversight costs associated with the cleanup of releases from underground storage tanks. The legislature has authorized funds to pay the local and state agency administrative and oversight costs associated with the cleanup of releases from underground storage tanks. The direct and indirect costs of site investigation or remedial action at the above site are funded, in whole or in part, from the Federal Trust Fund. The above individual(s) or entity(ies) have been identified as the party or parties responsible for investigation and cleanup of the above site. YOU ARE HEREBY NOTIFIED that pursuant to Title 42 of the United States Code, Section 6991b(h)(6) and Sections 25297.1 and 25360 of the California Health and Safety Code, the above Responsible Party or Parties must reimburse the State Water Resources Control Board not more than 150 percent of the total amount of site specific oversight costs actually incurred while overseeing the cleanup of the above underground storage tank site, and the above Responsible Party or Parties must make full payment of such costs within 30 days of receipt of a detailed invoice from the State Water Resources Control Board.

Please contact Juliet M SHIN, Hazardous Materials Specialist at this office if you have any questions concerning this matter.

linas Edgar B. Howell, III, Chief Wl Contract Project Director

Mike Harper, SWRCB

SWRCB Use:

Reason: Change in Rl3 address

04/06/94

### LIST OF RESPONSIBLE PARTIES FOR

SITE

StID: 3604

C M M & Pacific Int'l Steel

16525 Worthley Dr

San Lorenzo, CA 94580

Date First Reported 02/01/87

Substance: Gasoline

Petroleum (X) Yes

Richard Ernest Crown Metal Mrg. Co. Inc. 765 South State Route 83 Elmhurst, Il 60126-4700

Responsible Party #1 Property Owner

Elise Varon n/a 765 S. Route 83 Elmhurst, Illinois 60126

Responsible Party #2 Contact Person Contact Company

Na Cosmas, Ltd. 14 Mirada Road Half Moon Bay, Ca 94019

Responsible Party #3 Contact Person Contact Company

#### **銀 写具し ココム 1.4**年

|            | Sent Elise Varo   | verage Provided mornational Mail | the reverse sic | ENDER:  Complete items 1 and/or 2 for additional services.  Complete items 3, and b.  Print your name and add on the reverse of this form so turn this card to you.  Attach this form to the front of the mailpiece, or on the bares not permit.  Write "Return Receipt Requested" on the mallpiece below the The Return Receipt will show to whom the article was delivered. | ck if space<br>article number | - I also wish to receive the following rices (for an extra general):  1. Addressee's Address  2. Restricted Delivery Consult postmaster for fee. |
|------------|---|----------------------------------|-----------------|---|-------------------------------|--|
| '<br>'     | PO State an P Code Elmhurst IL  |                                  |                 | 3. Article Addressed to:<br>JMS #3604   | 1                             | icle Number 5 386 338 149 5  |
| j          | Postage * Certified Fee Special Delivery : ee   | <b>\$</b> v                      | 8               | Elise Varon<br>765 South State Route 83<br>Elmhurst IL 60126  | 4b. Sei<br>☐ Regi<br>🏡 Cert   | vice Type at stered  |
| _          | Restricted Delivery Fee  Return Receipt Showing   |                                  | -               | 1   |                               | of Belivery 4/12/94 8  |
| ne 199     | to Whom & Date Delivered  Return Receipt Showing to Whom, Date, and Addressep's Address |                                  | ETURN           | Signature (Agent)   |                               | ressee's Address (Only if requested tee is paid)   |
| ر <b>(</b> | TOTAL Postage<br>& Fees   | \$                               | E S             |   |                               | T  |
| Form 3800  | Postmark or Date 4/8/   | 94                               | y S             | S Form <b>3811</b> , December 1991 *U.S. GPO: 1992+   | 323-402 D                     | OMESTIC RETURN RECEIPT   |

DAVID J. KEARS, Agency Director

RAFAT A. SHAHID, ASST. AGENCY DIRECTOR

DEPARTMENT OF ENVIRONMENTAL HEALTH
State Water Resources Control Board
Division of Clean Water Programs
UST Local Oversight Program
80 Swan Way, Rm 200
Oakland, CA 94621
(510) 271-4530

**Certified Mail** # P 386 338 148

04/06/94 STID# 3604

### Notice of Requirement to Reimburse

Richard Ernest Crown Metal Mrg. Co. Inc. 765 South State Route 83 Elmhurst, Il 60126-4700

Responsible Party #1
Property Owner

Elise Varon n/a 765 S. Route 83 Elmhurst, Illinois 60126

Responsible Party #2 Contact Person Contact Company

C M M & Pacific Int'l Steel 16525 Worthley Dr San Lorenzo, CA 94580

SITE

Date First Reported 02/01/87

Substance: Gasoline Petroleum: (X) Yes

The federal Petroleum Leaking Underground Storage Tank Trust Fund (Federal Trust Fund) provides funding to pay the local and state agency administrative and oversight costs associated with the cleanup of releases from underground storage tanks. The legislature has authorized funds to pay the local and state agency administrative and oversight costs associated with the cleanup of releases from underground storage tanks. The direct and indirect costs of site investigation or remedial action at the above site are funded, in whole or in part, from the Federal Trust Fund. The above individual(s) or entity(ies) have been identified as the party or parties responsible for investigation and cleanup of the above site. YOU ARE HEREBY NOTIFIED that pursuant to Title 42 of the United States Code, Section 6991b(h)(6) and Sections 25297.1 and 25360 of the California Health and Safety Code, the above Responsible Party or Parties must reimburse the State Water Resources Control Board not more than 150 percent of the total amount of site specific oversight costs actually incurred while overseeing the cleanup of the above underground storage tank site, and the above Responsible Party or Parties must make full payment of such costs within 30 days of receipt of a detailed invoice from the State Water Resources Control Board.

Please contact Juliet M SHIN, Hazardous Materials Specialist at this office if you have any questions concerning this matter.

Edgar B. Howell, III, Chief Contract Project Director

cc: Mike Harper, SWRCB

SWRCB Use:

(plate: X Reason: Change in RP3 addien

04/06/94

### LIST OF RESPONSIBLE PARTIES FOR

SITE

StID: 3604

C M M & Pacific Int'l Steel

16525 Worthley Dr

San Lorenzo, CA 94580

Date First Reported 02/01/87

Substance: Gasoline Petroleum (X) Yes

Richard Ernest Crown Metal Mrg. Co. Inc. 765 South State Route 83 Elmhurst, Il 60126-4700

Responsible Party #1
Property Owner

Elise Varon n/a 765 S. Route 83 Elmhurst, Illinois 60126

Responsible Party #2 Contact Person Contact Company

Na Cosmas, Ltd. 14 Mirada Road Half Moon Bay, Ca 94019

Responsible Party #3 Contact Person Contact Company

| P · 38 | Ь | 3 | 38 | ľ | 4 | 8 |
|--------|---|---|----|---|---|---|
|--------|---|---|----|---|---|---|

| MS | 73004 |
|----|-------|
| 4  |       |
|    | 7 TM  |

### Receipt for Certified Mail

No Insurance Coverage Provided Do not use for International Mail (Con Reverse)

| 1                    | Richard Ern   | est         |
|----------------------|---|-------------|
|                      | 765 South Stat  |             |
| i<br>i               | Elmhurst IL 60  | 126-4700    |
|                      | Postage   | <b>\$</b> ; |
|                      | Certified Fer   |             |
| ł                    | Special Delivety Fre  |             |
| ţ                    | Restricted Delivery Fee                                     |             |
| 991                  | Beturn Bucept Showing<br>to Whom & Date Delivered           |             |
| ne 1                 | Return Receipt Showing to Whom Date, and Addresse's Address |             |
| J, Ju                | TOTAL Postage<br>& Fees                                     | \$          |
| Form 3800, June 1991 | Postmark or Date 4/8/9                                      | 4           |

| side       | SENDER:   |   |       |
|------------|---|---|-------|
| . <u>s</u> | Complete items 1 and/or 2 for additional services.                                  | I also wish to receive the                |       |
| à          | • Complete items 3, and 4 b.  | following 'ices (for an extra             | 'n    |
| reverse    | Print your name and add on the reverse of this form so the return this card to you. | <sup>nat we can</sup>   fee):             | Š     |
| ž          | Attach this form to the front of the mailpiece, or on the back if                   | If space 1. Addressee's Address           | ā     |
| 16         | does not permit.  | ·   | n     |
| ‡          | . Write "Return Receipt Requested" on the mailpiece below the arti                  | ticle number. 2. Restricted Delivery      | ă     |
| ₹          | . The Return Receipt will show to whom the article was delivered a                  | and the date                              | ceipt |
| 5          | delivered.  | Consult postmaster for fee.               | 3     |
| Ö          | 3. Article Addressed to: JMS #3604  | 4a. Article Number                        | C     |
| ×          | 21D #2004   | P 386 338 148                             | Ξ     |
| completed  | Richard Ernest  | <u> </u>                                  | 2     |
| Ę          | _   | 4b. Service Type                          | ב     |
| 8          | Crown Metal Mrg. Co. Inc.   | ☐ Registered ☐ Insured                    | -     |
|            | 765 South State Route 83  | X Certified                               | nsıng |
| 낇          | Elmhurst IL 60126-4700  | Express Mail Return Receipt for           | 3     |
| DRESS      | EIMIULSC ID 00120-4/00  | <u> </u>                                  | Ä     |
| ä          |   | 7. Date of Delivery                       | =     |
| 4          | /   | 4//2/94                                   | 3     |
| 긺          | 5. Signature (Addressee)  | 8. Addressee's Address (Only if requested | >     |
| TURN       | S. Stratage transaction   | and fee is paid)                          | É     |
| FI         | Mres / Kindly   | , and ree is para,                        | ğ     |
| 牊          | 6/ Signature (Agent)//  | ]   | =     |
| Ħ          |   |   |       |
| your       | 20 Carry 2011 Daniel 1001   |   |       |
| -          | PS Form <b>3811</b> , December 1991 *u.s. gpo: 1992-323-                            | 3-402 DOMESTIC RETURN DECEIDT             |       |

P 386 338 150

DAVID J. KEARS, Agency Director

Certified Mail #

RAFAT A. SHAHID, ASST. AGENCY DIRECTOR

DEPARTMENT OF ENVIRONMENTAL HEALTH
State Water Resources Control Board
Division of Clean Water Programs
UST Local Oversight Program
80 Swan Way, Rm 200
Oakland, CA 94621
(510) 271-4530

04/06/94 STID# 3604

### Notice of Requirement to Reimburse

Richard Ernest Crown Metal Mrg. Co. Inc. 765 South State Route 83 Elmhurst, Il 60126-4700

Responsible Party #1 Property Owner

Na Cosmas, Ltd. 14 Mirada Road Half Moon Bay, Ca 94019

Responsible Party #3 Contact Person Contact Company

C M M & Pacific Int'l Steel 16525 Worthley Dr San Lorenzo, CA 94580

SITE

Date First Reported 02/01/87

Substance: Gasoline Petroleum: (X) Yes

The federal Petroleum Leaking Underground Storage Tank Trust Fund (Federal Trust Fund) provides funding to pay the local and state agency administrative and oversight costs associated with the cleanup of releases from underground storage tanks. The legislature has authorized funds to pay the local and state agency administrative and oversight costs associated with the cleanup of releases from underground storage tanks. The direct and indirect costs of site investigation or remedial action at the above site are funded, in whole or in part, from the Federal Trust Fund. The above individual(s) or entity(ies) have been identified as the party or parties responsible for investigation and cleanup of the above site. YOU ARE HEREBY NOTIFIED that pursuant to Title 42 of the United States Code, Section 6991b(h)(6) and Sections 25297.1 and 25360 of the California Health and Safety Code, the above Responsible Party or Parties must reimburse the State Water Resources Control Board not more than 150 percent of the total amount of site specific oversight costs actually incurred while overseeing the cleanup of the above underground storage tank site, and the above Responsible Party or Parties must make full payment of such costs within 30 days of receipt of a detailed invoice from the State Water Resources Control Board.

Please contact Juliet M SHIN, Hazardous Materials Specialist at this office if you have any questions concerning this matter.

Edgar B. Howell, III, Chief Contract Project Director

cc: Mike Harper, SWRCB

SWRCB Use:

Uplate: x Reason: Change in RP 3 address

04/06/94

### LIST OF RESPONSIBLE PARTIES FOR

SITE

StID: 3604 C M M & Pacific Int'l Steel

16525 Worthley Dr

San Lorenzo, CA 94580

í.

Date First Reported 02/01/87

Substance: Gasoline Petroleum (X) Yes

Richard Ernest Crown Metal Mrg. Co. Inc. 765 South State Route 83 Elmhurst, Il 60126-4700

Responsible Party #1 Property Owner

Elise Varon n/a 765 S. Route 83 Elmhurst, Illinois 60126

Responsible Party #2 Contact Person Contact Company

Na Cosmas, Ltd. 14 Mirada Road Half Moon Bay, Ca 94019

Responsible Party #3 Contact Person Contact Company

### 386 338 150

| OTH | #200 |
|-----|------|
|     |      |
|     |      |
|     |      |
|     | 14   |
|     |      |

### Receipt for Certified Mail

No Insurance Coverage Provided UNITED STATES Do not use for International Mail (See Reverse)

| Cosmas, Ltd.   |          |  |  |  |  |
|--|----------|--|--|--|--|
| Street and No. 14 Mirada I                                   | Road     |  |  |  |  |
| P.O., State and ZIP Code<br>Half Moon F                      |          |  |  |  |  |
| Postage  | \$ 94019 |  |  |  |  |
| Certifica Lee  |          |  |  |  |  |
| Special Delivery Fee   |          |  |  |  |  |
| Restricted Delivery Lee                                      |          |  |  |  |  |
| Return Receipt Showing<br>to Whom & Oute Delivered           |          |  |  |  |  |
| Return Receipt Showing to Whom Date, and Addressee's Address |          |  |  |  |  |
| TOTAL Postage<br>& Fees                                      | \$       |  |  |  |  |
| Postmark or Date 4/8/94                                      |          |  |  |  |  |
|  |          |  |  |  |  |

| <b>DDRESS</b> completed on the reverse side? | SENDER:  • Complete items 1 and/or 2 for additional services. • Complete items 3, and 4 b. • Print your name and add on the reverse of this form so the return this card to you. • Attach this form to the front of the mailpiece, or on the back is does not permit. • Write "Return Receipt Requested" on the mailpiece below the article of the receipt will show to whom the article was delivered a delivered.  3. Article Addressed to: JMS #3604  Cosmas, Ltd. 14 Mirada Road Half Moon Bay CA 94019 | f space  1.  Addressee's Address  1.  Restricted Delivery Consult postmaster for fee.  4a. Article Number P 386 338 150 | tor using Keturn Receipt Service. |
|--|---|---|-----------------------------------|
| our RETURN A                                 | 5. Signature (Addressee) 6. Signature (Agent)  PS Form 3811, December 1991 *U.S. GPO 1992 222   | 8 Addressee's Address (Only if requested air fee is paid)   | i nank you                        |

ALCO HAZMAT

765 SOUTH STATE ROUTE 83 • ELMHURST, ILLINOIS 60126-4700 • PHONE 708/279-9801 157 708/279-9807

April 7, 1994

Mr. Edgar B. Howell, III
Chief Contract Project Director
Alameda County Health Care Services Agency
Department of Environmental Health
State Water Resources Control Board
Division of Clean Water Programs
UST Local Oversight Program
80 Swan Way Room 200
Oakland CA 94621

Dear Mr. Howell:

We recently received the attached Notice of Requirement to Reimburse dated 3/23/94. This was sent via Certified Mail to my attention here at Crown Metal in Illinois.

We wish to advise you that we are no longer owners of record of this property nor is Elise Varon. Mr. Anthony Varni, at the address shown as responsible party #3, is the contact person for the new owner of the property, Cosmos Ltd.

Should you have any question on the above or if I can be of further assistance please feel free to contact me.

Regards,

Richard C. Ernest

President

RCE/meb Enc.



DAVID J. KEARS, Agency Director

RAFAT A. SHAHID, ASST. AGENCY DIRECTOR

DEPARTMENT OF ENVIRONMENTAL HEALTH
State Water Resources Control Board
Division of Clean Water Programs
UST Local Oversight Program
80 Swan Way, Rm 200
Oakland, CA 94621
(510) 271-4530

Certified Mail # P 386 338 114

03/23/94 STID# 3604

### Notice of Requirement to Reimburse

Richard Ernest Crown Metal Mrg. Co. Inc. 765 South State Route 83 Elmhurst, Il 60126-4700

Responsible Party #1
Property Owner

Elise Varon n/a 765 S. Route 83 Elmhurst, Illinois 60126

Responsible Party #2 Contact Person Contact Company

C M M & Pacific Int'l Steel 16525 Worthley Dr San Lorenzo, CA 94580

SITE

Date First Reported 02/01/87

Substance: Gasoline Petroleum: (X) Yes

The federal Petroleum Leaking Underground Storage Tank Trust Fund (Federal Trust Fund) provides funding to pay the local and state agency administrative and oversight costs associated with the cleanup of releases from underground storage tanks. The legislature has authorized funds to pay the local and state agency administrative and oversight costs associated with the cleanup of releases from underground storage tanks. The direct and indirect costs of site investigation or remedial action at the above site are funded, in whole or in part, from the Federal Trust Fund. The above individual(s) or entity(ies) have been identified as the party or parties responsible for investigation and cleanup of the above site. YOU ARE HEREBY NOTIFIED that pursuant to Title 42 of the United States Code, Section 6991b(h)(6) and Sections 25297.1 and 25360 of the California Health and Safety Code, the above Responsible Party or Parties must reimburse the State Water Resources Control Board not more than 150 percent of the total amount of site specific oversight costs actually incurred while overseeing the cleanup of the above underground storage tank site, and the above Responsible Party or Parties must make full payment of such costs within 30 days of receipt of a detailed invoice from the State Water Resources Control Board.

Please contact Juliet M SHIN, Hazardous Materials Specialist at this office if you have any questions concerning this matter.

Edgar B. Howell, III, Chief Contract Project Director

cc: Mike Harper, SWRCB

SWRCB Use:

: X Reason:

03/23/94

| T.T CT | OF | RESPONSIBLE PARTIES | FOR    |
|--------|----|---------------------|--------|
| TTOT   | OF | KESLONSTDUE LUNITES | T ^ T/ |

|      | • |
|------|---|
| STTE |   |
|      |   |

StID: 3604 C M M & Pacific Int'l Steel

16525 Worthley Dr

San Lorenzo, CA 94580

Date First Reported 02/01/87 Substance: Gasoline

Petroleum (X) Yes

Richard Ernest Crown Metal Mrg. Co. Inc. 765 South State Route 83 Elmhurst, Il 60126-4700

Responsible Party #1 Property Owner

Elise Varon n/a 765 S. Route 83 Elmhurst, Illinois 60126

Responsible Party #2 Contact Person Contact Company

Anthony Varni n/a 22771 Main St. Hayward, C A 94543

Responsible Party #3 Contact Person Contact Company

### P 386 338 114

| MS | #3604 |
|----|-------|
| *  |       |

### Receipt for **Certified Mail**

No Insurance Coverage Provided Do not use for International Mail (See Reverse)

| Sent to Richard Ernest   |          |  |  |
|--|----------|--|--|
| 765 SouthState Rte 83  |          |  |  |
| Elmhurst IL 6  | 126-4700 |  |  |
| Postage  | \$       |  |  |
| Certified Fee  |          |  |  |
| Special Delivery Fee   |          |  |  |
| Restricted Delivery Fee  |          |  |  |
| Return Receipt Showing<br>to Whom & Date Delivered               |          |  |  |
| Return Receipt Showing to Whom,<br>Date, and Addressee's Address |          |  |  |
| TOTAL Postage<br>& Fecs  | \$       |  |  |
| Postmark or Date 3/29  | /94      |  |  |
|  |          |  |  |
|  |          |  |  |
| 1  |          |  |  |

| SENDER:  Complete items 1 and/or 2 for additional services.  Complete items 3, and 4 b.  Print your name and ad on the reverse of this form so the return this card to you.  Attach this form to the front of the mailpiece, or on the back if does not permit.  Write "Return Receipt Requested" on the mailpiece below the art the Return Receipt will show to whom the article was delivered a delivered. | f space<br>Icle number,                         | I also wish to receive the following vices (for an extra fee):  1. Addressee's Address  2. Restricted Delivery Consult postmaster for fee. |
|--|---|--|
| Richard Ernest Crown Metal Mrg. Co. Inc. 765 South State Route 83 Elmhurst IL 60126-4700   | P<br>4b, Serri<br>☐ Regis<br>☑ Certi<br>☐ Expre | cle Number  386 338 114  vice Type stered  |
| 5. Signature (Addressee) 6. Signature (Agent) PS Form 3811, December 1991 *u.s. GPO: 1992-325  | and 1   | essee's Address (Only if requested<br>fee is paid)  MESTIC RETURN RECEIPT  |



DAVID J. KEARS, Agency Director

RAFAT A. SHAHID, ASST. AGENCY DIRECTOR

DEPARTMENT OF ENVIRONMENTAL HEALTH
State Water Resources Control Board
Division of Clean Water Programs
UST Local Oversight Program
80 Swan Way, Rm 200
Oakland, CA 94621

(510) 271-4530

### Certified Mail # P 386 338 115

03/23/94 STID# 3604

### Notice of Requirement to Reimburse

Richard Ernest Crown Metal Mrg. Co. Inc. 765 South State Route 83 Elmhurst, Il 60126-4700

Responsible Party #1
Property Owner

Elise Varon n/a 765 S. Route 83 Elmhurst, Illinois 60126

Responsible Party #2 Contact Person Contact Company

C M M & Pacific Int'l Steel 16525 Worthley Dr San Lorenzo, CA 94580

SITE

Date First Reported 02/01/87

Substance: Gasoline Petroleum: (X) Yes

The federal Petroleum Leaking Underground Storage Tank Trust Fund (Federal Trust Fund) provides funding to pay the local and state agency administrative and oversight costs associated with the cleanup of releases from underground storage tanks. The legislature has authorized funds to pay the local and state agency administrative and oversight costs associated with the cleanup of releases from underground storage tanks. The direct and indirect costs of site investigation or remedial action at the above site are funded, in whole or in part, from the Federal Trust Fund. The above individual(s) or entity(ies) have been identified as the party or parties responsible for investigation and cleanup of the above site. YOU ARE HEREBY NOTIFIED that pursuant to Title 42 of the United States Code, Section 6991b(h)(6) and Sections 25297.1 and 25360 of the California Health and Safety Code, the above Responsible Party or Parties must reimburse the State Water Resources Control Board not more than 150 percent of the total amount of site specific oversight costs actually incurred while overseeing the cleanup of the above underground storage tank site, and the above Responsible Party or Parties must make full payment of such costs within 30 days of receipt of a detailed invoice from the State Water Resources Control Board.

Please contact Juliet M SHIN, Hazardous Materials Specialist at this office if you have any questions concerning this matter.

Edgar B. Howell, III, Chief Contract Project Director

cc: Mike Harper, SWRCB

SWRCB Use:

: X Reason:

03/23/94

### LIST OF RESPONSIBLE PARTIES FOR

SITE

StID: 3604

C M M & Pacific Int'l Steel

16525 Worthley Dr

San Lorenzo, CA 94580

Date First Reported 02/01/87 Substance: Gasoline Petroleum (X) Yes

Richard Ernest Crown Metal Mrg. Co. Inc. 765 South State Route 83 Elmhurst, Il 60126-4700

Responsible Party #1
Property Owner

Elise Varon n/a 765 S. Route 83 Elmhurst, Illinois 60126

Responsible Party #2 Contact Person Contact Company

Anthony Varni n/a 22771 Main St. Hayward, C A 94543

Responsible Party #3 Contact Person Contact Company

8 38k 338 115

JMS #3604

ž

UNITED STATES

### Receipt for Certified Mail

No Insurance Coverage Provided Do not use for International Mail (See Reverse)

| [                            | <sup>Sent to</sup> Elise Varon                                   | ,  |  |
|------------------------------|--|----|--|
|                              | 765 South State Rte 83   |    |  |
|                              | PO. State and ZIP Code<br>Elmhurst IL 60126                      |    |  |
|                              | Postage  | \$ |  |
| Ī                            | Certified Lee  |    |  |
| ļ                            | Special Delivery Fee   |    |  |
| ļ                            | Restricted Delivery Fee  |    |  |
| 991                          | Return Receipt Showing to Whom & Date Delivered                  |    |  |
| l aur                        | Return Receipt Showing to Whom,<br>Date, and Addressee's Address |    |  |
| J, J.                        | TOTAL Postage<br>& Fees  | \$ |  |
| 380                          | Postmark or Date 3/29/94   |    |  |
| Form <b>3800</b> , June 1991 |  |    |  |

| n the reverse side? | • Complete items 1 and/or 2 for additional services. • Complete items 3, and 4 b. • Print your name and add on the reverse of this form so the return this card to you. • Attach this form to the front of the mailpiece, or on the back iddes not permit. • Write "Return Receipt Requested" on the mailpiece below the art. • The Return Receipt will show to whom the article was delivered a delivered. | if space  1.  Addressee's Address ticle number.  2.  Restricted Delivery  |
|---------------------|---|---|
| etedo               | 3. Article Addressed to: JMS #3604  | 4a. Article Number<br>P 386 338 115   |
| ADDRESS completed   | Elise Varon<br>765 South State Route 83<br>Elmhurst IL 60126  | 4b. Service Type  Registered Insured  XX Certified COD  Express Mail Return Receipt for Merchandise  7. Date of Delivery APR 0 4 1994 |
| our RETURN          | 5. Signature (Addressee) 6. Signature (Agent)   | 8. Addressee's Address (Only if requested and fee is paid)  |
| ls yo               | PS Form <b>3811</b> , December 1991 ** ±0.8. gPo: 1992-320  | 3-402 DOMESTIC RETURN RECEIPT   |



DAVID J. KEARS, Agency Director

RAFAT A. SHAHID, ASST. AGENCY DIRECTOR

DEPARTMENT OF ENVIRONMENTAL HEALTH
State Water Resources Control Board
Division of Clean Water Programs
UST Local Oversight Program
80 Swan Way, Rm 200
Oakland, CA 94621

(510) 271-4530

Certified Mail # P 386 338 116

03/23/94 STID# 3604

### Notice of Requirement to Reimburse

Richard Ernest Crown Metal Mrg. Co. Inc. 765 South State Route 83 Elmhurst, Il 60126-4700

Responsible Party #1 Property Owner

Anthony Varni n/a 22771 Main St. Hayward, C A 94543

Responsible Party #3 Contact Person Contact Company

C M M & Pacific Int'l Steel 16525 Worthley Dr San Lorenzo, CA 94580

SITE

Date First Reported 02/01/87

Substance: Gasoline Petroleum: (X) Yes

The federal Petroleum Leaking Underground Storage Tank Trust Fund (Federal Trust Fund) provides funding to pay the local and state agency administrative and oversight costs associated with the cleanup of releases from underground storage tanks. The legislature has authorized funds to pay the local and state agency administrative and oversight costs associated with the cleanup of releases from underground storage tanks. The direct and indirect costs of site investigation or remedial action at the above site are funded, in whole or in part, from the Federal Trust Fund. The above individual(s) or entity(ies) have been identified as the party or parties responsible for investigation and cleanup of the above site. YOU ARE HEREBY NOTIFIED that pursuant to Title 42 of the United States Code, Section 6991b(h)(6) and Sections 25297.1 and 25360 of the California Health and Safety Code, the above Responsible Party or Parties must reimburse the State Water Resources Control Board not more than 150 percent of the total amount of site specific oversight costs actually incurred while overseeing the cleanup of the above underground storage tank site, and the above Responsible Party or Parties must make full payment of such costs within 30 days of receipt of a detailed invoice from the State Water Resources Control Board.

Please contact Juliet M SHIN, Hazardous Materials Specialist at this office if you have any questions concerning this matter.

Edgar B. Howell, III, Chief Contract Project Director

cc: Mike Harper, SWRCB

SWRCB Use:

: X Reason:

03/23/94

### LIST OF RESPONSIBLE PARTIES FOR

SITE

StID: 3604 C M M & Pacific Int'l Steel

16525 Worthley Dr

San Lorenzo, CA 94580

Date First Reported 02/01/87

Substance: Gasoline Petroleum (X) Yes

Richard Ernest Crown Metal Mrg. Co. Inc. 765 South State Route 83 Elmhurst, Il 60126-4700

Responsible Party #1 Property Owner

Elise Varon n/a 765 S. Route 83

Elmhurst, Illinois

Anthony Varni n/a 22771 Main St. Hayward, C A 94543 Responsible Party #2 Contact Person Contact Company

Responsible Party #3 Contact Person Contact Company

#### ALL BEE ABE 9

| S | #3604 |
|---|-------|
|   | A     |
|   | 7M    |

UNITED STATES

### JMS Receipt for **Certified Mail**

No Insurance Coverage Provided Do not use for International Mail (See Reverse)

|                                 | Sent to Anthony Varni  |  |  |  |
|---------------------------------|--|--|--|--|
| Ī                               | Street and No 22771 Main Street                                  |  |  |  |
|                                 | PO State and ZIP Code<br>Hayward CA 94543                        |  |  |  |
|                                 | Postage \$   |  |  |  |
|                                 | Certified Fee  |  |  |  |
| ļ                               | Special Delivery Fee   |  |  |  |
|                                 | Restricted Delivery Fee  |  |  |  |
| 991                             | Return Receipt Showing<br>to Whom & Date Delivered               |  |  |  |
| ne 1                            | Return Receipt Showing to Whom,<br>Date, and Addressee's Address |  |  |  |
| ٦,                              | TOTAL Postage & Fees \$  |  |  |  |
| PS Form <b>3800</b> , June 1991 | Postmark or Date 3 / 2 9 / 9 4                                   |  |  |  |

| n the reverse side?          | SENDER:  - Complete items 1 and/or 2 for additional services.  - Complete items 3, and 4a & b.  - Print your name and address on the reverse of this form so the return this and to your.  - Attach this form to the front of the malipiece, or on the back ideas not permit.  - Write "Return Receipt Requested" on the mailpiece below the article the return Receipt will show to whom the article was delivered a delivered. | if spece<br>icle number.               | I also wish to receive the following services (for an extra fee):  1. Addressee's Address 2. Restricted Dellvery Consult postmaster for fee. |
|------------------------------|--|--|--|
| URN ADDRESS completed on the | 3. Article Addressed to JMS #3604  Anthony Varni 22771 Main Street Hayward CA 94543 //515 Worthles Dr 5. Signature (Addressee)   | P 3  4bc Ser  Regl K Cert Expr  7 Date | icie_Number<br>86 338 116<br>vice Type<br>stered   |
| our RE                       | 6. Signature (Agent)   |  | CHECKIO OCTUBAL DECEME   |

DAVID J. KEARS, Agency Director



RAFAT A. SHAHID, ASST. AGENCY DIRECTOR

DEPARTMENT OF ENVIRONMENTAL HEALTH
State Water Resources Control Board
Division of Clean Water Programs
UST Local Oversight Program
80 Swan Way, Rm 200
Oakland, CA 94621
(510) 271-4530

November 2, 1992

Dear Sir:

The attached "Notice of Reimbursement" is not a bill. It is required by our contract with the State Water Resouces Control Board that we send this letter to all responsible parties involved in a leaking petroleum underground tank site. You fall into the following category:

You (or your contractor/consultant) deposited funds for us to use to oversee the tank removal followed by the cleanup. Your case has been transferred to the Alameda County Local Oversight Program. This will involve your being billed after the work has been accomplished. It is directed to all responsible parties as the law requires all operators and owners to be notified.

We will continue to work with you to resolve the site remediation in progress.

If you still have any question please call this office at 271-4530 and ask for the specialist noted in the attached notice.

Sincerely,

Thomas F. Peacock, Supervising HMS

Hazardous Material Division

03/23/94

### LIST OF RESPONSIBLE PARTIES FOR

SITE

StID: 3604 C M M & Pacific Int'l Steel

16525 Worthley Dr

San Lorenzo, CA 94580

Date First Reported 02/01/87 Substance: Gasoline Petroleum (X) Yes

Richard Ernest Crown Metal Mrg. Co. Inc. 765 South State Route 83 Elmhurst, Il 60126-4700

Responsible Party #1 Property Owner

Elise Varon n/a 765 S. Route 83 Elmhurst, Illinois 60126

Responsible Party #2 Contact Person Contact Company

Anthony Varni n/a 22771 Main St. Hayward, C A 94543

Responsible Party #3 Contact Person Contact Company



### MANUFACTURING COMPANY INC.

765 SOUTH STATE ROUTE 83 • ELMHURST, ILLINOIS 60126-4700 • PHONE 708/279-9800 • FAX 708/279-9807

STIO # 604

March 11, 1992

Alameda County
Department of Environmental Health
Hazardous Materials Program
80 Swan Way Room 200
Oakland, CA 94621

RE: Address Change

Attention: David J. Kears/Agency Director

Dear Mr. Kears:

Enclosed please find two separate correspondence copies from your office.

The following changes need to be made:

1.) On the Notice of Requirement to Reimburse, David S. & Elise J. Varon's address should be:

c/o Crown Metal Mfg. Co. 765 S. State Rt. 83 Elmhurst, IL 60126-4700

Save

- 2.) On the Deposit/Refund Account History:
  - a) Payor information should be:

Crown Metal Mfg. Co. 765 S. State Rt. 83 Elmhurst, IL 60126-4700 Degref.

b) Site Information should be:

Crown Metal Mfg. Co. c/o Pacific Intl. Steel Co. 16525 Worthley <u>Drive</u> San Lorenzo, CA 94580

Some

Please adjust your records accordingly. If you have any questions on the above please give me a call at the letterhead phone number.

Regards,

Richard C. Ernest President

RCE/meb Enc. AGENCY

DAVID J. KEARS, Agency Director



cate Water Resources Control Board Division of Clean Water Programs UST Local Oversight Program

DEPARTMENT OF ENVIRONMENTAL HEALTH Hazardous Materials Program 80 Swan Way, Rm. 200 Oakland, CA 94621

certified mailer #P 367 604 615

December 26, 1991 STID# 3604

### Notice of Requirement to Reimburse

Crown Metal Manufacturing Co. Inc.
ATTN: Richard Ernest
765 South State Route 83
Elmhurst, IL 60126-4700

David S. & Elise J. Varon 616 5925 So. Lowe Ave. Chicago, IL 60621

CMM @ Pacific Intl. Steel 16525 Worthley Dr. San Lorenzo, CA 94580

SITE

Contact Person Contact Company

Responsible Party

Responsible Party Property Owner

Date First Reported 02/--/87 Substance: gasoline Petroleum (X) Yes

The federal Petroleum Leaking Underground Storage Tank Trust Fund (Federal Trust Fund) provides funding to pay the local and state agency administrative and oversight costs associated with the cleanup of releases from underground storage tanks. The legislature has authorized funds to pay the local and state agency administrative and oversight costs associated with the cleanup of releases from underground storage tanks. The direct and indirect costs of overseeing removal or remedial action at the above site are funded, in whole or in part, from the Federal Trust Fund. The above individual(s) or entity(ies) have been identified as the party or parties responsible for investigation and cleanup of the above site. YOU ARE HEREBY NOTIFIED that pursuant to Title 42 of the United States Code, Section 6991b(h)(6) and Sections 25297.1 and 25360 of the California Health and Safety Code, the above Responsible Party or Parties must reimburse the State Water Resources Control Board not more than 150 percent of the total amount of site specific oversight costs actually incurred while overseeing the cleanup of the above underground storage tank site, and the above Responsible Party or Parties must make full payment of such costs within 30 days of receipt of a detailed invoice from the State Water Resources Control Board.

If you have any questions concerning this matter please contact Thomas Peacock, Supervising Hazardous Material Specialist, at this office. Notice of Requirement to Reimburse CMM @ Pacific Intl. Steel STID 3603 December 26, 1991 Page 2 of 2

Sincerely,

Edgar B. Howell, III, Chief Contract Project Director

> cc: Sandra Malos, SWRCB

| SWRCB Use :   | add:  | х                                   | Reason  | New                                      | C,                    |
|---|---|-------------------------------------|---|--|-----------------------|
|   |   |                                     |   |  |                       |
| SENDER: Complete items 1 and 2 wher 3 and 4. Put your address in the "RETURN TO" Space card from being returned to you. The return rece to and the date of delivery. For additional fees for fees and check box(es) for additional serving. Show to whom delivered, date, and additional serving. | on the rever<br>ipt fee will p<br>the following<br>ce(s) reques | se side<br>rovide<br>servic<br>ted. | a. Failure to do th<br>you the name of these are available. C | e will pro                               | vent<br>deliv<br>stm: |
| (Extra charge)  |   |                                     | (Extra cl   |  | <u></u>               |
| 3. Article Addressed to: David & Elise Varon 5925 S. Lowe Ave.  |   | 31                                  | rticle Number   | · · · · · · · · · · · · · · · · · · ·    | :                     |
| Chicago, IL 60621   |   | ∐ R<br>  <u>1</u>                   | egistered  ertified  xpress Mail                              | Insured<br>COD<br>Return Re<br>for Merch | ceip<br>andi          |
|   |   | 1                                   | ys obtain signature<br>ant and <u>DATE DELI</u>               |  | 3 <b>6</b> 6          |
| 5. Signature - Address  X Dorum 12 Baker  | <u></u> ノ   |                                     | ddressee's Addre<br>equested and fee po                       |  | if [                  |
| 6. Signature - Agent  |   | Ì                                   |   |  |                       |
| X   | AML 2 1   | 4000                                |   |  |                       |
| 7. Date of Delivery   | in to   | 1492                                |   |  | :                     |
| PS Form 3811, Mar. 1988 * U.S.G.P.O.  | 1988-212-   | -865                                | DOMESTIC  | RETURN                                   | RE                    |
|   |   |                                     |   |  |                       |

| The second secon |   |
|--|---|
| SENDER: Complete items 1 and 2 when additional 3 and 4.  Put your address in the "RETURN TO" Space on the reve card from being returned to you. The return receipt fee will read the date of delivery. For additional fees the following for fees and check box(es) for additional service(s) reques 1. St. Show to whom delivered, date, and addressee's ac (Extra charge)  | orse side. Feilure to do this will prevent                                    |
| 3. Article Addressed to:   | 4. Article Number   |
| Crown Metal Manufacturing attn: Richard Ernest 765 S. State Rt 83 Emhurst, IL 60126-4700   | Type of Service:  Registered Insured Cortified CoD Express Mail Return Receip |
|  | Always obtain signature of addressee or agent and DATE DELIVERED.             |
| 5. Signature — Address   | 8. Addressee's Address (ONLY if requested and fee paid)                       |
| 6. Signature – Agent   | ]   |
| X  | <u> </u>  |
| 7. Date of Delivery  |   |
| PS Form 3811, Mar. 1988 * U.S.G.P.O. 1988-212  | #865 DOMESTIC RETURN RE   |

### P 367 604 615 RECEIPT FOR CERTIFIED MAIL

NO INSURANCE COVERAGE PROVIDED NOT FOR INTERNATIONAL MAIL (See Reverse)

| ⊵U.S.G.P.O. 1989-234-55 | POLState and ZIP Code Chicago, IL 60                          | 621<br> s  |      |
|-------------------------|---|------------|------|
| ৱা ।                    | Certified Fee   |            |      |
|                         | Special Delivery Fee  | <i>J</i> - | アベーク |
|                         | Restricted Delivery Fee                                       |            | 0    |
|                         | Return Receipt showing to whom and Date Delivered             | ,          |      |
| ÷ 198                   | Return Receipt showing to whom, Date, and Address of Delivery |            |      |
| June,                   | TOTAL Postage and Fees  | \$ 2.31    |      |
| PS Form 3800, June 1985 | Postparyor Date  ### #30 pm 9                                 | 2          |      |
|                         |   |            |      |

### P 367 604 616

### RECEIPT FOR CERTIFIED MAIL

NO INSURANCE COVERAGE PROVIDED NOT FOR INTERNATIONAL MAIL (See Reverse)

| ю                         | (See neverse)   |         |   |
|---------------------------|---|---------|---|
| ☆ U.S.G.P.O. 1989-234-555 | Sen'Crown Metal Ma  | anufac. | ] |
|                           | Street and No. 765 S. South I                                 | Rt 83   | 1 |
| 3.G.P.O                   | Elmhurst, IL (  | 50126   | 1 |
| ∜<br>C                    | Postage   | \$      |   |
|                           | Certified Fee   | Ţ       |   |
|                           | Special Delivery Fee  | В       | ١ |
| Form 3800, June 1985      | Restricted Delivery Fee                                       |         |   |
|                           | Return Receipt showing to whom and Date Delivered             |         |   |
|                           | Return Receipt showing to whom, Date, and Address of Delivery |         |   |
|                           | TOTAL Postage and Fees  | \$2.29  |   |
|                           | Dogg Mk or Date   | 0       |   |
| ē,                        | AM 4301 9   |         |   |
| 2                         |   | ĺ       |   |

Fold at line over top of envelope to the right