

May 25, 1990

Golden, Stefan, Ellenberg & Toby 7677 Oakport, Suite 460 Oakland, CA 94621-1967

Attention:

Mr. George C. Rogers

Subject:

Summary Report for

Jean R. Larkin (Pacific Properties)

1628 Webster Street, Alameda, California

Exceltech Project No. 4358F

Dear Mr. Rogers:

At the request of Jean R. Larkin (Pacific Properties), Exceltech, Inc. is submitting this Summary Report, which includes analytical results and a short synopsis of the work completed at the subject site. The reason for the request, was the vast extent of contamination found in both groundwater and soil on the property.

This report, as stated, is an informational summary of the work completed at the subject site by Exceltech. Any attempt to use this report as an interpretive tool to establish responsible parties for the contamination found at the site will be done so at the sole risk, and liability of the parties doing so.

Yours truly,

Randall L. Stone Program Manager

RLS:jcd Enclosure

### **CONTENTS**

Section	Page
Background	1
Phase I Work Schedule and Objective	1
Excavation, Phase I	2
Exceltech's Proposal for Phase II	3
Excavation, Phase II	3
Phase II Summary	6
Excavation, Phase III	7
Job Summary	8
Appendices	
Background Documents	Α
Analytical Results	В
Permits/Correspondence/Manifests	С
1990 Work Summary	D

#### **Background**

Exceltech conducted Phase I work at the site based upon the proposed work plan submitted by LRA Environmental, and accepted by Alameda County Department of Environmental Health. (ACDEH) A copy of this work plan, "Plan of Corrections, Waste Oil Tank," July 24, 1989, is enclosed in Appendix A of this report. Based upon this report and our conversations with Pacific Property, the following work schedule was proposed.

#### Phase I. Work Schedule and Objective

- 1. Re-excavate the contaminated soils placed back into the waste oil tank excavation by the previous contractor.
- Excavate around the former waste oil tank area until soil sample readings
  reach non-detectable levels. Conduct confirmation sampling by sending
  samples to the laboratory.
- 3. Drill three soil borings around the new excavation and convert one to a groundwater monitoring well, as required by LRA's work plan.
- 4. Locate the monitoring well downgradient, as defined by an off-site well survey.

LRA's environmental work plan indicated the only contamination was localized only around the fill end of the waste oil tank excavation. Exceltech believed that excavation was the most prudent approach because (a) contaminated soils had been put back into the excavation and (b) the excavation boundaries were obscure. Furthermore, significant cost savings would result if the contamination could be defined and the soil borings placed in clean areas.

#### Excavation, Phase I

The first excavation phase was conducted from the end of November through early December 1989 (Site Map 1). Initially, the previously excavated soils were removed to expose native soil sidewalls. After exposing the sidewalls, it was evident that the east wall was substantially contaminated. The west wall had also visible strings of contamination.

It was agreed to extend the excavation in both west and east directions. To the west, the limit would be Webster Street; to the east, the existing building.

Excavation to the east was halted when it was determined that further excavation would undermine the building. At this time, contamination was apparent not only in the east wall of the excavation, but in the north wall as well.

Excavation to the west was stopped before Webster Street when a steel conduit was encountered. Since Pacific Properties had subleased the site to Christmas tree

vendors, Exceltech backfilled the excavation for safety and demobilized its field crews.

#### Exceltech's Proposal for Phase II

Exceltech proposed to Pacific Properties to demolish the existing building to extend the excavation in an attempt to determine the extent of contamination. Once the building was demolished, Exceltech also proposed to remove two hoists from inside excavating around their concrete-encased bases. Soil sampling would be conducted as required for formal excavation closure.

#### Excavation, Phase II

The extent of contamination at the subject site began to be revealed during the Phase II excavation (Site Map 2, photo record). Three possible additional sources of contamination besides the waste oil tank were discovered, significantly changing the scope of work. Additional sources included:

- 1. Two floor hoists.
- 2. Steel and fiberglass product lines.

Cosed in place.

Summary Report March 25, 1990 Page 4

#### Floor Hoist Area

Soil beneath the floor hoists were the first to be excavated and sampled. Contamination was extensive. Samples taken on February 2, 1990 in areas underneath and around the hoists revealed the following levels of contamination in the soils:

TPH as gasoline 1,800 ppm

TPH as diesel 6,300 ppm

Total oil and grease 4,400 ppm

The contamination had migrated not only laterally but vertically beneath the hoists. In areas underneath the hoists, visible contamination was removed below the water table, dewatering the excavation and removing soils. It was apparent (due to the extent of contamination) that these hoists had been leaking for many years.

A noteworthy discovery in the sample results taken in this area was the presence of gasoline and diesel. Gasoline constituents likely to migrate include benzene, toluene, ethyl benzene, and total xylenes (BTEX). Of those constituents, only total xylenes were present (at 19 ppm). The absence of the other constituents indicates that the contamination did not originate from a new source, but from one that had existed for some time.

Summary Report March 25, 1990 Page 5

Exceltech dewatered the excavation, pumping the water into a baker tank on-site. Samples of the water from the middle of the excavation were taken on March 14, 1990. The following constituents were present:

ТРН	860 ppb
Benzene	4.5 ppb
Toluene	8.4 ppb
Ethyl Benzene	7.1 ppb
Xylenes	7.5 ppb
High Boiling Point Hydrocarbons	2.100 ppm

#### Product Line Areas

The Phase II excavation led to the discovery of product lines, a second possible source of contamination. Both fiberglass and steel lines were exposed and removed (see photo documentation). Site Map 3 shows the approximate location of these lines.

Some of the lines were contained in the same trench, with the fiberglass lines situated above the steel lines. Staining, visible beneath some trench areas, indicated contamination. It was not apparent whether the lines had been properly capped; however, none of the lines had been grouted closed.

#### Fuel Tank

Another discovery that should be noted was a fuel tank of approximately 5,000-gallon capacity, located northwest of the demolished building. The tank had been closed in-place, that is, filled with sand and capped with cement. There was no evidence, such as staining or visible holes in the tank to suggest that the tank was a source of contamination.

#### Phase II Summary

The presence of fuel contamination became much more evident to the north and west as the excavation increased in size. Our objectives were (a) to excavate until the readings from the soils reached levels approved by the ACHD and (b) to close the excavation. Results from the February 28, 1990 sampling were sent to Mr. Ariv Levi of the ACDEH for approval. See Appendix B for a summary of work conducted in 1990.

Second, the fact that water had been impacted and needed to be addressed was now an issue. Confirming this was floating product being observed in the open excavation. Water samples taken in the north half of the excavation revealed the following water contamination levels:

High Boiling Point Hydrocarbons	(diesel)	8,600 ppm
---------------------------------	----------	-----------

TPH as gasoline	7,900 ppb
Benzene	95 ppb
Toluene	290 ppb
Ethyl Benzene	220 ppb
Xylenes	1,110 ppb
Oil and Grease	16 ppm

#### Excavation, Phase III

Based upon the analytical results of sample 1, taken on February 28, 1990 (see Appendix A), it was decided to further excavate the northwest corner of the property where Pacific and Webster Streets meet. (See Site Map 2 and photo record.) This phase of work took place between April 17 and 22, 1990.

Starting at the Pacific Street easement and moving south parallel to Webster Street, we excavated heavily contaminated soil. The contamination appeared at the 5-foot level and continued below groundwater at the 8- to 9-foot level. Contamination appeared to continue beyond the easement, underneath the Webster Street sidewalk.

During excavation, three large canopy footings were found. These footings were situated in a line running north to south, approximately 12 feet east of the Webster Street easement. The first footing, encountered approximately 25 feet south of the

Pacific Street easement, was saturated with petroleum hydrocarbons gasoline and diesel. While removing the middle footing, we noted that the contamination was very close to grade. About 2- feet to the south, contamination reached the surface underneath the concrete slab. This pattern continued to the location of the third footing which was also removed. Approximately 1 foot beyond the third footing, the depth of the contamination began to drop below grade gradually. Contamination was no longer visible at about 120 feet south of Pacific Street.

During the excavation, large amounts of asphalt and concrete rubble were encountered. This material may have been used as backfill when the underground tanks were removed. The largest amounts were found in the northwest corner extending approximately 20 feet east and 50 feet south. On several occasions, we encountered both fiberglass and steel product lines. Often the trenches had both types of product lines, with the steel below and fiberglass above. On April 18, 1990, Exceltech Staff Geologist, Douglas T. Young took soil samples from around the excavation (Appendix C). Two of the three samples had very high levels of gasoline and diesel fuel and moderate levels of oil and grease contamination.

During Phase III, approximately 1,300 cubic yards of contaminated soil were removed from the excavation. The soil was placed upon plastic sheeting on-site and covered to prevent volatilization.

#### Job Summary


It is evident that the current scope of this job has greatly exceeded anyone's expectations. To date, over 3,000 cubic yards have been excavated. The soil adjacent to Webster, and


the northwest corner of the property adjacent to Pacific, still have soil contamination that will need to be addressed in the future.


Exceltech maintains that the excavation could be closed without any further excavating in areas of the sidewalk and street. In talking with Mr. Larry Seto of the ACEDH, we agreed that backfilling wold be feasible based upon criteria outlined in a letter dated May 17, 1990 (Appendix D).

Point number 3 of that correspondence (May 17, 1990) address the attempt to place a barrier to ensure that no native contaminated soil would come into contact with clean fill. However, since groundwater has been contaminated, there are no assurances that the clean backfill will not be re-contaminated until the soil and groundwater have been cleaned up. However, Mr. Seto agreed with Exceltech that the most important aspect was to close the excavation and proceed with site development while monitoring the groundwater.

As previously stated, Exceltech has prepared this report as an informational summary. Any attempt to use this report for litigation, will be at the risk, liabilities, and responsibility of the parties involved.







### PHASE II EXCAVATON PHOTO RECORD

Photo #1
Orientation of Phase II excavation looking north.
Approximate average depth 10'




Photo #2
West wall of Phase II excavation.
Note: Fiberglass product line, steel product lines in place.




Photo #3
Northwest corner of excavation: Please note discoloration (contaminated soils) and debris in the corner.



## PHASE III EXCAVATION PHOTO RECORD

Photo #1A Orientation looking south. Note floating product on water.




Photo #2A & 3A

During excavating encountered fiberglass lines, contamination and steel lines.



#3 A

Photo #4A
Orientation looking west of current open excavation.
Note: Discoloration (contamination) on west wall, toward
Webster Street.



#### APPENDIX A

## BACKGROUND DOCUMENTS PROVIDED BY PACIFIC PROPERTIES

July 24, 1989

18UE TRIBUTE ROAD, SUITE E SACRAMENTO, CA 95E1E PHONE 916/929/92E1

FA x 516 (924.) 133

Mr. Jeff Larkin 16 Las Vegas Road Orinda, California 94563

Subject:

Plan of Correction

WASTE OIL TANK

1628 Webster Street

Alameda, Alameda County, California

OUR JOB NUMBER: E-8936

Dear Mr. Larkin:

After placing several requests to the Alameda County Health Care Services Agency our office is in receipt of a copy of the Certified letter (Certified Mail Number 833-981-267) mandating submission of a "workplan of correction" for the above referenced location. We received this copy on or about 17 July 1989.

Immediately upon our receipt of the Health Care Services Agency communication, our office contacted Mr. Larry Seto, Senior Hazardous Materials Specialist, in order to determine the exact concerns of the Health Care Services Agency regarding your site. Mr. Seto has advised us that in light of the initial results of the soils analysis from the waste oil tank excavation it is the opinion of his agency that groundwater protection is a major issue in this case. Consequently, we were advised by Mr. Seto that installation of a single monitoring well is required as part of the "workplan for correction" of conditions at your site.

As of the date that our office contacted the Alameda County Health Care Services Agency, we were provided no specific guidelines for meeting the mandates of the Agency. In the absence of such guidelines from the Health Care Services Agency, we are designing the preliminary workplan in accordance with the document entitled REGIONAL BOARD STAFF RECOMMENDATIONS FOR INITIAL EVALUATION AND INVESTIGATION OF UNDERGROUND TANKS, (2 JUNE 1988) as prepared by the staff of the Regional Water Quality Control Board North Coast, San Francisco, and Central Valley Regional Boards.

The Health Care Services Agency indicated that the release of product into the surrounding environment on your property was detected as a result of chemical analysis of a soil sample acquired from the waste oil tank excavation during the tank removal operations. Section II, Subsection 2 of the Regional Boards guidelines is specific in that soil and groundwater investigations are required if a level of Total Petroleum Hydrocarbons and/or Total Oil And Grease at one hundred (100) parts per million (ppm) is exceeded. The Health Care Services Agency further indicated that levels of Total Petroleum Hydrocarbons (as diesel) and Oil and Grease were detected at concentrations of 270 PPM and 760 PPM respectively. We feel that it is of significant importance to note that your laboratory analysis report indicates that these concentrations were detected only at the fill end of the tank. The only information that we have been provided with to date indicates that the concentrations of Total Petroleum Hydrocarbons and Oil and Grease were below the laboratory detection limits at the vent end of the tank. Given this circumstance, and the absence of any other definitive data suggesting otherwise these results might tend to suggest that the conditions at your site are the results of a small spill during the placement of product into the tank, or possibly a minor overfill.

Given this preliminary data it is proposed to conduct the investigation into the vertical and horizontal extent of the contamination per the proposed preliminary workplan.

It is the intent of this office to continue to move forward on this project pending review and acceptance of the workplan by the Alameda County Health Care Services Agency and our receipt of the agency's comments. We would appreciate receiving copies of any written communication referring to this matter that you may receive. Please reference all communications with our job number.

Very truly yours,

LRA ENVIRONMENTAL

Robert A. Nicholson Vice President

RAN:laj

- cc: 1 Rafat A. Shalid, Chief, Hazardous Materials Program
  Alameda County Healthcare Services Agency
  - l Larry Seto, Senior Hazardous Materials Specialist, Alameda County Healthcare Services Agency
  - 1 Gil Jensen, Alameda County District Attorney, Consumer and Environmental Protection Agency
  - l California Regional Water Quality Control Board San Francisco Bay Region, Oakland, California
  - 1 Bill Wagoner, George Navone & Associates
  - 1 Merwin Rose, REG, Elk Grove, CA
  - 2 Client
  - l File

# PRELIMINARY PLAN OF CORRECTION WASTE OIL TANK 1628 WEBSTER STREET ALAMEDA, ALAMEDA COUNTY, CALIFORNIA

LRA ENVIRONMENTAL JOB NUMBER E8936

STEP ONE: Obtain soil samples from three (3) borings located adjacent to the sides of the tank, and at the fill end of the tank at a distance of eight (8) to ten (10) feet from the furthest extent of the tank removal excavation. Given the laboratory results of the soil analysis indicating concentrations of Total Petroleum Hydrocarbon and Oil and Grease below laboratory detection limits at the vent end of the tank no additional boring will be placed at that location.

Under the direction of a State of California Registered Engineering Geologist soil samples will be acquired from each of the three borings at intervals of five (5) feet or at every change in lithology. Collection of the samples will commence at the surface of the soil underneath the currently existing parking lot and will terminate at a depth of fifteen (15) feet. All borings will be drilled by utilizing truck mounted drilling equipment equipped with eight (8) inch outside diameter continuous flight augers.

In each boring the Engineering Geologist will log the soils encountered. The logs of the borings will be presented in the preliminary report. Upon terminating the drilling and sampling operation, the boring will immediately be backfilled with neat Portland cement to grade.

Soil samples from each major stratigraphic unit will be collected for particle size analysis and determination of vertical permeability. Samples will be acquired by advancing either a two and one half (2 1/2) inch diameter modified California or split-spoon sampler into the soils a minimum of eighteen (18) inches using a one hundred and forty (140) pound hammer dropped thirty (30) inches. Blow counts will be recorded for every six (6) inch segment of the eighteen (18) inch drive, and will be included in the boring logs.

The soil samples will be retained in six (6) inch brass tubes contained in the sampling device. Those samples acquired for the purpose of chemical analysis will be sealed at both ends with aluminum foil sheets and then sealed with plastic end caps and taped. The samples will then be stored and transported to the laboratory in an ice chest filled with dry ice. The samples not being subjected to chemical analysis will be analyzed by field methods for volatile organic compounds. This procedure will consist of emptying the contents of the brass tube into a "ziplock" style plastic bag. The bag and its contents will be placed in the direct sunlight for a period of time, and then the bag will be pierced and the "headspace" within tested for volatile organic compounds with a portable photoionizing

hydrocarbon detection device. Results of the field analysis will be included in the preliminary report.

Based upon the headspace test results and field observations any sample with apparent contamination will be subjected to laboratory analysis. A sample from the first or second interval below the level believed to be affected will be analyzed to facilitate assessment of the vertical extent of contaminant migration. In event of no detectable contamination, those samples nearest the level of the bottom of the existing tank excavation will be arbitrarily analyzed in conjunction with those samples acquired from the first or second sampling interval below the level of suspected contamination.

Chemical analysis of the soil samples remanded to the custody of the analytical laboratory will consist of the following tests:

#1: Total Petroleum Hydrocarbons (diesel)

#2: Total Oil and Grease

#3: Benzene, Toluene, Xylene, Ethylbenzene

#4: Chloronated Hydrocarbons

#5: Detectable metals (Cd, Cr, Pb, Zn)

#6: Method 8270 (PCB's, PNA's, PCP, Creosote)

Drilling equipment including but not limited to samplers, drop hammer, drill rods, plugs, auger, etc. will be steam cleaned prior to use in each soil sampling location. Cleaning will be conducted in such a manner so as to contain the wash water, which will be contained in the appropriate drums, labeled, sealed and stored onsite prior to appropriate disposal. Sampler parts not subjected to steam cleaning will be triple rinsed in two tap water immersions and then distilled water after being decontaminated in a solution of Alconox and water. These rinse waters and the decontamination wash will also be contained in the proper drum, sealed, labeled, and stored onsite prior to appropriate disposal.

Auger cuttings (soil from the borings) produced during the drilling operations will be placed in approved drums which will be sealed, labeled, and stored onsite prior to appropriate disposal conditional upon the analytical results.

STEP 2: The environmental consultant will retain a properly licensed well driller to construct and develop a single groundwater monitoring well to be located within ten (10) feet of the fill end of the tank. Results of the particle size analysis and vertical permeability testing will be utilized for the selection of well screen slot size and well filter pack material. It is proposed to construct the monitoring well in accordance to A.S.T.M. Subcommittee D-18.21 proposed recommended practices for design and installation of groundwater monitoring wells. Soil samples will be continuously obtained as the auger is advanced. These soil samples will be subjected to the same testing protocols as the samples obtained from the soils borings.

All work will be under the direct supervision of a State of California licensed Registered Engineering Geologist. Decontamination procedures, soil and wash water storage and disposal will remain unchanged from those procedures utilized for the soils borings.

Prior to the collection of groundwater samples, the well will be purged of a minimum of five (5) wetted casing volumes prior to collection of the sample to be subjected to chemical analysis. Wetted volumes are to be determined in the field at the time the samples are collected.

Water quality parameters consisting of temperature, PH, and specific conductivity will be measured at the beginning and termination of the purging of the well. Appropriate well recovery will be allowed to take place based upon the static water level prior to collecting the sample to be analyzed in the laboratory.

STEP 3: In order to attempt to minimize future impacts to the surrounding environment it is proposed that a LIMITED soil removal program be implemented as soon as practicable. Soil from the existing tank excavation, including the material placed back into the excavation after the removal of the waste oil tank should be removed. The excavation should be limited to a depth of three (3) feet below the bottom of the waste oil tank, and extend no further than two (2) to three (3) feet beyond the existing walls of the waste oil tank excavation. Soil removed during this process will of necessity need to be disposed of in an appropriate manner, which will require your acquisition of a U.S.E.P.A. Identification number, retention of a properly licensed waste hauler, and making arrangements through the waste hauler to identify and access the proper disposal site.

The California Department of Health Services can issue a one-time U.S.E.P.A. Number by telephone. You as the property owner must acquire the identification number. Our office cannot act on your behalf in this matter. Contact the Department of Health Services at 1-916-324-1781, or 1-916-324-1790. We have been advised by that agency that this U.S.E.P.A. Identification Number can be utilized for not only the disposal of the excavated soils from the waste oil tank, but also for the disposal of the wash water and auger cuttings from the soils borings and groundwater monitoring well installation. Further information concerning the use of your U.S.E.P.A. Identification Number can be obtained from the issuing officer at the time that you contact the Department of Health Services.

#### APPENDIX A

## PROPOSED RECOMMENDED PRACTICE FOR DESIGN AND INSTALLATION OF GROUND WATER MONITORING WELLS IN AQUIFERS

PUBLISHED BY ASTM SUBCOMMITTEE D18.21

## APPENDIX B ANALYTICAL RESULTS

Exceltech 41674 Christy Street Fremont, CA 94538 Attention: John Rigter Client Project ID: Matrix Descript: #4358F, Larkin, PO# 17559 Soil Sampled: Received: Mar 19, 1990

Matrix Descript: Analysis Method: First Sample #:

EPA 5030/8015/8020 003-2897 Analyzed: Reported: Mar 21, 1990 Mar 28, 1990 Mar 29, 1990

#### TOTAL PETROLEUM FUEL HYDROCARBONS with BTEX DISTINCTION (EPA 8015/8020)

Sample Number	Sample Description	Low/Medium B.P. Hydrocarbons mg/kg (ppm)	Benzene mg/kg (ppm)	Toluene mg/kg (ppm)	Ethyl Benzene mg/kg (ppm)	Xylenes mg/kg (ppm)	
003-2897	1A	N.D.	0.0090	0.044	0.0090	0.030	
003-2898	<b>2</b> A	N.D.	0.0050	0.029	0.0060	0.020	
003-2899	3A	N.D.	N.D.	N.D.	N.D.	N.D.	
003-2900	4A '	N.D.	N.D.	N.D.	N.D.	0.011	
003-2901	<b>5A</b> 9	N.D.	N.D.	N.D.	N.D.	N.D.	
003-2902	6A 🗸	N.D.	N.D.	0.011	N.D.	N.D.	
003-2903	7A ~	N.D.	N.D.	N.D.	N.D.	N.D.	
003-2904	1B	7.0	0.020	0.021	0.075	0.22	
003-2905	<b>2B</b>	440	0.17	1.7	2.6	13	
003-2906	3B	480	0.029	0.012	0.76	1.0	
Detection Limits	<b>:</b>	1.0	0.0050	0.0050	0.0050	0.0050	

Low to Medium Boiling Point Hydrocarbons are quantitated against a gasoline standard. Analytes reported as N.D. were not present above the stated limit of detection.

**SEQUOIA ANALYTICAL** 

Vickle Tague U Project Manager



Exceltech 41674 Christy Street Fremont, CA 94538 Attention: John Rigter

Client Project ID: Matrix Descript:

First Sample #:

#4358F, Larkin, PO# 17559

Soil

Analysis Method: EPA 3550/8015 003-2897

Sampled: Mar 19, 1990 Received: Mar 21, 1990

Extracted: Mar 26, 1990 Analyzed: Mar 28, 1990

Reported: Mar 29, 1990

#### **TOTAL PETROLEUM FUEL HYDROCARBONS (EPA 8015)**

Sample Number	Sample Description	High B.P. Hydrocarbons mg/kg (ppm)
003-2897	1A	N.D.
003-2898	<b>2</b> A	N.D.
003-2899	<b>3</b> A	N.D.
003-2900	<b>4A</b>	N.D.
003-2901	5A	1.6
003-2902	<b>6A</b>	N.D.
003-2903	7A	N.D.
003-2904	1B	7.8
003-2905	28	540
003-2906	3B	1,500
Detection Limit	ls:	1.0

High Boiling Point Hydrocarbons are quantitated against a diesel fuel standard. Analytes reported as N.D. were not present above the stated limit of detection.

**SEQUOIA ANALYTICAL** 

Vickie Tague 0 **Project Manager** 



(415) 364-9600 • FAX (415) 364-9233

Exceltech 41674 Christy Street Fremont, CA 94538 Attention: John Rigter

Client Project ID: Matrix Descript:

#4358F, Larkin, PO# 17559

Soil

Analysis Method: SM 503 D&E (Gravimetric) First Sample #: 003-2897

Sampled: Mar 19, 1990

Received: Mar 21, 1990 Extracted: Mar 27, 1990

Analyzed: Mar 28, 1990 Reported: Mar 29, 1990

#### **TOTAL RECOVERABLE PETROLEUM OIL**

Sample Number	Sample Description	Oil & Grease mg/kg (ppm)
003-2897	1 <b>A</b>	N.D.
003-2898	2 <b>A</b>	N.D.
003-2899	3A	N.D.
003-2900	4A	N.D.
003-2901	5A	N.D.
003-2902	6A	N.D.
003-2903	7A	N.D.
003-2904	18	600
003-2905	28	22,000
003-2906	3B	5,000
etection Limit	s:	30

Analytes reported as N.D. were not present above the stated limit of detection.

**SEQUOIA ANALYTICAL** 

Vickie Tague U **Project Manager** 



Exceltech 41674 Christy Street

Fremont, CA 94538
Attention: John Ricter

Client Project ID: Matrix Descript:

Analysis Method:

#4358F, Larkin, Alameda, PO #17808

KSS6F, Larkin, Alameda, PU #17( 5)

Soil EPA 3550/8015

First Sample #: 004-2703

Sampled:

Apr 18, 1990

Received: Apr 19, 1990

Analyzed: Apr 20, 1990 Reported: Apr 20, 1990

#### **TOTAL PETROLEUM FUEL HYDROCARBONS (EPA 8015)**

Sample Number	Sample Description	High B.P. Hydrocarbons mg/kg (ppm)
004-2703	W-1	8,000
004-2704	W-2	N.D.
004-2705	W-3	9,800

**Detection Limits:** 

1.0

High Boiling Point Hydrocarbons are quantitated against a diesel fuel standard. Analytes reported as N.D. were not present above the stated limit of detection.

**SEQUOIA ANALYTICAL** 

Vickie Tague Project Manager

42703.EN\$ <1>



Exceltech

41674 Christy Street

Fremont, CA 94538 Attention: John Ricter Client Project ID:

#4358F, Larkin, Alameda, PO #17808

Soll

Matrix Descript: EPA 5030/8015/8020 Analysis Method: First Sample #:

004-2703

Sampled:

Apr 18, 1990

Received: Apr 19, 1990 Analyzed:

Apr 19, 1990 Reported: Apr 20, 1990

#### TOTAL PETROLEUM FUEL HYDROCARBONS with BTEX DISTINCTION (EPA 8015/8020)

Sample Number	Sample Description	Low/Medium B.P. Hydrocarbons mg/kg (ppm)	Benzene mg/kg (ppm)	Toluene mg/kg (ppm)	Ethyl Benzene mg/kg (ppm)	Xylenes mg/kg (ppm)
004-2703	W-1	6,800	13	83	130	680
004-2704	W-2	N.D.	0.0051	N.D.	N.D.	0.012
004-2705	W-3	11,000	0.33	9.1	47	300

Detection Limits: 1.0 0.0050 0.0050 0.0050
--

Low to Medium Boiling Point Hydrocarbons are quantitated against a gasoline standard. Analytes reported as N.D. were not present above the stated limit of detection.

**SEQUOIA ANALYTICAL** 

kie Tague Vickie rague Project Manager



#### **SEQUOIA ANALYTICAL**

680 Chesapeake Drive • Redwood City, CA 94063 (415) 364-9600 • FAX (415) 364-9233

Exceltech 41674 Christy Street Matrix Descript:

Client Project ID: #4358F, Larkin, Alameda, PO #17808 Soil

Sampled: Apr 18, 1990 Received: Apr 19, 1990

Fremont, CA 94538 Attention: John Ricter

Analysis Method: SM 503 D&E (Gravimetric) 004-2703

Extracted: Apr 19, 1990 Analyzed: Apr 19, 1990

First Sample #:

Reported:

Apr 20, 1990

#### **TOTAL RECOVERABLE PETROLEUM OIL**

Sample Number	Sample Description	Oil & Grease mg/kg (ppm)
004-2703	W-1	460
004-2704	W-2	N.D.
004-2705	W-3	1,500

**Detection Limits:** 

1

30

Analytes reported as N.D. were not present above the stated limit of detection.

SEQUOIA ANALYTICAL

Vickie Tague Project Manager

42703.ENS <3>



Exceltech

41674 Christy Street Fremont, CA 94538 Attention: John Rigter Client Project ID:

#4358F, Larkin, PO# 17559

Matrix Descript: Soil

Analysis Method:

SM 503 D&E (Gravimetric)

First Sample #: 003-2897 Sampled:

Mar 19, 1990

Received:

Mar 21, 1990

Extracted: Analyzed: Mar 27, 1990 Mar 28, 1990

Reported:

Mar 29, 1990

#### **TOTAL RECOVERABLE PETROLEUM OIL**

Sample Number	Sample Description	Oil & Grease mg/kg (ppm)	
003-2897	1A	N.D.	
003-2898	<b>2A</b>	N.D.	
003-2899	3A	N.D.	
003-2900	4A	N.D.	
003-2901	5A	N.D.	
003-2902	6A	N.D.	
003-2903	7A	N.D.	
003-2904	1B	600	
003-2905	28	22,000	
003-2906	3B	5,000	
etection Limit	s:	30	_

Def

Analytes reported as N.D. were not present above the stated limit of detection.

**SEQUOIA ANALYTICAL** 

Vickie Tague U Project Manager



Exceltech 41674 Christy Street Fremont, CA 94538 Attention: John Rigter

Client Project ID: Matrix Descript: Analysis Method:

First Sample #:

#4358F, Larkin, PO# 17559

Soil

EPA 3550/8015 003-2897 Sampled: Received: Mar 19, 1990 Mar 21, 1990

Extracted: M Analyzed: M Reported: M

Mar 26, 1990 Mar 28, 1990 Mar 29, 1990

### **TOTAL PETROLEUM FUEL HYDROCARBONS (EPA 8015)**

Sample Number	Sample Description	High B.P. Hydrocarbons mg/kg (ppm)		
003-2897	1A	N.D.		
003-2898	2A	N.D.		
003-2899	<b>3A</b>	N.D.		
003-2900	<b>4</b> A	N.D.		
003-2901	5A	1.6		
003-2902	<b>6</b> A	N.D.		
003-2903	7A	N.D.		,
003-2904	18	7.8		
003-2905	28	540		
003-2906	3B	1,500		
Detection Limits	s:	1.0		

High Boiling Point Hydrocarbons are quantitated against a diesel fuel standard. Analytes reported as N.D. were not present above the stated limit of detection.

**SEQUOIA ANALYTICAL** 

Vickie Tague () Project Manager Exceltech 41674 Christy Street Fremont, CA 94538 Attention: John Rigter Client Project ID: Matrix Descript: Analysis Method:

First Sample #:

#4358F, Larkin, PO# 17559

Soil EPA 5030/8015/8020

003-2897

Sampled: M Received: M

Mar 19, 1990 Mar 21, 1990

Analyzed: Mar 28, 1990 Reported: Mar 29, 1990

# TOTAL PETROLEUM FUEL HYDROCARBONS with BTEX DISTINCTION (EPA 8015/8020)

Sample Number	Sample Description	Low/Medium B.P. Hydrocarbons mg/kg (ppm)	Benzene mg/kg (ppm)	Toluene mg/kg (ppm)	Ethyl Benzene mg/kg (ppm)	Xylenes mg/kg (ppm)	
003-2897	1A	N.D.	0.0090	0.044	0.0090	0.030	
003-2898	2A	N.D.	0.0050	0.029	0.0060	0.020	
003-2899	3A	N.D.	N.D.	N.D.	N.D.	N.D.	
003-2900	4A	N.D.	N.D.	N.D.	N.D.	0.011	
003-2901	5A	N.D.	N.D.	N.D.	N.D.	N.D.	
003-2902	<b>6</b> A	N.D.	N.D.	0.011	N.D.	N.D.	
003-2903	7A	N.D.	N.D.	N.D.	N.D.	N.D.	
003-2904	18	7.0	0.020	0.021	0.075	0.22	
003-2905	28	440	0.17	1.7	2.6	13	
003-2906	3B	480	0.029	0.012	0.76	1.0	
Detection Limits	•	1.0	0.0050	0.0050	0.0050	0.0050	

Low to Medium Boiling Point Hydrocarbons are quantitated against a gasoline standard.

SEQUOIA ANALYTICAL

Analytes reported as N.D. were not present above the stated limit of detection.

Vickie Tague U Project Manager



680 Chesapeake Drive • Redwood City, CA 94063 (415) 364-9600 • FAX (415) 364-9233

**Exceltech** 

41674 Christy Street Fremont, CA 94538

Attention: Randy Stone

Client Project ID: Matrix Descript:

Analysis Method:

First Sample #:

#4358F, Larkin, PO #17559

Water

EPA 3510/8015 003-2896

Sampled: Received: Extracted: Mar 14, 1990 Mar 21, 1990

Mar 21, 1990

Mar 27, 1990

Analyzed: Reported: Apr 2, 1990

### **TOTAL PETROLEUM FUEL HYDROCARBONS (EPA 8015)**

Sample Number

Sample Description

High B.P. Hydrocarbons

> μg/L (ppb)

0032896 C

X

2,100

**Detection Limits:** 

50

High Boiling Point Hydrocarbons are quantitated against a diesel fuel standard. Analytes reported as N.D. were not present above the stated limit of detection.

SEQUOIA ANALYTICAL

Project Manager

32896.ENS <1>



#4358F, Larkin, PO #17559 Exceltech Client Project ID: Sampled: Mar 14, 1990 Sample Descript.: Water, XI 41674 Christy Street Received: Mar 21, 1990 Fremont, CA 94538 Analysis Method: EPA 5030/8015/8020 Analyzed: Mar 22, 1990 Attention: Randy Stone Lab Number: 003-2896 Reported: Apr 2, 1990

#### TOTAL PETROLEUM FUEL HYDROCARBONS WITH BTEX DISTINCTION (EPA 8015/8020)

Analyte	Detection Limit	Sample Results		
	μg/L (ppb)	pg/L (ppb)		

Low to Medium Boiling Point Hydrocarbons # 30	
Benzene	
Toluene	
Ethyl Benzene	
Xylenes	

Low to Medium Boiling Point Hydrocarbons are quantitated against a gasoline standard. Analytes reported as N.D. were not present above the stated limit of detection.

SEQUOIA ANALYTICAL

Vickie Tague Project Manager



680 Chesapeake Drive • Redwood City, CA 94063 (415) 364-9600 • FAX (415) 364-9233

Exceltech

41674 Christy Street Fremont, CA 94538 Attention: Randy Stone

Client Project ID: Matrix Descript:

#4358F, Larkin, PO #17559

Water

Analysis Method: SM 503 A&E (Gravimetric)

First Sample #: 003-2896 Sampled:

Mar 14, 1990

Received:

Mar 21, 1990 Mar 27, 1990

Extracted: Analyzed:

Mar 28, 1990

Reported:

Apr 2, 1990

#### TOTAL RECOVERABLE PETROLEUM OIL

Sample Number

Sample Description Oil & Grease

mg/L (ppm)

0032896 C

XI

N.D.

**Detection Limits:** 

10

Analytes reported as N.D. were not present above the stated limit of detection.

SEQUOIA ANALYTICAL

Vickie Tague Project Manager

32896.ENS <3>

4358F

# CHAIN OF CUSTODY RECORD

21 B-	. 1	DJECT NAN	1E		TE	STR	EQU	ESTE	D	Р	.0.11	255 <b>9</b>
SAMPLE	RS /	arkin_		٧ ا			١			L	AB C	1
(Signatur		tast		BTEX	TPH-D	J-419T	À	. 1		T	URN ARC	QUOIA DUND TIME 24/ha
NO.	DATE	TIME	STATION AND LOCATION	81	ग	ТР	6					REMARKS
	3-14-90	1700	Middle of excavation Lar	>	X	X	$\pm$				5 DA	1
: SE												
-1≱2												
100												
2												
, <b>18</b> ;	91 × 8		- s									
1885 C												
爱.											· · · · · · · · · · · · · · · · · · ·	
100											<del>'''                                  </del>	
A GARAGE	•			·							·	**************************************
17.00		a protection									·····	
	181 681											
	<u> </u>	<u> </u>	ť									
<b>*</b>	<u> </u>											
<b>19</b> 0												
34,5	, ,											
				•	1							
:36	<u>                                     </u>										<del></del>	<del>1 - 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1 -</del>
4	1		÷,		1							•
	UAGHED BY		12/ 11:00 Midule 1 Jam		LINQ	ÜIŞH	ED B	Ŷ;		DATE	: TIME:	RECEIVED BY:
AELINO	UISHED 8		ATE: TIME: RECEIVED BY:	RE	LINQ	ÜİSH	ED B	Y: .	<del></del>	DATE	: TIME:	RECEIVED BY:
REMAR				•	<b>* *</b>	ens	co (	envir			service	
REPOR	T TO: K.	<u>Stonë</u>			*			Fr	erno	41674 nt, C.A	Christy S 94538-3	IFO01 Fax (415) 651-4677



## **FAX TRANSMITTAL FORM**

Date of Transmission: 31990
Total number of pages sent, including this cover page:
Total humber of pages bond motoring who over pages
TO: Name: ARIU LEVI
Company: ALAMEDA CO HEACTH
FAX Number: 415) 568 - 3766
FROM: Name: JOHN RIGIER
SENT BY: SAME
TIME: <u>5:30PM</u>
MESSAGE: IN CLUDED ARE THE PURLYTICALS
FOR THE SITE AT 1628 WEBSTER ST
ALAMEDA (LARKIN SITE). PLEASE (ET ME
KNOW IF YOU NEED ANYTHING FURTHER.
THANKS FOR YOUR HELP
7047



680 Chasapeake Drive • Redwood City, CA 94063 (415) 364-9600 • FAX (415) 364-9233

SOIL SAMPLES

Exceltech

41674 Christy Street

Fremont, CA 94538 Attention: Randy Stone Client Project ID: Matrix Descript:

First Sample #:

CONTRACTOR OF THE PROPERTY OF

<del>anderia sikorro katendari /del> #1736-G, Larkin, PO #17074

Soll Analysis Method:

EPA 5030/8015/8020 003-0022

Sampled:

**Marie States of the States of** Feb 28, 1990

Received: Analyzed:

Mar 1, 1990 Mar 13, 1990§

Reported: Mar 15, 1990

# TOTAL PETROLEUM FUEL HYDROCARBONS with BTEX DISTINCTION (EPA 8015/8020)

Sample Number	Sample Description	Low/Medium B.P. Hydrocarbons mg/kg (ppm)	Benzene mg/kg (ppm)	Toluene mg/kg (ppm)	Ethyl Benzene mg/kg (ppm)	Xylenes mg/kg (ppm)
003-0022	<b>#1</b>	150	N.D.	N.D.	N.D.	0.20
003-0023	<b>#2</b>	3.7	N.D.	N.D.	N.D.	N.D.

**Detection Limits:** 

Wild .

1.0

0.050

0.10

0.10

0.10

Low to Medium Boiling Point Hydrocarbons are quantitated against a gasoline standard. Analytes reported as N.D. were not present above the stated limit of detection.

SEQUOIA ANALYTIÇAL

Vickle Tague Project Manager



680 Chesapeake Drive • Redwood City, CA 94063 (415) 364-9600 • FAX (415) 364-9233

SOIL SAMPLES

Exceltech

41674 Christy Street Fremont, CA 94538

Attention: Randy Stone

Client Project ID: Larkin, #1736-G Matrix Descript:

Soil

EPA 5030/8015/8020

Received: Analyzed:

Sampled:

Feb 28, 1990 Mar 1, 1990

Analysis Method: First Sample #: 003-0024

Reported:

Mar 2, 1990 Mar 9, 1990

## TOTAL PETROLEUM FUEL HYDROCARBONS with BTEX DISTINCTION (ÉPA 8015/8020)

Sample Number	Sample Description	Low/Medium B.P. Hydrocarbons mg/kg (ppm)	Benzene mg/kg (ppm)	Toluene mg/kg (ppm)	Ethyl Benzene mg/kg (ppm)	Xylenes mg/kg (ppm)	
003-0024	<b>#</b> 3	6.0	N.D.	N.D.	N.D.	N.D.	
003-0025	#4	N.D.	N.D.	N.D.	N.D.	N.D.	
003-0026	<b>#</b> 5	N.D.	N.D.	N.D.	N.D.	N.D.	
003-0027	<b>#</b> 6	1.0	N.D.	N.D.	N.D.	N.D.	
003-0103	<b>#</b> 7	N.D.	N.D.	N.D.	N.D.	N.D.	
003-0104	<b>#</b> 8	N.Ď.	N.D.	N.D.	N.D.	N.D.	

Detection Limits:	1.0	0.050	0.10	0.10	0.10

Low to Medium Boiling Point Hydrocarbons are quantitated against a gasoline standard. Analytes reported as N.D. were not present above the stated limit of detection.

**SEQUOIA ANALYTICAL** 

Vickie Tague) **Project Manager** 

30024.ENS <1>



680 Chesapeake Drive - Redwood City, CA 94063 (415) 364-9600 • FAX (415) 364-9233



Exceltech

41674 Christy Street

Fremont, CA 94538 Attention: Randy Stone Client Project ID:

#1736-G. Larkin, PO #17074

Soll Matrix Descript:

Analysis Method: First Sample #:

EPA 3550/8015 003-0022

Sampled: Received: Feb 28, 1990;

Extracted:

Mar 1, 1990§ Mar 14, 1990

Analyzed:

Mar 15, 1990

Reported: paramera esta de la completa del la completa de  la completa de  la completa de  la completa del la completa del la completa del la completa

### TOTAL PETROLEUM FUEL HYDROCARBONS (EPA 8015)

Sample Number	Sample Description	High B.P. Hydrocarbons mg/kg (ppm)
003-0022	<b>∉</b> 1	150
003-0023	<b>#</b> 2	22

**Detection Limits:** 

1.0

High Boiling Point Hydrocarbone are quantitated against a dieset fuel standard. Analytes reported as N.D. were not present above the stated limit of detection.

SEQUOIA ANALYTICAL

ForVickle Tague Project Manager



680 Chesapeake Drive • Redwood City, CA 94063 (415) 364-9600 • FAX (415) 364-9233

SOIL SAMPLES

Exceltech

41674 Christy Street Fremont, CA 94538

Attention: Randy Stone

Client Project ID: Matrix Descript:

Larkin, #1736-G

Soll

Analysis Method: EPA 3550/8015 First Sample #:

003-0024

Sampled:

Feb 28, 1990

Received: Extracted:

Mar 1, 1990 Mar 2, 1990

Analyzed:

Mar 5, 1990

Reported:

Mar 9, 1990

#### **TOTAL PETROLEUM FUEL HYDROCARBONS (EPA 8015)**

Sample Number	Sample Description	High B.P. Hydrocarbons mg/kg (ppm)
003-0024	#3	N.D.
003-0025	#4	N.D.
003-0026	<b>#</b> 5	N.D.
003-0027	<b>#</b> 6	2.9
003-0103	<b>#</b> 7	N.D.
003-0104	<b>#</b> 8	N.D.

**Detection Limits:** 

1.0

High Boiling Point Hydrocarbons are quantitated against a diesel fuel standard. Analytes reported as N.D. were not present above the stated limit of detection.

**SEQUOIA ANALYTICAL** 

Vickie Tague **Project Manager** 



680 Chesapeake Drive • Redwood City, CA 94063 (415) 364-9600 • FAX (415) 364-9233

SOIL SAMPLES

Exceltech 341674 Christy Street Fremont, CA 94538 Attention: Randy Stone

THE TAXABLE PROPERTY OF THE PR Client Project ID: Matrix Descript:

#1736-G, Larkin, PO #17074 \$01

Analysis Method: First Sample #: 003-0022

SM 503 D&E (Gravimetric)

Sampled: Feb 28, 1990

Received: Mar 1, 1990∰ Extracted: Mar 12, 1990

Analyzed: Mar 13, 1990 Reported: Mar 15, 1990 Reported:

# TOTAL RECOVERABLE PETROLEUM OIL

Sample Number	Sample Description	Oli & Greas mg/kg (ppm)		
003-0022	<b>#</b> 1	N.D.		
003-0023	<b>#</b> 2	N.D.		

**Detection Limite:** 

30

Analytes reported as N.D. were not present above the stated limit of detection.

SEQUOIA ANALYTICAL

Vickle Tague Project Manager



680 Chesapeake Drive • Redwood City, CA 94063 (415) 364-9600 • FAX (415) 364-9233

SOIL SAMPLES

Exceltech

41674 Christy Street Fremont, CA 94538 Attention: Randy Stone Client Project ID: Matrix Descript:

First Sample #:

Larkin, #1736-G

Soll

Analysis Method: SM 503 D&E (Gravimetric)

003-0024

Sampled: Received: Feb 28, 1990 Mar 1, 1990

Received: M Extracted: M

Mar 2, 1990 Mar 2, 1990

Analyzed: Reported:

Mar 9, 1990

#### TOTAL RECOVERABLE PETROLEUM OIL

Sample Number	Sample Description	Oil & Grease mg/kg (ppm)
003-0024	<b>#</b> 3	N.D.
003-0025	#4	N.D.
003-0026	<b>#</b> 5	72
003-0027	<b>#</b> 6	N.D.
003-0028	<b>#7</b>	N.D.
003-0029	#8	N.D.

-		
Det	есноп	Limits:

30

Analytes reported as N.D. were not present above the stated limit of detection.

**SEQUOIA ANALYTICAL** 

Vickie Tague ()
Project Manager

20024 ENC VE



680 Chesapeake Drive • Redwood City, CA 94063 (415) 364-9600 • FAX (415) 364-9233

WATTER SAMPLES

Exceltech

41674 Christy Street Fremont, CA 94538 Attention: Randy Stone Client Project ID:

Larkin, #1736-G Matrix Descript:

Water

SM 503 A&E (Gravimetric)

Analysis Method: First Sample #: 003-0028

Sampled:

Feb 28, 1990

Received: Extracted: Mar 1, 1990 Mar 2, 1990

Analyzed: Reported:

Mar 2, 1990 Mar 9, 1990

#### TOTAL RECOVERABLE PETROLEUM OIL

Sample Number	Sample Description	Oil & Greas mg/L (ppm)		
003-0028	<b>#</b> 7	13		
003-0030	9	16		

**Detection Limits:** 

5.0

Analytes reported as N.D. were not present above the stated limit of detection.

**SEQUOIA ANALYTICAL** 

Vickie Tague() Project Manager

30024.ENS <6>



680 Chesapeake Drive • Redwood City, CA 94063 (415) 364-9600 • FAX (415) 364-9233

WATER SAMPLES

Exceltech 41674 Christy Stree

41674 Christy Street Fremont, CA 94538 Attention: Randy Stone Client Project ID:

Laridin, #1736-G

Matrix Descript: Water
Analysis Method: EPA 3510/8015

First Sample #: 003-0028

Sampled:

Feb 28, 1990

Received: Extracted: Mar 1, 1990 Mar 2, 1990

Analyzed: Reported: Mar 5, 1990 Mar 9, 1990

#### **TOTAL PETROLEUM FUEL HYDROCARBONS (EPA 8015)**

Sample Number	Sample Description	High B.P. Hydrocarbons μg/L (ppb)
003-0028	<b>#</b> 7	8,700
003-0030	#9	8,600

**Detection Limits:** 

50

High Boiling Point Hydrocarbons are quantitated against a diesel fuel standard. Analytes reported as N.D. were not present above the stated limit of detection.

SEQUOIA ANALYTICAL

Vickle Tague Project Manager



680 Chesapeake Drive • Redwood City, CA 94063 (415) 364-9600 • FAX (415) 364-9233

NATER SAMPLES

Exceltech

41674 Christy Street Fremont, CA 94538

Attention: Randy Stone

Client Project ID:

Analysis Method:

First Sample #:

Matrix Descript:

Larkin, #1736-G, PO #17074

Water

EPA 5030/8015/8020

003-0029

Sampled:

Feb 28, 1990

Received:

Mar 1, 1990 Mar 5, 1990

Analyzed: Reported: Mar 9, 1990

TOTAL PETROLEUM FUEL HYDROCARBONS with BTEX DISTINCTION (EPA 8015/8020)

Sample Number	Sample Description	Low/Medium B.P. Hydrocarbons µg/L (ppb)	Benzene μg/L (ppb)	Toluene µg/L (ppb)	Ethyl Benzene µg/L (ppb)	<b>Xylenes</b> μg/L (ppb)
003-0029	#8	8,000	83	280	83	1,000
003-0031	#10	7,900	95	290	220	1,100

Detection Limits:	30	0.30	0.30	0.30	0.30	
<u> </u>						

Low to Medium Boiling Point Hydrocarbons are quantitated against a gasoline standard. Analytes reported as N.D. were not present above the stated limit of detection.

**SEQUOIA ANALYTICAL** 

Vickle Tague Project Manager


 $H^{-N}$ 

	PROJEC	T NOT PE	OJECT NA	ME	С	HAIN OF C	USTO	DY	RE	COR	D				
	SAMPLE	-6- 1	-arkin	)				۲ 		REQU			P.O. #	17074	<del>,                                      </del>
	(Signatur NO.	DATE	TIME	CTAT	10M AVE -	·	7-70	7-H	ンナウ	X			LABS	20 UNI	
30022	1 . 2	2-29-90	1115	See m	ON AND LO			ToH.	Š	8TE				REMAR	KS
2#	3	16	1130 1140		1 7 70	s lines,		X	S	X			غيمه ها الكا	a/ = 16 D	AYS
25	5	- 11	1200		16	11	X		X	X			24	c turn	a sound
28	<u>6</u> 7	- ''	0930	R-Ka	7,	1		X	X	X			11	,	11
II ]	8		0935	Caner.	/ank-v	laher Jar Voca		×	X	X			11		11
34	10	11	0945		cavation	n-Ambertar		X	X	X			11		(1
2030/03	7												10		11
04	8			501)			X	X	Ÿ	X		-	tour	asol	3/2.8F
	-							<del>X  </del>	<del>X</del> :	X			1/ 0	d	m
								-							Altri
											-	-			
		HED BY:	DA	TE: TIME:	RECEIVED	) BY:	To the second								
Ri		HED BY:	1 100 4 1	1-70 1:40 TE: TIME:	RECEIVED	Coli-	RELIN				<del></del>	DATE:	TIME:	RECEIVED	BY:
RI	MARKS:				HEOEIVED	ът:	RELIA	IQUIS	HED	BY:		DATE:	TIME:	RECEIVED	BY:
RE	PORT TO	D: Ranc	)v 5+	0.0 = 5	×T. 33			8	nsco	envi	ronm	ental s	ervices,		
F	ORM DATE	D 5-30-89	7		XI. 3.	2()			•	F	remor	11674 C I, C.A.	hristy Stre 94538-31		(415) 659-0401 Fax (415) 651-1677 nv. Lic. No. 550205

all samples Taken at 6 Depth Pacific 56' 120

#### ANAMETRIX INC.

Environmental & Analytical Chemistry 1521 Concourse Drive, Suite E. San 1997 (2014) 1439 | 132-8192 + Fax (408) 432-8199



Jim Durkin Ensco Environmental Services Inc. 41674 Christy Street Fremont, CA 94538-3114

February 22, 1990
Anametrix W.O.#: 9002040
Date Received : 02/05/90
Purchase Order#: 16945
Project Number : 1736G

Dear Mr. Durkin:

Your samples have been received for analysis. The REPORT SUMMARY lists your sample identifications and the analytical methods you requested. The following sections are included in this report: RESULTS and QUALITY ASSURANCE.

NOTE: 1) Amounts reported are net values, i.e. corrected for method blank contamination.

2) The following footnotes are applicable to Methods 624/8240:

\* A Method 624 priority pollutant compound (Federal Register, 10/26/84)

\*\* A compound on the U.S. EPA CLP Hazardous Substance List (HSL)

# An additional compound analyzed for by Anametrix, Inc.
ND: Not detected at or above the practical quantitation
limit for the method.

3) Surrrogate recovery for nitrobenzene-d5 was outside established limits in the EPA Method 8270 analysis.

If there is any more that we can do, please give us a call. Thank you for using ANAMETRIX, INC.

Sincerely,

ANAMETRIX, INC.

Sarah Schoen, Ph.D. Laboratory Manager

SRS/dmt

### REPORT SUMMARY ANAMETRIX, INC. (408) 432-8192

Client Address City Attn.	: Ensco Environmen : 41674 Christy St : Fremont, CA 945 : Jim Durkin	reet	Anametrix W.O.#: Date Received Purchase Order#: Project No. Date Released	02/05/90
Anametri	x   Sample I.D.	Date  Matrix Sampled	Date  Method  Extract	Date  Inst   Analyzed I.D.
RESULTS				
9002040-  9002040-	01 1,2,3,4 01 1,2,3,4 01 1,2,3,4 01 1,2,3,4	SOIL  02/02/90  SOIL  02/02/90  SOIL  02/02/90  SOIL  02/02/90	0  8270  02/12/90 0  TPH  02/08/90	02/08/90 F1    02/16/90 F2    02/13/90 N/A    02/15/90 ICP1
QUALITY	ASSURANCE (QA)			
2CB0212C	00 METHOD BLANK 02 METHOD BLANK S  METHOD BLANK	SOIL  N/A  SOIL  N/A  SOIL  N/A	8240     8270  02/12/90   6010	02/08/90 F1    02/15/90 F2    02/15/90 ICP1

#### ORGANIC ANALYSIS DATA SHEET - EPA METHOD 624/8240 ANAMETRIX, INC. (408) 432-8192

Sample I.D. : 1736G 1,2,3,4 Anametrix I.D.: 9002040-01

Matrix : SOIL
Date sampled : 02/02/90
Date analyzed: 02/08/90
Dilut. factor: 500 Analyst : w Supervisor

: 02/22/90 Date released

Instrument ID : F1

   CAS #	Compound Name	Reporting Limit (ug/Kg)	Amount   Found   (ug/Kg)
CAS #	* Chloromethane   * Vinyl Chloride   * Bromomethane   * Chloroethane   * Trichlorofluoromethane   * 1,1-Dichloroethene   # Trichlorotrifluoroethane   **Acetone   **Carbondisulfide   * Methylene Chloride   * Trans-1,2-Dichloroethene   * 1,1-Dichloroethane   * 2-Butanone   * Cis-1,2-Dichloroethene   * Chloroform   * 1,1,1-Trichloroethane   * Carbon Tetrachloride   * Benzene   * 1,2-Dichloroethane   * Trichloroethene   * 1,2-Dichloropropane   * Bromodichloromethane   * 2-Chloroethylvinylether   * *Vinyl Acetate   * Trans-1,3-Dichloropropene   * 4-Methyl-2-Pentanone   * Toluene   * cis-1,3-Dichloropropene   * 1,1,2-Trichloroethane   * Tetrachloroethene   * 2-Hexanone   * Dibromochloromethane   * Chlorobenzene   * Ethylbenzene   * *Total Xylenes   * *Styrene	5000   5000   5000   2500    ND N	
79-34-5  541-73-1  106-46-7  95-50-1	<pre>* Bromoform * 1,1,2,2-Tetrachloroethane * 1,3-Dichlorobenzene * 1,4-Dichlorobenzene * 1,2-Dichlorobenzene</pre>	2500 2500 2500 2500 2500	ND ND ND ND ND
CAS #   17060-07-0   2037-26-5   460-00-4	Surrogate Compounds 1,2-Dichloroethane-d4 Toluene-d8 p-Bromofluorobenzene	Limits   73-130%   74-121%   70-124%	% Recovery     93%     94%     100%

#### ORGANIC ANALYSIS DATA SHEET -- EPA METHOD 625/8270 ANAMETRIX, INC. (408) 432-8192

But the second of the second o

Anametrix I.D.: 9002040-01 Analyst: UK Supervisor: PG Sample I.D. : 1736G 1,2,3,4 Matrix : SOIL Date sampled : 02/02/90 Date ext. : 02/12/90 Date released : 02/22/90 Date analyzed: 02/16/90 Weight ext. : 30g Dilut. factor: NONE Instrument ID : F2

   CAS #	Compound Name	Reporting Limit (ug/Kg)	Amount   Found   (ug/Kg)
62-75-9  108-95-2	* N-Nitrosodimethylamine	330	ND
62-53-3	* Phenol	330	ND i
111-44-4	**Aniline	330	ND i
195-57-8	* bis(-2-Chloroethyl)Ether	330	ND
541-73-1	* 2-Chlorophenol	330	ND
106-46-7	* 1,3-Dichlorobenzene	ļ 330	ND
100-40-7	* 1,4-Dichlorobenzene	ļ 330	ND
95-50-1	**Benzyl Alcohol	ļ 330	ND
95-48-7	* 1,2-Dichlorobenzene	330	ND
108-60-1	**2-Methylphenol	330	ND
106-44-5	**bis(2-chloroisopropyl)Ether	330	ND
621-64-7	**4-Methylphenol	330	ND
67-72-1	* N-Nitroso-Di-n-Propylamine * Hexachloroethane	330	ND
98-95-3	* Nitrobenzene	330	ND
78-59-1	* Isophorone	330	ND
88-75-5	* 2-Nitrophenol	330	ND
105-67-9	* 2,4-Dimethylphenol	330	ND
65-85-0	**Benzoic Acid	330	ND
111-91-1	* bis(-2-Chloroethoxy) Methane	1600	ND
120-83-2	* 2,4-Dichlorophenol	330	ND
120-82-1	* 1,2,4-Trichlorobenzene	330	ND
91-20-3	* Naphthalene	330	ND
106-47-8	**4-Chloroaniline	330	790
87-68-3	* Hexachlorobutadiene	330	I ND j
59-50-7	* 4-Chloro-3-Methylphenol	330	ND
91-57-6	**2-Methylnaphthalene	330	ND
77-47-4	* Hexachlorocyclopentadiene	330	860
88-06-2	* 2,4,6-Trichlorophenol	330	ND
95-95-4	**2,4,5-Trichlorophenol	330	ND
91-58-7	* 2-Chloronaphthalene	1600	ND
88-74-4	**2-Nitroaniline	330	ND
131-11-3	* Dimethyl Phthalate	1600	ND
208-96-8	* Acenaphthylene	330	ND
99-09-2	**3-Nitroaniline	330	ND
83-32-9	* Acenaphthene	1600	ND
51-28-5	* 2,4-Dinitrophenol	330	ND
100-02-7	* 4-Nitrophenol	1600	ND
132-64-9	**Dibenzofuran	1600	ND
		330	ND i

ND: Not detected at or above practical quantitation limit for the method. A 625 approved compound (Federal Register, 10/26/84):

A compound on the U.S. EPA CLP Hazardous Substance List (HSL).

#### ORGANIC ANALYSIS DATA SHEET -- EPA METHOD 625/8270 ANAMETRIX, INC. (408) 432-8192

Sample I.D. : 1736G 1,2,3,4

Anametrix I.D.: 9002040-01 Analyst: UK Supervisor: FG Matrix : SOIL Date sampled : 02/02/90 : PG Date ext. : 02/12/90

Date released : 02/22/90 Date analyzed: 02/16/90 Weight ext. : 30g Dilut. factor: NONE Instrument ID : F2

   CAS #	Compound Name	Reporting Limit (ug/Kg)	Amount   Found   (ug/Kg)
121-14-2  606-20-2  84-66-2  7005-72-3  86-73-7  100-01-6  534-52-1  86-30-6  122-66-7  101-55-3  118-74-1  87-86-5  85-01-8  120-12-7  84-74-2  206-44-0  92-87-5  129-00-0  85-68-7  91-94-1  56-55-3  117-81-7  218-01-9  117-84-0  205-99-2  207-08-9  50-32-8  193-39-5  53-70-3  191-24-2	* 2,4-Dinitrotoluene   * 2,6-Dinitrotoluene   * Diethylphthalate   * 4-Chlorophenyl-phenylether   * Fluorene   **4-Nitroaniline   **4,6-Dinitro-2-Methylphenol   * N-Nitrosodiphenylamine   **Azobenzene   * 4-Bromophenyl-phenylether   * Hexachlorobenzene   * Pentachlorophenol   * Phenanthrene   * Anthracene   * Di-n-Butylphthalate   * Fluoranthene   * Benzidine   * Pyrene   * Butylbenzylphthalate   * 3,3'-Dichlorobenzidine   * Benzo(a)Anthracene   * bis(2-Ethylhexyl)Phthalate   * Chrysene   * Di-n-Octyl Phthalate   * Benzo(b)Fluoranthene   * Benzo(c)Pyrene   * Indeno(1,2,3-cd)Pyrene   * Dibenz(a,h)Anthracene   * Benzo(g,h,i)Perylene	330   330   330   330   1600   1600   330   300   30	ND N
CAS #	Surrogate Compounds	Limits	%Recovery
367-12-4  4165-62-2  4165-60-0  321-60-8  118-79-6  1718-51-0	2-Fluorophenol Phenol-d6 Nitrobenzene-d5 2-Fluorobiphenyl 2,4,6-Tribromophenol Terphenyl-d14	15-83%   18-92%   12-80%   16-100%   15-135%   15-117%	65% 67% 160% 64% 119%

ND: Not detected at or above practical quantitation limit for the method. A 625 approved compound (Federal Register, 10/26/84).

A compound on the U.S. EPA CLP Hazardous Substance List (HSL).

#### ANALYSIS DATA SHEET - PETROLEUM HYDROCARBON COMPOUNDS ANAMETRIX, INC. (408) 432-8192

Anametrix I.D.: 9002040-01 Sample I.D. : 1736G 1,2,3,4 : CB Analyst Matrix : SOIL : 7 Date sampled : 02/05/90 Supervisor Date released : 02/22/90 Date an1.TPHg: 02/07/90 Date ext. TOG : 02/08/90 Date ext.TPHd: 02/08/90 Date anl. TOG : 02/08/90 Date anl.TPHd: 02/13/90

CAS #	Compound Name	Detection Limit (ppm)	Amount   Found   (ppm)
71-43-2  108-88-3  100-41-4  1330-20-7	Benzene   Toluene   Ethylbenzene   Total Xylenes   TPH as Gasoline   TPH as Diesel   Total Oil & Grease	5 5 5 100 10 30	ND   ND   ND   19   1800   6300   4400

- ND Not detected at or above the practical quantitation limit for the method.
- TPHg Total Petroleum Hydrocarbons as gasoline is determined by
- GCFID using EPA Method 5030.

  TPHd Total Petroleum Hydrocarbons as diesel is determined by GCFID following either EPA Method 3510 or 3550.
- TOG Total Oil & Grease is determined by Standard Method 503E.
- BTEX Benzene, Toluene, Ethylbenzene, and Total Xylenes are determined by modified EPA 8020.

All testing procedures follow California Department of Health Services (Cal-DHS) approved methods.

# ANALYSIS DATA SHEET - INDIVIDUAL METALS ANAMETRIX, INC. - (408) 432-8192

Anametrix W.O.: 9002040 Matrix : SOIL Date Sampled : 02/02/90 Project Number: 1736G

Date Prepared: 02/13/90
Date Analyzed: 02/15/90
Date Released: 02/22/90
Instrument I.D.: ICP1

METALS	EPA Method#	Reporting Limit	Sample I.D.# 1,2,3,4	Sample I.D.# BLANK	Sample I.D.#	Sample I.D.#	Sample I.D.#
COMPOUNDS		(mg/Kg)	-01	MB0213S			
Cadmium (Cd) Total Cr Lead (Pb) Zinc (Zn)	6010 6010 6010 6010	0.5 0.5 1.0 0.5	ND 29.6 98.4 76.6	ND ND ND ND			

ND: Not detected at or above the practical quantitation limit for the method.

All Metals by EPA Method 6010/7000, Test Method for Evaluating Solid Waste, SW-846 3rd Edition November 1986, and California Administrative Code Title 22, Section 66699.

MK 2/22/90 Analyst Date X∧ 2/22/90
Supervisor Date

#### ORGANIC ANALYSIS DATA SHEET - EPA METHOD 624/8240

ANAMETRIX, INC. (408) 432-8192

Sample I.D.: METHOD BLANK Anametrix I.D.: 1CB0208V00

Matrix : SOIL Analyst : w Date sampled: N/A Supervisor : PG

Date analyzed: 02/08/90
Dilut. factor: NONE

Date released: 02/22/90
Instrument ID: F1

CAS #	Compound Name	Reporting Limit (ug/Kg)	Amount   Found   (ug/Kg)
74-87-3   75-01-4   74-83-9   75-00-3   75-69-4   75-35-4   76-13-1   67-64-1   75-15-0   75-09-2   156-60-5   75-34-3   78-93-3   156-59-2   67-66-3   71-55-6   56-23-5   71-43-2   107-06-2   79-01-6   78-87-5   75-27-4   110-75-8   108-10-1   108-10-1   108-88-3   10061-01-5   79-00-5   127-18-4   591-78-6   124-48-1   108-90-7   100-41-4   1330-20-7   100-42-5   75-25-2   79-34-5   541-73-1   106-46-7	* Chloromethane  * Vinyl Chloride  * Bromomethane  * Chloroethane  * Trichlorofluoromethane  * 1,1-Dichloroethene  # Trichlorotrifluoroethane  **Acetone  **Carbondisulfide  * Methylene Chloride  * Trans-1,2-Dichloroethene  * 1,1-Dichloroethane  **2-Butanone  * Cis-1,2-Dichloroethene  * Chloroform  * 1,1,1-Trichloroethane  * Carbon Tetrachloride  * Benzene  * 1,2-Dichloroethane  * Trichloroethene  * 1,2-Dichloropropane  * Bromodichloromethane  * 2-Chloroethylvinylether  **Vinyl Acetate  * Trans-1,3-Dichloropropene  * 4-Methyl-2-Pentanone  * Toluene  * cis-1,3-Dichloropropene  * 1,1,2-Trichloroethane  * Tetrachloroethene  * 2-Hexanone  * Dibromochloromethane  * Ethylbenzene  * Ethylbenzene  * Ethylbenzene  * Styrene  * Bromoform  * 1,1,2,2-Tetrachloroethane  * 1,3-Dichlorobenzene  * 1,4-Dichlorobenzene	10 10 10 10 10 10 10 10 10 10 10 10 10 1	ND N
95-50-1   CAS #  17060-07-0  2037-26-5	* 1,2-Dichlorobenzene  Surrogate Compounds 1,2-Dichloroethane-d4 Toluene-d8	5 Limits 73-130%	ND ND Recovery
460-00-4	p-Bromofluorobenzene	74-121% 70-124%	998 998

#### ORGANIC ANALYSIS DATA SHEET -- EPA METHOD 625/8270 ANAMETRIX, INC. (408) 432-8192

Sample I.D. : METHOD BLANK Anametrix I.D.: 2CB0212C02 Matrix : SOIL Analyst

PG Date sampled: N/A Supervisor Date ext. : 02/12/90 Date released : 02/22/90 Date analyzed: 02/15/90

Weight ext. : 30g Dilut. factor: NONE Instrument ID : F2

62-75-9	CAS #	Compound Name	Reporting Limit (ug/Kg)	Amount   Found   (ug/Kg)
208-96-8	62-75-9   108-95-2   62-53-3   111-44-4   95-57-8   541-73-1   106-46-7   100-51-6   95-50-1   95-48-7   108-60-1   106-44-5   621-64-7   67-72-1   98-95-3   78-59-1   88-75-5   105-67-9   65-85-0   111-91-1   120-83-2   120-82-1   91-20-3   106-47-8   87-68-3   59-50-7   91-57-6   77-47-4   88-06-2   95-95-4   91-58-7   88-74-4	* N-Nitrosodimethylamine * Phenol **Aniline * bis(-2-Chloroethyl)Ether * 2-Chlorophenol * 1,3-Dichlorobenzene   * 1,4-Dichlorobenzene   **Benzyl Alcohol   * 1,2-Dichlorobenzene   **2-Methylphenol   **bis(2-chloroisopropyl)Ether   **4-Methylphenol   * N-Nitroso-Di-n-Propylamine   * Hexachloroethane   * Nitrobenzene   * Isophorone   * 2-Nitrophenol   * 2,4-Dimethylphenol   **Benzoic Acid   * bis(-2-Chloroethoxy)Methane   * 2,4-Dichlorophenol   * 1,2,4-Trichlorobenzene   * Naphthalene   * 4-Chloro-3-Methylphenol   * 2-Methylnaphthalene   * 4-Chloro-3-Methylphenol   * 2-Methylnaphthalene   * Hexachlorocyclopentadiene   * 2,4,6-Trichlorophenol   * 2,4,5-Trichlorophenol   * 2-Chloronaphthalene   * 2-Chloronaphthalene   * 2-Chloronaphthalene   * 2-Chloronaphthalene	330 330 330 330 330 330 330 330	ND N
100-02-7	208-96-8  99-09-2  83-32-9  51-28-5  100-02-7	<pre>* Acenaphthylene **3-Nitroaniline * Acenaphthene * 2,4-Dinitrophenol * 4-Nitrophenol</pre>	330 1600 330 1600	ND ND ND ND

ND: Not detected at or above practical quantitation limit for the method \* A 625 approved compound (Federal Register, 10/26/84).

A compound on the U.S. EPA CLP Hazardous Substance List (HSL).

#### ORGANIC ANALYSIS DATA SHEET -- EPA METHOD 625/8270 ANAMETRIX, INC. (408) 432-8192

Anametrix I.D.: 2CB0212C02 Analyst: U Sample I.D. : METHOD BLANK

Matrix : SOIL Analyst · PG Date sampled : N/A Supervisor

Date ext. : 02/12/90 Date analyzed: 02/15/90 Date released : 02/22/90

Weight ext. : 30q Dilut. factor: NONE Instrument ID : F2

CAS #	Compound Name	Reporting Limit (ug/Kg)	Amount   Found   (ug/Kg)
121-14-2   606-20-2   84-66-2   7005-72-3   86-73-7   100-01-6   534-52-1   86-30-6   122-66-7   101-55-3   118-74-1   87-86-5   85-01-8   120-12-7   84-74-2   206-44-0   92-87-5   129-00-0   85-68-7   91-94-1   56-55-3   117-81-7   218-01-9   117-84-0   205-99-2   207-08-9   50-32-8   193-39-5   53-70-3	* 2,4-Dinitrotoluene * 2,6-Dinitrotoluene * Diethylphthalate * 4-Chlorophenyl-phenylether * Fluorene **4-Nitroaniline **4,6-Dinitro-2-Methylphenol * N-Nitrosodiphenylamine **Azobenzene * 4-Bromophenyl-phenylether * Hexachlorobenzene * Pentachlorophenol * Phenanthrene * Anthracene * Di-n-Butylphthalate * Fluoranthene * Benzidine * Pyrene * Butylbenzylphthalate * 3,3'-Dichlorobenzidine * Benzo(a) Anthracene * bis(2-Ethylhexyl) Phthalate * Chrysene * Di-n-Octyl Phthalate * Benzo(b) Fluoranthene * Benzo(a) Pyrene * Benzo(a) Pyrene * Indeno(1,2,3-cd) Pyrene * Dibenz(a,h) Anthracene	330 330 330 330 330 1600 1600 330 330 330 330 330 330 330 330 330	ND N
191-24-2	* Benzo(g,h,i)Perylene	330 330	ND   ND
CAS #	Surrogate Compounds	Limits	%Recovery
367-12-4  4165-62-2  4165-60-0  321-60-8  118-79-6  1718-51-0	2-Fluorophenol Phenol-d6 Nitrobenzene-d5 2-Fluorobiphenyl 2,4,6-Tribromophenol Terphenyl-d14	15-83% 18-92% 12-80% 16-100% 15-135% 15-117%	67% 69% 64% 70% 69% 80%

ND: Not detected at or above practical quantitation limit for the method A 625 approved compound (Federal Register, 10/26/84).

A compound on the U.S. EPA CLP Hazardous Substance List (HSL).

Anometri 9002040 ( CHAIN OF CUSTODY RECORDER )

PROJEC	T NO PR	OJECT NA	MF	<del></del>							\			<del></del>	
17360	9 1	arkin		•			<b> </b>	1 5	:51 F	T	JESTI		<del></del>	P.O. #	16945
SAMPLEI (Signature	RS N	mes				<del></del> -	ŀ			鬉	Cd, Cr,	The results	82.70 1000 1000 1000 1000 1000 1000 1000 1	LAB A	nametrix
NO.							7	BTYE	Ð	<b>9</b> +	Z Z	2 3 3 C	25.0		DUND TIME NORM
<u> </u>	DATE	TIME			N AND LOCATION		TO#6-	BT	TP#D	Ö	Metals - Sb, Zu	E P	750	1.	REMARKS
	2/2/9/0		12"×1	5" E	rass Luir	$\sum$								<del></del>	
2 3		· · · · · · · · · · · · · · · · · · ·					$\lambda$	X	X	X	X	X	X	Com	posite 4 into 1
4	1													and	
- 4	V		<del></del>	4											idual analygis on
			<del></del>											rey	7 7 7
			<del>                                     </del>											0	
<del></del>			<del> </del>	<del>*</del>										<del></del>	
· · · · · · · · · · · · · · · · · · ·			+						-						
					· · · · · · · · · · · · · · · · · · ·										
			<del></del>												
			<del>}</del>							{					
														<del></del>	
									<del></del>						
					······································	一									
				<del>"</del>									-		<u> </u>
															· · · · · · · · · · · · · · · · · · ·
BELINOL	01155 51	·													
RELINOU			ATE: TIN	/E:	RECEIVED BY:  RECEIVED BY:		RELI	NOU	ŞHE	D BY	4/	1	ATE	: TIME:	RECEIVED BY
· James	- Wale	X	15,90 9	50	79 11 11 11 11 11 11 11 11 11 11 11 11 11	1 1	Vis	hil	94	risk	1 M		)  5/9 c	10130	1)00- 10
RELINQUI	SHED BY	: D	ATE: TIN	ΛE:	RECEIVED BY:		PELI	Not	ISHÉ	D BY	<i>V  V </i> :		DATE	: TIME:	RECEIVED BY:
<u> </u>							<b>'</b>	,		•					1.1202172007.
REMARKS	):						•		ensc	o er	viro	nme	ntal	services	inc.
REPORT T	O:	700		<del></del> -			ensco environmental services, inc.  41674 Christy Street  (415) 659-0404 Fax (415) 651-4777								
FORM DAT		J.m.T	<u>Jurkin</u>					7	·		Fre	mont	, C.A	94538-31	991 Fax (415) 651-4577 14 Contr. Lic. No. 550205

### **APPENDIX C**

# PERMITS, CORRESPONDENCE AND MANIFESTS

November 21, 1989



Alameda County Health Care Services Department of Environmental Health Hazardous Materials Division 80 Swan Way, Suite 200 Oakland, CA 94621-1439

Attention:

Mr. Larry Seto

Subject:

Work Approval

Mr. Jeff Larkin

1628 Webster Street, Alameda, California

EES Project Number 1736G

Dear Mr. Seto:

Enclosed is a check to cover the cost of your office's approval for work to be done at 1628 Webster Street in Alameda. It is our understanding that a work plan for this action has been submitted by LRA Environmental and accepted by your office. I have also enclosed a copy of the site plan showing approximate locations for the three soil borings. It is our intention to convert one boring to a groundwater monitoring well. The boring to be converted will be that which is most nearly down-gradient from the former tank position. Determination of gradient will be made based upon data from wells installed at 1701 Webster Street by Blymer Engineers on 10/31/89, and by referring to data from the California Regional Water Quality Control Board, which show contaminant plumes moving in a northerly direction on sites in the area of the current investigation. This data is found in two reports: one on the Shell Station at 1601 Webster Street, filed by Weiss & Associates and dated 6/23/89; and one on the Alameda City Housing Authority at 1916 Webster Street by Aqua Science Engineers and dated 10/16/89.

If you have any questions regarding this work plan, please call me. Thank you.

Yours truly,

James F. Durkin Staff Geologist

XFD:idd

Enelosures (2)

ENSCO ENVIRONMENTAL SERVICES, INC. 41674 CHRISTY STREET, FREMONT, CA 94538-3114

. \_--

....

DAT	TE INVOICE NO.	DESCRIPTION	AMOUNT	DISCOUNT	NET AMOUNT
	CHK REQ	Permit	\$333.00		
				·	
:				v	
v	The state of the s		San	ing the second of the second o	



ensco environmental services, inc.

41674 CHRISTY STREET FREMONT, CA 94538-3114 (415) 659-0404 FIRST INTERSTATE BANK OF CALIFORNIA #705 NEWARK, CA 94560-0545

11-57

NO. 06425

 DATE	CHECK NO.	PAYEE I.D.
11 17 90	6125	

PAY TO THE ORDER OF Alameda County Health Services

\$333 Dollars & NO Cents\*

\$333.00

#006425# #121000578#705114364# 11



# **FAX TRANSMITTAL FORM**

Date of Transmission: 2113190
Total number of pages sent, including this cover page:
TO: Name: Vicki
company: BAY AREA AIR QUALITY MANAG. DIST
FAX Number: <u>(415)</u> 928-8560
FROM: Name: RANDY STONE
SENT BY: LOHN RIGITER
TIME:
MESSAGE: THIS WAS SENT BY MAIL ON 1/31.
YOU, I INCUDED THIS ONE JUST TO BE
SURF



REGULATION 8, RULE 40
Aeration of Contaminanted Soil and
Removal of Underground Storage Tanks

## **NOTIFICATION FORM**

	Removal or Replacement of	Tanks
Ø	Excavation of Contaminated	Soil

	TE INFORMATION			
SITE ADDRESS 1628 WERSTER CITY, STATE, ZIP ALAMEDA GA	ST			
OWNER NAME JEAN LARKIN				
SPECIFIC LOCATION OF PROJECT (A BOJE)				
TANK REMOVAL	CONTAMINATED SOIL EXCAVATION			
SCHEDULED STARTUP DATE	SCHEDULED STARTUP DATE 2790			
VAPORS REMOVED BY:	STOCKPILES WILL BE COVERED? YES V NO			
[ ] WATER WASH	ALTERNATIVE METHOD OF AERATION (DESCRIBE BELOW):			
[ ] VAPOR FREEING (CO <sup>2</sup> )				
[ ] VENTILATION	(MAY REQUIRE PERMIT)			
•				
CONTR	RACTOR INFORMATION			
NAME ENSCO ENVIRONMENTAL ADDRESS 14674 CHRISTY ST CITY, STATE, ZIP FRENONT GA 91				
CONSULTANT INFORMATION (IF APPLICABLE)				
NAME TO WE ARE)	CONTACT			
ADDRESS	PHONE ( )			
City, State, Zip				
•				
•				
FOR OFFICE USE ONLY				
DATE RECEIVED				
, , , , , , , , , , , , , , , , , , , ,	(init.)			
CC: INSPECTOR NO. DAT	TE			
TELEPHONE UPDATE: CALLER	• •			
BAAQMD N #				



APPLICANT'S

### ALAMEDA COUNTY FLOOD CONTROL AND WATER CONSERVATION DISTRICT


5997 PARKSIDE DRIVE

PLEASANTON, CALIFORNIA 94566

(415) 484-2600

#### GROUNDWATER PROTECTION ORDINANCE PERMIT APPLICATION

FOR APPLICANT TO COMPLETE	FOR OFFICE USE
1628 Webster St.  Alameda, Alameda County	PERHIT NUMBER  LOCATION NUMBER
None Jeff Larkin Address 16 Las Vegas Rd. Phone City Orinda Zip 94563	ApprovedDate
* APLICANT  None James Durkin  Eusco Environmental Services  Address 41674 (bristy St. Phone (415) 654-0404  City Fremont Zip 94538	PERMIT CONDITIONS  Circled Permit Requirements Apply
4) DESCRIPTION OF PROJECT  Water Well Construction X Geotechnical X  Cathodic Protection Hall Destruction	A. GENERAL  1. A permit application should be submitted so as in arrive at the Zone 7 office five days prior to proposed starting date.  2. Notify this office (484-2600) at least one day
Domestic Industrial trigation Hunicipal Monitoring X Other  PROPOSED CONSTRUCTION	prior to starting work on permitted work and before placing well seals.  3. Submit to Zone 7 within 60 days after completion of permitted work the original Department of Water Resources Water Well Drillers Report or
Orilling Hethod: Hud Rotary Air Rotary Auger Caple Other	equivalent for well projects, or bore hole logs— and location sketch for geotechnical projects.  Permitted work is completed when the last surface seel is placed or the last boring is completed.  4. Permit is void if project not begun within 90
WELL PROJECTS  Orill Hole Diameter & In. Depth(s) /5 ft.  Casing Diameter 2 In. Number  Surface Seal Dupth ~ 5 ft. of Wells /  Driller's License No. 550205	days of approval date.  B. WATER WELLS, INCLUDING PIEZOMETERS  1. Minimum surface seal thickness is two inches of cement grout placed by tremle, or equivalent.  2. Minimum seal_depth is 50 foot for municipal—and
GEOTECHNICAL PROJECTS  Number 3/8 In. Maximum Depth 1511.	Industrial wells or20 feet for domestic, irrigation, and monitoring wells unless a lesser-depth- is specially approved.  C. GEOTECHNICAL. Backfill bore hole with compacted cuttings or heavy bentonite and upper two feet with con-
ESTIMATED STARTING DATE  ESTIMATED COMPLETION DATE  1 thereby agree to comply with all requirements of this purally and Alementa County Ordinance No. 73-68.	pacted material.  D. CATHODIC. Fill hole above anode zone with concrete placed by trumin, or equivalent.  E. WELL DESTRUCTION. See attached.



r	I MILONW DATAUDOOD	ra US EPA ID No.:	Doc	Ashifest cument No.	2. Page of	· I muceum	ition in the shaded equired by Federa	
ľ	3. Generator's Name and Mailing Address						うどうばっぱ	
ı	JEFF AND JEAN LARKIN		•		7.1	7.6	J3263	加速医
İ	16 Las Vegas Road, Orinda, CA 4. Generator's Phone (419) 254-3035	74563	i		7.5 7.5			
	6. Transporter 1 Company Name	6.	US EPA ID Number			ransporter's K		被控制
	H & H Ship Service Company	10 JA JD 1	r 10   1 17 17 14	11  5  8			44(315)	J-48
	7. Transporter 2 Company Name		US EPA ID Number				<b>大学を大学</b>	
	9. Designated Facility Name and Site Address	10.	US EPA ID Number				AND AND A	
	H & H Ship Service Company	10.	*		At hinks a	The second secon	9 9 11 16	180 131 163
	220 China Basin Street					a Phone 15	ALC: NO AND	4
	San Francisco, CA 94107	CAD	1-10 14 17 17 11					
	11. US DOT Description (including Proper Shipping Name,	Hazard Class, and	ID Number)	12. Cont		13. Total Quantity	14. Unit	anio No
	* 3/2*		<u> </u>	No.	Туре	وروندوا دا	Wt/Vol Mark	79.0
	HAZARDOUS WASTE LIQUID, N.O.S	ORM-E	NA 9189	10.050	122		EPA/Oth	
	17 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1			0 10 11		2947	O DESCRIPTION	
E ×	Proceedings of the second		***	1 35	36		State of the state	
A .							EPA/OII	
) R	C.		÷ , ;	<del>                                     </del>			State	学校
	<b>公共</b> 统						EPA/Oth	064
			1 1				State	
	d.						<b>海科教</b>	<b>邻秦 特</b>
2	A CONTRACTOR OF THE PARTY OF TH	N. MARKET AND AND A	Paris of the sales	THE REAL PROPERTY.	· 14	Gardiak and	SAN ENAME	Bearing.
	J. Additional Descriptions for Materials Listed Above	TOTAL STATE	# 401 <b># 10</b> # 1	STATE OF THE	K Handi	g Codes for V	Vastea Listed Abo	on y
	PUEL TILL AND WATER			et me	a orth	到洲豚		
			The state of		Children	* # 8	10.734	17 E
					10	460.46	San Property	<b>31</b>
	15. Special Handling Instructions and Additional Information	<u>्रिक्षित्र क्षेत्रकृत (८८) व्य</u> व		a Landick of the San Line San	SERVING TOP		PARTY MAKE TAKE MAKEN	See and the see
			J	ob siti	. LAI	UKIN PRO	ject	
İ			•				er Street	
	APPROPRIATE PROTECTIVE CLATTER	ig and resi	PIRATOR.		A18	meda. C	A 1995	
	16. GENERATOR'S CERTIFICATION: I hereby declare the	hat the contents of	this consignment are	e fully and ac	curately de	scribed above	by proper shipping	i neme
	and are classified, packed, marked, and labeled, and national government regulations.	are in all respects	in proper condition t	or transport	y highway	according to a	pplicable internation	nal and
	Miles a base averthe assessed I postific that I have	a program in place	to reduce the volum	e and toxicit	of waste	penerated to th	e degree I have de	termined
	to be economically practicable and that I have selecte present and future threat to human health and the env	dronment: OR. if I i	em a small quantity o	renerator, l 🗈	ave made a	good faith eff	ort to minimize my	waste 🗧
	generation and select the best waste management me		ignature	car anoid.	***************************************		Month	Day
	Printed/Typed Names		~	Yang	(T)		10131	£16]
	110 A 1200 A 1600 A 100 A	1						
	17. Transporter 1 Acknowledgement of Receipt of Materia	is Y			-3	:		-
	Printed/Typed Name		iopatur				Month	Day
	Printed/Typed Name STEVE MESQUITE	8	igpature				[0]3]	1   6
P	Printed/Typed Name STEVE NESQUITE  18. Transporter 2 Acknowledgement of Receipt of Materia	s s	3h 1				[0]3]	1 [6]
P	Printed/Typed Name STEVE MESQUITE	s s	3/2/				[0]3]	1   6
TRANSPORTER	Printed/Typed Name STEVE NESQUITE  18. Transporter 2 Acknowledgement of Receipt of Materia	s s	3h 1				[0]3]	1 [6]
P P P P P P P P P	Printed/Typed Name STEVE MESQUITE  18. Transporter 2 Acknowledgement of Receipt of Materia Printed/Typed Name	s s	3h 1				[0]3]	1 [6]
P P P P P P P P P P P P P P P P P P P	Printed/Typed Name STEVE MESQUITE  18. Transporter 2 Acknowledgement of Receipt of Materia Printed/Typed Name	s s	3h 1				[0]3]	1 [6]
P	Printed/Typed Name STEVE MESCUITE  18. Transporter 2 Acknowledgement of Receipt of Materia Printed/Typed Name  19. Discrepancy Indication Space	S	ignature	M	Lan accord		Month	1   6   1   Dey
P P P P P P P P P P P P P P P P P P P	Printed/Typed Name STEVE MESQUITE  18. Transporter 2 Acknowledgement of Receipt of Materia Printed/Typed Name	sia S	ignature	M	t as noted i		Month	1   6   1   Dey

18. Transporter 2 Acknowledgement of Receipt of Materials. : Month - Day : Year Printed/Typed Name Signature 19. Discrepancy indication Space

20. Facility Owner or Operator Certification of receipt of hazardous materials covered by this manifest except as noted in item 19.

Signature (2.22) process of the 1.3

Printed/Typed Name :

: fu 🐏

Month. . Day

WASTE MANIFEST PARTED BY BULL BY BY BY BY BY BY BY BY BY BY BY BY BY	Manifest ocument No. (/ [() ]() [1		of 1 is not	required l	e shaded ereas by Federal law.
JEYP AND JEAN LARKIN			900	<b>13</b> I	<b>40</b>
16 Las Vegas Road, Orinda, CA 94563	West -		ite Generator's ID		
Generator's Phone (419) 254-3035			A STATE		特的特殊
i. Transporter 1 Company Name 6. US EPA ID Numbe		Cren	ite Transporter a M	<b>通河10</b>	3569 ****
15   11   31   12   32   32   32   33   34   35   35   35   35   35   35					5 <b>7</b> 543-483
. Hansporter 2 Company Name 0. US EFA ID NUMBER			te Transporter s JC		
Designated Facility Name and Site Address     10. US EPA 10 Number	<del></del>		te Facility's ID VI		
H & H Ship Service Company		12.0	Marie Care Care	2 N. C. (18)	1168
J20 China Basin Street	**	H Fa	lity's Phone (1981)	100	De Average
Gan Francisco, CA 94107					<b>建</b> 相似
US DOT Description (Including Proper Shipping Name, Hazard Class, and ID Number)	12. Con		13. Total Quantity	14. Unit	Waste No.
	No.	Туре	The second second	Wt/Vol	State Advisor Am
HABARDOUS WASTE LIQUID, N.O.S. ORM-B NA 9189 -	ind a			3.	
MANUAL WARE OF MANUAL WITH BY MA 3103		414	0150100		EVOID NA
the state of the s	25.50	4.3	<b>走就选择</b> !		Sandara San
				is and	EPA/Other®s
			18814	Sec. 1	State of the second
		(§.) N			
					EPA/Other 1027 k
	<del>- -!</del>				State WWW.
· · · · · · · · · · · · · · · · · · ·				) · - 1	EPA/Other
5. Special Handling Instructions and Additional Information		* - <u>N</u> . 35		4 + 7.	
	Job Siti		arkin proj		
SPUDITION OF THE PROPERTY OF CURITIES AND SERVICE OF THE SERVICE O		1	628 Webste	er St	reet
APPROPRIATE PROTECTIVE CLOTHING AND RESPIRATOR		<u> </u>	ismeds ()	<u> </u>	1
GENERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment as	re fully and ac	curately	described above t	y proper	shipping name
and are classified, packed, marked, and lebeled, and are in all respects in proper condition autional government regulations.	0.8356.50	98.00	and the first of the second	200	· 1988年7月1日
If I am a large quantity generator, I certify that I have a program in place to reduce the volume to be economically practicable and that I have selected the practicable method of treatment	ne and toxicity	of wast	e generated to the	degree	have determined ich minimizes the
present and future threat to human health and the environment; Off, if I am a small quantity generation and select the best waste management method that is available to me and that I	generator, I h	eve mad			
nted/Typed Name Signature	e de la companya de l	***************************************	er er er er er er er er er. Til også er er er er er		Month Day Ye
				ا در در	Iotalelalai
	χ. λ.				<u> </u>
				•	
. Transporter 1 Acknowledgement of Receipt of Materials  nted/Typed Name  Signature	1/2/			<b>,</b>	Month Day Ye
Transporter 1 Acknowledgement of Receipt of Materials  inted/Typed Name  OBERT V. PETRUCCI  (Green L. 4)	1. Pet	H.M			Month Day Ye
Transporter 1 Acknowledgement of Receipt of Materials inted/Typed Name OBERT V. PETRUCCI Transporter 2 Acknowledgement of Receipt of Materials	· \\ 11.58th	HM			
Transporter 1 Acknowledgement of Receipt of Materials  nted/Typed Name  OBERT V. PETRUCCI  Transporter 2 Acknowledgement of Receipt of Materials	L Bh				
Transporter 1 Acknowledgement of Receipt of Materials  inted/Typed Name  OBERT V. PETRUCCI  Transporter 2 Acknowledgement of Receipt of Materials  inted/Typed Name  Signature  Signature	1. 13th	420			
Transporter 1 Acknowledgement of Receipt of Materials inted/Typed Name  Signature  Signature  CERT V. PETRUCCI  Transporter 2 Acknowledgement of Receipt of Materials inted/Typed Name  Signature	I Sta	<i>u</i>			
Transporter 1 Acknowledgement of Receipt of Materials inted/Typed Name OBERT V. PETRUCCI L Transporter 2 Acknowledgement of Receipt of Materiale	1. j3t.				
Transporter 1 Acknowledgement of Receipt of Materials  Inted/Typed Hame  CEERT V. PETRUCCI  Transporter 2 Acknowledgement of Receipt of Materials  Inted/Typed Hame  Signature  Signature	1. 13h				

Salar Branch

TRANSPORTER

WSE CENTER 1-800-424-8802; WITHIN CALIFORNIA CALL T-806-8527/850

IN CASE OF AN EMERGENCY OR SPILL, CALL THE NATIONAL RE

DHS 8022 A (1/88) EPA 8700—22 (Rev. 9-88) Previous editions are obsolets.

3. Generator's Name and Mailing A		10 10 H to	11 10 12 11 0 10		of 1	<u> </u>	by Federal law.
•	ddress	•			A. State Manifes	TECCO	
JEFF AND JEAN LARK 16 Las Vegas Road.		A 94563			B. State General		
I. Generator's Phone (415); 2			5 15 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1		是清(数)多合	門管管	門門剛
5. Transporter 1 Company Name		6.	US EPA ID Number		C) State Transpo		
if & H Ship Service  7. Transporter 2 Company Name	Company		[i] [j] [4] [7] [1] US EPA ID Number		D. Transporter's Ex State Transpo		15 17 547 4H:
		111					
Designated Facility Name and Si	ite Address	10.	US EPA ID Number	* 34	GI State Facility	Dra Sa	LEARCE DISHE
# K # Ship Bervice	Company				H Facility's Pho		
220 China Basin St		la la la	la la la la la la la	5 No. 1	<b>SHAURICE SA</b>	A POST A SEA	
San Francisco CE	4, 5≠		√	12. Contai	iners 13. To	tal 14.	Trees were
11. US DOT Description (including i	Proper Shipping Page	e, Hazerd Class, a	ad ID Number)	No.	Туре	entity Unit Wt/Vol	
	(4) (4) (4) (4) (4) (4) (4) (4) (4) (4)	**************************************		144	A Comment	diction in the con-	State 17
HAZARDOUS VASTE LI	OUID, N.O.	.s. ORM-E	NA 9189		+ 1+ 0510	1000	PAOther Inst
		and the same	The second secon	12000			Stale Acade Sand
							EPA/Other出版
A CONTRACTOR OF A CONTRACTOR O		· Caratta	्राच्या क्षा स्थापना है। स्थापना स्थापना	· Financia	*   *   *   *   *   *   *   *   *   *	2 2 2	State *** a rank
							313 6 4 4 4
							EPA/Other Available
					. 4	-	State The Paris
<b>和沙理以外的遗传</b>	Tres de la companya della companya d	en de la companya de la companya de la companya de la companya de la companya de la companya de la companya de	***************************************	S TENESE		Silver makes	EPA/Other
Additional Descriptions for Meter	11				K. Handling Cod		
POEL OUE AND WATER							
*//		STATE OF			CHARTE	OLA CAS	AL M. IN SURVINIE
5. Special Handling Instructions an	d Additional Informat	NOU STATE OF THE PARTY OF THE P	A STATE OF THE PROPERTY OF THE	The second second	CAN AND MANAGEMENT	<u>्र पश्चमतात्र । संशासन् प्राप्त</u> े	to make the state of the state
	•	5 5 4 4 75	J	OB SITE		PROJECT	
Acquart grant a many	5'	4.				ebster St	treet
APPROPRIATE PROTECT 6.	TIVE CLOTHI	#F AND RE	PIRATOR		Alamed	<del>- Ch</del>	San e e e
GENERATOR'S CERTIFICATION	N: I hereby declare	that the contents	of this consignment an	e fully and acc	urately described	above by propi	or shipping name
and are classified, packed, mer national government regulations	به منوبه عمواه ي	1. M	The state of the state of	-34-64	Acres de la company	extension of	ै । भौतिसेक सीलक्षेत्री स्टब्सी र
If I am a large quantity generate to be economically practicable	and that I have selec	cted the practicable	e method of treatment,	, storage, or di	sposal currently a	valiable to 🗪 v	which minimizes the
present and future threat to her generation and select the best					e mage a good fi	nun entort to mit	witze my waste
rinted/Typed Name		\$5	Signature	1818			Month Day
rains 1.11	ed Deceler at the	data .		<u> </u>			<u> विभिन्न विभिन्न</u>
7. Transporter 1 Acknowledgement rinted/Typed Name	t or Preceipt Of Miller		Signature A	17-00			Month Day
DWARD C. MILANO			William.	1121	Mill		T01313131313
8. Transporter 2 Acknowledgement	t of Receipt of Mater		38 9 5 mg	3 - 4 <b>. 3</b> 5	Sales .		
rinted/Typed Name			Signature		See 1		Month Day
9. Discrepancy Indication Space			Neg a				
			*		· -		
<b>.</b>	tracting of any 1 and 1	•	4	allant and a		2	
Facility Owner or Operator Certification     Facility Owner or Operator Certification	fication of receipt of		als covered by this ma	nifest except a	is noted in Rem 1	9	Month Day)

NSE CENTER 1-800-424-8802: WITHIN CALIFORNIA CALL T-800-8624-660

CASE OF AN EMERGENCY OR SPILL, CALL THE NATIONAL RI

10 miles 10

	C 1 Cocomic	r's US EPA IC	A Ata	Menilest				
UNIFORM HAZARDOUS WASTE MANIFEST	<b>5</b>		/mo.  6 1         1	Document No.	2.1			he shaded areas
Generator's Name and Mailing Addre		3 13 1V 12	10141. []4	<u> </u>	A. Su	ite Manifest Docur	- /	· .
jepp and <mark>Jean L</mark> akkin	f				3.8	900	031	45
lu Laa Yegaa Koad. O		94563		• .	B. St	te Generator's ID	نقت	*
Generator's Phone (413) 254	-3035	4 6	S. Page		<b>63</b>			是於阿勒勒
Transporter 1 Company Name		» <b>6</b> .	US EPA ID N	ımber	C. Ste	ite Transporter's I	101	578 WH 56 86
HAR Ship Service C	Ompany	CA	D 6 6 4 13			asporter's Phone		51 543-4835
Transporter 2 Company Name	. •	. 8.	US EPA ID N	imber	E Su	te Transporter's il	12/200	er we contribute the second
Designated Facility Name and Site Ad	ddress	10.	US EPA 10 N	lmber		te Facility's ID 🤌		PS NO.
i & H Ship Service C					39 Y	的支援 。可是1956年		111683
120 China Basin Stre				o de la compansión de		Mity's Phone	18-13 X	THE SECOND SECOND
an Francisco, CA 9		IC IA	ID 19 10 14 17	711 11 16 18		151 31 4	7.63	
. US DOT Description (Including Prope	er Shlonion Neme	141.00	31 . 1	12. Cont		13. Total Quantity	14, Unit	· · · · · · · · · · · · · · · · · · ·
. 05 DOT Description (making Propi	er crapping reme,	HAZEIG CIESS	i, and as reuniber)	No.	Туре	Country	Wt/Vol	100 000 000
N. ( 1787 ) W.		Story in	Albert .					State 1741 Bloom
iazardous vaste Liou	E.O.H.O.S	. Orm-	E NA 918			1 0.0	r. • .	EPA/Other #/118.14
		e Karalak	A STATE OF THE STA		TI	<u>जहां ज्या</u>	. /2	
To # Marie Control				And Amilia	-	APPROXIMATE	- दहाँ दे	
								EPA/Others and S
A STATE OF THE STA		1,41			~ .	* *		State Company Company
								EPA/Others > No.
						1111		
	•		7					State will state to the state of the state o
the side in all thought to an election	ini di di bara ya	. Antikin .	i Laintiinis (1999) (Santiinis 1990) (S	and a second	20.24	e substantinue	3333	EPA/Other & N. S. A.
Additional Descriptions for Materials L		Contract to		#22 dr: #		<del>-                                      </del>	કર્યક્રા ક	
<b>人名巴拉斯尼 到的第三人称:"不是这个人的人</b>					a.	ndling Codes for V	astes Li	
UEL-TUTE AND HATER				10000	#61	<b>F 第</b> 第 第 第		APPENDING TO
					· 1	Martin E.	d y	
		100	E4516			4-91-14 (A.4)	100	****
Special Handling Instructions and Ad-	ditional Information		t man		٠,			
				JOB SITE	: L	ARKIN PRO	IECT	÷ .
A Comment					1	628 Webst	er St	reet
PPROPRIÀTE PROTECTIV	VE CLOTHIN	G AND R	ESPIRATOR.		Ą	lameda C	}	· -
GENERATOR'S CERTIFICATION: 1 and are classified, packed, marked,	, and iabeled, and a	ire in all respo	ecta in procer cond	ition for transport b	v hichw	av according to ac	olicable	shipping name international and
national government regulations.  If I am a large quantity generator, I c	onesta abna I baira a	the letter of	and the same	والمراونة أمون				
to on acoustineany biacocapie and t	tuiet i vieam šelecial	o tue blacica	ible memod of fles	ment, storage, or o	#SDOSEI	CRISOLISIA BASISTONS	to me w	NCU WINNISS INS
present and future threat to human higheration and select the best waste					ve mao	e a good tarm erro	rt to min	mize my waste
ted/Typed Name			Signature	1.10			·	Month Day Year
			1					101311131910
moundation as								1 1 1 2 1 2 1 1 1 1
	Receipt of Materials	<b>5</b> : :	•					
Transporter 1 Acknowledgement of R ted/Typed Name	Receipt of Material		Signature					Month Day Year
Transporter 1 Acknowledgement of R ted/Typed Name ARK A. DOSE			Signature					Month Day Year
Transporter 1 Acknowledgement of Rited/Typed Name ARK A. DOGS Transporter 2 Acknowledgement of R					. 11			19[3[1]3[9]9
Transporter 1 Acknowledgement of Rited/Typed Name ARK A. DOGS Transporter 2 Acknowledgement of R					. 1:			
Transporter 1 Acknowledgement of Rited/Typed Name ARK A. INOSE Transporter 2 Acknowledgement of Rited/Typed Name					1:			19[3[1]3[9]9
Transporter 1 Acknowledgement of Risted/Typed Name ARK A. DOSS Transporter 2 Acknowledgement of Risted/Typed Name					1:			19[3[1]3[9]9
Transporter 1 Acknowledgement of Rited/Typed Name ARK A. DOSS Transporter 2 Acknowledgement of Rited/Typed Name Discrepancy Indication Space					1:			19[3[1]3[9]9
Transporter 1 Acknowledgement of Rited/Typed Name RRK A. DOSS Transporter 2 Acknowledgement of Rited/Typed Name								19[3[1]3[9]9
Transporter 1 Acknowledgement of Rited/Typed Name RRK A. DOSE Transporter 2 Acknowledgement of Rited/Typed Name	Receipt of Materials		Signature	is manifest excent				19[3[1]3[9]9

NSE CENTER 1-800-424-88022-WITHIN

CABE OF AN EMERGENCY OR SPILL, CALL THE NATIONAL RE

Company of the Control of the Contro Z

**被** 

# THIS CARD MUST BE POSTED ON THE PREMISES AND PLACED SO AS TO BE SEEN FROM THE STREET

20040	JOB Sewel Whatdownest
FORMSREQUIRED BEFORE POURING CONCRETE	ADDRESS / GOS Wellstel St.
	OWNER_ JUST Jallen
VAULT TOILET	CONTRACTOR
PRELIMINARY GROUND PLUMBING	WILLIAM C. NORTON BY
	INTERIOR LATH
	REQUIRED BEFORE PLASTERING OR TAPING
FINAL GROUND PLUMBING	EXTERIOR LATH
	PROUBLE STREET ATTIONS
· · · · · · · · · · · · · · · · · · ·	DESIGN REVIEW
	INSULATION CERTIFICATE
	TRACT CONDITIONS
ROUGH PLUMBING	·
ROUGH HEATING & VENTILATING	
TOOLITICAL VERTICALITY	
<b>表為於</b> 學學 <b>清潔</b> 。	FINAL - FIRE DEPT.
SUB FLOOR	FINAL - FINE DEF (,
ON THE OWNER OF THE OWNER	FINAL PLUMBING /- 28-90
CANADA CONTRACTOR CONT	Sewer abandoned OK - Nell =
A STATE OF THE STA	No Das Meter on job - films
HAME	
	FINAL HEATING & VENTILATING
NSULATION	FINAL BUILDING
ASSAULT ASSECUTE OF CHARGE CONTROL OF CHARGE	
ABOVE APPROVALS REQUIRED BEFORE INTERIOR LATHING OR COVERING DO NOT OCCUPY STRUCTURE UNTIL CERTIFICATE	
OCCUPANCY HAS BEEN ISSUED.	ВҮ
EMARKS	

NOTE: ALL INSPECTION DECLISES ARE RECURED 24 HOURS IN



# CITY OF ALAMEDA · CALIFORNIA

CITY HALL . SANTA CLAHA AT OAK ST. \$4501 . (413) 323-4100

U LIC WORKS DEPARTMENT

CENTRAL PERMIT OFFICE

## TIME CONSTRUCTION PERHITTED

flunicipal Code Ordinance Section 11-575 (see below) sets out the time during which construction may occur. Please the Police Department for any violation of the Municipal Code.

#### TIME LIMITS

Monday - Priday Saturday & Sunday

7:00 a.m. to 7:00 p.m. 8:00 a.m. to 5:00 p.m.


Sec. 11-575. CONSTRUCTION. The provisions of this chapter shall not apply to noise sources associated with construction, provided said activities do not take place before 100 a.m. or after 7:00 p.m. on any day except Saturday or unday, or before 1:00 a.m. or after 5:00 p.m. on Saturday or

	PLEASE TYPE OR PRINT	LOG COMM. PERMIT
	TRACT BLOCKPAGE LOT PARCEL TO	NO. CODE NO. 1) 0/30
MER	NAME! 10 Los Vogas Ro.	JOB ADDRESS 1303 1303
$\mathcal{V}_{\mathbf{g}}$	ADDRESS PHONE Unlada CA. 94563	APPLICATION FOR BUILDING PERMIT
₩_	CITY STATE ZIP	CITY OF ALAMEDA Central Permit Office
Ēď	NAME ' LICENSE	2263 Santa Clara Avenue Alameda, CA 94501
ARCHIT.	ADDRESS PHONE	(415) 748-4584
1	CITY STATE ZIP	
	I hereby affirm that I am licensed under provisions of Chapter 9 commencing with section 7000 of Division 3 of the Business and Professions Code, and my license is in full force and effect.	NEW CONSTADDITIONALTERATION_X_REPAIR
	LICENSE No. CITY BUSINESS /// P	EXISTING USE: NGT / COMPANY TO TO THE PROPERTY USE: FOR 177 TO 17
TOR	SAND CLASS 550205 LICENSE NO. 5-624	PROPOSED USE: L-M/// C 2/1/
Ě	CONTRACTOR NAME Ensco Environmental Services, Inc.	DESCRIPTION OF WORK
8	ADDRESS 41674 Christy St.	Demolish former gas station located at
REKT	CITY STATEZIP 94532 (415) 659 1404	The state of the s
	SIGNATURE MALL HAMM	1528 Webster St., Alameda, Ca., Building
دېميا	Thereby affirm that Tam-exempt from the Contractor's License Law for the	has been condemned by City of Alameda.
	following reason (Sec. 7031.5, Business and Professions Code: Any city or county which requires a permit to construct, eiter, improve, demolish, or repair any struc-	
	ture, prior to its issuance, also requires the applicant for such permit to file a sign- ed statement that he is licensed pursuant to the provisions of the Contractor's License Law (Chapter 9 — commencing with Section 7000) of Division 3 of the	This permit will be for demolition of
- :	Business and Professions Code) or that he is exempt therefrom and the basis for the alleged exemption. Any violation of Section 7031.5 by any applicant for a permit	building only.
NATO	subjects the applicant to a civil penalty of not more than five hundred dollars (\$500):	
§	i, as owner of the property, or my employees with wages as their sole compensation, will do the work, and the structure is not intended or offered for sales of the sole of the sales of th	EIVED
100 B	by to an owner of property who builds or improves thereon, and who does such work and himself or through his own employees, provided that such improvements are not in the such improvements are not in the such improvements.	
100	tended or offered for sale. If, however, the building or improvement is sold within a one year of completion, the owner-builder will have the burden of proving that lief	1 1990
2	did not build or improve for the purpose of sale)	A STATE OF THE STA
5 1	fors to construct the project (Sec. 7044, Business and Professions Code: The CON-COT tractor's License Law does not apply to an owner of property who builds or im-	OF ALAMENA SQ. FT. ADDED : \$1.50
1	proves thereon, and who contracts for such projects with a contractor(a) licensed pursuant to the Contractor's License Law).	4
[	I am exempt under Sec.  8&P.C. for this reason	Including all labor, materials, and all lighting, heating, ventilating, water supply, plumb-
	Owner's Signature	ing, fire sprinklers, electric wiring, elevator equipment and all features that are affixed or a permanent part of the building.
. 51	I hereby affirm that I have a certificate of consent to self-insure, or a certificate of Worker's Compensation Insurance, or a certified copy thereof (Sec. 3800, Lab C.).  Policy No. 10-51-171-1 Company Amontonia	INSTALLATION OF SMOKE ALARM SYSTEM MANDATORY ON BUILDING PERMITS IN EXCESS OF \$1,000.
(O §	☐ Certified copy is hereby furnished. ☐ Certified copy is filed with the city Central Permit Office	CONTACT NAME: Randy Stons
<u>-</u> <u>-</u> - <u>-</u>	Applicant Date Date	CONTACT PHONE 415 - CS3-6422
. A	(This section need not be completed if the permit is for one hundred dollars (\$100) or less).	
€. ¥	I certify that in the performance of the work for which this permit is fasued, I shall not employ any person in any manner so as to become subject to the Workers'	OTHER PERMITS ARE REQUIRED FOR PLUMBING, HEATING, ELECTRICAL WORK,
8	Compensation Laws of California.  Applicant Date Date	AND CONSTRUCTION WITHIN THE PUBLIC RIGHT OF WAY.
WERS	NOTICE TO APPLICANT: If, after making this Certificate of Exemption, you should become subject to the Worker's Compensation provisions of the Labor	7.3
ğ	Code, you must forthwith comply with such provisions or this permit shall be deemed revoked.	BLDG. PERMIT \$ AB 941 FEE \$
. —	i hereby affirm that there is a construction lending agency for the performance of	PLAN CHECK \$ FILING FEE \$ //
ENDER	the work for which this permit is issued (Sec. 3097, Civ. C.) Lender's Name	SMIP \$ SEWER CONN. \$
=	Lender's Address	DESIGN RV \$ MICRO-FICHE FEE \$ 3
_ [	I certify that I have read this application and state that the information given is true and correct, I agree to comply with all local ordinance and state laws relating	IMPROVEMENT TAX \$ 50 SCHOOL FEE \$
	to building construction and I make this statement under penalty of law. I hereby authorize representatives of the cryscounty to enter upon the above mentioned pro-	APPLICATION, RECEIVED
Ę	perty for inspection purposes, NOTICE! This permit wall expire by limitation if work is not started in 180 days or it work is abandoned for more than 180 days. Do not conceal or cover any construction with the work is inspected and the inspection is	DATE////GO SIGNED
<b>\ </b> = 1	conceal or cover any construction until the work is inspected and the inspection is recorded on the Building Inspection Card. All Inspection enquests are required 24 hours in advance of the Inspection, 748-4564, 8:30AM to 19AM.	APPROVAL SIGNED
	Contractor	PATE 1-90 SIGNED L.W. D.
· · · · · ·	Owner X 1/2/ Xu	ISSUED

White: Office Copy Blue: County Of Alameda Yellow: Applicant's Copy

	PELASE	TYPE OR I	PRINI	LOG	SSO MM O88	PERMIT NO.	00-	4132,
TRACT	BL(	OCK PAGE	LOT PARCEL	1043.	2		70.	~~~
NAME	Tean R.	Larkin		JOB ADDRESS /	28 6/00	Ster	57	
ADDRES	\$ 16 has	Vegas F	PHONE	- APPLICATI	ON FOR PLUMBIN		HANICAL P	ERMIT
CITY	umda Co	STATE 94	56.3 ZIP		CITY OF AL Central Perm	alt Office		
NAME			LICENSE	7	2263 Santa Cla Alameda, C	A 94501	•	
ADDRES	Š	<del></del>	PHONE	DESCRIPTION OF WOL	(415) 522-410	5) (B	10	
CITY		STATE	ZIP	Sewer		n me	1	
section 700	irm that I am license to of Division 3 of the and effect.	id under provisions of ( e Business and Profes	Chapter 9 commencing with sions Code, and my license i	VALUATION OF WORK				
LICENSE N AND CLASS		CITY BUSIN LICENSE N		CONTACT NAME:	Jesen R.	2 T	tack	<b>-</b>
CONTRACT NAME	OR		fo.	CONTACT PHONE:	23 7 902	NO.	FEE	TOTAL
ADDRESS	٠٠٠ .			PLUMBING		NO.		IOIAL
СПҮ.	3.44	STATE/ZIP	PHONE	Basins Baths		1	\$ 6.00 6.00	
BIGNATUR	<u> </u>	<del></del>		Catch Basin			6.00	
BIGHATUR	The state of the s		*	i Closets Dishwasher	· · ·	1	6.00	<del> </del>
	<del></del>		atara Hanna I am das sta	Drinking Fountain			6.00	
fallowing or	18ac 2021 K A	Laineau and Professio	ctor's License Law for the ne Code: Any city or county	Fire Sprinklers Floor Drain		ļ	8.00	1
substant against	lana a annoult to cons	stauct altar bannonus di	emolish, or repair any struc- or such permit to file a sign-	Floor Sinks	· · · · · · · · · · · · · · · · · · ·	<u> </u>	6.00	<del> </del>
ad atelama	at that he is license	AN CHIMILIANT IN THE ON	WINDOW OF THE CONTRACTORS	Garbage Disposal		4	6.00	
Description of	ad Desirentana Casi	a) or that he is evenue.	7000) of Division 3 of the therefrom and the basis for	Gas Lines/Motors Gas Outlets		<b></b>	6.00 2.00	<del>                                     </del>
the alleged	exemption Any viola	etion of Section 7031.5	by any applicant for a permit than five hundred dollars	Gas Range		<del> </del>	6.00	
(\$500.):		in points or not more	- wat the transfer would	Gas Test			4.00	
	ne of the removative	or my employees with	rages as their sole compen-	Hot Tub/Spa Lawn Sprinklers		-	10.00	<del>                                      </del>
sation, will	do the work, and the	e structure la not inteni L'Coder The Contractor's	ged or offered for sale (Sec. a License Law does not soo-	Aye: Leaders Rain Wat	<b>6</b> ¢	1.882 to the	6.00	100 120 0
	ar all assaults who h	udiria or improvesa thera	on, and who does such work	Sewer Abandonm			14.00	14-
خرجة المحمد	diamet for a la 1f by	number the building or	ch improvements are not in- improvement is sold within	Sewer Extension/	Replacement		20.00	' '
one was of	completion, the ow	uet-policiet mili ueta iu	e burden of proving that he	Sewer Repair Showers		<del> </del>	10.00 6.00	<del> </del>
	d or improve for the		cting with licensed contrac-	Sinks %		<u> </u>	6.00	
tors to cons	struct the project (Se	ic. 7044. Business and l	Professions Code: The Con-	Solar System	RECEIV	FN	38.00	ļ
proves then	eon, and who contra	icts for such projects v	property who builds or im- vith a contractor(s) licensed	Sumps Storage Tanks		F	20.00	
pursuant to	the Contractor's Lic	pense Law).		Tollet	ADD 1 7 10	189	6.00	<u> </u>
	empt under Sec	<u> </u>		Vault Toilet Washing Machine		7/	20.00 6.00	<del> </del>
	for this region	· L Lack	Date 4/13/89	Water Heater Res	Committee Persit	<del> </del>	6.00/10.00	
Dyner's Si	onstura e e	<u> - Carre</u>	2 1010 7/15/89	Water Unes/Mete	TO CONTRACT OF ALL OF	र्म स्टब्स	- 6.00	
I hereby a	#17/m shat I have a ce	rtificate of consent to	elf-insure, or a certificate of	MECHANICAL		<del> </del>	<del> </del>	<del> </del>
		ice, or a certified copy	thereof (Sec. 3800, Lab C.). Company	Air Conditioning E	quip.	<u> </u>	10.00/20.00	
Policy No.:	d copy is hereby fur	minhad	_ company	Boiler			20.00	
		meneu. the city Central Permit	Office	Control Change Convectors	••	<del> </del>	6.00 4.00	
Apolicent	•		Dete	Dryer Res/Comm.	•		6.00/10.00	
		empleted If the permit	is for one hundred dollars	Fans and Blowers			10.00	
(\$100) or les	ia).			Fireplace		<del>                                     </del>	4.00	<del> </del>
Coertify the	set in the performance any person in any	a of the work for which manner so se to become	this permit is leaved, I shall me subject to the Workers	Furnace			10.00	
Compensati	ion Laws of Californ	191.	Whalea	Heaters			10.00	
Applicant	there K	- Seeles	Date_7/1.5/8/	Hoods Res./Comm	<u> </u>	<del> </del>	4.00/30.00	<del> </del>
many of head	ome authlect to the	Worker's Compensation	tificate of Exemption, you on provisions of the Labor	Registers	· · · · · · · · · · · · · · · · · · ·		2.00	
Code, you (	must forthwith com	ply with such provision	one or this permit shall be	Venta Bath/Kitche	n .	1	4.00	-
deemed rev	<u> </u>			ISSUANCE FEE		<del>                                     </del>	6.00	8.00
I hereby a	ffirm that there is a c	ponstruction lending ag is issued (Sec. 3097, Ci	ency for the performance of v. CJ			· · · · · ·		بسيت
Lender's N				Sub-Total Fees	*****************	•	40-	
Lender's Ad				AB 941 Fee			5.00	
		andication and state of	at the information also is	Yatal San		- 4	200	. ,
true and cor	rect, I agree to come	ply with all local ordina	nat the information given is not and state laws relating	Total Fees	5740	• • • • • • • • • • • • • • • • • • • •	70	
audhorine en	contaminations of the	citalchiusty to enter uno	der penalty of law. I hereby on the above mentioned pro-		MILZ		1 37	2/22/
porty for ins	pection purposes. N	IQTICE! This permit will	expire by limitation if work	400 to 170 / 700	שנינות		7	<u>~ 18 ~</u>
CORCEAL OF C	over any construction	on until the work is insp	nore than 180 days. Do not ected and the inspection is	APPLICATION RECEIVE				~1-
moorded to	the Building Inspec	tion Card. All inspection, 522-4100 X279, \$2	on requests are regulred 24	11301		<del></del>	· · · · · · · · · · · · · · · · · · ·	
☐ Contrac			orum to recome	APPROVAL DATE 57C/OC SIGN	uen 05/	/		<i>ו</i> א א
Owner.	:	0 4	$\mathcal{L}$	3/7/47	- Cat	(II)		1
🔲 Agent i	X	intractor, Owner or Age	ne ne	ISSUED	-	-		
	Signeture of Co	neactor, warner or Age	MIL.	DATE ///SIGN				

White: Office Copy - Yellow: Applicant's Copy



Santa Clara Avenue at Oak Street · 94501

Public Works Department, Room 204

City of Alameda California

City Hall

Don Rodrigues Senior Plumbing and Mechanical Inspector

1628 Webster ST

Webster St

1628 Webster St

Gas Station bldg.

PLUMBING & MECHANICAL PLANS A P P R O V E D

DATE: 5/9/89


BY:

Donald I Roungues, Sr. Piber & Mech. 1950.

APR 1 3 1989

competiti a sere-

APPROVED JOS PLAN
CITY OF ALAMEDA
BUILDING & INSPECTION DEPT.
Building Inspector KW. June
Date See 1-11-20



RECEIVED

CELLY CO

19584-041189-250 Books	CITY OF ALAME CALIFORNIA	EDA . Nº - 286	21
No 90 032		Date . / !!/90	On the second se
the sum of watty life	1628 Wills 1028 50/m - -1 1935- m185-  m	11.57 DOLLARS, \$. 20	150
For	LEWIS E. HURWITZ		

**AGENCY** 

DAVID J. KEARS, Agency Director



May 21, 1990

DEPARTMENT OF ENVIRONMENTAL HEALTH Hazardous Materials Program 80 Swan Way, Rm. 200 Oakland, CA 94621 (415)

Mrs. Jean Larkin Pacific Properties 16 Las Vegas Road Orinda, CA 94563

RE: 1628 Webster St., Alameda, CA 94501

Dear Mrs. Larkin:

I have reviewed a letter dated May 17, 1990, that was prepared by Exceltech concerning taking confirmatory samples and backfilling the excavation at the above site. It is acceptable.

Please submit to me, all reports and data as they become available.

If you have any questions, please contact me at 271-4320.

Sincerely,

Larry Seto, Senior,

Hazardous Materials Specialist

LS:mnc

cc: RWQCB

Gil Jensen, Alameda County District Attorney, Consumer and Environmental Protection Agency

Charlene Williams, DOHS Randy Stone, Exceltech

Rafat A. Shahid, Assistant Agency Director, Environmental Health

Files



April 26, 1990 Project 4714

Mr. John Rigter Exceltech Inc. 41674 Christy Street Fremont, Ca. 94538-3114

Subject: Field Density Tests

Larkin Site Tank Excavation Backfill

1628 Webster Street Alameda, California

Dear Mr. Rigter:

As requested, a representative of TERRATECH, INC. was present at the subject site on March 20, 1990 to perform field density tests within the baserock material used as tank excavation backfill. Four (4) field density tests were performed in accordance with the State of California Test Method 231 at a depth of approximately four (4) feet below the adjacent ground surface and within the import baserock backfill material.

The maximum wet density of 138 lbs./cu. ft. for the import baserock material used in calculation of the percent compaction of the backfill was provided to us by your representative.

The results of the field density tests are presented on the attached Table A. These are for record purposes only.

The excavation backfill was not completed while our representative was on site. It is our understanding that the remaining approximate four (4) feet of the fill will be placed and the surface tested at some future date.

Sincerely.

TERRATECH, INC.

James M. Koch

JMK/pwk

Attachments

# TABLE A SUMMARY OF FIELD DENSITY TEST RESULTS

		APPROX			FRE	ELD	LABORA	ATORY		
TEST NO.			LOCATION	APPROX. ELEVATION (feet)	DRY DENSITY (pcf)	WATER CONTENT	MAXIMUM DRY DENSITY (pcf)	OPTIMUM WATER CONTENT	COMPACTION	REMARKS
	1990		WITHIN TANK EXC	AVATTO	N BACI	FFTTT				
1	3-20	4.0	Northwest Corner		123.7		138	N/A	90	
2	3-20	4.0	Southeast Corner	Unk	123.5	N/A	138	N/A	90	
3	3-20	4.0	Southeast Corner	Unk	125.0	N/A	138	N/A	91	
4	3-20	4.0	Southwest Corner	Unk	120.0	N/A	138	N/A	87	
	NOTES:	mb a							·	
	MOIES:	The	average percent	compa	ction	= 90%				
									·	
			4714							

PROJECT\_\_\_4714

SHEET 1 of 1

TERRATECH, INC.

2/14/90

tit in vier een valen in trakval vervillet het dag et jakt van de van gevale van de verville.

Mr. Randall Stone Ensco Environmental Services, Inc. 41674 Christy Street Fremont, California 94538-3114

Re; 1628 Webster St.
Alameda, California

Dear Randy:

This is to advise you that we had absolutely no knowledge of any tank in the ground at the above address, with the exception of the waste oil tank which started this whole mess. We therefor have no knowledge of a tank being enclosed after 1984.

If there are any questions, please do not hesitate in calling.

Very truly yours;

Jean R. Larkin

/16 Las Vegas Road Orinda, Ca., 94563

415 254 3035



May 17, 1990

Lawrence Seto Alameda County Health Agency 80 Swan Way Room 200 Oakland, CA 94621

Re: Backfilling Larkin Project 1628 Webster Street Alameda, Alameda County, CA

Dear Lary,

As we discussed in our meeting on May 16, 1990, I am sending this letter to confirm the points of our agreement to backfill the above referenced site:

- 1. Samples in the current excavation will be sampled every 200 square feet on the north, west, and south walls-(the east wall is clean backfill).
- 2. The south end of the excavation will be left open until the confirmation sampling has been received, and copies sent to your office for approval.
- 3. A non-permeable, high density, polyethylene material will be used on the west wall to ensure no cross contamination will occur on contact.

Again Larry, it was nice to reach an agreement on these issues, and I certanily appreciate your time and help. I look foward to working with you.

Sincerely,

Randy Stone Exceltech, Inc.

RS/tr

### **HEALTH CARE SERVICES**

AGENCY

DAVID J. KEARS, Agency Director



May 21, 1990

DEPARTMENT OF ENVIRONMENTAL HEALTH Hazardous Materials Program 80 Swan Way, Rm. 200 Oakland, CA 94621 (415)

Mrs. Jean Larkin Pacific Properties 16 Las Vegas Road Orinda, CA 94563

> RE: 1628 Webster St., Alameda, CA 94501

Dear Mrs. Larkin:

I have reviewed a letter dated May 17, 1990, that was prepared by Exceltech concerning taking confirmatory samples and backfilling the excavation at the above site. It is acceptable.

Please submit to me, all reports and data as they become available.

If you have any questions, please contact me at 271-4320.

Sincerely,

Larry Seto, Senior,

Hazardous Materials Specialist

LS:mnc

cc: RWQCB

> Gil Jensen, Alameda County District Attorney, Consumer and Environmental Protection Agency

Charlene Williams, DOHS Randy Stone, Exceltech

Rafat A. Shahid, Assistant Agency Director, Environmental Health

Files

## APPENDIX D 1990 WORK SUMMARY

### 1990 WORK SUMMARY

1/11/90	Lubrication/maintenance building demolition permit approved by the City of Alameda.
1/23/90	Sewer line closure inspection and backfill sewer line trench.
1/25/90	Demolition of building interior is: shelves, desks, hangers, lights, windows, etc.
1/26/90	Demolition of building exterior, all the way to the ground and prepare for disposal.
1/29/90	Start demolition of concrete pad and foundation. Prepare for disposal.
1/30/90	Metal from building loaded and shipped to scrap metal yard.
1/31/90	Continue demolition of concrete pad and footings. Dispose of at Class III landfill.
2/1/90	Finish clearing steel and concrete rubble. Dispose of at Class III landfill. Prepare site for soil excavation.
2/2/90	With an ENSCO geologist present, the two floor hoists and approximately 100 cubic yards of contaminated soil were removed from beneath the demolished lubrication/maintenance building. The soil was stock piled, sampled and covered with plastic. What appeared to be groundwater was encountered at approximately 12 feet.
2/5/90	Continued to excavate contaminated soil in the vicinity of the demolished lubrication/maintenance building. This was done by following the contamination veins visually. Approximately 300 cubic yards was removed, stock-piled and covered.
2/6/90	Excavated approximately 200 cubic yards of contaminated soil, stockpiled and covered. While following contamination veins, a 5,000 gallon underground storage tank was discovered. It was located northwest of the demo building. The tank had been filled with sand and then capped with concrete. It is unknown what it's contents were and when it was sealed in place.
2/12/90	Mobilized pump and generator on-site to remove water from excavation. Replaced backhoe with track excavator to remove above mentioned tank and facilitate the excavation process.
2/13/90	Off-loaded a 20,000 gallon "Baker Tank" at site to pump water into. A sump was dug well below water level and pumping began. Using the excavator, an attempt was made to drag the tank out of the excavation. After finding that it was far too heavy, the sand and concrete was removed. Both the tank and it's contents were placed in the contaminated soil stockpile area. Continued digging contaminated soil and looking for the limits, stockpiled and covered.

2/14/90 The excavation was headed into the corner where Pacific and Webster Streets meet. A variety of backfill material was encountered in this area. This included: rebar, steel banding, wood, pea gravel, broken-up asphalt and concrete. The fuel odor in this area was very strong. Excavated material was moved to stockpile area and covered. After disturbing this backfill area, water began to enter the excavation at a fairly high rate. 2/15/90 Replace electric pump with air driven diaphragm pump to provide higher volume. Pump water from excavation. Continue following/excavating contaminated soil in the corner next to Pacific and Webster Streets. Stockpile and covered excavated materials. 2/16/90 Job is rained out. Remove generator from site and make sure that stockpiles are still covered (high winds). 2/17/90 Pump water from excavation and check covering on stockpiles. 2/18/90 Pump water from excavation and check covering on stockpiles. 2/19/90 Pump water from excavation and check covering on stockpiles. (Note: water is returning to excavation faster). 2/20/90 Pump water from excavation. Using a hydrocarbon meter, check sidewalls of hole to determine further excavation. Remove soil all along sidewall below house on the east side of excavation. Followed this vain of contamination down below water level to approximately 14 feet where it came clean. Stockpile and cover material that was removed. 2/22/90 Secured fencing along site access areas. Pump water from excavation. Started demolishing metal office building/shed. More room is needed for stockpiling contaminated soil. 2/23/90 Finished demolition of metal building. Moved around stockpiles for better use of space. Pump water out of excavation. Cover stockpiles. 2/24/90 Put up caution tape around excavation. Check site security. 2/26/90 Removed product lines along the north side wall of the excavation. There were both steel and fiberglass lines buried in pea gravel approximately 2 feet from the surface. The fiberglass lines were on top. The steel lines were on the bottom and quite rusty. Removed and stockpiled chunks of concrete and sandstone from the trench. Due to large amounts of water in the bottom of the excavation removal of soil was not attempted. Setup diaphragm pump at site and pump excavation. Remove contaminated 2/27/90 soil from the middle of the excavation. Stockpile and cover.

Pump excavation as much as possible. Take soil samples from sidewalls and water samples from the "Baker Tank" and the excavation. Excavated the middle of hole down to clean soil. Stockpile and cover removed material. In the process, a new vain on contamination was found. It started at a depth of approximately 5 feet and ended between 9 and 10 feet. The direction is towards Webster Street. Water flow into excavation is now too great to keep pumping into tank.

and the second second second

- Put up more caution tape around excavation. Place barricades with flashers along fence lines. Attached caution sign to security fencing. Checked out site security.
- 3/3/90 Moved stockpiles and covered them. Checked site security.
- 3/5 3/8/90 Down due to bad weather.
- 3/9/90 Move "Geofabric" and plastic sheeting to site. Install more barricades with flashers at site.
- Discuss with the regulator (by telephone) the water situation in the excavation, and the need to backfill the clean portion of the hole so that we could safely excavate the remaining contamination. It was his opinion that groundwater had been impacted and that we could discontinue excavation below the present water level. Further, based upon the analytical results read to him over the telephone, it was acceptable to backfill the excavation excluding the area around Sample #1. He requested that we send him the analytical results as soon as we received the hard copy of them from the lab.
- 3/13/90 The Baker Tank" is pumped out into licensed transport truck.

  Approximately 300 tons of crushed rock is placed inside excavation.

  Approximately 15,000 gallons of water was pumped directly from the excavation into transport trucks during this backfill process. All contaminated water was hauled to H&H Ship Service's TSD facility.
- Finish-up spreading crushed rock in excavation. Lay out "Geofabric" on top of rock. Start decontamination of "Baker Tank" walls. Take water sample from middle of excavation.
- 3/15/90 Spread plastic sheet over "Geofabric" and entire inside of excavation. Start back filling with Class II baserock.
- 3/16/90 Continued to backfill with Class II baserock. Compacted with "sheepsfoot" vibratory compactor (continuously). Finished decontamination of "Baker Tank".
- 3/19/90 Continued to backfill with Class II baserock. Wetted down material and compacted with "sheepsfoot" vibratory compactor between lifts.

- 3/20/90 Continued to backfill with Class II baserock. Wetted down material and compacted with "sheepsfoot" fibratory compactor between lifts. Sidewall samples taken at 4.5 foot depth stockpile composite samples taken. Field density tests were performed at 4 feet below grade by Terratech.
- 3/21/90 Continued to backfill with Class II baserock. Wetted down material and compactor with "sheepsfoot" vibratory compactor between lifts. Excavation is now approximately 3 feet below grade.
- 3/22/90 Continued to backfill with Class II baserock. Wetted down material and compacted with "sheepsfoot" vibratory compactor between lifts. Excavation is now approximately 1/2 foot below grade.
- 4/17/90 Starting at Pacific Street, excavated heavily contaminated soil parallel to Webster Street approximately 3 feet inside the property line and to a depth of 10 feet. The contamination appears to continue under the sidewalk. Removed between 300 and 400 cubic yards. Place on plastic sheet and cover at the end of the day. Much of the material removed was chunks of asphalt and concrete.
- 4/18/90 Begin building berms and laying out plastic sheeting for remediation beds. With an ENSCO geologist present, continued to excavate heavily contaminated soil along Webster Street. It begins about 5 feet below grade and has the odor of gasoline. Found two large canopy footings made of concrete and drenched in product. Just after the second footing the contamination came up to the surface. Both steel and fiberglass product lines were encountered on a number of occasions. Removed 400 to 500 cubic yards of soil. Spread it out on the remediation beds and covered it. During excavation, soil samples were taken of the side and end walls.
- 4/19/90 Continue to excavate heavily contaminated soil along Webster Street. A third large canopy footing drenched in product was found. Approximately 1-2 feet beyond this, the depth of the contamination began to drop below grade gradually. More product lines were encountered. About 400 cubic yards was removed, placed on beds and covered.
- 4/20/90 Excavated until the contamination quit (visually speaking). This was about 120 feet south of the Pacific Street sidewalk. Material included lots of concrete and debris. Stockpiled and covered. Covered beds with plastic.
- 4/22/90 Finish removing contaminated soil up against earlier excavation. Spread out soil and cover beds.