HEALTH CARE SERVICES

AGENCY



DAVID J. KEARS, Agency Director

RO#2727

ENVIRONMENTAL HEALTH SERVICES

1131 Harbor Bay Parkway, Suite 250 Alameda, CA 94502-6577

Remedial Action Completion) 567,6700

March 27, 1998

Mr. Jon Kawamoto

Seagate Magnetics 47010 Kato Road, Fremont, CA - 94538

Subject:

Seagate Fremont Building C, 47010 Kato Road, Fremont, California

Dear Mr. Kawamoto:

I am in receipt of a initial report, dated February 2, 1998, which included the background information and calculations for cleanup levels and two letters, dated March 24, 1998 and March 25, 1998, which included revised calculations and sample location maps, prepared by McElligott consulting for the above referenced site.

Based on past usage of the building (manufacturing rigid discs), nickel dust was found in the initial wipe samples collected from the floors and ceilings of building C. As part of facility closure requirements from this Department and City of Fremont Fire Department, the building was remediated by pressure washing, shot bead blasting and toweling, completed by DECON Environmental. Subsequent to the completion of remedial activities, confirmation wipe samples were collected and analyzed for nickel. The average nickel concentration found in each of the pertaining areas, the sludge room and the polish area was compared to the cleanup level derived through a site specific risk assessment conducted for the referenced site.

Based upon the available information and with provision that the information provided to this agency is accurate and representative of site conditions, no further action is required. If you have any questions, you may reach me at (510) 567-6764.

Sincerely,

Madhulla Logan

Hazardous Material Specialist

Anthony McElligott, McElligott Consulting, 41547 Chadbourne Drive, Fremont, CA – 94539
Sukla De, City of Fremont Fire Dept, 39100 Liberty Street, P.O. Box 5006, CA- 94537-5006