

July 27, 2010 Meeting Notes
RO 2737; Impulse Motors
1210 Bockman Rd, San Lorenzo

- Meet with Dale Hines of Olson Company and Kyle Emerson of Stantec 10:30 – 11:15
- Both express frustration with slow herky – jerky progress of site and an apparent change in direction with new case worker (potential closure to additional work needed)
- This is understandable; part of problem has been Resolution 2009-0042 delays (1 year) where we looked at all sites for potential closures or impediments to (data gaps) as well as a review for closure where one looks closely at the data. My review found that the downgradient high concentrations had not been limited downgradient. My guess is there is not a large problem, but it's not been investigated. I'm hopeful a couple of bores and grab gw samples might limit the extent enough that closure would be possible.
- They will submit a Work Plan ASAP; I commit to expediting the review but explain we have a one year backlog of reviews that I also need to keep going. I also commit to pushing through any potential case closure as fast as possible due to bonding issues for the Olsen Company, with the same limitations noted.

•

A handwritten signature in black ink, appearing to read "Mark", with a stylized, sweeping flourish extending to the right.