

5/13/98

## Meeting Wainwright

- 1) need to define extent of petroleum plume <sup>redox potential</sup> → up gradient borings; off site or on site releases; ↳ former refinery
- 2) underground piping - so many of them - associated with USTs? → need to conduct sampling.

5/13/98

Collect samples 3 <sup>soil</sup> sample bottom  
4 composite samples

Bottom samples →

piping →

Tomorrow @ 8 AM → Ariser  
↳ Lattor

every 10 ft →

Memorialize →

Magnetic →