

Wickham, Jerry, Env. Health

From: Shawn Munger [SMUNGER@engeo.com]
Sent: Wednesday, October 30, 2013 8:29 AM
To: Wickham, Jerry, Env. Health; Roe, Dilan, Env. Health
Subject: Jordan Ranch - Spring

Jerry/Dilan,

We wanted to follow up on the "spring" question.

I spoke with our Project Geologist and reviewed air photos. The actual spring was located approximately 2,500 feet north of the wetland and 80 feet greater in elevation. Historically, the spring fed a shallow drainage that led to the pond. A subsurface drainage system was constructed at the spring as part of mass grading of the subdivision. The pond is now fed by a drain pipe from a keyway subdrain located 400 feet north of the pond, off-site along Jordan Ranch Drive.

Hopefully this answers your question.

Thank You,

Shawn Munger, CHG, PG, EM

Principal



2213 Plaza Drive

Rocklin, CA 95765

(916) 786-8883

Direct: (916) 580-6535

Mobile: (916) 416-9000

(888) 279-2698 Fax

www.engeo.com



If you have feedback for ENGEO please take a moment and fill out a quick [survey](#)

Voted one of the Top 10 Best Places to Work in the United States of America!

*****Due to the potential that information by electronic media can deteriorate, be damaged, lost or modified unintentionally or otherwise, use of this electronic data by anyone other than ENGEO Incorporated shall be at the sole risk of such user and without liability or legal exposure to ENGEO Incorporated. The recipient is responsible for verifying the accuracy of data against governing hard copy documentation. Recipient assumes all risks in the changing or modification of data and revisions or updating of hard copy documents.*****