

UNDERGROUND STORAGE TANK UNAUTHORIZED RELEASE (LEAK) / CONTAMINATION SITE REPORT

EMERGENCY
 YES NO
 HAS STATE OFFICE OF EMERGENCY SERVICES REPORT BEEN FILED?
 YES NO

FOR LOCAL AGENCY USE ONLY
 I HEREBY CERTIFY THAT I AM A DESIGNATED GOVERNMENT EMPLOYEE AND THAT I HAVE REPORTED THIS INFORMATION TO LOCAL OFFICIALS PURSUANT TO SECTION 25180.7 OF THE HEALTH AND SAFETY CODE.

REPORT DATE: 05/02/88
 CASE #

SIGNED: _____ DATE: _____

REPORTED BY: NAME OF INDIVIDUAL FILING REPORT: **MARC PAPINEAU**
 PHONE: (415) 697 7103
 SIGNATURE: *Marc Papineau*
 REPRESENTING: OWNER/OPERATOR REGIONAL BOARD
 LOCAL AGENCY OTHER
 COMPANY OR AGENCY NAME: **EARTH METRICS INC.**
 ADDRESS: **859 COWAN ROAD BURLINGAME CA 94010**

OWNER RESPONSIBLE PARTY: NAME: **Christie Ave Partners**
 CONTACT PERSON: **Walt Kaczmarek**
 PHONE: (415) 652-5852
 ADDRESS: **c/o The Martin Co. 6425 Christie Ave #406, Emeryville, Calif. 94608**

SITE LOCATION: FACILITY NAME (IF APPLICABLE): **5800 SHELLMOUND STREET**
 OPERATOR: _____ PHONE: ()
 ADDRESS: **(A.K.A. NIELSEN SITE) EMERYVILLE ALAMEDA 94608**
 CROSS STREET: **64th**
 TYPE OF AREA: COMMERCIAL INDUSTRIAL RURAL
 RESIDENTIAL OTHER
 TYPE OF BUSINESS: RETAIL FUEL STATION
 FARM OTHER **TRUCK TERM**

IMPLEMENTING AGENCIES: LOCAL AGENCY: **ALAMEDA COUNTY HAZ MAT**
 AGENCY NAME: _____ CONTACT PERSON: **LOWELL MILLER**
 PHONE: (415) 271 4320
 REGIONAL BOARD: _____ PHONE: ()

SUBSTANCES INVOLVED: (1) **GASOLINE** QUANTITY LOST (GALLONS): UNKNOWN
 (2) **DIESEL** QUANTITY LOST (GALLONS): UNKNOWN

DISCOVERY/ABATEMENT: DATE DISCOVERED: 04/29/88
 HOW DISCOVERED: TANK TEST INVENTORY CONTROL SUBSURFACE MONITORING NUISANCE CONDITIONS
 TANK REMOVAL OTHER
 DATE DISCHARGE BEGAN: _____
 METHOD USED TO STOP DISCHARGE (CHECK ALL THAT APPLY):
 REMOVE CONTENTS REPLACE TANK CLOSE TANK
 REPAIR TANK REPAIR PIPING CHANGE PROCEDURE
 OTHER
 HAS DISCHARGE BEEN STOPPED?
 YES NO IF YES, DATE: _____

SOURCE/CAUSE: SOURCE OF DISCHARGE: TANK LEAK UNKNOWN
 PIPING LEAK OTHER
 TANKS ONLY/CAPACITY: **10,000** GAL.
 AGE: _____ YRS
 UNKNOWN
 MATERIAL: FIBERGLASS STEEL OTHER
 CAUSE(S): OVERFILL RUPTURE/FAILURE
 CORROSION UNKNOWN
 SPILL OTHER

CASE TYPE: CHECK ONE ONLY
 UNDETERMINED SOIL ONLY GROUNDWATER DRINKING WATER - (CHECK ONLY IF WATER WELLS HAVE ACTUALLY BEEN AFFECTED)

CURRENT STATUS: CHECK ONE ONLY
 SITE INVESTIGATION IN PROGRESS (DEFINING EXTENT OF PROBLEM) CLEANUP IN PROGRESS SIGNED OFF (CLEANUP COMPLETED OR UNNECESSARY)
 NO ACTION TAKEN POST CLEANUP MONITORING IN PROGRESS NO FUNDS AVAILABLE TO PROCEED EVALUATING CLEANUP ALTERNATIVES

REMEDIAL ACTION: CHECK APPROPRIATE ACTION(S) (SEE BACK FOR DETAILS)
 CAP SITE (CD) EXCAVATE & DISPOSE (ED) REMOVE FREE PRODUCT (FP) ENHANCED BIO DEGRADATION (IT)
 CONTAINMENT BARRIER (CB) EXCAVATE & TREAT (ET) PUMP & TREAT GROUNDWATER (GT) REPLACE SUPPLY (RS)
 TREATMENT AT HOOKUP (HU) NO ACTION REQUIRED (NA) OTHER (OT)

COMMENTS: **Owner purchased property in 1/88. Tanks and manifold had already been removed. The current condition of property existed prior to purchase of property.**