



1647 International Blvd.
B Jakub, April 7, 2016
Second tank being removed with drums of waste and
rinseate in front.



1647 International Blvd.
B Jakub, April 7, 2016
Second tank with large hole along seam

1647 International Blvd.
B Jakub, April 7, 2016
Hole approximately 6 inches long and 2 wide.

04/07/2016 12



1647 International Blvd.
B Jakub, April 7, 2016
Side of tank

04/07/2016 12



1647 International Blvd.
B Jakub, April 7, 2016
Opposite side of tank

04/07/2016 12



1647 International Blvd.
B Jakub, April 7, 2016
Tank pit with some hydrocarbons on water, soil staining

04/07/2016 12



1647 International Blvd
B Jakub, April 7, 2016
Tank pit





1647 International Blvd.
B Jakub, April 7, 2016
Possible tank discovered beneath sidewalk

04/07/2016 12



1647 International Blvd.
B Jakub, April 7, 2016
Second of three possible tanks discovered in sidewalk at facility.

04/07/2016 12





1647 International Blvd.
B Jakub, April 7, 2016
1.5 feet of water in tank in sidewalk.



1647 International Blvd.
B Jakub, April 7, 2016
Alan Dimen showing the depth of the bottom of the tank (8 feet.)

04/07/2016 13