

ALAMEDA COUNTY
HEALTH CARE SERVICES
AGENCY

DAVID J. KEARS, Agency Director



ROI
RAFAT A. SHAHID, ASST. AGENCY DIRECTOR

DEPARTMENT OF ENVIRONMENTAL HEALTH
State Water Resources Control Board
Division of Clean Water Programs
UST Local Oversight Program
80 Swan Way, Rm 200
Oakland, CA 94621
(510) 271-4530

Certified Mail #

01/04/93
STID# 23

Notice of Requirement to Reimburse

Nicholas Molnar
The A. P. A. Fund Ltd.
1904 Franklin St., #501
Oakland, Ca 94612

Responsible Party #1
Property Owner

Raymond W./ Grace Yu

4098 Laguna Ave.
Oakland, Ca 94602

Responsible Party #2
Contact Person
Contact Company

Dan's Auto Repair
2801 MacArthur Blvd.
Oakland, CA 94602

SITE

Date First Reported 05/19/89
Substance: Gasoline
Petroleum: (X) Yes

The federal Petroleum Leaking Underground Storage Tank Trust Fund (Federal Trust Fund) provides funding to pay the local and state agency administrative and oversight costs associated with the cleanup of releases from underground storage tanks. The legislature has authorized funds to pay the local and state agency administrative and oversight costs associated with the cleanup of releases from underground storage tanks. The direct and indirect costs of site investigation or remedial action at the above site are funded, in whole or in part, from the Federal Trust Fund. The above individual(s) or entity(ies) have been identified as the party or parties responsible for investigation and cleanup of the above site. YOU ARE HEREBY NOTIFIED that pursuant to Title 42 of the United States Code, Section 6991b(h)(6) and Sections 25297.1 and 25360 of the California Health and Safety Code, the above Responsible Party or Parties must reimburse the State Water Resources Control Board not more than 150 percent of the total amount of site specific oversight costs actually incurred while overseeing the cleanup of the above underground storage tank site, and the above Responsible Party or Parties must make full payment of such costs within 30 days of receipt of a detailed invoice from the State Water Resources Control Board.

Please contact Tom PEACOCK, Supervising Hazardous Materials Specialist at this office if you have any questions concerning this matter.

Edgar B. Howell, III, Chief
Contract Project Director

cc: Sandra Malos, SWRCB

SWRCB Use: Update Reason: New RP name

ALAMEDA COUNTY
HEALTH CARE SERVICES

AGENCY

DAVID J. KEARS, Agency Director



State Water Resources Control Board
Division of Clean Water Programs
UST Local Oversight Program

ROI

RAFAT A. SHAHID, Assistant Agency Director

certified mailer #P 367 604 658

January 8, 1992
STID# 23

DEPARTMENT OF ENVIRONMENTAL HEALTH
80 Swan Way, Rm. 210
Oakland, CA 94621
(415) ~~271~~ (510) 271-4320

Notice of Requirement to Reimburse

Cali France Corporation
ATTN: Nicholas Molnar
1904 Franklin St., Suite 501
Oakland, CA 94612

Responsible Party
Contact Person

Raymond W. & Grace S. Yu
4098 Laguna Ave.
Oakland, CA 94602

Responsible Party
Property Owner

Dan's Auto Repair Site
2801 MacArthur Blvd.
Oakland, CA 94602

SITE

Date First Reported 05/19/89
Substance: gasoline, waste oil
Petroleum (X) Yes

The federal Petroleum Leaking Underground Storage Tank Trust Fund (Federal Trust Fund) provides funding to pay the local and state agency administrative and oversight costs associated with the cleanup of releases from underground storage tanks. The legislature has authorized funds to pay the local and state agency administrative and oversight costs associated with the cleanup of releases from underground storage tanks. The direct and indirect costs of overseeing removal or remedial action at the above site are funded, in whole or in part, from the Federal Trust Fund. The above individual(s) or entity(ies) have been identified as the party or parties responsible for investigation and cleanup of the above site. **YOU ARE HEREBY NOTIFIED** that pursuant to Title 42 of the United States Code, Section 6991b(h)(6) and Sections 25297.1 and 25360 of the California Health and Safety Code, the above Responsible Party or Parties must reimburse the State Water Resources Control Board not more than 150 percent of the total amount of site specific oversight costs actually incurred while overseeing the cleanup of the above underground storage tank site, and the above Responsible Party or Parties must make full payment of such costs within 30 days of receipt of a detailed invoice from the State Water Resources Control Board.

If you have any questions concerning this matter please contact Thomas Peacock, Supervising Hazardous Material Specialist, at this office.

Edgar B. Howell, III, Chief
Contract Project Director

cc: Sandra Malos, SWRCB

SWRCB Use : add: X Reason: New case

ALAMEDA COUNTY
HEALTH CARE SERVICES

AGENCY

DAVID J. KEARS, Agency Director



State Water Resources Control Board
Division of Clean Water Programs
UST Local Oversight Program

ROI

RAFAT A. SHAHID, Assistant Agency Director

certified mailer #P 367 604 659

January 8, 1992
STID# 23

DEPARTMENT OF ENVIRONMENTAL HEALTH
80 Swan Way, Rm. 210
Oakland, CA 94621
(415) ~~527~~(500) 271-4320

Notice of Requirement to Reimburse

Cali France Corporation
ATTN: Nicholas Molnar
1904 Franklin St., Suite 501
Oakland, CA 94612

Responsible Party
Contact Person

Raymond W. & Grace S. Yu
4098 Laguna Ave.
Oakland, CA 94602

Responsible Party
Property Owner

Dan's Auto Repair Site
2801 MacArthur Blvd.
Oakland, CA 94602

SITE

Date First Reported 05/19/89
Substance: gasoline, waste oil
Petroleum (X) Yes

The federal Petroleum Leaking Underground Storage Tank Trust Fund (Federal Trust Fund) provides funding to pay the local and state agency administrative and oversight costs associated with the cleanup of releases from underground storage tanks. The legislature has authorized funds to pay the local and state agency administrative and oversight costs associated with the cleanup of releases from underground storage tanks. The direct and indirect costs of overseeing removal or remedial action at the above site are funded, in whole or in part, from the Federal Trust Fund. The above individual(s) or entity(ies) have been identified as the party or parties responsible for investigation and cleanup of the above site. **YOU ARE HEREBY NOTIFIED** that pursuant to Title 42 of the United States Code, Section 6991b(h)(6) and Sections 25297.1 and 25360 of the California Health and Safety Code, the above Responsible Party or Parties must reimburse the State Water Resources Control Board not more than 150 percent of the total amount of site specific oversight costs actually incurred while overseeing the cleanup of the above underground storage tank site, and the above Responsible Party or Parties must make full payment of such costs within 30 days of receipt of a detailed invoice from the State Water Resources Control Board.

If you have any questions concerning this matter please contact Thomas Peacock, Supervising Hazardous Material Specialist, at this office.

Edgar B. Howell, III, Chief
Contract Project Director

cc: Sandra Malos, SWRCB

SWRCB Use :

add: X Reason: New case

OAKLAND CA 94612
PM 10

SENDER: Complete Items 1 and 2 when additional services are desired, and complete Items 3 and 4. Put your address in the "RETURN TO" Space on the reverse side. Failure to do this will prevent this card from being returned to you. The return receipt fee will provide you the name of the person delivered to and the date of delivery. For additional fees the following services are available. Consult postmaster for fees and check box(es) for additional service(s) requested.

1. Show to whom delivered, date, and addressee's address. (Extra charge) 2. Restricted Delivery (Extra charge)

3. Article Addressed to: Raymond W. & Grace S. Yu 4098 Laguna Avenue Oakland, CA 94602	4. Article Number 23 #P 367 604 659 Type of Service: <input type="checkbox"/> Registered <input type="checkbox"/> Insured <input checked="" type="checkbox"/> Certified <input type="checkbox"/> COD <input type="checkbox"/> Express Mail <input type="checkbox"/> Return Receipt for Merchandise Always obtain signature of addressee or agent and DATE DELIVERED.
5. Signature - Addressee X <i>[Signature]</i>	8. Addressee's Address (ONLY if requested and fee paid)
6. Signature - Agent X <i>[Signature]</i>	
7. Date of Delivery 1/11/92	

PS Form 3811, Mar. 1986 • U.S.G.P.O. 1988-212-865 DOMESTIC RETURN RECEIPT

OAKLAND CA 94612
PM 10

SENDER: Complete Items 1 and 2 when additional services are desired, and complete Items 3 and 4. Put your address in the "RETURN TO" Space on the reverse side. Failure to do this will prevent this card from being returned to you. The return receipt fee will provide you the name of the person delivered to and the date of delivery. For additional fees the following services are available. Consult postmaster for fees and check box(es) for additional service(s) requested.

1. Show to whom delivered, date, and addressee's address. (Extra charge) 2. Restricted Delivery (Extra charge)

3. Article Addressed to: Cali France Corporation ATTN: Nicholas Molnar 1904 Franklin St., Suite 501 Oakland, CA 94612	4. Article Number 23 #P 367 604 658 Type of Service: <input type="checkbox"/> Registered <input type="checkbox"/> Insured <input checked="" type="checkbox"/> Certified <input type="checkbox"/> COD <input type="checkbox"/> Express Mail <input type="checkbox"/> Return Receipt for Merchandise Always obtain signature of addressee or agent and DATE DELIVERED.
5. Signature - Addressee X <i>[Signature]</i>	8. Addressee's Address (ONLY if requested and fee paid)
6. Signature - Agent X <i>[Signature]</i>	
7. Date of Delivery JAN 13 1992	

PS Form 3811, Mar. 1986 • U.S.G.P.O. 1988-212-865 DOMESTIC RETURN RECEIPT