



GETTLER-RYAN INC.

February 21, 1997

Mr. Phil Briggs
Chevron Products Company
P.O. Box 6004
San Ramon, California 94583

Subject: Utility Trench Survey at Chevron Service Station #9-0504, 15900 Hesperian Boulevard, San Lorenzo, California.

Mr. Briggs:

At the request of Chevron Products Company, Gettler-Ryan Inc. (G-R) conducted a utility trench survey near the above referenced site. The survey results are presented on the attached Underground Utility Location Map. Information regarding sewer, storm and water line locations and approximate depths were obtained from the Oro Loma Sanitary District (OLSD), Alameda County Flood Control and Water Conservation District (ACFCWCD), and East Bay Municipal Utility District (EBMUD), respectively. OLSD, ACFCWCD and EBMUD files did not contain plans showing construction details of the subject utility lines, therefore, specific information regarding trench backfill and exact depth could not be obtained. The locations of telephone lines were marked at the site by Pacific Bell, and locations of gas and electrical lines were marked at the site by Pacific Gas and Electric Company following the Underground Service Alert request #24805.


If you have any questions, please call us at (510) 551-8777.

Sincerely,
Gettler-Ryan Inc.

Stephan J. Carter, R.G./FOR
Barbara Sieminski
Project Geologist

Enclosures: Figure 1. Underground Utility Location Map

3/21/97
Due to the fact that
DTW is below 7 - to 8-foot
bgs at least 90% of the
time, it appears that
utility lines are not acting
as conduits of concern.
-Julius Stein



Gettler - Ryan Inc.

6747 Sierra Ct., Suite J (510) 551-7555
 Dublin, CA 94568

UNDERGROUND UTILITY LOCATION MAP
 Chevron Service Station No. 9-0504
 15900 Hesperian Boulevard
 San Lorenzo, California

FIGURE

1

JOB NUMBER
5259

REVIEWED BY

DATE
2/97

REVISED DATE