

ALAMEDA COUNTY
HEALTH CARE SERVICES

AGENCY

DAVID J. KEARS, Agency Director



State Water Resources Control Board
Division of Clean Water Programs
USF Local Oversight Program

DEPARTMENT OF ENVIRONMENTAL HEALTH
Hazardous Materials Division
80 Swan Way, Rm. 200
Oakland, CA 94621
(510) 271-4320

certified mailer #P 367 604 273

May 29, 1992
STID# 34

Notice of Requirement to Reimburse

Eandi Metal Works
ATTN: Mr. Jeffrey Eandi
976 23rd Ave.
Oakland, CA 94606

Responsible Party
Contact Person
Property Owner

Eandi Metal Works
976 23rd Ave.
Oakland, CA 94606

SITE

Date First Reported: 05/27/92
Substance: gasoline
Petroleum (X) Yes

The federal Petroleum Leaking Underground Storage Tank Trust Fund (Federal Trust Fund) provides funding to pay the local and state agency administrative and oversight costs associated with the cleanup of releases from underground storage tanks. The legislature has authorized funds to pay the local and state agency administrative and oversight costs associated with the cleanup of releases from underground storage tanks. The direct and indirect costs of overseeing removal or remedial action at the above site are funded, in whole or in part, from the Federal Trust Fund. The above individual(s) or entity(ies) have been identified as the party or parties responsible for investigation and cleanup of the above site. **YOU ARE HEREBY NOTIFIED** that pursuant to Title 42 of the United States Code, Section 6991b(h)(6) and Sections 25297.1 and 25360 of the California Health and Safety Code, the above Responsible Party or Parties must reimburse the State Water Resources Control Board not more than 150 percent of the total amount of site specific oversight costs actually incurred while overseeing the cleanup of the above underground storage tank site, and the above Responsible Party or Parties must make full payment of such costs within 30 days of receipt of a detailed invoice from the State Water Resources Control Board.

If you have any questions concerning this matter please contact Barney Chan, Hazardous Material Specialist, at (510) 271-4530.

Sincerely,

Edgar B. Howell, III, Chief
Contract Project Director

cc: Sandra Malos, SWRCB

SWRCB Use : add: X Reason: New case

SENDER: Complete Items 1 and 2 when additional services are desired, and complete items 3 and 4.
 Put your address in the "RETURN TO" Space on the reverse side. Failure to do this will prevent this card from being returned to you. The return receipt fee will provide you the name of the person delivered to and the date of delivery. For additional fees the following services are available. Consult postmaster for fees and check box(es) for additional service(s) requested.

1. Show to whom delivered, date, and addressee's address. (Extra charge) **ST10 39**
 2. Restricted Delivery (Extra charge)

3. Article Addressed to: **(BC) #34**

**Eandi Metal Works
 Attn: Mr. Jeffrey Eandi
 976 23rd Ave.
 Oakland, CA 94606**

4. Article Number
P 367 604 273

Type of Service:
 Registered Insured
 Certified COD
 Express Mail Return Receipt for Merchandise

Always obtain signature of addressee or agent and **DATE DELIVERED:**

5. Signature -- Address
X

6. Signature -- Agent
X *[Signature]*

7. Date of Delivery
6/2/92

8. Addressee's Address (ONLY if requested and fee paid)

PS Form 3811, Mar. 1988 * U.S.G.P.O. 1988-212-885 DOMESTIC RETURN RECEIPT

P 367 604 273

RECEIPT FOR CERTIFIED MAIL

NO INSURANCE COVERAGE PROVIDED
 NOT FOR INTERNATIONAL MAIL

(BC) #34 (See Reverse)

* U.S.G.P.O. 1989-234-555

Sent to Jeffrey Eandi	
Street and No 976 23rd Ave.	
P.O., State and ZIP Code Oakland, CA 94606	
Postage	\$
Certified Fee	
Special Delivery Fee	
Restricted Delivery Fee	
Return Receipt showing to whom and Date Delivered	
Return Receipt showing to whom, Date, and Address of Delivery	
TOTAL Postage and Fees	\$
Postmark or Date	

PS Form 3800, June 1985

ST10 39