

## Jakub, Barbara, Env. Health

---

**From:** Jakub, Barbara, Env. Health  
**Sent:** Thursday, August 13, 2009 12:01 PM  
**To:** 'John Reay'  
**Cc:** Determan, Mark, Env. Health  
**Subject:** RE: 3737

Yes. Please analyze the new wells for motor oil when they are installed.

---

**From:** John Reay [mailto:JReay@deltaenv.com]  
**Sent:** Thursday, August 13, 2009 10:37 AM  
**To:** Jakub, Barbara, Env. Health  
**Subject:** 3737

Barbara:

We have the CPT results from 3737 (1400 Powell St., Emeryville) back and while they look like ND or low hits, there are a few that exceed MCL for benzene, gas and diesel in groundwater, enough I think to follow up with some monitoring wells to verify these results. What I note, however, is that the analysis did not pick up Motor Oil specifically, which was in your letter. While, based on the results we have, I don't see that MO would be an issue, I would ask if we can follow up on this in the sampling program to be recommended for groundwater. Would that be OK with you?

Thanks!

**John R. Reay | Geologist | Global Oil & Gas Business Group**  
**Delta Consultants, an Oranjewoud N.V. Company**  
Direct (916) 503-1260 | Mobile (916) 903-4406 | USA Toll Free (800) 477-7411  
[jreay@deltaenv.com](mailto:jreay@deltaenv.com) | [www.deltaenv.com](http://www.deltaenv.com)

**THE TRUSTED PARTNER FOR MAXIMIZED ASSET VALUE**

Member of Inogen® | [www.inogenet.com](http://www.inogenet.com)

*Confidentiality Notice: If you are not the intended recipient of this email, please delete it. Thank you.*